



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	8536
Inspector	Brian Shields			Date/Time	9/28/2018 1:06 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11277+92
State	VA	Inspection Area	Partial	Station End	10929+90
County	Giles	Ground	Muddy	Temperature (°F)	78.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	2.25
GPS Location	37.296399024309, -80.4941388347111			Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					No
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication		24 Hours		
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Communication	See comments	24 Hours		
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Problem Area	Stabilize side slopes	24 Hours		
Waterbar	Acceptable				
Waterbar Outlet Protection	Problem Area	Repair undercut end treatments	24 Hours		
Slope drain	Problem Area	Repair/reinstall rock aprons	24 Hours		
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300137	Date/Time	9/28/2018 1:06 PM	Report #	8536
Pictures					
					
GPS Location	37.2963739573136, -80.4941299103921	GPS Location	37.2963739573136, -80.4941299103921		
Description	Gully in side slope at 11282+50; stabilization and repair needed.	Description	End treatment undercut at st11022+55		
					
GPS Location	37.2963739573136, -80.4941299103921	GPS Location	37.1361127795793, -80.3941768189708		
Description	Slope drain failure at st#11273+70.	Description	Super silt fence full and overtopped at st#11279+00		
					
GPS Location	37.2963739573136, -80.4941299103921	GPS Location	37.2957016033109, -80.4944009949237		
Description	Silt fence undercut at st#11287+50.	Description	Silt fence undercut top of access rd 244		