Mour Mour	ita V	in alley		Visual S	Site In	specti	on Repo	ort	t	
Project Name H-600 Pip		H-600 Pipe	eline Spread H AFE 124300138			Spread	H-6	H-600 Pipeline Spread H		
Contractor Precision			'			Report #	7496			
Inspector Dustin Lyons						Date/Time	9/7/2018 4:15 P		PM	
Permit #	TBC	)		Inspection Type VA SWPP		)	Station Begin 12072+50			
State	VA			Inspection Area	Partial		Station E	<b>nd</b> 12005+00		
County	Mor	ntgomery		Ground	Dry		Temp	Temperature (ºF)		88.00
Municipality	N/A			Weather	Cloudy		Rair	ı Ga	0.00	
GPS Location	<b>PS Location</b> 37.0424662432196, -80.6426			3469368313 Rain A			ccumulation Time (days)			1.00
1. Are the appr	ovec	d (stampe	d) E&S Plan	and PCSM Plan pre	sent on s	ite?				Yes
				the limits of disturba				?		No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							et being	Yes		
4. E&S BMPs ( is required.)	(List	BMPs and	note if insta	illed and maintained	as per th	e plan. If	corrective acti	ion i	is needed,	a pictur
E&S BMPs			Compliance Level		Correc	tive Action		Corrective Time Frame		
Compost Filter So	ock			Acceptable						
Erosion Control Blanket			Acceptable							
Housekeeping			Acceptable							
Rock Construction Entrance			Acceptable							
Silt Fence (Reinforced Filter Fabric Fence)			Acceptable							
Silt Fence (Filter Fabric Fence)			Acceptable							
Waterbar			Acceptable							
Sump Pit			Acceptable							
5. Site Conditi	ons				•					
beyond defined	limit	s of distur	bance resulti	iment, gravel, oil, HI ing from earth disturl ironmental Permittin	oance ac	tivity or ine	•			No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes			
Are slopes 3:1 a	and g	greater sta	abilized with a	appropriate BMPs as	per E&S	plans?				Yes
				a complete Clide D						N <sub>a</sub>

MVP-34 REV 0 Page 1 of 3

No

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

<b>AFE</b> 124300138	Date/Time 9/7/201	8 4:15 PM	Report #	7496							
<ol><li>PCSM BMPs (List BMPs and note if inst picture is required.)</li></ol>	alled and maintained as	per the plan. If corre	ctive action is	needed, a							
PCSM BMPs	Compliance Correct		ction	Corrective Time Frame							
7. Identify all remedial measures that have been taken since the previous inspection was conducted.											
7. Idonary an romodial moderno that have			, 00114401041								
Comments (Reference above questions as											
The remedial measures performed in this area in Repairing CFS at 12036+50 Repairing P1 silt fence at 12036+50 and 12029+ Cleaning sumps and adding triple stack CFS at And repairing slope drain inlets at 12024+00 and	+15 12029+94										
I walked from access road 270.00 (about station 12072+50) to the spread kickoff at station 12005+00 to perform the SWPPP inspection. No off-ROW impacts were observed during this inspection.											
The environmental crew cleaned out the sump a verified these items today.	at 12050+00 and keyed in	the CFS at 12049+70 (p	unch list items	1139 and 1140).							
Precision's crews also constructed one pass three installed at 12022+78 was added at the contract appeared to be constructed as detailed in the sucontractor began constructing another trench browns	ors discretion and was co applemental landslide mitic	nstructed using concrete	bags (sackrete	e). The breaker							

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3

**AFE** 124300138 Date/Time 9/7/2018 4:15 PM Report # 7496 **Pictures** DIRECTION 117 deg(T) GPS Location 37.0424499004376, -80.6426798891176 **GPS Location** 37.042449900275, -80.6426798894455 See photo for gps data. CFS keyed in at 12049+70. Punch list item 1139. See photo for gps data. Sump at 12050+00 was cleaned out. Punch list item 1140. Description Description 12059+00 **GPS Location GPS Location** 37.2621344821875, -80.3025332373383 37.2620736295704, -80.3023981210592 See photo for gps data. Added pas through trench breaker (MVP-43A) at 12022+78. See photo for gps data. Light plants placed in containment on ROW. Description Description GPS Location 37.2621429060002, -80.302289072499 **GPS Location** 37.2621161258195, -80.3023320716622 See photo for gps data. Slope drain inlet at See photo for gps data. Red line sketch showing the added trench breaker at 12022+78. 12025+00. Description Description

MVP-34 REV 0 Page 3 of 3