| Mour Mour | nta V | in alley | | Visual S | Site I | ns | specti | on Repo | ort | t | |
|--|--|---------------|----------------------|--|-------------------|----------|-------------------------|-------------------------|---------|------------|---------|
| Project Name H-600 Pipeline Spread 0 | | line Spread G | AFE 124300137 | | | Spread | H-600 Pipeline Spread G | | pread G | | |
| Contractor Precision | | | | | | Report # | 5083 | | | | |
| Inspector Clinton Banks | | | | | | | Date/Time | 7/2 | 11 AM | | |
| Permit # | TBD |) | | Inspection Type VA SWPP | | | | Station Begin +28 | | | |
| State | VA | | | Inspection Area | Full | | | Station End +26 | | | |
| County | Gile | s | | Ground | Damp | | | Temperature (°F) | | | 75.00 |
| Municipality | N/A | | | Weather | Cloudy | | | Rain Gauge (in) | | | 0.01 |
| 37.3359443899592, -80.8082 | | | 19239191 Rain A | | | Rain Ac | ccumulation Time (days) | | | 1.00 | |
| 1. Are the appr | Are the approved (stamped) E&S Plan and PCSM Plan present on site? | | | | | | | | Yes | | |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | | | | | | | | No | | | |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or P followed? (If No, notify MVP Environmental Permitting Coordinator and explain in co | | | | | | | | et being | Yes | | |
| 4. E&S BMPs (is required.) | (List | BMPs and | I note if insta | lled and maintained | as per | the | plan. If o | corrective acti | on | is needed, | a pictu |
| E&S BMPs | | | Compliance Level | | Corrective Action | | | Corrective Time Fram | | | |
| Safety Fence | | | | Acceptable | LY | 28 | | | | | |
| Housekeeping | | | | Acceptable | | | | | | | |
| Rock Construction Entrance | | | Acceptable | | | | | | | | |
| Compost Filter Sock | | | Problem Area | LY | LY 28 See Comment | | | | | | |
| Containment For Diesel Fuel | | | Acceptable | LY | LY 26 | | | | | | |
| Rock Constructio | n Ent | trance | | Acceptable | | | | | | | |
| Compost Filter Sock | | | Acceptable | | | | | | | | |
| Housekeeping | | | Acceptable | | | | | | | | |
| | | | | | | | | | | | |
| 5. Site Conditi | ons | | | | | | | | | | |
| beyond defined | limits | s of distur | bance resulti | ment, gravel, oil, HE ng from earth disturl ironmental Permittin | bance a | activ | vity or ine | • | | | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | | | | | | | | | Yes | | |
| Are slopes 3:1 a | and g | reater sta | abilized with a | ppropriate BMPs as | per E8 | λS μ | olans? | | | | Yes |
| | | | | | • | | _ | | | | |

MVP-34 REV 0 Page 1 of 3

No

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

| AFE 124300137 | Date/Time 7/24/20 | 18 10:41 AM | Report # | 5083 | | | | | | | | |
|---|---------------------|---------------------------|----------|--------------------------|--|--|--|--|--|--|--|--|
| PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | | | | | | | | | | | | |
| PCSM BMPs | Compliance Level | Corrective Ac | tion | Corrective Time Frame | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 7. Identify all remedial measures that have been taken since the previous inspection was conducted. | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| O | | | | | | | | | | | | |
| Conducted Weekly VA SWPP at LY 28 and LY 26 | | d to be Penair see nictur | o helow | | | | | | | | | |
| Conducted Weekly VA SWPP at LY 28 and LY 26. 18" Sock at LY 28 need to be Repair, see picture below. | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a | | | | | | | | | | | | |

MVP-34 REV 0 Page 2 of 3

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

Date/Time 7/24/2018 10:41 AM **AFE** 124300137 **Report #** |5083 **Pictures** GPS Location 37.3355222773155, -80.8081202489145 **GPS Location** 37.3339075874885, -80.8031097148366 Safety Fence at LY 28 Off Loading Sock at LY 28 Description Description Insert image here **GPS Location GPS Location** 37.3337562941362, -80.8027461916961 18" Sock need to be repair LY 28 behind where 12" Sock is Storage Description Description Insert image here Insert image here **GPS Location GPS Location** Description Description

MVP-34 REV 0 Page 3 of 3