Mour Mour	nta V	ain Valley		Visual Site Inspection Report							
Project Name H-600 Pipeline Spread			line Spread G	AFE 124300137			Spread	H-6	H-600 Pipeline Spread G		
Contractor Precision			-			Report #	6670				
Inspector Clinton Banks						Date/Time	8/21/2018 3:44 AM				
Permit #	ТВІ)		Inspection Type VA SWPP			Station Beg	Station Begin +28			
State	VA			Inspection Area	Full		Station E	Station End +26			
County	Gile	es		Ground	Wet		Temp	Temperature (°F) 70			
Municipality	N/A	١		Weather	Cloudy		Raiı	Rain Gauge (in)			
GPS Location 37.3192647285548, -80.6578			332659542 Rain A			Accumulation	ccumulation Time (days)				
Are the approved (stamped) E&S Plan and PCSM Plan present on site?								Yes			
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)									No		
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)								et being	Yes		
4. E&S BMPs (is required.)	(List	BMPs and	I note if insta	lled and maintained	as per ti	ne plan. I	f corrective act	ion	is needed,	a picture	
E&S BMPs			Compliance Level		Corre	ective Action		Corrective Time Frame			
Compost Filter Sock			Acceptable								
Housekeeping			Acceptable								
Rock Construction Entrance			Acceptable								
Safety Fence			Acceptable								
Fuel Containment			Acceptable								
Compost Filter Sock			Acceptable								
Housekeeping			Acceptable								
Rock Construction Entrance			Acceptable								
Silt Fence (Filter Fabric Fence)			Acceptable								
5. Site Conditi	ons	3							'		
beyond defined	limi	ts of distur	bance resulti	ment, gravel, oil, HE ng from earth disturl ironmental Permittin	bance ac	tivity or in	•			No	
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?								Yes			
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?								Yes			
Has a new alin/alide been abserved? (If was complete Clide Benert Form)									N _a		

MVP-34 REV 0 Page 1 of 3

No


Has a new slip/slide been observed? (If yes, complete Slide Report Form)

AFE	124300137	Date/Time 8/21/20	18 3:44 AM	Report #	6670								
6. P	6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a												
p	picture is required.)												
	PCSM BMPs	Compliance Level	Corrective Ac	Corrective Action									
7 . lo	lentify all remedial measures that have t	peen taken since the c	revious inspection was	conducted									
	ioning an romodial moderno machare	boom tanton ombo tino p	Torrodo mopositom mas										
	ments (Reference above questions as a												
Cond	ucted Weekly VA SWPP at LY 26 and LY 28	3											
Note	: It is a condition of National Pollutant D	ischarge Elimination S	System and Erosion and	d Sediment pe	ermits that a								
main	tenance program be conducted to provi	de for the operation ar	nd maintenance of all E	MPs to be ins	pected on a								
week	ly basis and after each stormwater ever	nt. Please list in the sp	pace provided commer	its to note if re	pairs or								

MVP-34 REV 0 Page 2 of 3

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.



MVP-34 REV 0 Page 3 of 3