Mountain Valley PIPELINE VISUAL Site Inspection Report										
Project Name H-600 Pipeline Spread G		AFE 124300137		Spread	H-600 Pipeline Spread G		oread G			
Contractor Precision						Report #	1437			
Inspector Garrett Barclay						Date/Time	5/4/2	PM		
Permit #	Permit # TBD			Inspection Type Weekly			jin 1			
State	VA		Inspection Area Full			Station End 12000+00				
County	Montgomery		Ground Dry			Temperature (ºF)			80.00	
Municipality	N/A		Weather	Sunny		Rain Gauge (in) 0.			0.00	
GPS Location	37.268220540	1708, -80.319	9624829742		Rain Ac	Accumulation Time (days)			1.00	
1. Are the appro	oved (stampe	d) E&S Plan a	and PCSM Plan pre	sent on sit	e?				Yes	
Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)										
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)								Yes		
 E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) 										
E&S BMPs		Compliance Level		Corrective Action			Corrective Time Frame			
5. Site Condition		(auch as as-1	mont groupl all LIF	ال السائط منا	0) 000:	ing to water-	Mark!	anda ar		
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.										
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									Yes	
Are slopes 3:1 a	ınd greater st	abilized with a	ppropriate BMPs as	per E&S	olans?				N/A	
Has a new slip/s	slide been obs	served? (If ye	s, complete Slide R	eport Form	1)				No	

MVP-34 REV 0 Page 1 of 3

AFE	124300137	Date/Time 5/4/201	8 4:59 PM	Report #	1437						
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a											
picture is required.)											
PCSM BMPs		Compliance Level	Corrective Action		Corrective Time Frame						
		Level			Time Frame						
7. Identify all remedial measures that have been taken since the previous inspection was conducted.											
7. Identity an remodial medadies that have been taken since the previous inspection was conducted.											
^	(Defended by 1997)										
	ments (Reference above questions as										
Obser	d stickers to newly arrived equipment @ ved crew installing rock @ AR MN 258.05	and building RCE @ MP	219.5								
Observed crew installing rock @ AR MN 258.05 and building RCE @ MP 219.5 Observed crew building travel lane near MP 223 and Karst area, Draper Aden was on site while crew worked in KARST area Observed crew burning timber piles @ MP 226 Observed crew building timber mat bridge @ MP 226.5 and stripping top soil											
Observed crew building timber mat bridge @ MP 226.5 and stripping top soil											
No environmental concerns or compliance issues to report at this time											

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3

AFE 124300137 Date/Time 5/4/2018 4:59 PM Report # 1437 **Pictures GPS Location** 37.2681702487518, -80.3199479822817 **GPS Location** 37.2681702487518, -80.3199479822817 Stickers for equipment @ Yards 26&28 ECD's around Top Soil stockpile @ MP 219 Description Description **GPS Location** GPS Location 37.2682583006446, -80.319932811037 37.2682583006446, -80.319932811037 Crew building travel lane @ MP 223 Crew burning piles of timber @ MP 226 Description Description GPS Location |37.2682583006446, -80.319932811037 **GPS Location** |37.2682583006446, -80.319932811037 Crew stabilizing top soil @ MP 226 Crew installed mat bridge for W-NN6 Description Description

MVP-34 REV 0 Page 3 of 3