



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G		AFE	124300137	Spread	H-600 Pipeline Spread G	
Contractor	Precision				Report #	3951	
Inspector	Jared Saunders				Date/Time	7/2/2018 4:04 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	11788+00	
State	VA	Inspection Area	Partial		Station End	11900+00	
County	Montgomery	Ground	Dry		Temperature (°F)	90.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
GPS Location	37.2983690305029, -80.3885879740868				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level		Corrective Action		Corrective Time Frame	
Compost Filter Sock		Acceptable		N/A		Addressed	
Rock Construction Entrance		Acceptable		N/A		Addressed	
Silt Fence (Filter Fabric Fence)		Acceptable		N/A		Addressed	
Sensitive Resource Buffer		Acceptable		N/A		Addressed	
Sensitive Resource Signage		Acceptable		N/A		Addressed	
Waterbar		Acceptable		N/A		Addressed	
Vegetative Stabilization (Temporary)		Acceptable		N/A		Addressed	
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable		N/A		Addressed	
Sump Pit		Acceptable		N/A		Addressed	
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300137	Date/Time	7/2/2018 4:04 PM	Report #	3951
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPP inspection from MP 223.26 to MP 225.38 Since last inspection Precision Pipeline has been on an environmental shut down and has been conducting maintenance on all ECDs and punch list items. ECDs observed were functional and in place in accordance with the E&S plans.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/2/2018 4:04 PM	Report #	3951
Pictures					
<div><div><div>Date & Time: Mon Jul 2 06:57:35 EDT 2018</div><div>Position: +037.293137, -80.362165</div><div>Altitude: 2071ft</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 004° N04E 0071mils (True)</div><div>Elevation Angle: +27.3°</div><div>Horizon Angle: +01.3°</div><div>Zoom: 1X</div><div>11788+00</div></div><div></div></div>		<div><div><div>Date & Time: Mon Jul 2 09:04:51 EDT 2018</div><div>Position: +037.296442, -80.362296</div><div>Altitude: 2138ft</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 183° N83E 1676mils (True)</div><div>Elevation Angle: +30.7°</div><div>Horizon Angle: +01.5°</div><div>Zoom: 1X</div><div>11793+00</div></div><div></div></div>			
GPS Location	37.2931316199996, -80.3621656800054		GPS Location	37.2931316199996, -80.3621656800054	
Description	See photo for GPS location and station number. RCE at Mt. Tabor Rd access. RCE is in good condition and will assist in prevention		Description	See photo for GPS location and station number. Spoil pile stabilized with seed and mulch.	
<div><div><div>Date & Time: Mon Jul 2 08:14:37 EDT 2018</div><div>Position: +037.270722, -80.370145</div><div>Altitude: 2147ft</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: +338° N22W 6009mils (True)</div><div>Elevation Angle: +25.2°</div><div>Horizon Angle: +02.0°</div><div>Zoom: 1X</div><div>11802+50</div></div><div></div></div>		<div><div><div>Date & Time: Mon Jul 2 12:49:45 EDT 2018</div><div>Position: +037.270722, -80.370145</div><div>Altitude: 2147ft</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 299° N61W 5316mils (True)</div><div>Elevation Angle: +27.4°</div><div>Horizon Angle: +02.4°</div><div>Zoom: 1X</div><div>11864+00 P-KL2</div></div><div></div></div>			
GPS Location	37.29313162, -80.36216568		GPS Location	37.29313162, -80.36216568	
Description	See photo for GPS location and station number. Water breaker and end treatment installed.		Description	See photo for GPS location and station number. Wetland P-KL2.	
<div><div><div>Date & Time: Mon Jul 2 13:04:05 EDT 2018</div><div>Position: +037.271052, -80.369935</div><div>Altitude: 2167ft</div><div>Datum: WGS-84</div><div>Azimuth/Bearing: 324° N36W 5760mils (True)</div><div>Elevation Angle: +26.6°</div><div>Horizon Angle: +02.4°</div><div>Zoom: 2X</div><div>AR 266.03 RCE</div></div><div></div></div>		Insert image here			
GPS Location	37.29313162, -80.36216568		GPS Location		
Description	See photo for GPS location and station number. RCE at Dry Run Rd. and access 266.03. RCE is in good condition and will		Description		