



Visual Site Inspection Report





Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	6384
Inspector	Jared Saunders			Date/Time	8/15/2018 5:15 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10883+50
State	VA	Inspection Area	Partial	Station End	11025+00
County	Giles	Ground	Dry	Temperature (°F)	88.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.2060816470739, -80.3943324103999			Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame
Broad-Based Dip	Acceptable		
Compost Filter Sock	Acceptable		
Rock Construction Entrance	Acceptable		
Erosion Control Blanket	Acceptable		
Silt Fence (Filter Fabric Fence)	Acceptable		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable		
Waterbar	Acceptable		
Sump Pit	Acceptable		

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/15/2018 5:15 PM	Report #	6384
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPP inspection from MP 206 to MP 208.8 Since last inspection Precision Pipeline has worked on ECD maintenance. Three environmental crews worked in the area installing water breakers, end treatments, and perimeter control maintenance. Tetra tech marked our stream S-RR4 on access road 243.01. When mat bridge was installed northern clearing placed mat in the stream bed. Environmental crew removed mat from stream bed and reestablished stream bed and banks. Item was wrote as a noncompliance report.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	8/15/2018 5:15 PM	Report #	6384
Pictures					
<p>Date & Time: Wed Aug 15 11:32:26 EDT 2018 Position: +037 302423 / -080 553182 Altitude: 2157ft Datum: WGS-84 Azimuth/Bearing: 186° S06W 3307mils (True) Elevation Angle: -18.1° Horizon Angle: -05.6° Zoom: 1X 10890+00</p> 		<p>Date & Time: Wed Aug 15 12:47:05 EDT 2018 Position: +037 334534 / -080 594818 Altitude: 2339ft Datum: WGS-84 Azimuth/Bearing: 186° S06W 3307mils (True) Elevation Angle: -18.1° Horizon Angle: -05.6° Zoom: 1X 10890+00</p> 			
GPS Location	37.206027376058, -80.3942190023665	GPS Location	37.2060893057261, -80.393808139563		
Description	See photo for GPS location and station number. Mat placed in stream bed during bridge installation.	Description	See photo for GPS location and station number. Water breaker and end treatment.		
<p>Date & Time: Wed Aug 15 14:17:00 EDT 2018 Position: +037 336921 / -080 563807 Altitude: 2572ft Datum: WGS-84 Azimuth/Bearing: 276° N84W 4907mils (True) Elevation Angle: -18.4° Horizon Angle: -01.0° Zoom: 1X 10970+00</p> 		<p>Date & Time: Wed Aug 15 15:13:06 EDT 2018 Position: +037 326201 / -080 566740 Altitude: 2435ft Datum: WGS-84 Azimuth/Bearing: 142° S18E 3840mils (True) Elevation Angle: -07.8° Horizon Angle: -01.0° Zoom: 1X 10970+00</p> 			
GPS Location	37.2060511060272, -80.3942183005055	GPS Location	37.20605062392, -80.3942222908458		
Description	See photo for GPS location and station number. Triple stack 18" CFS.	Description	See photo for GPS location and station number. Mat removed from stream bed.		
<p>Date & Time: Wed Aug 15 16:34:36 EDT 2018 Position: +037 323503 / -080 555523 Altitude: 2387ft Datum: WGS-84 Azimuth/Bearing: 315° N31W 5336mils (True) Elevation Angle: -10.1° Horizon Angle: -01.0° Zoom: 1X 11015+75 S-RR5</p> 		<p>Date & Time: Wed Aug 15 16:39:00 EDT 2018 Position: +037 322651 / -080 553010 Altitude: 2410ft Datum: WGS-84 Azimuth/Bearing: 142° S18E 2880mils (True) Elevation Angle: -07.8° Horizon Angle: -01.0° Zoom: 1X 11018+75</p> 			
GPS Location	37.2060511261571, -80.3942182660852	GPS Location	37.2060511261571, -80.3942182660852		
Description	See photo for GPS location and station number. Priority one site fence used at stream as controls.	Description	See photo for GPS location and station number. Spoil pile stabilized.		