









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	7440
Inspector	Jared Saunders			Date/Time	9/6/2018 3:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10883+50
State	VA	Inspection Area	Partial	Station End	11237+00
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.2060109937874, -80.3941368298835			Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame
Broad-Based Dip		Acceptable			
Compost Filter Sock		Acceptable			
Erosion Control Blanket		Acceptable			
Rock Construction Entrance		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Sensitive Resource Buffer		Acceptable			
Waterbar		Acceptable			
Waterbar Outlet Protection		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300137	Date/Time	9/6/2018 3:59 PM	Report #	7440
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
VA SWPP inspection from MP 206 to MP 212.7. Since last inspection Precision Pipeline has conducted ECD maintenance, ECD upgrades, and stabilization of the ROW for areas that permits are voided in. Temporary stabilization is being executed using a helicopter to prevent damage to water bars.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	9/6/2018 3:59 PM	Report #	7440
Pictures					
<p>Date & Time: Thu Sep 6 16:14:16 EDT 2018 Position: +037.317581° / -080.552977° Altitude: 2220ft Datum: WGS-84 Azimuth/Bearing: 145.538E 2573mils (True) Elevation Angle: -12.4° Horizon Angle: -02.8° Zoom: 1X AR 244</p> 		<p>Date & Time: Thu Sep 6 10:29:26 EDT 2018 Position: +037.322778° / -080.552977° Altitude: 2397ft Datum: WGS-84 Azimuth/Bearing: 075° N76E 1351mils (True) Elevation Angle: -07.7° Horizon Angle: -09.1° Zoom: 1X 11025+50 S-U18</p> 			
GPS Location	37.205799139738, -80.3942227085516	GPS Location	37.2062246315528, -80.3942435794327		
Description	See photo for GPS location and station number. Broad base dip in place.	Description	See photo for GPS location and station number. Sensitive resource buffer zone.		
<p>Date & Time: Thu Sep 6 10:42:28 EDT 2018 Position: +037.337082° / -080.570994° Altitude: 2426ft Datum: WGS-84 Azimuth/Bearing: 129° 551E 2293mils (True) Elevation Angle: -13.3° Horizon Angle: -04.3° Zoom: 1X 10291+00</p> 		<p>Date & Time: Thu Sep 6 16:16:42 EDT 2018 Position: +037.334992° / -080.596699° Altitude: 2025ft Datum: WGS-84 Azimuth/Bearing: 149° 531E 2649mils (True) Elevation Angle: -02.5° Horizon Angle: -06.0° Zoom: 1X 10883+50</p> 			
GPS Location	37.2061674250636, -80.3942057770494	GPS Location	37.206185488065, -80.3942004964504		
Description	See photo for GPS location and station number. Triple stack 18" CFS in place.	Description	See photo for GPS location and station number. RCE in place at ROW crossing of Kow Camp Road.		
<p>Date & Time: Thu, Sep 06, 2018, 11:29:42 EDT Position: +037.311638° / -080.516294° Altitude: 1807ft Datum: WGS-84 Azimuth/Bearing: 302° N13W 6169mils (True) Elevation Angle: +31.6° Horizon Angle: +04.2° Zoom: 1X Arnold's seeding helicopter dropping pellets at AR-249 00</p> 		<p>Date & Time: Thu, Sep 06, 2018, 10:55:05 EDT Position: +037.312800° / -080.519950° Altitude: 2093ft Datum: WGS-84 Azimuth/Bearing: 180° S00W 3200mils (True) Elevation Angle: -27.3° Horizon Angle: -04.0° Zoom: 1X Gravel bar construction at station 1102+00. M-301 not up graded to triple lake</p> 			
GPS Location	37.206000270619, -80.3942771047753	GPS Location	37.2060543059912, -80.3942408564857		
Description	See photo for GPS location and station number. Helicopter temporarily stabilizing ROW.	Description	See photo for GPS location and station number. Temporary end treatment and waterbar.		