Mour Mour	nta V	ain alley		Visual Site Inspection Report							
Project Name H-600 Pipeline S		eline Spread G	1 G AFE 124300137			Spread	H-600 Pipeline Spread G				
Contractor Precision						Report #	4121				
Inspector Tim Bowen						Date/Time	7/6/2018 8:42 AM				
Permit #	Permit # TBD			Inspection Type VA SWPP			Station Beg	jin			
State	VA			Inspection Area	Full		Station End 10460+00				
County	Gile	es		Ground	Damp		Temperature (ºF			70.00	
Municipality	N/A	\		Weather	Cloudy		Rain Gauge (in) 0.			0.10	
GPS Location	37.	333966025	473, -80.7282	534410547		Rain Ad	Accumulation Time (days)			1.00	
Are the approved (stamped) E&S Plan a				and PCSM Plan present on site?						Yes	
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)									No		
 Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture 											
is required.) E&S BMPs			Compliance Level		Correc	rective Action			Corrective Time Frame		
Compost Filter So	ock			Acceptable							
Housekeeping			Acceptable								
Sensitive Resource Signage			Acceptable								
Sediment Filter Log			Acceptable								
Silt Fence (Filter Fabric Fence)			Acceptable								
Sump Pit			Acceptable								
Waterbar			Acceptable								
5. Site Conditi	ons	<u> </u>			1						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.											
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?								N/A			
Are slopes 3:1 a	ind	greater sta	abilized with a	ppropriate BMPs as	per E&S	plans?				N/A	
Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No		

MVP-34 REV 0 Page 1 of 3

AFE 124300137	Date/Time 7/6/20	8 8:42 AM	Report #	4121							
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a											
picture is required.) PCSM BMPs	Compliance	Corrective Ac	tion	Corrective							
1 35 2 3	Level	0011001110710		Time Frame							
7. Identify all remedial measures that have been taken since the previous inspection was conducted.											
Comments (Reference above questions as appropriate.)											
SWPPP Report for Giles County. No significan construction activities have occurred to Mystery minimize sedimentation during rainfall events.	t rainfall event has occurre Ridge Road or Pocahont No compliance issues wei	ed since the last Stormwar as Road with the exception re observed today.	er report was on of adding roo	completed. No ck to the road to							
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a											

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a

MVP-34 REV 0 Page 2 of 3

AFE 124300137 Date/Time 7/6/2018 8:42 AM Report # 4121 **Pictures GPS Location** 37.398504023475, -80.6821938046074 **GPS Location** 37.3985192366293, -80.6821829919523 Mystery Ridge Road - Condition of Road through the Rock Skullcap area. See photo for correct coordinates and details. Mystery Ridge Road - Water bar and end treatment working properly at station 10408+38. See photo for correct coordinates. Description Description No impact to wetland at station 12 **GPS Location** GPS Location 37.3985192366293, -80.6821829919523 37.3985192366293, -80.6821829919523 Pocahontas Road - Rock installed to reduce Pocahontas Road - No impact to wetland sedimentation during a rainfall runoff event. See photo for correct coordinates and details. W-UU11 at station 125+00. See photo for Description Description correct coordinates and details. GPS Location 37.3985192366293, -80.6821829919523 GPS Location 37.3985192366293, -80.6821829919523 Pocahontas Road - No impact to stream S-PP14 at station 264+65. See photo for Pocahontas Road - Check dams functioning properly at station 279+60. See photo for Description Description correct coordinates and details. correct coordinates and details.

MVP-34 REV 0 Page 3 of 3