Mountain Valley		Visual Site Inspection Report									
Project Name H-600 Pipe		line Spread G AFE 124300137			Spread	H-60	H-600 Pipeline Spread G				
Contractor Precision						Report #	6111				
Inspector Timothy Watson						Date/Time	8/9/	/2018 4:18	PM		
Permit #	TBD)		Inspection Type VA SWPP			Station Begin 11058+00				
State	VA			Inspection Area	Partial		Station End 10829+00				
County	Gile	s		Ground	Damp		Temperature (°F) 89.0			89.00	
Municipality	N/A			Weather	Sunny		Rain Gauge (in)			0.01	
GPS Location	37.3	21563372	6473, -80.663 ⁻	1414487772		Rain Ad	ccumulation Time (days) 1.0			1.00	
1. Are the appr	oved	l (stampe	d) E&S Plan	and PCSM Plan pres	sent on si	te?	Yes				
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)									No		
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes				
4. E&S BMPs (is required.)	(List	BMPs and	l note if insta	lled and maintained	as per th	e plan. If	corrective acti	ion i	is needed,	a picture	
E&S BMPs			Compliance Level		Corrective Action				Corrective Time Frame		
Compost Filter Sock			Acceptable	See c	See comments						
Housekeeping			Communication	See c	See comments						
Rock Construction Entrance			Acceptable	See c	See comments						
Culvert (Ditch Relief)			Communication	See c	See comments						
Sensitive Resource Buffer			Acceptable	See c	See comments						
Silt Fence (Reinforced Filter Fabric Fence)			Communication	See c	See comments						
5. Site Conditi	ons										
ls an unauthoriz beyond defined	ed d	s of distur	bance resulti	ment, gravel, oil, HE ng from earth disturl ironmental Permittin	bance act	ivity or ine	•			No	
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?										Yes	
Are slopes 3:1 a	and g	reater sta	abilized with a	appropriate BMPs as	per E&S	plans?				Yes	
			10 ///							.	

MVP-34 REV 0 Page 1 of 3

No

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

AFE 124300137	Date/Time 8/9/201	8 1·18 PM	Report #	6111								
			<u> </u>									
PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)												
PCSM BMPs	Compliance Level	Corrective A	ction	Corrective Time Frame								
	20101			Time Traine								
7. Identify all remedial measures that have been taken since the previous inspection was conducted.												
Comments (Reference above questions as	appropriate.)											
Attended am inspection meeting, checked crew	and area at access 234,0	off Rogers Rd, crew rewo	orking culvert pip	oes , ditch and								
grading road. Communication after heavy rains Access 235,236 ok off Rogers Rd ,no issues ch	ecked access 237 off Gra	vely Hill Rd. No issues M	lp _. 200.1	5.								
Checked Big Stony Creek back to Norcross Rd and access 238, no issues but some housekeeping issues near Norcross Rd crew removed after discussing. Checked yard 29 crew installing triple sock around area. Checked crew at Buffalo Anklets Rd working at												
stream replacing super silt fence and installed filter sock. Checked crew at wetland area crew installing side rails and filter sock around area, discussed completing all disturbance controls. Station , to Henderson Rd. We're clearing is stopped.												
Checked area from Kow Camp Rd 2 back to Kow Camp Rd 1 to station , discussed with Foreman some issues at Kow Camp Rd 2 installing additional j hooks at the end of super silt fence.												

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3

AFE 124300137 Date/Time 8/9/2018 4:18 PM Report # 6111 **Pictures** GPS Location |37.3612059232254, -81.0554140096447 **GPS Location** 37.3612513253813, -81.0563209746788 Stream 32 station 10698+15 in progress Backfilling super silt fence. Stream 32 repairing controls. Description Description **GPS Location** GPS Location 37.3610077891847, -81.0553819500665 37.3610262293717, -81.0552999750535 Bridge over stream 32 crew installed controls completed station 10698+15 Crew working on wet land area station 10790+50 Description Description GPS Location 37.3610493215149, -81.0549774394194 GPS Location 37.3610472679486, -81.0551068560044 Yard 29 in progress adding triple sock around Kow Camp Rd 2 super silt fence problem area crew to add a few hay breakers 10827+00 mp 206 Description Description

MVP-34 REV 0 Page 3 of 3