



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread H	AFE	124300138	Spread	H-600 Pipeline Spread H
Contractor	Precision			Report #	8701
Inspector	Dennis Evans			Date/Time	10/1/2018 3:10 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12993+15
State	VA	Inspection Area	Partial	Station End	13024+06
County	Roanoke	Ground	Wet	Temperature (°F)	74.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
GPS Location	37.2803382605734, -80.0287055922042			Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Straw Bale Barrier	Acceptable				
Temporary Diversion Berm	Acceptable				
Waterbar	Acceptable				
Waterbar Outlet Protection	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300138	Date/Time	10/1/2018 3:10 PM	Report #	8701
Pictures					
					
GPS Location	37.280745310269, -80.0286737793323	GPS Location	37.2801706195225, -80.0292444695533		
Description	Sta:#12993+15 W-B24-PSS is stabilized. See photo for accurate coordinates.	Description	Sta:#12994+02 HWY 221 ROW stabilized. See photo for accurate coordinates		
					
GPS Location	37.2801539814447, -80.0292510912568	GPS Location	37.2801591363151, -80.029291324392		
Description	Sta:#13009+00 Cattle drinking water pool. See photo for accurate coordinates.	Description	Sta:#13012+40 looking West onto the BRP. See photo for accurate coordinates.		
					
GPS Location	37.2800130816524, -80.029463237226	GPS Location	37.2799865110193, -80.0294728764147		
Description	Sta:#13021+00 Precision returning sediment to the ROW. See photo for accurate coordinates	Description	Sta:#13024+06 S-G24 down stream from the ROW. See photo for accurate coordinates.		