C Mour	nta V	ain alley		Vis	ual S	Sit	e In	specti	on Re	epc	ort		
Project Nar	ne	H-600 Pipe	line Spread	d H	Α	FE	12430	0138	Spre	ead	H-600	Pipeline	Spread H
Contractor Precision					· ·				Repo	ort #	1798		
Inspect	tor	Doug Dave	nport						Date/Ti	ime	5/14/2	2018 3:4	15 PM
Permit #	TBI	C		Inspection	Туре	VA	SWPP		Station	Beg	j <b>in</b> 13	3415+40	)
State	VA			Inspection	n Area	Par	rtial		Static	on Er	<b>nd</b> 13	3670+0	ט
County	Fra	nklin		G	Ground		Dry		Temperatur			ıre (ºF)	89.00
Municipality	-		We	Weather		Sunny		Rain Gauge (in)			0.00		
<b>GPS</b> Location	37.	0593992124	4712, -79.8	825864319652 Rain Ac				cumulation Time (days)				0.00	
1. Are the appr	ove	d (stamped	d) E&S Pla	an and PCSM P	lan pre	sen	t on sit	e?					Yes
			0	e of the limits of o al Permitting Coo						ings?	)		No
		•		the construction mental Permittin				•		•		being	Yes
4. E&S BMPs ( is required.)	(List	BMPs and	l note if in	stalled and mair	ntained	l as	per the	e plan. If c	corrective	e actio	on is I	needec	l, a picture
E&S BMPs			Compliance Level		Corrective Action					rectiv Fran	rame Date		
Compost Filter So	ock			Acceptable									
Silt Fence (Filter	Fabr	ic Fence)		Acceptable									
Silt Fence (Reinforced Filter Fabric Fence)			ric Fence)	Acceptable									
Rock Construction Entrance				Acceptable									
Housekeeping		Acceptable											
5. Site Conditi	ons	;											
Is an unauthoriz beyond defined a photo and imn	limi	ts of distur	bance res	sulting from earth	n distur	ban	ce acti	vity or ine	-				
Have inactive di	stur	bed areas	(stockpile	es, final grade) b	een sta	abiliz	zed pe	r state req	uirement	ts?			Yes
Are slopes 3:1 a	and	greater sta	bilized wit	th appropriate B	MPs as	s pe	r E&S	plans?					Yes
Has a new slip/s	slide	been obs	erved? (li	f yes, complete	Slide R	lepo	ort Forn	n)					No

<b>AFE</b> 124300138	Date/Tir	<b>me</b> 5/14/2018 3:45 PM	<b>Report #</b> 179	98				
6. PCSM BMPs (List BMPs and note if	installed and ma	intained as per the plan. If corre	ective action is ne	eded, a				
picture is required.)	Compliance		Corrective	Date				
PCSM BMPs	Level	Corrective Action	Time Frame	Repaired				
			1					
			1					
			1					
7. Identify all remedial measures that h	l ave been taken s	since the previous inspection wa	s conducted					
Comments (Reference above questions	s as appropriate.)	)						
SWPPP Inspection: Traveled from the kicko	SWPPP Inspection: Traveled from the kickoff of this Spread at Cahas Mtn. Rd. To the S. end of Spread-H.							
The contractor was preparing the site for the conventional road bore. The necessary controls for that area were installed and functional at the time of this inspection.								
As I traveled toward the beginning of Spread-I, Environmental crews were observed installing specified ECDS ahead of the grade crew. All of the ECDS were being installed correctly and were functional.								
The Temporary bridges that were installed over sensitive resources were compliant at the time of this inspection.								
Mechanical clearing crews were working as I conducted the inspection. They were piling logs and grubbing the ROW.								
The RCE's were installed as required and being maintained. In a few locations, timber mats were used in lieu of the stone entrances. In those instances, they were clean and functional.								
The paved roads in the area were clean at the time of this inspection.								
Note: It is a condition of National Polluta	-	-						
maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a								
weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required								
inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required								
as part of a permit condition this form may be used to meet those monitoring requirements.								

AFE 12430013	124300138 Date/Time			M Report # 1798		
Pictures						
GPS Location	37.0593983781329, -79.8825871		GPS Location	37.0593984833957, -79.882588091587		
Description	Temporary bridge over S-II9 @ 1	3543+00	Description	Soil stockpiles temporarily stabilized		
GPS Location	37.0593877450076, -79.8825957			37.0593985246522, -79.8825873015401		
Description	Clearing crews piled logs on the	LOD	Description	RCE Cahas Mtn. Rd. 1		
	Insert image here			Insert image here		
GPS Location			GPS Location			
Description			Description			