Mountain Valley				Visual Site Inspection Report									
Project Name H-600 Pipeline Sprea			Н	FE 12	FE 124300138		Sprea	Spread H-600 Pipeline S		e Sp	Spread H		
Contractor Precision								Report	ort # 4358				
Inspector Glenn Mike Renfro									Date/Tin	<b>e/Time</b> 7/9/2018 3:46 PM			PM
Permit # TBD			Inspection	Туре	VA SV	/PP		Station E	tion Begin 13425+00				
State	VA			Inspection	Area	Full Sta		Station	tion End 13670+00				
County	Fra	nklin		Gr	ound	Dry		Temperature (°F)				34.00	
Municipality	N/A	١	Weather Sunny Rain					ain	n Gauge (in)		0.00		
GPS Location	ocation 36.9715525640191, -79.8697769090376 Rain Accumulation Time (day						ime (days	s)	1.00				
Are the approved (stamped) E&S Plan				an and PCSM Pla	and PCSM Plan present on site?								Yes
				of the limits of d I Permitting Coo						gs?			No
followed? (If	No,	notify MV	P Environi	the construction mental Permitting stalled and main	g Coor	dinato	and	d explain i	in commer	its.)			Yes a picture
E&	&S I	BMPs		Compliance Level	Corrective Action					orrective ne Frame R		Date epaired	
Rock Construction	n Er	ntrance		Acceptable									
Compost Filter So	ock			Acceptable									
Silt Fence (Reinfo	Silt Fence (Reinforced Filter Fabric Fence)			Acceptable									
Silt Fence (Filter I	Fabı	ric Fence)		Acceptable									
Housekeeping				Acceptable									
5. Site Condition	ono												
			(euch as a	ediment, gravel,	Oil LIF	ال النار	d et	c ) occurr	ing to wate	re '	wetlands :	or l	
beyond defined	limi	ts of distu	bance res	lediment, gravel, ulting from earth Invironmental Pe	distur	bance	activ	vity or ine	-				No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?										Yes			
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?										Yes			
Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No				

MVP-34 REV 0 Page 1 of 3

<b>AFE</b> 124300138		Date/Ti	<b>me</b> 7/9/2018 3:46 PM	Report # 435	58				
<ol><li>PCSM BMPs (List BMPs and note if picture is required.)</li></ol>	f installed	and ma	aintained as per the plan. If c	orrective action is ne	eded, a				
PCSM BMPs	Compl Lev		Corrective Action	Corrective Time Frame	Date Repaired				
7. Identify all remedial measures that h	nave been	taken :	since the previous inspection	was conducted.					
Comments (Reference above question		•	<u>′</u>	The center	6				
Performed SWPPP inspection of Spread H. All ECD's were inspected and there were no issues observed. The contractor is continuing work on Punch List items and touching up waterbars in preparation for DEQ inspection. The contractor is also working on retrieving sediment from off right of way in various locations. The section is considered ready for DEQ inspection.									
Note: It is a condition of National Pollut		_							
maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required									

MVP-34 REV 0 Page 2 of 3

inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b> 124300138	8	<b>Date/Time</b> 7/9/2018 3:46 PM			Report #	4358			
Pictures									
	36.9714189733435, -79.8697780	)82514	GPS Location	l					
Description	Rebuilt waterbar at 13530+78		Description	Bridge crossing	S-IJ4 in good	I condition			
GPS Location	36.9715037632528, -79.8697119		GPS Location						
Description	Retrieving sediment off right of w owner permission	ay with land	Description	ECD reinstallati	on at 13472+	57			
	Insert image here			Insert ima	ge here				
<b>GPS Location</b>			GPS Location						
Description			Description						

MVP-34 REV 0 Page 3 of 3