





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G		<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G	
<b>Contractor</b>	Precision				<b>Report #</b>	9976	
<b>Inspector</b>	Clinton Banks				<b>Date/Time</b>	10/26/2018 4:43 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP		<b>Station Begin</b>	+28	
<b>State</b>	VA	<b>Inspection Area</b>	Full		<b>Station End</b>	+28	
<b>County</b>	Giles	<b>Ground</b>	Wet		<b>Temperature (°F)</b>	47.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain		<b>Rain Gauge (in)</b>	0.00	
<b>GPS Location</b>	37.3363111296258, -80.8085777456705			<b>Rain Accumulation Time (days)</b>	1.00		
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable					
Housekeeping		Acceptable					
Rock Construction Entrance		Acceptable					
Safety Fence		Acceptable					
<b>5. Site Conditions</b>							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 4:43 AM	<b>Report #</b>	9976
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted Weekly VA SWPP at LY 28 did not observed any Deficiencies At LY 28.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 4:43 AM	<b>Report #</b>	9976
<b>Pictures</b>					
 <p> Date &amp; Time: Fri, Oct 26, 2018 08:14:18 EDT  Position: +037°20'10.57" N, -080°48'30.99" W  Altitude: 189ft  Datum: WGS 84  Azimuth Bearing: 022° N22E 0391mils (True)  Elevation Angle: +26°  Horizon Angle: -01.2°  Zoom: 1X  Compost Filter Sock at LY 28 </p>		 <p> Date &amp; Time: Fri, Oct 26, 2018 08:15:41 EDT  Position: +037°20'21.71" N, -080°48'10.05" W  Altitude: 189ft  Datum: WGS 84  Azimuth Bearing: 106° S74E 188mils (True)  Elevation Angle: +27.6°  Horizon Angle: -03.5°  Zoom: 1X  Mats at LY 28 </p>			
<b>GPS Location</b>	37.3362709069972, -80.8086124342688	<b>GPS Location</b>	37.334140059573, -80.8028020151712		
<b>Description</b>	Compost Filter Sock at LY 28	<b>Description</b>	Mats at LY 28		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Description</b>		<b>Description</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Description</b>		<b>Description</b>			





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G	
<b>Contractor</b>	Precision			<b>Report #</b>	9977	
<b>Inspector</b>	Clinton Banks			<b>Date/Time</b>	10/26/2018 4:45 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	+26	
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	+26	
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	42.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00	
<b>GPS Location</b>	37.317816680332, -80.6590588298446			<b>Rain Accumulation Time (days)</b>	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Safety Fence		Acceptable				
Fuel Containment		Acceptable				
Rock Construction Entrance		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 4:45 AM	<b>Report #</b>	9977
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted Weekly VA SWPP at LY 26. All inspected ECD's are in good working condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	10/26/2018 4:45 AM	<b>Report #</b>	9977
<b>Pictures</b>					
 <p><small>Date &amp; Time: Fri, Oct 26, 2018, 06:36:31 EST Position: +03°19'4.17" / -080°38'32.77" Altitude: 1254ft Datum: WGS-84 Azimuth/Bearing: 330° NGS 320mils (True) Elevation Angle: +27.9 Horizon Angle: -01.2 Zoom: 1X Lower Parking Lot at LY 26</small></p>		 <p><small>Date &amp; Time: Fri, Oct 26, 2018, 06:44:08 EST Position: +03°19'7.51" / -080°38'30.22" Altitude: 1830ft Datum: WGS-84 Azimuth/Bearing: 000° NGS 140mils (True) Elevation Angle: +48.0° Horizon Angle: -04.3° Zoom: 1X Dumpsters at LY 26</small></p>			
<b>GPS Location</b>	37.3177850386475, -80.6590846461064	<b>GPS Location</b>	37.3187569622298, -80.6584288460022		
<b>Description</b>	Lower Parking Lot at LY 26	<b>Description</b>	Dumpsters at LY 26		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Description</b>		<b>Description</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Description</b>		<b>Description</b>			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	9978
<b>Inspector</b>	Clinton Banks			<b>Date/Time</b>	10/26/2018 4:46 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11436+00
<b>County</b>	Craig	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.3295696173211, -80.4201878328625			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Sump Pit	Acceptable				
Waterbar	Acceptable				
Rock Construction Entrance	Acceptable				
End Treatment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 4:46 AM	<b>Report #</b>	9978
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>While conducting Weekly VA SWPP went to Access Rd 258.02 Station 11524+16 arrived at Entrance for Access Rd observed that gate was open, travel to bridge also observed that the Waddles was not across bridge, went across bridge and observed tire tracks going toward ROW when arriving at ROW Company cleaning Porta Johns was on site. I asked about the Waddles at bridge if Waddles was across bridge when they arrived, they stated that they were not across bridge, the gate was also open. Wen finished conducting check on ROW, put back Waddles across bridge, also closed gate at Access Rd Station 11524+16 &amp; Highway 42. Travel to Stevers Gap Trail Station 11489+70. Waddles at bridge was also off. When finished with check, placed Waddles across bridge. Travel to Steel Acres Station 11471+52 Waddles was in place on bridge at Steel Acres. Went from Station 11524+16 M.P. 218.0 To 11436+00 M.P. 216.5.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	10/26/2018 4:46 AM	<b>Report #</b>	9978
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Oct 26, 2018, 07:50:09 EDT  Position: +037° 20' 3.42" / -080° 25' 50.80"  Altitude: 1860ft  Datum: WGS-84  Azimuth/Bearing: 334° N26W 5938mils (True)  Elevation Angle: +19.5°  Horizon Angle: -01.5°  Zoom: 1X  WaterBar &amp; EndTreatment Station 11527+00</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 10:06:15 EDT  Position: +037° 19' 59.95" / -080° 25' 45.80"  Altitude: 2039ft  Datum: WGS-84  Azimuth/Bearing: 304° N56W 5404mils (True)  Elevation Angle: +22.4°  Horizon Angle: -01.0°  Zoom: 1X  Waddles not put back at Access Rd &amp; Highway 42 by Contractor</p> 			
<b>GPS Location</b>	37.3295228882109, -80.4201148264859	<b>GPS Location</b>	37.3333374504348, -80.4295060784374		
<b>Description</b>	WaterBar & EndTreatment at Station 11527+00	<b>Description</b>	Waddles was not put back in placed at Access Rd 258.02 & Highway 42. Station for 258.02 11524+16		
<p>Date &amp; Time: Fri, Oct 26, 2018, 10:17:12 EDT  Position: +037° 19' 59.87" / -080° 25' 46.27"  Altitude: 1982ft  Datum: WGS-84  Azimuth/Bearing: 295° N65W 5244mils (True)  Elevation Angle: +23.2°  Horizon Angle: -02.3°  Zoom: 1X  Waddles back in place at Highway 42 &amp; Access Rd 258.02 Station 11524+16</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 10:21:29 EDT  Position: +037° 20' 3.50" / -080° 25' 50.61"  Altitude: 2057ft  Datum: WGS-84  Azimuth/Bearing: 062° N62E 1102mils (True)  Elevation Angle: +24.4°  Horizon Angle: -01.8°  Zoom: 1X  Gate at Highway 42 was left open</p> 			
<b>GPS Location</b>	37.3333577346404, -80.4295672663305	<b>GPS Location</b>	37.3338637501349, -80.4308110569421		
<b>Description</b>	Waddles back in Place at Highway 42 & Access Rd 258.02 Station 11524+16	<b>Description</b>	Gate at Highway 42 was left open		
<p>Date &amp; Time: Fri, Oct 26, 2018, 10:31:29 EDT  Position: +037° 19' 16.76" / -080° 26' 19.00"  Altitude: 2065ft  Datum: WGS-84  Azimuth/Bearing: 341° N19W 6062mils (True)  Elevation Angle: +23.8°  Horizon Angle: -03.3°  Zoom: 1X  Entrance to Stevers Gap Trail Station 11489+70</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 10:35:34 EDT  Position: +037° 20' 1.56" / -080° 25' 51.26"  Altitude: 2059ft  Datum: WGS-84  Azimuth/Bearing: 340° N20W 6044mils (True)  Elevation Angle: +26.0°  Horizon Angle: -03.9°  Zoom: 1X  Closed Gate at Highway 42</p> 			
<b>GPS Location</b>	37.3249328742151, -80.4313361831758	<b>GPS Location</b>	37.333898451214, -80.4308670480553		
<b>Description</b>	Entrance to Stevers Gap Trail Station 11489+70	<b>Description</b>	Closed Gate at Highway 42		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	9979
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	10/26/2018 6:27 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11237+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10931+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	41.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.2982767190981, -80.5026600268274			<b>Rain Accumulation Time (days)</b>	6.00

- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)  |     |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Problem Area	Reseed for stabilization	48 Hours	

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 6:27 AM	<b>Report #</b>	9979
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Sta#10930+00- P1 silt fence has been repaired.					
<b>Comments</b> (Reference above questions as appropriate.) Inspection area: Sta#11237+00 to 10931+00- MP- 212.7 to 206.2 Steady rain fall this a.m. Checking row between AR-25 to AR 249.01- row in this area has good growth & ECD's are in good condition. AR- 249.02- ECD's, rock, maintained. AR-249.01- Access rd rock, controls, broad base dips, maintained. Sta#11068+00 to 11062+00- ECD's in good condition, row growth- 0%. AR-245.01- access road rock, controls, in good condition. AR-244- Mat bridge over stream S-IJ-18, clean controls in place. AR-244- access rd rock, controls, broad base dips in good condition. Sta#11022+00- extra work space that was reseeded is showing growth. Sta#10930+55- P1 that had washed out has been repaired. Contractor has rained out, no crews working on row.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



A/E	124300137	Date/Time	10/26/2018 6:27 AM	Report #	9979
Pictures					
<div><div><div>Date &amp; Time: Fri, Oct 26, 2018, 09:03:22 EDT Position: +037.3013527°N -080.501367°W Altitude: 2102ft Datum: WGS-84 Azimuth/Gearing: 030° N76W 5049mils (True) Elevation Angle: +06.2° Horizon Angle: +02.4° Zoom: 2X Sta#11227+00- row growth in this area is good. ECD's in good condition.</div><div></div></div></div>		<div><div><div>Date &amp; Time: Fri, Oct 26, 2018, 09:11:32 EDT Position: +037.306753°N -080.512570°W Altitude: 1908ft Datum: WGS-84 Azimuth/Gearing: 030° N30E 0533mils (True) Elevation Angle: +02.0° Horizon Angle: +00.0° Zoom: 1X AR-249.02- Rock check downs in bar ditch along access rd. clean &amp; maintained.</div><div></div></div></div>			
GPS Location	37.3013061331932, -80.5013617035751	GPS Location	37.3069406580527, -80.5125765223806		
Description	Sta#11227+00- row at sta#11227+00	Description	AR- 249.02- Rock check downs along access rd bar ditch.		
<div><div><div>Date &amp; Time: Fri, Oct 26, 2018, 09:41:43 EDT Position: +037.315362°N -080.54411°W Altitude: 2044ft Datum: WGS-84 Azimuth/Gearing: 088° N88E 0600mils (True) Elevation Angle: +15.2° Horizon Angle: +02.6° Zoom: 1X Sta#11064+00 to 11068+00- ECD's in good condition. 0% row growth 0% row.</div><div></div></div></div>		<div><div><div>Date &amp; Time: Fri, Oct 26, 2018, 09:41:43 EDT Position: +037.315144°N -080.54421°W Altitude: 2044ft Datum: WGS-84 Azimuth: +109° +1938mils Elevation Angle: +43.9° Horizon Angle: +10.0° Zoom: 2X AR-245.01- Access rd rock, controls. broad based base in good repair.</div><div></div></div></div>			
GPS Location	37.3151822481652, -80.5442270078515	GPS Location	37.3151349742313, -80.5442139320826		
Description	Sta#11064+00 to 11065+00- ECD's in good condition, 0% row growth .	Description	AR-245.01- access rd rock, controls in good condition.		
<div><div><div>Date &amp; Time: Fri, Oct 26, 2018, 10:04:00 EDT Position: +037.322267°N -080.553099°W Altitude: 2349ft Datum: WGS-84 Azimuth/Gearing: 0327mils Elevation Angle: +55.8° Horizon Angle: +09.7° Zoom: 1X Sta#11022+00- extra work space at row-reseeded area showing growth.</div><div></div></div></div>		<div><div><div>Date &amp; Time: Fri, Oct 26, 2018, 10:29:21 EDT Position: +037.331194°N -080.582802°W Altitude: 2135ft Datum: WGS-84 Azimuth: +085° +0800mils Elevation Angle: +65.3° Horizon Angle: +11.3° Zoom: 1X Sta#10930+55- Contractor has keyed in P1. Station has been built at Doe Creek Rd?</div><div></div></div></div>			
GPS Location	37.3219509283428, -80.5530771241342	GPS Location	37.3312076926579, -80.5828601215785		
Description	Sta#11022+00- AR-244- extra work space, reseeded area showing growth.	Description	Sta#10930+55- contractor has repaired P1, at Doe Creek .		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	9988
<b>Inspector</b>	Timothy Watson			<b>Date/Time</b>	10/26/2018 8:39 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10502+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10873+50
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.3492333107044, -80.6528187543905			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Housekeeping	Acceptable				
Sediment Filter Log	Acceptable				
Sump Pit	Acceptable				
Waterbar Outlet Protection	Acceptable				
Compost Filter Sock	Communication	Buffalo Anklets missing filter sock	24 Hours		
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No





<b>AFE</b>	124300137	<b>Date/Time</b>	10/26/2018 8:39 AM	<b>Report #</b>	9988
<b>Pictures</b>					
					
<b>GPS Location</b>	37.3491494916727, -80.6528347638255	<b>GPS Location</b>	37.3506958689888, -80.6504010782397		
<b>Description</b>	Stream S G 32 fiber in place no washing	<b>Description</b>	Buffalo Anklets 241.02 missing 2' of filter sock location		
					
<b>GPS Location</b>	37.3706446308991, -80.6819560938335	<b>GPS Location</b>	37.3337481122415, -80.7502498730787		
<b>Description</b>	Access 235 no issues off Roger Rd	<b>Description</b>	Kow camp 2 Checked were crew cut super silt fence		
					
<b>GPS Location</b>	37.3337533378797, -80.7502476950833	<b>GPS Location</b>	37.3337447152655, -80.7502512889053		
<b>Description</b>	Norcross rd all mats removed area seeded and mulched	<b>Description</b>	Access 240 checked area that had material picked up all clear		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	9990
<b>Inspector</b>	Brian Shields			<b>Date/Time</b>	10/26/2018 9:23 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11618+91
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11553+66
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	49.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.3141967458998, -80.4064750392739			<b>Rain Accumulation Time (days)</b>	1.00







- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)  |     |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Problem Area	Reinstall Waterbars	Immediate	
Waterbar Outlet Protection	Acceptable			
Slope Drain	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 9:23 AM	<b>Report #</b>	9990
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended morning management and inspection meeting Communicated with spread EIs Precision has rained out today, no crews are on site. EIs to conduct VA SWPPP inspection.  Conducted VA SWPPP inspection MP 219.9 to 218.6, Craig creek private area and sinking creek mountain. Active rain event during time of inspection.  Notified Rob Robertson and Mike Perry that the first two waterbars above Craig creek road crossing have not been reinstalled. Mike Perry to deploy Randy Biddle to install.  All inspected ECDs appear to be in good working condition, ECDs to be inspected again tomorrow 10/27/18 after rain event to evaluate effectiveness/failures.  No stream impacts have been observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	10/26/2018 9:23 AM	Report #	9990
Pictures					
<p>Date &amp; Time: Fri, Oct 26, 2018 09:08:52 EDT Position: +037.314621 / -080.406777 Altitude: 1972ft Datum: WGS-84 Azimuth/Bearing: 161° S19E 2862mils (True) Elevation Angle: -17.8° Horizon Angle: -00.8° Zoom: 1X waterbar not put back to spec at end of day 11/5/2017</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018 09:13:01 EDT Position: +037.314567 / -080.406597 Altitude: 2038ft Datum: WGS-84 Azimuth/Bearing: 298° N50W 5049mils (True) Elevation Angle: -28.3° Horizon Angle: -07.3° Zoom: 1X s-pp20</p> 			
GPS Location	37.3143402859916, -80.4066238180552	GPS Location	37.3143402859916, -80.4066238180552		
Description	Waterbars above Craig creek access rd not reinstalled.	Description	Stream s-pp20 no impacts observed.		
<p>Date &amp; Time: Fri, Oct 26, 2018 09:13:14 EDT Position: +037.316553 / -080.408610 Altitude: 2031ft Datum: WGS-84 Azimuth/Bearing: 249° S69W 4427mils (True) Elevation Angle: -20.4° Horizon Angle: -06.2° Zoom: 1X s-pp20</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018 09:18:26 EDT Position: +037.316614 / -080.408623 Altitude: 2031ft Datum: WGS-84 Azimuth/Bearing: 003° N03E 4063mils (True) Elevation Angle: -17.7° Horizon Angle: -02.6° Zoom: 1X s-pp20</p> 			
GPS Location	37.3144318163742, -80.4065476265553	GPS Location	37.3144318163742, -80.4065476265553		
Description	Stream s-pp20 no impacts observed.	Description	Stream s-pp21 no impacts observed.		
<p>Date &amp; Time: Fri, Oct 26, 2018 09:14:18 EDT Position: +037.317127 / -080.409179 Altitude: 2026ft Datum: WGS-84 Azimuth/Bearing: 275° N87W 4859mils (True) Elevation Angle: -23.2° Horizon Angle: -08.6° Zoom: 1X s-pp21</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018 09:20:40 EDT Position: +037.289238 / -080.423070 Altitude: 2020ft Datum: WGS-84 Azimuth/Bearing: 243° S63W 4571mils (True) Elevation Angle: -02.8° Horizon Angle: -02.1° Zoom: 1X equipment parked in waterbar</p> 			
GPS Location	37.3144318163742, -80.4065476265553	GPS Location	37.314387685654, -80.4065751191977		
Description	Stream s-pp21 no impacts observed.	Description	Hydroseeding truck parked within throat of waterbar. Mike Perry and Rob Robertson notified.		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	9997
<b>Inspector</b>	Trey Ingram			<b>Date/Time</b>	10/26/2018 1:45 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11766+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.3337633648699, -80.7502472207093			<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Communication		24 Hours	
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Filter Outlet	Acceptable			
Waterbar Outlet Protection	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 1:45 PM	<b>Report #</b>	9997
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection done from 12005+00 to 11766+00 MP227.2 to MP222.7. AR266 and AR266.03 inspection done during active rain event. Checked all P1, filter sock, RCEs, RFO, RCOs, and all other BMPs in area of inspection. Observed no issues with conditions of controls. 1 item was observed and added to punch list. 11788+00- trash observed on row down stream side of Mt. Tabor rd.  No crews worked due to active rain event.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



A/E	124300137	Date/Time	10/26/2018 1:45 PM	Report #	9997
Pictures					
<p>Date &amp; Time: Fri, Oct 26, 2018, 08:54:30 EDT Position: +037.241975 / -080.367928 Altitude: 2134ft Datum: WGS-84 Azimuth/Bearing: 331° N29W 5884mils (True) Elevation Angle: -05.5° Horizon Angle: -02.3° Zoom: 1X 11969+00</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 08:57:10 EDT Position: +037.241975 / -080.367928 Altitude: 2134ft Datum: WGS-84 Azimuth/Bearing: 331° N10W 6222mils (True) Elevation Angle: -05.4° Horizon Angle: -00.7° Zoom: 1X 11979+00</p> 			
GPS Location	37.3337692731212, -80.7502446764309	GPS Location	37.3337685447796, -80.7502449966479		
Description	Row 11969+00	Description	ECDs protecting karst feature 11979+00		
<p>Date &amp; Time: Fri, Oct 26, 2018, 09:06:40 EDT Position: +037.245957 / -080.360366 Altitude: 1637ft Datum: WGS-84 Azimuth/Bearing: 165° S15E 2933mils (True) Elevation Angle: -17.9° Horizon Angle: -01.3° Zoom: 1X 11779+00</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 09:10:31 EDT Position: +037.296032 / -080.361004 Altitude: 2148ft Datum: WGS-84 Azimuth/Bearing: 331° N29W 5884mils (True) Elevation Angle: -12.4° Horizon Angle: -00.7° Zoom: 1X 11788+00</p> 			
GPS Location	37.3337671883732, -80.7502455929951	GPS Location	37.3337678292928, -80.7502453112133		
Description	CFS 11979+00	Description	RCE 11788+00		
<p>Date &amp; Time: Fri, Oct 26, 2018, 09:17:43 EDT Position: +037.295957 / -080.360366 Altitude: 2052ft Datum: WGS-84 Azimuth/Bearing: 041° N41E 0729mils (True) Elevation Angle: -21.7° Horizon Angle: -00.4° Zoom: 1X 11788+00</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 09:18:59 EDT Position: +037.296032 / -080.361004 Altitude: 2148ft Datum: WGS-84 Azimuth/Bearing: 295° N46W 5227mils (True) Elevation Angle: -15.1° Horizon Angle: -01.0° Zoom: 1X 11788+00</p> 			
GPS Location	37.3337684066413, -80.7502450573808	GPS Location	37.3337418819765, -80.7502567190091		
Description	Super silt fence protecting karst feature 11788+00	Description	Trash observed on row 11788+00		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	9998
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	10/26/2018 2:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11780+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.2060601657339, -80.3942936679589			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Stone Inlet Protection	Acceptable				
Waterbar Outlet Protection	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 2:18 PM	<b>Report #</b>	9998
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
VA SWPPP inspection from MP 221 to MP 223. Since last VA SWPPP inspection Precision Pipeline has conducted work on ECD maintenance, ECD upgrades, trenching, welding of pipe, and coating of pipe. Due to on going rain event and safety concerns inspection of the entire ROW wasn't possible. Post rain event inspection will be conducted tomorrow once rain event is complete. No crew worked in the section today.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	10/26/2018 2:18 PM	Report #	9998
Pictures					
<p>Date &amp; Time: Fri Oct 26 10:04:00 EDT 2018 Position: +037.293070 / -080.360232 Altitude: 2111ft Datum: WGS-84 Azimuth/Bearing: 074° N74E 1316mils (True) Elevation Angle: -13.8° Horizon Angle: -00.6° Zoom: 1X 11768+00</p> 		<p>Date &amp; Time: Fri Oct 26 10:07:10 EDT 2018 Position: +037.293070 / -080.360232 Altitude: 2111ft Datum: WGS-84 Azimuth/Bearing: 186° S06W 3307mils (True) Elevation Angle: -21.3° Horizon Angle: -00.4° Zoom: 1X 11770+00</p> 			
GPS Location	37.2060370627039, -80.3942745548385	GPS Location	37.2059854268643, -80.3942539313744		
Description	See photo for GPS location and station number. RCE in place at main line valve 26 location.	Description	See photo for GPS location and station number. Water bar, sump pit, and end treatment in place.		
<p>Date &amp; Time: Fri Oct 26 10:09:48 EDT 2018 Position: +037.293070 / -080.360232 Altitude: 2111ft Datum: WGS-84 Azimuth/Bearing: 076° N76E 1354mils (True) Elevation Angle: -06.6° Horizon Angle: +02.5° Zoom: 1X 11768+25 S-IJ52</p> 		<p>Date &amp; Time: Fri Oct 26 10:09:58 EDT 2018 Position: +037.293070 / -080.360232 Altitude: 2111ft Datum: WGS-84 Azimuth/Bearing: 060° N60E 1067mils (True) Elevation Angle: -00.1° Horizon Angle: +00.7° Zoom: 1X 11770+00</p> 			
GPS Location	37.2059261851043, -80.3942485537541	GPS Location	37.2059274366538, -80.3942713336077		
Description	See photo for GPS location and station number. Buffer zone and sings in place at stream.	Description	See photo for GPS location and station number. Trenching completed.		
<p>Date &amp; Time: Fri Oct 26 10:10:55 EDT 2018 Position: +037.293070 / -080.360232 Altitude: 2111ft Datum: WGS-84 Azimuth/Bearing: 170° S10E 3022mils (True) Elevation Angle: -28.6° Horizon Angle: -00.4° Zoom: 1X 11774+50</p> 		Insert image here			
GPS Location	37.2060224663287, -80.3942574094108	GPS Location			
Description	See photo for GPS location and station number. Reinforced super silt fence along fill slope.	Description			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10000
<b>Inspector</b>	Timothy Watson			<b>Date/Time</b>	10/26/2018 2:42 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10873+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.3337485045779, -80.7502497095566			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock					
Silt Fence (Reinforced Filter Fabric Fence)					
Rock Construction Entrance					
Housekeeping					
Silt Fence (Filter Fabric Fence)	Communication	Land owner removed	24 Hours		
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 2:42 PM	<b>Report #</b>	10000
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
spread 9 Checked Kow Camp Rd 1 and Dow Creek Rd area 10873+00 to 10929+00 Mp 206.9 10929+50 Dow Creek Rd no issues checked super silt fence in ATWS ok. Checked stream S Y3 bridge near Dow Creek checked problem area at 10926+15 no Issues, Checked area between 10826+50 were land owner removed p1 silt fence to pass thru added to punch list yesterday.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	10/26/2018 2:42 PM	<b>Report #</b>	10000
<b>Pictures</b>					
					
<b>GPS Location</b>	37.3337493178953, -80.7502493705738	<b>GPS Location</b>	37.3337508382047, -80.7502487369236		
<b>Description</b>	Kow Camp Rd looking south toward Dow Creek Rd slow or no growth	<b>Description</b>	Kow Camp Rd 1 area stabilized no growth		
					
<b>GPS Location</b>	37.3337152714361, -80.7502826790315	<b>GPS Location</b>	37.3337191801454, -80.7502800728604		
<b>Description</b>	Dow Creek Rd ATWS checked sock and super silt ok	<b>Description</b>	Dow Creek area where land was passed through a row and removed silt fence		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Description</b>		<b>Description</b>			









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10001
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	10/26/2018 3:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10458+91
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10459+03
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	41.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.25
<b>GPS Location</b>	37.1330415644097, -80.3943810426448			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock		Acceptable			
Waterbar		Acceptable			
Waterbar Outlet Protection		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 3:12 PM	<b>Report #</b>	10001
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted a routine VADEQ SWPPP inspection on Mystery Ridge and Pocahontas access roads. Light rainfall occurred periodically during the inspection. No resource impact to wetlands and streams adjacent to or crossed by the roadways was located. ECDs installed for control of sediment at temporary water bars are functional with no maintenance needs apparent. Pocahontas Road should be graded with a crown and gravel added in a few areas. ECDs could then be removed. Traffic on the road is limited to security and environmental personnel for the MVP project. No construction activity. There could also be some light Forest Service traffic. Repaired damaged signage.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



A/E	124300137	Date/Time	10/26/2018 3:12 PM	Report #	10001
Pictures					
<p>Date &amp; Time: Fri, Oct 26, 2018, 09:30:49 EDT Position: +037°23'50.92"N -080°40'54.93"W Altitude: 3195ft Datum: WGS-84 Azimuth/Bearing: 325° N35W 576mils (True) Elevation Grade: +04% Horizon Grade: +00% Zoom: 1X Mystery Ridge Road, 10215+03, ECD functional.</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 09:35:00 EDT Position: +037°23'24.46"N -080°40'46.05"W Altitude: 3238ft Datum: WGS-84 Azimuth/Bearing: 311° S18E 2880mils (True) Elevation Grade: +03% Horizon Grade: +00% Zoom: 1X Mystery Ridge Road, 10442+03, ECD functional.</p> 			
GPS Location	37.1331241680655, -80.3943795339022	GPS Location	37.1331241680655, -80.3943795339022		
Description	Correct coordinates on photo. Mystery Ridge Road controls functional.	Description	Correct coordinates on photo. Mystery Ridge Road controls functional.		
<p>Date &amp; Time: Fri, Oct 26, 2018, 10:07:33 EDT Position: +037°24'57.65"N -080°42'11.55"W Altitude: 3042ft Datum: WGS-84 Azimuth/Bearing: 165° S25E 276mils (True) Elevation Grade: +047% Horizon Grade: +007% Zoom: 1X Pocahontas Road, 165+50, ECD functional.</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 10:07:33 EDT Position: +037°24'53.06"N -080°42'45.01"W Altitude: 3023ft Datum: WGS-84 Azimuth/Bearing: 224° S44W 3983mils (True) Elevation Grade: +037% Horizon Grade: +009% Zoom: 1X Pocahontas Road, 160+25, ECD functional.</p> 			
GPS Location	37.1330161253336, -80.3945991397653	GPS Location	37.1330161253336, -80.3945991397653		
Description	Correct coordinates on photo. Pocahontas Road controls functional.	Description	Correct coordinates on photo. Pocahontas Road controls functional.		
<p>Date &amp; Time: Fri, Oct 26, 2018, 10:12:46 EDT Position: +037°22'51.86"N -080°43'9.09"W Altitude: 2801ft Datum: WGS-84 Azimuth/Bearing: 343° N17W 6098mils (True) Elevation Grade: +037% Horizon Grade: +009% Zoom: 1X Pocahontas Road, 132+00, ECD functional.</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 10:22:55 EDT Position: +037°22'35.31"N -080°43'30.38"W Altitude: 2588ft Datum: WGS-84 Azimuth/Bearing: 216° S36W 3840mils (True) Elevation Grade: +023% Horizon Grade: +006% Zoom: 1X Pocahontas Road, 106+00, ECD functional.</p> 			
GPS Location	37.1330161253336, -80.3945991397653	GPS Location	37.1330161253336, -80.3945991397653		
Description	Correct coordinates on photo. Pocahontas Road controls functional.	Description	Correct coordinates on photo. Pocahontas Road controls functional.		




# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10005
<b>Inspector</b>	Timothy Watson			<b>Date/Time</b>	10/26/2018 3:09 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10692+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10692+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.3337320911006, -80.75025653763			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Housekeeping	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 3:09 PM	<b>Report #</b>	10005
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
spread 8 Yard 29 off Big Stony Creek Rd. Off access 238 station 10602+18 Mp 205.6 Checked perimeter of yard no issues. Checked 18" triple sock acceptable in area. Rock in yard acceptable.Observed Arnold's seeding using yard all equipment and material stored acceptable. Observed pipe and hay bales stocked piled. No Issues					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 3:09 PM	<b>Report #</b>	10005
<b>Pictures</b>					
 <p> Date &amp; Time: Fri, Oct 26, 2018, 09:08:39 EDT  Position: +43.736283° / -80.637700°  Altitude: 1700ft  Datum: WGS-84  Azimuth/Bearing: 241° 55'W 3761mils (True)  Elevation Angle: -01.5°  Horizon Angle: +01.5°  Zoom: 1X  yard 29 </p>		 <p> Date &amp; Time: Fri, Oct 26, 2018, 09:08:39 EDT  Position: +43.736283° / -80.637700°  Altitude: 1700ft  Datum: WGS-84  Azimuth/Bearing: 242° 54'W 4302mils (True)  Elevation Angle: -02.0°  Horizon Angle: +00.5°  Zoom: 1X  yard 29 </p>			
<b>GPS Location</b>	37.3336597908297, -80.7503098370506	<b>GPS Location</b>	37.3330738814895, -80.7502078358836		
<b>Description</b>	Yard 29 between to lots	<b>Description</b>	Yard 29 area near were Arnold's store material		
 <p> Date &amp; Time: Fri, Oct 26, 2018, 09:08:39 EDT  Position: +43.736283° / -80.637700°  Altitude: 1700ft  Datum: WGS-84  Azimuth/Bearing: 101° 55'W 1996mils (True)  Elevation Angle: +00.5°  Horizon Angle: +00.5°  Zoom: 1X  yard 29 </p>		<div style="text-align: center;">Insert image here</div>			
<b>GPS Location</b>	37.3327960213994, -80.7504062355317	<b>GPS Location</b>			
<b>Description</b>	Yard 29 area pipe and hay bails stored	<b>Description</b>			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Description</b>		<b>Description</b>			









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	10006
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	10/26/2018 1:44 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11266+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11434+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
<b>GPS Location</b>	37.2429972104219, -80.4292908575056			<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Waterbar Outlet Protection	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>AFE</b>	124300137	<b>Date/Time</b>	10/26/2018 1:44 PM	<b>Report #</b>	10006
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Contractor did not work today due to rain event. Performed SWPP from MP 213 - Mp 216 checking controls nad ROw conditions No. Streams are being impacted and did not observe any damage ECD's or missing ECD's No environmental concerns to report at this time Since last SWPP crews have retrieved sediment from S-NN12 and ATwS 633 as well as seeding and stabilizing ROW					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	10/26/2018 1:44 PM	<b>Report #</b>	10006
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Oct 26, 2018, 09:00:44 EDT  Position: +037°18'23.80" / -080°28'0.96"  Altitude: 2027ft  Datum: WGS-84  Azimuth/Bearing: 234° 25.63' 2.14mils (True)  Elevation Angle: -01.2°  Horizon Angle: -03.1°  Zoom: 1X  SKN 12</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 09:00:20 EDT  Position: +037°18'23.80" / -080°28'0.96"  Altitude: 1987ft  Datum: WGS-84  Azimuth/Bearing: 007° N07E 0124mils (True)  Elevation Angle: -10.0°  Horizon Angle: +01.2°  Zoom: 2X  SKL 43</p> 		<p><b>GPS Location</b> 37.2426994471226, -80.4292635899786</p> <p><b>Description</b> ECD's and ROW conditions @ S-NN11</p>	
<p>Date &amp; Time: Fri, Oct 26, 2018, 09:12:59 EDT  Position: +037°18'24.03" / -080°28'20.57"  Altitude: 2133ft  Datum: WGS-84  Azimuth/Bearing: 250° 57'0W 444mils (True)  Elevation Angle: -01.2°  Horizon Angle: -00.6°  Zoom: 1X  Snn12</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 09:12:00 EDT  Position: +037°18'23.38" / -080°28'17.96"  Altitude: 2157ft  Datum: WGS-84  Azimuth/Bearing: 221° S41W 3929mils (True)  Elevation Angle: -22.2°  Horizon Angle: -00.0°  Zoom: 1X  11329</p> 		<p><b>GPS Location</b> 37.2427522112031, -80.4293075111512</p> <p><b>Description</b> ECD's and ROW conditions @ S-Nn12</p>	
<p>Date &amp; Time: Fri, Oct 26, 2018, 09:17:06 EDT  Position: +037°18'24.91" / -080°28'16.81"  Altitude: 2200ft  Datum: WGS-84  Azimuth/Bearing: 274° N86W 4871mils (True)  Elevation Angle: -14.4°  Horizon Angle: +05.4°  Zoom: 1X  AtwS 633</p> 		<p>Date &amp; Time: Fri, Oct 26, 2018, 09:16:40 EDT  Position: +037°18'15.15" / -080°28'50.00"  Altitude: 2149ft  Datum: WGS-84  Azimuth/Bearing: 260° S47W 5401mils (True)  Elevation Angle: +10.0°  Horizon Angle: +03.5°  Zoom: 1X  AR 256.02</p> 		<p><b>GPS Location</b> 37.2427522112031, -80.4293075111512</p> <p><b>Description</b> Rock lined channel @ ATwS 633</p>	
<p><b>GPS Location</b> 37.2427522112031, -80.4293075111512</p> <p><b>Description</b> ECD's for KARST feature @ AR 256.02</p>		<p><b>GPS Location</b> 37.2427522112031, -80.4293075111512</p> <p><b>Description</b> Water bar and end treatment @ 11329+00</p>		<p><b>GPS Location</b> 37.2427522112031, -80.4293075111512</p> <p><b>Description</b> Rock lined channel @ ATwS 633</p>	