Certification Statement

I certify under penalty of law that I have read and understand this document and that this document and all attachments were prepared in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Inspector's Name (printed):	mike	Rento
-----------------------------	------	-------


Inspector's Signature:

Date: 9-18-18

Spread H section Report# 8046 SWIN 1369

Droject Nam	O H 600 Dinalina Co	411		EE 40400	0420		proad	H-600 Pipeli	o Cara	4 L
	ne H-600 Pipeline Sprea	d H	A	FE 12430	0138	-			ie Sprea	ан
	or Precision					<u> </u>	oort #		1.01 DN	1
	or Glenn Mike Renfro	T				+		9/18/2018		/1
	TBD	Inspection				-		in 13415-		
State	VA	Inspection		Full		Sta		13670+		-
County				Muddy				erature (°	_	_
Municipality			eather	Cloudy		L		Gauge (i	_	
	37.0136710729221, -79.					ccumul	ation	ime (day		_
	oved (stamped) E&S P									Yes
Are there ac (If yes, notify	tivities occurring outside the MVP Environment	e of the limits of c al Permitting Coc	disturba ordinato	ance snow or and exp	n on the p lain in cor	nments.	wings : .)			No
3. Is Construct	ion sequence outlined in	n the construction	notes	of the E&	S plan se	t or PCS	5M plar	set being	-,	/es
	No, notify MVP Environ				-	-		n is nood	nd 2 n	ictu
4. E&S BMPS is required.)	(List BMPs and note if i	nstalled and mail	ntained	as per the	e pian. Ir	correcti	ve actio	II is fleede	u, a pi	Ctu
	&S BMPs	Compliance Level		Correctiv	ve Action			rective Frame	Dat Repa	
Compost Filter S	ock	Communication	Mainte	nance need	led					
Housekeeping		Acceptable								
Rock Construction	on Entrance	Communication	Mainter	nance need	led	a e-i in e depen				
Silt Fence (Filter	Fabric Fence)	Communication	Mainter	nance need	led	7-5-04		- 72 by		
Silt Fence (Reinfo	orced Filter Fabric Fence)	Communication	Mainter	nance need	led	the se	har yes	by a ter	1.750	
Waterbar		Communication	Mainter	nance need	ed	yr.l			ā	
					11.75					
5. Site Condition										_
evond defined I	ed discharge (such as s imits of disturbance res rediately contact MVP E	ulting from earth	disturb	pance acti	vity or ine	ing to w ffective	vaters, BMP?	wetlands, If yes, ta	or	No
	turbed areas (stockpile					quireme	nts?	101 80 TO		Yes
re slopes 3:1 ar	nd greater stabilized wit	h appropriate BN	1Ps as	per E&S	plans?					Yes
		yes, complete S							_	

AFE 124300138	Date/Time	9/18/2018 1:01 PM	Report # 804	46
 PCSM BMPs (List BMPs and no picture is required.) 	ote if installed and main	tained as per the plan. If co	rrective action is ne	eded, a
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
			1	
4				
	1 1 1 1			
		Egendalon at		
. Identify all remedial measures	that have been taken sin	so the provious inspection w	vas conducted	
omments (Reference above que	stions as appropriate.)			
Comments (Reference above que Performed SWPPP inspection on the aspection. All perimeter ECD's were in eed to be refreshed with new rock. The acceptance to the contract of the contract the contract of the contract of	Spread H section. This sec nspected and multiple issu	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the spection. All perimeter ECD's were in spection to be refreshed with new rock. The second to be refreshed with new rock.	Spread H section. This sec nspected and multiple issu	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the spection. All perimeter ECD's were in spection.	Spread H section. This sec nspected and multiple issu	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the spection. All perimeter ECD's were in seed to be refreshed with new rock. The seed to be refreshed with new rock.	Spread H section. This sec nspected and multiple issu	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the spection. All perimeter ECD's were in the perimeter.	Spread H section. This sec nspected and multiple issu	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the spection. All perimeter ECD's were in spection to he refreshed with new rock. The second to he refreshed with new rock.	Spread H section. This sec nspected and multiple issu	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the spection. All perimeter ECD's were in spection to he refreshed with new rock. The second to he refreshed with new rock.	Spread H section. This sec nspected and multiple issu	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the spection. All perimeter ECD's were in seed to be refreshed with new rock. The seed to be refreshed with new rock.	Spread H section. This sec nspected and multiple issu	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the espection. All perimeter ECD's were in seed to be refreshed with new rock. T	Spread H section. This sec nspected and multiple issu here are also multiple wate	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
Performed SWPPP inspection on the	Spread H section. This sec nspected and multiple issu here are also multiple wate	es were found in the section. M whars, sumps and end treatmen	lany of the RCE's in the	is section cleaned ar
erformed SWPPP inspection on the ispection. All perimeter ECD's were is eed to be refreshed with new rock. The instance performed. All issues the instance performed.	Spread H section. This sec nspected and multiple issu here are also multiple wate at were found were added t	es were found in the section. Mirbars, sumps and end treatment of a punch list and given to the	lany of the RCE's in th nts that will need to be contractor to be addres	is section cleaned ar ssed.
Performed SWPPP inspection on the inspection. All perimeter ECD's were in eed to be refreshed with new rock. The internance performed. All issues the inspection of the inspec	Spread H section. This sec nspected and multiple issu here are also multiple wate at were found were added t ollutant Discharge Elimin d to provide for the oper	es were found in the section. Marbars, sumps and end treatment of a punch list and given to the control of the following section. The following section is at light and the following section. The following section is at light and the following section is at light and the following section. The following section is at light and the foll	and Sediment permi	its that a
Performed SWPPP inspection on the respection. All perimeter ECD's were in send to be refreshed with new rock. The send to be refreshed with new rock.	Spread H section. This sec nspected and multiple issu here are also multiple wate at were found were added to ollutant Discharge Eliming to provide for the oper vater event. Please list i	es were found in the section. Merbars, sumps and end treatment of a punch list and given to the control of the following section in a punch list and given to the control of the following section and maintenance of a punch and maintenance of a number of the space provided comments.	and Sediment permil BMPs to note in repair	its that a ted on a rs or



MVP-34 REV 0 Page 3 of 3