Certification Statement

I certify under penalty of law that I have read and understand this document and that this document and all attachments were prepared in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Inspector's Name (printed): (Asen Mchally

Inspector's Signature:

Date: 10-3-18

Spread I Report #8783 DIN 0847

Droinet Nam	PII	PELINE W	li 0 ·				specti				Pipeline S	Enraed I
Project Name H-600 Pipeline Spread I			Cure Courted	AF	E 12430	0139	-			Pipeline S	ohreag i	
Contract	-			1,48791					port #			4.514
	_	Casey Mo	Gaha							_	2018 6:1	
Permit #	rmit # TBD		Inspection Type		VA SWPP		Station Begin		\rightarrow			
State				Inspection Area				Station End				
County	+	klin/Pittsy	Ivania	Ground		Dry		·		erature (°F)		82.00
Municipality			Weather		,		Rain Ga				0.00	
SPS Location	37.0	26125653	6814, -79.59	908868592974			Rain Ad	ccumul	lation '	Time	(days)	0.00
. Are the appr	oved	(stampe	d) E&S Pla	n and PCSM Pla	an pres	sent on sit	te?					Yes
				of the limits of d Permitting Coo					_)		No
				the construction nental Permitting							being	Yes
is required.)		BMPs an	d note if ins	stalled and main	tained	as per th	e plan. If o	correcti	ve acti	on is r	needed,	, a pictu
E	&S E	BMPs		Compliance Level		Correcti	ve Action			rective Fran		Date
					0.00		Foo.	-70				
											+	
												U 15
. Site Conditi	ons											
	ed di	of distur	bance resu	ediment, gravel, ulting from earth	distur	oance act	ivity or ine	ing to v	waters, BMP?	wetla If ye	inds, or s, take	No
evond defined	nedia	tely cont	act MVP Er	Wildring Chian F		3						
eyond defined photo and imn	nedia			s, final grade) be				uireme	ents?			Yes
eyond defined photo and imn ave inactive di	nedia sturb	ed areas	(stockpiles		en sta	bilized pe	r state rec	quireme	ents?			Yes

MVP-34 REV 0 Page 1 of 3

AFE 124300139		10/3/2018 6:11 PM	Report # 878	-
. PCSM BMPs (List BMPs and no	te if installed and mair	tained as per the plan. If cor	rective action is ne	eded, a
picture is required.)				Deta
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaire
4.7				
		Indo an		
		ice the previous inspection w	as conducted.	
. Identify all remedial measures tr	at have been taken on		n ' v.	
. Identify all remedial measures tr	at have been taken on			
Comments (Reference above ques	tions as appropriate.)			
Comments (Reference above ques The EI team continues to travel ROW to Environmental crews continue to perfor	tions as appropriate.) o identify compliance issi m maintenance along th	ues. All issues will be added to the ROW.	ne punchlist.	
Comments (Reference above ques The EI team continues to travel ROW to Environmental crews continue to perfor Grade crews continue to install all CWI The EI, grade foremen, and the Tetra	tions as appropriate.) o identify compliance iss rm maintenance along th Os and plunge pools. Fech engineer continue to	ues. All issues will be added to the ROW.	ne punchlist.	
Comments (Reference above questine EI team continues to travel ROW to invironmental crews continue to perform the crews continue to install all CWI the EI, grade foremen, and the Tetra	tions as appropriate.) o identify compliance iss rm maintenance along th Os and plunge pools. Fech engineer continue to	ues. All issues will be added to the ROW.	ne punchlist.	
Comments (Reference above ques The EI team continues to travel ROW to Environmental crews continue to perfor Grade crews continue to install all CWI The EI, grade foremen, and the Tetra	tions as appropriate.) o identify compliance iss rm maintenance along th Os and plunge pools. Fech engineer continue to	ues. All issues will be added to the ROW.	ne punchlist.	
Comments (Reference above ques The EI team continues to travel ROW to Environmental crews continue to perfor Grade crews continue to install all CWI The EI, grade foremen, and the Tetra	tions as appropriate.) o identify compliance iss rm maintenance along th Os and plunge pools. Fech engineer continue to	ues. All issues will be added to the ROW.	ne punchlist.	
Comments (Reference above ques The EI team continues to travel ROW to Environmental crews continue to perfor Grade crews continue to install all CWI The EI, grade foremen, and the Tetra	tions as appropriate.) o identify compliance iss rm maintenance along th Os and plunge pools. Fech engineer continue to	ues. All issues will be added to the ROW.	ne punchlist.	
Comments (Reference above ques The EI team continues to travel ROW to Environmental crews continue to perfor Grade crews continue to install all CWI The EI, grade foremen, and the Tetra	tions as appropriate.) o identify compliance iss rm maintenance along th Os and plunge pools. Fech engineer continue to	ues. All issues will be added to the ROW.	ne punchlist.	
Comments (Reference above ques The EI team continues to travel ROW t Environmental crews continue to perfo Grade crews continue to install all CWI The EI, grade foremen, and the Tetra	tions as appropriate.) o identify compliance iss rm maintenance along th Os and plunge pools. Fech engineer continue to	ues. All issues will be added to the ROW.	ne punchlist.	
Comments (Reference above questine El team continues to travel ROW to invironmental crews continue to performade crews continue to install all CWI he El, grade foremen, and the Tetra Ree photo log report #8482 for addition	tions as appropriate.) o identify compliance iss rm maintenance along th Os and plunge pools. Fech engineer continue to	ues. All issues will be added to the ROW.	ne punchlist.	

MVP-34 REV 0 Page 2 of 3

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 12430013	39	Date/Time 10/3/2018 6:11	PM Report # 8783
		Pictures	
GPS Location	36.9786107495225, -79.621175		n 36.9660110691669, -79.5837172577189
Description	Installing CWD plunge pool sta 1	Description	Maintenance performed on P1 fence sta 14082+88
GPS Location	36.9660187326716, -79.621082	4140158 GPS Location	n 36.9660034356983, -79.6210263390836
Description	Rock added to MVP FR 309.05	Description	Maintenance required and silt off ROW sta 14414+00
GPS Location	36.9658861309634, -79.620827		10.02.102000012.10
Description	Sediment in buffer zone at S-GH 14420+00	39 sta Description	Maintenance required on bridge across S-MM42 sta 13770+69

MVP-34 REV 0 Page 3 of 3