



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15147
<b>Inspector</b>	Glenn Mike Renfro			<b>Date/Time</b>	3/25/2019 2:22 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13416+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	13670+00
<b>County</b>	Franklin	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Maintenance needed		
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Communication	Maintenance needed		
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/25/2019 2:22 PM	<b>Report #</b>	15147
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP inspection of Spread H section of RoW. All perimeter ECD's were inspected and there were a couple of potential issues observed with sediment build up along perimeter CFS. All RCE's were found to be in good condition. All streams in this section were flowing free and clear of any sediment. There are still potential issues with sediment build up in waterbar channels in a few areas. All temporary and permanent end treatments were in acceptable condition. All vegetative stabilization practices are in good condition, but there were some minor rill erosion issues that will need to be monitored and addressed if needed. All issues observed during the inspection were placed on the punch list and given to the contractor to address.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	3/25/2019 2:22 PM	Report #	15147
Pictures					
					
GPS Location		36.97	Field Station#		13437+88
Description		Erosion channels leading to sediment build up on CFS. Sediment off RoW			
					
GPS Location		36.97	Field Station#		13435+00
Description		Permanent stabilization and all ECD's in place and functioning properly.			
					
GPS Location		36.97	Field Station#		13430+00
Description		Permanent stabilization and ECD's in place and functioning properly.			
					
GPS Location		36.97	Field Station#		13442+00
Description		Spoil piles stabilization in good condition.			
					
GPS Location		36.97	Field Station#		13457+00
Description		Perimeter ECD's in good condition.			

<b>A/E</b>	124300138	<b>Date/Time</b>	3/25/2019 2:22 PM	<b>Report #</b>	15147
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		



<b>A/E</b>	124300138	<b>Date/Time</b>	3/25/2019 2:22 PM	<b>Report #</b>	15147
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H	
<b>Contractor</b>	Precision			<b>Report #</b>	15228	
<b>Inspector</b>	Pat Davis			<b>Date/Time</b>	3/28/2019 6:24 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	+0	
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	+0	
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	61.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00	
				<b>Rain Accumulation Time (days)</b>	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Sensitive Resource Signage		Acceptable				
Sensitive Resource Buffer		Acceptable				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:24 AM	<b>Report #</b>	15228
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Crews have continued to pickup loose trash, and pump out secondary containments under the light plants and supplies.					
<b>Comments</b> (Reference above questions as appropriate.) (Summary Spread 9) Checked rain gauge in the yard MVP-PY-006 and found 0 rainfall in the raingauge. EI preformed SWPPP Inspection on the MVP-PY-006. EI observed no trash in the yard. Secondary containment's were in good condition. EI observed no fluid deposits on the stone on the either side of the bulk fuel tanks. The flagging to mark the 100 foot boundary was in place. EI found no leaky equipment. The wash rack that was clean and in good condition. No other environmental issues were noted during today's inspection. SEAP Training was not given due to no new hires. No environmental issues were noted during today's inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	3/28/2019 6:24 AM	Report #	15228
Pictures					
 <p>DIRECTION SW (T) +37.23542° -080.22962° ACCURACY 16 ft DATUM WGS84</p> <p>2019-03-28 07:32:53-04:00</p>			 <p>DIRECTION W (T) +37.23539° -080.22963° ACCURACY 16 ft DATUM WGS84</p> <p>2019-03-28 07:32:59-04:00</p>		
GPS Location	37.23	Field Station# +0	GPS Location	37.23	Field Station# +0
Description MVP-PY-006_032819 condition of containment under light plant. Looking SW. See photo for gps data.			Description MVP-PY-006_032819 condition of containment under porta toilets. Looking W. See photo for gps data.		
 <p>DIRECTION NE (T) +37.23541° -080.22839° ACCURACY 16 ft DATUM WGS84</p> <p>2019-03-28 07:36:09-04:00</p>			 <p>DIRECTION E (T) +37.23412° -080.22900° ACCURACY 16 ft DATUM WGS84</p> <p>2019-03-28 07:37:59-04:00</p>		
GPS Location	37.23	Field Station# +0	GPS Location	37.23	Field Station# +0
Description MVP-PY-006_032819 flagging and buffer around feature. Looking NE. See photo for gps data.			Description MVP-PY-006_032819 condition of compost filter sock along south boundary. Looking E. See photo for gps data.		
 <p>DIRECTION SW (T) +37.23548° -080.22641° ACCURACY 16 ft DATUM WGS84</p> <p>2019-03-28 08:07:38-04:00</p>			 <p>DIRECTION SW (T) +37.23573° -080.22674° ACCURACY 16 ft DATUM WGS84</p> <p>2019-03-28 08:07:56-04:00</p>		
GPS Location	37.23	Field Station# +0	GPS Location	37.23	Field Station# +0
Description MVP-PY-006_032819 condition of containment under fuel cans. Looking SW. See photo for gps data.			Description MVP-PY-006_032819 no fluid deposits on the north side of the bulk fuel tanks. Looking SW. See photo for gps data.		



<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:24 AM	<b>Report #</b>	15228
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:24 AM	<b>Report #</b>	15228
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15231
<b>Inspector</b>	Pat Davis			<b>Date/Time</b>	3/28/2019 6:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	+0
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	+0
<b>County</b>	Roanoke	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	61.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:38 AM	<b>Report #</b>	15231
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> The crew continues to perform maintenance on the stone surface. Crews have kept loose trash picked up around dumpster area. Area around both dumpster areas free of loose trash.					
<b>Comments</b> (Reference above questions as appropriate.) (Summary Spread 10) EI preformed SWPPP Inspection on MVP-LY-049 check rain gauge found 0 rainfall in the gauge. EI checked the boundary of the LOD and found the triple stack compost filter sock in good condition. EI observed no trash along the boundary safety fence and by the timber mats. Observed the safety fence along the boundary was in good condition. The rock approaches are in good condition no mud on the stone. Contractor continues to pick up trash in the yard. No other environmental issues were noted during today's inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300138		Date/Time		3/28/2019 6:38 AM		Report #		15231	
Pictures											
<div>DIRECTION NW (T) +37.27207° -080.12288° ACCURACY 33 ft DATUM WGS84</div>  <div>2019-03-28 08:28:23-04:00</div>				<div>DIRECTION NW (T) +37.27160° -080.12234° ACCURACY 16 ft DATUM WGS84</div>  <div>2019-03-28 08:28:46-04:00</div>							
GPS Location		37.27		Field Station#		+0		GPS Location		37.27	
Description		MVP-LY-049_032819 condition of rock approach on center drive. Looking S. See photo for gps data.						Description		MVP-LY-049_032819 condition of compost filter sock and safety fence along drive. Looking S. See photo for gps.	
<div>DIRECTION S (T) +37.27099° -080.12189° ACCURACY 16 ft DATUM WGS84</div>  <div>2019-03-28 08:29:12-04:00</div>				<div>DIRECTION N (T) +37.27152° -080.12041° ACCURACY 16 ft DATUM WGS84</div>  <div>2019-03-28 08:31:34-04:00</div>							
GPS Location		37.27		Field Station#		+0		GPS Location		37.27	
Description		MVP-LY-049_032819 condition of containment under light plant. Looking N. See photo for gps data.						Description		MVP-LY-049_032819 dumpster area free of loose trash. Looking NE. See photo for gps data.	
<div>DIRECTION NW (T) +37.27002° -080.12350° ACCURACY 16 ft DATUM WGS84</div>  <div>2019-03-28 08:35:15-04:00</div>				<div>DIRECTION NE (T) +37.27083° -080.12391° ACCURACY 16 ft DATUM WGS84</div>  <div>2019-03-28 08:36:00-04:00</div>							
GPS Location		37.27		Field Station#		+0		GPS Location		37.27	
Description		MVP-LY-049_032819 condition of containment under light plant. Looking NW. See photo for gps data.						Description		MVP-LY-049_032819 condition of compost filter sock and safety fence along north drive. Looking N. See photo for gps data.	

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:38 AM	<b>Report #</b>	15231
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:38 AM	<b>Report #</b>	15231
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15232
<b>Inspector</b>	Pat Davis			<b>Date/Time</b>	3/28/2019 6:42 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13315+70
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13415+51
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar End Treatment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:42 AM	<b>Report #</b>	15232
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
Crews have corrected issues with waterbars and compost filter sock. Crews have removed trees blown down on the silt fence. Crews then repaired the damaged silt fence sections. The contractor has applied annual ryegrass and Earth Guard between station 13371+50 to station 13403+08. Crews have installed erosion control blanket on steep slopes between 13317+02 to station 13331+50.					
<b>Comments</b> (Reference above questions as appropriate.)					
Summary Spread 10) EI preformed SWPPP Inspection between Websters Corner station 13342+67 to Cahas Mt station 13415+51. EI observed 0 rainfall in the raingauge at Cahas Mountain Road. Environmental crew was in the process of making repairs per the punchlist and preforming maintenance on erosion control devices. EI observed the installed erosion control blanket on steep slopes was in good condition between station 13358+64 to station 13371+50 was in good condition and secured. EI observed timber mat bridges were clean and closed. The rock approaches at Webster's Corner Road station 13342+67 were in good condition and free of sediment. No environmental issues were noted during today's inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	3/28/2019 6:42 AM	Report #	15232		
Pictures							
							
GPS Location	37.27	Field Station#	13345+00	GPS Location	37.27	Field Station#	13348+46
Description	13345+00_032819 condition of plunge pool. Looking SE. See photo for gps data.			Description	13348+46_032819 S-RR08 mat bridge clean and closed. Looking SE. See photo for gps data.		
							
GPS Location	37.27	Field Station#	13352+23	GPS Location	37.27	Field Station#	13358+64
Description	13352+23_032819 S-RR09 mat bridge clean and closed. Looking SE. See photo for gps data.			Description	13358+64_032819 S-RR11 mat bridge clean and closed. Looking SE. See photo for gps data.		
							
GPS Location	37.27	Field Station#	13321+47	GPS Location	37.27	Field Station#	13317+02
Description	13321+47_032819 S-GH15 mat bridge clean and closed. Extra supplies by bridge. Looking NW. See photo for gps data.			Description	13317+02_032819 erosion control blanket on slope. Looking SE. See photo for gps data.		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:42 AM	<b>Report #</b>	15232
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 6:42 AM	<b>Report #</b>	15232
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15236
<b>Inspector</b>	Dustin Lyons			<b>Date/Time</b>	3/28/2019 5:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12072+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Sump Pit	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 5:12 PM	<b>Report #</b>	15236
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> No remedial measures were performed in this area since the last SWPPP inspection.					
<b>Comments</b> (Reference above questions as appropriate.) I met with the inspection team at the main yard this morning at 7:00 am, then attended the contractors weekly safety meeting. After the safety meeting I traveled to the access road MVP-MN-270.  I performed a SWPPP inspection of the ROW from station 12005+00 to 12072+00. The ROW through out this section has been temporarily stabilized with a combinations of Earthguard, seed and erosion control blanket. I observed the conditions of the ECDs, the stream crossings and general conditions of the ROW. No environmental issues, off-ROW sediment or stream impacts were observed in this area during today's SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300138	Date/Time	3/28/2019 5:12 PM	Report #	15236		
Pictures							
<div>DIRECTION 100 deg(T)</div> <div>+37.26157° -080.30187°</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>12055+00 to 12057+00</div> <div>Perimeter ECDs</div> <div>2019-03-28 09:39:37-04:00</div>			<div>DIRECTION 321 deg(T)</div> <div>+37.26178° -080.30241°</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>12036+00 to 12053+00</div> <div>ROW condition</div> <div>2019-03-28 09:43:27-04:00</div>				
GPS Location	37.27	Field Station#	12055+00	GPS Location	37.27	Field Station#	12053+00
Description	See photo for gps data. Photo shows the perimeter ECDs from about 12055+00 to 12057+00.			Description	See photo for gps data. Photo shows the ROW conditions from about 12036+00 to 12053+00.		
<div>DIRECTION 314 deg(T)</div> <div>+37.26482° -080.30731°</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>12035+11</div> <div>S-G40</div> <div>2019-03-28 10:10:15-04:00</div>			<div>DIRECTION 296 deg(T)</div> <div>+37.26530° -080.31035°</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>12020+00 to 12026+00</div> <div>ROW condition</div> <div>2019-03-28 10:43:54-04:00</div>				
GPS Location	37.27	Field Station#	12035+11	GPS Location	37.27	Field Station#	12026+00
Description	See photo for gps data. Photo shows the condition of stream S-G40 at about 12035+11.			Description	See photo for gps data. Photo shows the general condition of the ROW from about 12020+00 to 12026+00.		
<div>DIRECTION 229 deg(T)</div> <div>+37.26710° -080.31288°</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>12015+00</div> <div>S-G38</div> <div>2019-03-28 10:54:07-04:00</div>			<div>DIRECTION 92 deg(T)</div> <div>+37.26851° -080.31439°</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>12008+00</div> <div>S-G36</div> <div>2019-03-28 11:01:34-04:00</div>				
GPS Location	37.27	Field Station#	12015+00	GPS Location	37.27	Field Station#	12008+79
Description	See photo for gps data. Photo shows the general condition of stream S-G38 at about 12015+00.			Description	See photo for gps data. Photo shows the stream bank on the southeast side of stream S-G36.		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 5:12 PM	<b>Report #</b>	15236
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 5:12 PM	<b>Report #</b>	15236
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		











# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15243
<b>Inspector</b>	Joe Scott			<b>Date/Time</b>	3/28/2019 8:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12686+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13143+00
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Broad-Based Dip	Acceptable				
Waterbar End Treatment	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Waterbar	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Sump Pit	Acceptable				
Equipment Bridge	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 8:40 AM	<b>Report #</b>	15243
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px; border: 1px solid black;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>           Attended the MVP Inspectors morning meeting at the MVP-PY-006 along with the PPL weekly safety meeting. Attended the morning meeting with PPL management afterwards. Met with lead EI and fellow EI's and discussed activities for the day. Traveled to Honeysuckle Road and inspected the ROW, ECD's, and BMP's for possible deficiencies or impacts in the area. None were observed. Traveled to Bottom Creek Road. No issues or impacts found on either side of the road crossing. Traveled to RO-288. The ROW and the access road were within compliance. Traveled to US-221. From the CIS of the US-221 crossing, 12993+00 to FR-290, 13062+00 no issues or impacts were observed. Traveled to FR-291. From the GAS of FR-291, 13120+17 back to FR-291, 13062+00, no issues or impacts were found. Traveled to FR-292. No deficiencies were found along the access road.         </p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300138		<b>Date/Time</b>	3/28/2019 8:40 AM		<b>Report #</b>	15243	
<b>Pictures</b>								
<div><p>Date &amp; Time: Thu, Mar 28, 2019, 08:39:24 EDT Position: +037.191622° / -080.125026° Altitude: 2928ft Datum: WGS-84 Azimuth/Bearing: 207° N80W 5200mils (True) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1X 12690+00 GIS of the Honeysuckle Road crossing</p></div>				<div><p>Date &amp; Time: Thu, Mar 28, 2019, 08:14:28 EDT Position: +037.210230° / -080.128824° Altitude: 2994ft Datum: WGS-84 Azimuth/Bearing: 244° S42W 4300mils (True) Elevation Grade: +00% Horizon Grade: +003% Zoom: 1X 12865+00 Bottom Creek Road</p></div>				
<b>GPS Location</b>	37.19	<b>Field Station#</b>	12690+00		<b>GPS Location</b>	37.15	<b>Field Station#</b>	12865+00
<b>Description</b>	No issues or impacts found at Honeysuckle road.				<b>Description</b>	Bottom Creek Road was in good condition throughout the work area. No issues.		
<div><p>Date &amp; Time: Thu, Mar 28, 2019, 13:26:50 EDT Position: +037.126579° / -080.105765° Altitude: 3059ft Datum: WGS-84 Azimuth/Bearing: 246° S66W 4373mils (True) Elevation Grade: +055% Horizon Grade: +001% Zoom: 1X 13080+00 GAS of FR-290</p></div>				<div><p>Date &amp; Time: Thu, Mar 28, 2019, 13:47:51 EDT Position: +037.125451° / -080.102308° Altitude: 3097ft Datum: WGS-84 Azimuth/Bearing: 137° S43E 2430mils (True) Elevation Grade: +027% Horizon Grade: +002% Zoom: 1X 13087+00 GIS of FR-291</p></div>				
<b>GPS Location</b>	37.12	<b>Field Station#</b>	13080+00		<b>GPS Location</b>	37.12	<b>Field Station#</b>	13087+00
<b>Description</b>	ROW stabilized with Curlex. No issues or impacts observed.				<b>Description</b>	ROW stabilized with EarthGuard continues to resist erosion. No issues or impacts found throughout the area.		
<div><p>Date &amp; Time: Thu, Mar 28, 2019, 13:46:05 EDT Position: +037.126043° / -080.107152° Altitude: 2782ft Datum: WGS-84 Azimuth/Bearing: 273° N87W 4853mils (True) Elevation Grade: +040% Horizon Grade: +004% Zoom: 1X 13074+00 GAS of FR-290</p></div>				<div><p>Date &amp; Time: Thu, Mar 28, 2019, 14:24:11 EDT Position: +037.126043° / -080.107152° Altitude: 2782ft Datum: WGS-84 Azimuth/Bearing: 298° N62W 5298mils (True) Elevation Grade: +016% Horizon Grade: +001% Zoom: 1X 13064+00 GAS of S-G26 and S-G27</p></div>				
<b>GPS Location</b>	37.12	<b>Field Station#</b>	13074+00		<b>GPS Location</b>	37.12	<b>Field Station#</b>	13064+00
<b>Description</b>	All ECD's, BMP's, and stabilized ROW remain within compliance.				<b>Description</b>	S-G26 and S-G27 showed no signs of impact.		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 8:40 AM	<b>Report #</b>	15243
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 8:40 AM	<b>Report #</b>	15243
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		










# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15257
<b>Inspector</b>	Jason Nielsen			<b>Date/Time</b>	3/28/2019 10:00 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12445+01
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12450+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 10:00 PM	<b>Report #</b>	15257
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> There has been no PPL activity in the area.					
<b>Comments</b> (Reference above questions as appropriate.) Went to cove hollow road to perform a SWPPP inspection. While in the area I inspected all BMPs and everything was in good shape with no need for repairs.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300138		Date/Time 3/28/2019 10:00 PM		Report # 15257			
Pictures							
<div>DIRECTION SW (T)</div> <div>37.23066°N 080.19910°W</div> <div>ACCURACY 8 m DATUM WGS84</div>  <div>2019-03-28 09:00:54-04:00</div>		<div>DIRECTION E (T)</div> <div>37.23066°N 080.19910°W</div> <div>ACCURACY 8 m DATUM WGS84</div>  <div>2019-03-28 09:01:04-04:00</div>					
GPS Location 37.25		Field Station# 12448+41		GPS Location 37.25		Field Station# 12448+12	
Description		Stabilized disturbed variance. Looking SW. See picture for GPS data.		Description		RCE. Looking E. See picture for GPS data.	
<div>DIRECTION NE (T)</div> <div>37.23066°N 080.19847°W</div> <div>ACCURACY 45 m DATUM WGS84</div>  <div>2019-03-28 09:01:24-04:00</div>		<div>DIRECTION N (T)</div> <div>37.23106°N 080.19843°W</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>2019-03-28 09:02:09-04:00</div>					
GPS Location 37.25		Field Station# 12447+60		GPS Location 37.25		Field Station# 12446+50	
Description		P1 Perimeter controls. Looking NE. See picture for GPS data.		Description		End cap on well point system. Looking N. See picture for GPS data.	
<div>DIRECTION S (T)</div> <div>37.23112°N 080.19837°W</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>2019-03-28 09:02:25-04:00</div>		<div>DIRECTION Unavailable</div> <div>LOCATION Unavailable</div> <div>ACCURACY/DATUM Unavailable</div>  <div>2019-03-28 09:03:56-04:00</div>					
GPS Location 37.25		Field Station# 12447+00		GPS Location 37.25		Field Station# 12447+00	
Description		Stabilized channel where rain water was crossing the ROW. Looking S. See picture for GPS data.		Description		Stabilized ROW.	

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 10:00 PM	<b>Report #</b>	15257
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 10:00 PM	<b>Report #</b>	15257
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15258
<b>Inspector</b>	Tyler Cremeens			<b>Date/Time</b>	3/28/2019 10:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13262+62
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13316+16
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	68.
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.
				<b>Rain Accumulation Time (days)</b>	1.
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Waterbar Outlet Protection	Acceptable				
Waterbar	Acceptable				
Sump Pit	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Rock Construction Entrance	Acceptable				
Housekeeping	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 10:18 PM	<b>Report #</b>	15258
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>The day was sunny, clear &amp; cool with moderate winds. Field conditions were relatively dry.</p> <p>I conducted a SWPPP inspection of the ROW between Wade's Gap Road &amp; Flanders Road (13262+62 to 13316+16). During my inspections, no erosion or sedimentation was observed, nor corrections or repairs needed. No issues were observed at Waterway S-GH7, nor problems observed with the accompanying bridge, which was free of sediments.</p> <p>At the CIS of Wade's Gap Road, John Davis's environmental crew continued to stabilize recently disturbed soils. Work included equipment usage to prepare the area for installation of erosion control blanket (skid-steer removed trash/debris and stockpiled timber mats, while a mini-excavator smoothed the grade to facilitate blanket application as well as removed an old dewatering structure). Meanwhile, laborers installed erosion control blanket on the east side of waterway S-GH7 (working their way towards Wade's Gap Road).</p> <p>At Flanders Road, personnel delivered a load of rock to spread at the RCE and parking area.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	3/28/2019 10:18 PM	Report #	15258		
Pictures							
<div>Position: +037.098589° / -079.979968° Altitude: 1248ft Datum: WGS-84 Azimuth/Bearing: Not Available Elevation Angle: -65.5° Horizon Angle: -00.9° Zoom: 1X</div> 			<div>Position: +037.098589° / -079.979968° Altitude: 1248ft Datum: WGS-84 Azimuth/Bearing: Not Available Elevation Angle: -03.4° Horizon Angle: -00.1° Zoom: 2X</div> 				
GPS Location	37.29	Field Station#	13315+50	GPS Location	37.29	Field Station#	13315+00
Description	Bags of oats at Wade's Gap road being dispersed as temporary stabilization/seeding. See photo for GPS data.			Description	Mini-excavator removing old dewatering structure. View: southwest, see photo for GPS data.		
<div>Position: +037.098589° / -079.979968° Altitude: 1248ft Datum: WGS-84 Azimuth/Bearing: Not Available Elevation Angle: -15.6° Horizon Angle: -01.8° Zoom: 1X</div> 			<div>Position: +037.098589° / -079.979968° Altitude: 1248ft Datum: WGS-84 Azimuth/Bearing: Not Available Elevation Angle: -22.3° Horizon Angle: -01.1° Zoom: 1X</div> 				
GPS Location	37.29	Field Station#	13280+00	GPS Location	37.29	Field Station#	13280+00
Description	CFS installed atop the ridge between Wade's Gap & Flanders along soil piles and sump. View: south, see photo for GPS data.			Description	CFS installed atop the ridge between Wade's Gap & Flanders at sump. View: southwest, see photo for GPS data.		
<div>Position: +037.098589° / -079.979968° Altitude: 1248ft Datum: WGS-84 Azimuth/Bearing: Not Available Elevation Angle: -25.0° Horizon Angle: +01.6° Zoom: 1X</div> 			<div>Position: +037.098589° / -079.979968° Altitude: 1248ft Datum: WGS-84 Azimuth/Bearing: Not Available Elevation Angle: -26.2° Horizon Angle: -01.2° Zoom: 1X</div> 				
GPS Location	37.29	Field Station#	13280+00	GPS Location	37.29	Field Station#	13313+00
Description	CFS installed atop the ridge between Wade's Gap & Flanders at sump. View: west, see photo for GPS data.			Description	Location where contractor ended applying ECB for the day. View: west, see photo for GPS data.		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 10:18 PM	<b>Report #</b>	15258
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 10:18 PM	<b>Report #</b>	15258
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15265
<b>Inspector</b>	Jason Nielsen			<b>Date/Time</b>	3/28/2019 7:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12190+85
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12442+85
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 7:14 PM	<b>Report #</b>	15265
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Since the last inspection the environmental crew has worked on completing punch list items and making repairs to damaged ECDs.					
<b>Comments</b> (Reference above questions as appropriate.) Went to access road MVP-Mn-276.03 to begin my SWPPP inspection walk. While walking the ROW I didn't find anything that required maintenance. All BMPs were in good condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300138	Date/Time	3/28/2019 7:14 PM	Report #	15265		
Pictures							
<div>DIRECTION SW (T)</div> <div>37.24971°N 080.20722°W</div> <div>ACCURACY 6.39 km DATUM WGS84</div>  <div>2019-03-28 09:53:50-04:00</div>			<div>DIRECTION SE (T)</div> <div>37.25598°N 080.23078°W</div> <div>ACCURACY 6 m DATUM WGS84</div>  <div>2019-03-28 09:54:46-04:00</div>				
GPS Location	37.25	Field Station#	12281+00	GPS Location	37.25	Field Station#	12285+00
Description	Pipe in open ditch. Looking SW. See picture for GPS data.			Description	Stabilized hill side and water bars. Looking SE. See picture for GPS data.		
<div>DIRECTION SE (T)</div> <div>37.25600°N 080.23179°W</div> <div>ACCURACY 112 m DATUM WGS84</div>  <div>2019-03-28 10:05:30-04:00</div>			<div>DIRECTION W (T)</div> <div>37.25202°N 080.24382°W</div> <div>ACCURACY 9 m DATUM WGS84</div>  <div>2019-03-28 10:54:21-04:00</div>				
GPS Location	37.25	Field Station#	12268+00	GPS Location	37.25	Field Station#	12242+64
Description	Sump pit and water bar end treatment. Looking SE. See picture for GPS data.			Description	SSF perimeter controls. Looking W. See picture for GPS data.		
<div>DIRECTION E (T)</div> <div>37.25264°N 080.25848°W</div> <div>ACCURACY 165 m DATUM WGS84</div>  <div>2019-03-28 11:39:12-04:00</div>			<div>DIRECTION SW (T)</div> <div>37.25264°N 080.25849°W</div> <div>ACCURACY 165 m DATUM WGS84</div>  <div>2019-03-28 12:08:44-04:00</div>				
GPS Location	37.25	Field Station#	12205+86	GPS Location	37.25	Field Station#	12192+36
Description	Stabilized hill side. Looking E. See picture for GPS data.			Description	Bridge crossing S-C21. Looking SW. See picture for GPS data.		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 7:14 PM	<b>Report #</b>	15265
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	<b>Field Station#</b>
<b>Description</b>			<b>Description</b>		



<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 7:14 PM	<b>Report #</b>	15265
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15280
<b>Inspector</b>	John Brcic			<b>Date/Time</b>	3/28/2019 9:20 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12071+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12195+50
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Cleanwater Diversion Berm	Communication	12087+25 - 12089+00: repairs		Addressed	3/27/2019
Vegetative Stabilization (Temporary)	Communication	12140+00: restabilize stockpile		24 Hours	
Vegetative Stabilization (Temporary)	Communication	12170+00: restabilize stockpile		24 Hours	
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Sump Pit	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 9:20 AM	<b>Report #</b>	15280
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Since the last SWPPP inspection, Joe Amua's environmental repaired clean water diversion berm in three places between streams S-MM14 and S-MM11. They also addressed punch list items and performed minor maintenance in various locations throughout this inspection area.					
<b>Comments</b> (Reference above questions as appropriate.) At the beginning of the day, I attended the Spread H safety meeting in the PPL yard and then the morning meeting at the MVP inspection trailer. A SWPPP inspection was then conducted between stations 12071+00 and 12195+50. While inspecting this area, Joe Amua's environmental was working on repairing clean water diversion berm between streams S-MM14 and S-MM13, at stations 12087+25 and 12089+00, where the cut bank had eroded below the diversion berm causing damage to the berm. They also addressed three MBP/DEQ action items in this inspection area which I verified and documented. I observed two minor maintenance issues that will be added to the punch list. At station 12140+00, in the additional temporary workspace, the temporary stabilization of the stockpile has become sparse and needs to be refreshed with seed and straw mulch. At station 12170+00, the end of a stockpile next to the inlet of a slope drain needs to be stabilized, preferably with erosion control blanket. Aside from these items, there were no instances of stream or wetland impacts or ECD failure.  In the late afternoon, I updated and distributed the Spread H punch list adding the new items and removing the completed. There were no new action items turned in by MBP inspectors.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300138	Date/Time	3/28/2019 9:20 AM	Report #	15280		
Pictures							
<div>DIRECTION N (T)</div> <div>37.25853°N 080.29219°W</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>2019-03-28 09:19:42-04:00</div>			<div>DIRECTION W (T)</div> <div>37.25810°N 080.28919°W</div> <div>ACCURACY 10 m DATUM WGS84</div>  <div>2019-03-28 09:35:34-04:00</div>				
GPS Location	37.25	Field Station#	12089+00	GPS Location	37.25	Field Station#	12098+00
Description	The cut bank has eroded resulting in damage to the clean water diversion berm.			Description	An operator maintained the travel lane above stream S-MM13 on his way through to other work in the area.		
<div>DIRECTION SE (T)</div> <div>37.25744°N 080.28209°W</div> <div>ACCURACY 10 m DATUM WGS84</div>  <div>2019-03-28 10:28:03-04:00</div>			<div>DIRECTION NW (T)</div> <div>37.25636°N 080.27787°W</div> <div>ACCURACY 10 m DATUM WGS84</div>  <div>2019-03-28 10:57:10-04:00</div>				
GPS Location	37.25	Field Station#	12120+50	GPS Location	37.25	Field Station#	12133+00
Description	ECDs are all intact and functioning as needed through the series of streams and wetlands on the going away side of Flatwoods Road.			Description	PL item #1987 (MBP action item) has been completed. Fabric was reattached to chain link on SSF.		
<div>DIRECTION N (T)</div> <div>37.25462°N 080.26937°W</div> <div>ACCURACY 5 m DATUM WGS84</div>  <div>2019-03-28 11:56:54-04:00</div>			<div>DIRECTION S (T)</div> <div>37.25395°N 080.26593°W</div> <div>ACCURACY 10 m DATUM WGS84</div>  <div>2019-03-28 12:27:21-04:00</div>				
GPS Location	37.25	Field Station#	12158+75	GPS Location	37.25	Field Station#	12170+00
Description	PL item #1985 (MBP action item) has been completed. Fabric was reattached to the chain link on SSF.			Description	The end of the stockpile next to the fill slope drain inlet needs to be stabilized.		



<b>AFE</b>	124300138	<b>Date/Time</b>	3/28/2019 9:20 AM	<b>Report #</b>	15280
<b>Pictures</b>					
<b>GPS Location</b>	37.25	<b>Field Station#</b>	12089+00	<b>GPS Location</b>	37.25
<b>Description</b>	Diversion berm was repaired by Joe Amua's env crew where it had been damaged by erosion in the cut bank below.				
<b>GPS Location</b>	37.25	<b>Field Station#</b>	12140+00	<b>GPS Location</b>	37.25
<b>Description</b>	Stockpile could use another treatment of seed and mulch where stabilization has become sparse next to access road MVP-MN-272.				
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>					

<b>A/E</b>	124300138	<b>Date/Time</b>	3/28/2019 9:20 AM	<b>Report #</b>	15280
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread H	<b>AFE</b>	124300138	<b>Spread</b>	H-600 Pipeline Spread H
<b>Contractor</b>	Precision			<b>Report #</b>	15300
<b>Inspector</b>	Glenn Mike Renfro			<b>Date/Time</b>	3/29/2019 11:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13415+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	1367+00
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Communication				
Waterbar End Treatment	Acceptable	Maintenance needed			
Vegetative Stabilization (Permanent)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300138	<b>Date/Time</b>	3/29/2019 11:38 AM	<b>Report #</b>	15300
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP inspection of Spread H section of RoW. All perimeter ECD's were inspected and no issues were observed. The RCE's throughout this section of RoW were in good condition. There were some minor erosion problems observed that are currently being monitored by the inspection staff. The contractor is currently reseeding and stabilizing areas with Earth Guard Edge. All stream crossings were found to be flowing free and clear of any sediment. All permanent and temporary waterbars and end treatments were found to be in good condition. There were no new issues found to add to the punch list during today inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b> 124300138		<b>Date/Time</b> 3/29/2019 11:38 AM		<b>Report #</b> 15300	
<b>Pictures</b>					
					
<b>GPS Location</b> 37.01		<b>Field Station#</b> 13659+03		<b>GPS Location</b> 37.01	
<b>Field Station#</b> 13659+03		<b>GPS Location</b> 37.01		<b>Field Station#</b> 13659+03	
<b>Description</b>		ECD's at stream crossing S-GH3 in good condition.		<b>Description</b>	
		Stream S-GH3 flowing free and clear of sediment.			
					
<b>GPS Location</b> 37.01		<b>Field Station#</b> 13662+57		<b>GPS Location</b> 37.01	
<b>Field Station#</b> 13662+57		<b>GPS Location</b> 37.01		<b>Field Station#</b> 13666+27	
<b>Description</b>		Travel lane recently re-seeded and stabilized with Earth Guard Edge.		<b>Description</b>	
		Stream banks stabilized at S- GH2 and ECD's in good condition			
			Insert image here		
<b>GPS Location</b> 37.01		<b>Field Station#</b> 13666+33		<b>GPS Location</b> 37.01	
<b>Field Station#</b> 13666+33		<b>GPS Location</b> 37.01		<b>Field Station#</b>	
<b>Description</b>		ECD's in place and functioning properly		<b>Description</b>	

<b>A/E</b>	124300138	<b>Date/Time</b>	3/29/2019 11:38 AM	<b>Report #</b>	15300
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		

<b>A/E</b>	124300138	<b>Date/Time</b>	3/29/2019 11:38 AM	<b>Report #</b>	15300
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>Field Station#</b>		<b>GPS Location</b>	
<b>Description</b>			<b>Description</b>		