



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6258
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	12/2/2019 7:59 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11520+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11620+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	28.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock				
Housekeeping				
Rock Construction Entrance				
Vegetative Stabilization (Temporary)				
Sensitive Resource Buffer				
Sensitive Resource Signage				

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:59 AM	<b>Report #</b>	6258
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26. For morning meeting No damaged ECD's observed during SWPPP inspection ECD's installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked row checking ECD's and making minor repairs to ECD's  1.6" of rain recorded @ Pocahontas, 1.4" of rain recorded @ LDY 37					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	12/2/2019 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+37	
<b>Pic 1 Desc.</b>	1.6" of rain recorded @ Pocahontas		<b>Pic 2 Desc.</b>	1.4" of rain recorded @ LDY 37	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+28		<b>Field Station#</b>	+28	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+28		<b>Field Station#</b>	+28	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6261
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/2/2019 7:33 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	34.00
<b>Municipality</b>	N/A	<b>Weather</b>	Snow/Sleet	<b>Rain Gauge (in)</b>	1.70
				<b>Rain Accumulation Time (days)</b>	3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:33 AM	<b>Report #</b>	6261
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: LY-29 AR-238.00 is maintained in acceptable condition. Materials storage in the yard is acceptable, house keeping is acceptable. CFS triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. Overhead goal posts and flagging are in acceptable condition. The rock surface of the yard is maintained in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	12/2/2019 7:33 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Dec 02, 2019, 08:26:37 EST  Position: +037.349174° / -080.652652°  Altitude: 2072ft  Datum: WGS-84  Azimuth/Bearing: 307° N53W 348mils (True)  Elevation Angle: +20.8°  Horizon Angle: -02.1°  Zoom: 1x  Buffalo Anklets rain gauge reading: 1.70"</p> 		<p>Date &amp; Time: Mon, Dec 02, 2019, 08:26:37 EST  Position: +037.349174° / -080.652652°  Altitude: 2071ft  Datum: WGS-84  Azimuth/Bearing: 338° N62W 348mils (True)  Elevation Angle: +20.8°  Horizon Angle: -00.0°  Zoom: 1x  AR-234- Rain gauge reading: 1.20"</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10695+47		<b>Field Station#</b>	10700+00	
<b>Pic 1 Desc.</b>	Buffalo Anklets rain gauge reading 1.70"		<b>Pic 2 Desc.</b>	AR-234- Rain gauge reading- 1.20"	
<p>Date &amp; Time: Mon, Dec 02, 2019, 08:26:48 EST  Position: +037.349174° / -080.652652°  Altitude: 1830ft  Datum: WGS-84  Azimuth/Bearing: 032° N32E 664mils (True)  Elevation Angle: +19.0°  Horizon Angle: -00.3°  Zoom: 1x  LY-29- Culvert &amp; drainage feature are in good condition.</p> 		<p>Date &amp; Time: Mon, Dec 02, 2019, 08:26:48 EST  Position: +037.349174° / -080.652652°  Altitude: 1830ft  Datum: WGS-84  Azimuth/Bearing: 032° N32E 664mils (True)  Elevation Angle: +19.0°  Horizon Angle: -00.3°  Zoom: 1x  LY-29- CFS triple stack perimeter controls are in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	LY-29- Culvert & drainage feature are in good condition.		<b>Pic 4 Desc.</b>	LY-29- CFS triple stack perimeter controls are in acceptable condition.	
<p>Date &amp; Time: Mon, Dec 02, 2019, 08:49:54 EST  Position: +037.342524° / -080.677267°  Altitude: 1712ft  Datum: WGS-84  Azimuth/Bearing: 264° S66W 4373mils (True)  Elevation Angle: +23.2°  Horizon Angle: -04.7°  Zoom: 1x  LY-29- Materials storage, house keeping is acceptable.</p> 		<p>Date &amp; Time: Mon, Dec 02, 2019, 08:55:07 EST  Position: +037.343271° / -080.676562°  Altitude: 1825ft  Datum: WGS-84  Azimuth/Bearing: 262° S72W 4480mils (True)  Elevation Angle: +24.5°  Horizon Angle: -05.0°  Zoom: 1x  LY-29- The rock surface of the yard is maintained in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	LY-29- Materials storage, house keeping is acceptable.		<b>Pic 6 Desc.</b>	LY-29- The rock surface of the yard is maintained in acceptable condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6266
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	12/2/2019 7:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11250+00
<b>State</b>	WV	<b>Inspection Area</b>	Partial	<b>Station End</b>	11320+00
<b>County</b>	Monroe	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	34.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? WV: Exceeding 7 days if to be left inactive for more than 21 days	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:56 AM	<b>Report #</b>	6266
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 37 For morning meeting No damaged ECD's observed during SWPPP inspection ECD's installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked row checking ECD's and making minor repairs to ECD's  1.6" of rain recorded @ Pocahontas, 1.4" of rain recorded @ LDY 37					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	12/2/2019 7:56 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, Dec 02, 2019, 07:56:55 EST Position: +37°29'1.87" / -83°44'33.67" (433.61) Altitude: 1844ft (437.21) Datum: WGS-84 Azimuth/Bearing: 157° S 57° S 538mils True (41°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0X 37</p>		 <p>Date &amp; Time: Mon, Dec 02, 2019, 08:12:43 EST Position: +37°25'1.91" / -83°44'28.25" (419.41) Altitude: 1844ft (+11.21) Datum: WGS-84 Azimuth/Bearing: 054° N 54E 0760mils True (51°) Elevation Grade: -007% Horizon Grade: +002% Zoom: 1.0X 1.4" @ 37</p>			
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates		
<b>Field Station#</b>	+37	<b>Field Station#</b>	+37		
<b>Pic 1 Desc.</b>	ECD's and row conditions	<b>Pic 2 Desc.</b>	1.4" of rain recorded		
 <p>Date &amp; Time: Mon, Dec 02, 2019, 07:56:55 EST Position: +37°29'1.87" / -83°44'33.67" (433.61) Altitude: 1844ft (437.21) Datum: WGS-84 Azimuth/Bearing: 301° S 57° S 538mils True (41°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0X 37</p>		 <p>Date &amp; Time: Mon, Dec 02, 2019, 07:56:55 EST Position: +37°29'1.87" / -83°44'33.67" (433.61) Altitude: 1844ft (437.21) Datum: WGS-84 Azimuth/Bearing: 301° S 57° S 538mils True (41°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0X 37</p>			
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates		
<b>Field Station#</b>	+37	<b>Field Station#</b>	+37		
<b>Pic 3 Desc.</b>	ECD's and row conditions	<b>Pic 4 Desc.</b>	ECD's and row conditions		
 <p>Date &amp; Time: Mon, Dec 02, 2019, 08:11:41 EST Position: +37°29'1.87" / -83°44'33.67" (433.61) Altitude: 1844ft (437.21) Datum: WGS-84 Azimuth/Bearing: 341° S 57° S 538mils True (41°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0X 37</p>		 <p>Date &amp; Time: Mon, Dec 02, 2019, 08:11:41 EST Position: +37°29'1.87" / -83°44'33.67" (433.61) Altitude: 1844ft (437.21) Datum: WGS-84 Azimuth/Bearing: 157° S 57° S 538mils True (41°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0X 37</p>			
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates		
<b>Field Station#</b>	+37	<b>Field Station#</b>	+37		
<b>Pic 5 Desc.</b>	ECD's and row conditions	<b>Pic 6 Desc.</b>	ECD's and row conditions secondary containment		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 7:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6284
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/2/2019 12:54 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	35.00
<b>Municipality</b>	N/A	<b>Weather</b>	Snow/Sleet	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 12:54 PM	<b>Report #</b>	6284
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Kow Camp Road - 1.1 inches, Mount Tabor Road - 1.5 inches, Steele Acres Road - 1.5 inches, and Access Road 244 - 1.6 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	12/2/2019 12:54 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Dec 02, 2019 08:42:53 EST  Position: +037.31697° / +080.65637° (+203ft)  Altitude: 1795ft (+61.5ft)  Datum: WGS-84  Azimuth/Bearing: 124° 58'55" 334mils True (+10°)  Elevation Angle: +02.0°  Horizon Angle: +01.3°  Zoom: 1.0x  LDY 26</p> 		<p>Date &amp; Time: Mon, Dec 02, 2019 08:43:00 EST  Position: +037.31697° / +080.65637° (+11.4ft)  Altitude: 1805ft (+11.5ft)  Datum: WGS-84  Azimuth/Bearing: 88° 00' 00" 142mils True (+10°)  Elevation Angle: +02.0°  Horizon Angle: +01.3°  Zoom: 1.0x  LDY 26</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Secondary containment in place under fuel cell.		<b>Pic 2 Desc.</b>	RCE in place employee parking in lay down yard 26.	
<p>Date &amp; Time: Mon, Dec 02, 2019 08:18:27 EST  Position: +037.334274° / +080.596147° (+541.4ft)  Altitude: 1710ft (+71.5ft)  Datum: WGS-84  Azimuth/Bearing: 30° 05'41" 544mils True (+10°)  Elevation Angle: +00.0°  Horizon Angle: +01.0°  Zoom: 1.0x  Kow Camp 1.1"</p> 		<p>Date &amp; Time: Mon, Dec 02, 2019 08:27:12 EST  Position: +037.31697° / +080.65637° (+57.1ft)  Altitude: 2161ft (+82.6ft)  Datum: WGS-84  Azimuth/Bearing: 355° 37'56" 631mils True (+14°)  Elevation Angle: +01.8°  Horizon Angle: +00.1°  Zoom: 1.0x  AR 244 1.6"</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10883+50		<b>Field Station#</b>	11025+00	
<b>Pic 3 Desc.</b>	Rain gauge at Kow Camp Road reads 1.1 inches.		<b>Pic 4 Desc.</b>	Rain gauge at Access Road 244 reads 1.6 inches.	
<p>Date &amp; Time: Mon, Dec 02, 2019 09:34:23 EST  Position: +037.20188° / +080.65637° (+100.1ft)  Altitude: 2230ft (+43.9ft)  Datum: WGS-84  Azimuth/Bearing: 15° 58'55" 354mils True (+14°)  Elevation Angle: +00.0°  Horizon Angle: +01.1°  Zoom: 1.0x  11471+00 1.5"</p> 		<p>Date &amp; Time: Mon, Dec 02, 2019 10:59:57 EST  Position: +037.24681° / +080.367668° (+43.1ft)  Altitude: 2015ft (+58.7ft)  Datum: WGS-84  Azimuth/Bearing: 355° 05'56" 631mils True (+14°)  Elevation Angle: +00.5°  Horizon Angle: +01.8°  Zoom: 1.0x  11767+00 1.5"</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11471+00		<b>Field Station#</b>	11767+00	
<b>Pic 5 Desc.</b>	Rain gauge at Steele Acres Road reads 1.5 inches.		<b>Pic 6 Desc.</b>	Rain gauge at Main Line Valve 26 reads 1.5 inches.	



<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 12:54 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 12:54 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6294
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	12/2/2019 3:16 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	Daily	<b>Station Begin</b>	11255+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11354+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	35.00
<b>Municipality</b>	N/A	<b>Weather</b>	Snow/Sleet	<b>Rain Gauge (in)</b>	1.70
				<b>Rain Accumulation Time (days)</b>	3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	12/2/2019 3:16 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, Dec 02, 2019, 06:27:19 EST Position: +037.300765 / -080.507232 (+49934.0m) Altitude: 2147ft (+173.6m) Datum: WGS-84 Azimuth/Bearing: 225 S45W 3004mils True (+14) Elevation Angle: -07.4 Horizon Angle: -01.7 Zoom: 1.0X Winding Way 1.7"</p>		 <p>Date &amp; Time: Mon, Dec 02, 2019, 07:58:00 EST Position: +037.300765 / -080.507232 (+49934.0m) Altitude: 2147ft (+173.6m) Datum: WGS-84 Azimuth/Bearing: 169 S1N 3004mils True (+14) Elevation Angle: -08.8 Horizon Angle: -00.8 Zoom: 1.0X 11258+00</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11227+00	<b>Field Station#</b>	11258+00		
<b>Pic 1 Desc.</b>	Rain gauge at Winding Way showing 1.7".	<b>Pic 2 Desc.</b>	Temporary stabilization.		
 <p>Date &amp; Time: Mon, Dec 02, 2019, 09:13:33 EST Position: +037.300765 / -080.507232 (+49934.0m) Altitude: 2147ft (+173.6m) Datum: WGS-84 Azimuth/Bearing: 169 S1N 3004mils True (+14) Elevation Angle: -14.9 Horizon Angle: -01.0 Zoom: 1.0X S-MM18</p>		 <p>Date &amp; Time: Mon, Dec 02, 2019, 09:13:33 EST Position: +037.300765 / -080.507232 (+49934.0m) Altitude: 2147ft (+173.6m) Datum: WGS-84 Azimuth/Bearing: 169 S1N 3004mils True (+14) Elevation Angle: -14.9 Horizon Angle: -01.0 Zoom: 1.0X S-MM18</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11265+50	<b>Field Station#</b>	11292+80		
<b>Pic 3 Desc.</b>	P-1 silt fence in good condition.	<b>Pic 4 Desc.</b>	S-MM18.		
 <p>Date &amp; Time: Mon, Dec 02, 2019, 09:17:27 EST Position: +037.300765 / -080.472888 (+49934.0m) Altitude: 2147ft (+173.6m) Datum: WGS-84 Azimuth/Bearing: 056 N56E 0990mils True (+23) Elevation Angle: -07.1 Horizon Angle: +02.5 Zoom: 1.0X S-NN12</p>		 <p>Date &amp; Time: Mon, Dec 02, 2019, 10:03:06 EST Position: +037.300765 / -080.472888 (+49934.0m) Altitude: 2147ft (+173.6m) Datum: WGS-84 Azimuth/Bearing: 136 S36W 3004mils True (+14) Elevation Angle: -03.1 Horizon Angle: +02.2 Zoom: 1.0X S-NN11</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11327+85	<b>Field Station#</b>	11352+97		
<b>Pic 5 Desc.</b>	S-NN12.	<b>Pic 6 Desc.</b>	S-NN11.		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 3:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/2/2019 3:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6325
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	12/3/2019 7:12 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10842+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10923+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	33.00
<b>Municipality</b>	N/A	<b>Weather</b>	Below Freezing Temp	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 7:12 AM	<b>Report #</b>	6325
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 205 - MP 207 No damaged ECD's were observed during SWPP inspection outside of PL items The ECD's installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked ROW checking ECD's and making minor repairs to ECD's Observed damaged P1SF, SSF and Curlex. Items added to PL					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 7:12 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	2+34		<b>Field Station#</b>	10859+00	
<b>Pic 1 Desc.</b>	Damaged curlex off AR 234		<b>Pic 2 Desc.</b>	Damaged SSF	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10855+00		<b>Field Station#</b>	10855+35	
<b>Pic 3 Desc.</b>	Damaged P1SF		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10878+00		<b>Field Station#</b>	10888+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 7:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 7:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6326
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/3/2019 7:13 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11022+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	25.00
<b>Municipality</b>	N/A	<b>Weather</b>	Below Freezing Temp	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 7:13 AM	<b>Report #</b>	6326
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11024+00 to 10930+00. MP- 208.6 to 206.2 Attended inspection meeting. The row is wet from recent rain events, but remains in stable condition with no sediment movement. Perimeter controls, P1 silt fence, CFS are in acceptable condition. SSF at sta#11015+00 has been damaged by a fallen tree, chain link and fabric crushed in two locations, issue has been Punch listed. Water bars are stable. Water bar end treatments are in acceptable condition. Streams S- IJ18, S-RR5, S-E24, S-E25— Equipment Bridges, stream ECD's, buffers, sensitive resource signage are in acceptable condition, with no sediment impacting streams. Karst and Karst ECD's and signage are in acceptable condition. AR-244 and Doe Creek RCE are maintained in acceptable condition. Doe Creek Farms have removed cattle from row and gates are closed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	12/3/2019 7:13 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Dec 03, 2019, 09:43:46 EST Position: +037.317173 / -080.538055 Altitude: 2103ft Datum: WGS-84 Azimuth/Bearing: 333° N27W 5920mils (True) Elevation Angle: +23.6° Horizon Angle: -03.1° Zoom: 1X Sta#11024+00 - Stream - SJ18 Stream ECD's bridge, signage are in acceptable condition.</p>		 <p>Date &amp; Time: Tue, Dec 03, 2019, 09:53:48 EST Position: +037.323416 / -080.554918 Altitude: 2398ft Datum: WGS-84 Azimuth/Bearing: 337° N23W 5991mils (True) Elevation Angle: +27.2° Horizon Angle: -02.1° Zoom: 1X Sta#11017+00 - S-RR5 - Stream ECD's bridge, signage are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11024+00		<b>Field Station#</b>	11017+00	
<b>Pic 1 Desc.</b>	Stream S-IJ18- Equipment bridge, ECD's, signage, buffers are in acceptable condition		<b>Pic 2 Desc.</b>	Stream S-RR5- Equipment bridge, buffers, ECD's, signage are in acceptable condition	
 <p>Date &amp; Time: Tue, Dec 03, 2019, 10:00:05 EST Position: +037.323401 / -080.556026 Altitude: 2446ft Datum: WGS-84 Azimuth/Bearing: 022° N20E 0356mils (True) Elevation Angle: +15.4° Horizon Angle: -07.2° Zoom: 1X Sta#11015+00 - Tree down on SSF above stream S-RR5</p>		 <p>Date &amp; Time: Tue, Dec 03, 2019, 10:22:21 EST Position: +037.319214 / -080.637830 Altitude: 0ft Datum: WGS-84 Azimuth/Bearing: 022° N22E 0391mils (True) Elevation Angle: +23.8° Horizon Angle: -03.6° Zoom: 1X Sta#10986+00 Stream S-E25</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11015+00		<b>Field Station#</b>	10986+00	
<b>Pic 3 Desc.</b>	Tree fell on SSF crushing chain link fence and fabric in two locations.		<b>Pic 4 Desc.</b>	Stream S-E25- Equipment bridge, buffers, ECD's, signage are in acceptable condition	
 <p>Date &amp; Time: Tue, Dec 03, 2019, 10:42:20 EST Position: +037.325488 / -080.564895 Altitude: 2788ft Datum: WGS-84 Azimuth/Bearing: 334° N23W 5973mils (True) Elevation Angle: +23.4° Horizon Angle: -04.2° Zoom: 1X Sta#10985+00 Stream - S-E24</p>		 <p>Date &amp; Time: Tue, Dec 03, 2019, 10:47:03 EST Position: +037.325488 / -080.564895 Altitude: 2688ft Datum: WGS-84 Azimuth/Bearing: 027° N23W 6123mils (True) Elevation Angle: +20.2° Horizon Angle: -00.2° Zoom: 0.5 Sta#10965+00 - Karst Karst ECD's and signage are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10985+00		<b>Field Station#</b>	10965+00	
<b>Pic 5 Desc.</b>	Stream S-E24- Equipment bridge, buffers, signage, ECD's are in acceptable condition		<b>Pic 6 Desc.</b>	Karst and Karst ECD's and sensitive resource signage are in acceptable condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 7:13 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 7:13 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report




<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6334
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/3/2019 2:28 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10832+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	35.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 2:28 PM	<b>Report #</b>	6334
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 204.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	12/3/2019 2:28 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Safety fence blow off stakes. Contractor informed and agreed to repair safety fence.		<b>Pic 2 Desc.</b>	Compost filter sock check in place in bar ditch along AR 241.04.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10750+00		<b>Field Station#</b>	10710+00	
<b>Pic 3 Desc.</b>	Sensitive resource buffer in place at stream S-G33.		<b>Pic 4 Desc.</b>	ROW stabilized with natural vegetation.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10698+00		<b>Field Station#</b>	10696+00	
<b>Pic 5 Desc.</b>	Sensitive resource buffer in place at stream S-G32.		<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 2:28 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 2:28 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6340
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	12/3/2019 3:33 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11024+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11065+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	37.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 3:33 PM	<b>Report #</b>	6340
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection from MP 208.6 to 209.3. No major issues were located. Four locations of reinforced silt fence that has detached from chain link near 11024+50, 11051+95, 11052+75 and 11065+10 as well as one location of P-1 silt fence partially down near 11050+60. The items were placed on the punch list after notifying Precision Environmental Coordinator Mike Perry. Mr Perry stated that crews would attempt to begin repairs today. Sent photos to Lead EI Brian Shields and Land Agent Rolland Dean of a downed tree that fell from off RoW and damaged barbed wire fence on the edge of RoW LoD near 11032+00.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/3/2019 3:33 PM	Report #	
Pictures					
 <p>Date &amp; Time: Tue Dec 03 2019 09:51:04 EST Position: +037.322724 / -080.552451 (+19.7ft) Altitude: 2428ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 026° N26E 0462mils True (±15°) Elevation Angle: -08.0° Horizon Angle: -03.0° Zoom: 1.0x 11026+00</p>		 <p>Date &amp; Time: Tue Dec 03 2019 09:54:31 EST Position: +037.321650 / -080.551197 (+19.7ft) Altitude: 2378ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 298° N22W 038mils True (±18°) Elevation Angle: -15.8° Horizon Angle: -03.7° Zoom: 1.0x 11032+00</p>			
GPS Location	1	GPS Location	2		
Field Station#	11026+00	Field Station#	11032+00		
Pic 1 Desc.	S-IJ18.	Pic 2 Desc.	Downed tree from off RoW that damaged the barbed wire fence on the edge of the RoW LoD.		
 <p>Date &amp; Time: Tue Dec 03 2019 10:09:50 EST Position: +037.321656 / -080.551108 (+19.7ft) Altitude: 2378ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 104° S04W 3307mils True (±15°) Elevation Angle: -03.0° Horizon Angle: -01.1° Zoom: 1.0x 11032+00</p>		 <p>Date &amp; Time: Tue Dec 03 2019 10:09:50 EST Position: +037.321656 / -080.551108 (+19.7ft) Altitude: 2378ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 104° S04W 3307mils True (±15°) Elevation Angle: -03.0° Horizon Angle: -01.1° Zoom: 1.0x 11032+00</p>			
GPS Location	3	GPS Location	4		
Field Station#	11032+00	Field Station#	11050+14		
Pic 3 Desc.	Stabilization/vegetation.	Pic 4 Desc.	S-IJ16 11050+14, S-IJ17 11050+10.		
 <p>Date &amp; Time: Tue Dec 03 2019 10:22:13 EST Position: +037.317400 / -080.550716 (+19.7ft) Altitude: 2150ft (+8.2ft) Datum: WGS-84 Azimuth/Bearing: 002° N02E 0095mils True (±15°) Elevation Angle: -05.2° Horizon Angle: -01.2° Zoom: 1.0x 11054+00</p>		 <p>Date &amp; Time: Tue Dec 03 2019 10:22:13 EST Position: +037.317400 / -080.550716 (+19.7ft) Altitude: 2150ft (+8.2ft) Datum: WGS-84 Azimuth/Bearing: 110° S70E 1956mils True (±18°) Elevation Angle: -09.9° Horizon Angle: -01.2° Zoom: 1.0x 11055+00</p>			
GPS Location	5	GPS Location	6		
Field Station#	11054+00	Field Station#	11055+00		
Pic 5 Desc.	P-1 perimeter controls in good condition.	Pic 6 Desc.	Karst: ECDs functional		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 3:33 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/3/2019 3:33 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6356
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	12/4/2019 7:16 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11255+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11354+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	46.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			







## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:16 AM	<b>Report #</b>	6356
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection from MP 213 to MP 214.8. No issues were located. Temporary stabilization or vegetation is sufficient.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:16 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11258+50	<b>Field Station#</b>	11265+00		
<b>Pic 1 Desc.</b>	Temporary stabilization.	<b>Pic 2 Desc.</b>	P-1 perimeter control in good condition.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11292+80	<b>Field Station#</b>	11327+85		
<b>Pic 3 Desc.</b>	S-MM18	<b>Pic 4 Desc.</b>	S-NN12.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11329+00	<b>Field Station#</b>	11352+97		
<b>Pic 5 Desc.</b>	Temporary stabilization.	<b>Pic 6 Desc.</b>	S-NN11.		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:16 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:16 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6357
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/4/2019 7:19 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11161+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Slope Drain Pipe	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





<b>AFE</b>	124300137	<b>Date/Time</b>	12/4/2019 7:19 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11227+00		<b>Field Station#</b>	11225+00	
<b>Pic 1 Desc.</b>	Row temporary stabilization is acceptable.		<b>Pic 2 Desc.</b>	Slope drain, sump, end treatment, and rock channel are in acceptable condition.	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11216+00		<b>Field Station#</b>	11191+00	
<b>Pic 3 Desc.</b>	Slope drain, P1 checks, sump and end treatment are in acceptable condition.		<b>Pic 4 Desc.</b>	Equipment bridge, drainage feature and ECD's, and sensitive resource signage are in acceptable condition.	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11184+00		<b>Field Station#</b>	11184+50	
<b>Pic 5 Desc.</b>	CWD pipe and plunge pool are in good condition.		<b>Pic 6 Desc.</b>	AR-249.02 is maintained in acceptable condition	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:19 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:19 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6358
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	12/4/2019 7:51 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11065+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11130+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	30.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	12/4/2019 7:51 AM	<b>Report #</b>	6358
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 209.3 - MP 211 No damaged ECD's observed during inspection ECD's installed per spec and per the E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No punchlist items found on walk					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	12/4/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	2+34		<b>Field Station#</b>	11065+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11090+00		<b>Field Station#</b>	11098+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11118+00		<b>Field Station#</b>	11122+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6358
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	12/4/2019 7:51 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11065+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11130+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	30.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	12/4/2019 7:51 AM	<b>Report #</b>	6358
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 209.3 - MP 211 No damaged ECD's observed during inspection ECD's installed per spec and per the E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No punchlist items found on walk					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	2+34		<b>Field Station#</b>	11065+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11090+00		<b>Field Station#</b>	11098+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11118+00		<b>Field Station#</b>	11122+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 7:51 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6368
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/4/2019 3:00 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11525+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11351+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 3:00 PM	<b>Report #</b>	6368
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	12/4/2019 3:00 PM	Report #	
Pictures					
					
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11491+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Waterbar, sump pit, and waterbar end treatment in place.		<b>Pic 2 Desc.</b>	
					
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11488+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Clean water diversion pipe and plunge pool in place.		<b>Pic 4 Desc.</b>	
					
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11474+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Slope drain in place with rock inlet and outlet in place over two tone. Two tone Stabilized with ECB.		<b>Pic 6 Desc.</b>	
				CFS checks in place along Steele Acres access road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 3:00 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/4/2019 3:00 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6389
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/5/2019 7:27 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11900+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12000+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.



<b>AFE</b>	124300137	<b>Date/Time</b>	12/5/2019 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Dec 05, 2019, 10:06:15 EST  Position: +331.2310077, -74.08339515*  Altitude: 2290ft  Datum: WGS-84  Azimuth/Bearing: 245.545W, 4358mils True  Elevation Angle: +25.2  Horizon Angle: -04.2  Zoom: 1X  Star#11908-03- Roadside ditch and controls are in good condition.</p> 		<p>Date &amp; Time: Thu, Dec 05, 2019, 10:08:58 EST  Position: +337.2866771, -74.08339515*  Altitude: 2290ft  Datum: WGS-84  Azimuth/Bearing: 322.338W, 5724mils True  Elevation Angle: +20.9  Horizon Angle: -02.4  Zoom: 1X  Star#11908-00- Water bars &amp; level spreaders are in good condition in this inspection area.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11900+00		<b>Field Station#</b>	11908+00	
<b>Pic 1 Desc.</b>	Roadside ditch and controls are in acceptable condition.		<b>Pic 2 Desc.</b>	Level spreaders are in good condition condition	
<p>Date &amp; Time: Thu, Dec 05, 2019, 10:37:30 EST  Position: +337.2797481, -74.08339747*  Altitude: 2290ft  Datum: WGS-84  Azimuth/Bearing: 331.129W, 5884mils True  Elevation Angle: +14.8  Horizon Angle: -01.3  Zoom: 1X  Star#11942-00- Karst P1 check</p> 		<p>Date &amp; Time: Thu, Dec 05, 2019, 10:38:27 EST  Position: +337.2784811, -74.08339747*  Altitude: 2209ft  Datum: WGS-84  Azimuth/Bearing: 322.132W, 5942mils True  Elevation Angle: +19.5  Horizon Angle: -01.0  Zoom: 1X  Star#11942-00- Karst P1 check outside LODs down</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11942+00		<b>Field Station#</b>	11942+50	
<b>Pic 3 Desc.</b>	P1 perimeter control stake snapped off, fence down, Karst area, LOD.		<b>Pic 4 Desc.</b>	P1 check down outside LOD in Karst area	
<p>Date &amp; Time: Thu, Dec 05, 2019, 10:43:30 EST  Position: +337.2784811, -74.08339747*  Altitude: 2160ft  Datum: WGS-84  Azimuth/Bearing: 025.124W, 5716mils True  Elevation Angle: +16.0  Horizon Angle: -01.0  Zoom: 1X  Star#11943-75 P1 check outside LODs, shredded large holes in fabric</p> 		<p>Date &amp; Time: Thu, Dec 05, 2019, 10:48:55 EST  Position: +337.2784811, -74.08339747*  Altitude: 2160ft  Datum: WGS-84  Azimuth/Bearing: 025.124W, 5716mils True  Elevation Angle: +16.0  Horizon Angle: -01.0  Zoom: 1X  Star#11943-75 P1 check outside LODs, shredded large holes in fabric</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11942+60		<b>Field Station#</b>	1943+75	
<b>Pic 5 Desc.</b>	P1 check fabric shredded outside LOD in Karst area		<b>Pic 6 Desc.</b>	P1 wooden stake snapped off, fence down.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6390
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	12/5/2019 8:17 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11520+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11630+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 8:17 AM	<b>Report #</b>	6390
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting and attended contractor weekly safety meeting No damaged ECD's observed during SWPPP inspection other than the item added to PL ECD's are installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Crews walked ROW checking ECD's and making minor repairs to ECD's Tree fell onto ROW damaging P1SF @ 11534+00					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	12/5/2019 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu Dec 05 2019 10:57:15 EST  Position: +037 19 44.69 - -080 25 10.32 116016.3ft  Altitude: 2282ft 116016.3ft  Datum: WGS 84  Azimuth/Bearing: 147.533E 2613mils True 113.1  Elevation Grade: +021  Horizon Grade: +001  Zoom: 1.0X  11530</p> 		<p>Date &amp; Time: Thu Dec 05 2019 11:01:25 EST  Position: +037 19 44.69 - -080 25 10.32 116016.3ft  Altitude: 2283ft 116016.3ft  Datum: WGS 84  Azimuth/Bearing: 151.511W 3326mils True 113.1  Elevation Grade: +011  Horizon Grade: +002  Zoom: 1.0X  11530</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11530+00		<b>Field Station#</b>	11534+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Thu Dec 05 2019 11:03:11 EST  Position: +037 19 44.69 - -080 25 10.32 116016.3ft  Altitude: 2279ft 116016.3ft  Datum: WGS 84  Azimuth/Bearing: 147.533E 2613mils True 113.1  Elevation Grade: +001  Horizon Grade: +001  Zoom: 1.0X  11570</p> 		<p>Date &amp; Time: Thu Dec 05 2019 11:03:11 EST  Position: +037 19 44.69 - -080 25 10.32 116016.3ft  Altitude: 2279ft 116016.3ft  Datum: WGS 84  Azimuth/Bearing: 147.533E 2613mils True 113.1  Elevation Grade: +001  Horizon Grade: +001  Zoom: 1.0X  11570</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11552+00		<b>Field Station#</b>	11570+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Thu Dec 05 2019 12:12:28 EST  Position: +037 19 44.69 - -080 25 11.66 116016.3ft  Altitude: 2250ft 116016.3ft  Datum: WGS 84  Azimuth/Bearing: 107.540E 1112mils True 113.1  Elevation Grade: +019  Horizon Grade: +001  Zoom: 2.0X  11570</p> 		<p>Date &amp; Time: Thu Dec 05 2019 12:12:28 EST  Position: +037 19 44.69 - -080 25 11.66 116016.3ft  Altitude: 2250ft 116016.3ft  Datum: WGS 84  Azimuth/Bearing: 107.540E 1112mils True 113.1  Elevation Grade: +019  Horizon Grade: +001  Zoom: 2.0X  11570</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11570+00		<b>Field Station#</b>	11570+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6391
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	12/5/2019 8:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11789+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11900+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	46.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 8:40 AM	<b>Report #</b>	6391
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended Precisions weekly safety meeting. Attended the morning inspection meeting. Performed SWPPP inspection from MP 223.3 to MP 224.3 as well as AR 266.03. No major issues were located. A few minor wind or cattle caused damage to P-1 or or SSF and a small rill erosion within RoW limits were punch listed to be repaired on 12/6/2019.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	12/5/2019 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Dec 05, 2019, 09:43:41 EST  Position: +037.295447° / -080.356100° (+33.37ft)  Altitude: 2197ft (+10.4ft)  Datum: WGS-84  Azimuth/Bearing: 152° S82E 3547mils True (+17.1)  Elevation Angle: +00.8°  Horizon Angle: +00.0°  Zoom: 1.0X  11789+00</p> 		<p>Date &amp; Time: Thu, Dec 05, 2019, 09:58:07 EST  Position: +037.296249° / -080.358405° (+378.7ft)  Altitude: 1987ft (+10.6ft)  Datum: WGS-84  Azimuth/Bearing: 098° S82E 1742mils True (+17.1)  Elevation Angle: +00.8°  Horizon Angle: +00.0°  Zoom: 1.0X  11797+50</p> 			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11789+00	<b>Field Station#</b>	11797+50		
<b>Pic 1 Desc.</b>	RCE off of Mt Tabor rd.		<b>Pic 2 Desc.</b>	Restored RoW.	
<p>Date &amp; Time: Thu, Dec 05, 2019, 10:07:16 EST  Position: +037.295796° / -080.352689° (+52.5ft)  Altitude: 2198ft (+10.4ft)  Datum: WGS-84  Azimuth/Bearing: 225° S45W 4000mils True (+17.1)  Elevation Angle: +01.0°  Horizon Angle: +01.5°  Zoom: 1.0X  11814+75</p> 		<p>Date &amp; Time: Thu, Dec 05, 2019, 10:10:31 EST  Position: +037.299766° / -080.348495° (+52.5ft)  Altitude: 2161ft (+10.4ft)  Datum: WGS-84  Azimuth/Bearing: 180° S24W 3297mils True (+23.1)  Elevation Angle: +01.0°  Horizon Angle: +00.8°  Zoom: 1.0X  11841+00</p> 			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11814+75	<b>Field Station#</b>	11841+00		
<b>Pic 3 Desc.</b>	Water bar outlet protection.		<b>Pic 4 Desc.</b>	Restored RoW.	
<p>Date &amp; Time: Thu, Dec 05, 2019, 10:30:27 EST  Position: +037.295345° / -080.347321° (+90.5ft)  Altitude: 2204ft (+10.4ft)  Datum: WGS-84  Azimuth/Bearing: 051° N32E 0924mils True (+22.1)  Elevation Angle: +19.2°  Horizon Angle: +01.0°  Zoom: 1.0X  11863+65</p> 		<p>Date &amp; Time: Thu, Dec 05, 2019, 11:11:49 EST  Position: +037.297799° / -080.334548° (+19.7ft)  Altitude: 2239ft (+10.3ft)  Datum: WGS-84  Azimuth/Bearing: 259° S79W 4604mils True (+18.1)  Elevation Angle: +02.2°  Horizon Angle: +00.6°  Zoom: 1.0X  11900+00</p> 			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	111863+65	<b>Field Station#</b>	11900+00		
<b>Pic 5 Desc.</b>	P-KL2.		<b>Pic 6 Desc.</b>	Restored RoW.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6400
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	12/5/2019 2:10 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+12
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11669+87
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	49.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 2:10 PM	<b>Report #</b>	6400
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VADEQ SWPPP inspection on private tracts and JNF property on Brush Mountain. The ECDs are in place and functional. No maintenance needs were identified. Winter grasses in hydro mulch and straw mulch used for stabilization is effective. No erosion or slips were located. Resource crossings are stable with well vegetated buffers and ECDs as required. Slope breakers are working properly. End treatments are working properly. No environmental concerns were identified.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 2:10 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11663+00	<b>Field Station#</b>	11664+00		
<b>Pic 1 Desc.</b>	Perimeter controls and end treatments functional	<b>Pic 2 Desc.</b>	Perimeter controls and end treatments functional		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11656+00	<b>Field Station#</b>	11637+50		
<b>Pic 3 Desc.</b>	Perimeter controls and end treatments functional	<b>Pic 4 Desc.</b>	Perimeter controls and end treatments functional		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11637+00	<b>Field Station#</b>	11632+50		
<b>Pic 5 Desc.</b>	Hydro seeded JNF ROW is stable with no erosion issues located	<b>Pic 6 Desc.</b>	Hydro seeded JNF ROW is stable with no erosion issues located		



<b>AFE</b>	124300137	<b>Date/Time</b>	12/5/2019 2:10 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Dec 05, 2019, 1:55:55 EST Position: +037.313584° / -080.405273° (+14.4ft) Altitude: 1916ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 137° S43E 243mils Magnetic (+12°) Elevation Angle: +04.5° Horizon Angle: +01.3° Zoom: 1.0X Brush Mat Controls in place Effective S-HH18 crossing 11629+00</p>		 <p>Date &amp; Time: Thu, Dec 05, 2019, 1:55:55 EST Position: +037.313584° / -080.405273° (+14.4ft) Altitude: 1916ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 137° S43E 243mils Magnetic (+12°) Elevation Angle: +04.5° Horizon Angle: +01.3° Zoom: 1.0X Brush Mat Controls in place Effective S-HH18 crossing 11626+04</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11629+00	<b>Field Station#</b>	11626+04		
<b>Pic 7 Desc.</b>	Perimeter controls are in place and functional	<b>Pic 8 Desc.</b>	S-HH18 crossing stable		
 <p>Date &amp; Time: Thu, Dec 05, 2019, 12:14:40 EST Position: +037.313582° / -080.404422° (+3715.8ft) Altitude: 1888ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 137° S43E 243mils Magnetic (+12°) Elevation Angle: +04.5° Horizon Angle: +01.3° Zoom: 1.0X Brush Mat S-RR14 crossing stable</p>		 <p>Date &amp; Time: Thu, Dec 05, 2019, 12:14:40 EST Position: +037.313582° / -080.404422° (+3715.8ft) Altitude: 1888ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 145° S35E 257mils Magnetic (+12°) Elevation Angle: +11.2° Horizon Angle: +00.4° Zoom: 1.0X Brush Mat S-006 crossing stable</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11614+20	<b>Field Station#</b>	11607+81		
<b>Pic 9 Desc.</b>	Resource crossing S-RR14 crossing stable.	<b>Pic 10 Desc.</b>	S-006 crossing stable		
 <p>Date &amp; Time: Thu, Dec 05, 2019, 12:15:44 EST Position: +037.313648° / -080.405273° (+16.4ft) Altitude: 1817ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 289° S88W 476mils Magnetic (+12°) Elevation Angle: +01.3° Horizon Angle: +00.4° Zoom: 1.0X Brush Mat ROW stable</p>		<p>Insert image here</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>			
<b>Field Station#</b>	11606+00	<b>Field Station#</b>			
<b>Pic 11 Desc.</b>	Straw mulch covered private tract stable with necessary controls in place.	<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 2:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6402
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/5/2019 2:58 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	48.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 2:58 PM	<b>Report #</b>	6402
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 2:58 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Dec 05, 2019 11:35:55 Position: +037.299628° / -080.391291° (+23.4m) Altitude: 2072ft (+32.6m) Datum: WGS-84 Azimuth/Bearing: 189° S09W 3360mils True (±12°) Elevation Angle: -25.1° Horizon Angle: +00.6° Zoom: 1.0X 11670+00</p>		 <p>Date &amp; Time: Thu, Dec 05, 2019 11:35:55 Position: +037.299628° / -080.391291° (+23.4m) Altitude: 2072ft (+32.6m) Datum: WGS-84 Azimuth/Bearing: 189° S09W 3360mils True (±12°) Elevation Angle: -25.1° Horizon Angle: +00.6° Zoom: 1.0X 11670+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11670+00		<b>Field Station#</b>	11681+00	
<b>Pic 1 Desc.</b>	Waterbar, sump pit, and end treatment in place.		<b>Pic 2 Desc.</b>	ROW has been stabilized with seed and mulch. Minor vegetation growth present.	
 <p>Date &amp; Time: Thu, Dec 05, 2019 12:08:00 EST Position: +037.299628° / -080.391291° (+23.4m) Altitude: 2072ft (+32.6m) Datum: WGS-84 Azimuth/Bearing: 267° S87W 4747mils True (±12°) Elevation Angle: -13.9° Horizon Angle: +07.3° Zoom: 1.0X 11747+00</p>		 <p>Date &amp; Time: Thu, Dec 05, 2019 11:35:17 EST Position: +037.299628° / -080.391291° (+23.4m) Altitude: 2449ft (+52.4m) Datum: WGS-84 Azimuth/Bearing: 168° S12E 2987mils True (±13°) Elevation Angle: -16.7° Horizon Angle: +02.1° Zoom: 1.0X 11687+40 S-MN21</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11747+00		<b>Field Station#</b>	11687+40	
<b>Pic 3 Desc.</b>	ROW has been stabilized with seed and mulch. Minor vegetation growth present. Waterbar, sump pit, and end treatment in place.		<b>Pic 4 Desc.</b>	Sensitive resource buffer in place at stream S-MN21.	
 <p>Date &amp; Time: Thu, Dec 05, 2019 12:08:00 EST Position: +037.299628° / -080.391291° (+23.4m) Altitude: 2134ft (+59.1m) Datum: WGS-84 Azimuth/Bearing: 174° S04E 3129mils True (±12°) Elevation Angle: -42.4° Horizon Angle: +06.2° Zoom: 1.0X 11759+00</p>		 <p>Date &amp; Time: Thu, Dec 05, 2019 12:10:25 EST Position: +037.299628° / -080.391291° (+23.4m) Altitude: 2134ft (+59.1m) Datum: WGS-84 Azimuth/Bearing: 113° S67E 2009mils True (±12°) Elevation Angle: -07.7° Horizon Angle: +06.2° Zoom: 1.0X 11767+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11759+00		<b>Field Station#</b>	11767+00	
<b>Pic 5 Desc.</b>	Reinforced super silt fence in place along LOD.		<b>Pic 6 Desc.</b>	RCE in place at Main Line Valve 26.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 2:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/5/2019 2:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6423
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	12/6/2019 7:11 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	Daily	<b>Station Begin</b>	11789+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11856+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 7:11 AM	<b>Report #</b>	6423
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Observed crews repairing punch list items and ECDs between Mt Tabor rd and station 11856+00. All punch list items were completed in this area. Spoke with Lead EI Brian Shields and Precision Environmental Coordinator Mike Perry about re-seeding and curlexing a portion of the previously restored side slope between 11836+75 and 11837+15.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	12/6/2019 7:11 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11853+75	<b>Field Station#</b>	11846+25		
<b>Pic 1 Desc.</b>	Crews repairing P-1 silt fence.		<b>Pic 2 Desc.</b>	Repaired P-1 silt fence.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11844+25	<b>Field Station#</b>	11836+75		
<b>Pic 3 Desc.</b>	Reattaching SSF fabric to chain link.		<b>Pic 4 Desc.</b>	Repaired punch list item, removed sediment from CFS.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11798+50	<b>Field Station#</b>	11798+50		
<b>Pic 5 Desc.</b>	Crews installing curlex.		<b>Pic 6 Desc.</b>	Completed rill removal, re-seeding and curlexing.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 7:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 7:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6424
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	12/6/2019 7:18 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11250+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11520+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	28.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock				
Erosion Control Blanket				
Housekeeping				
Rock Construction Entrance				
Secondary Containment				
Sensitive Resource Buffer				
Vegetative Stabilization (Temporary)				

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 7:18 AM	<b>Report #</b>	6424
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 No damaged ECD's observed during inspection ECD's are installed per spec and per E&S plans ROW conditions are stable and showing good signs of vegetation LDY has several pieces of equipment have secondary containment No signs of sediment outside of LOD or impacting any sensitive resources No punchlist items observed during inspection					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	12/6/2019 7:18 AM	Report #	
Pictures					
 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:07:48 EST Position: +37°23.10'N / -80°45'39.25" W (19.87) Altitude: 1547ft (478.6m) Datum: WGS-84 Azimuth Bearing: 000° 00'00" Azimuth True (±1°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0x 28</p>		 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:08:25 EST Position: +37°23.10'N / -80°45'39.25" W (19.87) Altitude: 1547ft (478.6m) Datum: WGS-84 Azimuth Bearing: 000° 00'00" Azimuth True (±1°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0x 28</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+28		Field Station#	+28	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:11:49 EST Position: +37°19'54.01" N / -80°45'21.25" W (19.88) Altitude: 1557ft (478.3m) Datum: WGS-84 Azimuth Bearing: 240° 00'00" Azimuth True (±1°) Elevation Grade: +00% Horizon Grade: -00% Zoom: 1.0x 28</p>		 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:14:19 EST Position: +37°20'1.67" N / -80°45'39.38" W (19.91) Altitude: 1550ft (475.5m) Datum: WGS-84 Azimuth Bearing: 000° 00'00" Azimuth True (±1°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0x 28</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+28		Field Station#	+28	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:16:28 EST Position: +37°20'1.17" N / -80°45'12.21" W (19.92) Altitude: 1557ft (478.3m) Datum: WGS-84 Azimuth Bearing: 330° 00'00" Azimuth True (±1°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0x 28</p>		 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:17:15 EST Position: +37°20'2.42" N / -80°45'11.44" W (19.93) Altitude: 1570ft (478.6m) Datum: WGS-84 Azimuth Bearing: 000° 00'00" Azimuth True (±1°) Elevation Grade: -00% Horizon Grade: +00% Zoom: 1.0x 28</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+28		Field Station#	+28	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 7:18 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 7:18 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6425
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/6/2019 8:26 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	30.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 8:26 AM	<b>Report #</b>	6425
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: LY-29 AR-238.00- Access road coming into LY29 is maintained in acceptable condition. The rock surface of the yard is maintained in acceptable condition. CFS triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. Overhead flagging & goal posts are in acceptable condition. Materials storage and house keeping are acceptable. LY-29 is not active, PPL environmental crew doing maintenance as needed. There are no mechanical equipment stored in the yard.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	12/6/2019 8:26 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Dec 06, 2019, 08:55:41 EST Position: +037.36222° / -080.67784° Altitude: 1711ft Datum: WGS-84 Azimuth/Bearing: 19° S19°W 308m (True) Elevation Angle: +54.3° Horizon Angle: -05.7° Zoom: 1X LY-29 - Arnold's materials storage.</p>		 <p>Date &amp; Time: Fri, Dec 06, 2019, 08:55:38 EST Position: +037.36222° / -080.67782° Altitude: 1710ft Datum: WGS-84 Azimuth/Bearing: 08° N92°W 080m (True) Elevation Angle: +18.0° Horizon Angle: -00.0° Zoom: 0.8° LY-29- Culvert under road for drainage ditch is in good condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	LY- 29- Arnold's materials storage.		<b>Pic 2 Desc.</b>	Culvert Under access road for drainage ditch is in good condition.	
 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:07:04 EST Position: +037.36211° / -080.67355° Altitude: 1704ft Datum: WGS-84 Azimuth/Bearing: 02° N92°W 655m (True) Elevation Angle: +19.7° Horizon Angle: -02.9° Zoom: 1X LY-29- CFS triple stack perimeter controls are in acceptable condition.</p>		 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:11:38 EST Position: +037.36260° / -080.67732° Altitude: 1723ft Datum: WGS-84 Azimuth/Bearing: 262° S92°W 465m (True) Elevation Angle: +24.2° Horizon Angle: -06.5° Zoom: 1X LY-29- PPL materials storage, house keeping is acceptable.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	LY-29- CFS triple stack perimeter controls are in acceptable condition.		<b>Pic 4 Desc.</b>	LY-29- PPL Materials storage, house keeping is acceptable.	
 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:14:01 EST Position: +037.35302° / -080.67664° Altitude: 1721ft Datum: WGS-84 Azimuth/Bearing: 80° N90°W 555m (True) Elevation Angle: +30.1° Horizon Angle: -05.4° Zoom: 1X LY-29- Rock surface of the yard is maintained in acceptable condition.</p>		 <p>Date &amp; Time: Fri, Dec 06, 2019, 09:19:56 EST Position: +037.36493° / -080.67420° Altitude: 1763ft Datum: WGS-84 Azimuth/Bearing: 110° S70°E 195m (True) Elevation Angle: +24.4° Horizon Angle: -06.1° Zoom: 1X AR-238.00- Access road coming into LY-29 is maintained in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	LY- 29- Rock surface of the yard is maintained in acceptable condition.		<b>Pic 6 Desc.</b>	AR-238.00- Access road coming into LY-29 is maintained in acceptable condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 8:26 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 8:26 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6447
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/6/2019 3:17 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 3:17 PM	<b>Report #</b>	6447
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time	12/6/2019 3:17 PM	Report #	
Pictures					
<p>Date &amp; Time Fri, Dec 6, 2019, 09:40:23 Position: +48.21667° / +80.55556° (43.07) Altitude: 1930 (43.07) Datum: WGS-84 Azimuth/Heading: 120° N30E 100mils True (43.07) Elevation Angle: -0.1° Tilt/Lean Angle: +0.1° Zoom: 1.0x LDY 26</p> 		<p>Date &amp; Time Fri, Dec 6, 2019, 09:40:23 Position: +48.21667° / +80.55556° (43.07) Altitude: 1930 (43.07) Datum: WGS-84 Azimuth/Heading: 120° N30E 100mils True (43.07) Elevation Angle: -0.1° Tilt/Lean Angle: +0.1° Zoom: 1.0x LDY 26</p> 			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Dumpster being utilized for trash management.		<b>Pic 2 Desc.</b>	
<p>Date &amp; Time Fri, Dec 6, 2019, 09:40:23 Position: +48.21667° / +80.55556° (43.07) Altitude: 1930 (43.07) Datum: WGS-84 Azimuth/Heading: 120° N30E 100mils True (43.07) Elevation Angle: -0.1° Tilt/Lean Angle: +0.1° Zoom: 1.0x LDY 26</p> 		<p>Date &amp; Time Fri, Dec 6, 2019, 09:40:23 Position: +48.21667° / +80.55556° (43.07) Altitude: 1930 (43.07) Datum: WGS-84 Azimuth/Heading: 120° N30E 100mils True (43.07) Elevation Angle: -0.1° Tilt/Lean Angle: +0.1° Zoom: 1.0x LDY 26</p> 			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Secondary containment in place under light plant and port-a-potties.		<b>Pic 4 Desc.</b>	
<p>Date &amp; Time Fri, Dec 6, 2019, 09:40:23 Position: +48.21667° / +80.55556° (43.07) Altitude: 1930 (43.07) Datum: WGS-84 Azimuth/Heading: 120° N30E 100mils True (43.07) Elevation Angle: -0.1° Tilt/Lean Angle: +0.1° Zoom: 1.0x LDY 26</p> 		<p>Date &amp; Time Fri, Dec 6, 2019, 09:40:23 Position: +48.21667° / +80.55556° (43.07) Altitude: 1930 (43.07) Datum: WGS-84 Azimuth/Heading: 120° N30E 100mils True (43.07) Elevation Angle: -0.1° Tilt/Lean Angle: +0.1° Zoom: 1.0x LDY 26</p> 			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Secondary containment in place under fuel cell.		<b>Pic 6 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 3:17 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/6/2019 3:17 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		