



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6958
<b>Inspector</b>	Brian Shields			<b>Date/Time</b>	12/30/2019 8:37 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+88
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+12
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 8:37 AM	<b>Report #</b>	6958
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
VA swppp inspection MP 213.16 to 211.33 installed perimeter controls are functioning as designed with no maintenance needed ROW is stable with little to no sediment movement observed. waterbars and sumps are functioning as designed no maintenance needs observed during in8 0.1 inches of rain recorded st winding way rain gauge					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 8:37 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11222+00		<b>Field Station#</b>	11218+50	
<b>Pic 1 Desc.</b>	stabilized ROW conditions		<b>Pic 2 Desc.</b>	installed waterbar, no maintenance needed	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11210+00		<b>Field Station#</b>	11185+00	
<b>Pic 3 Desc.</b>	installed sump and end treatment		<b>Pic 4 Desc.</b>	installed plunge pool	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11211+00		<b>Field Station#</b>	11201+50	
<b>Pic 5 Desc.</b>	stabilized ROW conditions		<b>Pic 6 Desc.</b>	installed sump and end treatment	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 8:37 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 8:37 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6960
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	12/30/2019 8:52 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11250+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11130+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 8:52 AM	<b>Report #</b>	6960
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 208- MP 211.5 No damaged ECD's observed during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No punchlist items added .1" recorded @ Buffalo Anklets AR					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time	12/30/2019 8:52 AM	Report #	
Pictures					
					
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
<b>Field Station#</b>		11067+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		ECD's and row conditions		<b>Pic 2 Desc.</b>	
					
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
<b>Field Station#</b>		11104+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		ECD's and row conditions		<b>Pic 4 Desc.</b>	
					
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
<b>Field Station#</b>		11133+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		ECD's and row conditions		<b>Pic 6 Desc.</b>	
				.1" @ Buffalo Anklets	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 8:52 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 8:52 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6962
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/30/2019 9:33 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11354+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	58.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 9:33 AM	<b>Report #</b>	6962
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: Sta#11254+88 to 11354+00 MP- 214.8 to 213.00 The row is wet from the overnight rain event, the rain was light. Temporary stabilization and vegetation has kept the row stable with little to no sediment movement. Perimeter controls, silt fence, SSF, CFS are in acceptable condition. Water bars are stable. Sump pits and end treatments are in acceptable condition. Slope drain pipes, CWD pipes and plunge pools are in acceptable condition. Streams and stream ECD's, buffers, equipment bridges, sensitive resource signage are in acceptable condition. Access roads and RCE's are maintained in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/30/2019 9:33 AM	Report #	
Pictures					
 <p>Date &amp; Time: Mon, Dec 30, 2019, 09:44:35 EST Position: +402.256523° / -80.8492943° (+32.20) Altitude: 1954ft (+59.40) Datum: WGS-84 Azimuth/Bearing: 148° S10E 200mils True (+25) Elevation Angle: -10.1° Horizon Angle: -01.8° Zoom: 1.0X Sta#11258+00- Row stable. ECD's are in acceptable condition.</p>		 <p>Date &amp; Time: Mon, Dec 30, 2019, 09:58:16 EST Position: +402.256523° / -80.8492943° (+32.20) Altitude: 1977ft (+60.40) Datum: WGS-84 Azimuth/Bearing: 226° S42W 430mils True (+25) Elevation Angle: -31.5° Horizon Angle: +04.9° Zoom: 1.0X Sta#11269+00- CWD pipe and plunge pool. Slope drain pipe are in good condition.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11258+00		Field Station#	11269+00	
Pic 1 Desc.	Row and ECD's are in acceptable condition.		Pic 2 Desc.	Slope drain pipe, sump, CWD pipe & plunge pool are in good condition.	
 <p>Date &amp; Time: Mon, Dec 30, 2019, 10:09:20 EST Position: +402.256523° / -80.8492943° (+32.20) Altitude: 2157ft (+66.40) Datum: WGS-84 Azimuth/Bearing: 085° N85E 151mils True (+10.1) Elevation Angle: -23.9° Horizon Angle: +04.8° Zoom: 1.0X Sta#11292+00- Stream and stream controls are in acceptable condition.</p>		 <p>Date &amp; Time: Mon, Dec 30, 2019, 10:09:51 EST Position: +402.256523° / -80.8492943° (+32.20) Altitude: 2177ft (+66.40) Datum: WGS-84 Azimuth/Bearing: 085° N85E 140mils True (+10.1) Elevation Angle: -23.9° Horizon Angle: -01.4° Zoom: 1.0X Sta#11329+00- Stream and stream controls are in acceptable condition.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11292+00		Field Station#	11329+00	
Pic 3 Desc.	Stream and controls are in acceptable condition		Pic 4 Desc.	Stream and environmental controls are in acceptable condition.	
 <p>Date &amp; Time: Mon, Dec 30, 2019, 10:36:45 EST Position: +402.256523° / -80.8492943° (+32.20) Altitude: 2237ft (+68.40) Datum: WGS-84 Azimuth/Bearing: 226° S46W 405mils True (+25) Elevation Angle: -23.2° Horizon Angle: +02.5° Zoom: 1.0X Sta#11332+50- Rock channel &amp; Environmental controls are in acceptable condition.</p>		 <p>Date &amp; Time: Mon, Dec 30, 2019, 10:46:37 EST Position: +402.256523° / -80.8492943° (+32.20) Altitude: 1974ft (+59.40) Datum: WGS-84 Azimuth/Bearing: 063° N43E 874mils True (+10.1) Elevation Angle: -08.1° Horizon Angle: +08.1° Zoom: 1.0X Sta#11354+00- Erosion blanket installed on cut bank.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11332+50		Field Station#	11354+00	
Pic 5 Desc.	Rock channel is in acceptable condition.		Pic 6 Desc.	Cut bank has been stabilized with erosion blanket.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 9:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 9:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6993
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	12/31/2019 7:10 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11788+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	35.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00













1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			
Rock Check Dam	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 7:10 AM	<b>Report #</b>	6993
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11789+00 to 12005+00. MP- 223.3 to The row in this inspection area has final restoration completed, the vegetation is acceptable. The row is wet but in stable condition. Perimeter controls, CFS, SSF & P1 silt fence is in acceptable condition. Water bars and level spreaders are in good condition. Water bar outlet protection is in acceptable condition. Karst's and Karst ECD's and sensitive resource signage are in acceptable condition. RCE's and access roads are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	12/31/2019 7:10 AM	Report #	
Pictures					
 <p>Date &amp; Time: Tue, Dec 31, 2019, 08:09:05 EST Position: +037.294000, -100.361007 (+32.8ft) Altitude: 2140ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 185° S85W 429mils True (±10°) Elevation Angle: -18.7° Horizon Angle: -100.0° Zoom: 1.0x Star 11873+58 - Cattle stomped hole in P1 perimeter control.</p>		 <p>Date &amp; Time: Tue, Dec 31, 2019, 08:24:08 EST Position: +037.294188, -100.351572 (+16.4ft) Altitude: 2248ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 266° S86W 4729mils True (±10°) Elevation Angle: -18.7° Horizon Angle: -100.0° Zoom: 1.0x Star 11822+00 - Water bar level spreader &amp; row spreader in good condition.</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 11789+00</p> <p><b>Pic 1 Desc.</b> Tabor RCE is maintained in acceptable condition.</p>	
 <p>Date &amp; Time: Tue, Dec 31, 2019, 08:49:53 EST Position: +039.287980, -100.342472 (+16.4ft) Altitude: 2173ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 001° N01E 0018mils True (±25°) Elevation Angle: -38.3° Horizon Angle: -102.1° Zoom: 1.0x Star 11873+58 - Cattle stomped hole in P1 perimeter control.</p>		 <p>Date &amp; Time: Tue, Dec 31, 2019, 09:04:41 EST Position: +037.283570, -100.333800 (+16.4ft) Altitude: 2307ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 292° N88W 5181mils True (±10°) Elevation Angle: -16.1° Horizon Angle: -103.4° Zoom: 1.0x AR-266.03 - Access road &amp; controls are in good condition.</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 11822+00</p> <p><b>Pic 2 Desc.</b> Level spreaders are in good condition.</p>	
 <p>Date &amp; Time: Tue, Dec 31, 2019, 09:26:28 EST Position: +039.288110, -100.347673 (+32.8ft) Altitude: 2220ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 174° S06E 3093mils True (±25°) Elevation Angle: -19.6° Horizon Angle: -101.9° Zoom: 1.0x Star 11942+00 - Karst and Karst ECD's controls are in good condition.</p>		 <p>Date &amp; Time: Tue, Dec 31, 2019, 10:55:27 EST Position: +039.287799, -100.316421 (+32.8ft) Altitude: 1506ft (+8.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S76W 4551mils True (±10°) Elevation Angle: -42.3° Horizon Angle: -105.1° Zoom: 1.0x Star 12001+00 - P1 in wetland, broken off stake.</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 11873+58</p> <p><b>Pic 3 Desc.</b> P1 perimeter controls has a hole in fabric and stake snapped off, caused by livestock.</p>	
 <p>Date &amp; Time: Tue, Dec 31, 2019, 10:55:27 EST Position: +039.287799, -100.316421 (+32.8ft) Altitude: 1506ft (+8.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S76W 4551mils True (±10°) Elevation Angle: -42.3° Horizon Angle: -105.1° Zoom: 1.0x Star 12001+00 - P1 in wetland, broken off stake.</p>		 <p>Date &amp; Time: Tue, Dec 31, 2019, 10:55:27 EST Position: +039.287799, -100.316421 (+32.8ft) Altitude: 1506ft (+8.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S76W 4551mils True (±10°) Elevation Angle: -42.3° Horizon Angle: -105.1° Zoom: 1.0x Star 12001+00 - P1 in wetland, broken off stake.</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 11900+00</p> <p><b>Pic 4 Desc.</b> AR-266.03</p>	
 <p>Date &amp; Time: Tue, Dec 31, 2019, 10:55:27 EST Position: +039.287799, -100.316421 (+32.8ft) Altitude: 1506ft (+8.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S76W 4551mils True (±10°) Elevation Angle: -42.3° Horizon Angle: -105.1° Zoom: 1.0x Star 12001+00 - P1 in wetland, broken off stake.</p>		 <p>Date &amp; Time: Tue, Dec 31, 2019, 10:55:27 EST Position: +039.287799, -100.316421 (+32.8ft) Altitude: 1506ft (+8.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S76W 4551mils True (±10°) Elevation Angle: -42.3° Horizon Angle: -105.1° Zoom: 1.0x Star 12001+00 - P1 in wetland, broken off stake.</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 11942+00</p> <p><b>Pic 5 Desc.</b> Karst and Karst ECD's are in acceptable condition.</p>	
 <p>Date &amp; Time: Tue, Dec 31, 2019, 10:55:27 EST Position: +039.287799, -100.316421 (+32.8ft) Altitude: 1506ft (+8.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S76W 4551mils True (±10°) Elevation Angle: -42.3° Horizon Angle: -105.1° Zoom: 1.0x Star 12001+00 - P1 in wetland, broken off stake.</p>		 <p>Date &amp; Time: Tue, Dec 31, 2019, 10:55:27 EST Position: +039.287799, -100.316421 (+32.8ft) Altitude: 1506ft (+8.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S76W 4551mils True (±10°) Elevation Angle: -42.3° Horizon Angle: -105.1° Zoom: 1.0x Star 12001+00 - P1 in wetland, broken off stake.</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 12001+00</p> <p><b>Pic 6 Desc.</b> P1 down in wetland.</p>	



<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 7:10 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 7:10 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	6997
<b>Inspector</b>	Brian Shields			<b>Date/Time</b>	12/31/2019 8:09 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 8:09 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11688+00		<b>Field Station#</b>	11663+00	
<b>Pic 1 Desc.</b>	installed waterbars.		<b>Pic 2 Desc.</b>	stabilized ROW conditions	
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11655+00		<b>Field Station#</b>	11653+00	
<b>Pic 3 Desc.</b>	installed compost filter sock.		<b>Pic 4 Desc.</b>	installed perimeter controls	
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11642+00		<b>Field Station#</b>	11625+75	
<b>Pic 5 Desc.</b>	stabilized ROW conditions		<b>Pic 6 Desc.</b>	stream s-h18	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 8:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 8:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7001
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/30/2019 11:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11526+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11351+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Broad-Based Dip	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 11:38 AM	<b>Report #</b>	7001
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 11:38 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, Dec 30, 2019, 10:21:42 EST Position: +037 320295 / -080 426531 (+1990.2ft) Altitude: 2220ft (+53.0ft) Datum: WGS-84 Azimuth/Bearing: 308° NSW 547mils True (+13.1°) Elevation Angle: +18.0° Horizon Angle: -02.9° Zoom: 1.0x 11506+00</p>		 <p>Date &amp; Time: Mon, Dec 30, 2019, 10:22:02 EST Position: +037 320303 / -080 426531 (+1990.2ft) Altitude: 2198ft (+50.3ft) Datum: WGS-84 Azimuth/Bearing: 280° SWW 420mils True (+12.4°) Elevation Angle: +2.7° Horizon Angle: -00.1° Zoom: 1.0x 11502+00</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11506+00	<b>Field Station#</b>	11502+00	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 1 Desc.</b>	Clean water diversion pipe and plunge pool in place.	<b>Pic 2 Desc.</b>	Conveyance channel with rock checks in place at double cut section of ROW.	<b>GPS Location</b>	See photo for GPS location.
 <p>Date &amp; Time: Mon, Dec 30, 2019, 10:27:40 EST Position: +037 305195 / -080 480355 (+18600.0ft) Altitude: 2221ft (+58.1ft) Datum: WGS-84 Azimuth/Bearing: 120° S81W 445mils True (+13.1°) Elevation Angle: -02.3° Horizon Angle: -03.3° Zoom: 1.0x 11489+00</p>		 <p>Date &amp; Time: Mon, Dec 30, 2019, 12:56:26 EST Position: +037 268066 / -080 320088 (+885.0ft) Altitude: 1623ft (+35.3ft) Datum: WGS-84 Azimuth/Bearing: 126° S84E 2240mils True (+10.7°) Elevation Angle: -07.9° Horizon Angle: -05.2° Zoom: 1.0x Catawba</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11489+00	<b>Field Station#</b>	11990+00	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 3 Desc.</b>	RCE in place at Stevers Gap Road.	<b>Pic 4 Desc.</b>	Rain gauge at Catawba Road read 0.1 inches.	<b>GPS Location</b>	See photo for GPS location.
 <p>Date &amp; Time: Mon, Dec 30, 2019, 10:37:00 EST Position: +037 321547 / -080 435699 (+24.9ft) Altitude: 2256ft (+56.3ft) Datum: WGS-84 Azimuth/Bearing: 020° N20E 035mils True (+13.1°) Elevation Angle: -00.6° Horizon Angle: -01.5° Zoom: 1.0x 11471+00</p>		 <p>Date &amp; Time: Mon, Dec 30, 2019, 12:20:28 EST Position: +037 274880 / -080 367867 (+59.1ft) Altitude: 2015ft (+178.5ft) Datum: WGS-84 Azimuth/Bearing: 352° N8W 6268mils True (+10.1°) Elevation Angle: -00.0° Horizon Angle: -01.9° Zoom: 1.0x 11767+00</p>		<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11471+00	<b>Field Station#</b>	11767+00	<b>GPS Location</b>	See photo for GPS location.
<b>Pic 5 Desc.</b>	Rain gauge at Steele Acres Road reads 0.2 inches.	<b>Pic 6 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.1 inches.	<b>GPS Location</b>	See photo for GPS location.

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 11:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	12/30/2019 11:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7022
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	1/2/2020 8:12 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	48.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	1/2/2020 8:12 AM	<b>Report #</b>	7022
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: LY-29 AR-238.00 is maintained in acceptable condition. The rock surface of the yard is maintained in acceptable condition. PPL and Arnold's materials storage is acceptable. Overhead utility flagging is maintained in acceptable condition. CFS 18" Triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. Waste management is acceptable. House keeping is acceptable.  The contractor is not working, environmental inspection is present, along with MBP inspector.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time 1/2/2020 8:12 AM		Report #	
Pictures					
<p>Date &amp; Time: Thu, Jan 02, 2020, 05:55:09 EST Position: +407.345477° / -888.675848° (+16.40) Altitude: 1768ft (+19.37) Datum: WGS-84 Azimuth/Bearing: 259° 160W 4887mils True (+25°) Elevation Angle: -09.3° Horizon Angle: +02.3° Zoom: 1.0X LY-29- Over view of the yard.</p> 		<p>Date &amp; Time: Thu, Jan 02, 2020, 05:56:16 EST Position: +407.346177° / -888.677207° (+16.40) Altitude: 1768ft (+19.37) Datum: WGS-84 Azimuth/Bearing: 301° 53W 387mils True (+25°) Elevation Angle: -11.0° Horizon Angle: -04.1° Zoom: 1.0X LY-29- Arnolds materials storage.</p> 			
GPS Location		See photo GPS		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 1 Desc.		Over view of LY-29		Pic 2 Desc.	
				LY-29 - Arnold's materials storage.	
<p>Date &amp; Time: Thu, Jan 02, 2020, 05:55:09 EST Position: +407.345207° / -888.675848° (+16.40) Altitude: 1714ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 240° 560W 4267mils True (+25°) Elevation Angle: -09.7° Horizon Angle: +00.3° Zoom: 1.0X LY-29: PPL materials storage.</p> 		<p>Date &amp; Time: Thu, Jan 02, 2020, 05:55:09 EST Position: +407.345332° / -888.675848° (+16.40) Altitude: 1714ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 218° 538W 387mils True (+25°) Elevation Angle: -17.2° Horizon Angle: +01.6° Zoom: 1.0X LY-29- Rock surface of the yard is maintained in acceptable condition.</p> 			
GPS Location		See photo GPS		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 3 Desc.		LY-29- PPL Materials storage.		Pic 4 Desc.	
				LY-29- Rock surface of the yard is maintained in acceptable condition.	
<p>Date &amp; Time: Thu, Jan 02, 2020, 05:55:09 EST Position: +407.338342° / -888.671170° (+16.4ft) Altitude: 1746ft (+19.4ft) Datum: WGS-84 Azimuth/Bearing: 218° 538W 387mils True (+25°) Elevation Angle: -11.5° Horizon Angle: -02.8° Zoom: 1.0X LY-29- CFS triple stack perimeter controls are in acceptable condition.</p> 		<p>Date &amp; Time: Thu, Jan 02, 2020, 05:55:09 EST Position: +407.338342° / -888.671170° (+16.4ft) Altitude: 1746ft (+19.4ft) Datum: WGS-84 Azimuth/Bearing: 170° 83W 335mils True (+25°) Elevation Angle: -10.1° Horizon Angle: +05.1° Zoom: 1.0X Culvert and drainage feature are in acceptable condition.</p> 			
GPS Location		See photo GPS		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 5 Desc.		LY- 29- CFS 18" Triple stack perimeter controls are in acceptable condition.		Pic 6 Desc.	
				Culvert and drainage feature are in acceptable condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 8:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 8:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7023
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	1/2/2020 8:13 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11520+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11630+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	37.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	1/2/2020 8:13 AM	<b>Report #</b>	7023
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 218 MP 219.5 No damaged ECD's observed during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No punchlist items added					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	1/2/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11530+00		<b>Field Station#</b>	11552+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11561+00		<b>Field Station#</b>	11580+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11578+00		<b>Field Station#</b>	11620+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 8:13 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report









<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7025
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	1/2/2020 8:25 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	+28
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	+28
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	29.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Housekeeping	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Secondary Containment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	1/2/2020 8:25 AM	<b>Report #</b>	7025
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for LDY 28 No damaged ECD's observed during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No punchlist items added					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	1/2/2020 8:25 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu Jan 02, 2020 09:45:43 EST Position: +43°20'12.68" N -080°43'39.10" W (4319.370) Altitude: 1735ft (529m) Datum: WGS-84 Azimuth/Bearing: 09° S44E 1702mils True (417°) Elevation Grade: +01% Horizon Grade: +0.01% Zoom: 1.0X 28</p>		 <p>Date &amp; Time: Thu Jan 02, 2020 09:45:43 EST Position: +43°20'12.68" N -080°43'39.10" W (4319.370) Altitude: 1735ft (529m) Datum: WGS-84 Azimuth/Bearing: 32° N34W 4022mils True (416°) Elevation Grade: +01% Horizon Grade: +0.01% Zoom: 1.0X 28</p>		<b>GPS Location</b> See picture above for GPS coordinates <b>Field Station#</b> +28 <b>Pic 1 Desc.</b> ECD's and row conditions	
 <p>Date &amp; Time: Thu Jan 02, 2020 09:45:43 EST Position: +43°20'11.00" N -080°43'39.10" W (4319.370) Altitude: 1543ft (470m) Datum: WGS-84 Azimuth/Bearing: 22° N32W 4430mils True (416°) Elevation Grade: +00% Horizon Grade: +0.03% Zoom: 1.0X 28</p>		 <p>Date &amp; Time: Thu Jan 02, 2020 09:45:43 EST Position: +43°20'12.68" N -080°43'39.10" W (4319.370) Altitude: 1735ft (529m) Datum: WGS-84 Azimuth/Bearing: 34° N34W 4022mils True (416°) Elevation Grade: +01% Horizon Grade: +0.01% Zoom: 1.0X 28</p>		<b>GPS Location</b> See picture above for GPS coordinates <b>Field Station#</b> +28 <b>Pic 3 Desc.</b> ECD's and row conditions	
 <p>Date &amp; Time: Thu Jan 02, 2020 09:45:43 EST Position: +43°20'12.68" N -080°43'39.10" W (4319.370) Altitude: 1735ft (529m) Datum: WGS-84 Azimuth/Bearing: 32° N37W 5742mils True (416°) Elevation Grade: +01% Horizon Grade: +0.01% Zoom: 1.0X 28</p>		 <p>Date &amp; Time: Thu Jan 02, 2020 09:45:43 EST Position: +43°20'12.68" N -080°43'39.10" W (4319.370) Altitude: 1543ft (470m) Datum: WGS-84 Azimuth/Bearing: 32° N37W 5742mils True (416°) Elevation Grade: +01% Horizon Grade: +0.01% Zoom: 1.0X 28</p>		<b>GPS Location</b> See picture above for GPS coordinates <b>Field Station#</b> +28 <b>Pic 5 Desc.</b> ECD's and row conditions	
 <p>Date &amp; Time: Thu Jan 02, 2020 09:45:43 EST Position: +43°20'12.68" N -080°43'39.10" W (4319.370) Altitude: 1735ft (529m) Datum: WGS-84 Azimuth/Bearing: 32° N37W 5742mils True (416°) Elevation Grade: +01% Horizon Grade: +0.01% Zoom: 1.0X 28</p>		 <p>Date &amp; Time: Thu Jan 02, 2020 09:45:43 EST Position: +43°20'12.68" N -080°43'39.10" W (4319.370) Altitude: 1735ft (529m) Datum: WGS-84 Azimuth/Bearing: 32° N37W 5742mils True (416°) Elevation Grade: +01% Horizon Grade: +0.01% Zoom: 1.0X 28</p>		<b>GPS Location</b> See picture above for GPS coordinates <b>Field Station#</b> +28 <b>Pic 6 Desc.</b> ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 8:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 8:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7066
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	12/31/2019 11:47 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	40.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	12/31/2019 11:47 AM	<b>Report #</b>	7066
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 11:47 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11672+00		<b>Field Station#</b>	11687+40	
<b>Pic 1 Desc.</b>	Waterbar, sump pit, and CFS end treatment in place.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-MN21.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11706+00		<b>Field Station#</b>	11758+00	
<b>Pic 3 Desc.</b>	ROW stabilized with seed, mulch, and minor vegetation growth.		<b>Pic 4 Desc.</b>	Reinforced super silt fence in place along LOD.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11776+00	
<b>Pic 5 Desc.</b>	RCE in place at main line valve 26.		<b>Pic 6 Desc.</b>	Clean water diversion pipe and plunge pool in place.	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 11:47 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	12/31/2019 11:47 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7067
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	1/2/2020 10:53 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 10:53 PM	<b>Report #</b>	7067
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 1/2/2020 10:53 PM		Report #	
Pictures					
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 1 Desc.		18 inch CFS in place along LOD.		Pic 2 Desc.	
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 3 Desc.		Triple stack 12 inch CFS in place along LOD.		Pic 4 Desc.	
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 5 Desc.		No leaks observed under staged equipment.		Pic 6 Desc.	

<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 10:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	1/2/2020 10:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7072
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	1/3/2020 8:15 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11024+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	2.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	1/3/2020 8:15 AM	<b>Report #</b>	7072
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: Sta#11024+00 to 10930+00. MP- 208.6 to 206.2 There was overnight rain fall so the row was muddy, but remains in stable condition. Perimeter controls, CFS, SSF, P1 silt fence are in acceptable condition. Water bars and sump pits are in acceptable condition Water bar end treatments are in acceptable condition. Karst and Karst ECD's and sensitive resource signage are in acceptable condition. Streams and ECD's, equipment bridges, buffers, sensitive resource signage are in acceptable condition. Temporary stabilization of the row is acceptable. Access road 244 and Doe Creek RCE are maintained in acceptable condition. There was some damage to silt fence on on Doe Creek Farms, caused by livestock that the contractor is addressing. Rain gauge totals: AR-244-.20"— Tabor- .40"— Catawba- .40" The landowner at AR-266 has been moving round bales and has tracked mud on AR-266 and Catawba road. ( See photo's).					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	1/3/2020 8:15 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri Jan 03, 2020 09:22:29 EST  Position: +037.318042, +052.551587, +16.0111  Altitude: +187ft (+19.7m)  Datum: WGS-84  Azimuth/Bearing: 282, N78W, 0.13mils True (+25)  Elevation Angle: -19.5  Horizon Angle: +06.0  Zoom: 1.0x  AR-244 rain gauge reading: .20"</p> 		<p>Date &amp; Time: Fri Jan 03, 2020 09:30:42 EST  Position: +037.318042, +052.551587, +16.0111  Altitude: +268ft (+25.0m)  Datum: WGS-84  Azimuth/Bearing: 292, N85W, 0.13mils True (+25)  Elevation Angle: -10.8  Horizon Angle: +05.6  Zoom: 1.0x  Stream S-RR5- stan11017+00- Stream &amp; environmental controls are in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11017+00		
<b>Pic 1 Desc.</b>	AR-244 rain gauge reading- .20"	<b>Pic 2 Desc.</b>	11017- Stream S- RR5- Stream & environment controls are in acceptable condition.		
<p>Date &amp; Time: Fri Jan 03, 2020 09:54:59 EST  Position: +037.325432, +052.564705, +16.0111  Altitude: +234ft (+22.0m)  Datum: WGS-84  Azimuth/Bearing: 096, S84E, 1.702mils True (+25)  Elevation Angle: -02.5  Horizon Angle: +04.1  Zoom: 1.0x  Stan10987+00- Controls on steep slope are in acceptable condition.</p> 		<p>Date &amp; Time: Fri Jan 03, 2020 09:54:59 EST  Position: +037.325432, +052.564705, +16.0111  Altitude: +234ft (+22.0m)  Datum: WGS-84  Azimuth/Bearing: 096, S84E, 1.702mils True (+25)  Elevation Angle: -02.5  Horizon Angle: +04.1  Zoom: 1.0x  Stan10988+00- stream S -E25- Stream &amp; environmental controls are in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10987+00	<b>Field Station#</b>	10986+00		
<b>Pic 3 Desc.</b>	Steep slope ECD's are in acceptable condition.	<b>Pic 4 Desc.</b>	Stream S -E25 is in acceptable condition.		
<p>Date &amp; Time: Fri Jan 03, 2020 09:55:03 EST  Position: +037.325432, +052.564705, +16.0111  Altitude: +234ft (+22.0m)  Datum: WGS-84  Azimuth/Bearing: 297, N63W, 5.280mils True (+25)  Elevation Angle: -15.7  Horizon Angle: +01.8  Zoom: 1.0x  Stan1095+00- stream S- E24- Stream &amp; environmental controls are in acceptable condition.</p> 		<p>Date &amp; Time: Fri Jan 03, 2020 10:00:40 EST  Position: +037.325432, +052.564705, +16.0111  Altitude: +23.8ft (+2.3m)  Datum: WGS-84  Azimuth/Bearing: 329, N31W, 5.849mils True (+5)  Elevation Angle: -17.9  Horizon Angle: +07.7  Zoom: 1.0x  Stan10965+00- Karst and Karst controls are in acceptable condition.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10985+00	<b>Field Station#</b>	10965+00		
<b>Pic 5 Desc.</b>	Stream S-E24 is in acceptable condition	<b>Pic 6 Desc.</b>	Karst and Karst ECD's are in good condition		

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7073
<b>Inspector</b>	Brian Shields			<b>Date/Time</b>	1/3/2020 8:15 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:15 AM	<b>Report #</b>	7073
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
VA SWPPP inspection MP 209.55 to 208.79 0.2 inches of rain recorded within AR244 gauge. additional precipitation expected throughout the day. ROW conditions within section are stable with little to no sediment movement observed installed perimeter controls are in good working condition with no maintenance needed waterbars and sumps are functioning as designed no maintenance issues observed on inspection					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:15 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11027+50		<b>Field Station#</b>	11030+00	
<b>Pic 1 Desc.</b>	stabilized row conditions		<b>Pic 2 Desc.</b>	stabilized ROW conditions	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11032+00		<b>Field Station#</b>	11039+00	
<b>Pic 3 Desc.</b>	installed waterbar and end treatment		<b>Pic 4 Desc.</b>	installed perimeter controls	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11049+86		<b>Field Station#</b>	11055+00	
<b>Pic 5 Desc.</b>	stream S-IJ16		<b>Pic 6 Desc.</b>	stabilized ROW conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7074
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	1/3/2020 8:23 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10840+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10940+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00









1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:23 AM	<b>Report #</b>	7074
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 205 - 207 No damaged ECD's observed during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No punchlist items added					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	1/3/2020 8:23 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri Jan 03 2020 11:09:03 EST Position: +037 20 6 47 / -060 35 48 38 (±25.6m) Altitude: 2150ft (±52.2m) Datum: WGS-84 Azimuth/Bearing: 295° N65W 5264mils True (±10°) Elevation Grade: +001% Horizon Grade: +001% Zoom: 1.0X 2' post</p>		 <p>Date &amp; Time: Fri Jan 03 2020 09:16:19 EST Position: +037 20 15 28 / -060 34 19 71 (±39.3m) Altitude: 2215ft (±68.9m) Datum: WGS-84 Azimuth/Bearing: 236° N66W 5227mils True (±10°) Elevation Grade: +025% Horizon Grade: -001% Zoom: 1.0X 2' post</p>		<b>GPS Location</b> See picture above for GPS coordinates	
<b>Field Station#</b> +1		<b>Field Station#</b> +1		<b>Pic 1 Desc.</b> .3" @ Kow Camp	
 <p>Date &amp; Time: Fri Jan 03 2020 09:16:19 EST Position: +037 20 15 28 / -060 34 19 71 (±39.3m) Altitude: 2215ft (±68.9m) Datum: WGS-84 Azimuth/Bearing: 236° N66W 5227mils True (±10°) Elevation Grade: +025% Horizon Grade: -001% Zoom: 1.0X 2' 37</p>		 <p>Date &amp; Time: Fri Jan 03 2020 10:35:57 EST Position: +037 20 15 28 / -060 34 19 71 (±39.3m) Altitude: 2215ft (±68.9m) Datum: WGS-84 Azimuth/Bearing: 236° N66W 5227mils True (±10°) Elevation Grade: +025% Horizon Grade: -001% Zoom: 1.0X 10856</p>		<b>Pic 2 Desc.</b> .2" @ Pocahontas	
<b>GPS Location</b> See picture above for GPS coordinates		<b>GPS Location</b> See picture above for GPS coordinates		<b>Field Station#</b> +37	
<b>Field Station#</b> +37		<b>Field Station#</b> 10856+00		<b>Pic 3 Desc.</b> .2" @ LDY 37	
 <p>Date &amp; Time: Fri Jan 03 2020 10:42:13 EST Position: +037 20 13 26 / -060 36 13 26 (±16.3m) Altitude: 2377ft (±10.0m) Datum: WGS-84 Azimuth/Bearing: 037° N31E 0551mils True (±14°) Elevation Grade: +032% Horizon Grade: +009% Zoom: 1.0X 10865</p>		 <p>Date &amp; Time: Fri Jan 03 2020 10:40:00 EST Position: +037 20 11 12 / -060 36 41 67 (±22.2m) Altitude: 2390ft (±73.5m) Datum: WGS-84 Azimuth/Bearing: 88° S08E 160mils True (±15°) Elevation Grade: +041% Horizon Grade: +003% Zoom: 1.0X 108717</p>		<b>Pic 4 Desc.</b> ECD's and row conditions	
<b>GPS Location</b> See picture above for GPS coordinates		<b>GPS Location</b> See picture above for GPS coordinates		<b>Field Station#</b> 10865+00	
<b>Field Station#</b> 10865+00		<b>Field Station#</b> 10877+00		<b>Pic 5 Desc.</b> ECD's and row conditions	
				<b>Pic 6 Desc.</b> ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 8:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	7111
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	1/3/2020 9:33 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10832+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 9:33 PM	<b>Report #</b>	7111
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 204.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. Environmental crew replaced CFS along AR 241.04 because landowner burnt original CFS. Checked rain garages at AR 234 and Buffalo Anklets Road. Both gauges read 0.3 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	1/3/2020 9:33 PM	Report #	
Pictures					
 <p>Date &amp; Time: Fri, Jan 03, 2020, 08:52:39 EST Position: +037.349199° / -080.508600° (±19.2m) Altitude: 2065ft (±37.7m) Datum: WGS-84 Azimuth/Bearing: 07° N71E 1262mils True (±14°) Elevation Angle: -04.9° Horizon Angle: -00.9° Zoom: 1.0X AR 234</p>		 <p>Date &amp; Time: Fri, Jan 03, 2020, 08:55:59 EST Position: +037.349200° / -080.508600° (±19.2m) Altitude: 2065ft (±37.7m) Datum: WGS-84 Azimuth/Bearing: 07° N70W 1262mils True (±14°) Elevation Angle: -04.6° Horizon Angle: -03.6° Zoom: 2.0X 10670+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	10670+00	
Pic 1 Desc.	Rain gauge at access road 234 reads. 0.3 inches.		Pic 2 Desc.	Reinforced super silt fence in place along LOD.	
 <p>Date &amp; Time: Fri, Jan 03, 2020, 08:56:44 EST Position: +037.349199° / -080.508600° (±19.2m) Altitude: 2065ft (±37.7m) Datum: WGS-84 Azimuth/Bearing: 179° S01E 3182mils True (±14°) Elevation Angle: -07.3° Horizon Angle: -00.2° Zoom: 1.0X 10696+00</p>		 <p>Date &amp; Time: Fri, Jan 03, 2020, 08:56:44 EST Position: +037.349200° / -080.508600° (±19.2m) Altitude: 2065ft (±37.7m) Datum: WGS-84 Azimuth/Bearing: 109° S71E 1938mils True (±14°) Elevation Angle: -04.0° Horizon Angle: -02.2° Zoom: 1.0X 10696+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10696+00		Field Station#	10696+00	
Pic 3 Desc.	Rain gauge at Buffalo Anklets Road reads 0.3 inches.		Pic 4 Desc.	RCE in place at Buffalo Anklets Road.	
 <p>Date &amp; Time: Fri, Jan 03, 2020, 09:00:39 EST Position: +037.349199° / -080.508600° (±19.2m) Altitude: 2068ft (±37.7m) Datum: WGS-84 Azimuth/Bearing: 131° S49E 2329mils True (±10°) Elevation Angle: -06.0° Horizon Angle: -00.2° Zoom: 1.0X 10698+00 S-G32</p>		 <p>Date &amp; Time: Fri, Jan 03, 2020, 09:00:39 EST Position: +037.349199° / -080.508600° (±19.2m) Altitude: 2068ft (±37.7m) Datum: WGS-84 Azimuth/Bearing: 07° N70E 1262mils True (±14°) Elevation Angle: -04.6° Horizon Angle: -00.9° Zoom: 1.0X AR 241 01</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10698+00		Field Station#	12005+00	
Pic 5 Desc.	Sensitive resource buffer in place at stream S-G32.		Pic 6 Desc.	12 inch compost filter sock replaced due to fire.	

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 9:33 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	1/3/2020 9:33 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		