



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8737
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	3/2/2020 6:45 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	No
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 6:45 AM	<b>Report #</b>	8737
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection from MP 213 AND MP 214.8 as well as assessed AR 256.02. No major issues were located. One locations of wildlife damage to P-1 was identified. PPL Environmental Coordinator Mike Perry was notified. Crews made repairs prior to the end of day. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Light rain throughout PM hours.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	3/2/2020 6:45 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Mar 02, 2020, 09:38:58 EST  Position: +037.29975° / -080.483568° (±157.5ft)  Altitude: 2255ft (±10.5m)  Datum: WGS-84  Azimuth/Bearing: 047° N47E 8836mils True (±14°)  Elevation Angle: -23.5°  Horizon Angle: +03.6°  Zoom: 1.0X  S-MM18  11263+00</p> 		<p>Date &amp; Time: Mon, Mar 02, 2020, 09:38:58 EST  Position: +037.29975° / -080.483568° (±157.5ft)  Altitude: 2255ft (±10.5m)  Datum: WGS-84  Azimuth/Bearing: 047° N47E 8836mils True (±14°)  Elevation Angle: -23.5°  Horizon Angle: +03.6°  Zoom: 1.0X  S-MM18  11286+00</p> 			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11263+00	<b>Field Station#</b>	11286+00		
<b>Pic 1 Desc.</b>	Perimeter controls functional with good stabilization.	<b>Pic 2 Desc.</b>	Perimeter controls functional with sufficient side slope stabilized.		
<p>Date &amp; Time: Mon, Mar 02, 2020, 09:43:38 EST  Position: +037.29975° / -080.483568° (±157.5ft)  Altitude: 2097ft (±10.4ft)  Datum: WGS-84  Azimuth/Bearing: 194° S16W 3484mils True (±13°)  Elevation Angle: -08.4°  Horizon Angle: +02.5°  Zoom: 1.0X  S-MM18</p> 		<p>Date &amp; Time: Mon, Mar 02, 2020, 10:00:18 EST  Position: +037.300659° / -080.472281° (±157.5ft)  Altitude: 2044ft (±10.4ft)  Datum: WGS-84  Azimuth/Bearing: 202° S22W 3591mils True (±14°)  Elevation Angle: -09.3°  Horizon Angle: +01.9°  Zoom: 1.0X  S-MM18</p> 			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11292+80	<b>Field Station#</b>	11327+85		
<b>Pic 3 Desc.</b>	S-MM18.	<b>Pic 4 Desc.</b>	S-NN12.		
<p>Date &amp; Time: Mon, Mar 02, 2020, 10:12:06 EST  Position: +037.300659° / -080.471166° (±157.5ft)  Altitude: 2113ft (±10.4ft)  Datum: WGS-84  Azimuth/Bearing: 188° S08W 3342mils True (±14°)  Elevation Angle: -14.1°  Horizon Angle: +02.1°  Zoom: 1.0X  S-MM18  11332+00</p> 		<p>Date &amp; Time: Mon, Mar 02, 2020, 10:21:37 EST  Position: +037.300659° / -080.457981° (±157.5ft)  Altitude: 2050ft (±10.4ft)  Datum: WGS-84  Azimuth/Bearing: 060° N60E 1047mils True (±14°)  Elevation Angle: -20°  Horizon Angle: +02.0°  Zoom: 1.0X  S-NN11</p> 			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11332+00	<b>Field Station#</b>	11352+97		
<b>Pic 5 Desc.</b>	Rock lined channel and perimeter controls sufficient.	<b>Pic 6 Desc.</b>	S-NN11.		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 6:45 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 6:45 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8738
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	3/2/2020 7:07 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	32.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar Outlet Protection	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





<b>AFE</b>	124300137	<b>Date/Time</b>	3/2/2020 7:07 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time Wed, Mar 04, 2020, 05:45:50 EST  Position: +48°15'29.87" N -88°23'25.16" W (±21162.5m)  Altitude: 1830' (±1.20)  Datum: WGS-84  Azimuth/Bearing: 135° S45E 2400mils Error (Error)  Elevation Grade: -03%  Horizon Grade: -00%  Zoom: 1.0X  11068</p> 		<p>Date &amp; Time Wed, Mar 04, 2020, 05:46:50 EST  Position: +48°15'29.87" N -88°23'25.16" W (±21162.5m)  Altitude: 1830' (±1.20)  Datum: WGS-84  Azimuth/Bearing: 135° S45E 2400mils Error (Error)  Elevation Grade: -03%  Horizon Grade: -00%  Zoom: 1.0X  11080</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11068+00		<b>Field Station#</b>	11080+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time Wed, Mar 04, 2020, 10:47:47 EST  Position: +48°15'29.87" N -88°23'25.16" W (±21162.5m)  Altitude: 1830' (±1.20)  Datum: WGS-84  Azimuth/Bearing: 135° S45E 2400mils Error (Error)  Elevation Grade: -03%  Horizon Grade: -00%  Zoom: 1.0X  11120</p> 		<p>Date &amp; Time Wed, Mar 04, 2020, 10:48:47 EST  Position: +48°15'29.87" N -88°23'25.16" W (±21162.5m)  Altitude: 1830' (±1.20)  Datum: WGS-84  Azimuth/Bearing: 135° S45E 2400mils Error (Error)  Elevation Grade: -03%  Horizon Grade: -00%  Zoom: 1.0X  11132</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11120+00		<b>Field Station#</b>	11132+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time Wed, Mar 04, 2020, 10:51:47 EST  Position: +48°15'29.87" N -88°23'25.16" W (±21162.5m)  Altitude: 1830' (±1.20)  Datum: WGS-84  Azimuth/Bearing: 141° S59E 3300mils Error (Error)  Elevation Grade: -03%  Horizon Grade: -00%  Zoom: 1.0X  11140</p> 		<p>Date &amp; Time Wed, Mar 04, 2020, 10:52:47 EST  Position: +48°15'29.87" N -88°23'25.16" W (±21162.5m)  Altitude: 1830' (±1.20)  Datum: WGS-84  Azimuth/Bearing: 141° S59E 3300mils Error (Error)  Elevation Grade: -03%  Horizon Grade: -00%  Zoom: 1.0X  11142</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11140+00		<b>Field Station#</b>	11142+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 7:07 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 7:07 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8739
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	3/2/2020 7:18 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11161+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	3.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	3/2/2020 7:18 AM	<b>Report #</b>	8739
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: Sta#11524+18 to 21354+00 MP- 214.8 to 218.26 The row is drying and in stable condition, the contractor has re- stabilized some areas that had soil movement, rilling, by adding straw mulch to these areas. There were five issues with perimeter controls that PPL environmental crew working in the inspection area were informed of and will address by end of day. All other perimeter controls are in acceptable condition. Water bars are in acceptable condition. Sump pits and water bar end treatments are in acceptable condition. Slope drains, CWD pipes and plunge pools are in acceptable condition. Streams- S-PP4, S-PP3, S-0013, S-0014, S-RL43, and environment stream controls are in acceptable condition. Access roads and RCE's are maintained in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	3/2/2020 7:18 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11519+16	<b>Field Station#</b>	11507+78		
<b>Pic 1 Desc.</b>	Stream S-PP4- and environmental controls are in acceptable condition		<b>Pic 2 Desc.</b>	Stream S-PP3 and environmental controls are in acceptable condition.	
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11451+26	<b>Field Station#</b>	11448+93		
<b>Pic 3 Desc.</b>	Stream S-0013 and environmental controls are in acceptable condition.		<b>Pic 4 Desc.</b>	Stream S-0014 and stream ECD's are in acceptable condition.	
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11427+00	<b>Field Station#</b>	11418+00		
<b>Pic 5 Desc.</b>	SSF fabric detached from chain link, contractor has addressed the issue.		<b>Pic 6 Desc.</b>	Contractor trenching in P1 silt fence.	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 7:18 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 7:18 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8762
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	3/2/2020 3:52 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+88
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11161+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 3:52 PM	<b>Report #</b>	8762
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: Sta#11254+88 to 11161+00. MP- 211 to 213 The row is wet but stable with a small amount of sediment movement in water bar flow lines to sump pits. Temporary stabilization is acceptable. Perimeter controls, P1 silt fence, CFS, and SSF are in acceptable condition. Water bar end treatments are in acceptable condition. Water bars are stable. Slope drain pipes are in acceptable condition. Rock channel is in acceptable condition. CWD pipe and plunge pool are in good condition. Access roads MLV25, AR-249.02 , AR- 249.01 are maintained in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 3:52 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11252+00		<b>Field Station#</b>	11218+00	
<b>Pic 1 Desc.</b>	Rock lined channel in place over fill slope.		<b>Pic 2 Desc.</b>	Waterbar, sump pit, and waterbar end treatment in place.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11215+00		<b>Field Station#</b>	11208+00	
<b>Pic 3 Desc.</b>	Slope drain with rock inlet in place over fill slope.		<b>Pic 4 Desc.</b>	Reinforced super silt fence in place.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11187+00		<b>Field Station#</b>	11187+00	
<b>Pic 5 Desc.</b>	Clean water diversion berm and clean water diversion pipe inlet in place.		<b>Pic 6 Desc.</b>	Plunge pool in place.	



<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 3:52 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2020 3:52 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8779
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	3/3/2020 7:11 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			
Housekeeping	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:11 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11530+00		<b>Field Station#</b>	11552+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11565+00		<b>Field Station#</b>	11578+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11584+00		<b>Field Station#</b>	11588+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	



<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8780
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	3/3/2020 7:14 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11900+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:14 AM	<b>Report #</b>	8780
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: Sta#11900+00 to 12005+00. MP-225.3 to 223.3 Row is wet from recent rain event but in stable condition. Permanent restoration is acceptable. Perimeter controls, Silt fence, CFC & SSF are in acceptable condition. Water bars and level spreaders are in good condition. Water bar outlet protection is in acceptable condition. Karst's and Karst ECD's & signage are in acceptable condition. Ar-266.03 and 266.00 are maintained in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 3/3/2020 7:14 AM		Report #			
Pictures							
							
GPS Location		See photo GPS		GPS Location		See photo GPS	
Field Station#		11900+00		Field Station#		11923+93	
Pic 1 Desc.		AR-266.03 and environmental controls are in acceptable condition.		Pic 2 Desc.		Water bar outlet protection is acceptable.	
							
GPS Location		See photo GPS		GPS Location		See photo GPS	
Field Station#		11942+00		Field Station#		11944+00	
Pic 3 Desc.		Karst's and Karst ECD's are in acceptable condition.		Pic 4 Desc.		Permanent restoration is acceptable	
							
GPS Location		See photo GPS		GPS Location		See photo GPS	
Field Station#		11963+00		Field Station#		11989+00	
Pic 5 Desc.		Perimeter controls have been replaced where damaged.		Pic 6 Desc.		Catawba rain gauge reading- 0.20"	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8781
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	3/3/2020 7:16 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	59.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:16 AM	<b>Report #</b>	8781
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP from MP 223.3 to MP 225.3 as well as assessed AR 266.03. Inspection completed during ongoing rain event. No issues were located. All perimeter controls, ECDs and BMPs functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



A/E	124300137	Date/Time	3/3/2020 7:16 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11789+00	Field Station#	11797+00		
Pic 1 Desc.	RCE on the South side on Mt Tabor Rd.		Pic 2 Desc.	RoW conditions and controls.	
					
GPS Location	3	GPS Location	4		
Field Station#	11819+00	Field Station#	11842+00		
Pic 3 Desc.	RoW conditions and controls.		Pic 4 Desc.	RoW conditions and controls.	
					
GPS Location	5	GPS Location	6		
Field Station#	11863+65	Field Station#	11897+00		
Pic 5 Desc.	P-KL2.		Pic 6 Desc.	RoW conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:16 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 7:16 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8825
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	3/4/2020 7:12 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Culvert (Ditch Relief)	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	3/4/2020 7:12 AM	<b>Report #</b>	8825
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended inspection meeting at the work trailer. SWPPP inspection: LY-29 AR-238.00 - Access road leading into LY 29 is in acceptable condition. The rock surface of the yard is maintained in acceptable condition. CFS triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. Overhead utility protection flagging is in acceptable condition. House keeping is acceptable. Materials storage is acceptable. Waste management is acceptable. The yard does not house any mechanical equipment , spills are not an issue.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/4/2020 7:12 AM	Report #	
Pictures					
<div><div><div>Date &amp; Time: Wed Mar 04 2020 08:52:41 EST Position: +037.365513 / -080.675503 (-16.4ft) Altitude: 1731ft (+26.2ft) Datum: WGS-84 Azimuth Bearing: 205.526W 3698mils True (+26.2) Elevation Angle: -08.9 Horizon Angle: -00.0 Zoom: 1.0X LY-29- Overview of the yard</div><div></div></div></div>		<div><div><div>Date &amp; Time: Wed Mar 04 2020 08:56:50 EST Position: +037.363413 / -080.676666 (-16.4ft) Altitude: 1737ft (+26.2ft) Datum: WGS-84 Azimuth Bearing: 243.543W 4320mils True (+35.1) Elevation Angle: -10.8 Horizon Angle: -00.5 Zoom: 1.0X LY-29- PPL Materials storage</div><div></div></div></div>			
GPS Location	See photo GPS		GPS Location	See	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	LY-29- Overview of the yard.		Pic 2 Desc.	LY 29 - PPL Materials storage.	
<div><div><div>Date &amp; Time: Wed Mar 04 2020 08:58:06 EST Position: +037.363010 / -080.676717 (-16.4ft) Altitude: 1691ft (+25.9ft) Datum: WGS-84 Azimuth Bearing: 295.561W 5316mils True (+35.1) Elevation Angle: -08.6 Horizon Angle: -00.2 Zoom: 1.0X LY-29- Rock surface of the yard is maintained in acceptable condition</div><div></div></div></div>		<div><div><div>Date &amp; Time: Wed Mar 04 2020 09:00:15 EST Position: +037.363413 / -080.676666 (-16.4ft) Altitude: 1737ft (+26.2ft) Datum: WGS-84 Azimuth Bearing: 282.501W 5013mils True (+30.1) Elevation Angle: -12.8 Horizon Angle: -00.4 Zoom: 1.0X LY-29- CFS triple stack perimeter controls</div><div></div></div></div>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	LY 29- Rock surface of the yard is maintained in acceptable condition.		Pic 4 Desc.	LY 29- CFS triple stack perimeter controls are in acceptable condition.	
<div><div><div>Date &amp; Time: Wed Mar 04 2020 09:01:53 EST Position: +037.363793 / -080.677908 (-16.4ft) Altitude: 1720ft (+26.2ft) Datum: WGS-84 Azimuth Bearing: 207.521W 5102mils True (Error) Elevation Angle: -13.6 Horizon Angle: -00.2 Zoom: 1.0X LY-29- Culvert and drainage feature are in good condition</div><div></div></div></div>		<div><div><div>Date &amp; Time: Wed Mar 04 2020 09:06:33 EST Position: +037.362173 / -080.677243 (-16.4ft) Altitude: 1715ft (+26.2ft) Datum: WGS-84 Azimuth Bearing: 201.521W 3573mils True (Error) Elevation Angle: -07.5 Horizon Angle: -00.2 Zoom: 1.0X AR-238.00- Access road into LY-29 is in acceptable condition</div><div></div></div></div>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	LY 29- Culvert and Drainage feature are in acceptable condition.		Pic 6 Desc.	AR-238.00 - Access road into LY 29 is in acceptable condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2020 7:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2020 7:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8826
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	3/4/2020 7:14 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2020 7:14 AM	<b>Report #</b>	8826
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for LDY 28 Observed no damaged ECD's during inspection, ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list Crews walked ROW checking ECD's and row conditions					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 3/4/2020 7:14 AM		Report #	
Pictures					
 <p>Date &amp; Time: Wed Mar 04 2020 08:14:39 EST Position: +037 20 2 11.27 / -080 48 27 97 (±213.3ft) Altitude: 1568ft (±40.5ft) Datum: WGS-84 Azimuth/Bearing: 004 N04E 0071mils Error (Error) Elevation Grade: -003 Horizon Grade: +001 Zoom: 1.0X 28</p>		 <p>Date &amp; Time: Wed Mar 04 2020 08:22:24 EST Position: +037 20 2 52 / -080 48 10 47 (±55.5ft) Altitude: 1569ft (±40.5ft) Datum: WGS-84 Azimuth/Bearing: 285 N28W 3027mils Error (Error) Elevation Grade: -010 Horizon Grade: -003 Zoom: 1.0X 28</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
 <p>Date &amp; Time: Wed Mar 04 2020 08:25:18 EST Position: +037 20 2 307 / -080 48 10 57 (±104.1ft) Altitude: 1567ft (±35.3ft) Datum: WGS-84 Azimuth/Bearing: 104 S74E 1884mils Error (Error) Elevation Grade: -020 Horizon Grade: -002 Zoom: 1.0X 28</p>		 <p>Date &amp; Time: Wed Mar 04 2020 08:36:31 EST Position: +037 20 2 12 / -080 48 12 26 (±15.4ft) Altitude: 1568ft (±11.3ft) Datum: WGS-84 Azimuth/Bearing: 330 N22W 6007mils Error (Error) Elevation Grade: -004 Horizon Grade: -003 Zoom: 1.0X 28</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
 <p>Date &amp; Time: Wed Mar 04 2020 08:37:09 EST Position: +037 20 2 22 / -080 48 12 15 (±21.1ft) Altitude: 1565ft (±44.6ft) Datum: WGS-84 Azimuth/Bearing: 257 S77W 4569mils Error (Error) Elevation Grade: -005 Horizon Grade: -001 Zoom: 1.0X 28</p>		 <p>Date &amp; Time: Wed Mar 04 2020 08:42:50 EST Position: +037 20 2 48 / -080 48 9 27 (±51.7ft) Altitude: 1565ft (±21.3ft) Datum: WGS-84 Azimuth/Bearing: 117 S43E 2080mils Error (Error) Elevation Grade: -013 Horizon Grade: -002 Zoom: 1.0X 28</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2020 7:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2020 7:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8850
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	3/3/2020 3:29 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	3/3/2020 3:29 PM	<b>Report #</b>	8850
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during inspection. Checked rain gauges at Mount Tabor - 0.3 inches, Access Road 244 - 0.2 inches, Kow Camp Road - 0.3, Buffalo Anklets Road - 0.3 inches, and Access Road 234 - 0.3 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	3/3/2020 3:29 PM	Report #	
Pictures					
 <p>Date &amp; Time: Tue, Mar 03, 2020, 09:30:25 EST Position: +037.303115 / -080.394039 (+142.5ft) Altitude: 2823ft (+27.7ft) Datum: WGS-84 Azimuth/Bearing: 106° 50' 00" S 04W 3271mils True (+13°) Elevation Angle: +0.3° Horizon Angle: +0.3° Zoom: 1.0X 11670+00</p>		 <p>Date &amp; Time: Tue, Mar 03, 2020, 09:30:25 EST Position: +037.303115 / -080.394039 (+142.5ft) Altitude: 2823ft (+27.7ft) Datum: WGS-84 Azimuth/Bearing: 106° 50' 00" S 04W 3271mils True (+13°) Elevation Angle: +0.3° Horizon Angle: +0.3° Zoom: 1.0X 11671+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11670+00		Field Station#	11671+00	
Pic 1 Desc.	Triple stack CFS and priority one silt fence in place along LOD.		Pic 2 Desc.	Waterbar, sump pit, and waterbar end treatment in place.	
 <p>Date &amp; Time: Tue, Mar 03, 2020, 09:39:47 EST Position: +037.303115 / -080.389385 (+13290.7ft) Altitude: 2511ft (+23.3ft) Datum: WGS-84 Azimuth/Bearing: 106° 51' 12" S 004mils True (+13°) Elevation Angle: +22.8° Horizon Angle: +03.7° Zoom: 1.0X 11687+00</p>		 <p>Date &amp; Time: Tue, Mar 03, 2020, 10:47:55 EST Position: +037.318058 / -080.553592 (+68.2ft) Altitude: 2158ft (+20.1ft) Datum: WGS-84 Azimuth/Bearing: 100° 57' 05" S 04E 1866mils True (+2.4°) Elevation Angle: +0.1° Horizon Angle: +00.3° Zoom: 1.0X 11787+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11687+40		Field Station#	11787+00	
Pic 3 Desc.	Sensitive resource buffer in place at stream S-MN21.		Pic 4 Desc.	RCE in place at main line valve 26.	
 <p>Date &amp; Time: Tue, Mar 03, 2020, 10:47:55 EST Position: +037.318058 / -080.553592 (+68.2ft) Altitude: 2158ft (+20.1ft) Datum: WGS-84 Azimuth/Bearing: 100° 57' 05" S 04E 1866mils True (+2.4°) Elevation Angle: +0.1° Horizon Angle: +00.3° Zoom: 1.0X 11767+00</p>		 <p>Date &amp; Time: Tue, Mar 03, 2020, 10:47:55 EST Position: +037.318058 / -080.553592 (+68.2ft) Altitude: 2158ft (+20.1ft) Datum: WGS-84 Azimuth/Bearing: 100° 57' 05" S 04E 1866mils True (+2.4°) Elevation Angle: +0.1° Horizon Angle: +00.3° Zoom: 1.0X AR 244</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11025+00	
Pic 5 Desc.	Rain gauge at Mount Tabor Road read 0.3 inches.		Pic 6 Desc.	Rain gauge at AR 244 read 0.2 inches.	



<b>AFE</b>	124300137	<b>Date/Time</b>	3/3/2020 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.		
<b>Field Station#</b>	10883+00	<b>Field Station#</b>	10696+00		
<b>Pic 7 Desc.</b>	Rain gauge at Kow Camp Road road reads 0.3 inches.	<b>Pic 8 Desc.</b>	Rain gauge at Buffalo Anklets Road reads 0.3 inches.		
		Insert image here			
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>			
<b>Field Station#</b>	12005+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Rain gauge at AR 234 reads 0.3 inches.	<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2020 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8851
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	3/4/2020 3:51 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	61.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2020 3:51 PM	<b>Report #</b>	8851
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		3/4/2020 3:51 PM		Report #			
Pictures											
<p>Date &amp; Time: Wed Mar 04, 2020 11:10:03 EST Position: +037.319230 / -080.551702 (±12.15 ft) Altitude: 1793ft (±22.2ft) Datum: WGS-84 Azimuth/Bearing: 292° N68W 5191mils True (±17°) Elevation Angle: -16.2° Horizon Angle: -02.9° Zoom: 1.0X LDY 25</p> 				<p>Date &amp; Time: Wed Mar 04, 2020 11:11:32 EST Position: +037.318831 / -080.558428 (±15.3ft) Altitude: 1788ft (±11.5ft) Datum: WGS-84 Azimuth/Bearing: 180° S00W 3600mils True (±10°) Elevation Angle: -02.1° Horizon Angle: -02.7° Zoom: 1.0X LDY 25</p> 							
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		12005+00						Field Station#		12005+00	
Pic 1 Desc.		Triple stack compost filter sock in place.						Pic 2 Desc.		Dumpster being utilized for trash management.	
<p>Date &amp; Time: Wed Mar 04, 2020 11:12:29 EST Position: +037.318834 / -080.555549 (±15.2ft) Altitude: 1787ft (±11.5ft) Datum: WGS-84 Azimuth/Bearing: 047° N47E 0836mils True (±10°) Elevation Angle: -01.9° Horizon Angle: -00.9° Zoom: 1.0X LDY 25</p> 				<p>Date &amp; Time: Wed Mar 04, 2020 11:12:57 EST Position: +037.318499 / -080.557228 (±15.2ft) Altitude: 1787ft (±11.5ft) Datum: WGS-84 Azimuth/Bearing: 233° S53W 4142mils True (±10°) Elevation Angle: -00.0° Horizon Angle: -00.5° Zoom: 1.0X LDY 25</p> 							
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		12005+00						Field Station#		12005+00	
Pic 3 Desc.		RCE in place at employee parking lot.						Pic 4 Desc.		Secondary containment in place under fuel cell.	
<p>Date &amp; Time: Wed Mar 04, 2020 11:13:27 EST Position: +037.318804 / -080.557755 (±13.3ft) Altitude: 1791ft (±22.2ft) Datum: WGS-84 Azimuth/Bearing: 299° N61W 5316mils True (±10°) Elevation Angle: -03.4° Horizon Angle: -00.3° Zoom: 1.0X LDY 25</p> 				<p>Date &amp; Time: Wed Mar 04, 2020 11:11:32 EST Position: +037.318792 / -080.558575 (±15.4ft) Altitude: 1788ft (±11.5ft) Datum: WGS-84 Azimuth/Bearing: 300° S20W 3600mils True (±10°) Elevation Angle: -02.1° Horizon Angle: -00.4° Zoom: 1.0X LDY 25</p> 							
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		12005+00						Field Station#		12005+00	
Pic 5 Desc.		No leaks observed under staged equipment.						Pic 6 Desc.		18 inch compost filter sock in place along LOD.	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2020 3:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2020 3:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8880
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	3/5/2020 7:25 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	53.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	3/5/2020 7:25 AM	<b>Report #</b>	8880
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended PPLs weekly safety meeting. Attended the morning inspection meeting. Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 7:25 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Mar 05, 2020, 08:22:00 EST  Position: +037.222711° / -080.552469° (-78.7N)  Altitude: 2384ft (-10.4m)  Datum: WGS-84  Azimuth/Bearing: 051° N51E 0907mils True (-22°)  Elevation Angle: -10.4°  Horizon Angle: +00.9°  Zoom: 1.0x  11025+00</p> 		<p>Date &amp; Time: Thu, Mar 05, 2020, 08:44:00 EST  Position: +037.261167° / -080.66633° (-79.7N)  Altitude: 2353ft (-7.1m)  Datum: WGS-84  Azimuth/Bearing: 051° N51E 1010mils True (-22°)  Elevation Angle: -10.2°  Horizon Angle: +00.4°  Zoom: 1.0x  11034+00</p> 			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11025+50	<b>Field Station#</b>	11034+00		
<b>Pic 1 Desc.</b>	S-IJ18.	<b>Pic 2 Desc.</b>	RoW conditions and controls.		
<p>Date &amp; Time: Thu, Mar 05, 2020, 08:51:00 EST  Position: +037.318169° / -080.547713° (-52.5N)  Altitude: 2674ft (-8.0m)  Datum: WGS-84  Azimuth/Bearing: 029° N29E 0910mils True (-11°)  Elevation Angle: -12.2°  Horizon Angle: +01.2°  Zoom: 1.0x  11039+00</p> 		<p>Date &amp; Time: Thu, Mar 05, 2020, 08:51:00 EST  Position: +037.318169° / -080.547713° (-52.5N)  Altitude: 2674ft (-8.0m)  Datum: WGS-84  Azimuth/Bearing: 029° N29E 0910mils True (-11°)  Elevation Angle: -12.2°  Horizon Angle: +01.2°  Zoom: 1.0x  11039+00</p> 			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11039+00	<b>Field Station#</b>	11050+10		
<b>Pic 3 Desc.</b>	CFS perimeter controls.	<b>Pic 4 Desc.</b>	S-IJ16B and S-IJ17.		
<p>Date &amp; Time: Thu, Mar 05, 2020, 09:00:00 EST  Position: +037.211809° / -080.544488° (-19.3N)  Altitude: 2675ft (-8.0m)  Datum: WGS-84  Azimuth/Bearing: 051° N51E 0907mils True (-22°)  Elevation Angle: -10.4°  Horizon Angle: +00.9°  Zoom: 1.0x  11055+00</p> 		<p>Date &amp; Time: Thu, Mar 05, 2020, 09:00:00 EST  Position: +037.211809° / -080.544488° (-19.3N)  Altitude: 2675ft (-8.0m)  Datum: WGS-84  Azimuth/Bearing: 051° N51E 0907mils True (-22°)  Elevation Angle: -10.4°  Horizon Angle: +00.9°  Zoom: 1.0x  11055+00</p> 			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11055+00	<b>Field Station#</b>	11040+00		
<b>Pic 5 Desc.</b>	RoW conditions and controls.	<b>Pic 6 Desc.</b>	Vegetation or stabilization.		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 7:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 7:25 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8881
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	3/5/2020 7:27 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	39.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 7:27 AM	<b>Report #</b>	8881
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 205 - MP 207 Observed no damaged ECD's during inspection, ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list Crews making repairs to items identified off Seven Oaks					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	3/5/2020 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p> Date &amp; Time: Thu Mar 05 2020 09:26:57 EST  Position: -037 21 10.49 / -080 35 31.87 / 10826.7m  Altitude: 2290ft (+80.7m)  Datum: WGS-84  Azimuth/Bearing: 001° N31E 0018mils Error (Error)  Elevation Grade: +034  Horizon Grade: +008  Zoom: 1.0X  10858 </p>		 <p> Date &amp; Time: Thu Mar 05 2020 09:32:31 EST  Position: -037 20 9.51 / -080 37 23.24 / 10815.2m  Altitude: 2310ft (+77.3m)  Datum: WGS-84  Azimuth/Bearing: 327° N33W 5813mils Error (Error)  Elevation Grade: +041  Horizon Grade: +006  Zoom: 1.0X  10864 </p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10858+00		<b>Field Station#</b>	10864+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
 <p> Date &amp; Time: Thu Mar 05 2020 09:44:10 EST  Position: -037 20 10.65 / -080 35 45.99 / 10813.3m  Altitude: 2346ft (+64.8m)  Datum: WGS-84  Azimuth/Bearing: 061° N61E 1084mils Error (Error)  Elevation Grade: +024  Horizon Grade: +001  Zoom: 1.0X  10874 </p>		 <p> Date &amp; Time: Thu Mar 05 2020 09:44:10 EST  Position: -037 20 4.02 / -080 35 39.53 / 10813.5m  Altitude: 2297ft (+64.3m)  Datum: WGS-84  Azimuth/Bearing: 306° NS4W 5440mils Error (Error)  Elevation Grade: +063  Horizon Grade: +002  Zoom: 1.0X  10890 </p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10874+00		<b>Field Station#</b>	10890+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
 <p> Date &amp; Time: Thu Mar 05 2020 10:06:21 EST  Position: -037 19 55.87 / -080 35 34.67 / 10801.8m  Altitude: 2558ft (+98.9m)  Datum: WGS-84  Azimuth/Bearing: 263° S83W 4676mils Error (Error)  Elevation Grade: +033  Horizon Grade: +012  Zoom: 1.0X  1090 </p>		 <p> Date &amp; Time: Thu Mar 05 2020 10:06:21 EST  Position: -037 19 55.87 / -080 35 34.67 / 10801.8m  Altitude: 2164ft (+58.4m)  Datum: WGS-84  Azimuth/Bearing: 324° N26W 6938mils Error (Error)  Elevation Grade: +012  Horizon Grade: +086  Zoom: 1.0X  10935 </p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10910+00		<b>Field Station#</b>	10935+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 7:27 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8882
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	3/5/2020 7:49 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions




Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	3/5/2020 7:49 AM	<b>Report #</b>	8882
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended PPL safety meeting Attended inspection meeting at the work trailer. SWPPP inspection: Sta#11023+88 to 10930+00. MP- 208.6 to 206.2 The row is dry and in stable condition. Streams S-IJ18, S-RR5, S-E24, S-E25 and environment controls and sensitive resource signage are in acceptable condition. The Karst at sta#10965+00 has animal damage to silt fence but Karst has not been negatively impacted, repairs will be made. Perimeter controls, Silt fence, CFS, SSF are in acceptable condition. Water bars are in stable condition. Sump pits are in acceptable condition. Water bar end treatments are in acceptable condition. AR-244.00 and Doe Creek RCE are in acceptable condition. Landowner has removed the top sock of triple stack perimeter controls at sta#'s 10983+00 and 10969+00 and drove onto the row travel lane rutting the row and damaging the straw mulch in a few areas. The contractor will make repairs.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	3/5/2020 7:49 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Mar 05, 2020, 08:40:13 EST Position: +037 322319 / -080 553046 (±16.4ft) Altitude: 2338ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 350° N10W 4222mils True (±10°) Elevation Angle: -30.7° Horizon Angle: +04.6° Zoom: 1.0x AR-244-Stream S-IJ18- P1 stream buffer down stake broken off.</p>		 <p>Date &amp; Time: Thu, Mar 05, 2020, 08:43:52 EST Position: +037 322236 / -080 553260 (±16.4ft) Altitude: 2383ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 161° S19E 2862mils True (±10°) Elevation Angle: -21.2° Horizon Angle: +00.7° Zoom: 1.0x AR-244-Stream S-IJ18- Equipment bridge &amp; stream controls.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11024+00	<b>Field Station#</b>	11024+00		
<b>Pic 1 Desc.</b>	Animal damage to P1	<b>Pic 2 Desc.</b>	Stream bridge and stream controls are in acceptable condition, S-IJ18		
 <p>Date &amp; Time: Thu, Mar 05, 2020, 08:50:02 EST Position: +037 325319 / -080 555268 (±16.4ft) Altitude: 2442ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 300° N60W 5330mils True (±10°) Elevation Angle: -04.9° Horizon Angle: +04.3° Zoom: 1.0x Stream S-RR5- Equipment bridge &amp; stream controls.</p>		 <p>Date &amp; Time: Thu, Mar 05, 2020, 09:12:47 EST Position: +037 325485 / -080 566850 (±32.8ft) Altitude: 2364ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: +04° 576E 1849mils True (±10°) Elevation Angle: -07.6° Horizon Angle: -01.1° Zoom: 1.0x Sta#10985+00-Stream S-E25- Equipment bridge &amp; stream ECD's are in acceptable condition.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11017+00	<b>Field Station#</b>	10986+00		
<b>Pic 3 Desc.</b>	Stream S-RR5 and ECD's are in acceptable condition.	<b>Pic 4 Desc.</b>	Stream S-E25 and stream ECD's are in acceptable condition.		
 <p>Date &amp; Time: Thu, Mar 05, 2020, 09:14:01 EST Position: +037 325500 / -080 566891 (±16.4ft) Altitude: 2389ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 311° N45W 5529mils True (±10°) Elevation Angle: -12.0° Horizon Angle: +00.9° Zoom: 1.0x Sta#10985+00-Stream S-E24Equipment bridge &amp; stream ECD's are in acceptable condition</p>		 <p>Date &amp; Time: Thu, Mar 05, 2020, 09:19:45 EST Position: +037 325814 / -080 566391 (±32.8ft) Altitude: 2490ft (±78.7ft) Datum: WGS-84 Azimuth/Bearing: 219° S39W 3893mils True (±10°) Elevation Angle: -31.7° Horizon Angle: +03.3° Zoom: 1.0x Sta#10983+00- Top sock of triple stack perimeter controls rolled off.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10985+00	<b>Field Station#</b>	10983+00		
<b>Pic 5 Desc.</b>	Stream S-E24 and ECD's are in acceptable condition.	<b>Pic 6 Desc.</b>	Landowner removed top CFS perimeter control		



<b>AFE</b>	124300137	<b>Date/Time</b>	3/5/2020 7:49 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, Mar 05, 2020, 09:34:49 EST Position: +037 336951 / -080 570242 (±32.8ft) Altitude: 2422ft (±39.7m) Datum: WGS-84 Azimuth/Bearing: 292° N48W 5191mils True (±10°) Elevation Angle: -39.4° Horizon Angle: +03.1° Zoom: 1.0X Sta#10977+00: Landowner driving the travel rutting</small></p>		 <p><small>Date &amp; Time: Thu, Mar 05, 2020, 09:30:25 EST Position: +037 336951 / -080 570242 (±32.8ft) Altitude: 2422ft (±39.7m) Datum: WGS-84 Azimuth/Bearing: 203° S23W 3609mils True (±10°) Elevation Angle: -29.8° Horizon Angle: +00.4° Zoom: 1.0X Sta#10969+00: Landowner removed stakes and removed top sock of triple stake perimeter control.</small></p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10980+00	<b>Field Station#</b>	10969+00		
<b>Pic 7 Desc.</b>	Landowner drove on travel lane and rutted row and damaged mulch.	<b>Pic 8 Desc.</b>	Landowner removed top CFS perimeter control and drove onto row.		
 <p><small>Date &amp; Time: Thu, Mar 05, 2020, 09:35:34 EST Position: +037 337886 / -080 571527 (±36.4ft) Altitude: 2580ft (±26.2m) Datum: WGS-84 Azimuth/Bearing: 044° N44E 0782mils True (±10°) Elevation Angle: -33.3° Horizon Angle: +14.1° Zoom: 1.0X Sta#10965+00: Karst-P1 damaged, silt fence destroyed</small></p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>			
<b>Field Station#</b>	10964+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Animal damage to P1 at Karst.	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 7:49 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8891
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	3/5/2020 3:25 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	54.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)  |     |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 3:25 PM	<b>Report #</b>	8891
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137	Date/Time	3/5/2020 3:25 PM	Report #	
Pictures						
<div><div><div>Date &amp; Time: Thu, Mar 05, 2020, 09:41:05 EST Position: +037.351077 / -080.649432 (+274.3m) Altitude: 2211ft (+63.4ft) Datum: WGS-84 Azimuth/Bearing: 173° S07E 3076mils True (+10°) Elevation Angle: -05.8 Horizon Angle: -01.5 Zoom: 1.0x 10710+00</div><div></div></div></div>			<div><div><div>Date &amp; Time: Thu, Mar 05, 2020, 09:55:23 EST Position: +037.351077 / -080.649432 (+274.3m) Altitude: 2211ft (+63.4ft) Datum: WGS-84 Azimuth/Bearing: 090° S90E 1600mils True (+10°) Elevation Angle: -09.2 Horizon Angle: -05.6 Zoom: 1.0x 10712+50 S-G33</div><div></div></div></div>			
GPS Location		See photo for GPS location.		GPS Location		See photo for GPS location.
Field Station#		10710+00		Field Station#		10712+50
Pic 1 Desc.		Compost filter sock checks in place along access road 241.04.		Pic 2 Desc.		Sensitive resource buffer in place at stream S-G33.
<div><div><div>Date &amp; Time: Thu, Mar 05, 2020, 09:49:14 EST Position: +037.348643 / -080.647916 (+15.4ft) Altitude: 2313ft (+71.3ft) Datum: WGS-84 Azimuth/Bearing: 157° S22E 2791mils True (+10°) Elevation Angle: -29.4 Horizon Angle: -105.8 Zoom: 1.0x 10711+00</div><div></div></div></div>			<div><div><div>Date &amp; Time: Thu, Mar 05, 2020, 09:54:04 EST Position: +037.351077 / -080.649432 (+274.3m) Altitude: 2303ft (+70.2ft) Datum: WGS-84 Azimuth/Bearing: 126° S54E 2240mils True (+10°) Elevation Angle: -14.5 Horizon Angle: -03.2 Zoom: 1.0x 10698+00 S-G32</div><div></div></div></div>			
GPS Location		See photo for GPS location.		GPS Location		See photo for GPS location.
Field Station#		10711+00		Field Station#		10698+00
Pic 3 Desc.		Waterbar with CFS end treatment in place across travel.		Pic 4 Desc.		Sensitive resource buffer in place at stream S-G32.
<div><div><div>Date &amp; Time: Thu, Mar 05, 2020, 09:49:23 EST Position: +037.349223 / -080.632600 (+15.4ft) Altitude: 2265ft (+69.3ft) Datum: WGS-84 Azimuth/Bearing: 140° S40E 2489mils True (+10°) Elevation Angle: -07.6 Horizon Angle: -100.0 Zoom: 1.0x 10696+00</div><div></div></div></div>			<div><div><div>Date &amp; Time: Thu, Mar 05, 2020, 09:49:23 EST Position: +037.349223 / -080.632600 (+15.4ft) Altitude: 2265ft (+69.3ft) Datum: WGS-84 Azimuth/Bearing: 140° S40E 2489mils True (+10°) Elevation Angle: -07.6 Horizon Angle: -100.0 Zoom: 1.0x 10696+00</div><div></div></div></div>			
GPS Location		See photo for GPS location.		GPS Location		See photo for GPS location.
Field Station#		10710+00		Field Station#		10696+00
Pic 5 Desc.		ROW stabilized with natural vegetation.		Pic 6 Desc.		RCE in place at Buffalo Anklets Road.

<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 3:25 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/5/2020 3:25 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8910
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	3/6/2020 6:45 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	39.00
<b>Municipality</b>	N/A	<b>Weather</b>	Snow/Sleet	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 6:45 AM	<b>Report #</b>	8910
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Attended the morning inspection meeting. Performed SWPPP inspection from MP 213 to MP 214.8. No major issues were identified. One location of minor damage to controls was identified, crews made repairs prior to the end of day. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Crews are currently working in the section of RoW between Hwy 42 and the Seven Oaks access rd performing preventative maintenance.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 6:45 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11258+00	<b>Field Station#</b>	11287+00		
<b>Pic 1 Desc.</b>	Vegetation/stabilization sufficient.		<b>Pic 2 Desc.</b>	Crews performing maintenance on fill slope.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11292+80	<b>Field Station#</b>	11327+85		
<b>Pic 3 Desc.</b>	S-MM18.		<b>Pic 4 Desc.</b>	S-NN12.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11352+97	<b>Field Station#</b>	11334+00		
<b>Pic 5 Desc.</b>	S-NN11.		<b>Pic 6 Desc.</b>	Vegetation or stabilization sufficient.	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 6:45 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 6:45 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8911
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	3/6/2020 7:12 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	40.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)  |     |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	3/6/2020 7:12 AM	<b>Report #</b>	8911
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 209 - MP 211.5 Observed no damaged ECD's during inspection, ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list Crews making repairs to items identified off Seven Oaks and Doe Creek					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 7:12 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11078+00		<b>Field Station#</b>	11090+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11120+00		<b>Field Station#</b>	11110+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11127+00		<b>Field Station#</b>	11138+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 7:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 7:12 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8917
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	3/6/2020 7:41 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11161+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 7:41 AM	<b>Report #</b>	8917
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11254+88 to 11161+00. MP-211 to 213 Weather during inspection had a mix of rain, sleet, snow and gusty winds. The row is muddy but in stable condition. Temporary stabilization is acceptable. Perimeter controls, Silt fence, CFS, & SSF are in acceptable condition. Water bars are stable. Sump pits and water bar end treatments are in acceptable condition Slope drains are in acceptable condition. CWD pipe and plunge pool are in good condition. Access roads 25, 249.02 & 249.01 are maintained in acceptable condition. Drainage feature ECD's are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	3/6/2020 7:41 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Mar 06, 2020, 09:18:05 EST  Position: +437.301443° / -080.502571° (±32.8m)  Altitude: 2017ft (±39.4m)  Datum: WGS-84  Azimuth/Bearing: 189° S09W 3360mils True (±10°)  Elevation Angle: -30.3°  Horizon Angle: +02.8°  Zoom: 1.0X  Star 11225+00- Slope drain, end treatment and rock channel</p> 		<p>Date &amp; Time: Fri, Mar 06, 2020, 09:22:21 EST  Position: +437.302256° / -080.505147° (±32.8m)  Altitude: 2017ft (±39.4m)  Datum: WGS-84  Azimuth/Bearing: 244° S64W 4338mils True (±10°)  Elevation Angle: -26.3°  Horizon Angle: +06.3°  Zoom: 1.0X  Star 1121+00- Slope drain, PI check, perimeter controls</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11225+00	<b>Field Station#</b>	1121+40		
<b>Pic 1 Desc.</b>	Slope drain, end treatment and rock channel are in acceptable condition.	<b>Pic 2 Desc.</b>	Slope drain, checks and perimeter controls are in acceptable condition.		
<p>Date &amp; Time: Fri, Mar 06, 2020, 10:10:01 EST  Position: +437.300777° / -080.500000° (±32.8m)  Altitude: 1920ft (±39.4m)  Datum: WGS-84  Azimuth/Bearing: 225° S15W 5244mils True (±10°)  Elevation Angle: -19.2°  Horizon Angle: +06.8°  Zoom: 1.0X  Star 11184+00- CWD plunge pool</p> 		<p>Date &amp; Time: Fri, Mar 06, 2020, 10:16:30 EST  Position: +437.300132° / -080.501195° (±32.8m)  Altitude: 2227ft (±39.4m)  Datum: WGS-84  Azimuth/Bearing: 295° N05W 5244mils True (±10°)  Elevation Angle: -14.9°  Horizon Angle: +06.8°  Zoom: 1.0X  Star 11184+00- CWD plunge pool</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11191+00	<b>Field Station#</b>	11184+00		
<b>Pic 3 Desc.</b>	Drainage feature and ECD's are in acceptable condition.	<b>Pic 4 Desc.</b>	CWD pipe and plunge pool are in acceptable condition.		
<p>Date &amp; Time: Fri, Mar 06, 2020, 09:09:14 EST  Position: +437.307240° / -080.511552° (±16.0m)  Altitude: 1989ft (±13.1m)  Datum: WGS-84  Azimuth/Bearing: 214° S36W 3840mils True (±10°)  Elevation Angle: -21.9°  Horizon Angle: +07.5°  Zoom: 1.0X  Star 11184+00- Access road and rock check dams</p> 		<p>Date &amp; Time: Fri, Mar 06, 2020, 10:18:30 EST  Position: +437.310000° / -080.510000° (±14.4m)  Altitude: 2045ft (±19.3m)  Datum: WGS-84  Azimuth/Bearing: 141° S35E 3300mils True (±5°)  Elevation Angle: -41.0°  Horizon Angle: +04.0°  Zoom: 1.0X  Star 11161+00- Rain, sleet, snow with gusty winds during inspection</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11184+50	<b>Field Station#</b>	11161+00		
<b>Pic 5 Desc.</b>	AR-249.02- Access road and rock check dams are in acceptable condition.	<b>Pic 6 Desc.</b>	Rain, sleet, snow with gusty winds during inspection.		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 7:41 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 7:41 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	8934
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	3/6/2020 2:51 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11525+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11351+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	40.00
<b>Municipality</b>	N/A	<b>Weather</b>	Snow/Sleet	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 2:51 PM	<b>Report #</b>	8934
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	3/6/2020 2:51 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11506+00		<b>Field Station#</b>	11505+00	
<b>Pic 1 Desc.</b>	Clean water diversion pipe and plunge pool in place.		<b>Pic 2 Desc.</b>	Clean water diversion pipe and clean water diversion berm in place.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11502+00		<b>Field Station#</b>	11489+00	
<b>Pic 3 Desc.</b>	Conveyance channel with rock checks in place along double cut section of ROW.		<b>Pic 4 Desc.</b>	RCE in place at Stevers Gap Road.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11477+00		<b>Field Station#</b>	11380+00	
<b>Pic 5 Desc.</b>	Two-tone stabilized with ECB and slope drain pipes in place to minimize erosion.		<b>Pic 6 Desc.</b>	Off ROW karst feature protected with triple barrier ECDs.	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 2:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	3/6/2020 2:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		