



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9596
Inspector	Len Kruizenga			Date/Time	3/30/2020 2:01 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+88
State	VA	Inspection Area	Full	Station End	11161+00
County	Giles	Ground	Dry	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	3/30/2020 2:01 PM	Report #	9596
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met EI inspection team at Winding Way to discuss days task. SWPPP inspection: Sta# 11254+88 to 11161+00. MP-213 to 211. Row is dry and in stable condition. Temporary stabilization is in acceptable condition. Water bars are stable, there is some erosion in the flow lines of the water bars. Water bar end treatments are in acceptable condition. Perimeter controls, P1 silt fence, CFS, and SSF are all in acceptable condition. Slope drain pipes and inlets are acceptable condition. Rock channel is in acceptable condition. CWD pipe and plunge pool are in good condition. Drainage feature and ECD's are in acceptable condition. Access roads AR-25, AR- 249.02 & AR-249.01 are maintained in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	3/30/2020 2:01 PM	Report #	
Pictures					
<p>Date & Time: Mon, Mar 30, 2020, 09:39:51 EDT Position: +037.298364 / -080.502756 (+541.40) Altitude: 2031ft (+150.9m) Datum: WGS-84 Azimuth/Bearing: 354° N06W 6293mils True (Error) Elevation Angle: -09.6° Horizon Angle: -01.8° Zoom: 1.0X Sta#11227+00 to 11227+00: Row stabilization vegetation is good</p> 		<p>Date & Time: Mon, Mar 30, 2020, 09:46:52 EDT Position: +037.298334 / -080.502756 (+541.40) Altitude: 2031ft (+150.9m) Datum: WGS-84 Azimuth/Bearing: 197° S01W 3302mils True (+25) Elevation Angle: 37.0° Horizon Angle: -05.4° Zoom: 1.0X Sta#11225+00: Slope drain and treatment rock channels are in acceptable condition</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11227+00	Field Station#	11225+00		
Pic 1 Desc.	Row and temporary stabilization are in acceptable condition.	Pic 2 Desc.	Slope drain pipe, end treatment and rock channel are in acceptable condition.		
<p>Date & Time: Mon, Mar 30, 2020, 10:06:51 EDT Position: +037.300867 / -080.505803 (+164.70) Altitude: 2031ft (+150.9m) Datum: WGS-84 Azimuth/Bearing: 147° S33E 2613mils True (+10°) Elevation Angle: -10.6° Horizon Angle: +03.4° Zoom: 1.0X Sta#11211+00- P1 silt fence perimeter controls are in acceptable condition</p> 		<p>Date & Time: Mon, Mar 30, 2020, 10:06:51 EDT Position: +037.300867 / -080.511744 (+52.40) Altitude: 1848ft (+157.5m) Datum: WGS-84 Azimuth/Bearing: 111° N01E 0019mils True (+10°) Elevation Angle: 17.0° Horizon Angle: +08.3° Zoom: 1.0X Sta#11204+00: CFS perimeter and treatment & CFS perimeter controls are in acceptable condition</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11211+00	Field Station#	11204+00		
Pic 3 Desc.	Silt fence perimeter controls are in acceptable condition.	Pic 4 Desc.	CFS perimeter controls and triple stack end treatments are in acceptable condition.		
<p>Date & Time: Mon, Mar 30, 2020, 10:06:51 EDT Position: +037.300867 / -080.505803 (+164.70) Altitude: 1927ft (+158.8m) Datum: WGS-84 Azimuth/Bearing: 300° N60W 5043mils True (+10°) Elevation Angle: -12.2° Horizon Angle: -01.5° Zoom: 1.0X Sta#11192+00: Environmental controls and drainage feature are in acceptable condition</p> 		<p>Date & Time: Mon, Mar 30, 2020, 10:06:51 EDT Position: +037.300867 / -080.511744 (+52.40) Altitude: 1848ft (+157.5m) Datum: WGS-84 Azimuth/Bearing: 297° N43W 5280mils True (+10°) Elevation Angle: 12.1° Horizon Angle: -05.0° Zoom: 1.0X Sta#11184+00: CWD pipe & plunge pool are in acceptable condition</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11192+00	Field Station#	11184+00		
Pic 5 Desc.	Environmental controls and drainage feature are in acceptable condition.	Pic 6 Desc.	CWD pipe and plunge pool are in good condition.		

A/E	124300137	Date/Time	3/30/2020 2:01 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	3/30/2020 2:01 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9602
Inspector	Chris Burns			Date/Time	3/30/2020 2:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Damp	Temperature (°F)	64.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/30/2020 2:03 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11258+00	Field Station#	11265+25		
Pic 1 Desc.	Vegetation or stabilization sufficient.	Pic 2 Desc.	P-1 perimeter controls functional.		
					
GPS Location	3	GPS Location	4		
Field Station#	11292+80	Field Station#	11310+00		
Pic 3 Desc.	S-MM18.	Pic 4 Desc.	PPL crews replacing P-1 perimeter controls.		
					
GPS Location	5	GPS Location	6		
Field Station#	11327+85	Field Station#	11333+00		
Pic 5 Desc.	S-NN12.	Pic 6 Desc.	Vegetation or stabilization sufficient.		

A/E	124300137	Date/Time	3/30/2020 2:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/30/2020 2:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9608
Inspector	Garrett Barclay			Date/Time	3/30/2020 3:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10962+00
County	Giles	Ground	Dry	Temperature (°F)	69.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Secondary Containment	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/30/2020 3:22 PM	Report #	9608
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 209 - MP 211.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/30/2020 3:22 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11068+00		Field Station#	11084+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11090+00		Field Station#	11119+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11128+00		Field Station#	11137+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	3/30/2020 3:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/30/2020 3:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9637
Inspector	Rob Robertson			Date/Time	3/31/2020 11:56 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Wet	Temperature (°F)	47.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00





- | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Plunge Pool	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/31/2020 11:56 AM	Report #	9637
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
Conducted a routine VADEQ SWPPP inspection of ROW on Brush Mountain. The ROW remains in stable condition on all JNF and private property in the area. ECD maintenance needs are being addressed by the contractor. Slope breakers and end treatments are effective and controlling runoff. Resource buffers are effective, controls are in place and no impact has occurred. No rilling of surface was located. Vegetation is adequate. No sediment has migrated beyond the LOD. RCEs are in good condition. No evidence of vandalism located. There are currently no environmental concerns in this area.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 3/31/2020 11:56 AM		Report #	
Pictures					
 <p>Date & Time: Tue, Mar 31, 2020, 09:56:57 EDT Position: +037.385529° / -080.394601° (+52.270) Altitude: 2922ft (+98.770) Datum: WGS-84 Azimuth/Bearing: 109° S 80° E 341.00m Magnetic (+12°) Elevation Angle: +01.6° Horizon Angle: +04.8° Zoom: 1.0X Brush Min. Stable ROW: 11659+00</p>		 <p>Date & Time: Tue, Mar 31, 2020, 09:56:54 EDT Position: +037.385529° / -080.394601° (+52.270) Altitude: 2922ft (+98.770) Datum: WGS-84 Azimuth/Bearing: 109° S 80° E 341.00m Magnetic (+12°) Elevation Angle: +01.6° Horizon Angle: +04.8° Zoom: 1.0X Brush Min. Stable ROW: Perimeter controls in place 11659+00</p>			
GPS Location		On photo		GPS Location	
Field Station#		11669+87		Field Station#	
Pic 1 Desc.		ROW and topsoil piles are stable		Pic 2 Desc.	
				Perimeter controls are in place	
 <p>Date & Time: Tue, Mar 31, 2020, 09:11:47 EDT Position: +037.384229° / -080.397475° (+16.4ft) Altitude: 2937ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 127° N 81° W 344.00m Magnetic (+12°) Elevation Angle: +1.6° Horizon Angle: +0.0° Zoom: 1.0X Brush Min. Stable ROW: Perimeter controls in place 11655+00</p>		 <p>Date & Time: Tue, Mar 31, 2020, 09:25:58 EDT Position: +037.310577° / -080.397475° (+16.4ft) Altitude: 2156ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 127° N 81° W 344.00m Magnetic (+13°) Elevation Angle: +1.6° Horizon Angle: +0.0° Zoom: 1.0X Brush Min. Stable ROW: Slope breakers functional. Perimeter controls in place 11640+00</p>			
GPS Location		On photo		GPS Location	
Field Station#		11655+00		Field Station#	
Pic 3 Desc.		End treatments are effective		Pic 4 Desc.	
				Slope breakers and end treatments are effective	
 <p>Date & Time: Tue, Mar 31, 2020, 09:40:08 EDT Position: +037.318141° / -080.398018° (+32.8ft) Altitude: 1943ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 279° N 81° W 496.00m Magnetic (+13°) Elevation Angle: +19.6° Horizon Angle: +02.9° Zoom: 1.0X Brush Min. Stable ROW: ECDs functional 11628+50</p>		 <p>Date & Time: Tue, Mar 31, 2020, 09:40:55 EDT Position: +037.318141° / -080.398018° (+32.8ft) Altitude: 1919ft (+35.3ft) Datum: WGS-84 Azimuth/Bearing: 279° N 81° E 293.00m Magnetic (+13°) Elevation Angle: +22.8° Horizon Angle: +02.6° Zoom: 1.0X Brush Min. Stable ROW: S-HH18 crossing stable 11626+04</p>			
GPS Location		On photo		GPS Location	
Field Station#		11628+50		Field Station#	
Pic 5 Desc.		Diversion pipes are in place		Pic 6 Desc.	
				S-HH18 crossing is stable. Buffers are vegetated and controls in place.	

AFE	124300137	Date/Time	3/31/2020 11:56 AM	Report #	
Pictures					
 <p>Time & Date: Tue Mar 31 2020 11:56:01 EDT Position: -037.3135777, -080.4024725 (s32.8N) Altitude: 1925ft (s39.4N) Datum: WGS-84 Azimuth/Bearing: 141° S39E 2507mils Magnetic (s12°) Elevation Angle: -05.9° Horizon Angle: -02.2° Zoom: 1.0X Brush Mat: S-RR12 crossing stable</p>		 <p>Time & Date: Tue Mar 31 2020 11:56:01 EDT Position: -037.3135777, -080.4024725 (s32.8N) Altitude: 1925ft (s39.4N) Datum: WGS-84 Azimuth/Bearing: 208° S08W 2007mils Magnetic (s14°) Elevation Angle: -02.8° Horizon Angle: -00.4° Zoom: 1.0X Brush Mat: S-006 crossing stable</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11614+20	Field Station#	11608+17		
Pic 7 Desc.	Buffers stable with controls in place at S-RR14 crossing	Pic 8 Desc.	Buffers stable at S006 crossing		
 <p>Time & Date: Tue Mar 31 2020 10:02:32 EDT Position: -037.3135777, -080.402725 (s39.4N) Altitude: 1925ft (s39.4N) Datum: WGS-84 Azimuth/Bearing: 208° S08W 2007mils Magnetic (s14°) Elevation Angle: -02.8° Horizon Angle: -00.9° Zoom: 1.0X Brush Mat: S-006 crossing stable</p>		 <p>Time & Date: Tue Mar 31 2020 10:02:32 EDT Position: -037.3135777, -080.402725 (s39.4N) Altitude: 1925ft (s39.4N) Datum: WGS-84 Azimuth/Bearing: 153° S27E 2720mils Magnetic (s14°) Elevation Angle: -08.0° Horizon Angle: -00.9° Zoom: 1.0X Brush Mat: S-RR13 crossing stable</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11608+17	Field Station#	11613+69		
Pic 9 Desc.	Environmental controls are in place at the S006 crossing	Pic 10 Desc.	S-RR13 crossing at access road MN-258.04 is stable		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	3/31/2020 11:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9639
Inspector	Len Kruizenga			Date/Time	3/31/2020 12:57 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11898+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	45.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Sensitive Resource Signage	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			
Culvert	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/31/2020 12:57 PM	Report #	9639
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with EI's at Winding Way. SWPPP inspection: Sta#11899+00 to 12005+00. MP 225.3 to 227.3 Access roads 266.00 & 266.03 are maintained in acceptable condition. Row was try and in stable condition. Permanent restoration is acceptable. Perimeter controls are functional. Karst's are in good condition. Water bars and level spreaders are in acceptable condition. Wetland ECD's are in acceptable condition. Light rain fell during inspection and became heavier has the day progressed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	3/31/2020 12:57 PM	Report #	
Pictures					
<p>Date & Time: Tue, Mar 31, 2020, 09:46:53 EDT Position: +037.277436° / -080.275329° (±16.40) Altitude: 017.01m (±1.00) Datum: WGS-84 Azimuth/Bearing: 125.55SE 2222mils True (±10°) Elevation Angle: -09.7° Horizon Angle: +01.0° Zoom: 1.0X Start: 11900+00- Access road & controls are in acceptable condition</p> 		<p>Date & Time: Tue, Mar 31, 2020, 09:18:29 EDT Position: +037.306598° / -080.275329° (±19.67.44) Altitude: 017.01m (±1.00) Datum: WGS-84 Azimuth/Bearing: 055.50NW 6274mils True (±10°) Elevation Angle: -13.5° Horizon Angle: +00.9° Zoom: 1.0X Start: 11936+00- Row stable, new growth looks good</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11900+00	Field Station#	11936+00		
Pic 1 Desc.	AR-266.03- Access rd & ECD's.	Pic 2 Desc.	Row permanent restoration		
<p>Date & Time: Tue, Mar 31, 2020, 09:31:48 EDT Position: +037.277436° / -080.309199° (±8150.0m) Altitude: 017.01m (±1.00) Datum: WGS-84 Azimuth/Bearing: 132.54SE 2364mils True (±10°) Elevation Angle: -12.2° Horizon Angle: +00.0° Zoom: 1.0X Start: 11950+00- Karst ECD's are in acceptable condition</p> 		<p>Date & Time: Tue, Mar 31, 2020, 09:40:44 EDT Position: +037.270136° / -080.320000° (±98.4m) Altitude: 017.24m (±210.0m) Datum: WGS-84 Azimuth/Bearing: 160.53SE 2864mils True (±10°) Elevation Angle: -14.7° Horizon Angle: +01.3° Zoom: 1.0X Start: 11977+00- Karst ECD's are in acceptable condition</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11950+00	Field Station#	11977+00		
Pic 3 Desc.	ECD's protecting Karst	Pic 4 Desc.	Karst and Karst ECD's are in acceptable condition		
<p>Date & Time: Tue, Mar 31, 2020, 10:19:48 EDT Position: +037.262230° / -080.517017° (±16.40) Altitude: 15.57m (±105.0m) Datum: WGS-84 Azimuth/Bearing: 221.54W 3929mils True (±10°) Elevation Angle: -15.4° Horizon Angle: +01.5° Zoom: 1.0X Start: 12000+00 to 12001+00- Wetland ECD's are in acceptable condition</p> 		<p>Date & Time: Tue, Mar 31, 2020, 09:26:11 EDT Position: +037.306598° / -080.275329° (±19.67.6m) Altitude: 017.01m (±1.00) Datum: WGS-84 Azimuth/Bearing: 166.51SE 2951mils True (±10°) Elevation Angle: -23.3° Horizon Angle: +01.3° Zoom: 1.0X Start: 11943+00- SSF fabric sagging, Contractor has been notified</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12001+00	Field Station#	11943+00		
Pic 5 Desc.	Wetland ECD's are in acceptable condition.	Pic 6 Desc.	SSF fabric sagging, Contractor has been notified.		

A/E	124300137	Date/Time	3/31/2020 12:57 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/31/2020 12:57 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9646
Inspector	Chris Burns			Date/Time	3/31/2020 1:47 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+99
County	Montgomery	Ground	Wet	Temperature (°F)	46.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/31/2020 1:47 PM	Report #	9646
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.3 to MP 225.3 as well as assessed AR 266.03 No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/31/2020 1:47 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/31/2020 1:47 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9650
Inspector	Garrett Barclay			Date/Time	3/31/2020 4:48 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Damp	Temperature (°F)	45.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/31/2020 4:48 PM	Report #	9650
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 218 - MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	3/31/2020 4:48 PM	Report #	
Pictures					
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		11530+00		Field Station#	
Pic 1 Desc.		ECD's and row conditions		Pic 2 Desc.	
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		11563+00		Field Station#	
Pic 3 Desc.		ECD's and row conditions		Pic 4 Desc.	
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		11584+00		Field Station#	
Pic 5 Desc.		ECD's and row conditions		Pic 6 Desc.	

A/E	124300137	Date/Time	3/31/2020 4:48 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/31/2020 4:48 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9668
Inspector	Garrett Barclay			Date/Time	4/1/2020 8:23 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	39.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/1/2020 8:23 AM	Report #	
Pictures					
 <p>Date & Time: Wed, Apr 01, 2020 13:15:27 EDT Position: +037° 16' 43.1" / -086° 15' 10.37" (Error: 0) Altitude: 1618ft (+45.8ft) Datum: WGS-84 Azimuth/Bearing: 103° N03E 104mils Error (Error) Elevation Grade: +003% Horizon Grade: +003% Zoom: 1.0X 9" cat</p>		 <p>Date & Time: Wed, Apr 01, 2020 09:12:24 EDT Position: +037° 16' 43.1" / -086° 15' 10.37" (Error: 0) Altitude: 1618ft (+45.8ft) Datum: WGS-84 Azimuth/Bearing: 103° N03E 104mils Error (Error) Elevation Grade: +003% Horizon Grade: +003% Zoom: 1.0X 9"</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	.9" of rain recorded @ Catawba		Pic 2 Desc.	ECD's and row conditions	
 <p>Date & Time: Wed, Apr 01, 2020 11:03:07 EDT Position: +037° 19' 14.41" / -086° 26' 11.07" (Error: 0) Altitude: 2236ft (+63.1ft) Datum: WGS-84 Azimuth/Bearing: 103° N03E 103mils Error (Error) Elevation Grade: +003% Horizon Grade: +004% Zoom: 1.0X 11425</p>		 <p>Date & Time: Wed, Apr 01, 2020 11:03:07 EDT Position: +037° 19' 14.41" / -086° 26' 11.07" (Error: 0) Altitude: 2236ft (+63.1ft) Datum: WGS-84 Azimuth/Bearing: 103° N03E 103mils Error (Error) Elevation Grade: +003% Horizon Grade: +004% Zoom: 1.0X 11425</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	11425+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	New sinkhole discovered	
 <p>Date & Time: Wed, Apr 01, 2020 11:03:07 EDT Position: +037° 19' 14.41" / -086° 26' 11.07" (Error: 0) Altitude: 2236ft (+63.1ft) Datum: WGS-84 Azimuth/Bearing: 103° N03E 103mils Error (Error) Elevation Grade: +003% Horizon Grade: +004% Zoom: 1.0X 11408</p>		 <p>Date & Time: Wed, Apr 01, 2020 11:03:07 EDT Position: +037° 19' 14.41" / -086° 26' 11.07" (Error: 0) Altitude: 2236ft (+63.1ft) Datum: WGS-84 Azimuth/Bearing: 103° N03E 103mils Error (Error) Elevation Grade: +003% Horizon Grade: +004% Zoom: 1.0X 11469</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11408+00		Field Station#	11469+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	4/1/2020 8:23 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/1/2020 8:23 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9669
Inspector	Len Kruizenga			Date/Time	4/1/2020 8:24 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	120005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	39.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.20
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/1/2020 8:24 AM	Report #	
Pictures					
<p>Date & Time: Wed, Apr 01, 2020, 09:18:31 EDT Position: +427.349234° / +080.655386° (+213.3ft) Altitude: 1815ft (+59.9ft) Datum: WGS-84 Azimuth/Bearing: 184° S04W 3271mils True (+25°) Elevation Angle: -11.5° Horizon Angle: +03.4° Zoom: 1.0X Buffalo Anklets rain gauge reading- 1.10"</p>		<p>Date & Time: Wed, Apr 01, 2020, 09:24:50 EDT Position: +427.349104° / +080.655386° (+213.3ft) Altitude: 1815ft (+59.9ft) Datum: WGS-84 Azimuth/Bearing: 181° S04E 1440mils True (+25°) Elevation Angle: -11.0° Horizon Angle: +03.4° Zoom: 1.0X AR-234 rain gauge reading- 1.20"</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	10695+41	Field Station#	10500+00		
Pic 1 Desc.	Buffalo Anklets rain gauge reading- 1.10"	Pic 2 Desc.	AR-234 rain gauge reading- 1.20"		
<p>Date & Time: Wed, Apr 01, 2020, 09:39:53 EDT Position: +427.352102° / +080.671060° (+1109.3ft) Altitude: 1714ft (+52.1ft) Datum: WGS-84 Azimuth/Bearing: 282° S22W 4480mils True (+25°) Elevation Angle: -04.5° Horizon Angle: +01.4° Zoom: 1.0X LY-29- PPL materials storage.</p>		<p>Date & Time: Wed, Apr 01, 2020, 09:41:42 EDT Position: +427.332198° / +080.710826° (+1159.3ft) Altitude: 1712ft (+51.9ft) Datum: WGS-84 Azimuth/Bearing: 282° N34W 5740mils True (+25°) Elevation Angle: -13.0° Horizon Angle: +00.4° Zoom: 1.0X LY-29- CFS triple stack perimeter controls.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	LY-29- PPL Materials storage	Pic 4 Desc.	LY-29- CFS triple stack perimeter controls are in acceptable condition.		
<p>Date & Time: Wed, Apr 01, 2020, 09:45:02 EDT Position: +427.352102° / +080.676552° (+1164.1ft) Altitude: 1715ft (+52.4ft) Datum: WGS-84 Azimuth/Bearing: 287° N73W 5102mils True (+20.1°) Elevation Angle: -13.6° Horizon Angle: +05.2° Zoom: 1.0X LY-29- Culvert and drainage feature.</p>		<p>Date & Time: Wed, Apr 01, 2020, 09:47:00 EDT Position: +427.348917° / +080.676577° (+1164.1ft) Altitude: 1715ft (+52.4ft) Datum: WGS-84 Azimuth/Bearing: 242° S40W 4030mils True (+36°) Elevation Angle: -06.7° Horizon Angle: +04.9° Zoom: 1.0X LY-29- AR-238.00- Access road erosion caused by lime company ruptured water pipe.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	LY-29- Culvert and drainage feature.	Pic 6 Desc.	AR-238.00- Access road erosion caused by lime company ruptured water line.		

AFE	124300137	Date/Time	4/1/2020 8:24 AM	Report #	
Pictures					
					
GPS Location	See photo GPS	GPS Location			
Field Station#	12005+00	Field Station#			
Pic 7 Desc.	AR-238.00- Ruptured lime company water line.	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/1/2020 8:24 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report





Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9672
Inspector	Jared Saunders			Date/Time	3/30/2020 2:50 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11526+00
State	VA	Inspection Area	Partial	Station End	11351+00
County	Giles	Ground	Damp	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	3/30/2020 2:50 PM	Report #	9672
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		3/30/2020 2:50 PM		Report #							
Pictures															
<p>Date & Time: Mon, Mar 30, 2020, 09:13:20 EDT Position: +037.330171 / -080.439114 (+62162.9ft) Altitude: 2041ft (+121.0m) Datum: WGS-84 Azimuth/Bearing: 323° N37W 5742mils True (±12°) Elevation Angle: -16.0° Horizon Angle: +00.8° Zoom: 1.0X 11507+00</p> 				<p>Date & Time: Mon, Mar 30, 2020, 09:14:10 EDT Position: +037.330171 / -080.427030 (+596.5ft) Altitude: 2223ft (+67.6m) Datum: WGS-84 Azimuth/Bearing: 233° S53W 4142mils True (±12°) Elevation Angle: -02.7° Horizon Angle: +00.1° Zoom: 1.0X 11503+00</p> 											
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				11507+00				Field Station#				11503+00			
Pic 1 Desc.				Plunge pool in place.				Pic 2 Desc.				Conveyance channel with rock checks in place.			
<p>Date & Time: Mon, Mar 30, 2020, 09:19:14 EDT Position: +037.325114 / -080.430988 (+632.2ft) Altitude: 2181ft (+67.7m) Datum: WGS-84 Azimuth/Bearing: 244° S29W 4242mils True (±12°) Elevation Angle: -11.7° Horizon Angle: +03.8° Zoom: 1.0X 11489+00</p> 				<p>Date & Time: Mon, Mar 30, 2020, 09:34:07 EDT Position: +037.330327 / -080.437277 (+6739.2ft) Altitude: 2154ft (+172.1ft) Datum: WGS-84 Azimuth/Bearing: 275° N85W 4889mils True (±12°) Elevation Angle: +04.0° Horizon Angle: +00.6° Zoom: 1.0X 11478+00</p> 											
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				11489+00				Field Station#				11478+00			
Pic 3 Desc.				RCE in place at Stevers Gap Road.				Pic 4 Desc.				Slope drains and ECB in place.			
<p>Date & Time: Mon, Mar 30, 2020, 09:42:10 EDT Position: +037.335467 / -080.444461 (+24528.9ft) Altitude: 2221ft (+67.8m) Datum: WGS-84 Azimuth/Bearing: 224° S44W 3982mils True (±12°) Elevation Angle: -09.3° Horizon Angle: -01.9° Zoom: 1.0X 11451+00 S-0012 & S-0013</p> 				<p>Date & Time: Mon, Mar 30, 2020, 09:43:05 EDT Position: +037.322107 / -080.435547 (+4600.9ft) Altitude: 2275ft (+69.2ft) Datum: WGS-84 Azimuth/Bearing: 218° S38W 3876mils True (±12°) Elevation Angle: -15.0° Horizon Angle: +00.5° Zoom: 1.0X 11472+00</p> 											
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				11451+00				Field Station#				11472+00			
Pic 5 Desc.				Sensitive resource buffer in place at stream S-0012 and S-0013				Pic 6 Desc.				Triple barrier ECDs in place at off ROW karst feature.			

A/E	124300137	Date/Time	3/30/2020 2:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	3/30/2020 2:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9674
Inspector	Jared Saunders			Date/Time	4/1/2020 9:08 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Incident/Complaint	Station End	11788+50
County	Giles	Ground	Wet	Temperature (°F)	45.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/1/2020 9:08 AM	Report #	9674
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		4/1/2020 9:08 AM		Report #			
Pictures											
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11669+00						Field Station#		11720+00	
Pic 1 Desc.		ECDs in place along LOD.						Pic 2 Desc.		ROW stabilized with mulch and waterbars in place.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11687+40						Field Station#		11767+00	
Pic 3 Desc.		Sensitive resource buffer in place at stream S-MN21.						Pic 4 Desc.		RCE in place Main Line Valve 26.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11772+00						Field Station#		11775+00	
Pic 5 Desc.		Clean water diversion pipe inlet.						Pic 6 Desc.		Clean water diversion pipe and plunge pool in place.	

A/E	124300137	Date/Time	4/1/2020 9:08 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/1/2020 9:08 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9675
Inspector	Jared Saunders			Date/Time	4/1/2020 9:51 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Muddy	Temperature (°F)	48.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/1/2020 9:51 AM	Report #	9675
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauge at Kow Camp Road - 1.0 inches and Access Road 244 - 0.9 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/1/2020 9:51 AM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack CFS in place at drainage.		Pic 2 Desc.	18 inch CFS in place along LOD.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Checked staged equipment for leaks. No leaks observed.		Pic 4 Desc.	Secondary containment in place under fuel cell.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10883+50		Field Station#	11025+00	
Pic 5 Desc.	Rain gauge at Kow Camp Road reads 1 inch.		Pic 6 Desc.	Rain gauge at access road 244 reads 0.9 inches.	

A/E	124300137	Date/Time	4/1/2020 9:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/1/2020 9:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9704
Inspector	Len Kruizenga			Date/Time	4/2/2020 8:16 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	1102398+00
State	VA	Inspection Area	Full	Station End	10930+00
County	Giles	Ground	Muddy	Temperature (°F)	41.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | No |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/2/2020 8:16 AM	Report #	9704
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Attended inspection meeting at with EI,s SWPPP inspection: Sta#11023+98 to 10930+00. MP-208.6 to 206.2 When we got to AR-244 row there was a cow on the row, I went to the landowner to inform him. We got the cow back in but she damaged P1 buffer at stream S-RR5. I called PPL foreman Randy Biddle and crew will make repairs today. EI Chris Burns while walking from AR-244 to AR-245.01 found where fencing had been removed, (See Chris Burns report).PPL is replacing fencing. The row is wet from recent rain events, but remains in stable condition. Temporary stabilization is in acceptable condition. Perimeter controls, P1 silt fence, SSF and CFS are in acceptable condition. Water bars are stable. Water bar end treatments are in acceptable condition. Streams S-IJ18, S-RR5, S- E24, S-E25 and environmental controls are in acceptable condition. Karst and Karst ECD's are in acceptable condition. Sta#10977+00- P1 has been installed across the row on both sides of a recently delineated stream. Doe Creek Farms have again opened the gate onto the row for their cattle to graze. (See photo).					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/2/2020 8:16 AM	Report #	
Pictures					
 <p>Date & Time: Thu, Apr 02, 2020, 09:51:56 EDT Position: +037.322205 / -080.553061 (+16.4ft) Altitude: 2610ft (+29.2m) Datum: WGS-84 Azimuth/Bearing: 164.516E 2916mils True (+10°) Elevation Angle: -20.9° Horizon Angle: +03.1° Zoom: 1.0X Sta#11024+00-Stream S-IJ18</p>		 <p>Date & Time: Thu, Apr 02, 2020, 10:02:31 EDT Position: +037.322691 / -080.555679 (+32.8ft) Altitude: 2606ft (+29.4m) Datum: WGS-84 Azimuth/Bearing: 095° 58'E 1689mils True (+25°) Elevation Angle: -21.6° Horizon Angle: +01.6° Zoom: 1.0X Sta#11017+00-Stream S-RR5</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11024+00	Field Station#	11017+00		
Pic 1 Desc.	Stream S- IJ18.	Pic 2 Desc.	Stream S-RR5		
 <p>Date & Time: Thu, Apr 02, 2020, 10:29:53 EDT Position: +037.322557 / -080.564733 (+32.0ft) Altitude: 2608ft (+105.0ft) Datum: WGS-84 Azimuth/Bearing: 097° 58'E 1618mils True (+25°) Elevation Angle: -10.3° Horizon Angle: +01.6° Zoom: 1.0X Sta#10986+00-Stream S-E25</p>		 <p>Date & Time: Thu, Apr 02, 2020, 10:40:11 EDT Position: +037.322572 / -080.564733 (+32.0ft) Altitude: 2608ft (+105.0ft) Datum: WGS-84 Azimuth/Bearing: 307° 10'W 848mils True (+25°) Elevation Angle: -11.1° Horizon Angle: +03.9° Zoom: 1.0X Sta#10985+00-Stream S-E24</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	10986+00	Field Station#	10985+00		
Pic 3 Desc.	Stream S- E25	Pic 4 Desc.	Stream S- E24		
 <p>Date & Time: Thu, Apr 02, 2020, 10:37:43 EDT Position: +037.323624 / -080.567359 (+16.4ft) Altitude: 2378ft (+13.7m) Datum: WGS-84 Azimuth/Bearing: 305° 15'W 822mils True (+23°) Elevation Angle: -15.5° Horizon Angle: +15.9° Zoom: 1.0X Sta#10977+00-control isolated on recently delineated stream</p>		 <p>Date & Time: Thu, Apr 02, 2020, 10:56:10 EDT Position: +037.324077 / -080.568027 (+16.4ft) Altitude: 2372ft (+28.6m) Datum: WGS-84 Azimuth/Bearing: 299° 10'W 830mils True (+23°) Elevation Angle: -10.2° Horizon Angle: +04.4° Zoom: 1.0X Doe Creek farms have opened gate to row to allow cattle to graze row.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	10977+00	Field Station#	10950+00		
Pic 5 Desc.	Newly delineated stream and environmental controls.	Pic 6 Desc.	Doe Creek Farms have again opened gates to the row to graze cattle.		

A/E	124300137	Date/Time	4/2/2020 8:16 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	4/2/2020 8:16 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9706
Inspector	Garrett Barclay			Date/Time	4/2/2020 10:34 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+62
County	Giles	Ground	Damp	Temperature (°F)	48.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/2/2020 10:34 AM	Report #	9706
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 205 - MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		4/2/2020 10:34 AM		Report #							
Pictures															
															
GPS Location				See picture above for GPS coordinates				GPS Location				See picture above for GPS coordinates			
Field Station#				10858+00				Field Station#				10863+00			
Pic 1 Desc.				ECD's and row conditions				Pic 2 Desc.				ECD's and row conditions			
															
GPS Location				See picture above for GPS coordinates				GPS Location				See picture above for GPS coordinates			
Field Station#				10877+00				Field Station#				10882+00			
Pic 3 Desc.				ECD's and row conditions				Pic 4 Desc.				ECD's and row conditions			
															
GPS Location				See picture above for GPS coordinates				GPS Location				See picture above for GPS coordinates			
Field Station#				10891+00				Field Station#				10898+00			
Pic 5 Desc.				ECD's and row conditions				Pic 6 Desc.				ECD's and row conditions			

A/E	124300137	Date/Time	4/2/2020 10:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	4/2/2020 10:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9711
Inspector	Chris Burns			Date/Time	4/2/2020 1:12 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11064+53
County	Giles	Ground	Damp	Temperature (°F)	54.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Berm	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/2/2020 1:12 PM	Report #	9711
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245.01. No major issues were located. Two locations of livestock damage to controls were identified. PPL Environmental Coordinator Mike Perry was notified. PPL crews made repairs prior to the end of day. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. Fresh spring growth is coming in. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/2/2020 1:12 PM	Report #	
Pictures					
					
GPS Location	1		GPS Location	2	
Field Station#	11025+50		Field Station#	11034+00	
Pic 1 Desc.	S-IJ18.		Pic 2 Desc.	RoW conditions and controls.	
					
GPS Location	3		GPS Location	4	
Field Station#	11046+25		Field Station#	11050+10	
Pic 3 Desc.	Water bars and vegetation new growth.		Pic 4 Desc.	S-IJ16B and S-IJ17.	
					
GPS Location	5		GPS Location	6	
Field Station#	11055+00		Field Station#	11064+53	
Pic 5 Desc.	RoW conditions and controls.		Pic 6 Desc.	RoW conditions and controls.	

A/E	124300137	Date/Time	4/2/2020 1:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/2/2020 1:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9735
Inspector	Chris Burns			Date/Time	4/3/2020 9:56 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Wet	Temperature (°F)	60.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/3/2020 9:56 AM	Report #	9735
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213 to MP 214.8. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Participated in the inspection conference call.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/3/2020 9:56 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11265+50	Field Station#	11285+50		
Pic 1 Desc.	Perimeter controls functional.	Pic 2 Desc.	RoW conditions and controls.		
					
GPS Location	3	GPS Location	4		
Field Station#	11292+80	Field Station#	11327+85		
Pic 3 Desc.	S-MM18 showing overview.	Pic 4 Desc.	S-NN12 showing overview.		
					
GPS Location	5	GPS Location	6		
Field Station#	11350+00	Field Station#	11352+97		
Pic 5 Desc.	Recently replaced perimeter controls.	Pic 6 Desc.	S-NN11.		

A/E	124300137	Date/Time	4/3/2020 9:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	4/3/2020 9:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9738
Inspector	Len Kruizenga			Date/Time	4/3/2020 12:43 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+88
State	VA	Inspection Area	Full	Station End	11161+00
County	Giles	Ground	Damp	Temperature (°F)	45.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	2.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/3/2020 12:43 PM	Report #	9738
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with EI's at Winding Way to discuss schedule. SWPPP inspection: Sta#11254+88 to 11161+00. MP-213 to 211 The row is drying and in stable condition. Temporary stabilization is acceptable. Water bars are stable. End treatments and sump pits are in acceptable condition. Perimeter controls, silt fence, CFS and SSF are in acceptable condition. Slope drains are in acceptable condition. Drainage feature and ECD's are in acceptable condition. CWD pipe and plunge pool are in good condition. Rock channel and rock check dams are in acceptable condition. AR-25, AR-249.02, AR-249.01 are maintained in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/3/2020 12:43 PM	Report #	
Pictures					
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11232+00		Field Station#	11225+00	
Pic 1 Desc.	Row is in stable condition.		Pic 2 Desc.	Slope drain, end treatment and rock channel are in acceptable condition.	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11204+00		Field Station#	11191+00	
Pic 3 Desc.	Topsoil stockpiles are stable & well vegetated.		Pic 4 Desc.	Drainage feature and ECD's are in acceptable condition.	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11184+50		Field Station#	11184+00	
Pic 5 Desc.	AR-249.02- Road and environmental controls are in acceptable condition.		Pic 6 Desc.	CWD pipe and plunge pool are in good condition.	

AFE	124300137	Date/Time	4/3/2020 12:43 PM	Report #	
Pictures					
		<p>Insert image here</p>			
GPS Location	See photo GPS	GPS Location			
Field Station#	11172+70	Field Station#			
Pic 7 Desc.	Slope drain, CFS checks, sumps & end treatment are in acceptable condition.	Pic 8 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/3/2020 12:43 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9746
Inspector	Garrett Barclay			Date/Time	4/3/2020 3:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+00
State	VA	Inspection Area	Partial	Station End	11158+00
County	Giles	Ground	Dry	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/3/2020 3:13 PM	Report #	9746
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 209 MP 211.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/3/2020 3:13 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11130+00		Field Station#	11070+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11100+00		Field Station#	11120+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11138+00		Field Station#	11142+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	4/3/2020 3:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/3/2020 3:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9761
Inspector	Jared Saunders			Date/Time	4/2/2020 3:42 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	10750+00
County	Giles	Ground	Wet	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/2/2020 3:42 PM	Report #	9761
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 4/2/2020 3:42 PM		Report #	
Pictures					
					
<p>Date & Time: Thu Apr 02, 2020, 10:45:30 EDT Position: +037 33.137° / +080 650235° (+5361.0ft) Altitude: 2015ft (+5362ft) Datum: WGS-84 Azimuth/Bearing: 111° S49E 1973mils True (+12°) Elevation Angle: -07.1° Horizon Angle: -01.7° Zoom: 1.0X 10710+00</p>		<p>Date & Time: Thu Apr 02, 2020, 10:45:30 EDT Position: +037 33.137° / +080 650235° (+5361.0ft) Altitude: 2015ft (+5362ft) Datum: WGS-84 Azimuth/Bearing: 091° S89E 1618mils True (+12°) Elevation Angle: -08.0° Horizon Angle: -05.6° Zoom: 1.0X 10712+50</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		10710+00		Field Station#	
Pic 1 Desc.		Compost filter sock checks in place in bar ditch along access road 241.04.		Pic 2 Desc.	
					
<p>Date & Time: Thu Apr 02, 2020, 10:46:27 EDT Position: +037 340577° / +080 647985° (+5381.0ft) Altitude: 2290ft (+5381ft) Datum: WGS-84 Azimuth/Bearing: 223° S43W 3964mils True (+10°) Elevation Angle: +20.2° Horizon Angle: +05.0° Zoom: 1.0X 10711+00</p>		<p>Date & Time: Thu Apr 02, 2020, 10:48:37 EDT Position: +037 340577° / +080 647985° (+5381.0ft) Altitude: 2290ft (+5381ft) Datum: WGS-84 Azimuth/Bearing: 140° S38W 6609mils True (+10°) Elevation Angle: +02.0° Horizon Angle: +06.0° Zoom: 1.0X 10710+00</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		10711+00		Field Station#	
Pic 3 Desc.		Waterbar with compost filter sock end treatment in place across travel lane.		Pic 4 Desc.	
					
<p>Date & Time: Thu Apr 02, 2020, 10:47:19 EDT Position: +037 340577° / +080 647985° (+5381.0ft) Altitude: 2290ft (+5381ft) Datum: WGS-84 Azimuth/Bearing: 114° S46E 2027mils True (+10°) Elevation Angle: -00.4° Horizon Angle: -00.3° Zoom: 1.0X 10698+00 S-G32</p>		<p>Date & Time: Thu Apr 02, 2020, 10:47:19 EDT Position: +037 340577° / +080 647985° (+5381.0ft) Altitude: 2290ft (+5381ft) Datum: WGS-84 Azimuth/Bearing: 104° S76E 1849mils True (+10°) Elevation Angle: -07.5° Horizon Angle: -05.9° Zoom: 1.0X 10696+00</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		10698+00		Field Station#	
Pic 5 Desc.		Sensitive resource buffer in place at stream S-G32.		Pic 6 Desc.	
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		10696+00		Field Station#	
Pic 5 Desc.		Sensitive resource buffer in place at stream S-G32.		Pic 6 Desc.	

A/E	124300137	Date/Time	4/2/2020 3:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/2/2020 3:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	9762
Inspector	Jared Saunders			Date/Time	4/3/2020 11:44 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11351+00
State	VA	Inspection Area	Partial	Station End	11526+00
County	Giles	Ground	Damp	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Broad-Based Dip	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/3/2020 11:44 AM	Report #	9762
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		4/3/2020 11:44 AM		Report #			
Pictures											
<p>Date & Time: Fri, Apr 03, 2020, 09:03:45 EDT Position: +037.324974 / -080.426498 (+15.3h) Altitude: 2201ft (+11.4h) Datum: WGS-84 Azimuth/Bearing: 328° N32W 583mils True (+14°) Elevation Angle: -18.3° Horizon Angle: -00.1° Zoom: 1.0X 11507+00</p> 				<p>Date & Time: Fri, Apr 03, 2020, 09:04:20 EDT Position: +037.324974 / -080.426857 (+15.3h) Altitude: 2201ft (+11.4h) Datum: WGS-84 Azimuth/Bearing: 183° S03W 3253mils True (+14°) Elevation Angle: -07.9° Horizon Angle: -05.4° Zoom: 1.0X 11505+00</p> 							
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11507+00						Field Station#		11505+00	
Pic 1 Desc.		Clean water diversion pipe and plunge pool in place.						Pic 2 Desc.		Clean water diversion pipe and clean water diversion berm in place.	
<p>Date & Time: Fri, Apr 03, 2020, 09:04:37 EDT Position: +037.326010 / -080.426931 (+15.3h) Altitude: 2208ft (+11.4h) Datum: WGS-84 Azimuth/Bearing: 234° S54W 4160mils True (+14°) Elevation Angle: -00.2° Horizon Angle: -02.9° Zoom: 1.0X 11503+00</p> 				<p>Date & Time: Fri, Apr 03, 2020, 09:09:50 EDT Position: +037.324974 / -080.430953 (+15.3h) Altitude: 2162ft (+9.9h) Datum: WGS-84 Azimuth/Bearing: 209° S69W 4427mils True (+14°) Elevation Angle: -11.2° Horizon Angle: -03.3° Zoom: 1.0X 11489+00</p> 							
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11503+00						Field Station#		11489+00	
Pic 3 Desc.		Conveyance channel with rock checks in place at double cut section of ROW.						Pic 4 Desc.		RCE in place at Stevers Gap Road.	
<p>Date & Time: Fri, Apr 03, 2020, 09:15:16 EDT Position: +037.322684 / -080.434455 (+15.2h) Altitude: 2260ft (+11.5h) Datum: WGS-84 Azimuth/Bearing: 275° N85W 4889mils True (+14°) Elevation Angle: +14.3° Horizon Angle: +16.7° Zoom: 1.0X 11477+00</p> 				<p>Date & Time: Fri, Apr 03, 2020, 09:39:14 EDT Position: +037.322955 / -080.439143 (+15.2h) Altitude: 2138ft (+9.7h) Datum: WGS-84 Azimuth/Bearing: 244° S21W 4142mils True (+14°) Elevation Angle: -06.4° Horizon Angle: -01.2° Zoom: 1.0X 11380+00</p> 							
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11477+00						Field Station#		11380+00	
Pic 5 Desc.		Two-tone stabilized with ECB and slope drain in place to minimize erosion.						Pic 6 Desc.		Triple barrier ECDs in place at off ROW karst feature.	

A/E	124300137	Date/Time	4/3/2020 11:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/3/2020 11:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		