



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11274
Inspector	Chris Burns			Date/Time	5/26/2020 7:54 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Damp	Temperature (°F)	73.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/26/2020 7:54 AM	Report #	11274
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213 to MP 214.8. No issues were located. All perimeter controls, ECDs and BMPs are functional. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/26/2020 7:54 AM	Report #	
Pictures					
 <p>Date & Time: Tue, May 26, 2020, 09:29:18 EDT Position: +037.200422 / -080.473085 (+157.9ft) Altitude: 2227ft (+1042ft) Datum: WGS-84 Azimuth/Bearing: 165.538E 3522mils True (+12) Elevation Angle: -12.9 Horizon Angle: +01.7 Zoom: 1.0X 11286+00</p>		 <p>Date & Time: Tue, May 26, 2020, 08:53:01 EDT Position: +037.295966 / -080.463683 (+152.9ft) Altitude: 2242ft (+104ft) Datum: WGS-84 Azimuth/Bearing: 035.1395E 3622mils True (+12) Elevation Angle: -23.8 Horizon Angle: +00.8 Zoom: 1.0X 11286+00</p>			
GPS Location	1	GPS Location	2		
Field Station#	11327+85	Field Station#	11286+00		
Pic 1 Desc.	S-NN12 and controls.	Pic 2 Desc.	Perimeter controls functional.		
 <p>Date & Time: Tue, May 26, 2020, 08:57:38 EDT Position: +037.296474 / -080.481435 (+105.0ft) Altitude: 2093ft (+104ft) Datum: WGS-84 Azimuth/Bearing: 152.528E 2702mils True (+12) Elevation Angle: -15.9 Horizon Angle: +00.7 Zoom: 1.0X S-MM18</p>		 <p>Date & Time: Tue, May 26, 2020, 09:11:06 EDT Position: +037.292878 / -080.477933 (+108.5ft) Altitude: 2133ft (+269.0ft) Datum: WGS-84 Azimuth/Bearing: 268.1588E 4764mils True (+12) Elevation Angle: -20.6 Horizon Angle: +01.4 Zoom: 1.0X 11303+00</p>			
GPS Location	3	GPS Location	4		
Field Station#	11292+80	Field Station#	11303+00		
Pic 3 Desc.	S-MM18 and controls.	Pic 4 Desc.	Perimeter controls functional.		
 <p>Date & Time: Tue, May 26, 2020, 09:29:41 EDT Position: +037.309527 / -080.471449 (+169.3ft) Altitude: 2227ft (+105.7ft) Datum: WGS-84 Azimuth/Bearing: 131.589E 2161mils True (+12) Elevation Angle: -14.4 Horizon Angle: -00.3 Zoom: 1.0X 11333+00</p>		 <p>Date & Time: Tue, May 26, 2020, 09:40:28 EDT Position: +037.309527 / -080.471449 (+169.3ft) Altitude: 1853ft (+104ft) Datum: WGS-84 Azimuth/Bearing: 102.588E 1636mils True (+12) Elevation Angle: -21.5 Horizon Angle: +00.8 Zoom: 1.0X S-NN11</p>			
GPS Location	5	GPS Location	6		
Field Station#	11333+00	Field Station#	11352+97		
Pic 5 Desc.	RoW conditions or controls.	Pic 6 Desc.	S-NN11 and controls.		

A/E	124300137	Date/Time	5/26/2020 7:54 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/26/2020 7:54 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11290
Inspector	Len Kruizenga			Date/Time	5/26/2020 12:17 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Full	Station End	11158+27
County	Giles	Ground	Damp	Temperature (°F)	66.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/26/2020 12:17 PM	Report #	
Pictures					
 <p>Date & Time: Tue, May 26, 2020 08:55:44 EDT Position: +037.304167, -080.502536 (+16.4ft) Altitude: 2041ft (+39.6ft) Datum: WGS-84 Azimuth/Bearing: 353° N07W 6276mils True (±10°) Elevation Angle: -01.6° Horizon Angle: +02.4° Zoom: 1.0x Sta#11225+00- Rock channel, slope drain.</p>		 <p>Date & Time: Tue, May 26, 2020 09:07:34 EDT Position: +037.305140, -080.500240 (+32.8ft) Altitude: 2041ft (+39.6ft) Datum: WGS-84 Azimuth/Bearing: 323° N37W 5742mils True (±10°) Elevation Angle: -15.0° Horizon Angle: +05.2° Zoom: 1.0x Sta#11217+00- P1 silt fence perimeter controls.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11225+00		Field Station#	11217+00	
Pic 1 Desc.	Rock channel & ECD's		Pic 2 Desc.	P1 silt fence perimeter controls.	
 <p>Date & Time: Tue, May 26, 2020 09:15:21 EDT Position: +037.304347, -080.506867 (+16.1ft) Altitude: 2395ft (+729.9ft) Datum: WGS-84 Azimuth/Bearing: 353° N07W 6276mils True (±10°) Elevation Angle: -03.3° Horizon Angle: -06.5° Zoom: 1.0x Sta#11204+00- CFS perimeter controls & CFS triple stack end treatments.</p>		 <p>Date & Time: Tue, May 26, 2020 09:16:04 EDT Position: +037.305140, -080.500240 (+32.8ft) Altitude: 1935ft (+595.1ft) Datum: WGS-84 Azimuth/Bearing: 388° N06W 6371mils True (±10°) Elevation Angle: -02.4° Horizon Angle: -06.8° Zoom: 1.0x Sta#11200+00- Topsoil stockpiles are well vegetated. SSF perimeter controls.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11204+00		Field Station#	11200+00	
Pic 3 Desc.	CFS perimeter controls and triple stack end treatments.		Pic 4 Desc.	SSF perimeter controls and vegetated topsoil stockpiles.	
 <p>Date & Time: Tue, May 26, 2020 09:27:27 EDT Position: +037.304427, -080.510000 (+33.0ft) Altitude: 2142ft (+651.0ft) Datum: WGS-84 Azimuth/Bearing: 112° S88E 1831mils True (±10°) Elevation Angle: -07.4° Horizon Angle: +01.7° Zoom: 1.0x Sta#11193+00- Drainage feature & ECD's.</p>		 <p>Date & Time: Tue, May 26, 2020 09:38:37 EDT Position: +037.307877, -080.511848 (+16.4ft) Altitude: 1928ft (+58.2ft) Datum: WGS-84 Azimuth/Bearing: 281° N79W 4996mils True (±10°) Elevation Angle: -16.4° Horizon Angle: +06.4° Zoom: 1.0x Sta#11184+00- CWD pipe & plunge pool.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11190+00		Field Station#	11184+00	
Pic 5 Desc.	Drainage feature and ECD's		Pic 6 Desc.	CWD pipe and plunge pool are in good condition.	

A/E	124300137	Date/Time	5/26/2020 12:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/26/2020 12:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11296
Inspector	Jared Saunders			Date/Time	5/26/2020 2:08 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11351+00
State	VA	Inspection Area	Partial	Station End	11525+00
County	Giles	Ground	Damp	Temperature (°F)	70.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/26/2020 2:08 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11505+00		Field Station#	11493+00	
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 2 Desc.	ROW is stabilized with vegetation growth.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	11413+00	
Pic 3 Desc.	RCE in place Stevers Gap Road.		Pic 4 Desc.	Priority one silt fence needs retrenched.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11408+00		Field Station#	11767+00	
Pic 5 Desc.	Priority one silt fence undermined.		Pic 6 Desc.	Rain gauge at Mount Tabor Road reads 0.05 inches.	

A/E	124300137	Date/Time	5/26/2020 2:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/26/2020 2:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11298
Inspector	Garrett Barclay			Date/Time	5/26/2020 3:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+53
State	VA	Inspection Area	Partial	Station End	11158+27
County	Giles	Ground	Damp	Temperature (°F)	62.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock				
Erosion Control Blanket				
Rock Construction Entrance				
Sensitive Resource Buffer				
Silt Fence (Filter Fabric Fence)				
Silt Fence (Reinforced Filter Fabric Fence)				

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/26/2020 3:28 PM	Report #	
Pictures					
 <p>Date & Time: Tue, May 26, 2020, 09:46:11 EDT Position: +43°19'4.87" / -86°23'13.07" (+11.00) Altitude: 3333 (+11.00) Datum: WGS-84 Azimuth/Bearing: 264 S89W 46.8mils True (+13) Elevation Grade: +011 Horizon Grade: +003 Zoom: 1.0X 11264</p>		 <p>Date & Time: Tue, May 26, 2020, 08:42:41 EDT Position: +43°19'54.28" / -86°23'37.08" (+13.30) Altitude: 3129 (+11.00) Datum: WGS-84 Azimuth/Bearing: 269 S89W 47.62mils True (+13) Elevation Grade: +053 Horizon Grade: +007 Zoom: 1.0X 11068</p>		GPS Location	See picture above for GPS coordinates
Field Station#	+1	Field Station#	11068+00	GPS Location	See picture above for GPS coordinates
Pic 1 Desc.	.1" of rain recorded @ AR 244	Pic 2 Desc.	ECD's and row conditions	GPS Location	See picture above for GPS coordinates
 <p>Date & Time: Tue, May 26, 2020, 09:46:11 EDT Position: +43°19'4.87" / -86°23'13.07" (+11.00) Altitude: 3333 (+11.00) Datum: WGS-84 Azimuth/Bearing: 264 S89W 46.8mils True (+13) Elevation Grade: +011 Horizon Grade: +003 Zoom: 1.0X 11076</p>		 <p>Date & Time: Tue, May 26, 2020, 09:46:11 EDT Position: +43°19'54.28" / -86°23'37.08" (+13.30) Altitude: 3333 (+11.00) Datum: WGS-84 Azimuth/Bearing: 269 S89W 47.62mils True (+13) Elevation Grade: +053 Horizon Grade: +007 Zoom: 1.0X 11110</p>		GPS Location	See picture above for GPS coordinates
Field Station#	11076+00	Field Station#	11110+00	GPS Location	See picture above for GPS coordinates
Pic 3 Desc.	ECD's and row conditions	Pic 4 Desc.	ECD's and row conditions	GPS Location	See picture above for GPS coordinates
 <p>Date & Time: Tue, May 26, 2020, 09:46:11 EDT Position: +43°19'4.87" / -86°23'13.07" (+11.00) Altitude: 3333 (+11.00) Datum: WGS-84 Azimuth/Bearing: 264 S89W 46.8mils True (+13) Elevation Grade: +011 Horizon Grade: +003 Zoom: 1.0X 11130</p>		 <p>Date & Time: Tue, May 26, 2020, 09:46:11 EDT Position: +43°19'54.28" / -86°23'37.08" (+13.30) Altitude: 3333 (+11.00) Datum: WGS-84 Azimuth/Bearing: 269 S89W 47.62mils True (+13) Elevation Grade: +053 Horizon Grade: +007 Zoom: 1.0X 11134</p>		GPS Location	See picture above for GPS coordinates
Field Station#	11130+00	Field Station#	11134+00	GPS Location	See picture above for GPS coordinates
Pic 5 Desc.	ECD's and row conditions	Pic 6 Desc.	ECD's and row conditions	GPS Location	See picture above for GPS coordinates

A/E	124300137	Date/Time	5/26/2020 3:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/26/2020 3:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11331
Inspector	Rob Robertson			Date/Time	5/27/2020 1:16 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Wet	Temperature (°F)	64.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/27/2020 1:16 PM	Report #	11331
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a routine VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The perimeter controls are in place and functioning properly. Slope breakers are in place and controlling runoff as designed. Sumps and end treatments are working properly. No surface erosion or slips located. Resource crossings are stable with no visible impact. No ECD maintenance needs were identified. No vandalism was evident.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 5/27/2020 1:16 PM		Report #	
Pictures					
 <p>Date & Time: Wed, May 27, 2020, 1:15:28 EDT Position: +429.30338° / -88.39748° (±1.6 mi) Altitude: 2459 ft (±105.0 ft) Datum: WGS-84 Azimuth: Bearing: 119° S 41° E 289.6 mls Magnetic (±15°) Elevation Angle: -05.5° Horizon Angle: +00.3° Zoom: 1.0x Brush Min. Perimeter controls in place. 11669+00</p>		 <p>Date & Time: Wed, May 27, 2020, 10:45:51 EDT Position: +429.30422° / -88.39730° (±1.6 mi) Altitude: 2459 ft (±105.0 ft) Datum: WGS-84 Azimuth: Bearing: 329° N 31° W 584.9 mls Magnetic (±15°) Elevation Angle: -07.6° Horizon Angle: +00.3° Zoom: 1.0x Brush Min. Perimeter controls in place. functional. 11656+00</p>			
GPS Location		On photo		GPS Location	
Field Station#		11669+00		Field Station#	
Pic 1 Desc.		Perimeter controls in place and functioning. ROW stable.		Pic 2 Desc.	
				End treatments and sumps working properly.	
 <p>Date & Time: Wed, May 27, 2020, 10:51:41 EDT Position: +429.30770° / -88.39748° (±1.6 mi) Altitude: 2470 ft (±105.0 ft) Datum: WGS-84 Azimuth: Bearing: 191° S 11° W 339.6 mls Magnetic (±13°) Elevation Angle: +11.3° Horizon Angle: -01.6° Zoom: 1.0x Brush Min. Perimeter controls in place. ROW stable. 11650+00</p>		 <p>Date & Time: Wed, May 27, 2020, 11:15:13 EDT Position: +429.31300° / -88.39748° (±1.6 mi) Altitude: 2469 ft (±105.0 ft) Datum: WGS-84 Azimuth: Bearing: +149° -0348 ft mls (±13°) Elevation Angle: -06.5° Horizon Angle: -06.5° Zoom: 1.0x Brush Min. Perimeter controls in place. ROW stable. 11631+00</p>			
GPS Location		On photo		GPS Location	
Field Station#		11650+00		Field Station#	
Pic 3 Desc.		Slope breakers in place and functioning. ROW surface stable.		Pic 4 Desc.	
				Perimeter controls in place and functional.	
 <p>Date & Time: Wed, May 27, 2020, 11:22:56 EDT Position: +429.31489° / -88.39670° (±1.6 mi) Altitude: 2472 ft (±105.0 ft) Datum: WGS-84 Azimuth: Bearing: -100° -1192 mls (±13°) Elevation Angle: +00.3° Horizon Angle: -24.2° Zoom: 1.0x Brush Min. S-HH18 crossing stable. 11626+04</p>		 <p>Date & Time: Wed, May 27, 2020, 11:29:36 EDT Position: +429.31262° / -88.40227° (±1.6 mi) Altitude: 2003 ft (±105.0 ft) Datum: WGS-84 Azimuth: Bearing: -147° -2813 mls (±13°) Elevation Angle: +07.7° Horizon Angle: -24.7° Zoom: 1.0x Brush Min. S-RR14 crossing stable.</p>			
GPS Location		On photo		GPS Location	
Field Station#		11626+04		Field Station#	
Pic 5 Desc.		S-HH18 buffers stable. Controls in place.		Pic 6 Desc.	
				S-RR14 crossing stable. Controls in place.	

AFE	124300137	Date/Time	5/27/2020 1:16 PM	Report #	
Pictures					
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11613+69	Field Station#	11607+81		
Pic 7 Desc.	S-RR13 equipment bridge in good condition.	Pic 8 Desc.	S-006 crossing stable.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	5/27/2020 1:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11332
Inspector	Len Kruizenga			Date/Time	5/27/2020 1:24 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+99
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	62.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/27/2020 1:24 PM	Report #	
Pictures					
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11900+00	Field Station#	11915+00		
Pic 1 Desc.	AR-266.03	Pic 2 Desc.	Row vegetation, ECD's, level spreaders.		
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11942+00	Field Station#	11987+00		
Pic 3 Desc.	Karst ECD's	Pic 4 Desc.	Drainage feature and ECD's		
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11930+00	Field Station#	11989+00		
Pic 5 Desc.	AR-266.00- Sump and broad base dip end treatment.	Pic 6 Desc.	Catawba rain gauge reading- 0.00"		

A/E	124300137	Date/Time	5/27/2020 1:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/27/2020 1:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11342
Inspector	Jared Saunders			Date/Time	5/27/2020 3:17 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Wet	Temperature (°F)	68.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/27/2020 3:17 PM	Report #	11342
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/27/2020 3:17 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11675+00		Field Station#	11687+40	
Pic 1 Desc.	Waterbar, sump pit, and waterbar end treatment in place.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-MN21.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11770+00	
Pic 3 Desc.	RCE in place at Main Line Valve 26.		Pic 4 Desc.	Clean water diversion berm and clean water diversion pipe inlet.	
		Insert image here			
GPS Location	See photo for GPS location.		GPS Location		
Field Station#	11774+00		Field Station#		
Pic 5 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 6 Desc.		

A/E	124300137	Date/Time	5/27/2020 3:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/27/2020 3:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11352
Inspector	Garrett Barclay			Date/Time	5/27/2020 2:35 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Damp	Temperature (°F)	62.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/27/2020 2:35 PM	Report #	11352
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 218 - MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/27/2020 2:35 PM	Report #	
Pictures					
 <p> Date & Time: Wed, May 27, 2020, 05:00:00 EDT Position: +037° 19' 58.92" N -080° 24' 38.79" W (+15.8m) Altitude: 2544ft (+11.4ft) Datum: WGS-84 Azimuth/Bearing: 101° SSW 179mils True (+13°) Elevation/Grade: +001% Horizon/Grade: +004% Zoom: 1.0X SEP22 </p>		 <p> Date & Time: Wed, May 27, 2020, 05:00:00 EDT Position: +037° 19' 58.92" N -080° 24' 38.79" W (+15.8m) Altitude: 2544ft (+11.4ft) Datum: WGS-84 Azimuth/Bearing: 291° NW 512mils True (+13°) Elevation/Grade: +058% Horizon/Grade: +014% Zoom: 1.0X 11551 </p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11530+00		Field Station#	11551+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
 <p> Date & Time: Wed, May 27, 2020, 10:14:00 EDT Position: +037° 19' 13.76" N -080° 24' 46.09" W (+18.07m) Altitude: 2554ft (+11.6ft) Datum: WGS-84 Azimuth/Bearing: 172° SSW 216mils True (+13°) Elevation/Grade: +032% Horizon/Grade: +004% Zoom: 1.0X SEP22 </p>		 <p> Date & Time: Wed, May 27, 2020, 10:14:00 EDT Position: +037° 19' 13.92" N -080° 24' 46.13" W (+18.30m) Altitude: 2474ft (+11.4ft) Datum: WGS-84 Azimuth/Bearing: 133° S47E 236mils True (+13°) Elevation/Grade: +042% Horizon/Grade: +001% Zoom: 1.0X SEP22 </p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11568+22		Field Station#	11568+30	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
 <p> Date & Time: Wed, May 27, 2020, 10:38:39 EDT Position: +037° 19' 13.65" N -080° 24' 33.57" W (+15.20m) Altitude: 2102ft (+11.5ft) Datum: WGS-84 Azimuth/Bearing: 202° S22W 399mils True (+13°) Elevation/Grade: +031% Horizon/Grade: +008% Zoom: 1.0X 11587 </p>		 <p> Date & Time: Wed, May 27, 2020, 10:40:45 EDT Position: +037° 19' 58.92" N -080° 24' 38.79" W (+15.8m) Altitude: 2072ft (+11.4ft) Datum: WGS-84 Azimuth/Bearing: 212° S32W 376mils True (+13°) Elevation/Grade: +026% Horizon/Grade: +008% Zoom: 1.0X 11589 </p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11587+00		Field Station#	11589+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	5/27/2020 2:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/27/2020 2:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11355
Inspector	Chris Burns			Date/Time	5/27/2020 3:42 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+99
County	Montgomery	Ground	Wet	Temperature (°F)	67.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/27/2020 3:42 PM	Report #	11355
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from Mp 223.3 to MP 225.3 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/27/2020 3:42 PM	Report #	
Pictures					
<div><div><div>Date & Time: Wed, May 27, 2020 08:24:16 EDT Position: +48.25977° / -80.34977° (-80.34977) Altitude: 21401 (-80.34977) Datum: WGS-84 Azimuth/Bearing: 85° N48E 192mils True (-81°) Elevation Angle: -48.1° Horizon Angle: -48.1° Zoom: 1.0X 11792+00</div><div></div></div></div>		<div><div><div>Date & Time: Wed, May 27, 2020 08:24:16 EDT Position: +48.25977° / -80.34977° (-80.34977) Altitude: 21401 (-80.34977) Datum: WGS-84 Azimuth/Bearing: 85° N48E 192mils True (-81°) Elevation Angle: -48.1° Horizon Angle: -48.1° Zoom: 1.0X 11792+00</div><div></div></div></div>			
GPS Location	1	GPS Location	2		
Field Station#	11792+00	Field Station#	11806+00		
Pic 1 Desc.	Section of restored RoW showing conditions and controls.		Pic 2 Desc.	Section of restored RoW showing conditions and controls.	
<div><div><div>Date & Time: Wed, May 27, 2020 08:14:58 EDT Position: +48.25977° / -80.34977° (-80.34977) Altitude: 21390 (-80.34977) Datum: WGS-84 Azimuth/Bearing: 159° S28E 200mils True (-81°) Elevation Angle: -44.3° Horizon Angle: -44.3° Zoom: 1.0X 11817+00</div><div></div></div></div>		<div><div><div>Date & Time: Wed, May 27, 2020 08:14:58 EDT Position: +48.25977° / -80.34977° (-80.34977) Altitude: 21390 (-80.34977) Datum: WGS-84 Azimuth/Bearing: 159° S28E 200mils True (-81°) Elevation Angle: -44.3° Horizon Angle: -44.3° Zoom: 1.0X 11817+00</div><div></div></div></div>			
GPS Location	3	GPS Location	4		
Field Station#	11817+00	Field Station#	11836+00		
Pic 3 Desc.	Section of restored RoW showing conditions and controls.		Pic 4 Desc.	Section of restored RoW showing conditions and controls.	
<div><div><div>Date & Time: Wed, May 27, 2020 07:52:30 EDT Position: +48.25977° / -80.34977° (-80.34977) Altitude: 21424 (-80.34977) Datum: WGS-84 Azimuth/Bearing: 013° N13E 023mils True (-124°) Elevation Angle: -47.7° Horizon Angle: -40.1° Zoom: 1.0X P-KL2</div><div></div></div></div>		<div><div><div>Date & Time: Wed, May 27, 2020 07:44:38 EDT Position: +48.25977° / -80.34977° (-80.34977) Altitude: 21390 (-80.34977) Datum: WGS-84 Azimuth/Bearing: 314° N44E 550mils True (-13°) Elevation Angle: -48.2° Horizon Angle: -48.2° Zoom: 1.0X 11899+00</div><div></div></div></div>			
GPS Location	5	GPS Location	6		
Field Station#	11863+65	Field Station#	11899+00		
Pic 5 Desc.	P-KL2 and controls.		Pic 6 Desc.	Section of restored RoW showing conditions and controls.	

A/E	124300137	Date/Time	5/27/2020 3:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/27/2020 3:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11370
Inspector	Len Kruizenga			Date/Time	5/28/2020 8:19 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Muddy	Temperature (°F)	62.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/28/2020 8:19 AM	Report #	11370
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met for EI meeting at the work trailer. SWPPP inspection: LY-29 The inspection area received 1.00" of rain overnight. CFS triple stack perimeter controls are in acceptable condition. AR-238.00 leading into the yard is maintained in acceptable condition. Culvert and drainage feature are in acceptable condition. The rock surface of the yard is maintained in acceptable condition. Waste management is acceptable. House keeping is acceptable. There are no mechanical equipment stored in the yard.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/28/2020 8:19 AM	Report #	
Pictures					
 <p>Date & Time: Thu, May 28, 2020, 09:56:40 EDT Position: +437.343112° / -080.652797° (+16.4ft) Altitude: +045ft (+13.7m) Datum: WGS-84 Azimuth/Bearing: 218.538W 3876mils True (+31°) Elevation Angle: -12.8° Horizon Angle: +01.8° Zoom: 1.0X Buffalo Anklets rain gauge reading- 1.00"</p>		 <p>Date & Time: Thu, May 28, 2020, 10:44:51 EDT Position: +437.337827° / -080.676142° (+14.4ft) Altitude: 1764ft (+532.2m) Datum: WGS-84 Azimuth/Bearing: 022° 02'45.000mils True (+31°) Elevation Angle: -13.1° Horizon Angle: +00.0° Zoom: 1.0X AR-234.00 rain gauge reading- 1.00"</p>		GPS Location See photo GPS	
Field Station# 10671+00		Field Station# 10500+00		Pic 1 Desc. Buffalo Anklets rain gauge reading- 1.00"	
 <p>Date & Time: Thu, May 28, 2020, 10:15:40 EDT Position: +437.343888° / -080.677944° (+16.4ft) Altitude: 1690ft (+515.2m) Datum: WGS-84 Azimuth/Bearing: 244.564W 4238mils True (+35°) Elevation Angle: -08.5° Horizon Angle: +00.4° Zoom: 1.0X LY-29- PPL materials storage</p>		 <p>Date & Time: Thu, May 28, 2020, 10:16:40 EDT Position: +437.343888° / -080.677944° (+16.4ft) Altitude: 1720ft (+524.2m) Datum: WGS-84 Azimuth/Bearing: 230.530W 4266mils True (+36°) Elevation Angle: -04.5° Horizon Angle: +00.1° Zoom: 1.0X LY-29- CFS triple stack perimeter controls.</p>		GPS Location See photo GPS	
Field Station# 12005+00		Field Station# 12005+00		Pic 3 Desc. LY-29- PPL Materials storage	
 <p>Date & Time: Thu, May 28, 2020, 10:18:07 EDT Position: +437.343712° / -080.677267° (+16.4ft) Altitude: 1726ft (+526.2m) Datum: WGS-84 Azimuth/Bearing: 338.922W 3009mils True (+31°) Elevation Angle: -16.5° Horizon Angle: +00.1° Zoom: 1.0X LY-29- Culvert and drainage feature.</p>		 <p>Date & Time: Thu, May 28, 2020, 10:28:41 EDT Position: +437.344027° / -080.674256° (+16.4ft) Altitude: 1761ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 261.581W 4640mils True (+26°) Elevation Angle: -06.5° Horizon Angle: +00.3° Zoom: 1.0X AR-238.00 leading into yard 29.</p>		GPS Location See photo GPS	
Field Station# 12005+00		Field Station# 12005+00		Pic 5 Desc. LY-29- Culvert and drainage feature.	
		GPS Location See photo GPS		Pic 6 Desc. AR-238.00 leading into yard 29	

A/E	124300137	Date/Time	5/28/2020 8:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/28/2020 8:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11382
Inspector	Jared Saunders			Date/Time	5/28/2020 2:40 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	80.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.40
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Waste Management	Acceptable			
Secondary Containment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/28/2020 2:40 PM	Report #	11382
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauge at Stevers Gap Road read 1.4 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/28/2020 2:40 PM	Report #	
Pictures					
		 <p>Date & Time: Thu, May 28, 2020, 10:14:31 EDT Position: +37° 21'13.5" / -80° 55'76.7" (+213.3ft) Altitude: 1846ft (+63.7ft) Datum: WGS-84 Azimuth/Bearing: 311° N45W 5529mils True (+16°) Elevation Angle: -67.5° Horizon Angle: -01.8° Zoom: 1.0x LDY 26</p>			
		 <p>Date & Time: Thu, May 28, 2020, 10:14:30 EDT Position: +37° 21'13.5" / -80° 55'76.7" (+213.3ft) Altitude: 1846ft (+63.7ft) Datum: WGS-84 Azimuth/Bearing: 311° N45W 5529mils True (+16°) Elevation Angle: -67.5° Horizon Angle: -06.7° Zoom: 1.0x LDY 26</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack compost filter sock in place around drainage.		Pic 2 Desc.	RCE in place and lay down yard 26 entrance.	
		 <p>Date & Time: Thu, May 28, 2020, 10:14:30 EDT Position: +37° 21'13.5" / -80° 55'76.7" (+213.3ft) Altitude: 1846ft (+63.7ft) Datum: WGS-84 Azimuth/Bearing: 311° N45W 5529mils True (+16°) Elevation Angle: -67.5° Horizon Angle: -02.5° Zoom: 1.0x LDY 26</p>			
		 <p>Date & Time: Thu, May 28, 2020, 10:14:30 EDT Position: +37° 21'13.5" / -80° 55'76.7" (+213.3ft) Altitude: 1846ft (+63.7ft) Datum: WGS-84 Azimuth/Bearing: 311° N45W 5529mils True (+16°) Elevation Angle: -67.5° Horizon Angle: -02.5° Zoom: 1.0x LDY 26</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	18 inch compost filter sock in place along LOD.		Pic 4 Desc.	Secondary containment in place under fuel cell.	
		 <p>Date & Time: Thu, May 28, 2020, 11:58:43 EDT Position: +37° 21'13.5" / -80° 55'76.7" (+213.3ft) Altitude: 1846ft (+63.7ft) Datum: WGS-84 Azimuth/Bearing: 311° N45W 5529mils True (+16°) Elevation Angle: -67.5° Horizon Angle: -02.5° Zoom: 1.0x LDY 26</p>			
		 <p>Date & Time: Thu, May 28, 2020, 11:58:43 EDT Position: +37° 21'13.5" / -80° 55'76.7" (+213.3ft) Altitude: 1846ft (+63.7ft) Datum: WGS-84 Azimuth/Bearing: 311° N45W 5529mils True (+16°) Elevation Angle: -67.5° Horizon Angle: -00.7° Zoom: 1.0x 11489+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	11489+00	
Pic 5 Desc.	Checked staged equipment for leaks.		Pic 6 Desc.	Rain gauge at Stevers Gap Road reads 1.5 inches.	

A/E	124300137	Date/Time	5/28/2020 2:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/28/2020 2:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11402
Inspector	Chris Burns			Date/Time	5/29/2020 7:55 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11064+53
County	Giles	Ground	Wet	Temperature (°F)	78.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/29/2020 7:55 AM	Report #	11402
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245.01. No major issues were located. Three locations of minor wildlife damage to controls were identified. PPL Environmental Coordinator Mike Perry was notified and the items were added to the punch list. PPL crews made all repairs prior to the end of day. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/29/2020 7:55 AM	Report #	
Pictures					
GPS Location 1		GPS Location 2		GPS Location 3	
Field Station# 11025+50		Field Station# 11034+00		Field Station# 11049+00	
Pic 1 Desc. W-IJ18 and controls.		Pic 2 Desc. RoW conditions and controls.		Pic 3 Desc. RoW conditions and controls.	
GPS Location 4		GPS Location 5		GPS Location 6	
Field Station# 11050+10		Field Station# 11055+00		Field Station# 11064+50	
Pic 4 Desc. S-IJ16B and S-IJ17.		Pic 5 Desc. RoW conditions and controls.		Pic 6 Desc. RoW conditions and controls.	

A/E	124300137	Date/Time	5/29/2020 7:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/29/2020 7:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11417
Inspector	Len Kruizenga			Date/Time	5/29/2020 2:15 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Full	Station End	10930+00
County	Giles	Ground	Muddy	Temperature (°F)	65.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/29/2020 2:15 PM	Report #	11417
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
EI meeting at the work trailer. SWPPP inspection- Sta#11023+80 to 10930+00 The row is wet but in stable condition. Temporary stabilization is acceptable with vegetation becoming taller and thicker, after rain and warmer weather. Perimeter controls are in acceptable condition. Water bars are stable, sump pits and end treatments are in acceptable condition. Streams are in good condition with no sediment impact from the row. AR-244.00 and Doe Creek RCE are in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/29/2020 2:15 PM	Report #	
Pictures					
<p>Date & Time: Fri, May 29, 2020 09:32:38 EDT Position: +037301069 / +000560468 (+6421.0ft) Altitude: 2107ft (+77.9ft) Datum: WGS-84 Azimuth/Bearing: 175.50SE 3111mils True (+10°) Elevation Angle: +20.6° Horizon Angle: +01.2° Zoom: 1.0x Stream S-IJ18 - Bridge & ECD's at AR-244</p> 		<p>Date & Time: Fri, May 29, 2020 09:41:35 EDT Position: +037269031 / +000650728 (+20463.4ft) Altitude: 2107ft (+77.9ft) Datum: WGS-84 Azimuth/Bearing: 10x 526E 1849mils True (+10°) Elevation Angle: +26.6° Horizon Angle: +07.1° Zoom: 1.0x Stream S-RR5 - Bridge and stream ECD's</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11024+00	Field Station#	11016+00		
Pic 1 Desc.	AR-244- Stream S-IJ18, bridge & controls.	Pic 2 Desc.	Stream S-RR5.		
<p>Date & Time: Fri, May 29, 2020 10:02:24 EDT Position: +037325837 / +000544433 (+2326.0ft) Altitude: 2326ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 09x 53SE 1742mils True (+10°) Elevation Angle: +04.2° Horizon Angle: +00.5° Zoom: 1.0x Stream S-E25 - Bridge and stream ECD's</p> 		<p>Date & Time: Fri, May 29, 2020 10:04:02 EDT Position: +037325005 / +000544022 (+2326.0ft) Altitude: 2326ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 30x N38W 5429mils True (+10°) Elevation Angle: +15.8° Horizon Angle: +00.2° Zoom: 1.0x Stream S-E24 - Bridge and stream ECD's</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	10986+00	Field Station#	10985+00		
Pic 3 Desc.	Stream S - E25	Pic 4 Desc.	Stream S - E24		
<p>Date & Time: Fri, May 29, 2020 10:11:40 EDT Position: +037300000* / +000571000* (20000.0ft) Altitude: 2221ft (683.0m) Datum: WGS-84 Azimuth/Bearing: 25x N54W 5776mils True (+10°) Elevation Angle: +14.0° Horizon Angle: +04.3° Zoom: 1.0x Sta#10965+00- Bat habitat.</p> 		<p>Date & Time: Fri, May 29, 2020 10:31:14 EDT Position: +037331148 / +000562851 (+328.1ft) Altitude: 2022ft (+315.0ft) Datum: WGS-84 Azimuth/Bearing: 25x 572W 4480mils True (+10°) Elevation Angle: +15.8° Horizon Angle: +03.3° Zoom: 1.0x Sta#10930+00- Doe Creek RCE</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	10965+00	Field Station#	10930+00		
Pic 5 Desc.	Bat habitat	Pic 6 Desc.	Doe Creek RCE		

A/E	124300137	Date/Time	5/29/2020 2:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/29/2020 2:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11420
Inspector	Garrett Barclay			Date/Time	5/29/2020 3:19 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+62
County	Giles	Ground	Damp	Temperature (°F)	74.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/29/2020 3:19 PM	Report #	11420
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning Could not perform SWPPP from MP 205 - MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/29/2020 3:19 PM	Report #	
Pictures					
 <p>Date & Time: Fri, May 29, 2020 09:16:18 EDT Position: +037°20'14.37" / -080°06'13.02" (+15.1m) Altitude: 2312ft (+11.6m) Datum: WGS-84 Azimuth/Bearing: 268° S88W 4760mils True (+12.1) Elevation Grade: +0401 Horizon Grade: +0011 Zoom: 1.0X 10858</p>		 <p>Date & Time: Fri, May 29, 2020 09:20:06 EDT Position: +037°20'13.22" / -080°06'12.44" (+15.3m) Altitude: 2395ft (+11.6m) Datum: WGS-84 Azimuth/Bearing: 032° N32E 0569mils True (+13.1) Elevation Grade: +0311 Horizon Grade: +0181 Zoom: 1.0X 10864</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10858+00		Field Station#	10864+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
 <p>Date & Time: Fri, May 29, 2020 09:35:07 EDT Position: +037°20'19.11" / -080°06'08.10" (+16.1m) Altitude: 2343ft (+11.7m) Datum: WGS-84 Azimuth/Bearing: 072° N72E 1404mils True (+13.1) Elevation Grade: +0211 Horizon Grade: +0021 Zoom: 1.0X 10893</p>		 <p>Date & Time: Fri, May 29, 2020 09:40:07 EDT Position: +037°20'18.10" / -080°06'04.92" (+16.1m) Altitude: 2343ft (+11.7m) Datum: WGS-84 Azimuth/Bearing: 092° S92E 1700mils True (+13.1) Elevation Grade: +0021 Horizon Grade: +0021 Zoom: 1.0X 10884</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10873+00		Field Station#	10884+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
 <p>Date & Time: Fri, May 29, 2020 09:41:59 EDT Position: +037°20'23.87" / -080°06'04.64" (+15.1m) Altitude: 2361ft (+11.7m) Datum: WGS-84 Azimuth/Bearing: 271° N97W 4818mils True (+14.1) Elevation Grade: +0411 Horizon Grade: +0191 Zoom: 1.0X 10889</p>		 <p>Date & Time: Fri, May 29, 2020 09:42:01 EDT Position: +037°20'23.87" / -080°06'04.64" (+15.1m) Altitude: 2361ft (+11.7m) Datum: WGS-84 Azimuth/Bearing: 024° N24E 1700mils True (+14.1) Elevation Grade: +0391 Horizon Grade: +0131 Zoom: 1.0X 1</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10889+00		Field Station#	10910+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	5/29/2020 3:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/29/2020 3:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11421
Inspector	Jared Saunders			Date/Time	5/29/2020 3:33 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	10750+00
County	Giles	Ground	Wet	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/29/2020 3:33 PM	Report #	11421
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/29/2020 3:33 PM	Report #	
Pictures					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10750+00		Field Station#	10712+50	
Pic 1 Desc.	ROW stabilized with natural vegetation.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-G33.	
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10701+00		Field Station#	10700+00	
Pic 3 Desc.	ROW stabilized with ECB and priority one silt fence in place.		Pic 4 Desc.	Waterbar with CFS end treatment in place across travel lane.	
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10698+00		Field Station#	10696+00	
Pic 5 Desc.	Sensitive resource buffer in place at stream S-G33.		Pic 6 Desc.	RCE in place at Buffalo Anklets Road.	

A/E	124300137	Date/Time	5/29/2020 3:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/29/2020 3:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		