



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10655
Inspector	Len Kruizenga			Date/Time	5/4/2020 12:40 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	66.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			
Rock Check Dam	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/4/2020 12:40 PM	Report #	
Pictures					
<p>Date & Time: Mon, May 04, 2020, 09:54:44 EDT Position: +037.237965 / -080.320055 (+98.4ft) Altitude: 1618ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 157.523E 2791mils True (+10°) Elevation Angle: -14.7° Horizon Angle: +09.1° Zoom: 1.0X Catawba rain gauge reading- 0.10"</p> 		<p>Date & Time: Mon, May 04, 2020, 10:35:26 EDT Position: +037.252951 / -080.382771 (+1230.9ft) Altitude: 2531ft (+41.9ft) Datum: WGS-84 Azimuth/Bearing: 021° N21E 0273mils True (+10°) Elevation Angle: 51.4° Horizon Angle: 109.4° Zoom: 1.0X Sta# 11901+00 - Sediment build up in water bar outlet has been removed.</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11989+00	Field Station#	11901+00		
Pic 1 Desc.	Catawba rain gauge reading- 0.10"	Pic 2 Desc.	Sediment build up has been removed from water bar outlet		
<p>Date & Time: Mon, May 04, 2020, 10:39:29 EDT Position: +037.287543 / -080.333482 (+16.4ft) Altitude: 2287ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 275° NSW 4889mils True (+10°) Elevation Angle: -24.8° Horizon Angle: +07.8° Zoom: 1.0X AR-266.03- Access road & controls.</p> 		<p>Date & Time: Mon, May 04, 2020, 11:00:00 EDT Position: +037.277111 / -080.327643 (+37.4ft) Altitude: 2746ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 170° S10E 3022mils True (+10°) Elevation Angle: -15.1° Horizon Angle: +00.3° Zoom: 1.0X Sta# 11941+00- Karst & Karst controls.</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11902+00	Field Station#	11941+00		
Pic 3 Desc.	AR-266- Access road & controls.	Pic 4 Desc.	Karst and Karst ECD's		
<p>Date & Time: Mon, May 04, 2020, 11:15:31 EDT Position: +037.232714 / -080.325279 (+16.4ft) Altitude: 1935ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 223° S45W 4000mils True (+10°) Elevation Angle: -15.5° Horizon Angle: +03.3° Zoom: 1.0X Sta# 11964+00 - P1 damage - Damaged by tree branch impact.</p> 		<p>Date & Time: Mon, May 04, 2020, 11:20:01 EDT Position: +037.231701 / -080.327469 (+50.2ft) Altitude: 1835ft (+24.4ft) Datum: WGS-84 Azimuth/Bearing: 165° S10E 2833mils True (+10°) Elevation Angle: -24.6° Horizon Angle: +0.7° Zoom: 1.0X Sta# 11970+00- Row vegetation is very good.</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11964+00	Field Station#	11970+00		
Pic 5 Desc.	All P1 damage repaired.	Pic 6 Desc.	Row vegetation is in good condition.		

A/E	124300137	Date/Time	5/4/2020 12:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/4/2020 12:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10657
Inspector	Chris Burns			Date/Time	5/4/2020 9:54 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+99
County	Montgomery	Ground	Wet	Temperature (°F)	71.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/4/2020 9:54 AM	Report #	10657
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.3 to MP 225.3 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/4/2020 9:54 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	5/4/2020 9:54 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10658
Inspector	Rob Robertson			Date/Time	5/4/2020 1:07 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11667+00
County	Montgomery	Ground	Damp	Temperature (°F)	58.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/4/2020 1:07 PM	Report #	10658
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VADEQ SWPPP inspection on JNF and private tracts located on Brush Mountain. Topsoil piles remain stable. No rilling or channeling of ROW surface taking place. Perimeter ECDs are in place and effectively controlling runoff. No sediment deposits were located. ECD maintenance needs are being addressed by the contractor. Resource crossings are stable with no visible impact. RCEs are in acceptable condition. No evidence of vandalism or trespass. Slope breakers are in good conditions with functional end treatments.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/4/2020 1:07 PM	Report #	
Pictures					
 <p>Date & Time: Mon May 04, 2020 10:56:59 EDT Position: -037.302631, -080.394669, 11669.00 Altitude: 2723ft (11669.00) Datum: WGS-84 Azimuth/Bearing: 031.19°E, 2.19mils Magnetic (±15.1) Elevation Angle: -00.3 Horizon Angle: -00.3 Zoom: 2.0x Brush Mtn. Topsoil pile stable (FS#11669+00)</p>		 <p>Date & Time: Mon May 04, 2020 10:15:16 EDT Position: -037.302631, -080.394669, 11664.00 Altitude: 2723ft (11664.00) Datum: WGS-84 Azimuth/Bearing: 031.19°E, 2.19mils Magnetic (±15.1) Elevation Angle: -02.6 Horizon Angle: -00.0 Zoom: 2.0x Brush Mtn. Slope breakers functioning properly. 11664+00</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11669+50	Field Station#	11664+00		
Pic 1 Desc.	Topsoil pile stable. No environmental issues at the FS 188 crossing.	Pic 2 Desc.	Slope breakers in place, effective. ROW stable.		
 <p>Date & Time: Mon May 04, 2020 10:22:49 EDT Position: -037.302631, -080.394669, 11660.00 Altitude: 2700ft (11660.00) Datum: WGS-84 Azimuth/Bearing: 031.19°E, 2.19mils Magnetic (±15.1) Elevation Angle: -00.0 Horizon Angle: -00.0 Zoom: 2.0x Brush Mtn. Perimeter controls in place. 11660+00</p>		 <p>Date & Time: Mon May 04, 2020 10:25:49 EDT Position: -037.302631, -080.394669, 11656.00 Altitude: 2670ft (11656.00) Datum: WGS-84 Azimuth/Bearing: 031.19°E, 2.19mils Magnetic (±15.1) Elevation Angle: -00.0 Horizon Angle: -00.0 Zoom: 2.0x Brush Mtn. Perimeter controls in place. 11656+00</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11660+00	Field Station#	11656+00		
Pic 3 Desc.	Perimeter controls in place and effective.	Pic 4 Desc.	Perimeter controls in place. End treatments are functioning as designed.		
 <p>Date & Time: Mon May 04, 2020 10:38:32 EDT Position: -037.302631, -080.394669, 11642.00 Altitude: 2165ft (11642.00) Datum: WGS-84 Azimuth/Bearing: 203.54°W, 396mils Magnetic (±12.1) Elevation Angle: -03.5 Horizon Angle: -00.2 Zoom: 1.2x Brush Mtn. ROW stable, currently stable 11642+00</p>		 <p>Date & Time: Mon May 04, 2020 10:44:48 EDT Position: -037.302631, -080.394669, 11626.00 Altitude: 1945ft (11626.00) Datum: WGS-84 Azimuth/Bearing: 203.52°W, 360mils Magnetic (±12.1) Elevation Angle: -00.0 Horizon Angle: -01.5 Zoom: 1.2x Brush Mtn. S-HH18 stable 11626+04</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11642+00	Field Station#	11626+04		
Pic 5 Desc.	Perimeter controls in place and functional. ROW currently stable.	Pic 6 Desc.	S-HH18 crossing stable.		

AFE	124300137	Date/Time	5/4/2020 1:07 PM	Report #	
Pictures					
 <p><small>Date & Time: Mon May 04 2020 11:02:42 EDT Position: +037.3137201, -080.402693, +16.411 Altitude: 1972ft (+78.7ft) Datum: WGS-84 Azimuth/Bearing: 028° N28E 0478mits Magnetic (+12°) Elevation Angle: -38.5° Horizon Angle: +03.1° Zoom: 1.0X Brush Min: S-RR14 crossing is stable</small></p>		 <p><small>Date & Time: Mon May 04 2020 11:09:48 EDT Position: +037.3137201, -080.402693, +16.411 Altitude: 1932ft (+242ft) Datum: WGS-84 Azimuth/Bearing: 034° N34E 0778mits Magnetic (+12°) Elevation Angle: -23.1° Horizon Angle: +06.9° Zoom: 1.0X Brush Min: S-RR14 crossing is stable</small></p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11619+54	Field Station#	11614+20		
Pic 7 Desc.	Clean water pipe intake in good condition.	Pic 8 Desc.	S-RR14 crossing is stable.		
 <p><small>Date & Time: Mon May 04 2020 11:11:36 EDT Position: +037.3142711, -080.402585, +16.411 Altitude: 1923ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 047° N47E 0836mits Magnetic (+12°) Elevation Angle: -09.0° Horizon Angle: -01.5° Zoom: 1.0X Brush Min: S-RR13 crossing stable</small></p>		 <p><small>Date & Time: Mon May 04 2020 11:19:13 EDT Position: +037.3142711, -080.402585, +16.411 Altitude: 1910ft (+28.9ft) Datum: WGS-84 Azimuth/Bearing: 024° N24E 0404mits Magnetic (+12°) Elevation Angle: -11.4° Horizon Angle: -00.9° Zoom: 1.0X Brush Min: S-006 crossing stable</small></p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11613+69	Field Station#	11607+81		
Pic 9 Desc.	S-RR13 crossing on MN-258.04 stable.	Pic 10 Desc.	S-006 crossing is stable.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	5/4/2020 1:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10660
Inspector	Garrett Barclay			Date/Time	5/4/2020 1:39 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Damp	Temperature (°F)	58.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/4/2020 1:39 PM	Report #	10660
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for MP 218 - MP 219.5 Observed damaged ECD's during inspection Notified environmental foreman of damaged ECD's, crews made repairs same day ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/4/2020 1:39 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11553+00		Field Station#	11569+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11562+00		Field Station#	11569+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11579+00		Field Station#	11589+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	5/4/2020 1:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	5/4/2020 1:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10682
Inspector	Len Kruizenga			Date/Time	5/5/2020 8:20 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	52.00
Municipality	N/A	Weather	Heavy Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/5/2020 8:20 AM	Report #	10682
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met at work trailer with EI's. SWPPP inspection: LY-29 A.M. rain started out light and became heavy. AR-238.00 was in good condition at the time of inspection. The rock surface of the yard is maintained in acceptable condition. CFS triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. House keeping is acceptable. Waste management is acceptable. Yard is used for materials storage, no mechanical equipment stored in the yard at this time.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/5/2020 8:20 AM	Report #	
Pictures					
<p>Date & Time: Tue, May 05, 2020, 10:29:44 EDT Position: +487.243227° / -000.676627° (±16.4M) Altitude: 1437ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 344° 54'59" 438mils True (±26°) Elevation Angle: -02.7° Horizon Angle: +00.9° Zoom: 1.0X LY-29- Arnold's materials storage.</p> 		<p>Date & Time: Tue, May 05, 2020, 10:30:35 EDT Position: +487.243227° / -000.676627° (±16.4M) Altitude: 1437ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 217° 53'W 388mils True (±26°) Elevation Angle: -10.7° Horizon Angle: +00.9° Zoom: 1.0X LY-29- PPL materials storage.</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	LY-29- Arnold's materials storage.	Pic 2 Desc.	LY-29- PPL Materials storage.		
<p>Date & Time: Tue, May 05, 2020, 10:34:24 EDT Position: +487.363211° / -000.676647° (±16.4M) Altitude: 1531ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 259° 57'W 501mils True (±26°) Elevation Angle: -06.2° Horizon Angle: +02.1° Zoom: 1.0X LY-29- Rock surface of the road is in acceptable condition.</p> 		<p>Date & Time: Tue, May 05, 2020, 10:35:49 EDT Position: +487.363211° / -000.676627° (±16.4M) Altitude: 1704ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 282° N78W 501mils True (±26°) Elevation Angle: -06.2° Horizon Angle: +02.8° Zoom: 1.0X LY-29 CFS triple stack perimeter controls.</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	LY-29- Rock construction surface is in acceptable condition.	Pic 4 Desc.	LY-29- CFS triple stack perimeter controls.		
<p>Date & Time: Tue, May 05, 2020, 11:40:30 EDT Position: +487.243227° / -000.676627° (±16.4M) Altitude: 1437ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 322° N88W 504mils True (±16°) Elevation Angle: -03.1° Horizon Angle: +03.1° Zoom: 1.0X LY-29- Culvert & drainage feature.</p> 		<p>Date & Time: Tue, May 05, 2020, 11:40:30 EDT Position: +487.243227° / -000.676627° (±16.4M) Altitude: 1825ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 222° 50'W 430mils True (±16°) Elevation Angle: -09.8° Horizon Angle: +02.6° Zoom: 1.0X AR-238.00- RCE</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	LY-29- culvert and drainage feature.	Pic 6 Desc.	LY-29- AR-238.00 - RCE		

A/E	124300137	Date/Time	5/5/2020 8:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/5/2020 8:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10707
Inspector	Jared Saunders			Date/Time	5/4/2020 3:53 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Wet	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/4/2020 3:53 PM	Report #	10707
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during inspection. Checked rain gauge at Mount Tabor Road reads 0.2 inched.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/4/2020 3:53 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11669+00		Field Station#	11740+43	
Pic 1 Desc.	Triple stack compost filter sock and priority one silt fence in place along LOD.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-EP65.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11767+00	
Pic 3 Desc.	RCE in place at Main Line Valve 26.		Pic 4 Desc.	Rain gauge at Mount Tabor Road reads 0.2 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11772+00		Field Station#	11775+00	
Pic 5 Desc.	Clean water diversion pipe inlet and clean water diversion berm in place.		Pic 6 Desc.	Clean water diversion pipe and plunge pool in place.	

A/E	124300137	Date/Time	5/4/2020 3:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	5/4/2020 3:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10708
Inspector	Jared Saunders			Date/Time	5/5/2020 2:53 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	55.00
Municipality	N/A	Weather	Heavy Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/5/2020 2:53 PM	Report #	10708
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/5/2020 2:53 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack compost filter sock in place around drainage.		Pic 2 Desc.	18 inch compost filter sock in place along LOD.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	No leaks observed under staged equipment.		Pic 4 Desc.	Dumpsters being utilized for trash management.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Secondary containment in place under fuel cell.		Pic 6 Desc.	RCE in place Lay Down Yard 26.	

A/E	124300137	Date/Time	5/5/2020 2:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/5/2020 2:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10712
Inspector	Garrett Barclay			Date/Time	5/5/2020 3:06 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	48.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/5/2020 3:06 PM	Report #	10712
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP for LDY 28 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/5/2020 3:06 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	5/5/2020 3:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/5/2020 3:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10729
Inspector	Len Kruizenga			Date/Time	5/6/2020 8:31 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11024+00
State	VA	Inspection Area	Full	Station End	10930+00
County	Giles	Ground	Muddy	Temperature (°F)	51.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Broad-Based Dip	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/6/2020 8:31 AM	Report #	
Pictures					
<p>Date & Time: Wed May 06, 2020, 09:52:15 EDT Position: -037.317024, -080.554008 (-541 N 101 W) Altitude: 2105ft (-32.8m) Datum: WGS-84 Azimuth/Bearing: 279 N81W 4960mils True (-10) Elevation Angle: -07.9 Horizon Angle: -05.8 Zoom: 1.0X AR-244 rain gauge reading-0.70"</p>		<p>Date & Time: Wed May 06, 2020, 09:58:15 EDT Position: -037.213369, -080.507795 (-12548.6m) Altitude: 2105ft (-32.8m) Datum: WGS-84 Azimuth/Bearing: 320 N40W 5689mils True (-10) Elevation Angle: -16.5 Horizon Angle: -05.2 Zoom: 1.0X AR-244- Stream S-IJ18- bridge & controls</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11024+00	Field Station#	11024+00		
Pic 1 Desc.	AR-244 rain gauge reading- 0.70"	Pic 2 Desc.	Stream- S-IJ18		
<p>Date & Time: Wed May 06, 2020, 10:08:41 EDT Position: -037.323684, -080.555582 (-516.4ft) Altitude: 2431ft (-726.2ft) Datum: WGS-84 Azimuth/Bearing: 080 N08E 1422mils True (-25) Elevation Angle: -05.5 Horizon Angle: -00.4 Zoom: 1.0X Stream S-RR5- Stream bridge ECD 5</p>		<p>Date & Time: Wed May 06, 2020, 10:21:55 EDT Position: -037.313631, -080.402337 (-30246.0m) Altitude: 2442ft (-737.4ft) Datum: WGS-84 Azimuth/Bearing: 348 N12W 6187mils True (-10) Elevation Angle: -42.5 Horizon Angle: -06.6 Zoom: 1.0X Stat 10996+30- P1 down at end treatment</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11016+00	Field Station#	10996+30		
Pic 3 Desc.	Stream - S-RR5	Pic 4 Desc.	P1 damaged, contractor has made repairs.		
<p>Date & Time: Wed May 06, 2020, 10:24:23 EDT Position: -037.326689, -080.541963 (-432.0ft) Altitude: 2078ft (-627.5ft) Datum: WGS-84 Azimuth/Bearing: 343 N17W 6998mils True (-10) Elevation Angle: -40.7 Horizon Angle: -07.7 Zoom: 1.0X Stat 10996+20- P1 down at end treatment</p>		<p>Date & Time: Wed May 06, 2020, 10:30:42 EDT Position: -037.322571, -080.464771 (-110.8m) Altitude: 2335ft (-715.0ft) Datum: WGS-84 Azimuth/Bearing: 084 N84E 1493mils True (-50) Elevation Angle: -08.8 Horizon Angle: -00.8 Zoom: 1.0X Stream S-E25- Bridge ECD 6</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	10996+30	Field Station#	10986+00		
Pic 5 Desc.	P1 damaged by bear, contractor has made repairs.	Pic 6 Desc.	Stream- S- E25		

AFE	124300137	Date/Time	5/6/2020 8:31 AM	Report #	
Pictures					
		<p>Insert image here</p>			
GPS Location	See photo GPS	GPS Location			
Field Station#	10985+00	Field Station#			
Pic 7 Desc.	Stream S-E24	Pic 8 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	5/6/2020 8:31 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10738
Inspector	Garrett Barclay			Date/Time	5/6/2020 2:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+62
County	Giles	Ground	Wet	Temperature (°F)	44.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.60
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/6/2020 2:41 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+1	
Pic 1 Desc.	.6" of rain recorded @ Kow Camp		Pic 2 Desc.	.6" of rain recorded @ Stevens Gap	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10910+00		Field Station#	10909+00	
Pic 3 Desc.	SSF detached from wire backing		Pic 4 Desc.	Damaged P1	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10890+00		Field Station#	10857+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	5/6/2020 2:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/6/2020 2:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10739
Inspector	Jared Saunders			Date/Time	5/6/2020 2:55 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	10750+00
County	Giles	Ground	Wet	Temperature (°F)	50.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) Yes
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) No
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/6/2020 2:55 PM	Report #	10739
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. Checked rain gauges at Access Road 234 - 0.7 inches, Buffalo Anklets Road - 0.7 inches, Mount Tabor Road - 0.6 inches and Catawba Road - 0.3 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	5/6/2020 2:55 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10747+00		Field Station#	10696+00	
Pic 1 Desc.	ROW stabilized with natural vegetation growth.		Pic 2 Desc.	Rain gauge at Buffalo Anklets Road reads 0.7 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10696+00		Field Station#	12005+00	
Pic 3 Desc.	RCE in place at Buffalo Anklets Road.		Pic 4 Desc.	Rain gauge at Access Road 234 reads 0.7 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11990+00	
Pic 5 Desc.	Rain gauge at Mount Tabor Road reads 0.6 inches.		Pic 6 Desc.	Rain gauge at Catawba Road reads 0.3 inches.	

A/E	124300137	Date/Time	5/6/2020 2:55 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/6/2020 2:55 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10746
Inspector	Chris Burns			Date/Time	5/6/2020 4:10 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11064+53
County	Giles	Ground	Wet	Temperature (°F)	50.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/6/2020 4:10 PM	Report #	10746
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245.01. Accompanied by MBP representative Dane Blevins during SWPPP inspection. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/6/2020 4:10 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11025+50	Field Station#	11034+00		
Pic 1 Desc.	S-IJ18.	Pic 2 Desc.	RoW conditions and controls.		
					
GPS Location	3	GPS Location	4		
Field Station#	11048+00	Field Station#	11050+10		
Pic 3 Desc.	RoW conditions and controls.	Pic 4 Desc.	S-IJ16B and S-IJ17.		
					
GPS Location	5	GPS Location	6		
Field Station#	11055+00	Field Station#	11064+50		
Pic 5 Desc.	Karst protection perimeter controls functional.	Pic 6 Desc.	Perimeter controls functional.		

A/E	124300137	Date/Time	5/6/2020 4:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/6/2020 4:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10762
Inspector	Len Kruizenga			Date/Time	5/7/2020 8:15 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+88
State	VA	Inspection Area	Full	Station End	11161+00
County	Giles	Ground	Wet	Temperature (°F)	42.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/7/2020 8:15 AM	Report #	10762
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met EI's at Winding Way. SWPPP inspection: Sta#11254+88 to 11161+00. MP-213 to 211 The row is wet but in stable condition. Temporary stabilization is acceptable. Water bars are in stable condition. Water bar end treatments are in acceptable condition. Perimeter controls, silt fence, CFS, & SSF are in acceptable condition. Drainage feature and ECD's are in acceptable condition. Slope drains are in acceptable condition. CWD pipe and plunge pool are in good condition. Access roads, Winding Way, AR-249.02, AR-249.01 are in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/7/2020 8:15 AM	Report #	
Pictures					
 <p>Date & Time: Thu, May 07, 2020, 08:15 EDT Position: +037.301644 / -089.502637 (+32.8m) Altitude: 2093ft (+39.4m) Datum: WGS-84 Azimuth/Bearing: 192° S12W 34/3mils True (±10°) Elevation Angle: -31.4° Horizon Angle: +02.5° Zoom: 1.0X Star#11228+00- P1 perimeter controls</p>		 <p>Date & Time: Thu, May 07, 2020, 09:21 EDT Position: +037.301644 / -089.502637 (+32.8m) Altitude: 2093ft (+39.4m) Datum: WGS-84 Azimuth/Bearing: 192° S12W 34/3mils True (±10°) Elevation Angle: -31.4° Horizon Angle: +02.5° Zoom: 1.0X Star#11225+00- Slope drain, end treatment, rock channel</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11228+00	Field Station#	11225+00		
Pic 1 Desc.	P1 perimeter controls.	Pic 2 Desc.	Slope drain, end treatment, rock channel.		
 <p>Date & Time: Thu, May 07, 2020, 09:40 EDT Position: +037.306458 / -089.510068 (+32.8m) Altitude: 1972ft (+52.8m) Datum: WGS-84 Azimuth/Bearing: 100° S78E 186mils True (±10°) Elevation Angle: -69.5° Horizon Angle: -00.4° Zoom: 1.0X Star#11203+00- CFS perimeter controls</p>		 <p>Date & Time: Thu, May 07, 2020, 09:46 EDT Position: +037.306458 / -089.510068 (+32.8m) Altitude: 1972ft (+52.8m) Datum: WGS-84 Azimuth/Bearing: 100° S78E 186mils True (±10°) Elevation Angle: -69.5° Horizon Angle: -00.4° Zoom: 1.0X Star#11190+00- Drainage feature</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11203+00	Field Station#	11190+00		
Pic 3 Desc.	CFS perimeter controls and triple stack end treatments.	Pic 4 Desc.	Drainage feature		
 <p>Date & Time: Thu, May 07, 2020, 09:49 EDT Position: +037.307411 / -089.511989 (+32.8m) Altitude: 2031ft (+32.0m) Datum: WGS-84 Azimuth/Bearing: 248° S68W 4409mils True (±10°) Elevation Angle: -26.3° Horizon Angle: +00.8° Zoom: 1.0X AR-249.02- Access road to rock check dam</p>		 <p>Date & Time: Thu, May 07, 2020, 09:54 EDT Position: +037.307395 / -089.511993 (+32.8m) Altitude: 1923ft (+26.2m) Datum: WGS-84 Azimuth/Bearing: 348° N12W 46mils True (±10°) Elevation Angle: -18.4° Horizon Angle: +00.8° Zoom: 1.0X Star#11184+00- CWD pipe & plunge pool</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11184+50	Field Station#	11184+00		
Pic 5 Desc.	AR-249.02	Pic 6 Desc.	CWD pipe and plunge pool		

A/E	124300137	Date/Time	5/7/2020 8:15 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	5/7/2020 8:15 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10763
Inspector	Chris Burns			Date/Time	5/7/2020 8:26 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Wet	Temperature (°F)	59.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/7/2020 8:26 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11265+00	Field Station#	11286+00		
Pic 1 Desc.	Perimeter controls functional.	Pic 2 Desc.	Perimeter controls functional.		
					
GPS Location	3	GPS Location	4		
Field Station#	11292+80	Field Station#	11297+00		
Pic 3 Desc.	S-MM18 and controls.	Pic 4 Desc.	RoW conditions and controls.		
					
GPS Location	5	GPS Location	6		
Field Station#	11327+85	Field Station#	11352+97		
Pic 5 Desc.	S-NN12 and controls.	Pic 6 Desc.	S-NN11.		

A/E	124300137	Date/Time	5/7/2020 8:26 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/7/2020 8:26 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10775
Inspector	Garrett Barclay			Date/Time	5/7/2020 3:19 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+53
State	VA	Inspection Area	Partial	Station End	11158+00
County	Giles	Ground	Dry	Temperature (°F)	41.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	5/7/2020 3:19 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11083+00		Field Station#	11091+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11111+00		Field Station#	11127+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	Crews replacing P1SF	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11133+00		Field Station#	11143+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	5/7/2020 3:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/7/2020 3:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report



Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10791
Inspector	Len Kruizenga			Date/Time	5/8/2020 8:07 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Damp	Temperature (°F)	48.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/8/2020 8:07 AM	Report #	10791
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11899+00 to 12005+00. MP- 225.3 to 227.3 The row is dry and in stable condition. Permanent restoration is acceptable with good vegetative growth. Perimeter controls, silt fence, CFS, SSF are in acceptable condition. Water bars and level spreaders are in acceptable condition. Karst's and Karst ECD's are in acceptable condition. AR-266.03 and AR-266.00 are in good condition. Wetland ECD's are in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/8/2020 8:07 AM	Report #	
Pictures					
 <p>Date & Time: Fri, May 08, 2020, 08:49:40 EDT Position: +037.2027687° / -080.324602° (±0.2m) Altitude: 2280ft (±26.2m) Datum: WGS-84 Azimuth/Bearing: 114° 54' 48" 2007mils True (±0.1°) Elevation Angle: -07.0° Horizon Angle: +00.3° Zoom: 1.0X Sta#11900+00 - AR-266.03- Access road & controls.</p>		 <p>Date & Time: Fri, May 08, 2020, 08:59:07 EDT Position: +037.203783° / -080.331359° (±0.2m) Altitude: 2280ft (±26.2m) Datum: WGS-84 Azimuth/Bearing: 109° 57' 19" 1938mils True (±0.1°) Elevation Angle: -01.6° Horizon Angle: +04.5° Zoom: 1.0X Sta#11919+74- CFS water bar outlets, & perimeter controls.</p>		GPS Location See photo GPS Field Station# 11900+00 Pic 1 Desc. AR-266.03	
 <p>Date & Time: Fri, May 08, 2020, 09:12:05 EDT Position: +037.278933° / -080.327684° (±0.4m) Altitude: 2275ft (±26.2m) Datum: WGS-84 Azimuth/Bearing: 201° 52' 10" 3573mils True (±0.1°) Elevation Angle: -13.7° Horizon Angle: +01.7° Zoom: 2.0X Sta#11941+00- Karst ECD's</p>		 <p>Date & Time: Fri, May 08, 2020, 09:34:53 EDT Position: +037.301672° / -080.282258° (±0.2m) Altitude: 0ft: Erión Datum: WGS-84 Azimuth/Bearing: 192° 51' 20" 3413mils True (±0.1°) Elevation Angle: -16.5° Horizon Angle: +03.9° Zoom: 1.0X Sta#11953+00- Level spreader permanent stabilization.</p>		GPS Location See photo GPS Field Station# 11941+00 Pic 3 Desc. Karst ECD's	
 <p>Date & Time: Fri, May 08, 2020, 09:39:47 EDT Position: +037.269425° / -080.322704° (±0.4m) Altitude: 1877ft (±157.5m) Datum: WGS-84 Azimuth/Bearing: 083° 03' 38" 1476mils True (±0.1°) Elevation Angle: -22.4° Horizon Angle: +00.4° Zoom: 1.0X AR-266.00- Rock checks & ECD's</p>		 <p>Date & Time: Fri, May 08, 2020, 09:39:47 EDT Position: +037.269425° / -080.322704° (±0.4m) Altitude: 1877ft (±157.5m) Datum: WGS-84 Azimuth/Bearing: 083° 03' 38" 1476mils True (±0.1°) Elevation Angle: -22.4° Horizon Angle: +00.4° Zoom: 1.0X AR-266.00- Rock checks & ECD's</p>		GPS Location See photo GPS Field Station# 11973+00 Pic 5 Desc. Water bars are stable and well vegetated.	
 <p>Date & Time: Fri, May 08, 2020, 09:39:47 EDT Position: +037.269425° / -080.322704° (±0.4m) Altitude: 1877ft (±157.5m) Datum: WGS-84 Azimuth/Bearing: 083° 03' 38" 1476mils True (±0.1°) Elevation Angle: -22.4° Horizon Angle: +00.4° Zoom: 1.0X AR-266.00- Rock checks & ECD's</p>		 <p>Date & Time: Fri, May 08, 2020, 09:39:47 EDT Position: +037.269425° / -080.322704° (±0.4m) Altitude: 1877ft (±157.5m) Datum: WGS-84 Azimuth/Bearing: 083° 03' 38" 1476mils True (±0.1°) Elevation Angle: -22.4° Horizon Angle: +00.4° Zoom: 1.0X AR-266.00- Rock checks & ECD's</p>		GPS Location See photo GPS Field Station# 11979+00 Pic 6 Desc. AR-266.00- rock check dams and ECD's	

AFE	124300137	Date/Time	5/8/2020 8:07 AM	Report #	
Pictures					
					
GPS Location	See photo GPS	GPS Location			
Field Station#	12000+00	Field Station#			
Pic 7 Desc.	Wetland ECD's	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	5/8/2020 8:07 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10802
Inspector	Chris Burns			Date/Time	5/8/2020 12:11 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+99
County	Montgomery	Ground	Damp	Temperature (°F)	54.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/8/2020 12:11 PM	Report #	10802
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates Met with environmental staff. Performed SWPPP inspection from MP 223.3 to MP 225.3 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/8/2020 12:11 PM	Report #	
Pictures					
<p>Date & Time Fri, May 08, 2020, 08:33:40 EDT Position: +037.294229° / -080.341029° (+1233.40) Altitude: 2142ft (+22.8m) Datum: WGS-84 Azimuth/Bearing: 199° S01E 1724mils True (+13°) Elevation Angle: +03.2° Horizon Angle: +00.1° Zoom: 1.0X 11789+00</p> 		<p>Date & Time Fri, May 08, 2020, 08:35:54 EDT Position: +037.294229° / -080.359393° (+1668.7m) Altitude: 2142ft (+22.8m) Datum: WGS-84 Azimuth/Bearing: 097° S01E 1724mils True (+13°) Elevation Angle: +03.2° Horizon Angle: +00.1° Zoom: 1.0X 11797+00</p> 			
GPS Location	1	GPS Location	2		
Field Station#	11789+00	Field Station#	11797+00		
Pic 1 Desc.	RCE on the South side of Mt Tabor rd.	Pic 2 Desc.	Section of restored RoW showing conditions and controls.		
<p>Date & Time Fri, May 08, 2020, 08:41:13 EDT Position: +037.294179° / -080.357151° (+7774.5m) Altitude: 2142ft (+22.8m) Datum: WGS-84 Azimuth/Bearing: 172° S01E 2016mils True (+12°) Elevation Angle: +03.2° Horizon Angle: +01.1° Zoom: 1.0X 11812+00</p> 		<p>Date & Time Fri, May 08, 2020, 08:42:11 EDT Position: +037.294179° / -080.357151° (+7774.5m) Altitude: 2142ft (+22.8m) Datum: WGS-84 Azimuth/Bearing: 172° S01E 2016mils True (+12°) Elevation Angle: +03.2° Horizon Angle: +01.1° Zoom: 1.0X 11812+00</p> 			
GPS Location	3	GPS Location	4		
Field Station#	11812+00	Field Station#	11841+00		
Pic 3 Desc.	Water bar and level spreader.	Pic 4 Desc.	Section of restored RoW showing conditions and controls.		
<p>Date & Time Fri, May 08, 2020, 08:42:08 EDT Position: +037.294179° / -080.347942° (+7235.5m) Altitude: 2200ft (+23.8m) Datum: WGS-84 Azimuth/Bearing: 351° N09W 4240mils True (+12°) Elevation Angle: +09.0° Horizon Angle: +01.9° Zoom: 1.0X P-KL2</p> 		<p>Date & Time Fri, May 08, 2020, 08:43:08 EDT Position: +037.294179° / -080.359393° (+1668.7m) Altitude: 2142ft (+22.8m) Datum: WGS-84 Azimuth/Bearing: 097° S01E 1724mils True (+13°) Elevation Angle: +03.2° Horizon Angle: +00.1° Zoom: 1.0X 11797+00</p> 			
GPS Location	5	GPS Location	6		
Field Station#	11863+65	Field Station#	11886+00		
Pic 5 Desc.	P-KL2 and controls.	Pic 6 Desc.	Section of restored RoW showing conditions and controls.		

A/E	124300137	Date/Time	5/8/2020 12:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/8/2020 12:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10804
Inspector	Rob Robertson			Date/Time	5/8/2020 1:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Damp	Temperature (°F)	50.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/8/2020 1:25 PM	Report #	10804
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a full VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The ROW was found stable with no erosion issues identified. Runoff is being controlled by slope breakers and end treatments. No sediment deposits are being formed. Sumps are in good condition. ECDs are in place and functional. No maintenance needs were identified. Resource buffers are stable with adequate controls in place. No impact is apparent at crossings. No slips have occurred. No vandalism was noted. RCEs are in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/8/2020 1:25 PM	Report #	
Pictures					
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11668+50	Field Station#	11648+00		
Pic 1 Desc.	Soil piles and cuts are stable. Perimeter controls in place and functional.	Pic 2 Desc.	End treatments are functioning as designed. Perimeter controls in place.		
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11643+00	Field Station#	11630+00		
Pic 3 Desc.	Grasses adequate. Surface stable. Slope breakers effective.	Pic 4 Desc.	ROW stable. Slope breakers effective. Perimeter controls in place.		
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11626+04	Field Station#	11614+20		
Pic 5 Desc.	S-HH18 crossing stable. No resource impact.	Pic 6 Desc.	S-RR14 crossing stable. No resource impact.		

AFE	124300137	Date/Time	5/8/2020 1:25 PM	Report #	
Pictures					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11613+69	Field Station#	11607+81		
Pic 7 Desc.	S-RR13 crossing stable. No impact to resource.	Pic 8 Desc.	S-006 crossing is currently stable. No impact to resource.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	5/8/2020 1:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10817
Inspector	Garrett Barclay			Date/Time	5/8/2020 4:20 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+00
County	Giles	Ground	Damp	Temperature (°F)	41.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/8/2020 4:20 PM	Report #	10817
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP from MP 218 -MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No items added to the punch Accompanied Slip specialist to several stream crossings for notes.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/8/2020 4:20 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11534+00		Field Station#	11549+00	
Pic 1 Desc.	Confirmed repairs to end treatments		Pic 2 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11573+00		Field Station#	11573+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11583+00		Field Station#	11587+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	5/8/2020 4:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	5/8/2020 4:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10857
Inspector	Jared Saunders			Date/Time	5/8/2020 3:07 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Damp	Temperature (°F)	60.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/8/2020 3:07 PM	Report #	10857
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/8/2020 3:07 PM	Report #	
Pictures					
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.		
Field Station#	11669+00	Field Station#	11687+00		
Pic 1 Desc.	Triple stack compost filter sock and priority one silt fence in place along LOD.	Pic 2 Desc.	Sensitive resource buffer in place at stream S-MN21.		
		Insert image here			
GPS Location	See photo for GPS location.	GPS Location			
Field Station#	11672+00	Field Station#			
Pic 3 Desc.	Waterbar, sump pit, and waterbar end treatment in place.	Pic 4 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300137	Date/Time	5/8/2020 3:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	5/8/2020 3:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	10934
Inspector	Jared Saunders			Date/Time	5/7/2020 2:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11351+00
State	VA	Inspection Area	Partial	Station End	11525+00
County	Giles	Ground	Damp	Temperature (°F)	60.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	5/7/2020 2:59 PM	Report #	10934
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 214.9 to MP 218.3 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. Right of way has been stabilized using seed and mulch. Minor vegetation growth present. No forward progress has been completed due to shut down. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/7/2020 2:59 PM	Report #	
Pictures					
<p>Date & Time: Thu May 07 2020 09:48:13 EDT Position: +37°21'33.37" / -80°47'48.91" (+15971.9M) Altitude: 2227ft (+682m) Datum: WGS-84 Azimuth/Bearing: 343° N17W 698mils True (+17°) Elevation Angle: -17.4 Horizon Angle: +03.6 Zoom: 1.0X 11507+00</p> 		<p>Date & Time: Thu May 07 2020 09:49:01 EDT Position: +37°21'22.21" / -80°47'48.91" (+15971.9M) Altitude: 2209ft (+676m) Datum: WGS-84 Azimuth/Bearing: 166° S14E 295mils True (+17°) Elevation Angle: -01.9 Horizon Angle: -00.9 Zoom: 1.0X 11505+00</p> 			
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.		
Field Station#	11507+00	Field Station#	11505+00		
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.	Pic 2 Desc.	Clean water diversion pipe and clean water diversion berm in place.		
<p>Date & Time: Thu May 07 2020 09:49:01 EDT Position: +37°21'22.21" / -80°47'48.91" (+15971.9M) Altitude: 2209ft (+676m) Datum: WGS-84 Azimuth/Bearing: 209° S29W 3710mils True (+17°) Elevation Angle: -07.3 Horizon Angle: -00.9 Zoom: 1.0X 11487+00</p> 		<p>Date & Time: Thu May 07 2020 09:49:01 EDT Position: +37°21'22.21" / -80°47'48.91" (+15971.9M) Altitude: 2209ft (+676m) Datum: WGS-84 Azimuth/Bearing: 209° S29W 3710mils True (+17°) Elevation Angle: -07.3 Horizon Angle: -00.9 Zoom: 1.0X 11487+00</p> 			
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.		
Field Station#	11498+00	Field Station#	11487+00		
Pic 3 Desc.	RCE in place at Stevers Gap Road.	Pic 4 Desc.	Rock lined channel in place.		
<p>Date & Time: Thu May 07 2020 10:08:34 EDT Position: +37°21'51.11" / -80°47'48.91" (+15971.9M) Altitude: 2151ft (+655m) Datum: WGS-84 Azimuth/Bearing: 230° S50W 4089mils True (+22°) Elevation Angle: -07.4 Horizon Angle: -01.5 Zoom: 1.0X 11451+00 S-0012 & S-0013</p> 		<p>Date & Time: Thu May 07 2020 10:17:01 EDT Position: +37°21'51.11" / -80°47'48.91" (+15971.9M) Altitude: 2135ft (+650m) Datum: WGS-84 Azimuth/Bearing: 313° N47W 550mils True (+22°) Elevation Angle: -22.3 Horizon Angle: -05.0 Zoom: 1.0X 11426+00</p> 			
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.		
Field Station#	11451+00	Field Station#	11426+00		
Pic 5 Desc.	Sensitive resource buffer in place at stream S-0012 and S-0013.	Pic 6 Desc.	Rock lined channel, sump pit, waterbar and waterbar end treatment in place.		

A/E	124300137	Date/Time	5/7/2020 2:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	5/7/2020 2:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			