



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11443
Inspector	Chris Burns			Date/Time	6/1/2020 7:55 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/1/2020 7:55 AM	Report #	11443
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213 to MP 214.8. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/1/2020 7:55 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11265+00	Field Station#	11286+00		
Pic 1 Desc.	Perimeter controls functional.	Pic 2 Desc.	Perimeter controls functional.		
					
GPS Location	3	GPS Location	4		
Field Station#	11292+80	Field Station#	11327+85		
Pic 3 Desc.	S-MM18 and controls.	Pic 4 Desc.	S-NN12 and controls.		
					
GPS Location	5	GPS Location	6		
Field Station#	11336+00	Field Station#	11352+97		
Pic 5 Desc.	RoW conditions.	Pic 6 Desc.	S-NN11 and controls.		

A/E	124300137	Date/Time	6/1/2020 7:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/1/2020 7:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11464
Inspector	Len Kruizenga			Date/Time	6/1/2020 2:49 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Full	Station End	11158+27
County	Giles	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/1/2020 2:49 PM	Report #	11464
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with EI's at Winding Way. SWPPP inspection: Sta#11254+99 to 11158+27. MP- 213 to 211 The row is dry and in stable condition, with temporary stabilization acceptable. Perimeter controls, P1 silt fence, CFS & SSF in acceptable condition. Water bars sump pits, end treatments are in acceptable condition. Slope drains are in acceptable. CWD pipe and plunge pool are in acceptable condition. Access roads, Winding Way, AR-249.02, AR- 249.01 are maintained in acceptable condition. Topsoil stockpiles are well vegetated.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/1/2020 2:49 PM	Report #	
Pictures					
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11225+00		Field Station#	11218+00	
Pic 1 Desc.	Rock channel		Pic 2 Desc.	P1 silt fence perimeter controls.	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11204+00		Field Station#	11191+00	
Pic 3 Desc.	CFS perimeter controls & vegetated topsoil stockpiles.		Pic 4 Desc.	Drainage feature & controls.	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11184+00		Field Station#	11172+70	
Pic 5 Desc.	CWD pipe and plunge pool are in good condition.		Pic 6 Desc.	Slope drain, checks, sump pit, end treatment	

A/E	124300137	Date/Time	6/1/2020 2:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/1/2020 2:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11465
Inspector	Jared Saunders			Date/Time	6/1/2020 2:50 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+67
State	VA	Inspection Area	Partial	Station End	11524+16
County	Giles	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Broad-Based Dip	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE		124300137		Date/Time		6/1/2020 2:50 PM		Report #			
Pictures											
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11507+00						Field Station#		11505+00	
Pic 1 Desc.		Clean water diversion pipe and plunge pool in place.						Pic 2 Desc.		Clean water diversion pipe and clean water diversion berm in place.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11487+00						Field Station#		11478+00	
Pic 3 Desc.		Rock lined channel in place.						Pic 4 Desc.		Two-tone stabilized with ECB and slope drains in place to minimize erosion.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11451+00						Field Station#		11380+00	
Pic 5 Desc.		Sensitive resource buffer in place at stream S-0012 and S-0013.						Pic 6 Desc.		Triple barrier ECDs in place at off ROW karst feature.	

A/E	124300137	Date/Time	6/1/2020 2:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/1/2020 2:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11469
Inspector	Garrett Barclay			Date/Time	6/1/2020 3:50 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+53
State	VA	Inspection Area	Partial	Station End	11158+27
County	Giles	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/1/2020 3:50 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11067+00		Field Station#	11073+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	Trees cut by land owner	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11082+00		Field Station#	11084+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11120+00		Field Station#	11130+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	6/1/2020 3:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/1/2020 3:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11507
Inspector	Len Kruizenga			Date/Time	6/2/2020 1:08 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+99
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	67.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			
Sensitive Resource Signage	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/2/2020 1:08 PM	Report #	11507
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11899+00 to 12005+00. MP- 225.3 to 227.3 The row is dry and in stable condition. This inspection area has very good vegetation. Perimeter controls, P1 silt fence at sta# 11916+50 has been damaged, issue has been added to the punch list. CFS and SSF perimeter controls are in acceptable condition. Water bars and level spreaders are in good condition condition. Karst ECD's are in acceptable condition. Wetland ECD's are in acceptable condition. AR-266.03 and AR-266.00 are in good condition. AR-266.00- The contractor has cleaned sump pits, stabilized broad base dips, mulched spoil piles. Sta#11990+00 to 11995+00- The landowner has mowed the row for cattle feed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/2/2020 1:08 PM	Report #	
Pictures					
 <p>Date & Time: Tue Jun 02, 2020, 09:28:35 EDT Position: +037.246876° / +080.390672° (±121.59 ft) Altitude: 0 ft (0.00 m) Datum: WGS-84 Azimuth/Bearing: 303° N57W 5387mils True (±10°) Elevation Angle: -17.2° Horizon Angle: +02.8° Zoom: 1.0X Sta#11916+50- P1 damaged, most likely bear.</p>		 <p>Date & Time: Tue Jun 02, 2020, 09:37:17 EDT Position: +037.246876° / +080.390672° (±121.59 ft) Altitude: 0 ft (0.00 m) Datum: WGS-84 Azimuth/Bearing: 099° S83E 1724mils True (±10°) Elevation Angle: -45.7° Horizon Angle: -00.7° Zoom: 1.0X Sta#11916+50- P1 damaged, most likely bear.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11900+00		Field Station#	11916+50	
Pic 1 Desc.	AR-266.03- Access road and controls.		Pic 2 Desc.	P1 perimeter controls damaged by bear. Added to the punch list.	
 <p>Date & Time: Tue Jun 02, 2020, 09:47:10 EDT Position: +037.280534° / +080.328480° (±656.2 ft) Altitude: 255 ft (±1003.1 ft) Datum: WGS-84 Azimuth/Bearing: 197° S17W 3502mils True (±10°) Elevation Angle: -27.6° Horizon Angle: +02.1° Zoom: 1.0X AR-266.00- Sump cleaned, broad base dips, stabilized, mulched spoil stockpiles.</p>		 <p>Date & Time: Tue Jun 02, 2020, 10:57:07 EDT Position: +037.278866° / +080.327741° (±32.8 ft) Altitude: 224 ft (±157.5 ft) Datum: WGS-84 Azimuth/Bearing: 105° S89W 3330mils True (±10°) Elevation Angle: -13.2° Horizon Angle: +02.3° Zoom: 1.0X Sta#11942+00- Karst and Karst ECD's</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11930+00		Field Station#	11942+00	
Pic 3 Desc.	Contractor has cleaned sump pits, stabilized broad base dips, mulched spoil stockpiles, on AR- 266.00		Pic 4 Desc.	Karst ECD's	
 <p>Date & Time: Tue Jun 02, 2020, 10:26:20 EDT Position: +037.243104° / +080.394552° (±129.2 ft) Altitude: 630 ft (±192.3 ft) Datum: WGS-84 Azimuth/Bearing: 007° N07E 0124mils True (±10°) Elevation Angle: -08.1° Horizon Angle: +00.2° Zoom: 1.0X AR-266.00- Access road and rock checks.</p>		 <p>Date & Time: Tue Jun 02, 2020, 10:30:34 EDT Position: +037.248188° / +080.320352° (±98.4 ft) Altitude: 1432 ft (±39.4 ft) Datum: WGS-84 Azimuth/Bearing: 116° S01E 2110mils True (±10°) Elevation Angle: -10.9° Horizon Angle: -00.8° Zoom: 1.0X Sta#11990+00 to 11995+00- Landowner has mowed row for cattle feed.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11989+00		Field Station#	11990+00	
Pic 5 Desc.	AR-266.00 - Access road & rock checks.		Pic 6 Desc.	Landowner has mowed row for cattle feed, sta#11990+00 to 11995+00	

A/E	124300137	Date/Time	6/2/2020 1:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	6/2/2020 1:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11512
Inspector	Jared Saunders			Date/Time	6/2/2020 2:45 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Partial	Station End	11788+52
County	Montgomery	Ground	Dry	Temperature (°F)	82.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/2/2020 2:45 PM	Report #	11512
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 219.6 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		6/2/2020 2:45 PM		Report #			
Pictures											
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11687+40						Field Station#		11767+00	
Pic 1 Desc.		Sensitive resource buffer in place at stream S-MN21.						Pic 2 Desc.		RCE in place at Main Line Valve 26.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11772+00						Field Station#		11665+00	
Pic 3 Desc.		Clean water diversion pipe inlet and clean water diversion berm in place.						Pic 4 Desc.		ROW is stabilized with vegetation growth.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11649+00						Field Station#		11620+00	
Pic 5 Desc.		Slope drain in place with rock inlet and outlet to minimize erosion on two-tone.						Pic 6 Desc.		Clean water diversion pipe and plunge pool in place.	

A/E	124300137	Date/Time	6/2/2020 2:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/2/2020 2:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11515
Inspector	Chris Burns			Date/Time	6/2/2020 2:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+99
County	Montgomery	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/2/2020 2:59 PM	Report #	11515
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.3 to MP 225.3 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/2/2020 2:59 PM	Report #	
Pictures					
<p>Date & Time: Tue Jun 02, 2020 08:28:32 EDT Position: +037 237252 / -080 359449 (+213.5ft) Altitude: 2154ft (+22.2ft) Datum: WGS 84 Azimuth/Bearing: 083 N83E 1676mils True (+17.1) Elevation Angle: +05.0 Horizon Angle: +00.5 Zoom: 0.5x 11792+00</p> 		<p>Date & Time: Tue Jun 02, 2020 08:35:32 EDT Position: +037 239111 / -080 355835 (+474.4ft) Altitude: 2095ft (+201.8ft) Datum: WGS 84 Azimuth/Bearing: 073 N73E 1298mils True (+12.1) Elevation Angle: +02.2 Horizon Angle: +00.0 Zoom: 0.5x 11806+00</p> 			
GPS Location	1	GPS Location	2		
Field Station#	11792+00	Field Station#	11806+00		
Pic 1 Desc.	Section of restored RoW showing conditions and controls.		Pic 2 Desc.	Section of restored RoW showing conditions and controls.	
<p>Date & Time: Tue Jun 02, 2020 08:48:08 EDT Position: +037 239237 / -080 353807 (+1968.0ft) Altitude: 2223ft (+27.7ft) Datum: WGS 84 Azimuth/Bearing: 191 S19W 3449mils True (+12.1) Elevation Angle: +03.0 Horizon Angle: +02.4 Zoom: 0.5x 11828+00</p> 		<p>Date & Time: Tue Jun 02, 2020 08:53:02 EDT Position: +037 239076 / -080 348773 (+1076.5ft) Altitude: 2176ft (+89.2ft) Datum: WGS 84 Azimuth/Bearing: 192 S12W 3413mils True (+12.1) Elevation Angle: +01.9 Horizon Angle: +02.4 Zoom: 0.5x 11841+00</p> 			
GPS Location	3	GPS Location	4		
Field Station#	11828+00	Field Station#	11841+00		
Pic 3 Desc.	Section of restored RoW showing conditions and controls.		Pic 4 Desc.	Section of restored RoW showing conditions and controls.	
<p>Date & Time: Tue Jun 02, 2020 09:02:26 EDT Position: +037 239272 / -080 344193 (+20.7ft) Altitude: 2188ft (+25.5ft) Datum: WGS 84 Azimuth/Bearing: 315 N45W 5400mils True (+12.1) Elevation Angle: +07.1 Horizon Angle: +00.8 Zoom: 1.0x P-KL2</p> 		<p>Date & Time: Tue Jun 02, 2020 09:18:33 EDT Position: +037 239225 / -080 337922 (+1732.3ft) Altitude: 2193ft (+27.9ft) Datum: WGS 84 Azimuth/Bearing: 051 N51E 0907mils True (+12.1) Elevation Angle: +03.6 Horizon Angle: +02.8 Zoom: 1.0x 11892+00</p> 			
GPS Location	5	GPS Location	6		
Field Station#	11863+65	Field Station#	11892+00		
Pic 5 Desc.	P-KL2 and controls.		Pic 6 Desc.	Section of restored RoW showing conditions and controls.	

A/E	124300137	Date/Time	6/2/2020 2:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/2/2020 2:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11519
Inspector	Garrett Barclay			Date/Time	6/2/2020 4:05 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Dry	Temperature (°F)	71.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/2/2020 4:05 PM	Report #	11519
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 218 - MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/2/2020 4:05 PM	Report #	
Pictures					
 <p>Date & Time: Tue, Jun 02, 2020 08:37:17 EDT Position: +037°10'53.02" / -080°25'9.42" (+15.3N) Altitude: 2340ft (+11.5N) Datum: WGS-84 Azimuth/Bearing: 132° S44E 32.8mils True (+15.1) Elevation Grade: -019 Horizon Grade: -002 Zoom: 1.0x 11530</p>		 <p>Date & Time: Tue, Jun 02, 2020 09:00:12 EDT Position: +037°11'12.75" / -080°24'36.13" S44E Altitude: 2340ft (+11.5N) Datum: WGS-84 Azimuth/Bearing: 344° N16W 6.11mils True (+12) Elevation Grade: -019 Horizon Grade: -002 Zoom: 1.0x 11550</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11530+00		Field Station#	11550+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
 <p>Date & Time: Tue, Jun 02, 2020 09:21:56 EDT Position: +037°19'15.26" / -080°24'44.23" (+15.4N) Altitude: 2613ft (+11.3N) Datum: WGS-84 Azimuth/Bearing: 195° S14W 33.4mils True (+12) Elevation Grade: -004 Horizon Grade: -004 Zoom: 1.0x 11575</p>		 <p>Date & Time: Tue, Jun 02, 2020 09:22:57 EDT Position: +037°19'14.35" / -080°24'43.30" (+15.4N) Altitude: 2609ft (+11.3N) Datum: WGS-84 Azimuth/Bearing: 107° S70W 30.4mils True (+12) Elevation Grade: -011 Horizon Grade: -011 Zoom: 1.0x 11578</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11575+00		Field Station#	11578+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
 <p>Date & Time: Tue, Jun 02, 2020 09:36:49 EDT Position: +037°19'22.84" / -080°24'34.51" (+15.3N) Altitude: 2107ft (+11.4N) Datum: WGS-84 Azimuth/Bearing: 154° S24E 27.73mils True (+10N) Elevation Grade: -023 Horizon Grade: -004 Zoom: 1.0x 11584</p>		 <p>Date & Time: Tue, Jun 02, 2020 09:13:29 EDT Position: +037°19'22.84" / -080°24'34.51" (+15.3N) Altitude: 2107ft (+11.4N) Datum: WGS-84 Azimuth/Bearing: 120° S40E 21.33mils True (+12) Elevation Grade: -007 Horizon Grade: -019 Zoom: 1.0x 11562</p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11584+00		Field Station#	11562+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	6/2/2020 4:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	6/2/2020 4:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11535
Inspector	Len Kruizenga			Date/Time	6/3/2020 8:14 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Waste Management	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/3/2020 8:14 AM	Report #	
Pictures					
 <p>Date & Time: Wed, Jun 03, 2020, 10:20:30 EDT Position: +037.330151° / -080.665595° (+11312.911) Altitude: 1788ft (+182.2ft) Datum: WGS-84 Azimuth/Bearing: 258° S78W 4587mils True (+26°) Elevation Angle: -04.2° Horizon Angle: -00.3° Zoom: 1.0X AR-238.00 is in acceptable condition.</p>		 <p>Date & Time: Wed, Jun 03, 2020, 10:25:40 EDT Position: +037.330151° / -080.665595° (+11312.911) Altitude: 1788ft (+182.2ft) Datum: WGS-84 Azimuth/Bearing: 310° N65W 5311mils True (+31°) Elevation Angle: -10.1° Horizon Angle: +04.8° Zoom: 1.0X LY-29- Overview of the yard.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	AR-238.00 is maintained in acceptable condition.	Pic 2 Desc.	LY-29- Overview of the yard.		
 <p>Date & Time: Wed, Jun 03, 2020, 10:26:55 EDT Position: +037.331773° / -080.705133° (+11312.911) Altitude: 1788ft (+162.2ft) Datum: WGS-84 Azimuth/Bearing: 289° N71W 5198mils True (+31°) Elevation Angle: -09.4° Horizon Angle: +01.3° Zoom: 1.0X LY-29- PPL materials storage.</p>		 <p>Date & Time: Wed, Jun 03, 2020, 10:29:04 EDT Position: +037.330151° / -080.665595° (+11312.911) Altitude: 1788ft (+182.2ft) Datum: WGS-84 Azimuth/Bearing: 308° N63W 5355mils True (+26°) Elevation Angle: -10.1° Horizon Angle: +02.4° Zoom: 1.0X LY-29- Rock surface of the yard is in acceptable condition.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	LY-29- PPL Materials storage.	Pic 4 Desc.	LY-29- The rock surface of the yard is maintained in acceptable condition.		
 <p>Date & Time: Wed, Jun 03, 2020, 10:30:59 EDT Position: +037.330266° / -080.676570° (+166.1ft) Altitude: 1694ft (+157.5ft) Datum: WGS-84 Azimuth/Bearing: 089° N89E 1592mils True (Error) Elevation Angle: -18.0° Horizon Angle: +00.6° Zoom: 1.0X LY-29- CFS triple stack perimeter controls.</p>		 <p>Date & Time: Wed, Jun 03, 2020, 10:33:36 EDT Position: +037.330151° / -080.677192° (+207.8ft) Altitude: 1748ft (+159.7ft) Datum: WGS-84 Azimuth/Bearing: 335° N25W 5956mils True (+31°) Elevation Angle: -21.1° Horizon Angle: -00.2° Zoom: 1.0X LY-29- Drainage feature and culvert are in good condition.</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	LY-29- CFS triple stack perimeter controls are in acceptable condition.	Pic 6 Desc.	LY- 29- Drainage feature and culvert are in good condition.		

A/E	124300137	Date/Time	6/3/2020 8:14 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	6/3/2020 8:14 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11544
Inspector	Jared Saunders			Date/Time	6/3/2020 1:43 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			
Secondary Containment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/3/2020 1:43 PM	Report #	11544
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/3/2020 1:43 PM	Report #	
Pictures					
<p>Date & Time: Wed Jun 03 2020 11:05:12 EDT Position: +037 318787 / -080 658371 (+18.1ft) Altitude: 1797ft (+25.4ft) Datum: WGS-84 Azimuth/Bearing: 113.547E 2009mils True (+12.1) Elevation Angle: -02.6 Horizon Angle: -03.6 Zoom: 1.0X LDY 26</p> 		<p>Date & Time: Wed Jun 03 2020 11:04:50 EDT Position: +037 318924 / -080 657733 (+21.3 ft) Altitude: 1793ft (+22.8ft) Datum: WGS-84 Azimuth/Bearing: 299. N41W 9316mils True (+12.1) Elevation Angle: -03.0 Horizon Angle: -00.2 Zoom: 1.0X LDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Dumpsters being utilized for trash management.		Pic 2 Desc.	RCE in place at entrance of lay down yard 26.	
<p>Date & Time: Wed Jun 03 2020 11:05:05 EDT Position: +037 318805 / -080 658461 (+14.0ft) Altitude: 1797ft (+25.4ft) Datum: WGS-84 Azimuth/Bearing: 222.542W 3947mils True (+12.1) Elevation Angle: -03.7 Horizon Angle: -03.7 Zoom: 1.0X LDY 26</p> 		<p>Date & Time: Wed Jun 03 2020 11:05:54 EDT Position: +037 318728 / -080 657826 (+15.4ft) Altitude: 1800ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 317. N42W 5636mils True (+12.1) Elevation Angle: -00.3 Horizon Angle: -01.0 Zoom: 1.0X LDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	18 inch compost filter sock in place along LOD.		Pic 4 Desc.	Checked staged equipment for leaks.	
<p>Date & Time: Wed Jun 03 2020 11:06:12 EDT Position: +037 318644 / -080 657686 (+15.4ft) Altitude: 1797ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 086. N86E 1529mils True (+12.1) Elevation Angle: -00.3 Horizon Angle: -00.7 Zoom: 1.0X LDY 26</p> 		<p>Date & Time: Wed Jun 03 2020 11:06:31 EDT Position: +037 318491 / -080 657631 (+15.4ft) Altitude: 1798ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 195. S15W 3667mils True (+12.1) Elevation Angle: -02.6 Horizon Angle: -02.4 Zoom: 1.0X LDY 26</p> 			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Secondary containment in place under fuel cell.		Pic 6 Desc.	Checked staged equipment for leaks.	

A/E	124300137	Date/Time	6/3/2020 1:43 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/3/2020 1:43 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11563
Inspector	Chris Burns			Date/Time	6/4/2020 7:42 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11064+53
County	Giles	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/4/2020 7:42 AM	Report #	11563
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Performed SWPPP inspection from MP 208.6 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	6/4/2020 7:42 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11025+50	Field Station#	11034+00		
Pic 1 Desc.	S-IJ18 and controls.	Pic 2 Desc.	Section of RoW showing conditions and controls.		
					
GPS Location	3	GPS Location	4		
Field Station#	11058+00	Field Station#	11049+00		
Pic 3 Desc.	Section of RoW showing conditions and controls.	Pic 4 Desc.	Section of RoW showing conditions and controls.		
					
GPS Location	5	GPS Location	6		
Field Station#	11050+10	Field Station#	11064+50		
Pic 5 Desc.	S-IJ16B/S-IJ17 and controls.	Pic 6 Desc.	Section of RoW showing conditions and controls.		

A/E	124300137	Date/Time	6/4/2020 7:42 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/4/2020 7:42 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11566
Inspector	Garrett Barclay			Date/Time	6/3/2020 7:09 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300137		Date/Time 6/3/2020 7:09 AM		Report #	
Pictures					
<p>Date & Time: Wed Jun 03 2020 09:51:13 EDT Position: +037°20'2.29" / -080°48'10.72" (+25.9ft) Altitude: 1565ft (+22.7ft) Datum: WGS-84 Azimuth/Bearing: 238.558W 4231mils True (+17.1) Elevation Grade: +001 Horizon Grade: +001 Zoom: 1.0X 28</p> 		<p>Date & Time: Wed Jun 03 2020 09:52:32 EDT Position: +037°20'2.27" / -080°48'12.32" (+33.1ft) Altitude: 1565ft (+22.7ft) Datum: WGS-84 Azimuth/Bearing: 238.558W 4231mils True (+17.1) Elevation Grade: +001 Horizon Grade: +001 Zoom: 1.0X 28</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
<p>Date & Time: Wed Jun 03 2020 09:53:31 EDT Position: +037°20'5.24" / -080°48'8.25" (+213.3ft) Altitude: 1583ft (+77.8ft) Datum: WGS-84 Azimuth/Bearing: 121.559E 2151mils True (+14.0) Elevation Grade: +000 Horizon Grade: +003 Zoom: 1.0X 28</p> 		<p>Date & Time: Wed Jun 03 2020 09:50:41 EDT Position: +037°20'2.22" / -080°48'10.50" (+101.5ft) Altitude: 1569ft (+44.2ft) Datum: WGS-84 Azimuth/Bearing: 154.154W 1564mils True (+1.0) Elevation Grade: +000 Horizon Grade: +000 Zoom: 1.0X 28</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	Secondary containment	
<p>Date & Time: Wed Jun 03 2020 09:55:54 EDT Position: +037°20'11.01" / -080°48'6.26" (+156.1ft) Altitude: 1570ft (+42.1ft) Datum: WGS-84 Azimuth/Bearing: 227.547W 4036mils True (+3.1) Elevation Grade: +005 Horizon Grade: +003 Zoom: 1.0X 28</p> 		<p>Date & Time: Wed Jun 03 2020 09:56:54 EDT Position: +037°20'11.01" / -080°48'6.26" (+156.1ft) Altitude: 1570ft (+42.1ft) Datum: WGS-84 Azimuth/Bearing: 227.547W 4036mils True (+3.1) Elevation Grade: +005 Horizon Grade: +003 Zoom: 1.0X 28</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Secondary containment		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	6/3/2020 7:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/3/2020 7:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11567
Inspector	Len Kruizenga			Date/Time	6/4/2020 8:12 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+88
State	VA	Inspection Area	Full	Station End	10930+00
County	Giles	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sump Pit	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/4/2020 8:12 AM	Report #	11567
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met at work trailer with EI's SWPPP inspection: Sta#11023+88 to 10930+00. MP-208.6 to 206.2 The row is dry and in stable condition, temporary stabilization is very good. Perimeter controls, silt fence, CFS & SSF are in acceptable condition. Water bars, sump pits and end treatments are in acceptable condition. Bat habitat ECD's are in acceptable condition. Streams S-IJ18, S-RR5, S-E24, S-E25 are in acceptable condition, stream ECD's, buffers, equipment bridges are in acceptable condition. AR-244.00 and Doe Creek RCE are in good condition. PPL environmental crew is replacing P1 perimeter controls at sta#10993+00. They will be removing P1 controls at Doe Creek Farms, sta# 10956+00 to 10950+00. The landowner continues to graze cattle on the row causing damage to ECD's.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/4/2020 8:12 AM	Report #	
Pictures					
 <p>Date & Time: Thu, Jun 04, 2020, 10:33:03 EDT Position: +037.325610 / -080.564912 (+32.0ft) Altitude: 2374ft (+39.4ft) Datum: WGS-84 Azimuth Bearing: 095° 58.4E 1707mils True (+10.1) Elevation Angle: +08.0° Horizon Angle: +01.9° Zoom: 1.0X Stream S-IJ18</p>		 <p>Date & Time: Thu, Jun 04, 2020, 10:30:59 EDT Position: +037.325610 / -080.564912 (+32.0ft) Altitude: 2374ft (+39.4ft) Datum: WGS-84 Azimuth Bearing: 286° N24W 508mils True (+10.1) Elevation Angle: +11.0° Horizon Angle: +00.9° Zoom: 1.0X Stream RRS- Bridge, buffers, controls</p>		GPS Location	See photo GPS
Field Station#	11024+00	Field Station#	11017+00	GPS Location	See photo GPS
Pic 1 Desc.	Stream S-IJ18	Pic 2 Desc.	Row and stream S-RR5		
 <p>Date & Time: Thu, Jun 04, 2020, 10:07:28 EDT Position: +037.325610 / -080.564912 (+32.0ft) Altitude: 2374ft (+39.4ft) Datum: WGS-84 Azimuth Bearing: 095° 58.4E 1707mils True (+10.1) Elevation Angle: +08.0° Horizon Angle: +01.9° Zoom: 1.0X Stream S-E25- Start 10986+00</p>		 <p>Date & Time: Thu, Jun 04, 2020, 10:04:59 EDT Position: +037.325610 / -080.564912 (+32.0ft) Altitude: 2370ft (+26.2ft) Datum: WGS-84 Azimuth Bearing: 297° N43W 528mils True (+10.1) Elevation Angle: +14.0° Horizon Angle: +00.9° Zoom: 1.0X Stream S-E24- Start 10985+00</p>		GPS Location	See photo GPS
Field Station#	10986+00	Field Station#	10985+00	GPS Location	See photo GPS
Pic 3 Desc.	Stream S- E25	Pic 4 Desc.	Stream S- E24		
 <p>Date & Time: Thu, Jun 04, 2020, 10:26:00 EDT Position: +037.325610 / -080.564912 (+32.0ft) Altitude: 2370ft (+26.2ft) Datum: WGS-84 Azimuth Bearing: 314° N45W 508mils True (+10.1) Elevation Angle: +04.0° Horizon Angle: +01.9° Zoom: 1.0X Bat habitat</p>		 <p>Date & Time: Thu, Jun 04, 2020, 10:26:00 EDT Position: +037.325610 / -080.564912 (+32.0ft) Altitude: 2370ft (+26.2ft) Datum: WGS-84 Azimuth Bearing: 301° N39W 5351mils True (+10.1) Elevation Angle: +15.3° Horizon Angle: +01.8° Zoom: 1.0X Start 10950+00 to 10956+00. The contractor will remove controls because of cattle damage</p>		GPS Location	See photo GPS
Field Station#	10965+00	Field Station#	10956+00	GPS Location	See photo GPS
Pic 5 Desc.	Bat habitat	Pic 6 Desc.	Doe Creek Farms- PPL will remove P1 from sta#10950+00 to 10956+00 has cattle continue to damage controls.		

A/E	124300137	Date/Time	6/4/2020 8:12 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	6/4/2020 8:12 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11569
Inspector	Garrett Barclay			Date/Time	6/4/2020 8:21 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+62
County	Giles	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/4/2020 8:21 AM	Report #	11569
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 205 - MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/4/2020 8:21 AM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10858+00		Field Station#	10876+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10882+00		Field Station#	10891+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	10910+00		Field Station#	10920+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	6/4/2020 8:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/4/2020 8:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11581
Inspector	Jared Saunders			Date/Time	6/4/2020 2:17 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	10750+00
County	Giles	Ground	Dry	Temperature (°F)	88.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/4/2020 2:17 PM	Report #	11581
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		6/4/2020 2:17 PM		Report #							
Pictures															
															
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				10710+00				Field Station#				10712+50			
Pic 1 Desc.				Compost filter sock checks in place along bar on access road 241.04.				Pic 2 Desc.				Sensitive resource buffer in place at stream S-G33.			
															
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				10701+00				Field Station#				10698+00			
Pic 3 Desc.				Travel lane stabilized with erosion control blanket.				Pic 4 Desc.				Sensitive resource buffer in place at stream S-G32.			
															
GPS Location				See photo for GPS location.				GPS Location				See photo for GPS location.			
Field Station#				10696+00				Field Station#				10670+00			
Pic 5 Desc.				RCE in place at Buffalo Anklets Road.				Pic 6 Desc.				Reinforced super silt fence in place along LOD.			

A/E	124300137	Date/Time	6/4/2020 2:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	6/4/2020 2:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11607
Inspector	Chris Burns			Date/Time	6/5/2020 11:44 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Damp	Temperature (°F)	79.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/5/2020 11:44 AM	Report #	11607
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Gathered rain gauge data from LDY 37 (0.3") and Pocahontas rd (0.45"). Performed stormwater inspection of LDY 37 as required. Performed SWPPP inspection from MP 213 to MP 214.8. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/5/2020 11:44 AM	Report #	
Pictures					
<p>Date & Time: Fri Jun 05, 2020, 09:33:32 EDT Position: +037.235194° / -080.49619° (±36.40m) Altitude: 2219ft (±42.0ft) Datum: WGS-84 Azimuth/Bearing: 035° N35E 0622mils True (±12°) Elevation Angle: -04.2° Horizon Angle: +05.4° Zoom: 1.0X 11265+00</p> 		<p>Date & Time: Fri Jun 05, 2020, 09:43:52 EDT Position: +037.24933° / -080.468701° (±74.2ft) Altitude: 2270ft (±66.0ft) Datum: WGS-84 Azimuth/Bearing: 028° N28E 0678mils True (±12°) Elevation Angle: -03.8° Horizon Angle: -07.4° Zoom: 1.0X 11286+00</p> 			
GPS Location	1	GPS Location	2		
Field Station#	11265+00	Field Station#	11286+00		
Pic 1 Desc.	Perimeter controls functional.		Pic 2 Desc.	Perimeter controls functional.	
<p>Date & Time: Fri Jun 05, 2020, 09:48:53 EDT Position: +037.296177° / -080.481334° (±108.9ft) Altitude: 2100ft (±36ft) Datum: WGS-84 Azimuth/Bearing: 032° S32W 4124mils True (±12°) Elevation Angle: -07.4° Horizon Angle: -00.6° Zoom: 0.5X S-JJ18</p> 		<p>Date & Time: Fri Jun 05, 2020, 10:07:56 EDT Position: +037.30035° / -080.472920° (±169.6ft) Altitude: 2039ft (±27.2ft) Datum: WGS-84 Azimuth/Bearing: 166° S16E 2916mils True (±12°) Elevation Angle: -08.5° Horizon Angle: +04.1° Zoom: 0.5X S-NN12</p> 			
GPS Location	3	GPS Location	4		
Field Station#	11292+80	Field Station#	11327+85		
Pic 3 Desc.	S-MM18 and buffers and controls.		Pic 4 Desc.	S-NN12 and controls.	
<p>Date & Time: Fri Jun 05, 2020, 10:13:44 EDT Position: +037.30439° / -080.46539° (±34.1ft) Altitude: 2078ft (±41.6ft) Datum: WGS-84 Azimuth/Bearing: 032° N32E 0569mils True (±12°) Elevation Angle: -25.1° Horizon Angle: +05.2° Zoom: 1.0X 11349+00</p> 		<p>Date & Time: Fri Jun 05, 2020, 10:21:53 EDT Position: +037.305307° / -080.467172° (±155.8ft) Altitude: 2009ft (±31.1ft) Datum: WGS-84 Azimuth/Bearing: 140° S40E 2689mils True (±12°) Elevation Angle: -25.4° Horizon Angle: +07.6° Zoom: 0.5X S-NN11</p> 			
GPS Location	5	GPS Location	6		
Field Station#	11349+00	Field Station#	11352+97		
Pic 5 Desc.	Perimeter controls functional.		Pic 6 Desc.	S-NN11 and controls.	

A/E	124300137	Date/Time	6/5/2020 11:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/5/2020 11:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11612
Inspector	Len Kruizenga			Date/Time	6/5/2020 1:51 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Full	Station End	11158+27
County	Giles	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock-lined Channel	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/5/2020 1:51 PM	Report #	11612
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with EI's at Winding Way SWPPP inspection : Sta#11254+99 to 11158+27. MP-213 to 211 The row received 0.10" of rain overnight. The row is dry and in stable condition, temporary stabilization is in acceptable condition. Water bars, sump pits, triple stack end treatments are in acceptable condition. Perimeter controls, P1 silt fence, CFS, SSF are in acceptable condition. CWD pipe and plunge pool are in good condition. Slope drain pipes are in acceptable condition. Rock channel is in acceptable condition. ACCESS roads, Winding Way, AR-249.02, AR- 249.01 are maintained in acceptable condition. Rain gauge readings: Kow Camp- 0.20" AR-244.00- 0.15" Catawba- 0.00"					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/5/2020 1:51 PM	Report #	
Pictures					
 <p>Date & Time: Fri, Jun 05, 2020, 09:06:11 EDT Position: -037.314334 / -080.527931 (-16980.11) Altitude: 1842ft (-167.4m) (-515.75) Datum: WGS-84 Azimuth/Bearing: 131° S46°E 232mils True (-10°) Elevation Angle: -18.4° Horizon Angle: +01.9° Zoom: 1.0X Sta#11232+00- Row vegetation & Controls</p>		 <p>Date & Time: Fri, Jun 05, 2020, 09:10:47 EDT Position: -037.310224 / -080.501060 (-16183.28) Altitude: 2100ft (-149.8m) (-45.72) Datum: WGS-84 Azimuth/Bearing: 187° S07°W 332mils True (-10°) Elevation Angle: -30.5° Horizon Angle: +04.9° Zoom: 1.0X Sta#11225+00- Slope drain, end treatment, rock channel</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11232+00	Field Station#	11225+00		
Pic 1 Desc.	Row vegetation and controls	Pic 2 Desc.	Slope drain, end treatment, rock channel.		
 <p>Date & Time: Fri, Jun 05, 2020, 09:31:51 EDT Position: -037.301344 / -080.509708 (-169919.68) Altitude: 2057ft (-178.2m) (-54.50) Datum: WGS-84 Azimuth/Bearing: 358° N83°W 134mils True (-10°) Elevation Angle: +00.1° Horizon Angle: +07.6° Zoom: 1.0X Sta#11203+00- CFS perimeter controls & topsoil vegetation</p>		 <p>Date & Time: Fri, Jun 05, 2020, 09:36:03 EDT Position: -037.305816 / -080.501627 (-169820.77) Altitude: 1937ft (-153.0m) (-46.89) Datum: WGS-84 Azimuth/Bearing: 205° N05°W 349mils True (-10°) Elevation Angle: +13.6° Horizon Angle: +05.9° Zoom: 1.0X Sta#11198+00- CFS & SSF perimeter controls</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11203+00	Field Station#	11198+00		
Pic 3 Desc.	CFS perimeter controls and vegetated topsoil stockpiles	Pic 4 Desc.	SSF & CFS perimeter controls		
 <p>Date & Time: Fri, Jun 05, 2020, 09:31:12 EDT Position: -037.305993 / -080.509708 (-169820.77) Altitude: 1959ft (-149.8m) (-45.72) Datum: WGS-84 Azimuth/Bearing: 345° N15°W 5187mils True (-10°) Elevation Angle: -01.1° Horizon Angle: +03.9° Zoom: 1.0X Sta#11191+00- Drainage feature & ECD's</p>		 <p>Date & Time: Fri, Jun 05, 2020, 09:36:03 EDT Position: -037.305816 / -080.501627 (-169820.77) Altitude: 1959ft (-149.8m) (-45.72) Datum: WGS-84 Azimuth/Bearing: 285° N75°W 5007mils True (-10°) Elevation Angle: -16.0° Horizon Angle: +03.9° Zoom: 1.0X Sta#11184+00- CWD pipe & plunge pool</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11191+00	Field Station#	11184+00		
Pic 5 Desc.	Drainage feature and ECD's	Pic 6 Desc.	CWD pipe and plunge pool.		

A/E	124300137	Date/Time	6/5/2020 1:51 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/5/2020 1:51 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11614
Inspector	Jared Saunders			Date/Time	6/5/2020 3:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+50
State	VA	Inspection Area	Partial	Station End	11524+50
County	Giles	Ground	Damp	Temperature (°F)	80.00
Municipality	N/A	Weather	Heavy Rain	Rain Gauge (in)	0.05
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Erosion Control Blanket	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	6/5/2020 3:03 PM	Report #	11614
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection. Checked rain gauges at Stevers Gap Road - Trace amount and at Mount Tabor Road - 0.0.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/5/2020 3:03 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11507+00		Field Station#	11505+00	
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 2 Desc.	Clean water diversion pipe and clean water diversion berm in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	11477+00	
Pic 3 Desc.	RCE in place at Stevers Gap Road.		Pic 4 Desc.	Two-tone stabilized with ECB and slope drain in place over two-tone to minimize erosion.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	11767+00	
Pic 5 Desc.	Trace amount of rain in gauge Stevers Gap Road.		Pic 6 Desc.	Rain gauge at Mount Tabor Road reads 0.0 inches.	

A/E	124300137	Date/Time	6/5/2020 3:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	6/5/2020 3:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	11620
Inspector	Garrett Barclay			Date/Time	6/5/2020 2:04 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+53
State	VA	Inspection Area	Partial	Station End	11158+27
County	Giles	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	6/5/2020 2:04 PM	Report #	11620
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 209 - MP 211.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list 1" of rain recorded @ AR 234, .2" of rain recorded @ Buffalo Anklets					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/5/2020 2:04 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11066+00		Field Station#	11085+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11101+00		Field Station#	11130+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+1	
Pic 5 Desc.	.2" of rain recorded @ AR		Pic 6 Desc.	1" of rain recorded @ AR 234	

A/E	124300137	Date/Time	6/5/2020 2:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	6/5/2020 2:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		