



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12240
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/29/2020 11:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 11:31 AM	<b>Report #</b>	12240
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met EI's at Winding Way SWPPP inspection: Sta#11254+99 to 11158+27. MP- 213 to 211 The row is dry and in stable condition, temporary stabilization is acceptable. Water bars are in stable condition. Water bar sumps and triple stack end treatments are in acceptable condition. Topsoil stockpiles are well vegetated and stable. Perimeter controls, silt fence, SSF, CFS are in acceptable condition. Slope drain pipes are in acceptable condition. CWD pipe and plunge pool are in good condition. Sensitive resource ECD's at drainage feature are in acceptable condition. Access roads, Winding Way, AR-249.02, AR-249.01 are maintained in acceptable condition. Rock channel is in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/29/2020 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12227+00		<b>Field Station#</b>	11225+00	
<b>Pic 1 Desc.</b>	Row is stable		<b>Pic 2 Desc.</b>	Slope drain, end treatment and rock channel are in acceptable condition.	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11203+00		<b>Field Station#</b>	11202+00	
<b>Pic 3 Desc.</b>	CFS perimeter controls and topsoil stockpiles are well vegetated.		<b>Pic 4 Desc.</b>	CFS and SSF perimeter controls are in acceptable condition.	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11191+00		<b>Field Station#</b>	11184+00	
<b>Pic 5 Desc.</b>	Sensitive resource ECD's and bridge.		<b>Pic 6 Desc.</b>	CWD pipe and plunge pool are in good condition.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12263
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/29/2020 2:11 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 2:11 PM	<b>Report #</b>	12263
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Performed SWPPP inspection from MP 213 to MP 214.8 as well as assessed AR 256.02. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/29/2020 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11265+00	<b>Field Station#</b>	11286+00		
<b>Pic 1 Desc.</b>	Perimeter controls functional.	<b>Pic 2 Desc.</b>	Perimeter controls functional.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11292+80	<b>Field Station#</b>	11327+85		
<b>Pic 3 Desc.</b>	S-MM18 and controls.	<b>Pic 4 Desc.</b>	S-NN12 and controls.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11349+00	<b>Field Station#</b>	11352+97		
<b>Pic 5 Desc.</b>	Perimeter controls functional.	<b>Pic 6 Desc.</b>	S-NN11 and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12268
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	6/29/2020 2:07 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 2:07 PM	<b>Report #</b>	12268
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 209 - MP 211.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list .2" of rain recorded					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 6/29/2020 2:07 PM		Report #	
Pictures					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11065+00		Field Station#	11078+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11091+00		Field Station#	11120+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11110+00		Field Station#	+1	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 2:07 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 2:07 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12287
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/30/2020 8:01 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	6/30/2020 8:01 AM	<b>Report #</b>	12287
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Sta# 12000+00 and 12001+00 the contractor has installed a cattle gap fence at the landowner's request, gates have been installed to allow row travel access.					
<b>Comments</b> (Reference above questions as appropriate.) SWPPP inspection: Sta#11899+00 to 12005+00. MP- 225.3 to 227.3 The row is dry and in stable condition. Permanent restoration is acceptable. Row in the inspection area is heavily vegetated. Perimeter controls, silt fence, CFS and SSF are in acceptable condition. Karst's and Karst ECD's are in acceptable condition. Level spreaders and water bars are in stable condition. Water bar outlet protection is in acceptable condition. Wetland at sta#12001+00 is dry and ECD's in acceptable condition. The contractor has installed a cattle gap across the row to access pasture on both sides of the row. Gates have been installed to allow row access. Fence built at sta# 12000+00 and 12001+00. ( fence built at landowner request ). AR-266.03 and AR-266.00 are maintained in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 6/30/2020 8:01 AM		Report #	
Pictures					
<p>Date &amp; Time: Tue, Jun 30, 2020, 10:15:00 EDT Position: -037.287444° / -080.331471° (-63.9444°) Altitude: 2281ft (+210.0m) Datum: WGS-84 Azimuth/Bearing: 299° N61W 5316mils True (+10°) Elevation Angle: -14.2° Horizon Angle: +02.1° Zoom: 1.0x Star#11901+00- Access road and CFS checks in the band ditch</p> 		<p>Date &amp; Time: Tue, Jun 30, 2020, 10:24:59 EDT Position: -037.283489° / -080.331471° (-63.9444°) Altitude: 2205ft (+19.7m) Datum: WGS-84 Azimuth/Bearing: 127° 53E 2258mils True (+10°) Elevation Angle: -06.9° Horizon Angle: +00.3° Zoom: 1.0x Star#11919+00- Water bar outlet protection</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11901+00		Field Station#	11919+00	
Pic 1 Desc.	AR-266.03- Access road and bar ditch CFS checks.		Pic 2 Desc.	Water bar outlet protection is in acceptable condition.	
<p>Date &amp; Time: Tue, Jun 30, 2020, 10:19:08 EDT Position: -037.277889° / -080.317081° (-61.6831°) Altitude: 2329ft (+32.8m) Datum: WGS-84 Azimuth/Bearing: 174° 50E 3099mils True (+10°) Elevation Angle: -15.4° Horizon Angle: +02.9° Zoom: 1.0x Star#11942+00- Karst ECD's</p> 		<p>Date &amp; Time: Tue, Jun 30, 2020, 10:54:23 EDT Position: -037.272944° / -080.324844° (-61.9844°) Altitude: 1809ft (+39.4m) Datum: WGS-84 Azimuth/Bearing: 253° 57W 4438mils True (+10°) Elevation Angle: +11.1° Horizon Angle: +00.2° Zoom: 1.0x Star#11970+00- Level spreaders</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11942+00		Field Station#	11970+00	
Pic 3 Desc.	Karst ECD's are in acceptable condition.		Pic 4 Desc.	Level spreaders are in good condition.	
<p>Date &amp; Time: Tue, Jun 30, 2020, 10:58:56 EDT Position: -037.269944° / -080.320000° (-62.0000°) Altitude: 1789ft (+26.2m) Datum: WGS-84 Azimuth/Bearing: 163° 51W 3333mils True (+10°) Elevation Angle: -25.5° Horizon Angle: +03.5° Zoom: 1.0x Star#11974+00- Row is dry &amp; stable and heavily vegetated</p> 		<p>Date &amp; Time: Tue, Jun 30, 2020, 12:06:49 EDT Position: -037.269944° / -080.316667° (-62.0000°) Altitude: 1602ft (+56.4m) Datum: WGS-84 Azimuth/Bearing: 221° 54W 3926mils True (+10°) Elevation Angle: -11.3° Horizon Angle: +01.3° Zoom: 1.0x Star#12001+00 to 12000+00- Cattle gap has been installed</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11974+00		Field Station#	12001+00	
Pic 5 Desc.	Row is dry and in stable condition and heavily vegetated.		Pic 6 Desc.	Cattle gap has been installed at wetland at landowner request.	



<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 8:01 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 8:01 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12294
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	6/30/2020 12:10 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			


## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 12:10 PM	<b>Report #</b>	12294
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
A VADEQ SWPPP inspection was completed today on private and JNF property at Brush Mountain. Perimeter controls are in place, functional and in good condition. Slope breakers and end treatments are in place, functional and in good condition. No erosion issues were identified. Annual grasses are turning brown. Some perennial grasses are present on JNF property. No slips located. Resource crossings are stable with ECDs in place. No environmental concerns were identified.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 6/30/2020 12:10 PM		Report #			
Pictures							
							
GPS Location		On photo		GPS Location		On photo	
Field Station#		11668+50		Field Station#		11661+00	
Pic 1 Desc.		ROW stable. Slope breakers in place and effective. Annual grasses turning brown.		Pic 2 Desc.		Perimeter controls in place and functioning.	
							
GPS Location		On photo		GPS Location		On photo	
Field Station#		11657+00		Field Station#		11634+00	
Pic 3 Desc.		Perimeter controls in place and functional.		Pic 4 Desc.		Perimeter controls in place and functional. Annual grasses turning brown.	
							
GPS Location		On photo		GPS Location		On photo	
Field Station#		11626+04		Field Station#		11614+20	
Pic 5 Desc.		S-HH18 crossing stable. Buffers and ECDs in good condition.		Pic 6 Desc.		S-RR14 crossing stable. Buffers and ECDs in good condition.	



<b>AFE</b>	124300137	<b>Date/Time</b>	6/30/2020 12:10 PM	<b>Report #</b>	
<b>Pictures</b>					
<small>           Date &amp; Time: Tue, Jun 30, 2020: 11:10:10 EDT            Position: +037.306346° / -080.402638° (±1545.7ft)            Altitude: 1910ft (±39.4ft)            Datum: WGS-84            Azimuth/Bearing: 248° S65W 4356mils Magnetic (±12°)            Elevation Angle: +12.9°            Horizon Angle: -00.8°            Zoom: 1.0X            Brush Mtn. S-006 crossing stable         </small>				Insert image here	
<b>GPS Location</b>	On photo	<b>GPS Location</b>			
<b>Field Station#</b>	11608+17	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	S-006 crossing stable. Buffers and ECDs in good condition.	<b>Pic 8 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 12:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12302
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/29/2020 3:36 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+25
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.05
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Broad-Based Dip	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 3:36 PM	<b>Report #</b>	12302
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Stevers Gap Road - 0.05 inches, Mount Tabor Road - 0.05 inches, and Catawba Road - 0.05 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/29/2020 3:36 PM	Report #	
Pictures					
 <p>Date &amp; Time: Mon, Jun 29, 2020, 09:22:44 EDT Position: +037322507 / +080425947 (+1000m) Altitude: 2265ft (+406.0m) Datum: WGS-84 Azimuth/Bearing: 005° N05E 0089mils True (±14°) Elevation Angle: -06.1° Horizon Angle: -09.0° Zoom: 1.0X 11507+00</p>		 <p>Date &amp; Time: Mon, Jun 29, 2020, 09:21:13 EDT Position: +037322507 / +080425947 (+1000m) Altitude: 2196ft (+100.0m) Datum: WGS-84 Azimuth/Bearing: 276° N27W 400mils True (±14°) Elevation Angle: -06.5° Horizon Angle: -07.9° Zoom: 1.0X 11489+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11507+00		<b>Field Station#</b>	11489+00	
<b>Pic 1 Desc.</b>	Plunge pool and clean water diversion pipe in place.		<b>Pic 2 Desc.</b>	RCE in place at Stevers Gap Road.	
 <p>Date &amp; Time: Mon, Jun 29, 2020, 09:26:22 EDT Position: +037324957 / +080431008 (+1020m) Altitude: 2150ft (+102.0m) Datum: WGS-84 Azimuth/Bearing: 361° 007W 406mils True (±12°) Elevation Angle: -00.3° Horizon Angle: -01.0° Zoom: 1.0X 11489+00</p>		 <p>Date &amp; Time: Mon, Jun 29, 2020, 09:26:22 EDT Position: +037324957 / +080431008 (+1020m) Altitude: 2150ft (+102.0m) Datum: WGS-84 Azimuth/Bearing: 227° S47W 403mils True (±13°) Elevation Angle: -07.6° Horizon Angle: -03.3° Zoom: 1.0X 11451+00 S-0012 &amp; S-0013</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11489+00		<b>Field Station#</b>	11451+00	
<b>Pic 3 Desc.</b>	Rain gauge at Stevers Gap Road reads 0.05 inches.		<b>Pic 4 Desc.</b>	Sensitive resource buffer in place at stream S-0012 and S-0013 in place.	
 <p>Date &amp; Time: Mon, Jun 29, 2020, 11:09:55 EDT Position: +037329155 / +080367881 (+142.9m) Altitude: 2012ft (+142.8m) Datum: WGS-84 Azimuth/Bearing: 005° N05E 0089mils True (±12°) Elevation Angle: -03.7° Horizon Angle: -00.8° Zoom: 1.0X 11767+00</p>		 <p>Date &amp; Time: Mon, Jun 29, 2020, 11:20:09 EDT Position: +037368877 / +080368322 (+124.9m) Altitude: 1455ft (+124.9m) Datum: WGS-84 Azimuth/Bearing: 100° S10E 1038mils True (±12°) Elevation Angle: -01.8° Horizon Angle: -00.7° Zoom: 1.0X 11990+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11990+00	
<b>Pic 5 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.05 inches.		<b>Pic 6 Desc.</b>	Rain gauge at Catawba Road reads 0.05 inches.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/29/2020 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12307
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/30/2020 2:42 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 2:42 PM	<b>Report #</b>	12307
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	6/30/2020 2:42 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11670+00		Field Station#	11710+00	
Pic 1 Desc.	Triple stack compost filter sock and priority one silt fence in place along LOD.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-MN22.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11772+00	
Pic 3 Desc.	RCE in place at Main Line Valve 26.		Pic 4 Desc.	Clean water diversion pipe inlet and clean water diversion berm in place.	
		Insert image here			
GPS Location	See photo for GPS location.		GPS Location		
Field Station#	11776+00		Field Station#		
Pic 5 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 6 Desc.		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 2:42 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 2:42 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12308
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	6/30/2020 2:41 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 2:41 PM	<b>Report #</b>	12308
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218 - MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 2:41 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11530+00		<b>Field Station#</b>	11550+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11562+00		<b>Field Station#</b>	11568+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11585+00		<b>Field Station#</b>	11589+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 2:41 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 2:41 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12311
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/30/2020 3:23 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	76.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 3:23 PM	<b>Report #</b>	12311
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.3 to MP 225.3 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Jun 30, 2020, 09:46:40 EDT  Position: +037 295971 / -080 350280 (+32.8ft)  Altitude: 2119ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 093 587E 1653mils True (+10°)  Elevation Angle: -12.9°  Horizon Angle: -02.9°  Zoom: 1.0x  Sta# 11792+00 - Row vegetation is good karst EOD site in acceptable condition.</p> 		<p>Date &amp; Time: Tue, Jun 30, 2020, 09:26:05 EDT  Position: +037 295939 / -080 351020 (+32.8ft)  Altitude: 2265ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 244 564W 4338mils True (+10°)  Elevation Angle: -12.2°  Horizon Angle: -02.9°  Zoom: 1.0x  Sta# 11821+00 - Level spreaders are in acceptable condition.</p> 			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11792+00	<b>Field Station#</b>	11821+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing karst feature controls functional.		<b>Pic 2 Desc.</b>	Water bar and level spreader functional.	
<p>Date &amp; Time: Tue, Jun 30, 2020, 09:33:20 EDT  Position: +037 291260 / -080 350280 (+32.8ft)  Altitude: 2224ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 122 549E 4247mils True (+10°)  Elevation Angle: -19.6°  Horizon Angle: -04.3°  Zoom: 1.0x  Sta# 11838+00 - CFS and SSP perimeter controls are in acceptable condition.</p> 		<p>Date &amp; Time: Tue, Jun 30, 2020, 09:49:01 EDT  Position: +037 286170 / -080 348646 (+16.4ft)  Altitude: 2191ft (+19.7ft)  Datum: WGS-84  Azimuth/Bearing: 349 N11W 6204mils True (+10°)  Elevation Angle: -18.8°  Horizon Angle: -01.3°  Zoom: 1.0x  Sta# 11856+00 - Level spreaders on slope and perimeter controls are in acceptable condition.</p> 			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11838+00	<b>Field Station#</b>	11856+00		
<b>Pic 3 Desc.</b>	Perimeter controls functional.		<b>Pic 4 Desc.</b>	Section of RoW showing conditions and controls.	
<p>Date &amp; Time: Tue, Jun 30, 2020, 09:53:38 EDT  Position: +037 285971 / -080 344320 (+16.4ft)  Altitude: 2120ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 028 N28E 0498mils True (+10°)  Elevation Angle: -17.2°  Horizon Angle: -00.9°  Zoom: 1.0x  AR-266.03 - Access road and bar ditch controls.</p> 		<p>Date &amp; Time: Tue, Jun 30, 2020, 10:10:46 EDT  Position: +037 289701 / -080 338450 (+16.4ft)  Altitude: 2288ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 100 S08E 3200mils True (+10°)  Elevation Angle: -08.0°  Horizon Angle: -00.5°  Zoom: 1.0x  AR-266.03 - Access road and bar ditch controls.</p> 			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11863+65	<b>Field Station#</b>	11899+99		
<b>Pic 5 Desc.</b>	P-KL2 and controls.		<b>Pic 6 Desc.</b>	AR 266.03 at intersection of RoW with functional controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/30/2020 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12350
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	7/1/2020 8:35 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 8:35 AM	<b>Report #</b>	12350
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at the work trailer SWPPP inspection: LY- 29 AR-238.00 - Access road servicing LY-238.00 is in acceptable condition. Culvert and drainage feature are in acceptable condition. Rock surface of the yard is maintained in acceptable condition. Triple stack CFS perimeter controls are in acceptable condition. Materials storage is acceptable. House keeping is acceptable. Yard not currently in use. No mechanical equipment stored in the yard.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137	Date/Time	7/1/2020 8:35 AM	Report #	
Pictures						
						
GPS Location		See photo GPS		GPS Location		See photo GPS
Field Station#		12005+00		Field Station#		12005+00
Pic 1 Desc.		AR-238.00 is in acceptable condition.		Pic 2 Desc.		Overview of the yard
						
GPS Location		See photo GPS		GPS Location		See photo GPS
Field Station#		12005+00		Field Station#		12005+00
Pic 3 Desc.		PPL Materials storage.		Pic 4 Desc.		Rock surface of the yard is maintained in acceptable condition.
						
GPS Location		See photo GPS		GPS Location		See photo GPS
Field Station#		12005+00		Field Station#		12005+00
Pic 5 Desc.		CFS triple stack perimeter controls are in acceptable condition.		Pic 6 Desc.		Culvert and drainage feature are in acceptable condition condition.

<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 8:35 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 8:35 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12362
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	7/1/2020 3:06 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00




1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 3:06 PM	<b>Report #</b>	12362
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 3:06 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed Jul 01, 2020 10:41:43 EDT Position: +037 319344 / -080 657624 / (+213.3ft) Altitude: 1792ft (+213.3ft) Datum: WGS-84 Azimuth/Bearing: 312° N45W 5547mils True (+13.1°) Elevation Angle: +09.8° Horizon Angle: +06.4° Zoom: 1.0x LDY 26</p>		 <p>Date &amp; Time: Wed Jul 01, 2020 10:45:00 EDT Position: +037 319310 / -080 658323 / (+100.4ft) Altitude: 1792ft (+100.4ft) Datum: WGS-84 Azimuth/Bearing: 312° N41W 5671mils True (+13.1°) Elevation Angle: +13.0° Horizon Angle: +06.4° Zoom: 1.0x LDY 26</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Triple stack compost filter sock in place around drainage.		<b>Pic 2 Desc.</b>	RCE in place at Lay Down Yard 26 entrance.	
 <p>Date &amp; Time: Wed Jul 01, 2020 10:43:13 EDT Position: +037 318785 / -080 658473 / (+22.0ft) Altitude: 1793ft (+22.0ft) Datum: WGS-84 Azimuth/Bearing: 258° 578W 4587mils True (+13.1°) Elevation Angle: +01.4° Horizon Angle: +02.0° Zoom: 1.0x LDY 26</p>		 <p>Date &amp; Time: Wed Jul 01, 2020 10:43:16 EDT Position: +037 318751 / -080 658436 / (+32.0ft) Altitude: 1791ft (+32.0ft) Datum: WGS-84 Azimuth/Bearing: 119° S41E 2116mils True (+13.1°) Elevation Angle: +09.0° Horizon Angle: +02.5° Zoom: 1.0x LDY 26</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	18 inch compost filter sock in place along LOD.		<b>Pic 4 Desc.</b>	Dumpsters being utilized for trash management.	
 <p>Date &amp; Time: Wed Jul 01, 2020 10:44:07 EDT Position: +037 318724 / -080 657797 / (+29.2ft) Altitude: 1795ft (+29.2ft) Datum: WGS-84 Azimuth/Bearing: 323° N37W 5742mils True (+13.1°) Elevation Angle: +01.6° Horizon Angle: +01.0° Zoom: 1.0x LDY 26</p>		 <p>Date &amp; Time: Wed Jul 01, 2020 10:44:20 EDT Position: +037 318471 / -080 657652 / (+19.7ft) Altitude: 1793ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 105° S45E 1887mils True (+13.1°) Elevation Angle: +00.3° Horizon Angle: +01.2° Zoom: 1.0x LDY 26</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	Checked staged equipment for leaks.		<b>Pic 6 Desc.</b>	Secondary containment in place under fuel cell.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 3:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 3:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12365
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	7/1/2020 2:23 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Secondary Containment	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 2:23 PM	<b>Report #</b>	12365
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/1/2020 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Secondary containment		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	Secondary containment	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/1/2020 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12386
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	7/2/2020 8:11 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	109+30
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 8:11 AM	<b>Report #</b>	12386
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at work trailer. SWPPP inspection: Sta#11023+80 to 10930+00. MP- 208.6 to 206.2 The row is dry and in stable condition, temporary stabilization is acceptable with good ground cover . Perimeter controls, silt fence, CFS, SSF are in acceptable condition. Water bars, sump pits and end treatments are in acceptable condition. Streams S-IJ18, S-RR5, S-E24, S-E25- Streams are in good condition with no sediment impact from the row, stream ECD's, buffers, equipment bridges and signage are in acceptable condition. Bat habitat ECD's are in acceptable condition. AR-244.00 and Doe Creek RCE are in good condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/2/2020 8:11 AM	Report #	
Pictures					
 <p>Date &amp; Time: Thu Jul 02 2020 09:41:40 EDT Position: -037.322218° / -080.553139° (-037.322218° / -80.553139°) (NAD83) Altitude: 2359ft (+157.5m) Datum: WGS-84 Azimuth/Bearing: 177.503E 3147mils True (+10°) Elevation Angle: -20.4° Horizon Angle: +02.6° Zoom: 1.0X Sta#11023+80 - Stream S-IJ18 - Equipment bridge, stream ECD's</p>		 <p>Date &amp; Time: Thu Jul 02 2020 09:47:08 EDT Position: -037.322304° / -080.556216° (-037.322304° / -80.556216°) (NAD83) Altitude: 2465ft (+92.5m) Datum: WGS-84 Azimuth/Bearing: 288.922W 5120mils True (+10°) Elevation Angle: +10.5° Horizon Angle: +03.0° Zoom: 1.0X Sta#11019+00 - Stream S-RR5 - Equipment bridge, stream ECD's</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11023+80		Field Station#	11019+00	
Pic 1 Desc.	Stream S- IJ18, bridge, ECD's, buffers and signage.		Pic 2 Desc.	Stream S-RR5, equipment bridge, buffers signage are in acceptable condition.	
 <p>Date &amp; Time: Thu Jul 02 2020 10:24:01 EDT Position: -037.322214° / -080.553139° (-037.322214° / -80.553139°) (NAD83) Altitude: 2320ft (+19.7m) Datum: WGS-84 Azimuth/Bearing: 395.921W 4027mils True (+10°) Elevation Angle: -11.7° Horizon Angle: +03.2° Zoom: 1.0X Sta#10965+00 - ECD's protecting bat habitat</p>		 <p>Date &amp; Time: Thu Jul 02 2020 10:04:30 EDT Position: -037.322214° / -080.553139° (-037.322214° / -80.553139°) (NAD83) Altitude: 2364ft (+19.7m) Datum: WGS-84 Azimuth/Bearing: 305.933W 5422mils True (+10°) Elevation Angle: -16.1° Horizon Angle: +02.1° Zoom: 1.0X Sta#10994+00 to 10969+00 - Broad view of the row</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	10965+00		Field Station#	10994+00	
Pic 3 Desc.	Bat habitat ECD's.		Pic 4 Desc.	Broad view of the row.	
 <p>Date &amp; Time: Thu Jul 02 2020 10:11:27 EDT Position: -037.322544° / -080.564769° (-037.322544° / -80.564769°) (NAD83) Altitude: 2267ft (+157.5m) Datum: WGS-84 Azimuth/Bearing: 034.587E 1833mils True (+10°) Elevation Angle: +09.3° Horizon Angle: +00.3° Zoom: 1.0X Sta#10986+00 - Stream S-E25- Equipment bridge and ECD's</p>		 <p>Date &amp; Time: Thu Jul 02 2020 10:13:16 EDT Position: -037.322541° / -080.564769° (-037.322541° / -80.564769°) (NAD83) Altitude: 2364ft (+19.7m) Datum: WGS-84 Azimuth/Bearing: 307.933W 5433mils True (+10°) Elevation Angle: -10.0° Horizon Angle: +02.3° Zoom: 1.0X Sta#10985+00 - Stream S-E24- Equipment bridge and ECD's</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	10986+00		Field Station#	10985+00	
Pic 5 Desc.	S-E25- equipment bridge, ECD's, signage & buffers are in acceptable condition		Pic 6 Desc.	S-E24- Equipment bridge, buffers, signage & ECD's are in acceptable condition	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 8:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 8:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12392
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	7/2/2020 12:46 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	79.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 12:46 PM	<b>Report #</b>	12392
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection was completed today between GI-244 and GI-245.01 access roads. The ROW in this area is heavily vegetated with no evidence of erosion. Slope breakers with end treatments are effectively controlling runoff. Perimeter controls were checked and found in place and functional. Resource crossings are stable with no visible impact discovered. ECDs and equipment bridges are weathered but surface is stable with no sediment migration. No environmental concerns were identified.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/2/2020 12:46 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Jul 02, 2020, 09:45:54 EDT Position: +037.322707° / -080.552540° (±16.4ft) Altitude: 2403ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 163° S 60E 233mils True (±10°) Elevation Angle: -15.6° Horizon Angle: -01.9° Zoom: 1.0X S-IJ16 crossing stable. ECDs in place. Equipment bridge appears in good condition. 10937+00</p>		 <p>Date &amp; Time: Thu, Jul 02, 2020, 09:47:48 EDT Position: +037.322707° / -080.552540° (±16.4ft) Altitude: 2403ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 120° S 60E 213mils True (±10°) Elevation Angle: -14.6° Horizon Angle: -01.9° Zoom: 1.0X S-IJ18 crossing stable. ECDs in place. Equipment bridge appears in good condition. 10933+50</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	10937+00	<b>Field Station#</b>	10933+50		
<b>Pic 1 Desc.</b>	Perimeter controls in place and functional.	<b>Pic 2 Desc.</b>	S-IJ18 crossing is stable with ECDs in place. No visible impact to resource.		
 <p>Date &amp; Time: Thu, Jul 02, 2020, 10:11:31 EDT Position: +037.319000° / -080.550417° (±32.8ft) Altitude: 2312ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 150° S 60E 234mils True (±10°) Elevation Angle: -42.7° Horizon Angle: -02.3° Zoom: 1.0X ROW well vegetated. Perimeter controls in place. 11034+00</p>		 <p>Date &amp; Time: Thu, Jul 02, 2020, 10:11:31 EDT Position: +037.319000° / -080.550417° (±32.8ft) Altitude: 2312ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 151° N 60W 424mils True (±10°) Elevation Angle: -26.1° Horizon Angle: -01.2° Zoom: 1.0X Slope breakers and perimeter controls in place and functional. ROW stable. 11042+00</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11034+00	<b>Field Station#</b>	11042+00		
<b>Pic 3 Desc.</b>	Perimeter controls are in place and functional.	<b>Pic 4 Desc.</b>	No sediment migration. Perimeter controls in place.		
 <p>Date &amp; Time: Thu, Jul 02, 2020, 10:51:38 EDT Position: +037.318445° / -080.545512° (±18.6ft) Altitude: 2095ft (±25.4ft) Datum: WGS-84 Azimuth/Bearing: 130° S 50E 231mils True (±25°) Elevation Angle: -15.6° Horizon Angle: -04.4° Zoom: 1.0X S-IJ16B crossing stable. 11050+00</p>		 <p>Date &amp; Time: Thu, Jul 02, 2020, 10:51:38 EDT Position: +037.318445° / -080.545512° (±18.6ft) Altitude: 2095ft (±25.4ft) Datum: WGS-84 Azimuth/Bearing: 268° S 88W 474mils True (±35°) Elevation Angle: -02.2° Horizon Angle: -00.9° Zoom: 1.0X ROW stable. No erosion detected. Sedimented. 11050+00</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11050+00	<b>Field Station#</b>	11050+00		
<b>Pic 5 Desc.</b>	S-IJ16B crossing stable. Equipment mats to be checked by contractor for soundness.	<b>Pic 6 Desc.</b>	ROW well vegetated. Slope breakers effective. No erosion occurring.		



<b>AFE</b>	124300137	<b>Date/Time</b>	7/2/2020 12:46 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11054+00	<b>Field Station#</b>	11053+00		
<b>Pic 7 Desc.</b>	Perimeter controls in place and in acceptable condition.	<b>Pic 8 Desc.</b>	Worn P1 silt fence was replaced in this area recently. No sediment movement discovered.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11055+50	<b>Field Station#</b>	11064+53		
<b>Pic 9 Desc.</b>	End treatments are functioning as designed.	<b>Pic 10 Desc.</b>	Equipment bridge at access road GI-245.01. ROW stable with environmental controls in place.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 12:46 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12396
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	7/2/2020 3:04 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 3:04 PM	<b>Report #</b>	12396
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/2/2020 3:04 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00		<b>Field Station#</b>	10712+50	
<b>Pic 1 Desc.</b>	Compost filter sock checks in place along access road 241.04 in bar ditch.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G33.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00		<b>Field Station#</b>	10701+00	
<b>Pic 3 Desc.</b>	ROW is stabilized with natural vegetation growth.		<b>Pic 4 Desc.</b>	ECB is stalled in travel lane with vegetation growth for stabilization.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10698+00		<b>Field Station#</b>	10695+00	
<b>Pic 5 Desc.</b>	Sensitive resource buffer in place at stream S-G32.		<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 3:04 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 3:04 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12403
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	7/2/2020 1:59 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 1:59 PM	<b>Report #</b>	12403
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 205 - MP 207 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/2/2020 1:59 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10858+00		<b>Field Station#</b>	10862+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10876+00		<b>Field Station#</b>	10893+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10902+00		<b>Field Station#</b>	10915+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 1:59 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/2/2020 1:59 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12414
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	7/3/2020 8:05 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 8:05 AM	<b>Report #</b>	12414
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with EI's at Winding Way.</p> <p>SWPPP inspection: Sta#11254+99 to 11353+67 MP- 213 to 215</p> <p>The row in this inspection area is dry and in stable condition, temporary stabilization is acceptable.</p> <p>Water bars and sump pits and end treatments are in acceptable condition.</p> <p>Slope drain pipes are in acceptable condition.</p> <p>CWD pipe and plunge pools are in acceptable condition.</p> <p>Perimeter controls, silt fence, CFS and SSF are in acceptable condition.</p> <p>Streams, equipment bridges, buffers and controls are in acceptable condition.</p> <p>Access roads are maintained in acceptable condition.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	7/3/2020 8:05 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Jul 03, 2020, 08:59:45 EDT  Position: +037 293304 / -080 493116 (±32.000)  Altitude: 2031ft (±39.4ft)  Datum: WGS-84  Azimuth/Bearing: 118° 54'22" N81E 209m/mils True (±10°)  Elevation Angle: +10.9°  Horizon Angle: +00.9°  Zoom: 1.0X  Sta#11258+00- Perimeter controls, triple stack end treatments, water bars.</p> 		<p>Date &amp; Time: Fri, Jul 03, 2020, 08:58:45 EDT  Position: +037 294153 / -080 492649 (±39.8ft)  Altitude: 2090ft (±38.4ft)  Datum: WGS-84  Azimuth/Bearing: 211° 53'10" N31W 375ft/mils True (±10°)  Elevation Angle: +39.1°  Horizon Angle: +04.9°  Zoom: 1.0X  Sta#11279+00- Water bar slope drain &amp; plunge pool.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11258+00		<b>Field Station#</b>	11279+00	
<b>Pic 1 Desc.</b>	Perimeter controls, slope drains, water bars, sump pits and end treatments are in acceptable condition		<b>Pic 2 Desc.</b>	Slope drain, end treatment.	
<p>Date &amp; Time: Fri, Jul 03, 2020, 09:09:00 EDT  Position: +037 295774 / -080 481816 (±32.000)  Altitude: 2310ft (±26.2ft)  Datum: WGS-84  Azimuth/Bearing: 081° N81E 1440m/mils True (±10°)  Elevation Angle: +13.8°  Horizon Angle: +01.2°  Zoom: 1.0X  Sta#11284+00- Broad view of the row.</p> 		<p>Date &amp; Time: Fri, Jul 03, 2020, 09:09:00 EDT  Position: +037 295890 / -080 481816 (±30.0ft)  Altitude: 2020ft (±210.0ft)  Datum: WGS-84  Azimuth/Bearing: 086° N86E 1469m/mils True (±10°)  Elevation Angle: +22.4°  Horizon Angle: +04.0°  Zoom: 1.0X  Sta#11292+00- Stream and stream ECD's</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11284+00		<b>Field Station#</b>	11292+00	
<b>Pic 3 Desc.</b>	Broad view of the row		<b>Pic 4 Desc.</b>	Stream and stream ECD's	
<p>Date &amp; Time: Fri, Jul 03, 2020, 09:25:30 EDT  Position: +037 298015 / -080 475412 (±32.8ft)  Altitude: 2168ft (±59.6ft)  Datum: WGS-84  Azimuth/Bearing: 054° N56E 0996m/mils True (±25°)  Elevation Angle: +20.5°  Horizon Angle: +00.7°  Zoom: 1.0X  Sta#11326+00- Stream and stream ECD's.</p> 		<p>Date &amp; Time: Fri, Jul 03, 2020, 09:25:30 EDT  Position: +037 298268 / -080 475412 (±30.4ft)  Altitude: 2039ft (±26.2ft)  Datum: WGS-84  Azimuth/Bearing: 027° N27E 0480m/mils True (±33°)  Elevation Angle: +28.7°  Horizon Angle: +03.4°  Zoom: 1.0X  Sta#11352+00- Stream and stream ECD's.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11326+00		<b>Field Station#</b>	11352+00	
<b>Pic 5 Desc.</b>	Stream and stream ECD's		<b>Pic 6 Desc.</b>	Stream and stream ECD's.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 8:05 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 8:05 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12421
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	7/3/2020 11:27 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11158+27
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	79.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 11:27 AM	<b>Report #</b>	12421
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a regular scheduled VADEQ SWPPP inspection. The ROW is currently stable with ECDs installed as required. Perimeter controls were inspected, found in place and working as designed. No maintenance needs were identified. Slope breakers and end treatments are controlling runoff properly and in good condition. No erosion is occurring and no slips were located. RCEs are in good condition. No housekeeping issues were identified. No evidence of vandalism located.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 11:27 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11236+25	<b>Field Station#</b>	11217+00		
<b>Pic 1 Desc.</b>	ROW stable. Perimeter controls in place and working properly.	<b>Pic 2 Desc.</b>	End treatments effective		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11195+00	<b>Field Station#</b>	11191+00		
<b>Pic 3 Desc.</b>	Perimeter controls working as designed	<b>Pic 4 Desc.</b>	ROW stable. ECDs in place and effective.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11175+00	<b>Field Station#</b>	11160+00		
<b>Pic 5 Desc.</b>	Intake free from obstruction.	<b>Pic 6 Desc.</b>	ROW well vegetated and stable.		

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 11:27 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 11:27 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12426
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	7/3/2020 3:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 3:12 PM	<b>Report #</b>	12426
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 209 - MP 211 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11066+00		<b>Field Station#</b>	1132+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11077+00		<b>Field Station#</b>	11082+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11109+00		<b>Field Station#</b>	11138+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	12642
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	7/3/2020 2:57 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+25
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00




1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 2:57 PM	<b>Report #</b>	12642
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		7/3/2020 2:57 PM		Report #			
Pictures											
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11493+00						Field Station#		11489+00	
Pic 1 Desc.		Slope drain with rock inlet in place.						Pic 2 Desc.		RCE at Stevers Gap Road in place.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11488+00						Field Station#		11487+00	
Pic 3 Desc.		Rock lined channel in place.						Pic 4 Desc.		Plunge pool in place.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11496+00						Field Station#		11494+00	
Pic 5 Desc.		Waterbar, sump pit, and waterbar end treatment in place.						Pic 6 Desc.		ROW is stabilized with thick vegetation growth.	

<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 2:57 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	7/3/2020 2:57 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		