



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13489
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/10/2020 8:23 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 8:23 AM	<b>Report #</b>	13489
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	8/10/2020 8:23 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon Aug 10 2020 08:39:05 EDT  Position: +037.333135 / -080.803118 (±35.4ft)  Altitude: 1534ft (±62.7ft)  Datum: WGS-84  Azimuth/Bearing: 224.554W 4160mils True (±13.1)  Elevation Grade: +008%  Horizon Grade: +004%  Zoom: 1.0X  28</p> 		<p>Date &amp; Time: Mon Aug 10 2020 08:42:07 EDT  Position: +037.333745 / -080.803118 (±88.9ft)  Altitude: 1562ft (±57.5ft)  Datum: WGS-84  Azimuth/Bearing: 013.113E 0231mils True (±14.1)  Elevation Grade: +008%  Horizon Grade: +005%  Zoom: 1.0X  28</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Mon Aug 10 2020 08:50:23 EDT  Position: +037.333134 / -080.803150 (±15.1ft)  Altitude: 1534ft (±62.7ft)  Datum: WGS-84  Azimuth/Bearing: 182.143W 4330mils (±27°)  Elevation Grade: +000%  Horizon Grade: +003%  Zoom: 1.0X  28</p> 		<p>Date &amp; Time: Mon Aug 10 2020 08:55:43 EDT  Position: +037.336182 / -080.804330 (±15.2ft)  Altitude: 1556ft (±11.4ft)  Datum: WGS-84  Azimuth/Bearing: +002.4230mils (±12.1)  Elevation Grade: +001%  Horizon Grade: +001%  Zoom: 1.0X  28</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Secondary containment		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Mon Aug 10 2020 08:54:32 EDT  Position: +037.333912 / -080.803158 (±15.1ft)  Altitude: 1558ft (±11.4ft)  Datum: WGS-84  Azimuth/Bearing: -046.0818mils (±12.1)  Elevation Grade: +488%  Horizon Grade: +004%  Zoom: 1.0X  28</p> 		<p>Date &amp; Time: Mon Aug 10 2020 08:55:57 EDT  Position: +037.334260 / -080.803227 (±15.1ft)  Altitude: 1563ft (±11.5ft)  Datum: WGS-84  Azimuth/Bearing: +105.41867mils (±12.1)  Elevation Grade: +2415%  Horizon Grade: +001%  Zoom: 1.0X  28</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 8:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 8:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13455
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/10/2020 9:08 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 9:08 AM	<b>Report #</b>	13455
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at the work trailer. SWPPP inspection: LY-29 CFS triple stack perimeter controls are in acceptable condition. AR-238.00, the access road serving LY-29 is maintained in acceptable condition. The rock surface of the yard is maintained in acceptable condition. Culvert and drainage feature are in acceptable condition. House keeping is acceptable. Waste management is acceptable. There are no mechanical equipment stored in the yard.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	8/10/2020 9:08 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Aug 10, 2020, 09:42:13 EDT  Position: -037.344983° / -080.672160° (-32.8ft)  Altitude: 1628ft (-39.4ft)  Datum: WGS-84  Azimuth/Bearing: 227° S47W 403mils True (-26°)  Elevation Angle: -05.7°  Horizon Angle: -00.4°  Zoom: 1.0X  LY-238.00- Access road serving LY-29</p> 		<p>Date &amp; Time: Mon, Aug 10, 2020, 09:45:58 EDT  Position: -037.344983° / -080.674607° (-30.4ft)  Altitude: 1240ft (-45.2ft)  Datum: WGS-84  Azimuth/Bearing: 280° S00W 444mils True (-26°)  Elevation Angle: -05.8°  Horizon Angle: -00.7°  Zoom: 1.0X  LY-229- View of the yard from above.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	AR-238.00- Access road serving LY-29.	<b>Pic 2 Desc.</b>	LY-29- View of the yard from above.		
<p>Date &amp; Time: Mon, Aug 10, 2020, 09:49:21 EDT  Position: -037.362229° / -080.677007° (-16.4ft)  Altitude: 1725ft (-13.1ft)  Datum: WGS-84  Azimuth/Bearing: 259° S79W 440mils True (-33°)  Elevation Angle: -07.5°  Horizon Angle: -00.7°  Zoom: 1.0X  LY-29- Arnold's material storage.</p> 		<p>Date &amp; Time: Mon, Aug 10, 2020, 09:50:01 EDT  Position: -037.362229° / -080.674607° (-30.4ft)  Altitude: 1658ft (-35.2ft)  Datum: WGS-84  Azimuth/Bearing: 295° N65W 524mils True (-20°)  Elevation Angle: -08.4°  Horizon Angle: -01.3°  Zoom: 1.0X  LY-29- CFS triplestack perimeter control.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY-29- Arnold's materials storage.	<b>Pic 4 Desc.</b>	LY-29- CFS triple stack perimeter controls.		
<p>Date &amp; Time: Mon, Aug 10, 2020, 09:54:48 EDT  Position: -037.363787° / -080.676374° (-16.4ft)  Altitude: 1710ft (-35.2ft)  Datum: WGS-84  Azimuth/Bearing: 335° N35W 611mils True (-22°)  Elevation Angle: -07.6°  Horizon Angle: -03.0°  Zoom: 1.0X  LY-29- Pipe stored in the yard.</p> 		<p>Date &amp; Time: Mon, Aug 10, 2020, 09:56:52 EDT  Position: -037.363787° / -080.674658° (-16.4ft)  Altitude: 1688ft (-19.7ft)  Datum: WGS-84  Azimuth/Bearing: 322° N18W 611mils True (-22°)  Elevation Angle: -15.9°  Horizon Angle: -01.6°  Zoom: 1.0X  LY-29- Culvert and drainage feature.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	LY-29- Pipe stored in the yard.	<b>Pic 6 Desc.</b>	LY-29- Culvert and drainage feature.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 9:08 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 9:08 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13473
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/10/2020 2:59 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 2:59 PM	<b>Report #</b>	13473
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 2:59 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Triple stack compost filter sock in place around drainage.		<b>Pic 2 Desc.</b>	RCE in place at LDY 26 entrance.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Checked staged equipment for leaks.		<b>Pic 4 Desc.</b>	Secondary containment in place under fuel cell.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	Checked staged equipment for leaks.		<b>Pic 6 Desc.</b>	Dumpsters being utilized for trash management.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 2:59 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2020 2:59 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13490
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/11/2020 8:36 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 8:36 AM	<b>Report #</b>	13490
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at work trailer SWPPP inspection: Sta#11023+88 to 10930+00. MP-208.6 to 206.2 Streams S- IJ18, at AR-244, S- RR5, S- E24, S- E25 are in good condition, ECD's, equipment bridge's, buffers and signage are in acceptable condition. AR-244.00 and Doe Creek RCE are maintained in acceptable condition. Temporary stabilization is acceptable, vegetation is acceptable. Perimeter controls, silt fence, CFS, & SSF are in acceptable condition. Water bars, sump pits and end treatments are in acceptable condition. Sensitive resource area is in acceptable condition. There is damage to CFS and silt fence buy off road rally club at sta# 10984+00, 10977+00, 10969+00. Items will be added to the punch list.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/11/2020 8:36 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Aug 11, 2020, 09:37:18 EDT Position: +037.322193 / -080.553030 (+16.4 mi) Altitude: 2383ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 186° S00W 3200mils True (+10°) Elevation Angle: -19.4° Horizon Angle: +01.4° Zoom: 1.0X Sta#11023+88- Stream S-IJ18- Bridge &amp; environmental controls</p>		 <p>Date &amp; Time: Tue, Aug 11, 2020, 09:44:58 EDT Position: +037.322457 / -080.556760 (+16.4 mi) Altitude: 2413ft (+210 ft) Datum: WGS-84 Azimuth/Bearing: 286° N74W 5088mils True (+10°) Elevation Angle: -03.5° Horizon Angle: +06.7° Zoom: 1.0X Sta#11017+00- Stream S-RR5- Bridge &amp; environmental controls</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11023+88	<b>Field Station#</b>	11017+00	<b>GPS Location</b>	See photo GPS
<b>Pic 1 Desc.</b>	Stream S-IJ18- Equipment bridge, ECD's	<b>Pic 2 Desc.</b>	Sta#11017+00- Stream S-RR5		
 <p>Date &amp; Time: Tue, Aug 11, 2020, 09:45:35 EDT Position: +037.322457 / -080.556760 (+16.4 mi) Altitude: 2393ft (+36.2ft) Datum: WGS-84 Azimuth/Bearing: 307° N53W 5333mils True (+10°) Elevation Angle: -19.2° Horizon Angle: +01.3° Zoom: 1.0X Sta#10995+00 to 10995+01- Row vegetation &amp; ECD's</p>		 <p>Date &amp; Time: Tue, Aug 11, 2020, 10:12:32 EDT Position: +037.325472 / -080.566610 (+16.4 mi) Altitude: 2393ft (+52.5ft) Datum: WGS-84 Azimuth/Bearing: 300° N40W 5333mils True (+10°) Elevation Angle: -27.5° Horizon Angle: +05.5° Zoom: 1.0X Sta#10986+00- Stream S- E25- Buffers, bridge, ECD's</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	10995+00	<b>Field Station#</b>	10986+00	<b>GPS Location</b>	See photo GPS
<b>Pic 3 Desc.</b>	Row end and ECD's.	<b>Pic 4 Desc.</b>	Stream S- E25- Bridge, buffers, ECD's		
 <p>Date &amp; Time: Tue, Aug 11, 2020, 10:15:10 EDT Position: +037.325922 / -080.567725 (+16.4 mi) Altitude: 2373ft (+105 ft) Datum: WGS-84 Azimuth/Bearing: 295° N62W 5238mils True (+10°) Elevation Angle: -15.5° Horizon Angle: +03.0° Zoom: 1.0X Sta#10985+00- Stream S- E24- Buffers, bridge, ECD's</p>		 <p>Date &amp; Time: Tue, Aug 11, 2020, 10:21:09 EDT Position: +037.325922 / -080.567725 (+16.4 mi) Altitude: 2358ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 312° N48W 5527mils True (+10°) Elevation Angle: -19.4° Horizon Angle: +06.2° Zoom: 1.0X Sta#10977+00- Road rally people have opened up old fence on the travel lane.</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	10985+00	<b>Field Station#</b>	10977+00	<b>GPS Location</b>	See photo GPS
<b>Pic 5 Desc.</b>	Stream S- E24- Bridge, buffers, ECD's	<b>Pic 6 Desc.</b>	P1 silt fence removed by off road club,		



<b>AFE</b>	124300137	<b>Date/Time</b>	8/11/2020 8:36 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Tue, Aug 11, 2020 10:27:45 EDT Position: +037.327010° / -080.570290° (-s16.4ft) Altitude: 240ft (+s9.8ft) Datum: WGS-84 Azimuth/Bearing: 211° S31W 3751mils True (-s10°) Elevation Angle: -36.1° Horizon Angle: +05.9° Zoom: 1.0X Sta#10969+00: Road/rail people have damaged CFS perimeter controls.</small></p>		 <p><small>Date &amp; Time: Tue, Aug 11, 2020 10:40:26 EDT Position: +037.327026° / -080.576618° (-s16.4ft) Altitude: 2197ft (+s9.4ft) Datum: WGS-84 Azimuth/Bearing: 305° N55W 5422mils True (-s25°) Elevation Angle: -18.3° Horizon Angle: +08.3° Zoom: 1.0X Sta#10950+00: Doe Creek continue to allow cattle on the row.</small></p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10969+00	<b>Field Station#</b>	10950+00		
<b>Pic 7 Desc.</b>	CFS triple stack perimeter controls damaged by off road club.	<b>Pic 8 Desc.</b>	Doe Creek Farms continue to allow cattle to graze row.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 8:36 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13488
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/11/2020 10:15 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 10:15 AM	<b>Report #</b>	13488
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 205 - MP 207 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 10:15 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10850+00		<b>Field Station#</b>	10867+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10870+00		<b>Field Station#</b>	10910+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10891+00		<b>Field Station#</b>	109105+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 10:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 10:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13501
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/11/2020 3:06 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 3:06 PM	<b>Report #</b>	13501
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/11/2020 3:06 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Aug 11, 2020, 09:11:27 EDT  Position: +037.342737, +080.61826, +122367.0ft  Altitude: 1831ft (+155.8ft)  Datum: WGS-84  Azimuth/Bearing: 135 S45E 2400mils True (+10.1)  Elevation Angle: -07.0  Horizon Angle: -00.8  Zoom: 1.0x  10710+00</p> 		<p>Date &amp; Time: Tue, Aug 11, 2020, 09:25:12 EDT  Position: +037.342233, +080.618416, +122367.4ft  Altitude: 2290ft (+125.2ft)  Datum: WGS-84  Azimuth/Bearing: 104 S76E 1849mils True (+15.4)  Elevation Angle: -09.5  Horizon Angle: -04.4  Zoom: 1.0x  10712+50</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00		<b>Field Station#</b>	10712+50	
<b>Pic 1 Desc.</b>	CFS checks in place along AR 241.04.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G33.	
<p>Date &amp; Time: Tue, Aug 11, 2020, 09:45:45 EDT  Position: +037.348616, +080.647963, +12257ft  Altitude: 2296ft (+43.0ft)  Datum: WGS-84  Azimuth/Bearing: 262 S82W 4458mils True (+12.1)  Elevation Angle: -05.1  Horizon Angle: -00.2  Zoom: 1.0x  10710+00</p> 		<p>Date &amp; Time: Tue, Aug 11, 2020, 11:12:22 EDT  Position: +037.348876, +080.651494, +1215.5ft  Altitude: 2120ft (+1.1ft)  Datum: WGS-84  Azimuth/Bearing: 294 N86W 522mils True (+12.1)  Elevation Angle: -30.2  Horizon Angle: -00.4  Zoom: 1.0x  10701+00</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00		<b>Field Station#</b>	10701+00	
<b>Pic 3 Desc.</b>	ROW stabilized with natural vegetation.		<b>Pic 4 Desc.</b>	Waterbar in place across travel lane.	
<p>Date &amp; Time: Tue, Aug 11, 2020, 11:53:22 EDT  Position: +037.349244, +080.652867, +12155ft  Altitude: 2633ft (+11.3ft)  Datum: WGS-84  Azimuth/Bearing: 114 S45E 2052mils True (+10.2)  Elevation Angle: -04.0  Horizon Angle: -01.7  Zoom: 1.0x  10698+00 S-G32</p> 		<p>Date &amp; Time: Tue, Aug 11, 2020, 11:53:18 EDT  Position: +037.349244, +080.652867, +12155ft  Altitude: 2633ft (+11.3ft)  Datum: WGS-84  Azimuth/Bearing: 118 S42E 2098mils True (+10.1)  Elevation Angle: -07.1  Horizon Angle: -04.2  Zoom: 1.0x  10696+00</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10698+00		<b>Field Station#</b>	10696+00	
<b>Pic 5 Desc.</b>	Sensitive resource buffer in place at stream S-G32.		<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 3:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 3:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13502
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/11/2020 3:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	88.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Energy Dissipater	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 3:12 PM	<b>Report #</b>	13502
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.78 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Reviewed project documents.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Aug 11, 2020, 08:56:50 EDT Position: +037.102286, -080.551529, 1-451.2ft Altitude: 2344ft (724m) Datum: WGS84 Azimuth/Bearing: 025.1 SSW 459mils True (±12.1) Elevation/Angle: 0.0° Horizon Angle: 01.0° Zoom: 0.5X Scale: 11025+50</p>		 <p>Date &amp; Time: Tue, Aug 11, 2020, 08:41:12 EDT Position: +037.102286, -080.551529, 1-451.2ft Altitude: 2344ft (724m) Datum: WGS84 Azimuth/Bearing: 025.1 SSW 459mils True (±12.1) Elevation/Angle: 0.0° Horizon Angle: 01.0° Zoom: 0.5X Scale: 11027+50</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11025+50	<b>Field Station#</b>	11027+50		
<b>Pic 1 Desc.</b>	S-IJ18 and controls.	<b>Pic 2 Desc.</b>	Perimeter controls functional.		
 <p>Date &amp; Time: Tue, Aug 11, 2020, 08:43:49 EDT Position: +037.101217, -080.550791, 1-222.4ft Altitude: 2368ft (721m) Datum: WGS84 Azimuth/Bearing: 159.3 S01E 3182mils True (±12.1) Elevation/Angle: 00.3° Horizon Angle: +02.3° Zoom: 0.5X Scale: 11034+00</p>		 <p>Date &amp; Time: Tue, Aug 11, 2020, 09:01:14 EDT Position: +037.101023, -080.547265, 1-109.0ft Altitude: 2090ft (637m) Datum: WGS84 Azimuth/Bearing: 002.1 N2SE 0444mils True (±12.1) Elevation/Angle: +12.5° Horizon Angle: +02.1° Zoom: 0.5X Scale: S-IJ16B/S-IJ17</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11034+00	<b>Field Station#</b>	11050+10		
<b>Pic 3 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 4 Desc.</b>	S-IJ16B/S-IJ17 and controls.		
 <p>Date &amp; Time: Tue, Aug 11, 2020, 08:59:16 EDT Position: +037.115156, -080.566279, 1-444.9ft Altitude: 2184ft (666m) Datum: WGS84 Azimuth/Bearing: 159.3 S01E 359mils True (±12.1) Elevation/Angle: 0.0° Horizon Angle: +02.0° Zoom: 0.5X Scale: 11055+00</p>		 <p>Date &amp; Time: Tue, Aug 11, 2020, 09:05:09 EDT Position: +037.115156, -080.566148, 1-458.2ft Altitude: 2175ft (663m) Datum: WGS84 Azimuth/Bearing: 306.1 N6W 5640mils True (±12.1) Elevation/Angle: +18.4° Horizon Angle: 04.5° Zoom: 1.0X Scale: 11064+50</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11055+00	<b>Field Station#</b>	11064+50		
<b>Pic 5 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13524
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/12/2020 8:37 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar End Treatment	Acceptable			



## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 8:37 AM	<b>Report #</b>	13524
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at Winding Way. SWPPP inspection: Sta#11254+99 to 11158+27. MP- 213 to 211 The inspection area received 0.40" of rain overnight, the row was muddy and slick. Water bars, sump pits, and end treatments are in acceptable condition. Perimeter controls, silt fence, CFS, SSF are in acceptable condition. Sta#11191+00- Silt fence stakes are broken off, the contractor has been notified, issue will be added to the punch list. Temporary stabilization is acceptable. Slope drain pipes are in acceptable condition. CWD pipe and plunge pool are in good condition condition. Topsoil stockpiles are well vegetated. Access roads, Winding Way, AR-249.02, AR-249.01 are in acceptable condition, rock check dams are in acceptable condition. Rain event was spotty with rain accumulations from 0.45" to 0.00".					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/12/2020 8:37 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed Aug 12, 2020, 09:07:48 EDT  Position: +037.301184° / -080.500949° (+32.8m)  Altitude: 2130ft (+26.2m)  Datum: WGS-84  Azimuth/Bearing: 120° S40E 263mils True (+2.4)  Elevation Angle: -09.8  Horizon Angle: -00.0  Zoom: 1.0X  Sta#11228+00- Row and topsoil stock pile vegetation.</p> 		<p>Date &amp; Time: Wed Aug 12, 2020, 09:12:16 EDT  Position: +037.301540° / -080.502619° (+32.8m)  Altitude: 2085ft (+105.0m)  Datum: WGS-84  Azimuth/Bearing: 180° S00E 320mils True (+10)  Elevation Angle: -25.5  Horizon Angle: +03.5  Zoom: 1.0X  Sta#11225+00- Slope drain pipe, end treatment &amp; rock channel.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11228+00	<b>Field Station#</b>	11225+00		
<b>Pic 1 Desc.</b>	Row and topsoil stockpiles vegetation.	<b>Pic 2 Desc.</b>	Slope drain pipe, end treatment, rock channel.		
<p>Date &amp; Time: Wed Aug 12, 2020, 09:38:08 EDT  Position: +037.305224° / -080.507132° (+32.8m)  Altitude: 2061ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 162° S18E 288mils True (+10)  Elevation Angle: -22.4  Horizon Angle: -00.9  Zoom: 1.0X  Sta#11201+00- Water bars on slope, are stable.</p> 		<p>Date &amp; Time: Wed Aug 12, 2020, 09:41:16 EDT  Position: +037.306390° / -080.509849° (+32.8m)  Altitude: 1967ft (+78.7ft)  Datum: WGS-84  Azimuth/Bearing: 282° N77W 503mils True (+10)  Elevation Angle: -20.9  Horizon Angle: +05.3  Zoom: 1.0X  Sta#11191+00- Drainage feature &amp; ECD's</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11201+00	<b>Field Station#</b>	11191+00		
<b>Pic 3 Desc.</b>	Water bars on slope.	<b>Pic 4 Desc.</b>	Drainage feature and ECD's		
<p>Date &amp; Time: Wed Aug 12, 2020, 09:45:00 EDT  Position: +037.306414° / -080.507807° (+32.8m)  Altitude: 2030ft (+315.6ft)  Datum: WGS-84  Azimuth/Bearing: 224° S26W 4018mils Tr  Elevation Angle: -36.2  Horizon Angle: +13.2  Zoom: 1.0X  Sta#11191+00- Drainage feature &amp; ECD's  P1 stakes broken off</p> 		<p>Date &amp; Time: Wed Aug 12, 2020, 09:50:35 EDT  Position: +037.309533° / -080.511735° (+32.8m)  Altitude: 1967ft (+78.7ft)  Datum: WGS-84  Azimuth/Bearing: 282° N78W 5013mils True (+10)  Elevation Angle: -17.7  Horizon Angle: -07.2  Zoom: 1.0X  Sta#11184+00- CWD pipe and plunge pool.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11191+00	<b>Field Station#</b>	11184+00		
<b>Pic 5 Desc.</b>	Three P1 silt fence stakes broken off at drainage feature	<b>Pic 6 Desc.</b>	CWD pipe and plunge pool.		



<b>AFE</b>	124300137	<b>Date/Time</b>	8/12/2020 8:37 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11184+50		<b>Field Station#</b>	11989+00	
<b>Pic 7 Desc.</b>	AR-249.02 - Access road & rock check dams		<b>Pic 8 Desc.</b>	Catawba rain gauge reading- 0.00"	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 8:37 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13525
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/12/2020 8:55 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/12/2020 8:55 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11265+00	<b>Field Station#</b>	11286+50		
<b>Pic 1 Desc.</b>	Perimeter controls functional.		<b>Pic 2 Desc.</b>	Perimeter controls functional.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11292+80	<b>Field Station#</b>	11327+85		
<b>Pic 3 Desc.</b>	S-MM18 and controls.		<b>Pic 4 Desc.</b>	S-NN12 and controls.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11340+00	<b>Field Station#</b>	11352+97		
<b>Pic 5 Desc.</b>	Crimping in fresh mulch.		<b>Pic 6 Desc.</b>	S-NN11 and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 8:55 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 8:55 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13533
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/12/2020 3:32 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+20
<b>State</b>	VA	<b>Inspection Area</b>	Incident/Complaint	<b>Station End</b>	11524+25
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 3:32 PM	<b>Report #</b>	13533
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. Checked rain gauges at Stevers Gap Road - 0.1 inches and Mount Tabor Road - 0.0 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	8/12/2020 3:32 PM	Report #	
Pictures					
 <p>Date &amp; Time: Wed, Aug 12, 2020, 09:45:40 EDT Position: +409.234887° / -80.631702° (+60.47) Altitude: 2269ft (+100.3ft) Datum: WGS-84 Azimuth/Bearing: 328° N32W 583mils True (+13°) Elevation Angle: -19.8° Horizon Angle: -02.0° Zoom: 1.0X 11507+00</p>		 <p>Date &amp; Time: Wed, Aug 12, 2020, 09:45:40 EDT Position: +409.234887° / -80.631702° (+60.47) Altitude: 2169ft (+20.0ft) Datum: WGS-84 Azimuth/Bearing: 267° S67W 440mils True (+13°) Elevation Angle: -09.6° Horizon Angle: -01.2° Zoom: 1.0X 11489+00</p>			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11507+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Plunge pool in place.		<b>Pic 2 Desc.</b>	
 <p>Date &amp; Time: Wed, Aug 12, 2020, 11:48:40 EDT Position: +409.234887° / -80.631702° (+60.47) Altitude: 2174ft (+11.2ft) Datum: WGS-84 Azimuth/Bearing: 352° N35W 430mils True (+13°) Elevation Angle: -05.5° Horizon Angle: -01.5° Zoom: 1.0X 11489+00</p>		 <p>Date &amp; Time: Wed, Aug 12, 2020, 11:48:40 EDT Position: +409.234887° / -80.631702° (+60.47) Altitude: 2140ft (+8.0ft) Datum: WGS-84 Azimuth/Bearing: 266° S66W 439mils True (+13°) Elevation Angle: -01.9° Horizon Angle: -01.9° Zoom: 1.0X 11487+00</p>			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11489+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Rain gauge at Stevers Gap Road reads 0.1 inches.		<b>Pic 4 Desc.</b>	
 <p>Date &amp; Time: Wed, Aug 12, 2020, 11:48:40 EDT Position: +409.234887° / -80.631702° (+60.47) Altitude: 2140ft (+8.0ft) Datum: WGS-84 Azimuth/Bearing: 334° N34W 440mils True (+13°) Elevation Angle: -00.9° Horizon Angle: -00.9° Zoom: 1.0X 11473+00</p>		 <p>Date &amp; Time: Wed, Aug 12, 2020, 11:48:40 EDT Position: +409.234887° / -80.631702° (+60.47) Altitude: 2070ft (+2.0ft) Datum: WGS-84 Azimuth/Bearing: 036° N36E 0440mils True (+13°) Elevation Angle: -05.3° Horizon Angle: -02.0° Zoom: 1.0X 11535+00</p>			
<b>GPS Location</b>		See photo for GPS location.		<b>GPS Location</b>	
<b>Field Station#</b>		11473+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Two tone stabilized with ECB. Slope drains in place.		<b>Pic 6 Desc.</b>	
				Rain gauge at Mount Tabor Road reads 0.0 inches.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 3:32 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 3:32 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13534
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/12/2020 3:41 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 3:41 PM	<b>Report #</b>	13534
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 209 - MP 211.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/12/2020 3:41 PM	<b>Report #</b>	
<b>Pictures</b>					
<p><small>Date &amp; Time: Wed, Aug 12, 2020 08:53:19 EDT Position: +49.345107° / +80.83329° (+10.2m) Altitude: 2299ft (+70.3m) Datum: WGS-84 Azimuth/Bearing: 104° 59'55.136"mile True (+14°) Elevation Grade: -015° Horizon Grade: -001° Zoom: 1.0X 1</small></p> 		<p><small>Date &amp; Time: Wed, Aug 12, 2020 08:56:21 EDT Position: +49.345107° / +80.837422° (+10.0m) Altitude: 2301ft (+70.1m) Datum: WGS-84 Azimuth/Bearing: 104° 59'55.136"mile True (+14°) Elevation Grade: -015° Horizon Grade: -001° Zoom: 1.0X 1</small></p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11070+00		<b>Field Station#</b>	11090+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<p><small>Date &amp; Time: Wed, Aug 12, 2020 09:07:46 EDT Position: +49.3451358° / +80.836618° (+10.2m) Altitude: 1829ft (+51.5m) Datum: WGS-84 Azimuth/Bearing: 124° 58'55.136"mile True (+14°) Elevation Grade: -014° Horizon Grade: +003° Zoom: 1.0X 1</small></p> 		<p><small>Date &amp; Time: Wed, Aug 12, 2020 09:07:46 EDT Position: +49.3451358° / +80.836618° (+10.2m) Altitude: 1829ft (+51.5m) Datum: WGS-84 Azimuth/Bearing: 124° 58'55.136"mile True (+14°) Elevation Grade: -014° Horizon Grade: +003° Zoom: 1.0X 1</small></p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11100+00		<b>Field Station#</b>	11110+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<p><small>Date &amp; Time: Wed, Aug 12, 2020 09:14:47 EDT Position: +49.3451447° / +80.836618° (+10.2m) Altitude: 2340ft (+70.7m) Datum: WGS-84 Azimuth/Bearing: 104° 59'55.136"mile True (+14°) Elevation Grade: -001° Horizon Grade: -001° Zoom: 1.0X 1</small></p> 		<p><small>Date &amp; Time: Wed, Aug 12, 2020 09:15:01 EDT Position: +49.3451447° / +80.836618° (+10.2m) Altitude: 2340ft (+70.7m) Datum: WGS-84 Azimuth/Bearing: 104° 59'55.136"mile True (+14°) Elevation Grade: -001° Horizon Grade: -001° Zoom: 1.0X 1</small></p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11120+00		<b>Field Station#</b>	11140+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 3:41 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2020 3:41 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13566
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	8/13/2020 11:43 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.40
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 11:43 AM	<b>Report #</b>	13566
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a regular scheduled VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The area received approximately 1.4" of rainfall in the past 24 hours. The ROW surface was wet but stable. No erosion is occurring at this time. ECDs are in place and in acceptable condition. The contractor is taking care of routine maintenance as needed. Equipment bridges appear to be in good conditions. Resource buffers are stable with no evidence of impact to streams. No sediment movement and no disturbance beyond LOD. There was no signs of trespass or vandalism. No environmental concerns identified.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/13/2020 11:43 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Aug 13, 2020, 09:23:48 EDT  Position: +482.29599° / -880.39599° (+14.47)  Altitude: 2220 (+19.37)  Datum: WGS-84  Azimuth/Bearing: 314° 5455' 5010mils Magnetic (+13°)  Elevation Angle: -31.2°  Horizon Angle: -01.3°  Zoom: 1.0x  Brush Min. Slope breakers functional, 11662+00</p> 		<p>Date &amp; Time: Thu, Aug 13, 2020, 09:30:43 EDT  Position: +482.29599° / -880.39599° (+14.47)  Altitude: 2220 (+19.37)  Datum: WGS-84  Azimuth/Bearing: 179° 501E 3162mils Magnetic (+15°)  Elevation Angle: 23.6°  Horizon Angle: -08.4°  Zoom: 1.0x  Brush Min. Slope breakers functional, 11662+00</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11667+00	<b>Field Station#</b>	11662+00		
<b>Pic 1 Desc.</b>	Slope breakers functional. ROW stable.	<b>Pic 2 Desc.</b>	Perimeter controls in place and functioning.		
<p>Date &amp; Time: Thu, Aug 13, 2020, 09:34:05 EDT  Position: +482.29599° / -880.39599° (+14.47)  Altitude: 2241 (+19.87)  Datum: WGS-84  Azimuth/Bearing: 141° 5825' 3300mils Magnetic (+12°)  Elevation Angle: -07.2°  Horizon Angle: -00.8°  Zoom: 1.0x  Brush Min. ROW stable. Signs in place, 11658+50</p> 		<p>Date &amp; Time: Thu, Aug 13, 2020, 09:45:05 EDT  Position: +482.29599° / -880.39599° (+14.47)  Altitude: 2240 (+19.87)  Datum: WGS-84  Azimuth/Bearing: 139° 581W 3460mils Magnetic (+12°)  Elevation Angle: -04.0°  Horizon Angle: -00.8°  Zoom: 1.0x  Brush Min. ROW stable. Signs in place, 11644+00</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11658+50	<b>Field Station#</b>	11644+00		
<b>Pic 3 Desc.</b>	ROW stable. Perimeter controls in place.	<b>Pic 4 Desc.</b>	ROW stable. Perimeter controls in place.		
<p>Date &amp; Time: Thu, Aug 13, 2020, 10:06:34 EDT  Position: +491.43244° / -880.399107° (+16.48)  Altitude: 1945ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 048° N45E 0853mils Magnetic (+13°)  Elevation Angle: -07.3°  Horizon Angle: +00.1°  Zoom: 1.0x  S-HH18 crossing stable, 11626+04</p> 		<p>Date &amp; Time: Thu, Aug 13, 2020, 10:15:12 EDT  Position: +491.43244° / -880.402117° (+16.48)  Altitude: 1945ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 261° S81W 4640mils Magnetic (+13°)  Elevation Angle: -07.3°  Horizon Angle: -02.3°  Zoom: 1.0x  S-RR14 crossing stable</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+20		
<b>Pic 5 Desc.</b>	The S-HH18 crossing.	<b>Pic 6 Desc.</b>	The S-RR14 crossing is stable		



<b>AFE</b>	124300137	<b>Date/Time</b>	8/13/2020 11:43 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu Aug 13, 2020 07:36:33PT Position: +037.31421° / -090.402548° (±32.8ft) Altitude: 1878ft (±5.1ft) Datum: WGS-84 Azimuth/Bearing: 104° S19W 3538mils Magnetic (±10°) Elevation Angle: -00.3° Horizontal Angle: +01.3° Zoom: 1.0X AR 258.04/S-RR13 crossing</small></p>		 <p><small>Date &amp; Time: Thu Aug 13, 2020 10:33:34 EDT Position: +037.313592° / -090.404448° (±16.4ft) Altitude: 1908ft (±5.3ft) Datum: WGS-84 Azimuth/Bearing: 104° S19W 1040mils Magnetic (±13°) Elevation Angle: -00.3° Horizontal Angle: +00.5° Zoom: 1.0X S-006 crossing stable</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11613+69	<b>Field Station#</b>	11608+17		
<b>Pic 7 Desc.</b>	AR MN-258.04 and equipment bridge at S-RR13 in good condition.	<b>Pic 8 Desc.</b>	The S-006 crossing is stable.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 11:43 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13572
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/13/2020 2:10 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.90
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Check Dam	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 2:10 PM	<b>Report #</b>	13572
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with EI's at Winding Way.</p> <p>SWPPP inspection: Sta#11899+99 to 12005+00. MP-225.3 to 227.3</p> <p>The inspection area received 0.90" of rain overnight, row is wet but in stable condition.</p> <p>Permanent restoration vegetation is very good prohibiting sediment movement.</p> <p>Perimeter controls, silt fence, CFS, SSF are in acceptable condition.</p> <p>Karst ECD's are in acceptable condition.</p> <p>Water bars and level spreaders are in acceptable condition.</p> <p>Access roads are maintained in acceptable condition.</p> <p>Sta#12001+00- There is a cattle crossing at the wetland, used by the landowner to move cattle to pasture on both sides of the row.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/13/2020 2:10 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Aug 13, 2020, 09:45:55 EDT  Position: +409.233797° / -080.333688° (±16.4m)  Altitude: 1419ft (±16.4m)  Datum: WGS-84  Azimuth/Bearing: 185° S85E 185°mils True (±10°)  Elevation Angle: -33.3°  Horizon Angle: +01.3°  Zoom: 1.0x  Catawba rain gauge reading: 0.90"</p> 		<p>Date &amp; Time: Thu, Aug 13, 2020, 09:37:30 EDT  Position: +407.269797° / -080.333688° (±16.4m)  Altitude: 2310ft (±16.9m)  Datum: WGS-84  Azimuth/Bearing: 281° N79W 499°mils True (±10°)  Elevation Angle: -31.4°  Horizon Angle: +01.8°  Zoom: 1.0x  Sta#11900+00- AR-266.03 access road and CFS check dams</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11989+00	<b>Field Station#</b>	11901+00		
<b>Pic 1 Desc.</b>	Catawba rain gauge reading- 0.90"	<b>Pic 2 Desc.</b>	AR-266.03- Access road and CFS check dams		
<p>Date &amp; Time: Thu, Aug 13, 2020, 10:00:00 EDT  Position: +409.277121° / -080.327524° (±19.4m)  Altitude: 2148ft (±21.0m)  Datum: WGS-84  Azimuth/Bearing: 183° S83W 325°mils True (±10°)  Elevation Angle: -13.5°  Horizon Angle: -00.6°  Zoom: 1.0x  Sta#11942+00- Karst ECD's</p> 		<p>Date &amp; Time: Thu, Aug 13, 2020, 10:04:00 EDT  Position: +407.9277121° / -080.327524° (±19.4m)  Altitude: 2148ft (±21.0m)  Datum: WGS-84  Azimuth/Bearing: 185° S85E 279°mils True (±10°)  Elevation Angle: -22.5°  Horizon Angle: -00.5°  Zoom: 1.0x  Sta#11949+00- Row vegetation, level spreaders, perimeter controls</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11942+00	<b>Field Station#</b>	11949+00		
<b>Pic 3 Desc.</b>	Karst ECD's and row vegetation	<b>Pic 4 Desc.</b>	Row vegetation, level spreaders, perimeter controls.		
<p>Date &amp; Time: Thu, Aug 13, 2020, 10:27:07 EDT  Position: +413.269711° / -080.322703° (±32.8m)  Altitude: 1781ft (±32.8m)  Datum: WGS-84  Azimuth/Bearing: 344° N14W 615°mils True (±25°)  Elevation Angle: -19.2°  Horizon Angle: -07.9°  Zoom: 1.0x  Sta#11978+00- Karst ECD's</p> 		<p>Date &amp; Time: Thu, Aug 13, 2020, 10:38:41 EDT  Position: +413.269711° / -080.316941° (±32.8m)  Altitude: 1557ft (±32.8m)  Datum: WGS-84  Azimuth/Bearing: 120° S40E 213°mils True (±25°)  Elevation Angle: -09.9°  Horizon Angle: +01.1°  Zoom: 1.0x  Sta#11200+00- Karst ECD's Sta#12001+00- Wetland and cattle crossing</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11978+00	<b>Field Station#</b>	12001+00		
<b>Pic 5 Desc.</b>	Karst ECD's	<b>Pic 6 Desc.</b>	Wetland and cattle crossing.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 2:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 2:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13575
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/13/2020 3:23 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.70
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 3:23 PM	<b>Report #</b>	13575
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Rain gauge at Mount Tabor reads 0.7 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/13/2020 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11670+00		<b>Field Station#</b>	11730+00	
<b>Pic 1 Desc.</b>	Triple stack compost filter sock and priority one silt fence in place along LOD.		<b>Pic 2 Desc.</b>	ROW stabilized with seed and mulch.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11754+00		<b>Field Station#</b>	11767+00	
<b>Pic 3 Desc.</b>	Priority one silt fence checks in place.		<b>Pic 4 Desc.</b>	RCE in place at Mount Tabor Road.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11778+00	
<b>Pic 5 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.7 inches.		<b>Pic 6 Desc.</b>	Clean water diversion pipe inlet and clean water diversion berm in place.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13576
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/13/2020 3:39 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	79.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.90
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 3:39 PM	<b>Report #</b>	13576
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.27 to MP 225.37 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/13/2020 3:39 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11792+00	<b>Field Station#</b>	11818+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11848+00	<b>Field Station#</b>	11863+65		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	P-KL2 and conditions.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11886+00	<b>Field Station#</b>	11899+50		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 3:39 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 3:39 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13581
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/13/2020 4:32 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 4:32 PM	<b>Report #</b>	13581
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218 - MP 219.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Collected rain gauge amounts					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/13/2020 4:32 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11530+00		<b>Field Station#</b>	11551+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11567+00		<b>Field Station#</b>	11585+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11585+00		<b>Field Station#</b>	+1	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	No rain recorded	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 4:32 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2020 4:32 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13609
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/14/2020 8:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 8:31 AM	<b>Report #</b>	13609
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at the work trailer SWPPP inspection: LY-29 AR-238.00- Access road serving LY-29 is in acceptable condition, there is some shallow rilling on slopes from recent rain events. Perimeter controls are 18" triple stack CFS and are in acceptable condition. Culvert and drainage feature are in acceptable condition. House keeping is acceptable. Waste management is acceptable. Store materials are acceptable. There are no mechanical equipment stored in the yard and very little activity.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 8/14/2020 8:31 AM		Report #	
Pictures					
<div><div>Date &amp; Time: Fri, Aug 14, 2020, 09:45:22 EDT Position: +037 349106 / -080 652637 (±16.4ft) Altitude: 202ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 158 522E 2809mils True (±15°) Elevation Angle: -36.9 Horizon Angle: +05.3 Zoom: 1.0X Buffalo Anklets rain gauge reading- 0.10</div></div>		<div><div>Date &amp; Time: Fri, Aug 14, 2020, 10:12:17 EDT Position: +037 370636 / -080 678242 (±16.4ft) Altitude: 1756ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 130° 550E 2311mils True (±26°) Elevation Angle: -12.5 Horizon Angle: +00.5 Zoom: 1.0X AR-234.00 rain gauge reading- 0.20</div></div>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11671+00		Field Station#	12005+00	
Pic 1 Desc.	Buffalo Anklets rain gauge reading- 0.10"		Pic 2 Desc.	AR-234.00 rain gauge reading- 0.20"	
<div><div>Date &amp; Time: Fri, Aug 14, 2020, 16:35:49 EDT Position: +007 363577 / -080 677201 (±16.4ft) Altitude: 1690ft (±32.2ft) Datum: WGS-84 Azimuth/Bearing: 304° 0650W 6486mils True (±25°) Elevation Angle: -11.5 Horizon Angle: +03.0 Zoom: 1.0X LY-29- PPL materials stored.</div></div>		<div><div>Date &amp; Time: Fri, Aug 14, 2020, 16:35:49 EDT Position: +037 363577 / -080 677201 (±16.4ft) Altitude: 1717ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 032° N32E 0569mils True (Error) Elevation Angle: -15.4 Horizon Angle: -00.4 Zoom: 1.0X LY-29- CFS triple stack perimeter controls.</div></div>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	LY-29- PPL materials stored.		Pic 4 Desc.	LY-29- CFS triple stack perimeter controls.	
<div><div>Date &amp; Time: Fri, Aug 14, 2020, 16:35:49 EDT Position: +037 363120 / -080 676873 (±16.4ft) Altitude: 1707ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 261° S81W 4440mils True (±26°) Elevation Angle: -13.1 Horizon Angle: +03.2 Zoom: 1.0X LY-29- Stored pipe.</div></div>		<div><div>Date &amp; Time: Fri, Aug 14, 2020, 16:28:07 EDT Position: +037 362897 / -080 677260 (±16.4ft) Altitude: 1688ft (±19.1ft) Datum: WGS-84 Azimuth/Bearing: 345° N15W 6133mils True (±26°) Elevation Angle: -17.6 Horizon Angle: +09.8 Zoom: 1.0X LY-29- Culvert and drainage feature.</div></div>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	LY-29- Pipe stored in the yard.		Pic 6 Desc.	LY-29- Culvert and drainage feature.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 8:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 8:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13640
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/14/2020 10:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	120050+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 10:56 AM	<b>Report #</b>	13640
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed Post storm inspection for LDY 28 Performed post storm inspection from MP 217 - MP 218.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Collected rain gauge amounts					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 10:56 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	112005+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD' and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11510+00		<b>Field Station#</b>	11503+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 10:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 10:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13623
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/14/2020 3:53 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	2.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			
Secondary Containment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 3:53 PM	<b>Report #</b>	13623
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked Rain gauges at Catawba Road - 2.0 inches and amount Tabor Road - 0.7 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/14/2020 3:53 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11990+00		<b>Field Station#</b>	11767+00	
<b>Pic 1 Desc.</b>	Rain gauge at Catawba Road reads 2.0 inches.		<b>Pic 2 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.7 inches.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Triple stack CFS around drainage feature.		<b>Pic 4 Desc.</b>	RCE in place at Lay Down Yard 26 entrance.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	Dumpsters being utilized for trash management.		<b>Pic 6 Desc.</b>	Secondary containment in place under fuel cell.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 3:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/14/2020 3:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13641
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/15/2020 9:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11158+27
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11254+59
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/15/2020 9:56 AM	<b>Report #</b>	13641
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed Post storm inspection for MP 211- MP 212.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Collected rain gauge amounts					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/15/2020 9:56 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	11226+00	
<b>Pic 1 Desc.</b>	.4" of rain recorded		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11220+00		<b>Field Station#</b>	11218+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11210+00		<b>Field Station#</b>	112209+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/15/2020 9:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/15/2020 9:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13642
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	8/15/2020 11:26 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	71.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.95
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			


## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/15/2020 11:26 AM	<b>Report #</b>	13642
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>The project area continues to receive significant amount of rainfall. The ROW is saturated and rain continues today. The ROW is currently stable with no erosion issues. ECDs are in place and functioning properly. No sediment has been located beyond LOD. No slips have occurred to date. Resource crossings are stable. No evidence of trespass or vandalism noted. RCEs are in good condition. No environmental concerns at this time.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 8/15/2020 11:26 AM	Report #
Pictures			
 <p>Date &amp; Time Sat, Aug 15, 2020, 10:02:10 EDT Position: +037°31'42.92" / -080°40'26.81" (±16.4m) Altitude: 1912m (±26.8m) Datum: WGS-84 Azimuth: 340° - 002°mils (±13°) Elevation Angle: +03.8° Horizon Angle: -06.8° Zoom: 1.0X S-RR13 crossing stable.</p>		 <p>Date &amp; Time Sat, Aug 15, 2020, 10:06:49 EDT Position: +037°31'39.77" / -080°40'56.67" (±16.4m) Altitude: 1908m (±26.8m) Datum: WGS-84 Azimuth: +004° - 014°mils (±13°) Elevation Angle: +03.3° Horizon Angle: -06.3° Zoom: 1.0X S-006 crossing stable.</p>	
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11613+69	<b>Field Station#</b>	11608+17
<b>Pic 1 Desc.</b>	S-RR13 crossing on AR MN-258.04 stable	<b>Pic 2 Desc.</b>	S-006 crossing stable with no sign of impact.
 <p>Date &amp; Time Sat, Aug 15, 2020, 10:08:29 EDT Position: +037°31'37.14" / -080°40'26.11" (±16.4m) Altitude: 1912m (±26.8m) Datum: WGS-84 Azimuth: 104° - 071°mils (±14°) Elevation Angle: +03.8° Horizon Angle: -06.8° Zoom: 1.0X S-RR14 crossing stable.</p>		 <p>Date &amp; Time Sat, Aug 15, 2020, 10:12:24 EDT Position: +037°31'39.48" / -080°39'59.77" (±16.4m) Altitude: 1944m (±26.8m) Datum: WGS-84 Azimuth: +008° - 033°mils (±13°) Elevation Angle: +04.9° Horizon Angle: -03.9° Zoom: 1.0X S-HH18 crossing stable.</p>	
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11614+20	<b>Field Station#</b>	11626+04
<b>Pic 3 Desc.</b>	S-RR14 crossing stable. ECDs in place and functional.	<b>Pic 4 Desc.</b>	S-HH18 crossing stable with ECDs in place and functional.
 <p>Date &amp; Time Sat, Aug 15, 2020, 10:25:12 EDT Position: +037°31'47.47" / -080°40'56.67" (±16.4m) Altitude: 1912m (±26.8m) Datum: WGS-84 Azimuth: 102° - 022°mils (±13°) Elevation Angle: +07.6° Horizon Angle: -06.3° Zoom: 1.0X W-CD46 adjacent wetland shows no impact.</p>		 <p>Date &amp; Time Sat, Aug 15, 2020, 10:31:17 EDT Position: +037°31'43.51" / -080°40'56.16" (±16.4m) Altitude: 1937m (±26.8m) Datum: WGS-84 Azimuth: +160° - 320°mils (±13°) Elevation Angle: +06.1° Horizon Angle: -06.3° Zoom: 1.0X S-PP20 crossing stable.</p>	
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11589+75	<b>Field Station#</b>	11588+41
<b>Pic 5 Desc.</b>	Adjacent wetland W-CD46 shows no impact.	<b>Pic 6 Desc.</b>	S-PP20 crossing stable with ECDs in place and functional.



<b>AFE</b>	124300137	<b>Date/Time</b>	8/15/2020 11:26 AM	<b>Report #</b>	
<b>Pictures</b>					
					
		Insert image here			
<b>GPS Location</b>	On photo	<b>GPS Location</b>			
<b>Field Station#</b>	11585+48	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	S-PP21 crossing stable with effective controls in place.	<b>Pic 8 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/15/2020 11:26 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		