



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13868
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/24/2020 8:17 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 8:17 AM	<b>Report #</b>	13868
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at Winding Way SWPPP inspection area: Sta#11254+99 to 11158+27. MP-213 to 211. The row is dry and in stable condition, temporary stabilization is in acceptable condition. Perimeter controls, silt fence, SSF, CFS are in acceptable condition. Water bars, sump pits and end treatments are in acceptable condition. Topsoil stockpiles are well vegetated in stable condition. Slope drain pipes are in acceptable condition. CWD pipe and plunge pool are in good condition. Access roads are maintained in acceptable condition. Rain gauge readings: Winding Way- Trace Buffalo Anklets- Trace AR-234.00- 0.10"					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	8/24/2020 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Aug 24, 2020 09:30:31 EDT  Position: +037 301227 / -080 500876 (+32.011°  Altitude: 2076ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 119° S61E 2116mils True (±15°)  Elevation Angle: -09.2°  Horizon Angle: +00.8°  Zoom: 1.0X  Sta#11228+00 to 11237+00- Row vegetation is acceptable.</p> 		<p>Date &amp; Time: Mon, Aug 24, 2020 09:35:42 EDT  Position: +037 301586 / -080 502674 (+32.261°  Altitude: 2081ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 192° S64W 3449mils True (±10°)  Elevation Angle: -38.8°  Horizon Angle: +03.1°  Zoom: 1.0X  Sta#11221+00- Slope drain pipe and treatment rock channel.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11228+00	<b>Field Station#</b>	11225+00		
<b>Pic 1 Desc.</b>	Row vegetation is acceptable in this area.	<b>Pic 2 Desc.</b>	Slope drain, end treatment, rock channel.		
<p>Date &amp; Time: Mon, Aug 24, 2020 09:41:05 EDT  Position: +037 303289 / -080 505871 (+39.999° 9ft)  Altitude: 2088ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 121° S59E 2151mils True (±10°)  Elevation Angle: +11.7°  Horizon Angle: +01.2°  Zoom: 1.0X  Sta#11217+00- Contractor staged material for ECD repair.</p> 		<p>Date &amp; Time: Mon, Aug 24, 2020 09:45:36 EDT  Position: +037 306549 / -080 510038 (+40.241°  Altitude: 1953ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 127° S50E 4239mils True (±5°)  Elevation Angle: -08.8°  Horizon Angle: -03.7°  Zoom: 1.0X  Sta#11190+00- Row drainage feature, ECD's.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11217+00	<b>Field Station#</b>	11190+00		
<b>Pic 3 Desc.</b>	Materials staged for ECD repairs	<b>Pic 4 Desc.</b>	Row, drainage feature, and ECD's.		
<p>Date &amp; Time: Mon, Aug 24, 2020 09:59:35 EDT  Position: +037 307265 / -080 511708 (+44.507° 1ft)  Altitude: 1935ft (+35.7ft)  Datum: WGS-84  Azimuth/Bearing: 241° S61W 4284mils True (±10°)  Elevation Angle: -25.6°  Horizon Angle: +05.7°  Zoom: 1.0X  Sta#11185+00- Rock check dams on access road.</p> 		<p>Date &amp; Time: Mon, Aug 24, 2020 10:00:12 EDT  Position: +037 307405 / -080 511671 (+44.64m  Altitude: 1925ft (+19.7ft)  Datum: WGS-84  Azimuth/Bearing: 312° N68W 6507mils True (±10°)  Elevation Angle: +17.6°  Horizon Angle: +07.2°  Zoom: 1.0X  Sta#11184+00- CWD pipe and plunge pool.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11185+50	<b>Field Station#</b>	11184+00		
<b>Pic 5 Desc.</b>	Access road and rock check dams.	<b>Pic 6 Desc.</b>	CWD pipe and plunge pool.		

<b>AFE</b>	124300137	<b>Date/Time</b>	8/24/2020 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
					
		Insert image here			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>			
<b>Field Station#</b>	11561+00	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	AR-234.00- rain gauge reading- 0.10".	<b>Pic 8 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 8:17 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13885
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/24/2020 3:42 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:42 PM	<b>Report #</b>	13885
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 209 - MP 211.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist .1" of rain recorded					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/24/2020 3:42 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	11080+00	
<b>Pic 1 Desc.</b>	.1" of rain recorded		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11092+00		<b>Field Station#</b>	11120+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11130+00		<b>Field Station#</b>	11140+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:42 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:42 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13887
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/24/2020 3:55 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:55 PM	<b>Report #</b>	13887
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213.16 to MP 215.03 as well as assessed AR 256.02. No major issues were located. Four locations of minor wildlife damage to controls were identified. PPL Environmental Coordinator Mike Perry was notified the items were added to the punch list. All other perimeter controls, ECDs and BMPs are functional. No impact to sensitive resources observed. During the inspection it was discovered that the non graded portion of the AWS near 11335+00 has been cut for hay by others.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/24/2020 3:55 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11263+75	<b>Field Station#</b>	11286+00		
<b>Pic 1 Desc.</b>	Perimeter controls functional.	<b>Pic 2 Desc.</b>	Perimeter controls functional.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11292+80	<b>Field Station#</b>	11301+00		
<b>Pic 3 Desc.</b>	S-MM18 and controls.	<b>Pic 4 Desc.</b>	Section of RoW showing conditions and controls.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11327+85	<b>Field Station#</b>	11352+97		
<b>Pic 5 Desc.</b>	S-NN12 and controls.	<b>Pic 6 Desc.</b>	S-NN11 and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:55 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:55 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13890
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/24/2020 3:59 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+20
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.35
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:59 PM	<b>Report #</b>	13890
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. Deficiencies located at station numbers; 11401+00 to 11404+00 - holes in priority one silt fence. Holes appear to be from animals. 11437+00 - priority one silt fence ripped off of stakes. 11423+00 - broke priority one silt fence stake. Checked rain gauges at Steve's Gap Road - 0.1 inches and at Mount Tabor Road - 0.35 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 8/24/2020 3:59 PM		Report #	
Pictures					
 <p>Date &amp; Time: Mon, Aug 24, 2020, 09:45:45 EDT Position: +037.297272° / -080.452675° (+28265.8ft) Altitude: 2252ft (+104.8ft) Datum: WGS-84 Azimuth/Bearing: 322° N38W 572mils True (+12°) Elevation Angle: +16.1° Horizon Angle: -01.9° Zoom: 1.0X 11506+00</p>		 <p>Date &amp; Time: Mon, Aug 24, 2020, 09:46:15 EDT Position: +037.297272° / -080.452675° (+28265.8ft) Altitude: 2162ft (+102.1ft) Datum: WGS-84 Azimuth/Bearing: 277° N38W 472mils True (+5°) Elevation Angle: +01.2° Horizon Angle: +04.9° Zoom: 1.0X 11489+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11506+00		Field Station#	11489+00	
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 2 Desc.	RCE in place at Stevers Gap Road.	
 <p>Date &amp; Time: Mon, Aug 24, 2020, 10:19:38 EDT Position: +037.297272° / -080.452675° (+28265.8ft) Altitude: 2156ft (+95.3ft) Datum: WGS-84 Azimuth/Bearing: 001° N61E 808mils True (+13°) Elevation Angle: +37.3° Horizon Angle: -04.6° Zoom: 1.0X 11437+00</p>		 <p>Date &amp; Time: Mon, Aug 24, 2020, 10:41:14 EDT Position: +037.310796° / -080.453691° (+42.5ft) Altitude: 2308ft (+31.7ft) Datum: WGS-84 Azimuth/Bearing: 127° S53E 2258mils True (+13°) Elevation Angle: +22.7° Horizon Angle: -04.3° Zoom: 1.0X 11403+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11437+00		Field Station#	11403+00	
Pic 3 Desc.	Priority one silt fence ripped off of stakes.		Pic 4 Desc.	Hole in priority one silt fence. Appears to be from animals.	
 <p>Date &amp; Time: Mon, Aug 24, 2020, 11:24:46 EDT Position: +037.297272° / -080.452675° (+28265.8ft) Altitude: 2156ft (+95.3ft) Datum: WGS-84 Azimuth/Bearing: 350° N10W 622mils True (+25°) Elevation Angle: +01.1° Horizon Angle: -01.0° Zoom: 1.0X 11489+00</p>		 <p>Date &amp; Time: Mon, Aug 24, 2020, 12:47:06 EDT Position: +037.246122° / -080.367034° (+39.4ft) Altitude: 2015ft (+33.4ft) Datum: WGS-84 Azimuth/Bearing: 350° N10W 622mils True (+25°) Elevation Angle: +01.1° Horizon Angle: -01.0° Zoom: 1.0X 11767+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	11767+00	
Pic 5 Desc.	Rain gauge at Stevers Gap Road reads 0.1 inches.		Pic 6 Desc.	Rain gauge at Mount Tabor Road reads 0.35 inches.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:59 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/24/2020 3:59 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13910
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/25/2020 8:00 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 8:00 AM	<b>Report #</b>	13910
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px; border: 1px solid black;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with EI's at Winding Way          SWPPP inspection area: Sta#11899+99 to 12005+00. MP-225.3 to 227.3          The row in the inspection area has permanent restoration, the vegetation is very good. The row is dry and in stable condition.          Perimeter controls are in acceptable condition.          Water bars and level spreaders are in good condition, outlet protection is in acceptable condition.          Karst ECD's are in acceptable condition.          AR-266.03 and 266.00 are maintained in acceptable condition.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/25/2020 8:00 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<p>Date &amp; Time: Tue, Aug 25, 2020, 08:01:20 EDT Position: +037 283244 / -080 331478 (+16.2m) Altitude: 2314ft (+197m) Datum: WGS-84 Azimuth/Bearing: 132.548E (+327mils True (+10°)) Elevation Angle: -04.8° Horizon Angle: +01.0° Zoom: 1.0X Sta#11919+00- Access road and CFS checks in bar ditch.</p>		<p>Date &amp; Time: Tue, Aug 25, 2020, 09:30:15 EDT Position: +037 283244 / -080 331478 (+16.2m) Altitude: 2314ft (+197m) Datum: WGS-84 Azimuth/Bearing: 128° 552E 2276mils True (+10°) Elevation Angle: -04.8° Horizon Angle: +01.0° Zoom: 1.0X Sta#11919+00- Water bars, water bar outlet protection, no vegetation.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11900+00	<b>Field Station#</b>	11919+00		
<b>Pic 1 Desc.</b>	AR-266.03 Acces road and CFS checks.	<b>Pic 2 Desc.</b>	Row vegetation, water bars, water bar outlet protection.		
					
<p>Date &amp; Time: Tue, Aug 25, 2020, 09:45:11 EDT Position: +037 283244 / -080 332285 (+16.4m) Altitude: 2355ft (+197m) Datum: WGS-84 Azimuth/Bearing: 178° 502E 316mils True (+25°) Elevation Angle: -00.5° Horizon Angle: +03.0° Zoom: 1.0X Sta#11935+00- View of row &amp; row vegetation.</p>		<p>Date &amp; Time: Tue, Aug 25, 2020, 09:48:38 EDT Position: +037 278902 / -080 332285 (+16.4m) Altitude: 2203ft (+197m) Datum: WGS-84 Azimuth/Bearing: 192° 513W 343mils True (+19°) Elevation Angle: -00.5° Horizon Angle: -00.5° Zoom: 1.0X Sta#11942+00- Karst ECD's.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11935+00	<b>Field Station#</b>	11942+00		
<b>Pic 3 Desc.</b>	View of the row and row vegetation.	<b>Pic 4 Desc.</b>	Karst ECD's.		
					
<p>Date &amp; Time: Tue, Aug 25, 2020, 10:00:07 EDT Position: +037 283244 / -080 332440 (+16.4m) Altitude: 1972ft (+197m) Datum: WGS-84 Azimuth/Bearing: 261° 581W 440mils True (+10°) Elevation Angle: -07.9° Horizon Angle: -00.4° Zoom: 1.0X Sta#11967+00- Level spreader.</p>		<p>Date &amp; Time: Tue, Aug 25, 2020, 10:04:50 EDT Position: +037 283244 / -080 332440 (+16.4m) Altitude: 1972ft (+197m) Datum: WGS-84 Azimuth/Bearing: 027° N27E 0480mils True (+25°) Elevation Angle: -11.7° Horizon Angle: +04.3° Zoom: 1.0X AR-266.00- Access road and rock check dams.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11967+00	<b>Field Station#</b>	11989+00		
<b>Pic 5 Desc.</b>	Level spreader	<b>Pic 6 Desc.</b>	AR-266.00- Access road, rock check dams.		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 8:00 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 8:00 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13912
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/25/2020 8:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 8:40 AM	<b>Report #</b>	13912
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.27 to MP 225.37 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/25/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Aug 25, 2020, 09:13:53 EDT Position: +037 296058 / -080 351336 (-1213.3ft) Altitude: 2271ft (+33.3ft) Datum: WGS-84 Azimuth/Bearing: 095 S84E 1707mils True (+12.1) Elevation Angle: +05.2 Horizon Angle: +00.8 Zoom: 0.5X 11792+00</p>		 <p>Date &amp; Time: Tue, Aug 25, 2020, 09:26:35 EDT Position: +037 296008 / -080 351693 (-115.3ft) Altitude: 2271ft (+33.3ft) Datum: WGS-84 Azimuth/Bearing: 095 S84E 2809mils True (+12.1) Elevation Angle: +05.0 Horizon Angle: +00.7 Zoom: 0.5X 11821+00</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	117920+00	<b>Field Station#</b>	11821+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.	
 <p>Date &amp; Time: Tue, Aug 25, 2020, 09:29:48 EDT Position: +037 293187 / -080 351336 (-1151.5ft) Altitude: 2271ft (+33.3ft) Datum: WGS-84 Azimuth/Bearing: 170 S85E 3111mils True (+14.1) Elevation Angle: +00.4 Horizon Angle: +00.4 Zoom: 0.5X 11826+00</p>		 <p>Date &amp; Time: Tue, Aug 25, 2020, 09:39:20 EDT Position: +037 289572 / -080 348745 (-115.4ft) Altitude: 2110ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 184 S04W 3271mils True (+12.1) Elevation Angle: +0.5 Horizon Angle: +00.5 Zoom: 0.5X 11849+00</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11826+00	<b>Field Station#</b>	11849+00		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	Section of restored RoW showing conditions and controls.	
 <p>Date &amp; Time: Tue, Aug 25, 2020, 09:45:52 EDT Position: +037 285976 / -080 346957 (-1246.5ft) Altitude: 2253ft (+11.2ft) Datum: WGS-84 Azimuth/Bearing: 345 N15W 4133mils True (+12.1) Elevation Angle: +06.7 Horizon Angle: +00.3 Zoom: 0.5X P-KL2</p>		 <p>Date &amp; Time: Tue, Aug 25, 2020, 10:06:52 EDT Position: +037 287903 / -080 334665 (-115.5ft) Altitude: 2253ft (+11.2ft) Datum: WGS-84 Azimuth/Bearing: 264 S84W 4693mils True (+12.1) Elevation Angle: +05.1 Horizon Angle: +01.3 Zoom: 0.5X 11899+00</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11863+65	<b>Field Station#</b>	11899+99		
<b>Pic 5 Desc.</b>	P-KL2 and controls.		<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13927
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	8/25/2020 1:08 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			
Compost Filter Sock	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			


## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 1:08 PM	<b>Report #</b>	13927
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a routine VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The ROW surface is currently stable with no erosion or slips located. Perimeter ECDs are in place and functional. Slope breakers are controlling runoff properly and in good condition. Resource buffers are stable with ECDs in place as required. No housekeeping issues were identified. No trespass or vandalism noted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	8/25/2020 1:08 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Aug 25, 2020, 10:40:00 EDT  Position: +037.200397° / -080.394544° (±16.4ft)  Altitude: 2627ft (±262m)  Datum: WGS-84  Azimuth/Bearing: 271° N89W 4818mils Magnetic (±12°)  Elevation Angle: +03.6°  Horizon Angle: +00.2°  Zoom: 1.0X  Brush Mtn. Safety fence installed at equipment wash station near 11669+87</p> 		<p>Date &amp; Time: Tue, Aug 25, 2020, 10:16:49 EDT  Position: +037.200397° / -080.394544° (±16.4ft)  Altitude: 2629ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 156° S34E 2773mils Magnetic (±12°)  Elevation Angle: +06.5°  Horizon Angle: -01.2°  Zoom: 1.0X  Brush Mtn. 11660+00. Perimeter controls in place</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11667+00	<b>Field Station#</b>	11660+00		
<b>Pic 1 Desc.</b>	Orange barricade fence around the equipment cleaning station installed per landowner request.	<b>Pic 2 Desc.</b>	Perimeter controls in place and functional.		
<p>Date &amp; Time: Tue, Aug 25, 2020, 15:15:10 EDT  Position: +037.200397° / -080.394544° (±16.4ft)  Altitude: 2600ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 189° S22E 2909mils Magnetic (±12°)  Elevation Angle: +05.2°  Horizon Angle: -01.6°  Zoom: 1.0X  Brush Mtn. 11658+00. Slope breakers working properly.</p> 		<p>Date &amp; Time: Tue, Aug 25, 2020, 15:42:02 EDT  Position: +037.211305° / -080.397445° (±16.4ft)  Altitude: 2421ft (±62.5ft)  Datum: WGS-84  Azimuth/Bearing: 214° S14E 1893mils (±12°)  Elevation Angle: -01.2°  Horizon Angle: -27.7°  Zoom: 1.0X  Brush Mtn. 11639+00. Perimeter controls in place</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11658+00	<b>Field Station#</b>	11639+00		
<b>Pic 3 Desc.</b>	Slope breakers functioning as designed. ROW stable.	<b>Pic 4 Desc.</b>	Perimeter controls in place and effective.		
<p>Date &amp; Time: Tue, Aug 25, 2020, 11:06:30 EDT  Position: +037.212228° / -080.402601° (±16.4ft)  Altitude: 1891ft (±39.4ft)  Datum: WGS-84  Azimuth/Bearing: 150° S30E 2667mils Magnetic (±12°)  Elevation Angle: -07.6°  Horizon Angle: -00.9°  Zoom: 1.0X  11626+04. S-HH18 crossing stable</p> 		<p>Date &amp; Time: Tue, Aug 25, 2020, 11:06:38 EDT  Position: +037.212228° / -080.402601° (±16.4ft)  Altitude: 1897ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 139° S41E 2471mils Magnetic (±13°)  Elevation Angle: -05.7°  Horizon Angle: -02.1°  Zoom: 1.0X  S-RR14 crossing stable</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+20		
<b>Pic 5 Desc.</b>	S-HH18 crossing stable with ECDs in place.	<b>Pic 6 Desc.</b>	S-RR14 crossing stable with ECDs in place.		

<b>AFE</b>	124300137	<b>Date/Time</b>	8/25/2020 1:08 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>		On photo		<b>GPS Location</b>	
<b>Field Station#</b>		11608+17		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		S-006 crossing is stable with ECDs in place.		<b>Pic 8 Desc.</b>	
<b>GPS Location</b>				<b>GPS Location</b>	
<b>Field Station#</b>				<b>Field Station#</b>	
<b>Pic 9 Desc.</b>				<b>Pic 10 Desc.</b>	
<b>GPS Location</b>				<b>GPS Location</b>	
<b>Field Station#</b>				<b>Field Station#</b>	
<b>Pic 11 Desc.</b>				<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 1:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13932
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/25/2020 3:31 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 3:31 PM	<b>Report #</b>	13932
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218 - MP 219.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 3:31 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11530+00		<b>Field Station#</b>	11551+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11562+00		<b>Field Station#</b>	11567+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11570+00		<b>Field Station#</b>	11585+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 3:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 3:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13933
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/25/2020 3:48 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	86.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 3:48 PM	<b>Report #</b>	13933
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Environmental crew is using equipment to rebuild waterbars at station number 11676+00 to 11680+00. Straw is being staged to re stabilize the ROW.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/25/2020 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Aug 25, 2020, 10:31:12 EDT Position: +037 235327 / -080 35478 (±50.9ft) Altitude: 2102ft (±107.3ft) Datum: WGS-84 Azimuth/Bearing: 158.522° / 609ftils True (±12°) Elevation Angle: ±21.0° Horizon Angle: +01.5° Zoom: 1.0X 11775+00</p>		 <p>Date &amp; Time: Tue, Aug 25, 2020, 11:59:15 EDT Position: +037 235327 / -080 35478 (±50.9ft) Altitude: 2101ft (±107.3ft) Datum: WGS-84 Azimuth/Bearing: 337.284° / 591ftils True (±13°) Elevation Angle: +06.7° Horizon Angle: +02.7° Zoom: 1.0X 11775+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11775+00		<b>Field Station#</b>	11775+00	
<b>Pic 1 Desc.</b>	Clean water diversion pipe and plunge pool in place.		<b>Pic 2 Desc.</b>	Clean water diversion berm and clean water diversion pipe inlet in place.	
 <p>Date &amp; Time: Tue, Aug 25, 2020, 12:30:52 EDT Position: +037 239647 / -080 390954 (±38.3ft) Altitude: 2459ft (±65.3ft) Datum: WGS-84 Azimuth/Bearing: 281.199° / 499ftils True (±13°) Elevation Angle: +08.7° Horizon Angle: +01.7° Zoom: 1.0X 11687+00 S-MN21</p>		 <p>Date &amp; Time: Tue, Aug 25, 2020, 12:32:31 EDT Position: +037 239294 / -080 391026 (±3059.3ft) Altitude: 2463ft (±41.3ft) Datum: WGS-84 Azimuth/Bearing: 336.244° / 597ftils True (±13°) Elevation Angle: +14.8° Horizon Angle: +08.4° Zoom: 1.0X 11690+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11687+40		<b>Field Station#</b>	11690+00	
<b>Pic 3 Desc.</b>	Sensitive resource buffer in place at stream S-MN21.		<b>Pic 4 Desc.</b>	Waterbar, sump pit, and waterbar end treatment in place.	
 <p>Date &amp; Time: Tue, Aug 25, 2020, 12:40:43 EDT Position: +037 239647 / -080 390954 (±38.3ft) Altitude: 2459ft (±65.3ft) Datum: WGS-84 Azimuth/Bearing: 180.500° / 3200ftils True (±13°) Elevation Angle: +19.0° Horizon Angle: +01.7° Zoom: 1.0X 11710+00</p>		 <p>Date &amp; Time: Tue, Aug 25, 2020, 12:40:43 EDT Position: +037 239647 / -080 390954 (±38.3ft) Altitude: 2459ft (±65.3ft) Datum: WGS-84 Azimuth/Bearing: 354.284° / 623ftils True (±13°) Elevation Angle: +09.6° Horizon Angle: +16.8° Zoom: 1.0X 11736+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11710+00		<b>Field Station#</b>	11736+00	
<b>Pic 5 Desc.</b>	ROW stabilized with mulch.		<b>Pic 6 Desc.</b>	Track hoe installing waterbars.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/25/2020 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13962
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/26/2020 8:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	8/26/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed Aug 26 2020 09:51:21 EDT  Position: +037.349100 / +080.1527074 (+16.4m)  Altitude: 2058ft (+9.8m)  Datum: WGS-84  Azimuth/Bearing: 156.546E 203mils True (+25°)  Elevation Angle: +20.5°  Horizon Angle: +05.9°  Zoom: 1.0x  Buffalo Anklets rain gauge reading- 0.25"</p> 		<p>Date &amp; Time: Wed Aug 26 2020 10:06:59 EDT  Position: +037.370244 / +080.078000 (+16.4m)  Altitude: 1955ft (+9.7m)  Datum: WGS-84  Azimuth/Bearing: 114.546E 2027mils True (+25°)  Elevation Angle: +26.2°  Horizon Angle: +05.9°  Zoom: 1.0x  AR234.00 rain gauge reading- 0.30"</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Buffalo Anklets rain gauge reading- 0.25"	<b>Pic 2 Desc.</b>	AR-234.00 rain gauge reading- 0.30"		
<p>Date &amp; Time: Wed Aug 26 2020 10:12:06 EDT  Position: +037.362207 / +080.076931 (+16.4m)  Altitude: 1733ft (+18.7m)  Datum: WGS-84  Azimuth/Bearing: 200.520W 3958mils True (+26°)  Elevation Angle: +02.5°  Horizon Angle: +01.2°  Zoom: 1.0x  LY29- Materials storage.</p> 		<p>Date &amp; Time: Wed Aug 26 2020 10:14:44 EDT  Position: +037.369272 / +080.076200 (+16.4m)  Altitude: 1709ft (+19.4m)  Datum: WGS-84  Azimuth/Bearing: 276.184W 4907mils True (+26°)  Elevation Angle: +10.8°  Horizon Angle: +01.2°  Zoom: 1.0x  LY29- Triple stack CFS perimeter controls.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY-29- Materials storage.	<b>Pic 4 Desc.</b>	LY- 29- triple stack CFS perimeter controls.		
<p>Date &amp; Time: Wed Aug 26 2020 10:16:56 EDT  Position: +037.368667 / +080.076931 (+16.4m)  Altitude: 1708ft (+18.7m)  Datum: WGS-84  Azimuth/Bearing: 229.845W 5000mils True (+26°)  Elevation Angle: +07.4°  Horizon Angle: +01.0°  Zoom: 1.0x  LY29- Pipe stored in yard.</p> 		<p>Date &amp; Time: Wed Aug 26 2020 10:19:06 EDT  Position: +037.369112 / +080.077295 (+16.4m)  Altitude: 1720ft (+18.1m)  Datum: WGS-84  Azimuth/Bearing: 284.124W 5049mils True (+26°)  Elevation Angle: +17.7°  Horizon Angle: +06.6°  Zoom: 1.0x  LY29- Culvert and drainage feature.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	LY-29- Pipe stored in the yard.	<b>Pic 6 Desc.</b>	Culvert and drainage feature		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2020 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13989
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/26/2020 3:36 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Secondary Containment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2020 3:36 PM	<b>Report #</b>	13989
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist Collected rain gauge amounts, .2" recorded					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/26/2020 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed Aug 26, 2020 09:14:27 EDT  Position: -037.332889 / -080.808110 (-15.9m)  Altitude: 1555ft (+11.3m)  Datum: WGS-84  Azimuth/Bearing: 288° N72W 5120mils True (+10.1)  Elevation Grade: +008%  Horizon Grade: +003%  Zoom: 1.0X  28</p> 		<p>Date &amp; Time: Wed Aug 26, 2020 09:16:37 EDT  Position: -037.334022 / -080.808688 (-15.974m)  Altitude: 1555ft (+11.3m)  Datum: WGS-84  Azimuth/Bearing: 188° S18W 3920mils True (+15.7)  Elevation Grade: +008%  Horizon Grade: +002%  Zoom: 1.0X  28</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Wed Aug 26, 2020 09:18:15 EDT  Position: -037.334229 / -080.802954 (-15.4024m)  Altitude: 1537ft (+14.685m)  Datum: WGS-84  Azimuth/Bearing: 205° S28W 3662mils True (+16.1)  Elevation Grade: +003%  Horizon Grade: +012%  Zoom: 1.0X  28</p> 		<p>Date &amp; Time: Wed Aug 26, 2020 09:18:15 EDT  Position: -037.334229 / -080.804499 (+213.3m)  Altitude: 1536ft (+14.630m)  Datum: WGS-84  Azimuth/Bearing: 178° S98E 3111mils True (+16.1)  Elevation Grade: +041%  Horizon Grade: +001%  Zoom: 1.0X  28</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	Secondary containment	
<p>Date &amp; Time: Wed Aug 26, 2020 09:45:57 EDT  Position: -037.316589 / -080.553612 (+20.5m)  Altitude: 2154ft (+33.8m)  Datum: WGS-84  Azimuth/Bearing: 357° S19W 400mils True (+18.1)  Elevation Grade: +001%  Horizon Grade: +001%  Zoom: 1.0X  05</p> 		<p>Date &amp; Time: Wed Aug 26, 2020 10:00:17 EDT  Position: -037.216274 / -080.688697 (+15.3m)  Altitude: 1427ft (+14.4m)  Datum: WGS-84  Azimuth/Bearing: 104° S08E 1800mils True (+10.1)  Elevation Grade: +002%  Horizon Grade: +003%  Zoom: 1.0X  28</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+1	
<b>Pic 5 Desc.</b>	.05" of rain recorded @ AR 244		<b>Pic 6 Desc.</b>	.2" of rain recorded @ Catawba	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2020 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2020 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	13976
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/26/2020 3:45 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2020 3:45 PM	<b>Report #</b>	13976
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Rain gauge at Kow Camp read 0.2 inched and rain gauge at Mount Tabor Road read 0.1 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/26/2020 3:45 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Aug 26, 2020 08:38:58 EDT Position: +337 319432 / -080 657625 / -1212.3N Altitude: 1840ft (-89.4m) Datum: WGS 84 Azimuth/Bearing: 306° N50W 5422mils True (-12°) Elevation Angle: -19° Horizon Angle: -100.2° Horizon Angle: -100.2° Zoom: 1.0X LDY 26</p>		 <p>Date &amp; Time: Wed, Aug 26, 2020 08:39:48 EDT Position: +337 319432 / -080 658431 / -1219.5N Altitude: 1841ft (-89.3m) Datum: WGS 84 Azimuth/Bearing: 281° N79W 4996mils True (-12°) Elevation Angle: -58.4° Horizon Angle: -101.8° Horizon Angle: -101.8° Zoom: 1.0X LDY 26</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Triple stack compost filter sock in place around drainage.		<b>Pic 2 Desc.</b>	RCE in place at entrance of LDY 26.	
 <p>Date &amp; Time: Wed, Aug 26, 2020 08:39:58 EDT Position: +337 318882 / -080 658392 / -1218.4N Altitude: 1793ft (-88.6m) Datum: WGS 84 Azimuth/Bearing: 100° S44E 2618mils True (-12°) Elevation Angle: -45.0° Horizon Angle: -105.3° Horizon Angle: -105.3° Zoom: 1.0X LDY 26</p>		 <p>Date &amp; Time: Wed, Aug 26, 2020 08:40:08 EDT Position: +337 318621 / -080 659761 / -1218.4N Altitude: 1819ft (-89.3m) Datum: WGS 84 Azimuth/Bearing: 101° S39E 1796mils True (-12°) Elevation Angle: -51.0° Horizon Angle: -105.6° Horizon Angle: -105.6° Zoom: 1.0X LDY 26</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Dumpsters being utilized for trash management.		<b>Pic 4 Desc.</b>	Secondary containment in place under fuel cell.	
 <p>Date &amp; Time: Wed, Aug 26, 2020 09:53:13 EDT Position: +422 856229 / -080 658184 / -1210.6N Altitude: 1625ft (-100.7m) Datum: WGS 84 Azimuth/Bearing: 318° N42W 5653mils True (-12°) Elevation Angle: -52.6° Horizon Angle: -101.0° Horizon Angle: -101.0° Zoom: 1.0X Kow Camp</p>		 <p>Date &amp; Time: Wed, Aug 26, 2020 11:52:18 EDT Position: +337 324104 / -080 379119 / -1108.3N Altitude: 2091ft (-299.0m) Datum: WGS 84 Azimuth/Bearing: 337° N23W 5991mils True (-12°) Elevation Angle: -51.0° Horizon Angle: -100.7° Horizon Angle: -100.7° Zoom: 1.0X 11267-00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10883+50		<b>Field Station#</b>	11767+00	
<b>Pic 5 Desc.</b>	Rain gauge at Kow Camp Road reads 0.2 inches.		<b>Pic 6 Desc.</b>	Rain gauge at Mount Tabor Road read 0.1 inches.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2020 3:45 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/26/2020 3:45 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14012
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/27/2020 8:09 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 8:09 AM	<b>Report #</b>	14012
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.78 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 8:09 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11025+50	<b>Field Station#</b>	11037+50		
<b>Pic 1 Desc.</b>	S-IJ18 and controls.	<b>Pic 2 Desc.</b>	Section of RoW showing conditions and controls.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11049+00	<b>Field Station#</b>	11050+10		
<b>Pic 3 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 4 Desc.</b>	S-IJ16B/S-IJ17 and controls.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11057+00	<b>Field Station#</b>	11064+50		
<b>Pic 5 Desc.</b>	Karst perimeter controls functional.	<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 8:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 8:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14013
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/27/2020 8:18 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 8:18 AM	<b>Report #</b>	14013
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with EI's at the work trailer.</p> <p>SWPPP inspection area: Sta#11023+99 to 10930+00. MP- 208.6 to 206.2</p> <p>The row is dry and in stable condition.</p> <p>Temporary stabilization is acceptable.</p> <p>Perimeter controls, silt fence, CFS, SSF are in acceptable condition.</p> <p>There are four streams in the inspection area, S- IJ18, S- RR5, S-E24, S-E25, equipment bridges, buffers, ECD's are in acceptable condition.</p> <p>Sensitive resource area is vegetated, ECD's are acceptable.</p> <p>AR-244.00 and Doe Creek RCE are in acceptable condition.</p> <p>Water bars, sump pits and end treatments are in acceptable condition.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/27/2020 8:18 AM	Report #	
Pictures					
					
Date & Time: Thu, Aug 27, 2020, 09:53:39 EDT Position: +037 322238 / -080 553054 (+16.4ft) Altitude: 2397ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 179° S01E 3182mils True (+15°) Elevation Angle: -21.5° Horizon Angle: +02.8° Zoom: 1.0X Sta#11023+88- Stream S- IJ18 at AR-244.00-		Date & Time: Thu, Aug 27, 2020, 09:58:13 EDT Position: +037 31933292 / -080 556327 (+16.4ft) Altitude: 2454ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 280° N80W 4098mils True (+25°) Elevation Angle: -12.7° Horizon Angle: 01.8° Zoom: 1.0X Sta#11019+54- Stream S- RR5			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11023+88		Field Station#	11019+54	
Pic 1 Desc.	S-IJ18 stream bridge at AR-244.00		Pic 2 Desc.	Slopes coming into stream S- RR5	
					
Date & Time: Thu, Aug 27, 2020, 10:22:48 EDT Position: +037 325203 / -080 563602 (+16.4ft) Altitude: 2747ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 114° S34E 2027mils True (+25°) Elevation Angle: +04.9° Horizon Angle: +03.6° Zoom: 1.0X Sta#10990+00- Perimeter controls on steep slope.		Date & Time: Thu, Aug 27, 2020, 10:27:44 EDT Position: +037 325038 / -080 566736 (+16.4ft) Altitude: 2505ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 103° S27E 1881mils True (+18°) Elevation Angle: -12.1° Horizon Angle: 01.6° Zoom: 1.0X Sta#10986+00- Stream S- E25			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	10990+00		Field Station#	10986+00	
Pic 3 Desc.	Perimeter controls on steep slope.		Pic 4 Desc.	Stream S- E25- Equipment bridge and ECD's.	
					
Date & Time: Thu, Aug 27, 2020, 10:36:17 EDT Position: +037 325497 / -080 562507 (+16.4ft) Altitude: 2400ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 296° N64W 5262mils True (+10°) Elevation Angle: -16.2° Horizon Angle: +01.7° Zoom: 1.0X Sta#10985+00- Stream S- E24		Date & Time: Thu, Aug 27, 2020, 10:45:03 EDT Position: +037 32212309 / -080 562057 (+16.4ft) Altitude: 2297ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 89° N89W 9343mils True (+24°) Elevation Angle: +07.9° Horizon Angle: +03.6° Zoom: 1.0X Sta#10964+00- Drainage feature			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	10985+00		Field Station#	10964+00	
Pic 5 Desc.	Stream S- E24- Bridge, buffers, travel lane.		Pic 6 Desc.	Drainage feature & controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 8:18 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 8:18 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14030
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/27/2020 3:08 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 3:08 PM	<b>Report #</b>	14030
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 205 - MP 207 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/27/2020 3:08 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Aug 27, 2020 09:32:25 EDT  Position: +097.332239 / -080.604528 (s16.24)  Altitude: 2124ft (s14.04)  Datum: WGS-84  Azimuth/Bearing: 074° N85W 5627mils True (s15°)  Elevation Grade: -033%  Horizon Grade: -001%  Zoom: 1.0X  10858</p> 		<p>Date &amp; Time: Thu, Aug 27, 2020 09:44:35 EDT  Position: +097.335559 / -080.598537 (s16.31)  Altitude: 2310ft (s15.80)  Datum: WGS-84  Azimuth/Bearing: 097° S83E 1724mils True (s16°)  Elevation Grade: -034%  Horizon Grade: -002%  Zoom: 1.0X  10875</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10858+00		<b>Field Station#</b>	10875+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Thu, Aug 27, 2020 09:53:35 EDT  Position: +097.334472 / -080.594948 (s15.26)  Altitude: 2340ft (s15.50)  Datum: WGS-84  Azimuth/Bearing: 002° N09E 0149mils True (s14°)  Elevation Grade: -003%  Horizon Grade: -1004%  Zoom: 1.0X  10890</p> 		<p>Date &amp; Time: Thu, Aug 27, 2020 10:00:35 EDT  Position: +097.336559 / -080.591831 (s15.31)  Altitude: 3077ft (s16.41)  Datum: WGS-84  Azimuth/Bearing: 070° N74E 1810mils True (s16°)  Elevation Grade: -043%  Horizon Grade: -006%  Zoom: 1.0X  10898</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10890+00		<b>Field Station#</b>	10898+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<p>Date &amp; Time: Thu, Aug 27, 2020 10:06:29 EDT  Position: +097.334464 / -080.591928 (s15.31)  Altitude: 2517ft (s16.46)  Datum: WGS-84  Azimuth/Bearing: 152° S28E 2702mils True (s125°)  Elevation Grade: -072%  Horizon Grade: -001%  Zoom: 1.0X  10901</p> 		<p>Date &amp; Time: Thu, Aug 27, 2020 10:06:58 EDT  Position: +097.335559 / -080.595019 (s16.31)  Altitude: 2507ft (s16.37)  Datum: WGS-84  Azimuth/Bearing: 110° S30E 1956mils True (s10°)  Elevation Grade: -044%  Horizon Grade: -008%  Zoom: 1.0X  10911</p> 			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10901+00		<b>Field Station#</b>	10910+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 3:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 3:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14031
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/27/2020 3:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 3:12 PM	<b>Report #</b>	14031
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/27/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00		<b>Field Station#</b>	10712+50	
<b>Pic 1 Desc.</b>	CFS in place along AR 241.04		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G33.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10711+00		<b>Field Station#</b>	10712+00	
<b>Pic 3 Desc.</b>	Priority one silt fence checks in place.		<b>Pic 4 Desc.</b>	ROW stabilized with natural vegetation growth.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10698+00		<b>Field Station#</b>	10696+00	
<b>Pic 5 Desc.</b>	sensitive resource buffer in place at stream S-G32.		<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/27/2020 3:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14056
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/28/2020 7:59 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 7:59 AM	<b>Report #</b>	14056
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with EI's at Winding Way.</p> <p>SWPPP inspection area: Sta#11254+99 to 11158+27. MP 213 to 211</p> <p>The weather was sunny at the start of inspection turning cloudy later.</p> <p>The row is dry, vegetation is good in some areas and sparse in others, straw mulch helps with stabilization.</p> <p>There is some shallow rilling on slopes into water bar flow lines to sump pits.</p> <p>The perimeter controls, silt fence, CFS and SSF are in acceptable condition.</p> <p>Drainage feature, ( sensitive resource), area and ECD's are in acceptable condition.</p> <p>Water bars are in acceptable condition.</p> <p>Sumps and water bar end treatments are in acceptable condition.</p> <p>Access roads, Winding Way, AR-249.02, AR-249.01 are in acceptable condition.</p> <p>Slope drain pipes, CWD pipe and plunge pool are in acceptable condition.</p> <p>CFS and rock check dams are in acceptable condition.</p> <p>Rock channel is in acceptable condition.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/28/2020 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:10:12 EDT Position: +037.303398 / -080.509556 (+24300.9ft) Altitude: 1830ft (+95.2m) Datum: WGS-84 Azimuth Bearing: 086° S82° 1004mils True (+10°) Elevation Angle: +1.5° Horizon Angle: +06.8° Zoom: 1.0X Stat#11225+00- Temporary dirt berm protect. slope</p>		 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:11:05 EDT Position: +037.303596 / -080.502603 (+16.4ft) Altitude: 2034ft (+98.2m) Datum: WGS-84 Azimuth Bearing: 196° S16W 3484mils True (+10°) Elevation Angle: -26.7° Horizon Angle: +06.8° Zoom: 1.0X Stat#11225+00- Slope drain pipe, end treatment rock channel</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11226+00	<b>Field Station#</b>	11225+00		
<b>Pic 1 Desc.</b>	Temporary dirt berm protecting slope.	<b>Pic 2 Desc.</b>	Slope drain pipe, end treatment, rock channel.		
 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:16:36 EDT Position: +037.301597 / -080.502648 (+9159.9ft) Altitude: 2058ft (+80.1ft) Datum: WGS-84 Azimuth Bearing: 291° N69W 5173mils True (+10°) Elevation Angle: +20.5° Horizon Angle: +03.7° Zoom: 1.0X Stat#11217+00- Water bars on slope</p>		 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:30:16 EDT Position: +037.307514 / -080.508509 (+16070.2ft) Altitude: 2072ft (+125.4ft) Datum: WGS-84 Azimuth Bearing: 272° N87W 4853mils True (+10°) Elevation Angle: -23.1° Horizon Angle: +01.1° Zoom: 1.0X Stat#11191+00- Drainage feature ECD's</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11217+00	<b>Field Station#</b>	11191+00		
<b>Pic 3 Desc.</b>	Water bars on slope.	<b>Pic 4 Desc.</b>	Sensitive resource area, drainage feature and ECD's.		
 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:36:12 EDT Position: +037.305112 / -080.509310 (+21325.2ft) Altitude: 1969ft (+152.7m) Datum: WGS-84 Azimuth Bearing: 214° S24W 3804mils True (+10°) Elevation Angle: +3.2° Horizon Angle: +06.8° Zoom: 1.0X Stat#11184+00- CWD pipe and plunge pool ECD's</p>		 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:41:12 EDT Position: +037.309471 / -080.513213 (+97.8m) Altitude: 1938ft (+139.4ft) Datum: WGS-84 Azimuth Bearing: 218° S38W 3825mils True (+10°) Elevation Angle: +1.2° Horizon Angle: +06.8° Zoom: 1.0X Stat#11177+00- Water bar flow line</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11184+00	<b>Field Station#</b>	11177+00		
<b>Pic 5 Desc.</b>	CWD pipe and plunge pool, ECD's	<b>Pic 6 Desc.</b>	Rilling in water bar flow line.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 7:59 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14072
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/28/2020 2:28 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+20
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	86.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	8/28/2020 2:28 PM	<b>Report #</b>	14072
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. Deficiencies located at station numbers; 11497+50 - broken priority one silt fence stake. 11487+00 - silt foam dike damaged 11447+75 - holes in priority one silt fence.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/28/2020 2:28 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Aug 28, 2020, 09:14:43 EDT  Position: +037.22168° / -080.43549° (+541.8ft)  Altitude: 2216ft (+80.2ft)  Datum: WGS-84  Azimuth/Bearing: 216° S36W 3840mils True (+13°)  Elevation Angle: -14.9°  Horizon Angle: +00.6°  Zoom: 1.0X  11497+50</p> 		<p>Date &amp; Time: Fri, Aug 28, 2020, 09:38:48 EDT  Position: +037.22439° / -080.43199° (+21.2ft)  Altitude: 2163ft (+35.0ft)  Datum: WGS-84  Azimuth/Bearing: 167° S13E 2949mils True (+14°)  Elevation Angle: -19.3°  Horizon Angle: +00.5°  Zoom: 1.0X  11487+00</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11497+50		<b>Field Station#</b>	11487+00	
<b>Pic 1 Desc.</b>	Broken priority one silt fence.		<b>Pic 2 Desc.</b>	Silt foam dike damaged at landowner access point.	
<p>Date &amp; Time: Fri, Aug 28, 2020, 10:04:08 EDT  Position: +037.31844° / -080.44194° (+59.4ft)  Altitude: 2141ft (+68.2ft)  Datum: WGS-84  Azimuth/Bearing: 105° S75E 1867mils True (+14°)  Elevation Angle: -13.3°  Horizon Angle: +02.4°  Zoom: 1.0X  11447+75</p> 		<p>Date &amp; Time: Fri, Aug 28, 2020, 10:05:47 EDT  Position: +037.22224° / -080.43422° (+61.1ft)  Altitude: 2244ft (+82.3ft)  Datum: WGS-84  Azimuth/Bearing: 337° S87W 4090mils True (+14°)  Elevation Angle: -02.2°  Horizon Angle: +00.5°  Zoom: 1.0X  11473+00</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11447+75		<b>Field Station#</b>	11473+00	
<b>Pic 3 Desc.</b>	Holes in priority one silt fence.		<b>Pic 4 Desc.</b>	ECB used to stabilize two-tone.	
<p>Date &amp; Time: Fri, Aug 28, 2020, 10:20:30 EDT  Position: +037.25552° / -080.42614° (+1584.2ft)  Altitude: 2555ft (+160.2ft)  Datum: WGS-84  Azimuth/Bearing: 243° S33W 4010mils True (+10°)  Elevation Angle: -10.2°  Horizon Angle: +01.3°  Zoom: 1.0X  11489+00</p> 		<p>Date &amp; Time: Fri, Aug 28, 2020, 10:35:47 EDT  Position: +037.31104° / -080.43261° (+1584.2ft)  Altitude: 2264ft (+82.4ft)  Datum: WGS-84  Azimuth/Bearing: 144° S36E 2560mils True (+16°)  Elevation Angle: -18.8°  Horizon Angle: +01.8°  Zoom: 1.0X  11403+00</p> 			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11489+00		<b>Field Station#</b>	11403+00	
<b>Pic 5 Desc.</b>	RCE in place at Stevers Gap Road.		<b>Pic 6 Desc.</b>	Priority one silt fence repaired where holes were found previous inspection.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 2:28 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 2:28 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14088
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/28/2020 3:21 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 3:21 PM	<b>Report #</b>	14088
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 209 - MP 211.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/28/2020 3:21 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11068+00		<b>Field Station#</b>	11075+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11100+00		<b>Field Station#</b>	11120+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11130+00		<b>Field Station#</b>	11140+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 3:21 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 3:21 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14084
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/28/2020 3:29 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 3:29 PM	<b>Report #</b>	14084
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213.16 to MP 215.03 as well as assessed AR 256.02. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	8/28/2020 3:29 PM	Report #	
Pictures					
 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:03:42 EDT Position: +037 296122° / -080 491297° (+2113.2ft) Altitude: 2202ft (+51.0ft) Datum: WGS-84 Azimuth/Bearing: 019° N15E 022mils True (+12°) Elevation Angle: +03.5° Horizon Angle: +07.2° Zoom: 0.5X 11264+00</p>		 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:21:34 EDT Position: +037 295292° / -080 481382° (+13.5ft) Altitude: 2198ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 163° S17E 289mils True (+12°) Elevation Angle: +07.4° Horizon Angle: +01.7° Zoom: 0.5X S-MM18</p>			
GPS Location	1	GPS Location	2		
Field Station#	11264+00	Field Station#	11292+80		
Pic 1 Desc.	Perimeter controls functional.	Pic 2 Desc.	S-MM18 and controls.		
 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:30:29 EDT Position: +037 310704° / -080 488201° (+21379.0ft) Altitude: 2208ft (+51.3ft) Datum: WGS-84 Azimuth/Bearing: 143° S37E 2542mils True (+12°) Elevation Angle: +15.2° Horizon Angle: +03.3° Zoom: 0.5X S-MM12</p>		 <p>Date &amp; Time: Fri, Aug 28, 2020, 09:14:32 EDT Position: +037 300694° / -080 471431° (+60.0ft) Altitude: 11100ft (+26.0ft) Datum: WGS-84 Azimuth/Bearing: 055° N35E 0978mils True (+19°) Elevation Angle: +12.4° Horizon Angle: +00.4° Zoom: 0.5X 11331+25</p>			
GPS Location	3	GPS Location	4		
Field Station#	11327+85	Field Station#	11331+25		
Pic 3 Desc.	S-NN12 and controls.	Pic 4 Desc.	Rock lined channel functional.		
 <p>Date &amp; Time: Fri, Aug 28, 2020, 08:16:56 EDT Position: +037 301793° / -080 471109° (+68.9ft) Altitude: 2220ft (+58.5ft) Datum: WGS-84 Azimuth/Bearing: 310° S90W 2033mils True (+10°) Elevation Angle: +08.1° Horizon Angle: +00.1° Zoom: 0.5X 11335+00</p>		 <p>Date &amp; Time: Fri, Aug 28, 2020, 08:22:09 EDT Position: +037 305525° / -080 467198° (+52.7ft) Altitude: 2011ft (+27.7ft) Datum: WGS-84 Azimuth/Bearing: 144° S38E 2500mils True (+12°) Elevation Angle: +15.5° Horizon Angle: +02.2° Zoom: 0.5X S-NN11</p>			
GPS Location	5	GPS Location	6		
Field Station#	11335+00	Field Station#	11352+97		
Pic 5 Desc.	Section of RoW showing conditions and controls.	Pic 6 Desc.	S-NN11 and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/28/2020 3:29 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		