



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14137
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	8/31/2020 12:30 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions






Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 12:30 PM	<b>Report #</b>	14137
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a routine scheduled VADEQ SWPPP inspection on private and JNF property at Brush Mountain. Light rain during inspection with 0.5" occurring in the area within the past 24 hours. The ROW surface is currently stable with no erosion issues. Perimeter controls are in place and effective. Resource buffers are well vegetated and ECDs in place. Equipment bridge environmental controls are in place. No area with movement of sediment within or beyond approved work space located. No evidence of vandalism or trespass. RCEs in good condition. No environmental concerns were identified.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	8/31/2020 12:30 PM	Report #	
Pictures					
<p>Date &amp; Time: Mon, Aug 31, 2020, 09:34:26 EDT  Position: +487.202489° / -488.394899° (±16.17)  Altitude: 3433ft (±30.10)  Datum: WGS-84  Azimuth/Bearing: 111° 50'E 3170mils Magnetic (±17°)  Elevation Angle: +02.0°  Horizon Angle: -02.3°  Zoom: 1.0X  Brush Mtn. ROW stable. No evidence of vandalism or trespass. 11669+00</p> 		<p>Date &amp; Time: Mon, Aug 31, 2020, 09:34:22 EDT  Position: +487.304171° / -488.37476° (±16.40)  Altitude: 3528ft (±19.70)  Datum: WGS-84  Azimuth/Bearing: 181° 56'W 3128mils Magnetic (±16°)  Elevation Angle: +17.2°  Horizon Angle: -01.0°  Zoom: 1.0X  Perimeter controls in place and effective. 11655+00</p> 			
<b>GPS Location</b>	On photo		<b>GPS Location</b>	On photo	
<b>Field Station#</b>	11669+00		<b>Field Station#</b>	11655+00	
<b>Pic 1 Desc.</b>	ROW stable at top of Brush Mountain near Forest Service access FS188		<b>Pic 2 Desc.</b>	Perimeter controls in place.	
<p>Date &amp; Time: Mon, Aug 31, 2020, 09:44:41 EDT  Position: +487.310168° / -488.377204° (±16.40)  Altitude: 3525ft (±19.8)  Datum: WGS-84  Azimuth/Bearing: 180° 58'W 3120mils Magnetic (±16°)  Elevation Angle: +11.1°  Horizon Angle: -07.0°  Zoom: 1.0X  Perimeter controls in place and effective. 11644+50</p> 		<p>Date &amp; Time: Mon, Aug 31, 2020, 09:46:02 EDT  Position: +487.310168° / -488.377204° (±16.40)  Altitude: 3179ft (±19.70)  Datum: WGS-84  Azimuth/Bearing: 179° 20'E 3144mils Magnetic (±13°)  Elevation Angle: +03.1°  Horizon Angle: +00.0°  Zoom: 1.0X  ROW stable. Perimeter controls in place and effective. 11643+00</p> 			
<b>GPS Location</b>	On photo		<b>GPS Location</b>	On photo	
<b>Field Station#</b>	11646+50		<b>Field Station#</b>	11643+00	
<b>Pic 3 Desc.</b>	Perimeter controls are in place and functional		<b>Pic 4 Desc.</b>	Perimeter controls and slope breakers in place. ROW currently stable.	
<p>Date &amp; Time: Mon, Aug 31, 2020, 09:46:40 EDT  Position: +487.313441° / -488.377488° (±16.40)  Altitude: 3550ft (±39.40)  Datum: WGS-84  Azimuth/Bearing: 173° 50'E 3075mils Magnetic (±12°)  Elevation Angle: +05.0°  Horizon Angle: -01.4°  Zoom: 1.0X  ROW stable. Perimeter controls in place and effective. 11632+00</p> 		<p>Date &amp; Time: Mon, Aug 31, 2020, 09:47:43 EDT  Position: +487.313441° / -488.377488° (±16.40)  Altitude: 3550ft (±39.40)  Datum: WGS-84  Azimuth/Bearing: 120° 56'E 3130mils Magnetic (±13°)  Elevation Angle: +05.9°  Horizon Angle: -01.8°  Zoom: 1.0X  ROW stable. Perimeter controls in place and effective. 11628+00</p> 			
<b>GPS Location</b>	On photo		<b>GPS Location</b>	On photo	
<b>Field Station#</b>	11632+00		<b>Field Station#</b>	11628+00	
<b>Pic 5 Desc.</b>	Perimeter controls are in place and functional		<b>Pic 6 Desc.</b>	Perimeter controls are in place and functioning	



A/E	124300137	Date/Time	8/31/2020 12:30 PM	Report #	
Pictures					
					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11626+04		Field Station#	11614+20	
Pic 7 Desc.	S-HH18 crossing stable with ECDs in place		Pic 8 Desc.	The S-RR14 crossing is stable with ECDs in place.	
					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11613+69		Field Station#	11608+17	
Pic 9 Desc.	The S-RR13 crossing on AR 258.04 is stable with ECDs in place.		Pic 10 Desc.	The S-006 crossing is currently stable with ECDs in place	
			Insert image here		
GPS Location	On photo		GPS Location		
Field Station#	11606+00		Field Station#		
Pic 11 Desc.	ROW stable currently. Perimeter controls are in place.		Pic 12 Desc.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 12:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14143
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	8/31/2020 1:26 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	69.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.35
				<b>Rain Accumulation Time (days)</b>	3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 1:26 PM	<b>Report #</b>	14143
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area: Sta#11899+99 to 12005+00. MP- 225.3 to 227.3 There was light rain fall during inspection walk. Possible heavy rain in the forecast for later. The row in the inspection area is stable with very good vegetation. The ECD's, SSF, CFS, silt fence are in acceptable condition. Water bars and level spreaders are in good condition. Water bar outlet protection is in acceptable condition. Karst ECD's are in acceptable condition. AR-266.03 and AR- 266.00 are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	8/31/2020 1:26 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, Aug 31, 2020, 08:46:46 EDT Position: +037.284524° / -080.322636° (+298.4ft) Altitude: 0ft (Error) Datum: WGS-84 Azimuth/Bearing: 325° N35W 5778mils True (Error) Elevation Angle: -29.0° Horizon Angle: +01.0° Zoom: 1.0X Catawba rain gauge reading- 0.35"</p>		 <p>Date &amp; Time: Mon, Aug 31, 2020, 08:45:46 EDT Position: +037.287804° / -080.333350° (+297.4ft) Altitude: 2240ft (+22.0ft) Datum: WGS-84 Azimuth/Bearing: 135° S45E 2400mils True (+10°) Elevation Angle: -12.2° Horizon Angle: +00.2° Zoom: 1.0X AR-266.03- Access road &amp; controls.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11989+00	<b>Field Station#</b>	11900+00		
<b>Pic 1 Desc.</b>	Catawba rain gauge reading- 0.35"	<b>Pic 2 Desc.</b>	AR-266.03- Access road and controls.		
 <p>Date &amp; Time: Mon, Aug 31, 2020, 09:44:46 EDT Position: +037.285839° / -080.322636° (+298.4ft) Altitude: 2231ft (+159.0ft) Datum: WGS-84 Azimuth/Bearing: 135° S45E 2400mils True (+10°) Elevation Angle: -03.0° Horizon Angle: +00.5° Zoom: 1.0X Sta#11919+74- Water bars, level spreaders, water bar outlet protection.</p>		 <p>Date &amp; Time: Mon, Aug 31, 2020, 09:15:46 EDT Position: +037.283112° / -080.322636° (+298.4ft) Altitude: 2334ft (+159.0ft) Datum: WGS-84 Azimuth/Bearing: 159° S21E 2827mils True (+10°) Elevation Angle: -31.3° Horizon Angle: +00.5° Zoom: 1.0X Sta#11936+00- Row is heavily vegetated.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11919+74	<b>Field Station#</b>	11936+00		
<b>Pic 3 Desc.</b>	Water bars, level spreaders and water bar outlet protection.	<b>Pic 4 Desc.</b>	Row is heavily vegetated.		
 <p>Date &amp; Time: Mon, Aug 31, 2020, 09:44:13 EDT Position: +037.285839° / -080.322636° (+298.4ft) Altitude: 2231ft (+159.0ft) Datum: WGS-84 Azimuth/Bearing: 342° N11W 6204mils True (+10°) Elevation Angle: -17.1° Horizon Angle: +07.1° Zoom: 1.0X Sta#11979+00- Access road.</p>		 <p>Date &amp; Time: Mon, Aug 31, 2020, 09:46:06 EDT Position: +037.285839° / -080.322636° (+298.4ft) Altitude: 1652ft (+129.4ft) Datum: WGS-84 Azimuth/Bearing: 357° N03W 6347mils True (+10°) Elevation Angle: -13.0° Horizon Angle: -03.4° Zoom: 1.0X AR- 266.00- Access road and rock check dams.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11979+00	<b>Field Station#</b>	11989+00		
<b>Pic 5 Desc.</b>	Karst ECD's	<b>Pic 6 Desc.</b>	AR-266.00- Access road and rock check dams.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 1:26 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 1:26 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14144
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	8/31/2020 1:58 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 1:58 PM	<b>Report #</b>	14144
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.27 to MP 225.37 as well as assessed AR 266.03. Inspection completed during ongoing rain event. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Gathered rain gauge data from LDY 37 (0.2"), Pocahontas rd (0.55"), AR 234 (0.8") and Buffalo Anklets (0.5"). Participated in the inspection conference call.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 1:58 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11792+00	<b>Field Station#</b>	11826+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11837+00	<b>Field Station#</b>	11863+65		
<b>Pic 3 Desc.</b>	Perimeter controls functional.		<b>Pic 4 Desc.</b>	P-KL2 and controls.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11870+00	<b>Field Station#</b>	11899+75		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 1:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 1:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14145
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/31/2020 2:31 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 2:31 PM	<b>Report #</b>	14145
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Environmental crew currently working on re stabilizing area. Rain gauge at Mount Tabor Road read 0.4 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 8/31/2020 2:31 PM		Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11670+00		Field Station#	11670+75	
Pic 1 Desc.	Triple stack CFS and priority one silt fence in place along LOD.		Pic 2 Desc.	Fence and gate installed to prevent ATV trespassing.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11676+00		Field Station#	11687+40	
Pic 3 Desc.	Waterbar, sump pit, and waterbar end treatment in place. ROW stabilized with seed and mulch.		Pic 4 Desc.	Sensitive resource buffer in place at stream S-MN21.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11767+00	
Pic 5 Desc.	Rain gauge at Mount Tabor Road reads 0.4 inches.		Pic 6 Desc.	RCE in place at Main Line Valve 26.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 2:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 2:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14146
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	8/31/2020 3:00 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 3:00 PM	<b>Report #</b>	14146
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218 - MP 219.5 Observed damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Damaged P1 added to the punchlist					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/31/2020 3:00 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11530+00		<b>Field Station#</b>	11545+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11557+00		<b>Field Station#</b>	11558+00	
<b>Pic 3 Desc.</b>	Damaged P1		<b>Pic 4 Desc.</b>	ECD's and row conditions SPP22	
					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11582+00		<b>Field Station#</b>	11585+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	Damaged P1	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 3:00 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/31/2020 3:00 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14207
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	9/1/2020 8:49 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.70
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/1/2020 8:49 AM	<b>Report #</b>	14207
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with EI's at the work trailer. SWPPP inspection area: LY29 AR-238.00 serving LY29 is in acceptable condition. Waste management is acceptable. House keeping is acceptable. CFS triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. There are no mechanical equipment stored in the yard. Rain gauge readings: Buffalo Anklets- 0.70" AR-238.00- 0.70"					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	9/1/2020 8:49 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Buffalo Anklets rain gauge reading- 0.70"	<b>Pic 2 Desc.</b>	AR-234.00 rain gauge reading- 0.70"		
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY-29- Materials storage	<b>Pic 4 Desc.</b>	LY-29 - CFS triple stack perimeter controls.		
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	LY-29- Culvert and drainage feature.	<b>Pic 6 Desc.</b>	AR-238.00 serving LY-29		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/1/2020 8:49 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/1/2020 8:49 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14219
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	9/1/2020 3:04 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.70
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Signage	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	9/1/2020 3:04 PM	<b>Report #</b>	14219
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist Collected rain gauge amounts, .7" recorded					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	9/1/2020 3:04 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+1	
Pic 1 Desc.	.6" of rain recorded		Pic 2 Desc.	.7" of rain recorded	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	Secondary containment	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/1/2020 3:04 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	9/1/2020 3:04 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14222
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	9/1/2020 3:36 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	9/1/2020 3:36 PM	<b>Report #</b>	14222
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Rain gauge at Catawba Road read 1.1 inched and rain gauge at Mount Tabor Road read 0.7 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	9/1/2020 3:36 PM	Report #	
Pictures					
<p>Date &amp; Time Tue, Sep 01, 2020, 09:44:35 EDT  Position: +027.319438° / -080.557480° ±0.150m  Altitude: 1846ft ±0.3m  Datum: WGS-84  Azimuth/Bearing: 315° N45W 5400mils True ±12.1°  Elevation Angle: -14.3°  Horizon Angle: -02.0°  Zoom: 1.0x  LDY 26</p>				<p>Date &amp; Time Tue, Sep 01, 2020, 09:44:13 EDT  Position: +027.319438° / -080.557480° ±0.150m  Altitude: 1855ft ±0.15m  Datum: WGS-84  Azimuth/Bearing: 275° N5W 4889mils True ±12.1°  Elevation Angle: -10.4°  Horizon Angle: -02.2°  Zoom: 1.0x  LDY 26</p>	
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack compost filter sock in place around drainage.		Pic 2 Desc.	RCE in place at LDY 26 entrance.	
<p>Date &amp; Time Tue, Sep 01, 2020, 09:45:45 EDT  Position: +027.319438° / -080.557480° ±0.150m  Altitude: 1850ft ±0.15m  Datum: WGS-84  Azimuth/Bearing: 115° S35E 3064mils True ±13.7°  Elevation Angle: -07.7°  Horizon Angle: -00.4°  Zoom: 1.0x  LDY 26</p>				<p>Date &amp; Time Tue, Sep 01, 2020, 09:46:30 EDT  Position: +027.319438° / -080.557480° ±0.150m  Altitude: 1850ft ±0.15m  Datum: WGS-84  Azimuth/Bearing: 329° S35E 1451mils True ±13.7°  Elevation Angle: -05.7°  Horizon Angle: -00.7°  Zoom: 1.0x  LDY 26</p>	
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Dumpsters being utilized for trash management.		Pic 4 Desc.	Secondary containment in place under fuel cell.	
<p>Date &amp; Time Tue, Sep 01, 2020, 10:47:30 EDT  Position: +027.319438° / -080.557480° ±0.150m  Altitude: 2015ft ±0.475m  Datum: WGS-84  Azimuth/Bearing: 015° N15E 0247mils True ±13.0°  Elevation Angle: -02.4°  Horizon Angle: -00.9°  Zoom: 1.0x  Labor</p>				<p>Date &amp; Time Tue, Sep 01, 2020, 10:47:00 EDT  Position: +027.319438° / -080.557480° ±0.150m  Altitude: 1924ft ±0.10m  Datum: WGS-84  Azimuth/Bearing: 114° S45E 3000mils True ±13.0°  Elevation Angle: -00.1°  Horizon Angle: -00.1°  Zoom: 1.0x  Catawba</p>	
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11990+00	
Pic 5 Desc.	Rain gauge at Mount Tabor Road reads 0.7 inches.		Pic 6 Desc.	Rain gauge at Catawba Road reads 1.1 inches.	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/1/2020 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/1/2020 3:36 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14244
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	9/2/2020 7:46 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	9/2/2020 7:46 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Sep 02, 2020, 07:46:00 EDT Position: +037.322730° / -080.552200° (-85.2m) Altitude: 2410ft (-634.3m) Datum: WGS-84 Azimuth/Bearing: 031° N31E 0551mils True (-14°) Elevation Angle: -12.3° Horizon Angle: -00.2° Zoom: 0.5X 11025+50</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 08:50:00 EDT Position: +037.374176° / -080.540000° (-83.2m) Altitude: 2521m (-824.9m) Datum: WGS-84 Azimuth/Bearing: 148° S148E 883mils True (-50°) Elevation Angle: -15.0° Horizon Angle: -00.1° Zoom: 1.0X 11034+00</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11025+50	<b>Field Station#</b>	11034+00		
<b>Pic 1 Desc.</b>	S-IJ18 and controls.	<b>Pic 2 Desc.</b>	Section of RoW showing conditions and controls.		
 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:04:00 EDT Position: +037.310000° / -080.549200° (-85.2m) Altitude: 2310ft (-693.0m) Datum: WGS-84 Azimuth/Bearing: 234° S234E 531mils True (-12°) Elevation Angle: -22° Horizon Angle: -02° Zoom: 0.8X 11049+00</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:14:00 EDT Position: +037.318166° / -080.547700° (-85.0m) Altitude: 2095ft (-638.5m) Datum: WGS-84 Azimuth/Bearing: 027° N27E 0480mils True (-12°) Elevation Angle: -21.7° Horizon Angle: -03.2° Zoom: 1.0X 11050+10</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11049+00	<b>Field Station#</b>	11050+10		
<b>Pic 3 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 4 Desc.</b>	S-IJ16B/S-IJ17 and controls.		
 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:39:10 EDT Position: +037.316950° / -080.545700° (-83.7m) Altitude: 2180ft (-664.3m) Datum: WGS-84 Azimuth/Bearing: 311° N311E 523mils True (-12°) Elevation Angle: -04.5° Horizon Angle: -00.2° Zoom: 0.5X 11058+00</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:44:00 EDT Position: +037.316510° / -080.546200° (-83.6m) Altitude: 2095ft (-638.5m) Datum: WGS-84 Azimuth/Bearing: -00° N00W 5023mils True (-13°) Elevation Angle: -10.0° Horizon Angle: -03.6° Zoom: 1.0X 11064+50</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11058+00	<b>Field Station#</b>	11064+50		
<b>Pic 5 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 7:46 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 7:46 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14252
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	9/2/2020 1:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+88
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10930+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	Yes
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	No
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	No
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	Yes



<b>AFE</b>	124300137	<b>Date/Time</b>	9/2/2020 1:14 PM	<b>Report #</b>	14252
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with EI's at work trailer.</p> <p>SWPPP inspection area: Sta#11023+88 to 10930+00. MP- 208.6 to 206.2</p> <p>The inspection area received 0.30" of rain overnight, the row is wet but in stable condition.</p> <p>Temporary stabilization is good, vegetation doing well.</p> <p>Perimeter controls, silt fence, CFS &amp; SSF are in acceptable condition.</p> <p>Water bars and sump pits and end treatments are in acceptable condition.</p> <p>Streams S- IJ18, S-RR5, S-E24, S- E25 are in good condition, buffers, bridges, ECD's are in acceptable condition.</p> <p>AR-244.00 and Doe Creek RCE are in acceptable condition.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	9/2/2020 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:30:54 EDT Position: +037.33250° / -080.556538° (Error) Altitude: 2024ft (+20m) Datum: WGS-84 Azimuth/Bearing: +62.5385° (338mils True) (+10°) Elevation Angle: -26.6° Horizon Angle: -00.2° Zoom: 1.0X Sta#10124-00- Stream S- IJ18</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:37:13 EDT Position: +037.332511° / -080.588362° (+0037.3325) Altitude: 2024ft (+20m) Datum: WGS-84 Azimuth/Bearing: 291° N49W 5173mils True (+10°) Elevation Angle: -08.2° Horizon Angle: -00.2° Zoom: 1.0X Sta#10121-00- Stream S- RR5</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11023+88	<b>Field Station#</b>	11017+00	<b>GPS Location</b>	See photo GPS
<b>Pic 1 Desc.</b>	AR-244- Stream S-IJ18	<b>Pic 2 Desc.</b>	Stream S- RR5, buffers & ECD's		
 <p>Date &amp; Time: Wed, Sep 02, 2020, 10:02:44 EDT Position: +037.344667° / -080.612182° (+32634.6ft) Altitude: 2647ft (+2693ft) Datum: WGS-84 Azimuth/Bearing: 282° N77W 5331mils True (+10°) Elevation Angle: -28.6° Horizon Angle: -01.7° Zoom: 1.0X Sta#10986-00- Stream S-E25</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 10:03:55 EDT Position: +037.325652° / -080.566922° (+33.8ft) Altitude: 2324ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 292° N47W 5209mils True (+10°) Elevation Angle: -16.5° Horizon Angle: -05.5° Zoom: 1.0X Sta#10985-00- Stream S- E24</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	10986+00	<b>Field Station#</b>	10985+00	<b>GPS Location</b>	See photo GPS
<b>Pic 3 Desc.</b>	Stream S- E25- Bridge & ECD's.	<b>Pic 4 Desc.</b>	Stream S- E24- Buffers, bridge & ECD's		
 <p>Date &amp; Time: Wed, Sep 02, 2020, 10:14:53 EDT Position: +037.329118° / -080.570147° (+98.4ft) Altitude: 1980ft (+1915ft) Datum: WGS-84 Azimuth/Bearing: 258° S78W 4587mils True (+10°) Elevation Angle: -20.8° Horizon Angle: -01.4° Zoom: 1.0X Sta#10969-00- LOD pyramid waddle</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 10:19:46 EDT Position: +037.322254° / -080.571453° (+98.4ft) Altitude: 2325ft (+22.5ft) Datum: WGS-84 Azimuth/Bearing: 339° N21W 4027mils True (+10°) Elevation Angle: -18.7° Horizon Angle: -00.8° Zoom: 1.0X Sta#10965-00- Sensitive resource ECD</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	10969+00	<b>Field Station#</b>	10965+00	<b>GPS Location</b>	See photo GPS
<b>Pic 5 Desc.</b>	LOD pyramid waddle	<b>Pic 6 Desc.</b>	Sensitive resource ECD's.		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14256
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	9/2/2020 2:26 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10850+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 2:26 PM	<b>Report #</b>	14256
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 205 - MP 207 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist Collected rain gauge amounts, .3" recorded @ Kow Camp					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	9/2/2020 2:26 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Sep 02, 2020, 07:18:44 EDT Position: +489.288361° / +680.367760° (+62.8°) Altitude: 2140ft (+611.5ft) Datum: WGS-84 Azimuth/Bearing: 283° N77W 593mils True (+13°) Elevation Grade: +001% Horizon Grade: -001% Zoom: 1.0x 3. kow</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 10:13:25 EDT Position: +487.787411° / +680.367760° (+62.8°) Altitude: 2080ft (+622.3ft) Datum: WGS-84 Azimuth/Bearing: 335° N25W 595mils True (+13°) Elevation Grade: +002% Horizon Grade: +003% Zoom: 1.0x 1" tabee</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	+1	
<b>Pic 1 Desc.</b>	.3" of rain recorded @ Kow Camp		<b>Pic 2 Desc.</b>	.1" of rain recorded @ Tabor	
 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:02:27 EDT Position: +447.355819° / +680.592117° (+62.8°) Altitude: 2050ft (+62.5ft) Datum: WGS-84 Azimuth/Bearing: 306° N54W 340mils True (+13°) Elevation Grade: -043% Horizon Grade: +000% Zoom: 1.0x 10858</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:15:48 EDT Position: +449.288361° / +680.592117° (+62.8°) Altitude: 2050ft (+62.5ft) Datum: WGS-84 Azimuth/Bearing: 100° S29E 100mils True (+13°) Elevation Grade: +24% Horizon Grade: +002% Zoom: 1.0x 10870</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10858+00		<b>Field Station#</b>	10870+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:08:01 EDT Position: +447.355819° / +680.592117° (+62.8°) Altitude: 2110ft (+643.0ft) Datum: WGS-84 Azimuth/Bearing: 124° S53E 320mils True (+13°) Elevation Grade: +000% Horizon Grade: +003% Zoom: 1.0x 10900</p>		 <p>Date &amp; Time: Wed, Sep 02, 2020, 09:41:34 EDT Position: +447.355819° / +680.592117° (+62.8°) Altitude: 2450ft (+746.7ft) Datum: WGS-84 Azimuth/Bearing: 166° N46E 117mils True (+13°) Elevation Grade: +07% Horizon Grade: +007% Zoom: 1.0x 10909</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	10900+00		<b>Field Station#</b>	10909+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 2:26 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 2:26 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14305
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	9/2/2020 3:23 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10750+00
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.05
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Flume Pipe	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 3:23 PM	<b>Report #</b>	14305
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection. Checked rain gauges at AR 234 - trace and at Buffalo Anklets Road - trace.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	9/2/2020 3:23 PM	Report #	
Pictures					
 <p>Date &amp; Time: Wed Sep 02 2020 09:58:19 EDT Position: -037.291046, -080.647227, 11.081107 Altitude: 2225ft (+88.5ft) Datum: WGS-84 Azimuth/Bearing: 152.528E 2702mils True (+12.1) Elevation Angle: -05.1 Horizon Angle: -00.9 Zoom: 1.0X AR 241.04</p>		 <p>Date &amp; Time: Wed Sep 02 2020 10:01:35 EDT Position: -037.245633, -080.647573, 11.284410 Altitude: 2292ft (+94.4ft) Datum: WGS-84 Azimuth/Bearing: 088° N88E 1544mils True (+12.1) Elevation Angle: -09.4 Horizon Angle: -00.9 Zoom: 1.0X 10712+50 S-G33</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10711+00		Field Station#	10712+50	
Pic 1 Desc.	CFS in place along AR 241.04.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-G33.	
 <p>Date &amp; Time: Wed Sep 02 2020 10:05:19 EDT Position: -037.245633, -080.652653, 11.284410 Altitude: 2292ft (+94.4ft) Datum: WGS-84 Azimuth/Bearing: 088° N88E 1544mils True (+12.1) Elevation Angle: -09.4 Horizon Angle: -00.9 Zoom: 1.0X 10696+00</p>		 <p>Date &amp; Time: Wed Sep 02 2020 10:08:06 EDT Position: -037.245633, -080.652653, 11.284410 Altitude: 2292ft (+94.4ft) Datum: WGS-84 Azimuth/Bearing: 088° N88E 1544mils True (+12.1) Elevation Angle: -09.4 Horizon Angle: -00.9 Zoom: 1.0X 10696+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10711+00		Field Station#	10696+00	
Pic 3 Desc.	ROW stabilized with natural vegetation growth.		Pic 4 Desc.	Rain gauge at Buffalo Anklets Road reads a trace amount.	
 <p>Date &amp; Time: Wed Sep 02 2020 10:12:45 EDT Position: -037.245633, -080.652653, 11.284410 Altitude: 2292ft (+94.4ft) Datum: WGS-84 Azimuth/Bearing: 120° S60E 2133mils True (+14.1) Elevation Angle: -11.7 Horizon Angle: -02.9 Zoom: 1.0X 10696+00</p>		 <p>Date &amp; Time: Wed Sep 02 2020 10:12:45 EDT Position: -037.245633, -080.652653, 11.284410 Altitude: 2292ft (+94.4ft) Datum: WGS-84 Azimuth/Bearing: 088° N88E 1544mils True (+12.1) Elevation Angle: -09.4 Horizon Angle: -00.9 Zoom: 1.0X AR 234</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10696+00		Field Station#	12005+00	
Pic 5 Desc.	RCE in place at Buffalo Anklets Road.		Pic 6 Desc.	Rain gauge at AR 234 reads a trace amount.	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/2/2020 3:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14282
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	9/3/2020 8:02 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			


## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 8:02 AM	<b>Report #</b>	14282
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met with EI's at Winding Way:          SWPPP inspection area: Sta#11254+99 to 11158+27. MP-213 to 211          The row was muddy and slick, but in stable condition.          The vegetation in some areas is sparse but straw mulch aids in stabilization, topsoil stockpiles are all very heavily vegetated.          Perimeter controls, silt fence, CFS &amp; SSF is in acceptable condition.          Slope drain pipes, CWD pipe and plunge pool are in acceptable condition.          Water bars, sump pits and end treatments are in acceptable condition.          Rock channel is in acceptable condition.          Access roads, Winding Way, AR-249.02 and AR-249.01 are in acceptable condition.          Sensitive resource area, drainage feature ECD's are in acceptable condition.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	9/3/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Sep 03, 2020 09:16:32 EDT  Position: +027.306112° / -080.501160° (+16.4ft)  Altitude: 1939ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 35° N35W 358mils True (+10)  Elevation Angle: -13.1°  Horizon Angle: +01.9°  Zoom: 1.0X  Sta#11224+00- Row is muddy &amp; slippery.</p> 		<p>Date &amp; Time: Thu, Sep 03, 2020 09:17:08 EDT  Position: +027.306112° / -080.501360° (+16.4ft)  Altitude: 1939ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 346° N14W 615mils True (+10)  Elevation Angle: -13.7°  Horizon Angle: +01.5°  Zoom: 1.0X  Sta#11224+00- P1 lod at very steep slope.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11227+00	<b>Field Station#</b>	11224+00		
<b>Pic 1 Desc.</b>	Row is muddy and slippery.	<b>Pic 2 Desc.</b>	P1 lod protecting steep slope		
<p>Date &amp; Time: Thu, Sep 03, 2020 09:31:40 EDT  Position: +027.306112° / -080.501660° (+16.4ft)  Altitude: 1939ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 286° N74W 508mils True (+10)  Elevation Angle: -03.6°  Horizon Angle: +02.9°  Zoom: 1.0X  Sta#11206+00- Topsoil stockpiles are heavily vegetated.</p> 		<p>Date &amp; Time: Thu, Sep 03, 2020 09:34:33 EDT  Position: +037.305226° / -080.507166° (+32.3ft)  Altitude: 2038ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 171° S09E 3040mils True (+10)  Elevation Angle: -20.8°  Horizon Angle: +00.2°  Zoom: 1.0X  Sta#11200+00- Water bars on slope.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11206+00	<b>Field Station#</b>	11200+00		
<b>Pic 3 Desc.</b>	Topsoil stockpiles are heavily vegetated.	<b>Pic 4 Desc.</b>	Water bars on slope.		
<p>Date &amp; Time: Thu, Sep 03, 2020 09:42:49 EDT  Position: +037.304521° / -080.510127° (+16.4ft)  Altitude: 1945ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 106° S74E 1834mils True (+10)  Elevation Angle: -08.6°  Horizon Angle: +02.5°  Zoom: 1.0X  Sta#11190+00- Sensitive resource area, row and drainage feature ECD's.</p> 		<p>Date &amp; Time: Thu, Sep 03, 2020 09:44:35 EDT  Position: +037.302510° / -080.511953° (+16.4ft)  Altitude: 1945ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 213° S33W 3787mils True (+10)  Elevation Angle: -29.4°  Horizon Angle: +00.9°  Zoom: 1.0X  Sta#11184+00- CWD pipe and plunge pool controls.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11190+00	<b>Field Station#</b>	11184+00		
<b>Pic 5 Desc.</b>	Sensitive resource area, row and drainage feature ECD's.	<b>Pic 6 Desc.</b>	CWD pipe and plunge pool.		

<b>AFE</b>	124300137	<b>Date/Time</b>	9/3/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>			
<b>Field Station#</b>	11172+70	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Slope drain pipe, checks, sump pits, end treatment.	<b>Pic 8 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 8:02 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14304
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	9/3/2020 2:23 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Slope Drain Pipe	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Temporary Diversion Berm	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 2:23 PM	<b>Report #</b>	14304
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213.16 to MP 215.03 as well as assessed AR 256.02. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	9/3/2020 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Sep 03, 2020, 09:22:50 EDT Position: +037.290123 / -080.482771 (+26.5ft) Altitude: 2109ft (+70.0ft) Datum: WGS-84 Azimuth/Bearing: 145 S38E 2578mils True (+12°) Elevation Angle: +37.6° Horizon Angle: +00.9° Zoom: 0.5X S-MM18</p>		 <p>Date &amp; Time: Thu, Sep 03, 2020, 09:23:24 EDT Position: +037.295900 / -080.483041 (+19.4ft) Altitude: 2219ft (+116.9ft) Datum: WGS-84 Azimuth/Bearing: 145 S38E 2578mils True (+12°) Elevation Angle: +37.6° Horizon Angle: +00.9° Zoom: 0.5X S-MM18</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11258+00	<b>Field Station#</b>	11292+80		
<b>Pic 1 Desc.</b>	Clearing stop/skip location.	<b>Pic 2 Desc.</b>	S-MM18 and controls.		
 <p>Date &amp; Time: Thu, Sep 03, 2020, 09:19:21 EDT Position: +037.290123 / -080.488004 (+162.0ft) Altitude: 2383ft (+70.0ft) Datum: WGS-84 Azimuth/Bearing: 358 N02W 6364mils True (+12°) Elevation Angle: +37.6° Horizon Angle: +09.8° Zoom: 0.5X 11286+00</p>		 <p>Date &amp; Time: Thu, Sep 03, 2020, 09:19:30 EDT Position: +037.304707 / -080.484404 (+202.0ft) Altitude: 2109ft (+72.4ft) Datum: WGS-84 Azimuth/Bearing: 145 S18E 2933mils True (+12°) Elevation Angle: +09.8° Horizon Angle: +04.1° Zoom: 0.5X S-NN12</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11286+00	<b>Field Station#</b>	11327+85		
<b>Pic 3 Desc.</b>	Perimeter controls functional.	<b>Pic 4 Desc.</b>	S-NN12 and controls.		
 <p>Date &amp; Time: Thu, Sep 03, 2020, 08:34:25 EDT Position: +037.355579 / -080.467269 (+17.1ft) Altitude: 2020ft (+3.4ft) Datum: WGS-84 Azimuth/Bearing: 154 S14E 2251mils True (+12°) Elevation Angle: +29.6° Horizon Angle: +10° Zoom: 0.5X S-NN11</p>		 <p>Date &amp; Time: Thu, Sep 03, 2020, 08:31:57 EDT Position: +037.349727 / -080.468107 (+14.4ft) Altitude: 2020ft (+3.4ft) Datum: WGS-84 Azimuth/Bearing: 032 N02E 4629mils True (+15°) Elevation Angle: +26.1° Horizon Angle: +03.7° Zoom: 0.5X 11349+00</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11352+97	<b>Field Station#</b>	11349+00		
<b>Pic 5 Desc.</b>	S-NN11 and controls.	<b>Pic 6 Desc.</b>	Perimeter controls functional.		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14306
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	9/3/2020 3:38 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11158+27
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 3:38 PM	<b>Report #</b>	14306
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 209 - MP 211.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist Collected rain gauge amounts, .2" recorded @ Kow Camp					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	9/3/2020 3:38 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	+1		<b>Field Station#</b>	11067+00	
<b>Pic 1 Desc.</b>	.2" of rain recorded		<b>Pic 2 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11082+00		<b>Field Station#</b>	11099+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11130+00		<b>Field Station#</b>	11140+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 3:38 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 3:38 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14320
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	9/3/2020 3:49 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+20
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 3:49 PM	<b>Report #</b>	14320
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Stevers Gap Road - 0.3 inches, Mount Tabor Road - 0.1 inches, and Catawba Road - trace.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	9/3/2020 3:49 PM	Report #	
Pictures					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11507+00		<b>Field Station#</b>	11489+00	
<b>Pic 1 Desc.</b>	Clean water diversion pipe and plunge pool in place.		<b>Pic 2 Desc.</b>	RCE in place at Stevers Gap Road.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11489+00		<b>Field Station#</b>	11474+00	
<b>Pic 3 Desc.</b>	Rain gauge at Stevers Gap Rad reads 0.3 inches.		<b>Pic 4 Desc.</b>	Two-tone stabilized with ECB.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11990+00	
<b>Pic 5 Desc.</b>	Rain gauge at Mount Tabor Road reads 0.1 inches.		<b>Pic 6 Desc.</b>	Rain gauge at Catawba Road reads a trace amount.	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 3:49 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/3/2020 3:49 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14342
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	9/4/2020 11:30 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 11:30 AM	<b>Report #</b>	14342
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a regular scheduled VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. ECDs were found in place, functional and in good condition. The ROW surface is currently stable with no areas of erosion located. No slips have occurred and no sediment located beyond LOD. Resource crossings show no impact and buffers are stable with ECDs in place. RCEs in good condition. No evidence of vandalism or trespass located.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 9/4/2020 11:30 AM		Report #	
Pictures					
<p>Date &amp; Time: Fri, Sep 04, 2020, 09:21:36 EDT Position: +037.2026927° / -080.3996444° (±32.8ft) Altitude: 2726ft (±32.8ft) Datum: WGS-84 Azimuth/Bearing: 190° S08E 2647ft/mile Magnetic (±12°) Elevation Angle: +01.6° Horizon Angle: -04.3° Zoom: 1.0X ROW stable. Slope breakers functional.</p> 		<p>Date &amp; Time: Fri, Sep 04, 2020, 09:26:07 EDT Position: +037.20468° / -080.396075° (±16.4m) Altitude: 2706ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 249° S64W 442ft/mile Magnetic (±12°) Elevation Angle: -01° Horizon Angle: 00.0° Zoom: 1.0X Perimeter controls in place. 11663+00</p> 			
GPS Location		On photo		GPS Location	
Field Station#		11665+00		Field Station#	
Pic 1 Desc.		ROW stable. ECDs in place.		Pic 2 Desc.	
<p>Date &amp; Time: Fri, Sep 04, 2020, 09:35:47 EDT Position: +037.304651° / -080.397684° (±16.4m) Altitude: 2447ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 328° S31W 344ft/mile Magnetic (±13°) Elevation Angle: -01° Horizon Angle: -02.7° Zoom: 1.0X ROW stable. Perimeter controls in place. 11665+00</p> 		<p>Date &amp; Time: Fri, Sep 04, 2020, 09:40:01 EDT Position: +037.310016° / -080.397572° (±32.8ft) Altitude: 2371ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 199° S03E 3147ft/mile Magnetic (±14°) Elevation Angle: +01.6° Horizon Angle: -02.7° Zoom: 1.0X ROW stable. Perimeter controls in place. 11642+00</p> 			
GPS Location		On photo		GPS Location	
Field Station#		11655+00		Field Station#	
Pic 3 Desc.		Perimeter controls are in place.		Pic 4 Desc.	
<p>Date &amp; Time: Fri, Sep 04, 2020, 09:48:00 EDT Position: +037.310016° / -080.397572° (±32.8ft) Altitude: 2371ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 199° S03E 3147ft/mile Magnetic (±14°) Elevation Angle: +01.6° Horizon Angle: -02.7° Zoom: 1.0X ROW stable. Perimeter controls in place. 11642+00</p> 		<p>Date &amp; Time: Fri, Sep 04, 2020, 09:48:01 EDT Position: +037.310016° / -080.397572° (±32.8ft) Altitude: 2371ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 199° S03E 3147ft/mile Magnetic (±14°) Elevation Angle: +01.6° Horizon Angle: -02.7° Zoom: 1.0X ROW stable. Perimeter controls in place. 11642+00</p> 			
GPS Location		On photo		GPS Location	
Field Station#		11630+00		Field Station#	
Pic 5 Desc.		Perimeter controls are in place		Pic 6 Desc.	



<b>AFE</b>	124300137	<b>Date/Time</b>	9/4/2020 11:30 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+20		
<b>Pic 7 Desc.</b>	S-HH18 crossing stable with ECDs in place	<b>Pic 8 Desc.</b>	S-RR14 crossing stable with ECDs in place		
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11613+69	<b>Field Station#</b>	11608+17		
<b>Pic 9 Desc.</b>	S-RR13 at access road MN-258.04 stable with ECDs in place	<b>Pic 10 Desc.</b>	S-006 crossing stable with ECDs in place		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 11:30 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14349
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	9/4/2020 1:56 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Broad-Based Dip	Acceptable			
Culvert	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	9/4/2020 1:56 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Sep 04, 2020, 11:01:30 EDT Position: 437.29735, -80.31331, 143.400 Altitude: 2277ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 307° N 69° 04.83mils True (+10°) Elevation Angle: -28.2° Horizon Angle: -10.7° Zoom: 1.0x Sta#119001+00- Access road and controls.</p>		 <p>Date &amp; Time: Fri, Sep 04, 2020, 11:21:19 EDT Position: 437.26260, -80.32632, 143.400 Altitude: 2277ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 138° S 42E 2453mils True (+10°) Elevation Angle: -26.6° Horizon Angle: -10.7° Zoom: 1.0x Sta#11933+00- Row Vegetation is very good.</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	119001+00	<b>Field Station#</b>	11933+00	<b>GPS Location</b>	See photo GPS
<b>Pic 1 Desc.</b>	AR-266.03- Access road and controls.	<b>Pic 2 Desc.</b>	Row vegetation is very good.	<b>GPS Location</b>	See photo GPS
 <p>Date &amp; Time: Fri, Sep 04, 2020, 11:24:01 EDT Position: 437.27263, -80.32762, 143.400 Altitude: 2066ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 185° S 05W 389mils True (+10°) Elevation Angle: -12.4° Horizon Angle: -10.0° Zoom: 1.0x Sta#11942+00- Karst ECD's</p>		 <p>Date &amp; Time: Fri, Sep 04, 2020, 11:24:24 EDT Position: 437.27263, -80.32762, 143.400 Altitude: 2066ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 025° N 35E 0644mils True (+25°) Elevation Angle: -13.2° Horizon Angle: -0.3° Zoom: 1.0x Sta#11950+00- Size and depth of subsidence is unchanged.</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11942+00	<b>Field Station#</b>	11950+00	<b>GPS Location</b>	See photo GPS
<b>Pic 3 Desc.</b>	Karst ECD's are in acceptable condition.	<b>Pic 4 Desc.</b>	Size and depth of subsidence remains unchanged.	<b>GPS Location</b>	See photo GPS
 <p>Date &amp; Time: Fri, Sep 04, 2020, 11:39:04 EDT Position: 437.27122, -80.32269, 143.400 Altitude: 1809ft (+79.7ft) Datum: WGS-84 Azimuth/Bearing: 155° S 25E 2784mils True (+10°) Elevation Angle: -28.1° Horizon Angle: -10.4° Zoom: 1.0x Sta#11974+00- View of row, water bars and vegetation are in acceptable condition.</p>		 <p>Date &amp; Time: Fri, Sep 04, 2020, 11:39:45 EDT Position: 437.24849, -80.32700, 143.400 Altitude: 1634ft (+79.7ft) Datum: WGS-84 Azimuth/Bearing: 146° S 34E 2576mils True (+10°) Elevation Angle: -17.0° Horizon Angle: -10.7° Zoom: 1.0x Sta#11986+00- Drainage feature ECD's</p>		<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11974+00	<b>Field Station#</b>	11986+00	<b>GPS Location</b>	See photo GPS
<b>Pic 5 Desc.</b>	View of the row, water bars and vegetation are in acceptable condition.	<b>Pic 6 Desc.</b>	Drainage feature ECD's	<b>GPS Location</b>	See photo GPS

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 1:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 1:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14351
<b>Inspector</b>	Garrett Barclay			<b>Date/Time</b>	9/4/2020 3:25 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Craig	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 3:25 PM	<b>Report #</b>	14351
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 218 + MP 219.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punchlist					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 3:25 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Sep 04, 2020 05:41:26 EDT Position: +039.321032 / -080.412989 / +15.31m Altitude: 2534ft (+11.4m) Datum: WGS-84 Azimuth/Bearing: 131° S30E 330mils True (+13°) Elevation Grade: +01% Horizon Grade: +01% Zoom: 1.0X 11530</p>		 <p>Date &amp; Time: Fri, Sep 04, 2020 05:02:09 EDT Position: +037.325419 / -080.414290 / +15.41m Altitude: 2768ft (+7.1m) Datum: WGS-84 Azimuth/Bearing: 331° N29W 388mils True (+16°) Elevation Grade: +03% Horizon Grade: +00% Zoom: 1.0X 11551</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11530+00		<b>Field Station#</b>	11551+00	
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions	
 <p>Date &amp; Time: Fri, Sep 04, 2020 07:12:18 EDT Position: +039.321032 / -080.412989 / +15.31m Altitude: 2534ft (+11.4m) Datum: WGS-84 Azimuth/Bearing: 119° S41E 211mils True (+13°) Elevation Grade: +04% Horizon Grade: +00% Zoom: 1.0X 11567spz22</p>		 <p>Date &amp; Time: Fri, Sep 04, 2020 05:00:00 EDT Position: +037.325419 / -080.414290 / +15.41m Altitude: 2768ft (+7.1m) Datum: WGS-84 Azimuth/Bearing: 331° N29W 388mils True (+16°) Elevation Grade: +03% Horizon Grade: +00% Zoom: 1.0X 11548</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11567+00		<b>Field Station#</b>	11548+00	
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions	
 <p>Date &amp; Time: Fri, Sep 04, 2020 09:20:02 EDT Position: +039.321032 / -080.411999 / +15.31m Altitude: 2534ft (+11.4m) Datum: WGS-84 Azimuth/Bearing: 070° N02E 264mils True (+14°) Elevation Grade: +01% Horizon Grade: +01% Zoom: 1.0X 11574</p>		 <p>Date &amp; Time: Fri, Sep 04, 2020 05:28:31 EDT Position: +037.325419 / -080.414290 / +15.41m Altitude: 2768ft (+7.1m) Datum: WGS-84 Azimuth/Bearing: 127° S30E 225mils True (+14°) Elevation Grade: +01% Horizon Grade: +01% Zoom: 1.0X 11585 app 21-20</p>			
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates	
<b>Field Station#</b>	11574+00		<b>Field Station#</b>	11585+00	
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 3:25 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 3:25 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14352
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	9/4/2020 3:58 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+99
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 3:58 PM	<b>Report #</b>	14352
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.27 to MP 225.37 as well as assessed AR 266.03. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 3:58 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11792+00	<b>Field Station#</b>	11826+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11849+00	<b>Field Station#</b>	11863+65		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	P-KL2 and controls.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11873+00	<b>Field Station#</b>	11899+50		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 3:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 3:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	14382
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	9/4/2020 4:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+50
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 4:18 PM	<b>Report #</b>	14382
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection. Environmental crew currently working on re stabilizing area.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	9/4/2020 4:18 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11670+00		<b>Field Station#</b>	11672+00	
<b>Pic 1 Desc.</b>	Triple stack compost filter sock and priority one silt fence in place along LOD.		<b>Pic 2 Desc.</b>	ROW stabilized with seed and mulch.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11687+40	
<b>Pic 3 Desc.</b>	RCE in place at Main Line Valve 26.		<b>Pic 4 Desc.</b>	Sensitive resource buffer in place at stream S-MN21.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11778+00		<b>Field Station#</b>	11776+00	
<b>Pic 5 Desc.</b>	Clean water diversion pipe and plunge pool in place.		<b>Pic 6 Desc.</b>	Reinforced super silt fence in place along LOD.	

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 4:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	9/4/2020 4:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		