



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19584	
Inspector Chris Burns		Date/Time 2/1/2021 11:46 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11254+99	
State VA	Inspection Area Partial	Station End 11353+67	
County Giles	Ground Frozen	Temperature (°F) 36.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/1/2021 11:46 AM	Report # 19584
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection from MP 213.16 to MP 215.03.
 No issues were located.
 Ground covered with 4 to 6 inches of snow hindering visibility for inspection.
 All visible perimeter controls, ECDs and BMPs are functional.
 No impact to sensitive resources observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/1/2021 11:46 AM		Report #	
Pictures					
					
GPS Location 1		GPS Location 2			
Field Station# 11263+00		Field Station# 11292+80			
Pic 1 Desc. Section of RoW showing conditions and controls.		Pic 2 Desc. S-MM18 and controls.			
					
GPS Location 3		GPS Location 4			
Field Station# 11297+00		Field Station# 11327+85			
Pic 3 Desc. Equipment and materials staged.		Pic 4 Desc. S-NN12 and controls.			
					
GPS Location 5		GPS Location 6			
Field Station# 11350+00		Field Station# 11352+97			
Pic 5 Desc. Section of RoW showing conditions and controls.		Pic 6 Desc. S-NN11.			

AFE 124300137	Date/Time 2/1/2021 11:46 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/1/2021 11:46 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19597	
Inspector Len Kruizenga		Date/Time 2/1/2021 2:09 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11254+99	
State VA	Inspection Area Full	Station End 11158+27	
County Giles	Ground Frozen	Temperature (°F) 31.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/1/2021 2:09 PM	Report # 19597
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Met with EI's at Winding Way:
 SWPPP inspection area: Sta#11254+99 to 11158+27. MP- 213 to 211
 Row is snow covered after weekend snow event.
 Perimeter controls are in acceptable condition,
 Water bars and sump pits are in acceptable condition.
 CFS perimeter controls and end treatments are covered up by snow.
 Slope drain pipes are in acceptable condition.
 CWD pipe and plunge pool are in good condition.
 Rock channel is in acceptable condition.
 Access roads- Winding Way, AR-249.02, AR-249.01 are in acceptable condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/1/2021 2:09 PM		Report #	
Pictures					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11237+00	Field Station#	11217+00		
Pic 1 Desc.	Snow covered row and controls.	Pic 2 Desc.	Water bar, sump pit and triple stack end treatment under snow.		
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11191+00	Field Station#	11184+00		
Pic 3 Desc.	Sensitive resource area/ drainage feature.	Pic 4 Desc.	CWD pipe and plunge pool.		
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11172+70	Field Station#	11169+00		
Pic 5 Desc.	Slope drain inlet	Pic 6 Desc.	P1 perimeter controls.		

AFE 124300137	Date/Time 2/1/2021 2:09 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	2/1/2021 2:09 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19601	
Inspector Jared Saunders		Date/Time 2/1/2021 3:19 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11353+64
State VA	Inspection Area Partial	Station End	11524+16
County Giles	Ground Frozen	Temperature (°F)	35.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300137	Date/Time	2/1/2021 3:19 PM	Report #	19601
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from MP 215 to MP 218.3.
 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.
 No forward progress has been completed due to FERC shut down.
 Right of way has been stabilized using seed, mulch, and natural vegetation.
 No deficiencies located during VA SWPPP inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/1/2021 3:19 PM	Report #
Pictures				
 <p><small>Date & Time: Mon, Feb 01, 2021 09:02:38 EST Position: +037 329184 / -080 421114 / +16421.4ft Altitude: 2234ft (+152.9m) Datum: WGS-84 Azimuth/Bearing: 356° N04W 6329mils True (+14°) Elevation Angle: -10.5° Horizon Angle: +04.0° Zoom: 1.0X 11506+00</small></p>		 <p><small>Date & Time: Mon, Feb 01, 2021 09:02:38 EST Position: +037 329184 / -080 421114 / +16421.4ft Altitude: 2234ft (+152.9m) Datum: WGS-84 Azimuth/Bearing: 183° S08W 3253mils True (+14°) Elevation Angle: -02.9° Horizon Angle: -00.4° Zoom: 1.0X 11506+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11506+00	Field Station#	11506+00	
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.	Pic 2 Desc.	Clean water diversion pipe and clean water diversion berm in place.	
 <p><small>Date & Time: Mon, Feb 01, 2021 09:15:19 EST Position: +037 329201 / -080 421061 / +16421.4ft Altitude: 2215ft (+86.2m) Datum: WGS-84 Azimuth/Bearing: 239° S59W 4018mils True (+18°) Elevation Angle: -11.2° Horizon Angle: -01.2° Zoom: 1.0X 11490+00</small></p>		 <p><small>Date & Time: Mon, Feb 01, 2021 09:28:34 EST Position: +037 316716 / -080 465553 / +321423.5ft Altitude: 2215ft (+86.2m) Datum: WGS-84 Azimuth/Bearing: 276° N84W 4907mils True (+15°) Elevation Angle: -05.4° Horizon Angle: -00.7° Zoom: 1.0X 11473+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11490+00	Field Station#	11473+00	
Pic 3 Desc.	RCE in place at Stevers Gap Road.	Pic 4 Desc.	Slope drains in place over two-tone.	
 <p><small>Date & Time: Mon, Feb 01, 2021 10:02:48 EST Position: +030 3333647 / -080 426807 / +62833.0m Altitude: 2127ft (+64.2m) Datum: WGS-84 Azimuth/Bearing: 084° N84E 1693mils True (+14°) Elevation Angle: -07.9° Horizon Angle: +01.4° Zoom: 1.0X 11428+00</small></p>		 <p><small>Date & Time: Mon, Feb 01, 2021 10:02:48 EST Position: +030 3333647 / -080 426807 / +62833.0m Altitude: 2127ft (+64.2m) Datum: WGS-84 Azimuth/Bearing: 200° S20W 4087mils True (+14°) Elevation Angle: -04.1° Horizon Angle: +01.5° Zoom: 1.0X 11380+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11428+00	Field Station#	11380+00	
Pic 5 Desc.	ROW frozen and snow covered.	Pic 6 Desc.	Triple barrier ECDs in place at off ROW karst feature.	

AFE 124300137	Date/Time 2/1/2021 3:19 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	2/1/2021 3:19 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19602	
Inspector Garrett Barclay		Date/Time 2/1/2021 3:26 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11064+53
State VA	Inspection Area Partial	Station End	11158+27
County Giles	Ground Frozen	Temperature (°F)	28.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300137	Date/Time 2/1/2021 3:26 PM	Report # 19602
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting
 Performed SWPPP for MP 209 - MP 211
 No damaged ECD's observed during inspection
 ROW conditions are stable and showing minimal signs of erosion
 No items added to the punch list

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/1/2021 3:26 PM		Report #	
Pictures					
 <p><small>Date & Time: Mon, Feb 01, 2021, 09:06:57 EST Position: +46.310222° / +80.02222° (s10-10) Altitude: 2153ft (s11.2ft) Datum: WGS-84 Azimuth Bearing: 225° (225° 000mils True (s15°)) Elevation Grade: -0.0% Horizon Grade: +0.0% Zoom: 1.0X 11066</small></p>		 <p><small>Date & Time: Mon, Feb 01, 2021, 09:10:05 EST Position: +46.310222° / +80.02222° (s10-10) Altitude: 2153ft (s11.2ft) Datum: WGS-84 Azimuth Bearing: 225° (225° 000mils True (s15°)) Elevation Grade: -0.0% Horizon Grade: +0.0% Zoom: 1.0X 11088</small></p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11066+00		Field Station#	11088+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
 <p><small>Date & Time: Mon, Feb 01, 2021, 09:10:43 EST Position: +46.310222° / +80.02222° (s10-10) Altitude: 2153ft (s11.2ft) Datum: WGS-84 Azimuth Bearing: 225° (225° 000mils True (s15°)) Elevation Grade: -0.0% Horizon Grade: +0.0% Zoom: 1.0X 11098</small></p>		 <p><small>Date & Time: Mon, Feb 01, 2021, 09:10:15 EST Position: +46.310222° / +80.02222° (s10-10) Altitude: 2153ft (s11.2ft) Datum: WGS-84 Azimuth Bearing: 225° (225° 000mils True (s15°)) Elevation Grade: -0.0% Horizon Grade: +0.0% Zoom: 1.0X 11111-00</small></p>			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11098+00		Field Station#	11111+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
 <p><small>Date & Time: Mon, Feb 01, 2021, 03:20:22 EST Position: +46.310222° / +80.02222° (s10-10) Altitude: 2153ft (s11.2ft) Datum: WGS-84 Azimuth Bearing: 225° (225° 000mils True (s15°)) Elevation Grade: -0.0% Horizon Grade: +0.0% Zoom: 1.0X 11540</small></p>		<p style="text-align: center;">Insert image here</p>			
GPS Location	See picture above for GPS coordinates		GPS Location		
Field Station#	11540+00		Field Station#		
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.		

AFE 124300137	Date/Time 2/1/2021 3:26 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/1/2021 3:26 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19636	
Inspector Rob Robertson		Date/Time 2/2/2021 12:54 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11600+01
State VA	Inspection Area Full	Station End	11670+00
County Montgomery	Ground Frozen	Temperature (°F)	27.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/2/2021 12:54 PM	Report # 19636
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

A regular scheduled VADEQ SWPPP inspection was completed today on JNF and private lands on Brush Mountain. The ROW surface is frozen and covered with approximately 5" of snow making it very difficult to inspect the condition of ECDs. Confirmed that environmental controls are in place on the perimeter of LOD and at all resource crossings. No runoff is occurring due to frozen conditions. No evidence of failed ECDs or slips was discovered. Resource crossings and associated buffers are currently stable with no apparent impact. Equipment bridges have required environmental controls. No evidence of vandalism or trespass was identified.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/2/2021 12:54 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	On photo	GPS Location	On photo
Field Station#	11665+00	Field Station#	11626+04
Pic 1 Desc.	ROW stable with perimeter controls in place. Ground frozen with no runoff occurring.	Pic 2 Desc.	The S-HH18 crossing is stable, ECDs in place and no visible impact.



GPS Location	On photo	GPS Location	On photo
Field Station#	11625+00	Field Station#	11614+20
Pic 3 Desc.	Frozen conditions. ROW stable with no runoff. ECDs are in place.	Pic 4 Desc.	S-RR14 crossing and buffer currently stable with ECDs in place.



GPS Location	On photo	GPS Location	On photo
Field Station#	11613+69	Field Station#	11608+17
Pic 5 Desc.	S-RR13 crossing at access road MN-258.04 stable with ECDs in place.	Pic 6 Desc.	The S-006 crossing and buffer zone is stable with ECDs in place.

AFE 124300137	Date/Time 2/2/2021 12:54 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/2/2021 12:54 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19640	
Inspector Len Kruizenga		Date/Time 2/2/2021 1:49 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11899+99	
State VA	Inspection Area Full	Station End 12005+00	
County Montgomery	Ground Frozen	Temperature (°F) 27.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar Outlet Protection	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/2/2021 1:49 PM	Report # 19640
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection area: Sta# 11899+99 to 12005+00. MP- 225.3 to 227.3
 The row is blanketed with about 5" of snow with a crust making walking more difficult. Twenty to thirty mile an hour sustained with forty to fifty mile gusts forecasted.
 CFS perimeter controls and water bar outlet protection is covered in snow, silt fence and SSF ECD's are in acceptable condition.
 Water bars and level spreaders are in acceptable condition.
 No issues observed with the row condition.
 Karst ECD's are in acceptable condition.
 AR-266.03 is snow and ice covered, broad based dips and end treatments are in acceptable condition.
 AR-266.00 is in acceptable condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/2/2021 1:49 PM		Report #	
Pictures					
 <p>Date & Time: Tue, Feb 02, 2021, 08:39:11 EST Position: +037.237724 / -080.334405 (-124.9ft) Altitude: 2204ft (-24.5m) Datum: WGS-84 Azimuth/Bearing: 124° S56E 2204mils True (+16°) Elevation Angle: -07.4° Horizon Angle: +07.0° Stair# 11919+00- CFS water bar outlet under snow</p>		 <p>Date & Time: Tue, Feb 02, 2021, 08:39:19 EST Position: +037.237712 / -080.331452 (-124.9ft) Altitude: 2204ft (-24.5m) Datum: WGS-84 Azimuth/Bearing: 124° S56E 2204mils True (+16°) Elevation Angle: -07.4° Horizon Angle: +07.0° Stair# 11919+00- CFS water bar outlet under snow</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11900+00	Field Station#	11919+00		
Pic 1 Desc.	AR-266.00 is snow covered	Pic 2 Desc.	CFS water bar outlet protection is under snow		
 <p>Date & Time: Tue, Feb 02, 2021, 09:45:05 EST Position: +039.283554° / +080.328107° (-121.8ft) Altitude: 2271ft (-65.3ft) Datum: WGS-84 Azimuth/Bearing: 165° S15E 2933mils True (+16°) Elevation Angle: -16.3° Horizon Angle: +03.7° Stair# 11932+00- P1 dissipaters on slope</p>		 <p>Date & Time: Tue, Feb 02, 2021, 09:45:05 EST Position: +039.283554° / +080.328107° (-121.8ft) Altitude: 2271ft (-65.3ft) Datum: WGS-84 Azimuth/Bearing: 165° S15E 2933mils True (+16°) Elevation Angle: -16.3° Horizon Angle: +03.7° Stair# 11942+00- Karst ECD's</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11932+00	Field Station#	11942+00		
Pic 3 Desc.	P1 dissipater,s on slope	Pic 4 Desc.	Karst ECD's		
 <p>Date & Time: Tue, Feb 02, 2021, 09:35:07 EST Position: +037.270121 / -080.323148 (-875.6ft) Altitude: 1713ft (-247.9ft) Datum: WGS-84 Azimuth/Bearing: 165° S15E 2933mils True (+16°) Elevation Angle: -15.0° Horizon Angle: +00.5° Stair# 11952+00- Row view</p>		 <p>Date & Time: Tue, Feb 02, 2021, 09:35:07 EST Position: +037.270121 / -080.323148 (-875.6ft) Altitude: 1713ft (-247.9ft) Datum: WGS-84 Azimuth/Bearing: 160° S40E 2689mils True (+16°) Elevation Angle: -18.0° Horizon Angle: +00.8° Stair# 11977+00- Karst ECD's</p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11952+00	Field Station#	11977+00		
Pic 5 Desc.	Broad view of the row	Pic 6 Desc.	Karst ECD's and sensitive resource signage.		

AFE 124300137	Date/Time 2/2/2021 1:49 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	2/2/2021 1:49 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19642	
Inspector Chris Burns		Date/Time 2/2/2021 2:50 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11788+52	
State VA	Inspection Area Partial	Station End 11899+99	
County Montgomery	Ground Frozen	Temperature (°F) 29.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/2/2021 2:50 PM	Report # 19642
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection from MP 223.27 to MP 225.37 as well as assessed AR 266.03.
 Ground covered in 3 to 5 inches of snow hindering visibility for inspection.
 No issues were located.
 All visible perimeter controls, ECDs and BMPs are functional.
 No impact to sensitive resources observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/2/2021 2:50 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11792+00	Field Station#	11818+00		
Pic 1 Desc.	Section of restored RoW showing conditions and controls.	Pic 2 Desc.	Section of restored RoW showing conditions and controls.		
					
GPS Location	3	GPS Location	4		
Field Station#	11841+00	Field Station#	11863+65		
Pic 3 Desc.	Section of restored RoW showing conditions and controls.	Pic 4 Desc.	P-KL2.		
					
GPS Location	5	GPS Location	6		
Field Station#	11886+00	Field Station#	11899+99		
Pic 5 Desc.	Section of restored RoW showing conditions and controls.	Pic 6 Desc.	Section of restored RoW showing conditions and controls.		

AFE 124300137	Date/Time 2/2/2021 2:50 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	2/2/2021 2:50 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19643	
Inspector Jared Saunders		Date/Time 2/2/2021 3:09 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11670+00
State VA	Inspection Area Partial	Station End	11788+50
County Montgomery	Ground Frozen	Temperature (°F)	25.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/2/2021 3:09 PM	Report # 19643
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from MP 221 to MP 223.8.
 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.
 No forward progress has been completed due to FERC shut down.
 ROW has been stabilized using seed, mulch, and minor vegetation growth.
 No deficiencies located during VA SWPPP inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/2/2021 3:09 PM		Report #			
Pictures							
 <p>Date & Time: Tue, Feb 02, 2021, 09:50:00 EST Position: +037.232933° / -080.407033° (+6394.970) Altitude: 2739ft (+32.6ft) Datum: WGS-84 Azimuth/Bearing: 090 S90E 1600mils True (+13.1) Elevation Angle: -13.6° Horizon Angle: -03.1° Zoom: 1.0X 11672+00</p>		 <p>Date & Time: Tue, Feb 02, 2021, 09:50:00 EST Position: +037.232933° / -080.407033° (+6394.970) Altitude: 2739ft (+32.6ft) Datum: WGS-84 Azimuth/Bearing: 090 S90E 1600mils True (+13.1) Elevation Angle: -13.6° Horizon Angle: -03.1° Zoom: 1.0X 11672+00</p>		 <p>Date & Time: Tue, Feb 02, 2021, 09:53:33 EST Position: +037.229145° / -080.381376° (+6422.148) Altitude: 2483ft (+32.2ft) Datum: WGS-84 Azimuth/Bearing: 228 N228E 1038mils True (+13.1) Elevation Angle: -20.2° Horizon Angle: -00.2° Zoom: 1.0X 11687+00</p>		 <p>Date & Time: Tue, Feb 02, 2021, 10:18:12 EST Position: +037.294552° / -080.379008° (+8336.44ft) Altitude: 2275ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 057 N57E 1013mils True (+13.1) Elevation Angle: -20.2° Horizon Angle: -00.2° Zoom: 1.0X 11733+00</p>	
GPS Location		See photo for GPS location.		GPS Location		See photo for GPS location.	
Field Station#		11670+00		Field Station#		11672+00	
Pic 1 Desc.		ECDs in place along LOD.		Pic 2 Desc.		ROW frozen and snow covered.	
GPS Location		See photo for GPS location.		GPS Location		See photo for GPS location.	
Field Station#		11687+40		Field Station#		11733+00	
Pic 3 Desc.		Sensitive resource buffer in place at stream S-MN21.		Pic 4 Desc.		ROW frozen and snow covered. Waterbars in place.	
 <p>Date & Time: Tue, Feb 02, 2021, 10:30:57 EST Position: +037.293779° / -080.356896° (+6523.3ft) Altitude: 2011ft (+124.1ft) Datum: WGS-84 Azimuth/Bearing: 258 S78W 4587mils True (+13.1) Elevation Angle: -21.5° Horizon Angle: -03.1° Zoom: 1.0X 11745+00</p>		 <p>Date & Time: Tue, Feb 02, 2021, 10:50:42 EST Position: +037.295847° / -080.361656° (+471.6ft) Altitude: 2122ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 152 S28E 2702mils True (+13.1) Elevation Angle: -21.5° Horizon Angle: -03.1° Zoom: 1.0X 11775+00</p>					
GPS Location		See photo for GPS location.		GPS Location		See photo for GPS location.	
Field Station#		11745+00		Field Station#		11775+00	
Pic 5 Desc.		Priority one silt fence checks in place.		Pic 6 Desc.		Clean water diversion pipe and plunge pool in place.	

AFE 124300137	Date/Time 2/2/2021 3:09 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/2/2021 3:09 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19644	
Inspector Garrett Barclay		Date/Time 2/2/2021 3:16 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11524+16	
State VA	Inspection Area Partial	Station End 11600+01	
County Craig	Ground Frozen	Temperature (°F) 17.00	
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/2/2021 3:16 PM	Report # 19644
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting
 Performed SWPPP for MP 218 - MP 219
 No damaged ECD's observed during inspection
 ROW conditions are stable and showing minimal signs of erosion
 No items added to the punch list

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/2/2021 3:16 PM	Report #
Pictures				
<p>Date & Time: Tue, Feb 02, 2021, 08:41:00 EST Position: +037.32485° / -080.41534° (+15.4ft) Altitude: 2998ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 093° 58'E 1600mils True (+19°) Elevation Grade: +02% Horizon Grade: +00% Zoom: 1.0x 11530</p> 		<p>Date & Time: Tue, Feb 02, 2021, 08:40:18 EST Position: +037.32485° / -080.41534° (+15.4ft) Altitude: 2998ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 124° 55'E 1200mils True (+19°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 1.0x 11544</p> 		
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates
Field Station#	11530+00		Field Station#	11544+00
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions
<p>Date & Time: Tue, Feb 02, 2021, 09:14:37 EST Position: +037.32485° / -080.41534° (+15.4ft) Altitude: 2998ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 153° 52'E 2720mils True (+13°) Elevation Grade: +0% Horizon Grade: +00% Zoom: 1.0x 11555</p> 		<p>Date & Time: Tue, Feb 02, 2021, 09:27:58 EST Position: +037.322551° / -080.414246° (+15.4ft) Altitude: 2734ft (+11.2ft) Datum: WGS-84 Azimuth/Bearing: 162° 53'E 2500mils True (+12°) Elevation Grade: +1% Horizon Grade: +00% Zoom: 1.0x 11560</p> 		
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates
Field Station#	11555+00		Field Station#	11560+00
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions
<p>Date & Time: Tue, Feb 02, 2021, 09:24:25 EST Position: +037.323649° / -080.415736° (+15.5ft) Altitude: 2497ft (+11.1ft) Datum: WGS-84 Azimuth/Bearing: 182° 51'E 3300mils True (+18°) Elevation Grade: +0% Horizon Grade: +00% Zoom: 1.0x 11585</p> 		<p>Date & Time: Tue, Feb 02, 2021, 09:27:05 EST Position: +037.32485° / -080.41534° (+15.4ft) Altitude: 2848ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 134° 54'E 2300mils True (+19°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0x 11585</p> 		
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates
Field Station#	11569+00		Field Station#	11585+00
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions

AFE 124300137	Date/Time 2/2/2021 3:16 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/2/2021 3:16 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19669	
Inspector Len Kruizenga		Date/Time 2/3/2021 8:51 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Full	Station End	12005+00
County Giles	Ground Frozen	Temperature (°F)	22.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/3/2021 8:51 AM	Report # 19669
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Met with EI's at the work trailer.
 SWPPP inspection area: LY-29
 AR-238.00- Access road and RCE are maintained in acceptable condition.
 CFS triple stack perimeter controls are in acceptable condition.
 Culvert and drainage feature are in acceptable condition.
 Waste management is acceptable.
 House keeping is acceptable.
 Overhead utility flagging is acceptable.
 Welders are working in the yard.
 Weather today is cold, clear and windy.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/3/2021 8:51 AM	Report #			
Pictures							
<p>Date & Time: Wed, Feb 03, 2021, 11:53:05 EST Position: +037.363263 / -080.676997 (±16.6ft) Altitude: 1839ft (±36.6ft) Datum: WGS-84 Azimuth/Bearing: 232° S59W 426ftmils True (±10°) Elevation Angle: +03.7° Horizon Angle: -04.8° Zoom: 1.0X LY29-00- Access road RCE</p>		<p>Date & Time: Wed, Feb 03, 2021, 11:54:58 EST Position: +037.363214 / -080.675315 (±14.4ft) Altitude: 1255ft (±12.5ft) Datum: WGS-84 Azimuth/Bearing: 252° S72W 448ftmils True (±10°) Elevation Angle: -06.4° Horizon Angle: -01.3° Zoom: 1.0X LY29- Overhead view of the yard</p>		GPS Location	See photo GPS	GPS Location	See photo GPS
Field Station#	12005+00	Field Station#	12005+00	Pic 1 Desc.	AR-238.00 and RCE	Pic 2 Desc.	LY29- Overhead view of the yard.
<p>Date & Time: Wed, Feb 03, 2021, 11:58:39 EST Position: +037.363257 / -080.676697 (±36.3ft) Altitude: 1705ft (±35.2ft) Datum: WGS-84 Azimuth/Bearing: 222° S42W 394ftmils True (±10°) Elevation Angle: -01.4° Horizon Angle: -02.9° Zoom: 1.0X LY29- Track hoe used for moving pipe in the yard</p>		<p>Date & Time: Wed, Feb 03, 2021, 11:59:35 EST Position: +037.363263 / -080.676795 (±14.9ft) Altitude: 1706ft (±11.9ft) Datum: WGS-84 Azimuth/Bearing: 286° N76W 504ftmils True (±10°) Elevation Angle: -08.8° Horizon Angle: +03.3° Zoom: 1.0X LY29- Welders are working in the yard</p>		GPS Location	See photo GPS	GPS Location	See photo GPS
Field Station#	12005+00	Field Station#	12005+00	Pic 3 Desc.	LY29- Track hoe staged in the yard for welders moving pipe	Pic 4 Desc.	LY29- welders are in the yard
<p>Date & Time: Wed, Feb 03, 2021, 12:00:50 EST Position: +037.362083 / -080.677437 (±14.2ft) Altitude: 1717ft (±12.2ft) Datum: WGS-84 Azimuth/Bearing: 260° S80W 462ftmils True (±10°) Elevation Angle: -11.3° Horizon Angle: -00.3° Zoom: 1.0X LY29- CFS perimeter controls</p>		<p>Date & Time: Wed, Feb 03, 2021, 12:01:50 EST Position: +037.362311 / -080.677317 (±14.9ft) Altitude: 1710ft (±12.2ft) Datum: WGS-84 Azimuth/Bearing: 266° S59W 460ftmils True (±10°) Elevation Angle: -11.0° Horizon Angle: -00.0° Zoom: 1.0X LY29- Culvert and drainage feature</p>		GPS Location	See photo GPS	GPS Location	See photo GPS
Field Station#	12005+00	Field Station#	12005+00	Pic 5 Desc.	CFS triple stack perimeter controls.	Pic 6 Desc.	Culvert and drainage feature.

AFE 124300137	Date/Time 2/3/2021 8:51 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	2/3/2021 8:51 AM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19689	
Inspector Jared Saunders		Date/Time 2/3/2021 3:08 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Partial	Station End	12005+00
County Giles	Ground Frozen	Temperature (°F)	35.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/3/2021 3:08 PM	Report # 19689
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection at lay down yard 26.
 Checked equipment in yards for leaks. No leaks observed.
 All perimeter ECDs in place and functional.
 Secondary containment in place at stationary equipment.
 No deficiencies located during VA SWPPP inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/3/2021 3:08 PM	Report #
Pictures				
 <p>Date & Time: Wed, Feb 03, 2021, 09:27:10 EST Position: -037.319434, -080.657658 (±213.3ft) Altitude: 1791ft (±32.8ft) Datum: WGS-84 Azimuth/Bearing: 305° N55W 5422mils True (±12°) Elevation Angle: -16.3° Horizon Angle: -00.5° Zoom: 1.0X LDY: 26</p>		 <p>Date & Time: Wed, Feb 03, 2021, 09:28:00 EST Position: -037.319323, -080.658457 (±115.4ft) Altitude: 1891ft (±31.7ft) Datum: WGS-84 Azimuth/Bearing: 85° S27W 4569mils True (±10°) Elevation Angle: -07.3° Horizon Angle: -02.6° Zoom: 1.0X LDY: 26</p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	12005+00	Field Station#	12005+00	
Pic 1 Desc.	Triple stack cfs in place around drainage.	Pic 2 Desc.	RCE in place at LDY 26 entrance.	
 <p>Date & Time: Wed, Feb 03, 2021, 09:28:18 EST Position: -037.318796, -080.658667 (±118.4ft) Altitude: 1797ft (±11.2ft) Datum: WGS-84 Azimuth/Bearing: 225° S45W 4000mils True (±10°) Elevation Angle: -10.5° Horizon Angle: +00.3° Zoom: 1.0X LDY: 26</p>		 <p>Date & Time: Wed, Feb 03, 2021, 09:28:25 EST Position: -037.318931, -080.658477 (±115.4ft) Altitude: 1800ft (±1.3ft) Datum: WGS-84 Azimuth/Bearing: 041° S39E 2507mils True (±10°) Elevation Angle: -03.5° Horizon Angle: -00ft Zoom: 1.0X LDY: 26</p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	12005+00	Field Station#	12005+00	
Pic 3 Desc.	18 inch compost filter sock in place along LOD.	Pic 4 Desc.	Dumpsters being utilized for trash management.	
 <p>Date & Time: Wed, Feb 03, 2021, 09:29:03 EST Position: -037.318721, -080.657834 (±115.4ft) Altitude: 1795ft (±11.3ft) Datum: WGS-84 Azimuth/Bearing: 358° S78W 4587mils True (±10°) Elevation Angle: -31.4° Horizon Angle: +01.7° Zoom: 1.0X LDY: 26</p>		 <p>Date & Time: Wed, Feb 03, 2021, 09:29:34 EST Position: -037.318249, -080.657634 (±115.4ft) Altitude: 1821ft (±11.3ft) Datum: WGS-84 Azimuth/Bearing: 245° S65W 4350mils True (±10°) Elevation Angle: -03.9° Horizon Angle: -00.6° Zoom: 1.0X LDY: 26</p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	12005+00	Field Station#	12005+00	
Pic 5 Desc.	Checked staged equipment for leaks.	Pic 6 Desc.	Secondary containment in place under fuel.	

AFE 124300137	Date/Time 2/3/2021 3:08 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/3/2021 3:08 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19690	
Inspector Garrett Barclay		Date/Time 2/3/2021 3:23 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Partial	Station End	12005+00
County Giles	Ground Frozen	Temperature (°F)	28.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Signage	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/3/2021 3:23 PM	Report # 19690
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting
 Performed SWPPP for LDY 28
 No damaged ECD's observed during inspection
 ROW conditions are stable and showing minimal signs of erosion
 No items added to the punch list

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/3/2021 3:23 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures



GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates
Field Station#	12005+00	Field Station#	12005+00
Pic 1 Desc.	ECD's and row conditions	Pic 2 Desc.	ECD's and row conditions



GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates
Field Station#	12005+00	Field Station#	12005+00
Pic 3 Desc.	ECD's and row conditions	Pic 4 Desc.	Secondary containment



GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates
Field Station#	12005+00	Field Station#	12005+00
Pic 5 Desc.	ECD's and row conditions	Pic 6 Desc.	Secondary containment

AFE 124300137	Date/Time 2/3/2021 3:23 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/3/2021 3:23 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19712	
Inspector Chris Burns		Date/Time 2/4/2021 7:53 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11023+80
State VA	Inspection Area Partial	Station End	11064+53
County Giles	Ground Frozen	Temperature (°F)	45.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar Outlet Protection	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/4/2021 7:53 AM	Report # 19712
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection from MP 208.78 to MP 209.56 as well as assessed AR 254.01.
 No issues were located.
 All perimeter controls, ECDs and BMPs are functional.
 Vegetation or stabilization sufficient.
 No impact to sensitive resources observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/4/2021 7:53 AM		Report #	
Pictures					
<p>Date & Time: Thu, Feb 04, 2021, 10:23:02 EST Position: +037.322772 / -080.522271 (+157.5ft) Altitude: 2235ft (+386.2ft) Datum: WGS-84 Azimuth/Bearing: 008° N88E 0162mils True (±14°) Elevation Angle: -07.5° Horizon Angle: 000° Zoom: 1.0X 11025+00</p> 		<p>Date & Time: Thu, Feb 04, 2021, 10:27:31 EST Position: +037.328919 / -080.520737 (+1219.5ft) Altitude: 2301ft (+354.5ft) Datum: WGS-84 Azimuth/Bearing: 181° S81E 284mils True (±15°) Elevation Angle: -02.8° Horizon Angle: 400.0° Zoom: 1.0X 11034+00</p> 			
GPS Location 1		GPS Location 2			
Field Station# 11025+50		Field Station# 11034+00			
Pic 1 Desc. S-IJ18 and controls.		Pic 2 Desc. Section of RoW showing conditions and controls.			
<p>Date & Time: Thu, Feb 04, 2021, 10:41:54 EST Position: +037.308918 / -080.544522 (+13550.5ft) Altitude: 2235ft (+386.2ft) Datum: WGS-84 Azimuth/Bearing: 272° N88W 483mils True (±12°) Elevation Angle: +25.7° Horizon Angle: +04.0° Zoom: 1.0X 11049+00</p> 		<p>Date & Time: Thu, Feb 04, 2021, 10:43:10 EST Position: +037.315295 / -080.542622 (+315.0ft) Altitude: 2301ft (+354.5ft) Datum: WGS-84 Azimuth/Bearing: 007° N37E 0658mils True (±12°) Elevation Angle: 43.5° Horizon Angle: 000° Zoom: 1.0X 11050+10</p> 			
GPS Location 3		GPS Location 4			
Field Station# 11049+00		Field Station# 11050+10			
Pic 3 Desc. Section of RoW showing conditions and controls.		Pic 4 Desc. S-IJ16B/S-IJ17 and controls.			
<p>Date & Time: Thu, Feb 04, 2021, 10:45:06 EST Position: +037.317425 / -080.546337 (+1203.0ft) Altitude: 2184ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 157° S23E 2791mils True (±10°) Elevation Angle: -06.2° Horizon Angle: -00.5° Zoom: 1.0X 11055+00</p> 		<p>Date & Time: Thu, Feb 04, 2021, 10:55:34 EST Position: +037.310010 / -080.562244 (+13530.5ft) Altitude: 2185ft (+32.9ft) Datum: WGS-84 Azimuth/Bearing: 307° N53W 5458mils True (±12°) Elevation Angle: +28.8° Horizon Angle: +03.6° Zoom: 1.0X 11064+53</p> 			
GPS Location 5		GPS Location 6			
Field Station# 11055+00		Field Station# 11064+53			
Pic 5 Desc. Section of RoW showing conditions and controls.		Pic 6 Desc. Section of RoW showing conditions and controls.			

AFE 124300137	Date/Time 2/4/2021 7:53 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/4/2021 7:53 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19713	
Inspector Len Kruizenga		Date/Time 2/4/2021 8:26 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11023+88	
State VA	Inspection Area Full	Station End 10930+00	
County Giles	Ground Frozen	Temperature (°F) 23.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/4/2021 8:26 AM	Report # 19713
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Met with EI's at the work trailer.
 SWPPP inspection area: Sta#11023+88 to 10930+00. MP-208.6 to 206.2
 Access road 244.00 and Doe Creek RCE are snow covered but in acceptable condition.
 Perimeter controls, silt fence, CFS, SSF are in acceptable condition.
 The row in this inspection area has the deepest snow that I have encountered, water bars are drifted over with knee deep snow in the flow lines.
 Streams are running clean & clear, ECD's are in acceptable condition.
 Drainage feature ECD's and crossing bridges are in acceptable condition.
 Sensitive resource area ECD's are in acceptable condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/4/2021 8:26 AM	Report #	
Pictures					
 <p><small>Date & Time: Thu, Feb 04, 2021, 10:20:10 EST Position: +037.321680 / -080.522917 (-62.110) Altitude: 2329ft (-70.0m) Datum: WGS-84 Azimuth/Bearing: 325° N5W, 5778mils True (-22) Elevation Angle: -17.1 Horizon Angle: -05.2 Zoom: 1.0x Stn: 10922+00 - Row, snow covered water bars, controls</small></p>		 <p><small>Date & Time: Thu, Feb 04, 2021, 10:28:40 EST Position: +037.322461 / -080.554895 (-62.110) Altitude: 2399ft (-73.0m) Datum: WGS-84 Azimuth/Bearing: 301° N5W, 5353mils True (-10) Elevation Angle: -06.1 Horizon Angle: -01.3 Zoom: 1.0x Stn: 10917+00 - Stream crossing S-RR5</small></p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11023+88	Field Station#	11017+00		
Pic 1 Desc.	Stream crossing S-IJ18	Pic 2 Desc.	Stream crossing S-RR5		
 <p><small>Date & Time: Thu, Feb 04, 2021, 10:54:46 EST Position: +037.324972 / -080.522924 (-62.1403hr) Altitude: 2350ft (-71.6m) Datum: WGS-84 Azimuth/Bearing: 313° N3W, 5813mils True (-15) Elevation Angle: -10.1 Horizon Angle: -01.1 Zoom: 1.0x Stn: 10992+00 - Row, snow covered water bars, controls</small></p>		 <p><small>Date & Time: Thu, Feb 04, 2021, 11:03:32 EST Position: +037.325371 / -080.564444 (-62.1198hr) Altitude: 2363ft (-72.0m) Datum: WGS-84 Azimuth/Bearing: 305° N3W, 5613mils True (-15) Elevation Angle: -09.5 Horizon Angle: -00.1 Zoom: 1.0x Stn: 10986+00 - Stream S- E25</small></p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	10992+00	Field Station#	10986+00		
Pic 3 Desc.	Row, snow covered water bars, controls	Pic 4 Desc.	Stream S- E25		
 <p><small>Date & Time: Thu, Feb 04, 2021, 11:04:23 EST Position: +037.325381 / -080.564895 (-62.152hr) Altitude: 2352ft (-71.7m) Datum: WGS-84 Azimuth/Bearing: 309° N5W, 5693mils True (-15) Elevation Angle: -13.3 Horizon Angle: -06.0 Zoom: 1.0x Stn: 10985+00 - Stream S- E24, bridge and ECD's</small></p>		 <p><small>Date & Time: Thu, Feb 04, 2021, 11:26:40 EST Position: +037.327084 / -080.571014 (-62.303hr) Altitude: 2398ft (-73.0m) Datum: WGS-84 Azimuth/Bearing: 310° N4W, 5418mils True (-15) Elevation Angle: -14.3 Horizon Angle: -09.4 Zoom: 1.0x Stn: 10965+00 - Sensitive resource area, bat habitat trees</small></p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	10985+00	Field Station#	10965+00		
Pic 5 Desc.	Stream S- E24, bridge and ECD's.	Pic 6 Desc.	Sensitive resource area, bat habitat trees.		

AFE 124300137	Date/Time 2/4/2021 8:26 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/4/2021 8:26 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19731	
Inspector Garrett Barclay		Date/Time 2/4/2021 2:57 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10850+00
State VA	Inspection Area Partial	Station End	10929+62
County Giles	Ground Frozen	Temperature (°F)	26.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Communication			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/4/2021 2:57 PM	Report # 19731
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting
 Performed SWPPP for MP 205 - MP 207
 damaged ECD's observed during inspection
 ROW conditions are stable and showing minimal signs of erosion
 Damaged items added to the punchlist

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/4/2021 2:57 PM		Report #	
Pictures					
					
GPS Location		See picture above for GPS coordinates		GPS Location	
See picture above for GPS coordinates				See picture above for GPS coordinates	
Field Station#		10858+00		Field Station#	
10858+00				10865+00	
Pic 1 Desc.		ECD's and row conditions		Pic 2 Desc.	
				ECD's and row conditions	
					
GPS Location		See picture above for GPS coordinates		GPS Location	
See picture above for GPS coordinates				See picture above for GPS coordinates	
Field Station#		10865+00		Field Station#	
10865+00				10915+00	
Pic 3 Desc.		Damaged ECD's		Pic 4 Desc.	
				Damaged ECD's	
					
GPS Location		See picture above for GPS coordinates		GPS Location	
See picture above for GPS coordinates				See picture above for GPS coordinates	
Field Station#		10883+00		Field Station#	
10883+00				10924+00	
Pic 5 Desc.		ECD's and row conditions		Pic 6 Desc.	
				ECD's and row conditions	

AFE 124300137	Date/Time 2/4/2021 2:57 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/4/2021 2:57 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19734	
Inspector Jared Saunders		Date/Time 2/4/2021 3:21 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10670+00
State VA	Inspection Area Partial	Station End	10750+00
County Giles	Ground Frozen	Temperature (°F)	45.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300137	Date/Time	2/4/2021 3:21 PM	Report #	19734
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from MP 201.7 to MP 203.6.
 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.
 No forward progress has been completed due to FERC shut down.
 Right of way has been stabilized using seed, mulch, and natural vegetation.
 No deficiencies located during VA SWPPP inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/4/2021 3:21 PM	Report #
Pictures				
 <p><small>Date & Time: Thu, Feb 04, 2021, 10:52:42 EST Position: +037.342735 / -080.647616 (±91.8ft) Altitude: 2304ft (±93.8ft) Datum: WGS-84 Azimuth/Bearing: 107.573E 1902mils True (±12°) Elevation Angle: -11.7° Horizon Angle: -06.6° Zoom: 1.0X 10712+50</small></p>		 <p><small>Date & Time: Thu, Feb 04, 2021, 10:33:42 EST Position: +037.350753 / -080.648454 (±113.3ft) Altitude: 2134ft (±32.8ft) Datum: WGS-84 Azimuth/Bearing: 209.529W 3716mils True (±10°) Elevation Angle: -04.8° Horizon Angle: -02.6° Zoom: 1.0X 10710+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	10712+50	Field Station#	10710+00	
Pic 1 Desc.	Sensitive resource buffer in place at stream S-G33.	Pic 2 Desc.	CFS in place along access road 241.04.	
 <p><small>Date & Time: Thu, Feb 04, 2021, 10:53:24 EST Position: +037.348702 / -080.647974 (±15.4ft) Altitude: 2303ft (±11.3ft) Datum: WGS-84 Azimuth/Bearing: 151.539E 2688mils True (±12°) Elevation Angle: -24.8° Horizon Angle: +00.2° Zoom: 1.0X 10711+00</small></p>		 <p><small>Date & Time: Thu, Feb 04, 2021, 10:53:33 EST Position: +037.348696 / -080.648042 (±15.3ft) Altitude: 2305ft (±11.4ft) Datum: WGS-84 Azimuth/Bearing: 270° N90W 4800mils True (±12°) Elevation Angle: -04.5° Horizon Angle: -00.2° Zoom: 1.0X 10711+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	10711+00	Field Station#	10711+00	
Pic 3 Desc.	Priority one silt fence checks in place.	Pic 4 Desc.	ROW stabilized with natural vegetation growth. Currently snow covered and frozen.	
 <p><small>Date & Time: Thu, Feb 04, 2021, 11:05:00 EST Position: +037.319218 / -080.652879 (±15.3ft) Altitude: 2061ft (±11.4ft) Datum: WGS-84 Azimuth/Bearing: 114.544E 2042mils True (±10°) Elevation Angle: -06.4° Horizon Angle: -03.3° Zoom: 1.0X 10696+00</small></p>		 <p><small>Date & Time: Thu, Feb 04, 2021, 11:04:15 EST Position: +037.324100 / -080.653100 (±32.92ft) Altitude: 2168ft (±36.3ft) Datum: WGS-84 Azimuth/Bearing: 113.567E 2009mils True (±10°) Elevation Angle: -02.2° Horizon Angle: -01.2° Zoom: 1.0X 10698+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	10696+00	Field Station#	10698+00	
Pic 5 Desc.	RCE in place at Buffalo Anklets Road.	Pic 6 Desc.	Sensitive resource buffer in place at stream S-G32.	

AFE 124300137	Date/Time 2/4/2021 3:21 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/4/2021 3:21 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19754	
Inspector Chris Burns		Date/Time 2/5/2021 7:58 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11254+99	
State VA	Inspection Area Partial	Station End 11353+67	
County Giles	Ground Muddy	Temperature (°F) 38.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/5/2021 7:58 AM	Report # 19754
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection from from MP 213.16 to MP 215.03.
 The majority of the RoW was covered in 2 to 4 inches of snow hindering visibility for inspection.
 No issues were located.
 All visible perimeter controls, ECDs and BMPs are functional.
 Vegetation or stabilization sufficient.
 No impact to sensitive resources observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/5/2021 7:58 AM		Report #			
Pictures							
 <p>Date & Time: Fri, Feb 05, 2021, 09:22:13 EST Position: +037.239163° / +080.483831° (+420.0ft) Altitude: 2195ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 029° N29E 0516mils True (±12°) Elevation Angle: -19.1° Horizon Angle: +01.7° Zoom: 1.0X 11286+00</p>		 <p>Date & Time: Fri, Feb 05, 2021, 09:30:58 EST Position: +037.242265° / +080.481094° (+55777.0ft) Altitude: 2245ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 139° S41E 2471mils True (±12°) Elevation Angle: -12.8° Horizon Angle: +02.1° Zoom: 1.0X 11292+80</p>		<p>GPS Location 1</p> <p>Field Station# 11286+00</p> <p>Pic 1 Desc. Perimeter controls functional.</p>		<p>GPS Location 2</p> <p>Field Station# 11292+80</p> <p>Pic 2 Desc. S-MM18 and controls.</p>	
 <p>Date & Time: Fri, Feb 05, 2021, 09:37:14 EST Position: +037.244322° / +080.481008° (+35507.0ft) Altitude: 2101ft (+72.1ft) Datum: WGS-84 Azimuth/Bearing: 005° N84E 1529mils True (±12°) Elevation Angle: -3.2° Horizon Angle: +00.1° Zoom: 1.0X 11300+00</p>		 <p>Date & Time: Fri, Feb 05, 2021, 09:53:05 EST Position: +037.300426° / +080.472938° (+52.5ft) Altitude: 2149ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 163° S27E 2720mils True (±12°) Elevation Angle: -1.0° Horizon Angle: +01.1° Zoom: 1.0X 11327+85</p>		<p>GPS Location 3</p> <p>Field Station# 11300+00</p> <p>Pic 3 Desc. Section of RoW showing conditions and controls.</p>		<p>GPS Location 4</p> <p>Field Station# 11327+85</p> <p>Pic 4 Desc. S-NN12 and controls.</p>	
 <p>Date & Time: Fri, Feb 05, 2021, 10:04:31 EST Position: +037.237020° / +080.576999° (+43379.0ft) Altitude: 2137ft (+7.9ft) Datum: WGS-84 Azimuth/Bearing: 221° S41W 3925mils True (±12°) Elevation Angle: +13.8° Horizon Angle: +02.5° Zoom: 1.0X 11350+00</p>		 <p>Date & Time: Fri, Feb 05, 2021, 10:06:12 EST Position: +037.235555° / +080.576999° (+43379.0ft) Altitude: 2171ft (+7.9ft) Datum: WGS-84 Azimuth/Bearing: 104° S78E 1802mils True Elevation Angle: +13.8° Horizon Angle: +02.5° Zoom: 1.0X 11352+97</p>		<p>GPS Location 5</p> <p>Field Station# 11350+00</p> <p>Pic 5 Desc. Section of RoW showing conditions and controls.</p>		<p>GPS Location 6</p> <p>Field Station# 11352+97</p> <p>Pic 6 Desc. S-NN11.</p>	

AFE 124300137	Date/Time 2/5/2021 7:58 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/5/2021 7:58 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19764	
Inspector Len Kruizenga		Date/Time 2/5/2021 1:29 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11254+99	
State VA	Inspection Area Full	Station End 11158+27	
County Giles	Ground Frozen	Temperature (°F) 35.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.80	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300137	Date/Time	2/5/2021 1:29 PM	Report #	19764
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Met with EI's at Winding Way:
 SWPPP inspection area: Sta# 11254+99 to 11158+27. MP- 213 to 211
 The row is stable with snow melt on south facing slopes, snow remains on north facing slopes.
 Perimeter controls, silt fence, CFS, SSF are in acceptable condition.
 Water bars, sump pits and end treatments are in acceptable condition.
 Slope drains are in acceptable condition.
 CWD pipe and plunge pool are in acceptable condition.
 Rock channel is in acceptable condition.
 Access roads, Winding Way,AR-249.02, AR- 249.01 are maintained in acceptable condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 2/5/2021 1:29 PM		Report #			
Pictures							
 <p>Date & Time: Fri, Feb 05, 2021, 09:12:35 EST Position: +037.301521 / -080.501193 (+31.6°) Altitude: 2071ft (+633m) Datum: WGS-84 Azimuth Bearing: 121 S59E 215ft True (+17°) Elevation Angle: +34.3° Horizon Angle: +01.0° Zoom: 1.0X Sta# 11237+00 - Row and ECD's from sta# 11227+00 to 11237+00</p>		 <p>Date & Time: Fri, Feb 05, 2021, 09:16:09 EST Position: +037.301521 / -080.502632 (+31.6°) Altitude: 2071ft (+633m) Datum: WGS-84 Azimuth Bearing: 163 S17E 289ft True (+17°) Elevation Angle: +22.2° Horizon Angle: +00.8° Zoom: 1.0X Sta# 11225+00 - Slope drain inlet, rock channel at the base of the slope.</p>		<p>GPS Location See photo GPS</p> <p>Field Station# 11237+00</p> <p>Pic 1 Desc. Row and ECD's</p>		<p>GPS Location See photo GPS</p> <p>Field Station# 11225+00</p> <p>Pic 2 Desc. Slope drain inlet, rock channel at the base of the slope.</p>	
 <p>Date & Time: Fri, Feb 05, 2021, 09:29:36 EST Position: +037.305247 / -080.507078 (+32.1ft) Altitude: 2049ft (+97.8ft) Datum: WGS-84 Azimuth Bearing: 163 S17E 289ft True (+17°) Elevation Angle: +22.2° Horizon Angle: +00.8° Zoom: 1.0X Sta# 11200+00 - Southern exposed slopes are melting, southern side snow covered.</p>		 <p>Date & Time: Fri, Feb 05, 2021, 09:54:08 EST Position: +037.306539 / -080.510103 (+32.0ft) Altitude: 1965ft (+115ft) Datum: WGS-84 Azimuth Bearing: 121 S59E 231ft True (+17°) Elevation Angle: +02.2° Horizon Angle: +00.8° Zoom: 1.0X Sta# 11190+00 - Sensitive resource area, drainage feature.</p>		<p>GPS Location See photo GPS</p> <p>Field Station# 11200+00</p> <p>Pic 3 Desc. Snow melting on south facing slopes, snow remains on north facing slopes.</p>		<p>GPS Location See photo GPS</p> <p>Field Station# 11190+00</p> <p>Pic 4 Desc. Sensitive resource area, drainage feature.</p>	
 <p>Date & Time: Fri, Feb 05, 2021, 09:43:27 EST Position: +037.307411 / -080.511917 (+42.2ft) Altitude: 1951ft (+143.9ft) Datum: WGS-84 Azimuth Bearing: 198 S18W 352ft True (+13°) Elevation Angle: +31.2° Horizon Angle: +01.0° Zoom: 1.0X Sta# 11184+00 - CWD pipe and plunge pool.</p>		 <p>Date & Time: Fri, Feb 05, 2021, 09:50:19 EST Position: +037.307993 / -080.515041 (+32.1ft) Altitude: 1951ft (+143.9ft) Datum: WGS-84 Azimuth Bearing: 121 S59E 231ft True (+17°) Elevation Angle: +02.2° Horizon Angle: +00.8° Zoom: 1.0X Sta# 11172+70 - Slope drain, sump, end treatment.</p>		<p>GPS Location See photo GPS</p> <p>Field Station# 11184+00</p> <p>Pic 5 Desc. CWD pipe and plunge pool.</p>		<p>GPS Location See photo GPS</p> <p>Field Station# 11172+70</p> <p>Pic 6 Desc. Slope drain, sump, end treatment.</p>	

AFE 124300137	Date/Time 2/5/2021 1:29 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 2/5/2021 1:29 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19770	
Inspector Garrett Barclay		Date/Time 2/5/2021 3:09 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11064+53	
State VA	Inspection Area Partial	Station End 11158+27	
County Giles	Ground Frozen	Temperature (°F) 38.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300137	Date/Time 2/5/2021 3:09 PM	Report # 19770
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting
 Performed SWPPP for MP 209- MP 211
 No damaged ECD's observed during inspection
 ROW conditions are stable and showing minimal signs of erosion
 No items added to the punch list

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	2/5/2021 3:09 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--



Pictures

<p><small>Date & Time: Fri, Feb 05, 2021, 08:52:50 EST Position: -080.513350 / -080.543078 (+15.21) Altitude: 1920m (+11.74) Datum: WGS-84 Azimuth/Bearing: 308° N268W 3276mis True (+12.1) Elevation Grade: +013 Horizon Grade: +002 Zoom: 1.0X 11067</small></p> 	<p><small>Date & Time: Fri, Feb 05, 2021, 09:21:08 EST Position: -037.315493 / -080.528214 (+15.31) Altitude: 2054m (+11.41) Datum: WGS-84 Azimuth/Bearing: 105° S75E 1867mis True (+3.82) Elevation Grade: +013 Horizon Grade: +000 Zoom: 1.0X 11120</small></p> 
--	--

GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates
Field Station#	11067+00	Field Station#	11120+00
Pic 1 Desc.	ECD's and row conditions	Pic 2 Desc.	ECD's and row conditions

<p><small>Date & Time: Fri, Feb 05, 2021, 09:07:23 EST Position: -037.313350 / -080.534363 (+15.14) Altitude: 1969m (+11.74) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mis True (+12.1) Elevation Grade: +007 Horizon Grade: +003 Zoom: 1.0X 11098</small></p> 	<p><small>Date & Time: Fri, Feb 05, 2021, 10:22:25 EST Position: -037.317695 / -080.553112 (+20.71) Altitude: 2154m (+8.31) Datum: WGS-84 Azimuth/Bearing: 304° S34W 4140mis True (+12.1) Elevation Grade: +053 Horizon Grade: +003 Zoom: 1.0X Trace</small></p> 
--	--

GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates
Field Station#	11098+00	Field Station#	+1
Pic 3 Desc.	ECD's and row conditions	Pic 4 Desc.	Trace recorded

<p><small>Date & Time: Fri, Feb 05, 2021, 09:58:39 EST Position: -037.320444 / -080.533390 (+17.41) Altitude: 1933m (+4.41) Datum: WGS-84 Azimuth/Bearing: 108° S72E 1920mis True (+12.1) Elevation Grade: +010 Horizon Grade: +008 Zoom: 1.0X g-winding</small></p> 	<p><small>Date & Time: Fri, Feb 05, 2021, 09:35:18 EST Position: -037.319811 / -080.528311 (+15.41) Altitude: 2142m (+8.31) Datum: WGS-84 Azimuth/Bearing: 280° N68W 3292mis True (+13.1) Elevation Grade: +013 Horizon Grade: +002 Zoom: 1.0X 11124</small></p> 
--	---

GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates
Field Station#	+1	Field Station#	11140+00
Pic 5 Desc.	.8" of rain recorded	Pic 6 Desc.	ECD's and row conditions

A/E	124300137	Date/Time	2/5/2021 3:09 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	2/5/2021 3:09 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 19771	
Inspector Jared Saunders		Date/Time 2/5/2021 3:23 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11353+54
State VA	Inspection Area Partial	Station End	11524+16
County Giles	Ground Frozen	Temperature (°F)	47.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Broad-Based Dip	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Hole in P-1	Addressed	
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 2/5/2021 3:23 PM	Report # 19771
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from MP 215 to MP 218.3.
 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.
 No forward progress has been completed due to FERC shut down.
 Right of way has been stabilized using seed, mulch, and natural vegetation.
 Deficiency located at station number 11447+95 - hole in priority one silt fence. Crew repaired item.
 Checked rain gauges at Stevers Gap Road - 0.3 frozen, Mount Tabor - 0.5 inches and Catawba Road - 0.7 inches.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

Pictures



GPS Location See photo for GPS location.	GPS Location See photo for GPS location.
---	---

Field Station# 11767+00	Field Station# 11990+00
--------------------------------	--------------------------------


Pic 1 Desc. Rain gauge at Catawba Road reads 0.7 inches.	Pic 2 Desc. Rain gauge at Mount Tabor Road reads 0.5 inches.
---	---



GPS Location See photo for GPS location.	GPS Location See photo for GPS location.
---	---

Field Station# 11489+00	Field Station# 11380+00
--------------------------------	--------------------------------

Pic 3 Desc. Rain gauge at Stevers Gap Road reads 0.3 inches.	Pic 4 Desc. Triple barrier ECDs in place at off ROW karst feature.
---	---



GPS Location See photo for GPS location.	GPS Location See photo for GPS location.
---	---

Field Station# 11474+00	Field Station# 11451+00
--------------------------------	--------------------------------

Pic 5 Desc. Slope drains in place over two-tone.	Pic 6 Desc. Sensitive resource buffer in place at stream S-0012 and S-0013.
---	--

AFE 124300137	Date/Time 2/5/2021 3:23 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	2/5/2021 3:23 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	