



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	22933
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/3/2021 8:30 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	See comments		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Other - Explain in Comments	Communication	Safety fence/ See comments		

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/3/2021 8:30 AM	<b>Report #</b>	22933
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 to ST# 11788+52 (MP 221.02 to MP 223.27) Deficiencies found at the following station numbers: 11670+73 orange construction safety fence is down 11689+00 P1 damaged by wildlife replace 11711+50 P1 damaged by wildlife replace 11722+30 P1 damaged by wildlife replace 11724+30 P1 damaged by wildlife replace No crews are actively working in area P1 silt fence is in place across travel lane of steep slopes before bridges for added protection to streams Topsoil stock piles, clean water diversion berms, and travel lane are stabilized Waterbars are in place with sump pits and waterbar end treatments 50' buffers in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52 MLV-AR-26 and MT. Tabor road crossing RCE are maintained in acceptable condition MT. Tabor rain gauge will be checked tomorrow due to active rain event at time of inspection The ROW is wet and in stable condition No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2021 8:30 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11670+73	<b>Field Station#</b>	11686+80		
<b>Pic 1 Desc.</b>	Orange safety fence down	<b>Pic 2 Desc.</b>	P1 silt fence across travel lane for added protection		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11722+30	<b>Field Station#</b>	11732+33		
<b>Pic 3 Desc.</b>	P1 damaged by wildlife	<b>Pic 4 Desc.</b>	P1 silt fence perimeter control		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11747+00	<b>Field Station#</b>	11764+01		
<b>Pic 5 Desc.</b>	Good vegetation on topsoil piles	<b>Pic 6 Desc.</b>	RCE in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2021 8:30 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2021 8:30 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	22945
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	5/3/2021 1:15 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	P1 down at 11626+25	24 Hours	
Silt Fence (Reinforce Filter Fence)	Communication	SSF fabric down at 3 locations	24 Hours	
Other - Explain in Comments	Communication	Orange barricade fence down	24 Hours	
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2021 1:15 PM	<b>Report #</b>	22945
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a regular scheduled VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The ROW received light rainfall during inspection. The ROW is currently stable with no erosion on the surface or any issues caused by runoff. Slope breakers remain intact. Perimeter control are in place. ECD maintenance needs identified today will be compiled on a punch list and submitted to the contractor for repair or replacement. Some ECDs in the area are worn but the amount of disturbance required to replace them does not warrant the effort at this time. Resource buffers are stable and ECDs are in place. No slips were located. No evidence of vandalism was discovered.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time 5/3/2021 1:15 PM		Report #			
Pictures							
<p>Date &amp; Time: Mon, May 03, 2021, 1:15:00 EDT Position: +037.312847 / -080.317294 (+16.4ft) Altitude: 2023ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 085° N85E 1511mits Magnetic (+15°) Elevation Angle: -34.8° Horizon Angle: +00.2° Zoom: 1.0X 11631+50 repair SSF fabric</p> 		<p>Date &amp; Time: Mon, May 03, 2021, 1:25:00 EDT Position: +037.313547 / -080.406747 (+32.8ft) Altitude: 1881ft (+78.7ft) Datum: WGS-84 Azimuth/Bearing: 186° S06W 1807mits Magnetic (+15°) Elevation Angle: -00.3° Horizon Angle: -06.9° Zoom: 1.0X 11626+25 P1 silt fence crossing</p> 					
GPS Location		On photo		GPS Location		On photo	
Field Station#		11631+50		Field Station#		11626+25	
Pic 1 Desc.		Communication; SSF fabric down at 11625+10, 11631+00 and 11631+50.		Pic 2 Desc.		Communication; P1 silt fence down at S-HH18 crossing.	
<p>Date &amp; Time: Mon, May 03, 2021, 10:55:12 EDT Position: +037.313547 / -080.406747 (+32.8ft) Altitude: 1881ft (+78.7ft) Datum: WGS-84 Azimuth/Bearing: 186° S06W 1807mits Magnetic (+15°) Elevation Angle: -00.3° Horizon Angle: -06.9° Zoom: 1.0X 11624+00 repair orange barricade fence</p> 		<p>Date &amp; Time: Mon, May 03, 2021, 10:55:12 EDT Position: +037.313547 / -080.406747 (+32.8ft) Altitude: 1881ft (+78.7ft) Datum: WGS-84 Azimuth/Bearing: 186° S06W 1807mits Magnetic (+15°) Elevation Angle: -00.3° Horizon Angle: -06.9° Zoom: 1.0X 11600+75 perimeter controls</p> 					
GPS Location		On photo		GPS Location		On photo	
Field Station#		11624+00		Field Station#		11600+75	
Pic 3 Desc.		Communication; orange barricade fence down.		Pic 4 Desc.		Perimeter controls are in place and functional.	
<p>Date &amp; Time: Mon, May 03, 2021, 10:40:18 EDT Position: +037.313147 / -080.404028 (+13.4ft) Altitude: 1960ft (+78.7ft) Datum: WGS-84 Azimuth/Bearing: 234° S56W 419mits Magnetic (+15°) Elevation Angle: -08.5° Horizon Angle: -02.8° Zoom: 1.0X 11608+17 S-006 crossing</p> 		<p>Date &amp; Time: Mon, May 03, 2021, 10:36:48 EDT Position: +037.303597 / -080.402657 (+16.4ft) Altitude: 1970ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 074° N74E 1316mits Magnetic (+15°) Elevation Angle: -11.2° Horizon Angle: +00.8° Zoom: 1.0X 11614+20 S-RR14 crossing</p> 					
GPS Location		On photo		GPS Location		On photo	
Field Station#		11608+17		Field Station#		11614+20	
Pic 5 Desc.		The S-006 crossing is stable.		Pic 6 Desc.		The S-RR14 crossing is stable.	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/3/2021 1:15 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11614+75	<b>Field Station#</b>	11626+04		
<b>Pic 7 Desc.</b>	Perimeter controls are in place.	<b>Pic 8 Desc.</b>	The S-HH18 crossing is stable.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11635+00	<b>Field Station#</b>	11658+00		
<b>Pic 9 Desc.</b>	Perimeter controls are in place.	<b>Pic 10 Desc.</b>	Perimeter controls are in place.		
		<div style="text-align: center; height: 100px;">Insert image here</div>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>			
<b>Field Station#</b>	11669+00	<b>Field Station#</b>			
<b>Pic 11 Desc.</b>	Top of Brush Mountain stable. No evidence of vandalism discovered.	<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2021 1:15 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	22950
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/3/2021 4:02 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/3/2021 4:02 PM	<b>Report #</b>	22950
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11788+52 to ST# 12005+00 (MP 223.27 to MP 227.37) No crews actively working in area No stream crossings through this section of ROW Significant vegetation throughout ROW ROW has been stabilized with permanent waterbars and level spreaders in place. Triple ECD protection at karst features in place AR- 266.03, 266, and MT Tabor road crossing RCE are maintained in acceptable condition AR- 266.02 has not been constructed Catawba rain gauge will be checked tomorrow due to active rain event at time of inspection Row is wet and in stable condition No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2021 4:02 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11790+00	<b>Field Station#</b>	11796+00		
<b>Pic 1 Desc.</b>	RCE in place	<b>Pic 2 Desc.</b>	ECDs in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11843+83	<b>Field Station#</b>	11833+00		
<b>Pic 3 Desc.</b>	P1 and supersilt perimeter controls in place	<b>Pic 4 Desc.</b>	Waterbars and level spreaders in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11977+00	<b>Field Station#</b>	11200+00		
<b>Pic 5 Desc.</b>	Triple protection in place at karst	<b>Pic 6 Desc.</b>	Vegetation on ROW		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2021 4:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2021 4:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	22980
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/4/2021 8:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Craig	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2021 8:31 AM	<b>Report #</b>	22980
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="border: 1px solid black; height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to MP 219.70) No compliance issues found Observed composite crew lowering in section of pipe between ST# 11544+00 and ST# 11549+00 ECDs have been replaced in area where composite crew is working ROW is damp and in stable condition up until JNF property line ST# 11553+66. Top soil piles stabilized and slope drain pipes installed from two-tone carrying water across open ditch into waterbar. No crews are actively working in JNF Rain gauge measures 0.2" at Craig Creek from 5/3/21 Row is damp and stabilized throughout JNF with areas of vegetation 50' buffers in place at stream crossings S-PP22, S-PP21, S-PP20 AR-258.02 and Craig Creek road crossing RCE are maintained in acceptable condition No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:31 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11549+00	<b>Field Station#</b>	11549+55		
<b>Pic 1 Desc.</b>	End treatments in place	<b>Pic 2 Desc.</b>	Slope drains in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11569+00	<b>Field Station#</b>	11573+77		
<b>Pic 3 Desc.</b>	Waterbars in place	<b>Pic 4 Desc.</b>	Clean water diversion berm in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11583+00	<b>Field Station#</b>	11588+00		
<b>Pic 5 Desc.</b>	P1 perimeter control in place	<b>Pic 6 Desc.</b>	Buffer in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	22981
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/4/2021 8:33 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.05
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Culvert	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, May 04, 2021, 12:32:28 EDT  Position: +037.342493° / -080.677255° (+16.30)  Altitude: 1692ft (+11.20)  Datum: WGS-84  Azimuth/Bearing: 135° S45E 3200mils True (+12°)  Elevation Angle: -05.8°  Horizon Angle: +00.5°  Zoom: 1.0X  12005+00</p> 		<p>Date &amp; Time: Tue, May 04, 2021, 12:30:03 EDT  Position: +037.342493° / -080.677255° (+16.30)  Altitude: 1692ft (+11.20)  Datum: WGS-84  Azimuth/Bearing: 198° S18W 3520mils True (+12°)  Elevation Angle: -15.5°  Horizon Angle: +00.7°  Zoom: 1.0X  12005+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	Secondary containment in place		<b>Pic 2 Desc.</b>	Culvert in place	
<p>Date &amp; Time: Tue, May 04, 2021, 12:05:16 EDT  Position: +037.342272° / -080.676920° (+16.24)  Altitude: 1706ft (+11.20)  Datum: WGS-84  Azimuth/Bearing: 171° S09E 3050mils True (+13°)  Elevation Angle: -03.3°  Horizon Angle: +01.6°  Zoom: 1.0X  12005+00</p> 		<p>Date &amp; Time: Tue, May 04, 2021, 12:04:37 EDT  Position: +037.342262° / -080.676920° (+16.24)  Altitude: 1706ft (+11.20)  Datum: WGS-84  Azimuth/Bearing: 337° N03W 3340mils True (+13°)  Elevation Angle: -00.2°  Horizon Angle: +00.7°  Zoom: 1.0X  12005+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Waste bins in place		<b>Pic 4 Desc.</b>	Employee parking	
<p>Date &amp; Time: Tue, May 04, 2021, 12:04:37 EDT  Position: +037.342262° / -080.676920° (+16.24)  Altitude: 1706ft (+11.20)  Datum: WGS-84  Azimuth/Bearing: 133° S03E 3370mils True (+13°)  Elevation Angle: -07.1°  Horizon Angle: +00.6°  Zoom: 1.0X  12005+00</p> 		<p>Date &amp; Time: Tue, May 04, 2021, 12:04:37 EDT  Position: +037.342262° / -080.676920° (+16.24)  Altitude: 1706ft (+11.20)  Datum: WGS-84  Azimuth/Bearing: 076° N06E 3360mils True (+13°)  Elevation Angle: -10.8°  Horizon Angle: -06.6°  Zoom: 1.0X  12005+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	Secondary containment in place		<b>Pic 6 Desc.</b>	CFS triple stack perimeter control in place	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:33 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	22982
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/4/2021 8:34 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			
Secondary Containment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:34 AM	<b>Report #</b>	22982
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
VA SWPPP inspection of LDY 28 Western portion: RCE is in acceptable condition CFS perimeter control in place Secondary containments are in place for portable toilets and where needed under buses and trucks. Two transport buses, six road trucks, and six trailers are being stored at the time of inspection Eastern portion: RCE is in acceptable condition CFS perimeter control in place Five road trucks, five trailers, one fuel truck, one transport bus, and one mechanic truck are being stored at the time of inspection. Secondary containments are in place for portable toilets and where needed under trucks. Pocahontas rain gauge measures trace amounts from 5/3/21 Thunderstorms rolled in around 2PM					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2021 8:34 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Trucks and transport buses parked at yard	<b>Pic 2 Desc.</b>	Secondary containment in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	Waste bins in place	<b>Pic 4 Desc.</b>	RCE in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	Secondary containment in place	<b>Pic 6 Desc.</b>	CFS perimeter control in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:34 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:34 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	22983
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/4/2021 8:35 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			
Roadside Ditch	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:35 AM	<b>Report #</b>	22983
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
VA SWPPP inspection of LDY 26 Waste management is acceptable House keeping is acceptable. CFS triple stack perimeter controls are in acceptable condition. Secondary containments are in place for light plants, portable toilets, and other hazardous materials where needed Rock surface is in acceptable condition. Rain gauge at Kow camp measured 0.1" of accumulation from 5/3/21 Thunderstorms moved in around 2PM					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2021 8:35 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Secondary containment in place	<b>Pic 2 Desc.</b>	CFS triple stack perimeter control in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	Waste bins in place	<b>Pic 4 Desc.</b>	Fuel island in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	Secondary containment in place	<b>Pic 6 Desc.</b>	Safety fence in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:35 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2021 8:35 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	23025
<b>Inspector</b>	James Cotton			<b>Date/Time</b>	5/5/2021 7:00 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.45
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) No
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Communication	complete install of diversion pipe		
Compost Filter Berm	Communication	Remove soil against CFS		
Waterbar End Treatment	Communication	Complete install of end treatment		
Equipment Bridge	Communication	Repair side boards remove sed.		
Silt Fence (Filter Fabric Fence)	Communication	Repair fence		
Sensitive Resource Buffer	Communication	Pull soil back f/P1 fence on Karst		
Silt Fence (Reinforce Filter Fence)	Communication	Repair SSF		





## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2021 7:00 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10936+00	<b>Field Station#</b>	10939+72		
<b>Pic 1 Desc.</b>	Repair SSF.	<b>Pic 2 Desc.</b>	Install ECDs to protect top soil.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11065+10	<b>Field Station#</b>	10952+75		
<b>Pic 3 Desc.</b>	CFS added to equipment bridge over drainage feature. BMPs	<b>Pic 4 Desc.</b>	Pic 1 equipment bridge needs runner mats replaced.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10963+90	<b>Field Station#</b>	10952+75		
<b>Pic 5 Desc.</b>	Bridge over drainage feature needs repaired.	<b>Pic 6 Desc.</b>	Pic 2 side boards need repaired on bridge.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2021 7:00 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Wed, May 05, 2021, 12:22:45 EDT Position: +037.320410° / -080.571310° (s=30.00) Altitude: 2317ft (s=30.00) Datum: WGS-84 Azimuth/Bearing: 301° N59W 5391mils True (s=12°) Elevation Grade: -02% Horizon Grade: -02% Elevation: 10966+00 SWPPP Inspection: 10966+00 MVP H-600</small></p>		 <p><small>Date &amp; Time: Wed, May 05, 2021, 12:33:22 EDT Position: +037.320172° / -080.575020° (s=541.40) Altitude: 2254ft (s=79.80) Datum: WGS-84 Azimuth/Bearing: 299° N61W 5314mils True (s=12°) Elevation Grade: -02% Horizon Grade: +000% Elevation: 10955+57 SWPPP Inspection: 10955+57 MVP H-600</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10966+00	<b>Field Station#</b>	10955+57		
<b>Pic 7 Desc.</b>	Pull soil back from P1 filter fence around Karst feature.	<b>Pic 8 Desc.</b>	VA SWPPP INSPECTION		
 <p><small>Date &amp; Time: Wed, May 05, 2021, 12:22:18 EDT Position: +037.327414° / -080.571310° (s=21.70) Altitude: 2333ft (s=37.30) Datum: WGS-84 Azimuth/Bearing: 301° N59W 5391mils True (s=12°) Elevation Grade: -02% Horizon Grade: -02% Elevation: 10966+00 SWPPP Inspection: 10966+00 MVP H-600</small></p>		 <p><small>Date &amp; Time: Wed, May 05, 2021, 12:34:37 EDT Position: +037.326574° / -080.577758° (s=18.50) Altitude: 2401ft (s=37.30) Datum: WGS-84 Azimuth/Bearing: 119° S68E 5332mils True (s=12°) Elevation Grade: -02% Horizon Grade: -01% Elevation: 10977+00 SWPPP Inspection: 10977+00 MVP H-600</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10966+00	<b>Field Station#</b>	10978+00		
<b>Pic 9 Desc.</b>	VA SWPPP INSPECTION	<b>Pic 10 Desc.</b>	Pull soil back from CFS.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2021 7:00 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	23053
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/5/2021 6:22 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10674+81
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+62
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Housekeeping	Acceptable			

## 5. Site Conditions







Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2021 6:22 PM	<b>Report #</b>	23053
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10674+81 to ST# 10929+62 (MP 202.17 to MP 207.00) No compliance issues found. Rain gauge measured 0.3" at Kow camp road crossing #2 accumulated from 5/4/21 The ROW from ST# 10802+44 (Archer Trail) to ST# 10929+62 (Doe Creek) is damp and in stable condition. Observed Northern clearing using stump grinder at ST# 10863+00 Observed Grade crew stripping top soil between ST# 10912+00 and ST# 10921+00 The ROW from ST# 10674+81 (Big Stony Rd) to ST# 10749+51 (Hendricks Rd) is damp and stable with plenty of vegetation. Observed northern clearing building brush piles at ST# 10719+00 Observed forward control crew installing supersilt fence at ST# 10707+00. Observed Northern clearing burning brush piles between ST# 10686+50 and ST# 10677+50. Water morooka and fire extinguishers on site. 50' buffers in place at stream crossings S-Y2, S-Y3, S-A32, S-A33, S-A34, S-Z14, S-G33, S-G32, and S-G30 Buffer in place at wetland W-Z11 AR-241.02, 241.04, 241.01, and 241 are maintained in acceptable condition. Doe Creek, Kow Camp #1, Kow Camp #2, and Big Stony creek road crossing RCE's are maintained in acceptable condition. AR- 241.03 has been cleared and ECDs have been installed. Rock still needs to be added before use. Hendricks road crossing RCE has not yet been constructed. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time 5/5/2021 6:22 PM		Report #			
Pictures							
 <p>Date &amp; Time: Wed, May 05, 2021, 10:24:50 EDT Position: 400° 29' 33.92" N / -80° 51' 40.92" W Altitude: 2570 ft (+19.7m) Datum: WGS 84 Azimuth/Bearing: 281° N29W 4996mils True (+12°) Elevation Angle: -33.0 Horizon Angle: +00.6 Zoom: 1.0X 10804+50</p>		 <p>Date &amp; Time: Wed, May 05, 2021, 10:24:50 EDT Position: 400° 29' 33.92" N / -80° 51' 40.92" W Altitude: 2570 ft (+19.7m) Datum: WGS 84 Azimuth/Bearing: 281° N29W 4996mils True (+12°) Elevation Angle: -33.0 Horizon Angle: +00.6 Zoom: 1.0X 10822+57</p>					
GPS Location		See photo		GPS Location		See photo	
Field Station#		10804+50		Field Station#		10822+57	
Pic 1 Desc.		Sensitive resource signage on display		Pic 2 Desc.		CFS perimeter control in place	
 <p>Date &amp; Time: Wed, May 05, 2021, 10:24:50 EDT Position: 400° 29' 33.92" N / -80° 51' 40.92" W Altitude: 2570 ft (+19.7m) Datum: WGS 84 Azimuth/Bearing: 174° S06E 3093mils True (+12°) Elevation Angle: -26.9 Horizon Angle: +07.1 Zoom: 1.0X 10830+50</p>		 <p>Date &amp; Time: Wed, May 05, 2021, 10:24:50 EDT Position: 400° 29' 33.92" N / -80° 51' 40.92" W Altitude: 2570 ft (+19.7m) Datum: WGS 84 Azimuth/Bearing: 174° S06E 3093mils True (+12°) Elevation Angle: -26.9 Horizon Angle: +07.1 Zoom: 1.0X 10839+00</p>					
GPS Location		See photo		GPS Location		See photo	
Field Station#		10830+50		Field Station#		10839+00	
Pic 3 Desc.		Triple protection for karst in place		Pic 4 Desc.		Triple stack CFS perimeter control in place	
 <p>Date &amp; Time: Wed, May 05, 2021, 10:24:50 EDT Position: 403° 33' 52.71" N / -80° 52' 14.31" W Altitude: 2168 ft (+9.8ft) Datum: WGS 84 Azimuth/Bearing: 138° S42E 2453mils True (+12°) Elevation Angle: +13.4 Horizon Angle: +00.5 Zoom: 1.0X 10864+00</p>		 <p>Date &amp; Time: Wed, May 05, 2021, 10:24:50 EDT Position: 403° 33' 52.71" N / -80° 52' 14.31" W Altitude: 2168 ft (+9.8ft) Datum: WGS 84 Azimuth/Bearing: 138° S42E 2453mils True (+12°) Elevation Angle: +13.4 Horizon Angle: +00.5 Zoom: 1.0X 10882+00</p>					
GPS Location		See photo		GPS Location		See photo	
Field Station#		10864+00		Field Station#		10882+00	
Pic 5 Desc.		Perimeter control supersilt in place		Pic 6 Desc.		Buffer in place	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2021 6:22 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10883+45	<b>Field Station#</b>	10886+00		
<b>Pic 7 Desc.</b>	Kow camp rain gauge measures 0.3"	<b>Pic 8 Desc.</b>	End treatments on hill in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10899+50	<b>Field Station#</b>	10745+67		
<b>Pic 9 Desc.</b>	Perimeter control silt fence in place	<b>Pic 10 Desc.</b>	Vegetation on ROW		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10720+00	<b>Field Station#</b>	10679+71		
<b>Pic 11 Desc.</b>	Northern building brush piles	<b>Pic 12 Desc.</b>	Replaced CFS buffer		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2021 6:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	23086
<b>Inspector</b>	James Cotton			<b>Date/Time</b>	5/6/2021 2:01 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	66.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Equipment Bridge	Communication	Fix ECDs at edge of drainage feat.		
Stone Inlet Protection	Communication	Remove soil from stone inlet		
Rock Construction Entrance	Acceptable	AR249, 249.01, 249.02, 245.02,		
Energy Dissipater	Acceptable			
Equipment Bridge	Communication	waddles across drainage feature.		







<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2021 2:01 PM	<b>Report #</b>	23086
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP Inspection from 11064+53 to 11254+99 (MP 209.56 to MP 213.16) Deficiencies found are as follows; 11191+40 Repair equipment bridge and ECDs beside. Remove sediment from drainage feature leading to Karst. 11188+30 Repair two tone slope inlet 11125+00 Repair OCSF around sensitive resource area. 11098+25 Close off equipment bridge with waddles. Buffers were installed and functional on drainage features 11026+00 and 11099+00. 11191+00 was in disrepair and will be added to the punch list No further issues seen. Stabilization was adequate on stockpiles. Clean-water diversion pipes were functional. Earthen water bars had clean flow path except for travel lane. Crews actively working in area was pipe facing, fire line, welding, coating, environmental. Access roads 245.01, 245.02, and 249.02, 249.01, and 249. Winding Way RCE had adequate stone. And street was clean. Access roads 249.03 not in use. Mountain lake road clear of sediment and debris. Karst feature at 11135+00-11131+00 & 11190+00-11193+00 had triple protection in place and functional with no issues. Punch listed sediment drainage feature inside/leading to Karst and to fix equipment bridge and ECDs. Rain fall was .45" taken from AR244 on 5/4/21. ROW is dry and sunny.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2021 2:01 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11098+25	<b>Field Station#</b>	11125+00		
<b>Pic 1 Desc.</b>	Place wattle across equipment bridge on drainage feature.	<b>Pic 2 Desc.</b>	Repair OCSF around sensitive area.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11191+00	<b>Field Station#</b>	11191+40		
<b>Pic 3 Desc.</b>	Repair ECDs beside bridge. Remove soil in feature.	<b>Pic 4 Desc.</b>	Repair ECDs beside bridge.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11168+00	<b>Field Station#</b>	11190+75		
<b>Pic 5 Desc.</b>	Diversion pipe and energy dissipater functional.	<b>Pic 6 Desc.</b>	Karst feature. Triple protection functional.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2021 2:01 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, May 06, 2021, 11:00:44 EDT Position: +037.215550° / -080.516248° (s1826.22) Altitude: 2204ft (s38.00) Datum: WGS-84 Azimuth/Bearing: 107° 57'3E 1902mils True (s15°) Elevation Grade: +014X Horizon Grade: +002X Zoom: 1.0X VA SWPPP INSPECTION 11078+69 MVP H-600</p>		 <p>Date &amp; Time: Thu, May 06, 2021, 09:41:43 EDT Position: +037.309551° / -080.560788° (s13780.22) Altitude: 1902ft (s31.40) Datum: WGS-84 Azimuth/Bearing: 300° 00'1W 0402mils True (s10°) Elevation Grade: +010X Horizon Grade: +000X Zoom: 1.0X VA SWPPP INSPECTION 11068+00 MVP H-600</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11151+25	<b>Field Station#</b>	11068+00		
<b>Pic 7 Desc.</b>	CWDB was stabilized. Water bars functional.	<b>Pic 8 Desc.</b>	Water bars functional.		
 <p>Date &amp; Time: Thu, May 06, 2021, 09:49:08 EDT Position: +037.215550° / -080.539404° (s32.88) Altitude: 2204ft (s38.00) Datum: WGS-84 Azimuth/Bearing: 107° 57'3E 1902mils True (s15°) Elevation Grade: +014X Horizon Grade: +002X Zoom: 1.0X VA SWPPP INSPECTION 11078+69 MVP H-600</p>		 <p>Date &amp; Time: Thu, May 06, 2021, 09:49:08 EDT Position: +037.215550° / -080.539404° (s32.88) Altitude: 2204ft (s38.00) Datum: WGS-84 Azimuth/Bearing: 107° 57'3E 1902mils True (s15°) Elevation Grade: +014X Horizon Grade: +002X Zoom: 1.0X VA SWPPP INSPECTION 11078+69 MVP H-600</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11078+69	<b>Field Station#</b>	11078+69		
<b>Pic 9 Desc.</b>	Construction berm along grade functional.	<b>Pic 10 Desc.</b>	Stockpiles & CWDB stabilized.		
 <p>Date &amp; Time: Thu, May 06, 2021, 11:25:40 EDT Position: +037.215550° / -080.539404° (s32.88) Altitude: 1902ft (s31.40) Datum: WGS-84 Azimuth/Bearing: 300° 00'1W 0402mils True (s10°) Elevation Grade: +010X Horizon Grade: +000X Zoom: 1.0X VA SWPPP INSPECTION 11125+00 MVP H-600</p>		 <p>Date &amp; Time: Thu, May 06, 2021, 11:28:25 EDT Position: +037.215550° / -080.539404° (s32.88) Altitude: 1902ft (s31.40) Datum: WGS-84 Azimuth/Bearing: 300° 00'1W 0402mils True (s10°) Elevation Grade: +010X Horizon Grade: +000X Zoom: 1.0X VA SWPPP INSPECTION 11188+00 MVP H-600</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11125+00	<b>Field Station#</b>	11188+00		
<b>Pic 11 Desc.</b>	Soil stockpiles stabilized. Waddles in place between gaps.	<b>Pic 12 Desc.</b>	Clean slope drain inlet. PL item		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2021 2:01 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	23093
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/6/2021 6:07 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+16
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Communication	See comments		
Silt Fence (Filter Fabric Fence)	Communication	See comments		
Temporary Diversion Berm	Communication	See comments		
Other - Explain in Comments	Communication	Stabilization/ see comments		
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			







### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2021 6:07 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, May 06, 2021, 08:51:49 EDT Position: +032.33773° / -080.46638° (-548.4ft) Altitude: 2244ft (+696ft) Datum: WGS-84 Azimuth Bearing: 204° S24W 3627mils True (+12°) Elevation Angle: -51.1° Horizon Angle: +0.2° Zoom: 1.0x 11278+79</p>		 <p>Date &amp; Time: Thu, May 06, 2021, 09:04:25 EDT Position: +032.33773° / -080.46638° (-548.4ft) Altitude: 2244ft (+696ft) Datum: WGS-84 Azimuth Bearing: 107° S23E 1902mils True (+12°) Elevation Angle: -51.1° Horizon Angle: +0.2° Zoom: 1.0x 11292+30</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11278+79	<b>Field Station#</b>	11292+30		
<b>Pic 1 Desc.</b>	Temporary ROW berm needs stabilized	<b>Pic 2 Desc.</b>	P1 needs retrenched and backfilled		
 <p>Date &amp; Time: Thu, May 06, 2021, 10:15:28 EDT Position: +032.30370° / -080.46672° (-543.2ft) Altitude: 2184ft (+626.2ft) Datum: WGS-84 Azimuth Bearing: 035° N38E 0676mils True (+12°) Elevation Angle: -18.9° Horizon Angle: -10.2° Zoom: 1.0x 11344+00</p>		 <p>Date &amp; Time: Thu, May 06, 2021, 10:45:09 EDT Position: +037.307735° / -080.466351° (-511.6ft) Altitude: 1959ft (+59.1ft) Datum: WGS-84 Azimuth Bearing: 200° S20W 3556mils True (+12°) Elevation Angle: -50.2° Horizon Angle: -12.8° Zoom: 1.0x 11361+70</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11344+00	<b>Field Station#</b>	11361+70		
<b>Pic 3 Desc.</b>	Segregate soils and rebuild temporary ROW berm	<b>Pic 4 Desc.</b>	Stabilize behind end treatment		
 <p>Date &amp; Time: Thu, May 06, 2021, 12:00:48 EDT Position: +037.25887° / -080.45531° (-567.2ft) Altitude: 2210ft (+612.1ft) Datum: WGS-84 Azimuth Bearing: 054° N55E 1316mils True (+13°) Elevation Angle: -47.0° Horizon Angle: -05.0° Zoom: 1.0x 11507+59</p>		 <p>Date &amp; Time: Thu, May 06, 2021, 06:34:01 EDT Position: +037.25523° / -080.45549° (-568.2ft) Altitude: 2204ft (+606.4ft) Datum: WGS-84 Azimuth Bearing: 101° S79E 1790mils True (+13°) Elevation Angle: -03.0° Horizon Angle: -05.0° Zoom: 1.0x 11271+32</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11507+59	<b>Field Station#</b>	11271+32		
<b>Pic 5 Desc.</b>	Reattach mining belt	<b>Pic 6 Desc.</b>	Good vegetation on slope		



AFE	124300137	Date/Time	5/6/2021 6:07 PM	Report #	
Pictures					
<p>Date &amp; Time: Thu, May 06, 2021, 09:08:51 EDT Position: +037.296351° / -080.480950° (+28.5ft) Altitude: 2078ft (+29.4ft) Datum: WGS-84 Azimuth/Bearing: 253° S73W 4498mils True (+12°) Elevation Angle: -01.3° Horizon Angle: -00.4° Zoom: 1.0X 11294+00</p> 		<p>Date &amp; Time: Thu, May 06, 2021, 09:07:57 EDT Position: +037.311221° / -080.482111° (+28.1ft) Altitude: 2091ft (+29.7ft) Datum: WGS-84 Azimuth/Bearing: 358° N62W 5329mils True (+12°) Elevation Angle: -19.0° Horizon Angle: -04.6° Zoom: 1.0X 11342+70</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11294+00	Field Station#	11342+70		
Pic 7 Desc.	Stream buffer in place	Pic 8 Desc.	Rock inlet in place		
<p>Date &amp; Time: Thu, May 06, 2021, 10:53:08 EDT Position: +037.319563° / -080.443018° (+28.1ft) Altitude: 2093ft (+29.7ft) Datum: WGS-84 Azimuth/Bearing: 303° N57W 5387mils True (+12°) Elevation Angle: -27.1° Horizon Angle: -00.5° Zoom: 1.0X 11373+80</p> 		<p>Date &amp; Time: Thu, May 06, 2021, 12:04:57 EDT Position: +037.318525° / -080.442511° (+28.1ft) Altitude: 2135ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 242° S82W 4658mils True (+12°) Elevation Angle: -07.6° Horizon Angle: -04.4° Zoom: 1.0X 11446+55</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11373+80	Field Station#	11446+55		
Pic 9 Desc.	Plunge pool in place	Pic 10 Desc.	6" buffer of mulch on topsoil pile		
<p>Date &amp; Time: Thu, May 06, 2021, 12:37:49 EDT Position: +037.321953° / -080.435807° (+34.4ft) Altitude: 2270ft (+39.7ft) Datum: WGS-84 Azimuth/Bearing: 100° N05E 5037mils True (+12°) Elevation Angle: -03.2° Horizon Angle: -06.0° Zoom: 1.0X 11472+43</p> 		<p>Date &amp; Time: Thu, May 06, 2021, 12:45:49 EDT Position: +037.325555° / -080.425555° (+38.0ft) Altitude: 2317ft (+45.9ft) Datum: WGS-84 Azimuth/Bearing: 100° N07E 4855mils True (+12°) Elevation Angle: -04.1° Horizon Angle: -06.1° Zoom: 1.0X 11484+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11472+43	Field Station#	11484+00		
Pic 11 Desc.	Karst triple protection ECDs in place	Pic 12 Desc.	CFS perimeter control in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2021 6:07 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	23124
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	5/7/2021 12:01 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 12:01 PM	<b>Report #</b>	23124
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
A regular scheduled VADEQ SWPPP inspection was completed today on JNF and private lands at Brush Mountain. The ROW is currently stable with no erosion issues or slips located. Perimeter ECDs are in place with no maintenance needs identified. Slope breakers and end treatments are functioning as designed and controlling stormwater runoff properly. Resource crossing buffers are stable. ECDs at the crossings are in place. There has not been any apparent impact to streams in the area. No evidence of vandalism was discovered today.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/7/2021 12:01 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, May 07, 2021, 09:49:45 EDT Position: +037.202547° / -880.394887° (+16.470) Altitude: 2300ft (+13.170) Datum: WGS-84 Azimuth/Bearing: 140° S46E 340ft/mile Magnetic (+13°) Elevation Angle: +07.7° Horizon Angle: +00.6° Zoom: 1.0X 11668+00</p>		 <p>Date &amp; Time: Fri, May 07, 2021, 09:51:01 EDT Position: +037.202547° / -880.394887° (+16.470) Altitude: 2326ft (+13.250) Datum: WGS-84 Azimuth/Bearing: 347° N18W 616ft/mile Magnetic (+13°) Elevation Angle: +07.7° Horizon Angle: +00.7° Zoom: 1.0X 11660+00</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11668+00	<b>Field Station#</b>	11660+00		
<b>Pic 1 Desc.</b>	Perimeter controls are in place. ROW surface stable.	<b>Pic 2 Desc.</b>	Perimeter controls are in place. No maintenance needs were identified.		
 <p>Date &amp; Time: Fri, May 07, 2021, 09:52:17 EDT Position: +037.202547° / -880.394887° (+16.470) Altitude: 2300ft (+13.170) Datum: WGS-84 Azimuth/Bearing: 166° S14E 295ft/mile Magnetic (+13°) Elevation Angle: +07.7° Horizon Angle: +02.3° Zoom: 1.0X 11653+00</p>		 <p>Date &amp; Time: Fri, May 07, 2021, 09:54:25 EDT Position: +037.202547° / -880.394887° (+16.470) Altitude: 2198ft (+12.930) Datum: WGS-84 Azimuth/Bearing: 189° S09W 336ft/mile Magnetic (+13°) Elevation Angle: +04.1° Horizon Angle: +04.9° Zoom: 1.0X 11646+00</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11653+00	<b>Field Station#</b>	11646+00		
<b>Pic 3 Desc.</b>	Perimeter controls in place. ROW stable.	<b>Pic 4 Desc.</b>	Perimeter ECDs in place.		
 <p>Date &amp; Time: Fri, May 07, 2021, 09:55:17 EDT Position: +037.202547° / -880.394887° (+16.470) Altitude: 2126ft (+12.970) Datum: WGS-84 Azimuth/Bearing: 205° S04W 366ft/mile Magnetic (+13°) Elevation Angle: +06.6° Horizon Angle: +08.5° Zoom: 1.0X 11639+00</p>		 <p>Date &amp; Time: Fri, May 07, 2021, 09:57:01 EDT Position: +037.213600° / -880.398137° (+16.401 7ft) Altitude: 1947ft (+5.250) Datum: WGS-84 Azimuth/Bearing: 336° N24W 597ft/mile Magnetic (+13°) Elevation Angle: +18.5° Horizon Angle: +00.1° Zoom: 1.0X 11626+50</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11639+00	<b>Field Station#</b>	11626+50		
<b>Pic 5 Desc.</b>	Perimeter ECDs in place.	<b>Pic 6 Desc.</b>	ECDs functional upslope of S-HH18 crossing.		



AFE	124300137	Date/Time	5/7/2021 12:01 PM	Report #	
Pictures					
 <p>Date &amp; Time: Fri, May 07, 2021, 09:17:00 EDT Position: +037.313887° / -080.401370° (±16.4ft) Altitude: 1998ft (±78.7ft) Datum: WGS-84 Azimuth/Bearing: 277° N83W 4924mils Magnetic (±13°) Elevation Angle: -18.4° Horizon Angle: -03.3° Zoom: 1.0X 11614+50</p>		 <p>Date &amp; Time: Fri, May 07, 2021, 09:19:53 EDT Position: +037.313887° / -080.402337° (±98.4ft) Altitude: 1998ft (±78.7ft) Datum: WGS-84 Azimuth/Bearing: 277° N83W 4924mils Magnetic (±13°) Elevation Angle: -18.4° Horizon Angle: -03.3° Zoom: 1.0X 11614+20 S-RR14 crossing</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11618+50	Field Station#	11614+20		
Pic 7 Desc.	ROW stable.	Pic 8 Desc.	Buffers stable at the S-RR14 crossing.		
 <p>Date &amp; Time: Fri, May 07, 2021, 09:26:50 EDT Position: +037.313887° / -080.404766° (±32.8ft) Altitude: 1922ft (±70.0ft) Datum: WGS-84 Azimuth/Bearing: 178° S02E 3164mils Magnetic (±13°) Elevation Angle: -08.5° Horizon Angle: -00.2° Zoom: 1.0X 11608+17 S-006 crossing</p>		 <p>Date &amp; Time: Fri, May 07, 2021, 09:29:00 EDT Position: +037.313887° / -080.408835° (±16.4ft) Altitude: 1899ft (±69.7ft) Datum: WGS-84 Azimuth/Bearing: 001° N00E 3164mils Magnetic (±13°) Elevation Angle: -04.6° Horizon Angle: -01.0° Zoom: 1.0X 11605+00</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11608+17	Field Station#	11605+00		
Pic 9 Desc.	The S-006 crossing is stable.	Pic 10 Desc.	ROW is stable.		
 <p>Date &amp; Time: Fri, May 07, 2021, 09:31:14 EDT Position: +037.313498° / -080.264488° (±16.6ft) Altitude: 1925ft (±76.2ft) Datum: WGS-84 Azimuth/Bearing: 289° S72W 4480mils Magnetic (±13°) Elevation Angle: -09.1° Horizon Angle: +01.4° Zoom: 1.0X 11601+00</p>		Insert image here			
GPS Location	On photo			GPS Location	
Field Station#	11601+00	Field Station#			
Pic 11 Desc.	Perimeter ECDs in place. ROW currently stable.	Pic 12 Desc.			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 12:01 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	23131
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/7/2021 5:15 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	56.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 5:15 PM	<b>Report #</b>	23131
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11788+52 to ST# 12005+00 (MP 223.27 to MP 227.37) No compliance issues found. No crews actively working in area. No stream crossings through this section of ROW. Significant vegetation throughout ROW. ROW has been stabilized with permanent waterbars and level spreaders in place. Triple ECD protection at karst features in place. AR- 266.03, 266, and MT Tabor road crossing RCE are maintained in acceptable condition. AR- 266.02 has not been constructed. Light rain shower moved in on ROW around 1PM. Row is damp and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300137		Date/Time		5/7/2021 5:15 PM		Report #							
Pictures															
															
GPS Location				See photo				GPS Location				See photo			
Field Station#				11792+07				Field Station#				11826+00			
Pic 1 Desc.				CFS controls in place				Pic 2 Desc.				Waterbars/ level spreaders in place			
															
GPS Location				See photo				GPS Location				See photo			
Field Station#				11850+00				Field Station#				11929+00			
Pic 3 Desc.				Level spreaders in place				Pic 4 Desc.				P1 perimeter control in place			
															
GPS Location				See photo				GPS Location				See photo			
Field Station#				11958+00				Field Station#				11971+00			
Pic 5 Desc.				Good vegetation on ROW				Pic 6 Desc.				Waterbars in place			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 5:15 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 5:15 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	23133
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	5/7/2021 5:30 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	53.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 5:30 PM	<b>Report #</b>	23133
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 to ST# 11788+52 (MP 221.02 to MP 223.27) No compliance issues found. No crews are actively working in area. Environmental crew has been through section and completed punch list items since last VA SWPPP inspection. P1 silt fence is in place across travel lane of steep slopes before bridges for added protection to streams. Top soil stock piles, clean water diversion berms, and travel lane are stabilized. Waterbars are in place with sump pits and waterbar end treatments. Triple ECD protection at karst features in place. 50' buffers in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCE are maintained in acceptable condition. The ROW is damp and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 5:30 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, May 07, 2021, 09:24:10 EDT Position: +037 294322° / -85° 380764° (-28.846°) Altitude: 2215ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 100° 50W (-80mils True) (-12°) Elevation Angle: +0.3° Horizon Angle: +0.3° Zoom: 1.0X 11771+00</p>		 <p>Date &amp; Time: Fri, May 07, 2021, 09:04:55 EDT Position: +037 294322° / -85° 380764° (-28.846°) Altitude: 2215ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 113° 50E (200mils True) (-2°) Elevation Angle: +0.3° Horizon Angle: +0.3° Zoom: 1.0X 11705+50</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11771+00	<b>Field Station#</b>	11705+50		
<b>Pic 1 Desc.</b>	Supersilt perimeter control in place	<b>Pic 2 Desc.</b>	ROW stabilized		
 <p>Date &amp; Time: Fri, May 07, 2021, 09:26:51 EDT Position: +037 294322° / -85° 380764° (-28.846°) Altitude: 2215ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 090° 49W (-160mils True) (-12°) Elevation Angle: +0.3° Horizon Angle: +0.3° Zoom: 1.0X 11724+74</p>		 <p>Date &amp; Time: Fri, May 07, 2021, 10:06:45 EDT Position: +037 294322° / -85° 380764° (-28.846°) Altitude: 2160ft (+36.3ft) Datum: WGS-84 Azimuth/Bearing: 140° 51E (240mils True) (-2°) Elevation Angle: +0.3° Horizon Angle: +0.3° Zoom: 1.0X 11787+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11724+74	<b>Field Station#</b>	11787+00		
<b>Pic 3 Desc.</b>	P1 perimeter control in place	<b>Pic 4 Desc.</b>	RCE in place		
 <p>Date &amp; Time: Fri, May 07, 2021, 09:52:11 EDT Position: +037 294322° / -85° 375760° (-16.11.804°) Altitude: 2025ft (+10.31ft) Datum: WGS-84 Azimuth/Bearing: 231° 55W (-107mils True) (-12°) Elevation Angle: +0.3° Horizon Angle: +0.3° Zoom: 1.0X 11740+79</p>		 <p>Date &amp; Time: Fri, May 07, 2021, 10:13:39 EDT Position: +037 294322° / -85° 367244° (-15.51ft) Altitude: 2094ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 123° 55E (2187mils True) (-12°) Elevation Angle: +0.3° Horizon Angle: +0.3° Zoom: 1.0X 11762+61</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11740+79	<b>Field Station#</b>	11762+61		
<b>Pic 5 Desc.</b>	Buffer in place	<b>Pic 6 Desc.</b>	CFS perimeter control in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 5:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/7/2021 5:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		