



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23723
Inspector	John White			Date/Time	5/24/2021 10:27 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Dry	Temperature (°F)	86.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Other - Explain in Comments	Communication	Repair safety fence		

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	5/24/2021 10:27 AM	Report #	23723
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There was one issue identified and added to the punch list. The Contractor is working on repairing the identified issue. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/24/2021 10:27 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15746+00	Field Station#	15745+00		
Pic 1 Desc.	Observing safety fence that requires maintenance	Pic 2 Desc.	Observing temporary stabilization and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15763+80	Field Station#	15768+00		
Pic 3 Desc.	Observing temporary stabilization, signage, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization		
					
GPS Location	O	GPS Location	O		
Field Station#	15658+43	Field Station#	15677+00		
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's		

AFE	124300139	Date/Time	5/24/2021 10:27 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15690+00	Field Station#	157003+00		
Pic 7 Desc.	Observing sump and end treatment	Pic 8 Desc.	Observing temporary stabilization, erosion control blanket, water bar and cfs check.		
					
GPS Location	O	GPS Location	O		
Field Station#	15720+00	Field Station#	15735+00		
Pic 9 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 10 Desc.	Observing temporary stabilization, sump and end treatment		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	5/24/2021 10:27 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23724
Inspector	Justin Burch			Date/Time	5/24/2021 10:44 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Dry	Temperature (°F)	82.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	5/24/2021 10:44 AM	Report #	23724
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). The contractor had an Environmental laborer walk with the EI on his inspection. No issues were submitted for the punch list because inspected ECDs were in compliance at the time of inspection. • The EI has not observed that the contractor has worked in the inspection area since the last SWPPP inspection. • Since the last SWPPP inspection the area has not received any rainfall events. • The ROW ground condition is dry. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14011+00 to 14018+00. • At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/24/2021 10:44 AM	Report #	
Pictures					
227°SW (M) 37°2'46"N, 79°53'32"W ±1568ft ▲1093ft  13959+00 24 May 2021, 08:42:04		79°E (M) 37°2'59"N, 79°53'32"W ±45ft ▲1116ft  13969+00 24 May 2021, 08:49:07			
GPS Location	0	GPS Location	0		
Field Station#	13959+00	Field Station#	13969+00		
Pic 1 Desc.	P1 silt fence in acceptable condition	Pic 2 Desc.	Temporary vegetative stabilization in acceptable condition		
276°W (M) 37°3'42"N, 79°52'45"W ±59ft ▲1099ft  14038+00 24 May 2021, 09:36:22		289°W (M) 37°3'42"N, 79°52'46"W ±475ft ▲1061ft  14038+00 24 May 2021, 09:35:56			
GPS Location	0	GPS Location	0		
Field Station#	14038+00	Field Station#	14038+00		
Pic 3 Desc.	Waterbar in acceptable condition	Pic 4 Desc.	Waterbar end treatment in acceptable condition		
82°E (M) 37°3'57"N, 79°52'35"W ±101ft ▲1173ft  14057+00 24 May 2021, 10:59:40		214°SW (M) 37°3'25"N, 79°52'51"W ±52ft ▲1094ft  14016+00 24 May 2021, 13:06:07			
GPS Location	0	GPS Location	0		
Field Station#	14057+00	Field Station#	14016+00		
Pic 5 Desc.	Slope drain in acceptable condition	Pic 6 Desc.	Permanent vegetative stabilization in acceptable condition		

A/E	124300139	Date/Time	5/24/2021 10:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/24/2021 10:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23726
Inspector	Ben Farmer			Date/Time	5/24/2021 12:30 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Dry	Temperature (°F)	77.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to			
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	5/24/2021 12:30 PM	Report #	23726
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 77 F) Rain Gauge= 0.0" 15260+00-15370+62 -EI began inspection at Snowberry Rd. -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in place and functioning. -Buffer area P1 has been damaged at 15346+20 and needs to be replaced. -CWDs are in good condition throughout this section of ROW. -Wetland buffer at 15312+27 remains in good condition. -Waterbars are in good condition throughout this section of ROW. -Vegetation continuing to fill in throughout this section *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/24/2021 12:30 PM	Report #	
Pictures					
 <p>232°SW (T) LAT: 36.925140 LON: -79.517306 ±13ft ▲ 689ft</p> <p>1534620 24 May 2021, 08:49:15</p>		 <p>286°W (T) LAT: 36.922257 LON: -79.511044 ±9ft ▲ 792ft</p> <p>0 24 May 2021, 10:32:42</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	15346+20		Field Station#	15370+00	
Pic 1 Desc.	P1 has been damaged and needs to be replaced.		Pic 2 Desc.	Vegetation continues to fill in ROW throughout this section.	
 <p>311°NW (T) LAT: 36.924875 LON: -79.516808 ±13ft ▲ 698ft</p> <p>0 24 May 2021, 08:47:54</p>		 <p>257°W (T) LAT: 36.926596 LON: -79.519621 ±9ft ▲ 763ft</p> <p>0 24 May 2021, 08:54:18</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	15346+70		Field Station#	15338+00	
Pic 3 Desc.	Equipment bridge ECDs are in good condition and functioning.		Pic 4 Desc.	CWDs are in good condition throughout this section of ROW.	
 <p>132°SE (T) LAT: 36.929169 LON: -79.523094 ±13ft ▲ 732ft</p> <p>0 24 May 2021, 09:04:20</p>		 <p>137°SE (T) LAT: 36.929435 LON: -79.523464 ±13ft ▲ 732ft</p> <p>0 24 May 2021, 09:05:17</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	15325+00		Field Station#	15323+24	
Pic 5 Desc.	Vegetation continues to fill in ROW throughout this section.		Pic 6 Desc.	RCEs are in good condition at all road crossings.	

AFE	124300139	Date/Time	5/24/2021 12:30 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15312+27	Field Station#	15310+00		
Pic 7 Desc.	Wetland buffer at this location remains in good condition.	Pic 8 Desc.	Waterbars are in good condition throughout this section of ROW.		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	15299+00	Field Station#			
Pic 9 Desc.	CWDs are functioning as intended.	Pic 10 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	5/24/2021 12:30 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23732
Inspector	Ben Davenport			Date/Time	5/24/2021 1:07 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Temporary Diversion Berm	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	5/24/2021 1:07 PM	Report #	23732
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Cloudy with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14802+19 — 14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -No items added to punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/24/2021 1:07 PM	Report #	
Pictures					
					
36°58'31" N 79°40'31" W 149°SE COURSE 211' GPS 05.24.2021 09:08:20 Accur +/-36.3 Ft ALT 955 Ft			36°58'23" N 79°40'12" W 123°SE COURSE 116' GPS 05.24.2021 09:18:47 Penhook, VA 24137, United States Accur +/-54.0 Ft ALT 951 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14815+00		Field Station#	14832+61	
Pic 1 Desc.	Permanent vegetation growing in final cleanup area along ROW.		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing	
					
36°58'12" N 79°39'5" W 120°SE COURSE 24' GPS 05.24.2021 09:59:01 2201 Bar Ridge Rd, Penhook, VA 24137, United States Accur +/-118.8 Ft ALT 987 Ft			36°58'20" N 79°39'55" W 176°S COURSE 36' GPS 05.24.2021 11:26:23 Penhook, VA 24137, United States Accur +/-63.5 Ft ALT 821 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14881+54		Field Station#	14847+00	
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing		Pic 4 Desc.	View of extra workspace GAS Listening Hill Rd	
					
36°58'12" N 79°39'5" W 116°SE COURSE 86' GPS 05.24.2021 10:04:03 Penhook, VA 24137, United States Accur +/-213.0 Ft ALT 887 Ft			36°58'6" N 79°38'25" W 142°SE COURSE 295' GPS 05.24.2021 10:19:52 Sorry no results found Accur +/-35.4 Ft ALT 821 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14895+00		Field Station#	14923+00	
Pic 5 Desc.	Temporary vegetation growing along ROW. Area is stabilized.		Pic 6 Desc.	Temporary vegetation growing along ROW. Area is stabilized. Perimeter controls in place and functional.	

A/E	124300139	Date/Time	5/24/2021 1:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/24/2021 1:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23728
Inspector	Charles Head			Date/Time	5/24/2021 1:24 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
3rd Party Damages	Communication	Repair P-1 damaged by livestock			
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Repair livestock damage			
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/24/2021 1:24 PM	Report #	23728
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/24/2021 1:24 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14546+33	Field Station#	14524+50		
Pic 1 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.		Pic 2 Desc.	Approximately 14524+50. Overview of road crossing and RCEs.	
					
GPS Location	0	GPS Location	0		
Field Station#	14497+20	Field Station#	14496+50		
Pic 3 Desc.	Approximately 14497+20. P-1 requires maintenance. Damaged by livestock.		Pic 4 Desc.	Approximately 14496+50. Overview of ROW. Cattle graze and frequent area and were present during inspection.	
					
GPS Location	0	GPS Location	0		
Field Station#	14486+60	Field Station#	14471+00		
Pic 5 Desc.	Approximately 14486+60. Overview of stream crossing, equipment bridge and ECDs at stream S-G22.		Pic 6 Desc.	Approximately 14471+00. Overview of ROW.	

A/E	124300139	Date/Time	5/24/2021 1:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/24/2021 1:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23758
Inspector	Ben Davenport			Date/Time	5/25/2021 7:40 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Dry	Temperature (°F)	78.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Housekeeping	Communication	Remove trash	Addressed	5/25/2021	
Compost Filter Sock	Communication	Routine maintenance	Addressed	5/25/2021	
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance	Addressed	5/25/2021	
Temporary Diversion Berm	Communication	Routine maintenance	Addressed	5/25/2021	
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/25/2021 7:40 AM	Report #	23758
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Cloudy with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14928+52 — 15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; 4 issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Observed contractor performing environmental maintenance and completing punch list items submitted -Verified the completion of punch list item in section -Continue to monitor ROW for signs of erosion -4 items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/25/2021 7:40 AM	Report #	
Pictures					
					
36°57'55" N 79°35'55" W 306°NW COURSE -1° GPS Penhook, VA 24137, United States 05.25.2021 08:06:57 Accur +/-15.9 Ft ALT 814 Ft			36°57'55" N 79°35'54" W 276°W COURSE -1° GPS Penhook, VA 24137, United States 05.25.2021 08:05:57 Accur +/-38.9 Ft ALT 821 Ft		
GPS Location	1		GPS Location	2	
Field Station#	15046+00		Field Station#	15046+50	
Pic 1 Desc.	Housekeeping. Remove trash pile from ROW.		Pic 2 Desc.	Routine maintenance. Replace CFS check dams that are beyond effective lifespan.	
					
36°57'55" N 79°35'54" W 287°W COURSE 2° GPS Penhook, VA 24137, United States 05.25.2021 08:05:47 Accur +/-82.7 Ft ALT 909 Ft			36°57'50" N 79°35'43" W 277°W COURSE 307° GPS Penhook, VA 24137, United States 05.25.2021 07:56:10 Accur +/-260.0 Ft ALT 901 Ft		
GPS Location	3		GPS Location	4	
Field Station#	15047+00		Field Station#	15052+00	
Pic 3 Desc.	Routine maintenance. Replace worn/damaged rows of P1 silt fence.		Pic 4 Desc.	Routine maintenance. Seed and stabilize denuded area of temporary diversion berm.	
					
36°57'49" N 79°35'42" W 11°N COURSE -1° GPS Penhook, VA 24137, United States 05.25.2021 08:03:07 Accur +/-33.3 Ft ALT 909 Ft			36°57'56" N 79°37'16" W 320°NW COURSE 286° GPS 19101-19383 Snow Creek Rd, Penhook, VA 24137, United States 05.25.2021 09:03:19 Accur +/-23.3 Ft ALT 953 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15060+00		Field Station#	14971+00	
Pic 5 Desc.	Area marked off limit for work after completion of avian survey.		Pic 6 Desc.	Vegetation growing in final cleanup area of ROW.	

A/E	124300139	Date/Time	5/25/2021 7:40 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	5/25/2021 7:40 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23763
Inspector	John White			Date/Time	5/25/2021 10:03 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Rock Filter Outlet	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Contractor is working on repairs			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/25/2021 10:03 AM	Report #	23763
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/25/2021 10:03 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15934+00	Field Station#	15923+49		
Pic 1 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15878+08	Field Station#	15838+00		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing p1 that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15825+00	Field Station#	15785+00		
Pic 5 Desc.	Observing temporary stabilization,plunge pool and ECD's	Pic 6 Desc.	Observing temporary stabilization,CWD outlet and ECD's		

AFE	124300139	Date/Time	5/25/2021 10:03 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15800+00	Field Station#	15838+00		
Pic 7 Desc.	Observing temporary stabilization, erosion control blanket and cfs checks		Pic 8 Desc.	Observing p1 that requires maintenance	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	5/25/2021 10:03 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23766
Inspector	Justin Burch			Date/Time	5/25/2021 11:30 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar End Treatment	Acceptable				
Waterbar	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Compost Filter Sock	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/25/2021 11:30 AM	Report #	23766
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). The contractor had an Environmental laborer walk with the EI on his inspection. No issues were submitted for the punch list because inspected ECDs were in compliance at the time of inspection. • The EI observed that the contractor has addressed a punch list item submitted at the last SWPPP inspection. • Since the last SWPPP inspection the area has not received any rainfall events. • The ROW ground condition is dry. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. • At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/25/2021 11:30 AM	Report #	
Pictures					
91°E (M) 37°3'52"N, 79°52'32"W ±1466ft ▲1204ft  14063+00 25 May 2021, 08:39:04		22°NE (M) 37°3'48"N, 79°52'31"W ±226ft ▲1180ft  14071+00 25 May 2021, 08:44:29			
GPS Location	0	GPS Location	0		
Field Station#	14063+00	Field Station#	14071+00		
Pic 1 Desc.	Temporary vegetative stabilization in acceptable condition.	Pic 2 Desc.	P1 silt fence in acceptable condition		
223°SW (M) 37°3'49"N, 79°52'30"W ±541ft ▲1186ft  14077+00 25 May 2021, 08:58:03		236°SW (M) 37°3'52"N, 79°52'15"W ±32ft ▲1185ft  14077+00 25 May 2021, 08:58:23			
GPS Location	0	GPS Location	0		
Field Station#	14077+00	Field Station#	14077+00		
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	Waterbar in acceptable condition		
304°NW (M) 37°3'46"N, 79°51'28"W ±36ft ▲1098ft  14120+00 25 May 2021, 09:36:33		85°E (M) 37°3'22"N, 79°50'51"W ±22ft ▲1027ft  14165+00 25 May 2021, 12:28:43			
GPS Location	0	GPS Location	0		
Field Station#	14120+00	Field Station#	14165+00		
Pic 5 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 6 Desc.	Perimeter CFS in acceptable condition		

A/E	124300139	Date/Time	5/25/2021 11:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		













A/E	124300139	Date/Time	5/25/2021 11:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23775
Inspector	Charles Head			Date/Time	5/25/2021 3:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Dry	Temperature (°F)	82.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/25/2021 3:41 PM	Report #	23775
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/25/2021 3:41 PM	Report #	
Pictures					
  25 May 2021, 10:05:40		  25 May 2021, 10:44:35		GPS Location	0
Field Station#	14646+00	Field Station#	14599+00	Field Station#	14599+00
Pic 1 Desc.	Approximately 14646+00. Overview of ROW.	Pic 2 Desc.	Approximately 14599+00. Overview of road crossing and RCEs.	Pic 2 Desc.	Approximately 14599+00. Overview of road crossing and RCEs.
  25 May 2021, 10:44:49		  25 May 2021, 13:24:16		GPS Location	0
Field Station#	14595+50	Field Station#	14603+00	Field Station#	14603+00
Pic 3 Desc.	Approximately 14595+50. Overview of ROW.	Pic 4 Desc.	Approximately 14603+00. Overview of ROW.	Pic 4 Desc.	Approximately 14603+00. Overview of ROW.
  25 May 2021, 13:45:54		  25 May 2021, 13:48:22		GPS Location	0
Field Station#	14549+00	Field Station#	14568+10	Field Station#	14568+10
Pic 5 Desc.	Approximately 14549+00. Overview of ROW.	Pic 6 Desc.	Approximately 14568+10. Overview of stream crossing, equipment bridge and ECDs at stream S-E18.	Pic 6 Desc.	Approximately 14568+10. Overview of stream crossing, equipment bridge and ECDs at stream S-E18.

A/E	124300139	Date/Time	5/25/2021 3:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/25/2021 3:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23780
Inspector	Logan Box			Date/Time	5/25/2021 3:52 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Damp	Temperature (°F)	80.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Timber Mat	Acceptable				
Equipment Bridge	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/25/2021 3:52 PM	Report #	23780
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/25/2021 3:52 PM	Report #	
Pictures					
	North Elevation 			South Elevation 	
GPS Location	00000	GPS Location	0000		
Field Station#	13728+11	Field Station#	13728+11		
Pic 1 Desc.	Stream observation photo facing downstream during routine inspection today. No issues observed at the time of inspection.		Pic 2 Desc.	Stream observation photo facing upstream during routine inspection today. No issues observed at the time of inspection.	
	South East Elevation 			South East Elevation 	
GPS Location	0000	GPS Location	00000		
Field Station#	13729+00	Field Station#	13721+10		
Pic 3 Desc.	Monitored ECDs and stream protection along with stabilization on hill side above stream crossing. No environmental issues observed at the time of inspection.		Pic 4 Desc.	Vegetation observation photo up row from stream crossing. No environmental issues observed at the time of inspection. Good coverage noted at the time of inspection.	
	South Elevation 			South East Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13691+28	Field Station#	13739+20		
Pic 5 Desc.	Monitored ECDs around wetland area. All ECDs functioning at the time of inspection.		Pic 6 Desc.	Observed CFS on row boundary. All ECDs functioning at the time of inspection.	

A/E	124300139	Date/Time	5/25/2021 3:52 PM	Report #	
Pictures					
		<p>Insert image here</p>		<p>Insert image here</p>	
GPS Location	0000	GPS Location			
Field Station#	13692+78	Field Station#			
Pic 7 Desc.	Monitored ECDs and protection in wetland area , no environmental issues observed at the time of inspection .	Pic 8 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	5/25/2021 3:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23782
Inspector	Ben Farmer			Date/Time	5/25/2021 5:52 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	P1 is damaged/degraded and needs	Addressed	5/25/2021
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300139	Date/Time	5/25/2021 5:52 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15413+72		Field Station#	15413+72	
Pic 1 Desc.	P1 is damaged and needs to be replaced.		Pic 2 Desc.	Environmental crew has corrected this issue.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15427+31		Field Station#	15427+31	
Pic 3 Desc.	P1 has been damaged and needs to be replaced.		Pic 4 Desc.	Environmental crew has corrected this issue.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15375+00		Field Station#	15383+00	
Pic 5 Desc.	Drainage ECDs are in good condition and functioning.		Pic 6 Desc.	Waterbars are functioning as intended.	

AFE	124300139	Date/Time	5/25/2021 5:52 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15384+24		Field Station#	15385+00	
Pic 7 Desc.	Equipment bridge ECDs are in good condition.		Pic 8 Desc.	Sensitive resource buffer is in good condition at this location.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15390+00		Field Station#	15440+00	
Pic 9 Desc.	Vegetation continues to fill in ROW.		Pic 10 Desc.	Vegetation continues to fill in ROW.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15453+00		Field Station#	15457+00	
Pic 11 Desc.	CWD is in good condition.		Pic 12 Desc.	Drainage is in good condition with no evidence of sedimentation from 3rd party disturbance.	

AFE	124300139	Date/Time	5/25/2021 5:52 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15460+81		Field Station#	15460+81	
Pic 13 Desc.	3rd party rock outlet appears to be in good condition at this drainage.		Pic 14 Desc.	CWD is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15465+00		Field Station#	15475+00	
Pic 15 Desc.	3rd party rock outlet appears to be in good condition.		Pic 16 Desc.	3rd party rock outlet in good condition along this drainage.	
				Insert image here	
GPS Location	See photo		GPS Location		
Field Station#	15480+67		Field Station#		
Pic 17 Desc.	RCEs are in good condition at all road crossings		Pic 18 Desc.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23817
Inspector	Ben Farmer			Date/Time	5/26/2021 10:31 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Partial	Station End	15584+23
County	Pittsylvania	Ground	Dry	Temperature (°F)	77.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/26/2021 10:31 AM	Report #	23817
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px; border: 1px solid black;"></div>					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 77 F) Rain Gauge= 0.0" 15480+67-15584+23 -EI began inspection at Anderson Mill Rd. -RCEs are in good condition at all road crossings. -Slope drain is in good condition and functioning at 15575+87. -Waterbars are functioning as intended throughout this section of ROW. -Equipment bridge ECDs are in place and functioning. -CWDs are in good condition throughout this section. -3rd party ECDs appear to be in good condition with no evidence of sedimentation onto MVP ROW at 15510+29. EI will continue to monitor this area for any changes in condition. -P1 is in good condition at all stream and wetland buffers. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/26/2021 10:31 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15580+00		Field Station#	15575+87	
Pic 1 Desc.	Vegetation continues to fill in ROW throughout this section.		Pic 2 Desc.	Slope drain is in good condition and continues to function as intended.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15547+37		Field Station#	15542+32	
Pic 3 Desc.	Waterbars are in good condition throughout this section.		Pic 4 Desc.	Equipment bridge ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15515+00		Field Station#	15510+29	
Pic 5 Desc.	CWDs are in good condition.		Pic 6 Desc.	3rd party ECDs appear to be in good condition. No evidence of sedimentation onto MVP ROW.	

AFE	124300139	Date/Time	5/26/2021 10:31 AM	Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15506+41		Field Station#	15506+41	
Pic 7 Desc.	P1 is in good condition at all stream and wetland buffers.		Pic 8 Desc.	Vegetation continues to fill in ROW throughout this section.	
GPS Location	See photo		GPS Location	See photo	
Field Station#	15496+70		Field Station#	15495+00	
Pic 9 Desc.	RCEs are in good condition at all road crossings.		Pic 10 Desc.	Vegetation continues to fill in ROW throughout this section.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	5/26/2021 10:31 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	23820	
Inspector	John White			Date/Time	5/26/2021 10:59 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Dry	Temperature (°F)	88.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
Waterbar End Treatment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	5/26/2021 10:59 AM	Report #	23820
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/26/2021 10:59 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	8+00	Field Station#	6+00		
Pic 1 Desc.	Observing temporary stabilization, water bar, sump and end treatment		Pic 2 Desc.	Observing temporary stabilization, sump and end treatment	
GPS Location	O	GPS Location	O		
Field Station#	10+00	Field Station#	18+83		
Pic 3 Desc.	Observing temporary stabilization		Pic 4 Desc.	Observing temporary stabilization, signage, buffer and ECD's	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	5/26/2021 10:59 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





A/E	124300139	Date/Time	5/26/2021 10:59 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I		AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision				Report #	23822	
Inspector	John White				Date/Time	5/26/2021 11:09 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	00+00	
State	VA	Inspection Area	Full		Station End	19+25	
County	Pittsylvania	Ground	Dry		Temperature (°F)	88.00	
Municipality	Chatham	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Housekeeping		Acceptable					
Sediment Filter Log		Acceptable					
Sensitive Resource Buffer		Acceptable					
Sensitive Resource Signage		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	5/26/2021 11:09 AM	Report #	23822
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/26/2021 11:09 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	19+00	Field Station#	15+00		
Pic 1 Desc.	Observing temporary stabilization and ECD's		Pic 2 Desc.	Observing temporary stabilization	
					
GPS Location	O	GPS Location	O		
Field Station#	12+65	Field Station#	6+00		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		Pic 4 Desc.	Observing temporary stabilization and access road	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	5/26/2021 11:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






A/E	124300139	Date/Time	5/26/2021 11:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23836
Inspector	John White			Date/Time	5/26/2021 11:15 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	88.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/26/2021 11:15 AM	Report #	23836
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/26/2021 11:15 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	16016+36	Field Station#	16006+00		
Pic 1 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing temporary stabilization, water bar, sump and end treatment		
					
GPS Location	O	GPS Location	O		
Field Station#	16004+00	Field Station#	16010+00		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer and ECD's	Pic 4 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15999+80	Field Station#	15982+00		
Pic 5 Desc.	Observing temporary stabilization, water bar, signage, buffer and ECD's	Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's		

AFE	124300139	Date/Time	5/26/2021 11:15 AM	Report #	
Pictures					
GPS Location	O		GPS Location	O	
Field Station#	15977+35		Field Station#	15970+00	
Pic 7 Desc.	Observing temporary stabilization, water bar, signage, buffer, equipment crossing and ECD's		Pic 8 Desc.	Observing temporary stabilization	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 9 Desc.			Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	5/26/2021 11:15 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23825
Inspector	Ben Davenport			Date/Time	5/26/2021 11:53 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Partial	Station End	15142+66
County	Pittsylvania	Ground	Dry	Temperature (°F)	86.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Routine maintenance	Addressed	5/26/2021	
Rock Check Dam	Communication	Routine maintenance	Addressed	5/26/2021	
Equipment Bridge	Acceptable				
Sediment Filter Log	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/26/2021 11:53 AM	Report #	23825
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; 2 issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Identified areas marked off-limits for construction activities following avian survey -Observed contractor performing environmental maintenance on punch list items in covered area -Verified the completion of punch list items -Continue to monitor ROW for signs of erosion -2 items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/26/2021 11:53 AM	Report #	
Pictures					
					
36°57'8" N 79°34'49" W 14°N COURSE 39° GPS Sandy Level, VA 24161, United States 05.26.2021 07:59:15 Accur +/-45.2 Ft ALT 880 Ft			36°57'7" N 79°34'49" W 6°N COURSE 136° GPS Sandy Level, VA 24161, United States 05.26.2021 10:07:46 Accur +/-73.2 Ft ALT 883 Ft		
GPS Location	1		GPS Location	2	
Field Station#	15126+40		Field Station#	15126+40	
Pic 1 Desc.	Routine maintenance. Replace worn perimeter CFS in resource buffer beyond effective lifespan.		Pic 2 Desc.	Contractor replaced perimeter CFS per punch list item.	
					
36°57'7" N 79°34'50" W 76°E COURSE -1° GPS Sandy Level, VA 24161, United States 05.26.2021 08:02:31 Accur +/-44.3 Ft ALT 885 Ft			36°57'7" N 79°34'49" W 306°NW COURSE 99° GPS Sandy Level, VA 24161, United States 05.26.2021 10:07:58 Accur +/-19.8 Ft ALT 878 Ft		
GPS Location	3		GPS Location	4	
Field Station#	15127+00		Field Station#	15127+00	
Pic 3 Desc.	Routine maintenance. Replace CFS check dams that are beyond effective lifespan.		Pic 4 Desc.	Contractor replaced CFS check dams per punch list item.	
					
36°57'44" N 79°35'26" W 85°E COURSE 299° GPS Sandy Level, VA 24161, United States 05.26.2021 09:11:18 Accur +/-50.3 Ft ALT 863 Ft			36°57'44" N 79°35'21" W 295°NW COURSE 320° GPS Sandy Level, VA 24161, United States 05.26.2021 09:07:38 Accur +/-103.3 Ft ALT 882 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15075+00		Field Station#	15076+00	
Pic 5 Desc.	Area marked off-limits for construction activities due to avian survey completed at bridge crossing.		Pic 6 Desc.	CFS check dams performing intended function.	

A/E	124300139	Date/Time	5/26/2021 11:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	5/26/2021 11:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	23823		
Inspector	Justin Burch	Date/Time	5/26/2021 12:13 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Full	Station End	14311+57
County	Franklin	Ground	Dry	Temperature (°F)	87.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Other - Explain in Comments		Communication			
Silt Fence (Reinforce Filter Fence)		Communication			
Sump Pit		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	5/26/2021 12:13 PM	Report #	23823
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). Three issues were submitted for the punch list consisting of two locations where livestock damaged electric livestock fencing and another location where P1 silt fence appeared to have been damaged by livestock. Other inspected ECDs were in compliance at the time of inspection. The EI observed that the contractor has worked in the inspection area and addressed punch list items submitted at the last SWPPP inspection. Since the last SWPPP inspection the area has not received any rainfall events. The ROW ground condition is dry. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14258+00 to 14277+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/26/2021 12:13 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14172+00	Field Station#	14207+00		
Pic 1 Desc.	Waterbar in acceptable condition	Pic 2 Desc.	P1 silt fence in acceptable condition		
GPS Location	0	GPS Location	0		
Field Station#	14205+00	Field Station#	14302+00		
Pic 3 Desc.	Electric livestock fence damaged by livestock in multiple locations from 14203+00 to 14208+00	Pic 4 Desc.	Electric livestock fence damaged by livestock		
GPS Location	0	GPS Location	0		
Field Station#	14308+00	Field Station#	14251+50		
Pic 5 Desc.	P1 silt fence damaged by livestock (3 panels)	Pic 6 Desc.	Waterbar sump pit in acceptable condition		

A/E	124300139	Date/Time	5/26/2021 12:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/26/2021 12:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	23839	
Inspector	Glenn Mike Renfro			Date/Time	5/26/2021 3:20 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00	
State	VA	Inspection Area	Full	Station End	0000+00	
County	Franklin	Ground	Dry	Temperature (°F)	81.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable					
Housekeeping	Acceptable					
Rock Construction Entrance	Acceptable					
Secondary Containment	Acceptable					
Other - Explain in Comments	Acceptable	Inlet protection for catch basins				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	5/26/2021 3:20 PM	Report #	23839
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I main laydown yards MVP-LY-045 and MVP-LY-046. - The locations have not received any rainfall since the last inspection. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were in acceptable condition. - All secondary containment structures at both locations were in good condition. - All equipment was inspected and no leaks were observed during the time of the inspection. - The RCE at LY-045 was in good condition. - The General construction permits and contact information are posted at the main entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/26/2021 3:20 PM	Report #	
Pictures					
					
GPS Location		000000000000			
Field Station#		0000+00			
Pic 1 Desc.		Secondary containment structure for fuel cell at LY-046 in good condition.			
					
GPS Location		000000000000			
Field Station#		0000+00			
Pic 2 Desc.		Perimeter ECD's on west side of LY-046 in good condition.			
					
GPS Location		000000000000			
Field Station#		0000+00			
Pic 3 Desc.		Inlet protection for catch basin near storage building in acceptable condition.			
					
GPS Location		000000000000			
Field Station#		0000+00			
Pic 4 Desc.		Secondary containment structure on north end of LY-045 in good condition.			
					
GPS Location		000000000000			
Field Station#		0000+00			
Pic 5 Desc.		Perimeter ECD's on northwest corner near employee parking area at LY-045 in good condition.			
					
GPS Location		000000000000			
Field Station#		0000000000+00			
Pic 6 Desc.		RCE at LY-045 in good condition.			

A/E	124300139	Date/Time	5/26/2021 3:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/26/2021 3:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23816
Inspector	Logan Box			Date/Time	5/26/2021 3:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Plunge Pool	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Sump Pit	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/26/2021 3:21 PM	Report #	23816
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Monitored plunge pool and end treatment as well as Row boundary silt fence. All ECDs were functioning properly.</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/26/2021 3:21 PM	Report #	
Pictures					
	South West Elevation <small>46°NE (T) • 37.062178, -79.921199 ±7 m ▲ 312 m</small> 			North Elevation <small>195°S (T) • 37.06954, -79.928803 ±6 m ▲ 330 m</small> 	
GPS Location	00000	GPS Location	0000		
Field Station#	13840+00	Field Station#	13800+00		
Pic 1 Desc.	Observed plunge pool and row boundary silt fence. No environmental issues observed at the time of inspection.		Pic 2 Desc.	Monitored sump pit and end treatment as well as Row boundary silt fence . No issues were observed at the time of inspection.	
	West Elevation <small>87°E (T) • 37.060569, -79.921138 ±6 m ▲ 301 m</small> 			East Elevation <small>281°W (T) • 37.069339, -79.934123 ±4 m ▲ 291 m</small> 	
GPS Location	0000	GPS Location	0000		
Field Station#	13846+93	Field Station#	13780+80		
Pic 3 Desc.	Stream observation photo facing downstream during routine inspection today. No issues observed at the time of inspection.		Pic 4 Desc.	Row photo showing vegetation and row conditions during inspection today.	
	East Elevation <small>287°W (T) • 37.060585, -79.921127 ±5 m ▲ 298 m</small> 			North Elevation <small>186°S (T) • 37.070265, -79.930935 ±4 m ▲ 297 m</small> 	
GPS Location	0000	GPS Location	0000		
Field Station#	13846+93	Field Station#	13790+80		
Pic 5 Desc.	Stream observation photo facing downstream during routine inspection today. No issues were observed at the time of inspection.		Pic 6 Desc.	Monitored stabilization and ECDs at stream crossing. No issues observed at the time of inspection.	

A/E	124300139	Date/Time	5/26/2021 3:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/26/2021 3:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23835
Inspector	Charles Head			Date/Time	5/26/2021 4:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Dry	Temperature (°F)	87.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/26/2021 4:36 PM	Report #	23835
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/26/2021 4:36 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	14655+00		Field Station#	14665+00	
Pic 1 Desc.	Approximately 14655+00. Overview of ROW.		Pic 2 Desc.	Approximately 14665+00. Overview of ROW.	
					
GPS Location	0		GPS Location	0	
Field Station#	14673+10		Field Station#	14680+30	
Pic 3 Desc.	Approximately 14673+10. Overview of stream crossing, equipment bridge and ECDs at stream S-H37.		Pic 4 Desc.	Approximately 14680+30. Overview of stream crossing, equipment bridge and ECDs at stream S-H36.	
					
GPS Location	0		GPS Location	0	
Field Station#	14689+36		Field Station#	14694+50	
Pic 5 Desc.	Approximately 14689+36. Overview of stream crossing, equipment bridge and ECDs at stream S-H34.		Pic 6 Desc.	Approximately 14694+50. Overview of road crossing and RCE.	

A/E	124300139	Date/Time	5/26/2021 4:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/26/2021 4:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	23840	
Inspector	Frank Craycroft			Date/Time	5/26/2021 7:22 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Dry	Temperature (°F)	90.00	
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Timber Mat		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	5/26/2021 7:22 PM	Report #	23840
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All perimeter ECDs were functional and in good condition. All portable equipment and hazardous materials were within functional secondary containment. All waste was disposed of in bulk dumpsters which still have adequate capacity and inlet protections were free of debris to maintain adequate drainage. No issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/26/2021 7:22 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 1 Desc.	LY-048 Housekeeping		Pic 2 Desc.	LY-048 Equipment staging & construction entrance	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 3 Desc.	L-032 Secondary containment & equipment staging		Pic 4 Desc.	LY-032 Housekeeping & secondary containment	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 5 Desc.	LY-033 Waste management		Pic 6 Desc.	LY-033 Rock Construction Entrance	

AFE	124300139	Date/Time	5/26/2021 7:22 PM	Report #	
Pictures					
 <p>GPS: 177°S (T) 36.953307, -79.878718 ±16ft ▲ 1126ft</p> <p>Insert image here</p>		 <p>GPS: 128°SE (T) 36.952809, -79.87842 ±14ft ▲ 1111ft</p> <p>Insert image here</p>			
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	ANC-006 Inlet protection & secondary containment		Pic 8 Desc.	ANC-006 CFS Southeast corner	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	5/26/2021 7:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23862
Inspector	John White			Date/Time	5/27/2021 9:12 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Dry	Temperature (°F)	80.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/27/2021 9:12 AM	Report #	23862
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/27/2021 9:12 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15592+00	Field Station#	15594+00		
Pic 1 Desc.	Observing temporary stabilization and water bar.	Pic 2 Desc.	Observing temporary stabilization, water bar and erosion control blanket		
GPS Location	O	GPS Location	O		
Field Station#	15596+00	Field Station#	15617+00		
Pic 3 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing sump and end treatment		
GPS Location	O	GPS Location	O		
Field Station#	15623+00	Field Station#	15632+00		
Pic 5 Desc.	Observing temporary stabilization and water bars	Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's		

AFE	124300139	Date/Time	5/27/2021 9:12 AM	Report #	
Pictures					
		Insert image here			
GPS Location	O	GPS Location			
Field Station#	15636+45	Field Station#			
Pic 7 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	5/27/2021 9:12 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23864
Inspector	Justin Burch			Date/Time	5/27/2021 10:57 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Dry	Temperature (°F)	86.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Equipment Bridge	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/27/2021 10:57 AM	Report #	23864
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). An Environmental laborer from Precision walked with the EI on his inspection. No issues were submitted for the punch list because inspected ECDs were in compliance at the time of inspection. The EI has not observed that the contractor has worked in the inspection area since the last SWPPP inspection. Since the last SWPPP inspection the area has not received any rainfall events. The ROW ground condition is generally dry. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 13900+00 to 13940+00. At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/27/2021 10:57 AM	Report #	
Pictures					
<div>☉ 264°W (M) ● 37°2'53"N, 79°53'41"W ±22ft ▲ 1109ft</div> <div></div> <div>13957+00 27 May 2021, 08:43:42</div>			<div>☉ 220°SW (M) ● 37°2'52"N, 79°53'49"W ±82ft ▲ 1083ft</div> <div></div> <div>13952+00 27 May 2021, 08:51:23</div>		
GPS Location			0		
Field Station#			13957+00		
Pic 1 Desc.			Temporary vegetative stabilization in acceptable condition		
GPS Location			0		
Field Station#			13952+00		
Pic 2 Desc.			Waterbar in acceptable condition		
<div>☉ 17°N (M) ● 37°3'9"N, 79°54'35"W ±213ft ▲ 1111ft</div> <div></div> <div>13902+00 27 May 2021, 09:31:46</div>			<div>☉ 192°S (M) ● 37°3'9"N, 79°54'35"W ±26ft ▲ 1116ft</div> <div></div> <div>13902+00 27 May 2021, 09:32:05</div>		
GPS Location			0		
Field Station#			13902+00		
Pic 3 Desc.			P1 silt fence in acceptable condition		
GPS Location			0		
Field Station#			13902+00		
Pic 4 Desc.			Permanent vegetative stabilization in acceptable condition		
<div>☉ 282°W (M) ● 37°3'27"N, 79°54'49"W ±39ft ▲ 1025ft</div> <div></div> <div>13875+35 27 May 2021, 10:02:23</div>			<div>☉ 152°SE (M) ● 37°3'30"N, 79°55'6"W ±29ft ▲ 1040ft</div> <div></div> <div>13862+00 27 May 2021, 11:13:08</div>		
GPS Location			0		
Field Station#			13875+35		
Pic 5 Desc.			Equipment bridge in acceptable condition		
GPS Location			0		
Field Station#			13862+00		
Pic 6 Desc.			Waterbar end treatment in acceptable condition		

A/E	124300139	Date/Time	5/27/2021 10:57 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/27/2021 10:57 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23880
Inspector	Ben Davenport			Date/Time	5/27/2021 12:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Rock Construction Entrance	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Temporary Diversion Berm	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/27/2021 12:21 PM	Report #	23880
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Cloudy with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 - 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -No items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/27/2021 12:21 PM	Report #	
Pictures					
					
36°59'17" N 79°42'36" W 314°NW COURSE 65° GPS Union Hall, VA 24176, United States 05.27.2021 09:00:01 Accur +/-41.3 Ft ALT 950 Ft			36°59'19" N 79°42'10" W 12°N COURSE 262° GPS Union Hall, VA 24176, United States 05.27.2021 08:46:09 Accur +/-73.6 Ft ALT 902 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14694+77	Field Station#	14714+99		
Pic 1 Desc.	RCE at Jacks Creek Rd in good condition		Pic 2 Desc.	Perimeter SSF in extra workspace in place and functional	
					
36°59'0" N 79°41'23" W 180°S COURSE 72° GPS Union Hall, VA 24176, United States 05.27.2021 09:51:49 Accur +/-45.6 Ft ALT 825 Ft			36°59'15" N 79°41'54" W 8°N COURSE 271° GPS Union Hall, VA 24176, United States 05.27.2021 08:28:29 Accur +/-138.1 Ft ALT 902 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14760+00	Field Station#	14727+62		
Pic 3 Desc.	Spoil piles in extra workspace stabilized and vegetated		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional	
					
36°59'6" N 79°41'32" W 156°SE COURSE 85° GPS Sorry no results found 05.27.2021 08:19:42 Accur +/-76.2 Ft ALT 898 Ft			36°58'39" N 79°40'47" W 207°SW COURSE 99° GPS Union Hall, VA 24176, United States 05.27.2021 10:13:14 Accur +/-282.1 Ft ALT 958 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14751+50	Field Station#	14797+00		
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional		Pic 6 Desc.	ROW stabilized and vegetated in temporary area	

A/E	124300139	Date/Time	5/27/2021 12:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/27/2021 12:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23872
Inspector	Charles Head			Date/Time	5/27/2021 4:06 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Dry	Temperature (°F)	86.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/27/2021 4:06 PM	Report #	23872
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/27/2021 4:06 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14314+00	Field Station#	14333+00		
Pic 1 Desc.	Approximately 14314+00. Overview of ROW.	Pic 2 Desc.	Approximately 14333+00. Overview of road crossing and RCEs.		
					
GPS Location	0	GPS Location	0		
Field Station#	14408+00	Field Station#	14347+00		
Pic 3 Desc.	Approximately 14408+00. Overview of ROW.	Pic 4 Desc.	Approximately 14347+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14416+00	Field Station#	14450+00		
Pic 5 Desc.	Approximately 14416+00. Overview of ROW.	Pic 6 Desc.	Approximately 14450+00. Overview of ROW.		

A/E	124300139	Date/Time	5/27/2021 4:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/27/2021 4:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	23875		
Inspector	Ben Farmer	Date/Time	5/27/2021 4:54 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	78.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Equipment Bridge	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/27/2021 4:54 PM	Report #	23875
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 78F) Rain Gauge= 0.0" 15142+66-15260+00 -EI began inspection at the HDD exit. -RCEs are in good condition at all road crossings. -Sensitive resource buffer remains in good condition around ground nest at 15230+00. -Drainage ECDs are in good condition and functioning at 15195+00. -Waterbars are in good condition throughout this section. -Slope drain remains in good condition at 15170+50. -P1 is in good condition at all stream and wetland buffers. -Equipment bridge ECDs are in place and in good condition. -Rock outlet/inlet are in good condition at 15166+00/15165+57. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/27/2021 4:54 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15260+00		Field Station#	15235+00	
Pic 1 Desc.	Vegetation continues to fill in throughout this section of ROW.		Pic 2 Desc.	Vegetation continues to fill in throughout this section of ROW.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15230+00		Field Station#	15209+00	
Pic 3 Desc.	Sensitive resource buffer is in good condition around ground nest.		Pic 4 Desc.	Vegetation continues to fill in throughout this section of ROW.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15195+00		Field Station#	15190+00	
Pic 5 Desc.	Drainage ECDs are in place and in good condition.		Pic 6 Desc.	Vegetation continues to fill in throughout this section of ROW.	

AFE	124300139	Date/Time	5/27/2021 4:54 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15172+00		Field Station#	15170+50	
Pic 7 Desc.	Waterbars are in good condition throughout this section of ROW.		Pic 8 Desc.	Slope drain remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15169+47		Field Station#	15167+95	
Pic 9 Desc.	P1 is in good condition at all stream and wetland buffers.		Pic 10 Desc.	Equipment bridge ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15166+00		Field Station#	15165+57	
Pic 11 Desc.	Rock outlet is in good condition.		Pic 12 Desc.	Rock inlet is in good condition.	







A/E	124300139	Date/Time	5/27/2021 4:54 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23901
Inspector	Ben Davenport			Date/Time	5/28/2021 8:13 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Dry	Temperature (°F)	84.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Rock Construction Entrance	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Temporary Diversion Berm	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/28/2021 8:13 AM	Report #	23901
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14802+19 — 14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Walked ROW with environmental foreman and straw making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Observed contractor material staged in various parts of ROW for environmental maintenance -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Observed condition of vegetation in section both permanent and temporary areas of ROW -Continue to monitor ROW for signs of erosion -No items added to punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/28/2021 8:13 AM	Report #	
Pictures					
					
36°58'36" N 79°40'42" W 14°N COURSE -1° GPS 05.28.2021 10:56:07 Accur +/-32.5 Ft ALT 949 Ft			36°58'22" N 79°40'0" W 284°W COURSE 231° GPS 05.28.2021 10:32:10 1120 Listening Hill Rd, Penhook, VA 24137, United States Accur +/-16.2 Ft ALT 968 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14802+19	Field Station#	14840+00		
Pic 1 Desc.	MVP-FR-323 in good condition at time of inspection	Pic 2 Desc.	Temporary fill slope stabilized and vegetated. ECDs in place and functional		
					
36°58'15" N 79°39'26" W 60°NE COURSE 173° GPS 05.28.2021 08:47:28 1912 Novelty Rd, Penhook, VA 24137, United States Accur +/-80.0 Ft ALT 878 Ft			36°58'8" N 79°38'47" W 86°E COURSE 155° GPS 05.28.2021 09:08:54 Penhook, VA 24137, United States Accur +/-89.1 Ft ALT 0 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14870+00	Field Station#	14904+00		
Pic 3 Desc.	Perimeter SSF in place and functional	Pic 4 Desc.	Slope in temporary stabilized and vegetated. Water bars performing intended functions.		
					
36°58'6" N 79°38'26" W 186°S COURSE 108° GPS 05.28.2021 09:18:31 Sorry no results found Accur +/-130.3 Ft ALT 825 Ft			36°58'6" N 79°38'26" W 23°N COURSE 108° GPS 05.28.2021 09:21:39 Sorry no results found Accur +/-347.1 Ft ALT 825 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14913+00	Field Station#	14923+00		
Pic 5 Desc.	Permanent vegetation growing in final cleanup area along ROW	Pic 6 Desc.	P1 silt fence in good condition at resource		

A/E	124300139	Date/Time	5/28/2021 8:13 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/28/2021 8:13 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23908
Inspector	Justin Burch			Date/Time	5/28/2021 12:20 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Dry	Temperature (°F)	82.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Fabric was attached to wire fence		Immediate	5/28/2021
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/28/2021 12:20 PM	Report #	23908
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). The contractor had an Environmental laborer and Straw Foreman walk with the EI on his inspection. One issue was submitted for the punch list consisting of a location where super silt fence fabric was detached from the wire fence. The contractor address this issue immediately. Other inspected ECDs were found to be in compliance at the time of inspection. The EI has not observed that the contractor has worked in the inspection area since the last SWPPP inspection. Since the last SWPPP inspection the area has not received any rainfall events. The ROW ground condition is dry. At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14011+00 to 14018+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/28/2021 12:20 PM	Report #	
Pictures					
<div>☉ 101°E (M) ● 37°2'47"N, 79°53'40"W ±393ft ▲ 1116ft</div> <div></div> <div>13960 28 May 2021, 08:40:22</div>			<div>☉ 206°SW (M) ● 37°3'38"N, 79°52'48"W ±22ft ▲ 1081ft</div> <div></div> <div>14034+00 28 May 2021, 09:32:48</div>		
GPS Location	0		GPS Location	0	
Field Station#	13960+00		Field Station#	14034+00	
Pic 1 Desc.	Perimeter CFS in acceptable condition		Pic 2 Desc.	Super silt fence fabric is detached from the wire fence, contractor addressed it immediately	
<div>☉ 200°S (M) ● 37°3'45"N, 79°52'57"W ±541ft ▲ 1140ft</div> <div></div> <div>14034+00 28 May 2021, 09:35:21</div>			<div>☉ 278°W (M) ● 37°3'42"N, 79°52'45"W ±39ft ▲ 1100ft</div> <div></div> <div>14038+00 28 May 2021, 09:40:59</div>		
GPS Location	0		GPS Location	0	
Field Station#	14034+00		Field Station#	14038+00	
Pic 3 Desc.	Super silt fence after fabric was re-attached to the wire fence		Pic 4 Desc.	Waterbar in acceptable condition	
<div>☉ 288°W (M) ● 37°3'42"N, 79°52'46"W ±42ft ▲ 1099ft</div> <div></div> <div>14038+00 28 May 2021, 09:40:40</div>			<div>☉ 235°SW (M) ● 37°3'56"N, 79°52'34"W ±26ft ▲ 1188ft</div> <div></div> <div>14059+00 28 May 2021, 12:17:40</div>		
GPS Location	0		GPS Location	0	
Field Station#	14038+00		Field Station#	14059+00	
Pic 5 Desc.	Waterbar end treatment in acceptable condition		Pic 6 Desc.	Sump pit in acceptable condition	

A/E	124300139	Date/Time	5/28/2021 12:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	5/28/2021 12:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23910
Inspector	Ben Farmer			Date/Time	5/28/2021 1:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Dry	Temperature (°F)	78.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/28/2021 1:36 PM	Report #	23910
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 78 F) Rain Gauge= 0.0" 15260+00-15370+62 -EI began inspection at Snowberry Rd. -RCEs are in good condition at all road crossings. -MVP-PI-332 is in good condition with controls in place. -P1 is in good condition at all stream and wetland buffers. -Equipment bridge ECDs are in place and functioning. -Waterbars are in good condition throughout this section. -CWDs are functioning as intended. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	5/28/2021 1:36 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15349+02		Field Station#	15346+87	
Pic 1 Desc.	P1 is in good condition at all stream and wetland buffers.		Pic 2 Desc.	Equipment bridge ECDs are in good condition and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15343+34		Field Station#	15338+00	
Pic 3 Desc.	Waterbars are functioning throughout this section.		Pic 4 Desc.	CWDs are in good condition and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15335+00		Field Station#	15325+00	
Pic 5 Desc.	Vegetation continues to fill in throughout this section of ROW.		Pic 6 Desc.	Vegetation continues to fill in throughout this section of ROW.	

AFE	124300139	Date/Time	5/28/2021 1:36 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15323+24	Field Station#	15311+78		
Pic 7 Desc.	RCEs are in good condition at all road crossings.	Pic 8 Desc.	P1 is in good condition around wetland buffers.		
GPS Location	See photo	GPS Location	See photo		
Field Station#	15308+00	Field Station#	15299+00		
Pic 9 Desc.	Vegetation continues to fill in throughout this section of ROW.	Pic 10 Desc.	CWD is in good condition and functioning.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	5/28/2021 1:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23912
Inspector	John White			Date/Time	5/28/2021 3:31 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Dry	Temperature (°F)	91.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Housekeeping		Acceptable			
Sediment Filter Log		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sump Pit		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/28/2021 3:31 PM	Report #	23912
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/28/2021 3:31 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15650+00	Field Station#	15653+00		
Pic 1 Desc.	Observing temporary stabilization, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization		
GPS Location	O	GPS Location	O		
Field Station#	15700+40	Field Station#	15696+00		
Pic 3 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization, sump and end treatment		
GPS Location	O	GPS Location	O		
Field Station#	15693+89	Field Station#	15690+00		
Pic 5 Desc.	Observing road crossing and RCE's	Pic 6 Desc.	Observing temporary stabilization,erosion control blanket and water bar		

A/E	124300139	Date/Time	5/28/2021 3:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	5/28/2021 3:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	23917
Inspector	Charles Head			Date/Time	5/28/2021 4:50 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	5/28/2021 4:50 PM	Report #	23917
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Daily walk through included inspection of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, general compliance issues, and any compliance issues that may arise. No issues observed during daily walk through.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	5/28/2021 4:50 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14472+00	Field Station#	14486+60		
Pic 1 Desc.	Approximately 14472+00. Overview of ROW.	Pic 2 Desc.	Approximately 14486+60. Overview of stream crossing, equipment bridge and ECDs at stream S-G22.		
GPS Location	0	GPS Location	0		
Field Station#	14510+00	Field Station#	14524+76		
Pic 3 Desc.	Approximately 14510+00. Overview of ROW.	Pic 4 Desc.	Approximately 14524+76. Overview of road crossing and RCEs.		
GPS Location	0	GPS Location	0		
Field Station#	14529+00	Field Station#	14531+58		
Pic 5 Desc.	Approximately 14529+00. Overview of ROW.	Pic 6 Desc.	Approximately 14531+58. Overview of stream crossing, equipment bridge and ECDs at stream S-G18.		

AFE	124300139	Date/Time	5/28/2021 4:50 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14546+90	Field Station#	14546+75		
Pic 7 Desc.	Approximately 14546+90. Observed during inspection a third party substance leaking. Substance observed crossing LOD onto ROW, full length of ROW and approximately 700		Pic 8 Desc.	Approximately 14546+75. Observed during inspection a third party substance leaking. Substance observed crossing LOD onto ROW, full length of ROW and approximately 700	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	5/28/2021 4:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	23821
Inspector	John White			Date/Time	5/26/2021 11:05 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dusty	Temperature (°F)	88.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	5/26/2021 11:05 AM	Report #	23821
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	5/26/2021 11:05 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 1 Desc.	Observing temporary stabilization, storm water pond and ECD's	Pic 2 Desc.	Observing temporary stabilization and sediment basin		
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 3 Desc.	Observing emergency overflow at the storm water pond	Pic 4 Desc.	Observing sediment basin		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300113	Date/Time	5/26/2021 11:05 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	5/26/2021 11:05 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		