









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	23982
<b>Inspector</b>	Logan Box			<b>Date/Time</b>	6/1/2021 3:38 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13784+35
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Equipment Bridge	Acceptable				
Erosion Control Blanket	Communication				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Rock Construction Entrance	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 3:38 PM	<b>Report #</b>	23982
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspection the EI noticed erosion control blanket on S-E28 required maintenance due to being weathered and torn. Documented and sent in the item to be added to the punch list for repairs.</p> <p>Other than the item listed there were no other environmental issues observed at the time of inspection.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 3:38 PM	<b>Report #</b>	
<b>Pictures</b>					
	<b>South Elevation</b> 			<b>East Elevation</b> 	
<b>GPS Location</b>	000000	<b>GPS Location</b>	000000		
<b>Field Station#</b>	137746+00	<b>Field Station#</b>	13747+90		
<b>Pic 1 Desc.</b>	Vegetation observation photo showing coverage.	<b>Pic 2 Desc.</b>	Monitored ECDs at road crossing . No issues observed at the time of inspection.		
	<b>North East Elevation</b> 			<b>East Elevation</b> 	
<b>GPS Location</b>	000000	<b>GPS Location</b>	000000		
<b>Field Station#</b>	13686+12	<b>Field Station#</b>	13690+00		
<b>Pic 3 Desc.</b>	Monitored LOD ECDs while checking row conditions. No issues observed at the time of inspection.	<b>Pic 4 Desc.</b>	Row photo taken while checking row conditions throughout. No issues observed at the time of inspection.		
	<b>North West Elevation</b> 			<b>East Elevation</b> 	
<b>GPS Location</b>	000000	<b>GPS Location</b>	000000		
<b>Field Station#</b>	13692+77	<b>Field Station#</b>	13680+00		
<b>Pic 5 Desc.</b>	Erosion control blanket on S-E28 requires maintenance due to being weathered and torn. Documented and added to the punch list.	<b>Pic 6 Desc.</b>	Row photo showing vegetation growth. No issues observed at the time of inspection.		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 3:38 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 3:38 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	23978
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	6/1/2021 9:52 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14928+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	15063+85
<b>County</b>	Franklin/Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance	Addressed	6/1/2021	
Rock Construction Entrance	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Waterbar	Acceptable				
Cleanwater Diversion Berm	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 9:52 AM	<b>Report #</b>	23978
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>-Available for work</li> <li>-Received instruction from Lead EI for daily tasks</li> <li>-Sunny with dry ground conditions during inspection</li> <li>-Performed SWPPP inspection on portion of MVP Spread I section</li> <li>-Covered territory between station# 14928+52 — 15063+85 (Ramsey Memorial Rd to Armstrong Rd)</li> <li>-Walked ROW with environmental foreman making note of condition of ROW and environmental controls</li> <li>-Perimeter controls and ECD's were inspected; 1 issue identified</li> <li>-Inspection observed condition of RCEs and culverts in section; no issues identified</li> <li>-Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified</li> <li>-Observed contractor performing environmental maintenance and completing punch list items submitted</li> <li>-Continue to monitor ROW for signs of erosion</li> <li>-1 item added to punch list</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300139	Date/Time	6/1/2021 9:52 AM	Report #	
Pictures					
					
36°57'55" N 79°35'57" W 37°NE COURSE 36' GPS 06.01.2021 12:45:09 Sorry no results found Accur +/-86.4 Ft ALT 914 Ft			36°58'2" N 79°38'15" W 14°N COURSE 326' GPS 06.01.2021 11:18:15 2082 Ramsey Memorial Rd, Penhook, VA 24137, United States Accur +/-19.6 Ft ALT 863 Ft		
GPS Location	1		GPS Location	2	
Field Station#	15044+50		Field Station#	14929+00	
Pic 1 Desc.	Routine maintenance. Replace damaged panel of P1 silt fence from third party damage.		Pic 2 Desc.	Temporary vegetation growing in extra workspace. RCE in good condition.	
					
36°57'58" N 79°37'25" W 49°NE COURSE 82' GPS 06.01.2021 10:42:48 Penhook, VA 24137, United States Accur +/-129.7 Ft ALT 949 Ft			36°57'51" N 79°36'57" W 3°N COURSE 340' GPS 06.01.2021 12:14:43 Penhook, VA 24137, United States Accur +/-26.3 Ft ALT 940 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14967+00		Field Station#	14995+00	
Pic 3 Desc.	Natural drainage area performing intended function. Perimeter controls in place and functional.		Pic 4 Desc.	Permanent vegetation growing along ROW in final cleanup area.	
					
36°57'52" N 79°36'55" W 113°E COURSE 103' GPS 06.01.2021 12:28:44 Penhook, VA 24137, United States Accur +/-339.7 Ft ALT 914 Ft			36°57'55" N 79°36'5" W 134°SE COURSE 103' GPS 06.01.2021 12:41:03 Penhook, VA 24137, United States Accur +/-167.7 Ft ALT 914 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15009+00		Field Station#	15036+00	
Pic 5 Desc.	Temporary vegetation growing along ROW. Area is stabilized.		Pic 6 Desc.	Temporary vegetation growing along ROW. Area is stabilized.	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 9:52 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 9:52 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

















# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24001
<b>Inspector</b>	Ben Farmer			<b>Date/Time</b>	6/1/2021 7:36 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15370+62
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	15480+67
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No






<b>AFE</b>	124300139	<b>Date/Time</b>	6/1/2021 7:36 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15480+67		<b>Field Station#</b>	15475+00	
<b>Pic 1 Desc.</b>	RCEs are in good condition at all road crossings.		<b>Pic 2 Desc.</b>	3rd party rock outlet remains in good condition along this drainage.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15465+00		<b>Field Station#</b>	15460+81	
<b>Pic 3 Desc.</b>	3rd party rock outlet appears to be in good condition with no evidence of sedimentation onto MVP ROW.		<b>Pic 4 Desc.</b>	3rd party rock outlet appears to be in good condition with no evidence of sedimentation onto MVP ROW.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15460+81		<b>Field Station#</b>	15457+00	
<b>Pic 5 Desc.</b>	CWD is in good condition.		<b>Pic 6 Desc.</b>	Drainage ECDs are in good condition with no evidence of sedimentation onto MVP ROW.	



<b>AFE</b>	124300139	<b>Date/Time</b>	6/1/2021 7:36 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15453+00		<b>Field Station#</b>	15442+00	
<b>Pic 7 Desc.</b>	CWD is in good condition with no evidence of sedimentation from 3rd party disturbance.		<b>Pic 8 Desc.</b>	Vegetation continues to fill in ROW.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15427+31		<b>Field Station#</b>	15422+00	
<b>Pic 9 Desc.</b>	Equipment bridge ECDs are in good condition and functioning.		<b>Pic 10 Desc.</b>	Vegetation continues to fill in ROW.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15413+72		<b>Field Station#</b>	15400+00	
<b>Pic 11 Desc.</b>	P1 is in good condition at all stream and wetland crossings.		<b>Pic 12 Desc.</b>	Vegetation continues to fill in ROW.	



<b>AFE</b>	124300139	<b>Date/Time</b>	6/1/2021 7:36 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15385+00		<b>Field Station#</b>	15383+00	
<b>Pic 13 Desc.</b>	Sensitive resource buffer is in good condition.		<b>Pic 14 Desc.</b>	Waterbars are functioning as intended throughout this section.	
				Insert image here	
<b>GPS Location</b>	See photo		<b>GPS Location</b>		
<b>Field Station#</b>	15375+00		<b>Field Station#</b>		
<b>Pic 15 Desc.</b>	Drainage ECDs are in good condition and functioning.		<b>Pic 16 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 17 Desc.</b>			<b>Pic 18 Desc.</b>		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I	
<b>Contractor</b>	Precision			<b>Report #</b>	24003	
<b>Inspector</b>	Glenn Mike Renfro			<b>Date/Time</b>	6/1/2021 5:14 PM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	0000+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	0000+00	
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	71.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.80	
				<b>Rain Accumulation Time (days)</b>	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable					
Housekeeping	Acceptable					
Rock Construction Entrance	Acceptable					
Secondary Containment	Acceptable					
Other - Explain in Comments	Acceptable	Catch basin inlet protection				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 5:14 PM	<b>Report #</b>	24003
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>- Performed SWPPP inspection of Spread I main laydown yards MVP- LY-045 and MVP-LY-046 in Rocky Mount, Va.</li> <li>- The locations have received.80" of rainfall since the last inspection and site conditions were dry.</li> <li>- All perimeter ECD's were inspected and no issues observed found.</li> <li>- The inlet protection for the catch basins at LY-046 were in acceptable condition.</li> <li>- All secondary containment structures were found to be in good condition.</li> <li>- All equipment at both locations were inspected and no leaks were observed during the inspection.</li> <li>- The RCE at LY-045 was in good condition.</li> <li>- The General Construction permits and contact information are posted at the main entrance of LY-046 as required.</li> <li>- There were no issues found to report during today's inspection.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300139	Date/Time	6/1/2021 5:14 PM	Report #	
Pictures					
					
GPS Location	00000000000		GPS Location	00000000000	
Field Station#	0000+00		Field Station#	0000+00	
Pic 1 Desc.	Perimeter ECD's on north end of LY046 in good condition.		Pic 2 Desc.	Secondary containment structure for fuel cell in good condition.	
					
GPS Location	00000000000		GPS Location	00000000000	
Field Station#	0000+00		Field Station#	0000+00	
Pic 3 Desc.	Secondary containment structure for and perimeter ECD's on south end of LY-046 in good condition.		Pic 4 Desc.	Secondary containment structure for on north end of LY-045 in good condition.	
					
GPS Location	00000000000		GPS Location	00000000000	
Field Station#	0000+00		Field Station#	0000+00	
Pic 5 Desc.	Perimeter ECD's on south end of LY-045 in good condition.		Pic 6 Desc.	Secondary containment structure for for station at LY-045 in good condition.	



<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 5:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 12 Desc.</b>	







<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 5:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	23989
<b>Inspector</b>	Justin Burch			<b>Date/Time</b>	6/1/2021 3:02 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14062+17
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	14171+36
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Plunge Pool	Acceptable				
Waterbar End Treatment	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Equipment Bridge	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 3:02 PM	<b>Report #</b>	23989
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>• The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). No issues were submitted for the punch list because inspected ECDs were in compliance at the time of inspection.</li> <li>• The EI observed that the contractor installed temporary stabilization at a location (14148+61) where anode work was done since the last SWPPP inspection.</li> <li>• Since the last SWPPP inspection the area has received one rainfall event totaling 0.80" at Bonbrook Mill Road #1.</li> <li>• The ROW ground condition is damp</li> <li>• At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00.</li> <li>• At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	6/1/2021 3:02 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14071+00	<b>Field Station#</b>	14067+00		
<b>Pic 1 Desc.</b>	Clean water diversion plunge pool in acceptable condition	<b>Pic 2 Desc.</b>	Waterbar end treatment in acceptable condition		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14096+00	<b>Field Station#</b>	14108+00		
<b>Pic 3 Desc.</b>	Temporary vegetative stabilization in acceptable condition	<b>Pic 4 Desc.</b>	Perimeter CFS in acceptable condition		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14124+00	<b>Field Station#</b>	14141+62		
<b>Pic 5 Desc.</b>	P1 silt fence in acceptable condition	<b>Pic 6 Desc.</b>	Equipment bridge in acceptable condition		



<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 3:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 3:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I		<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I	
<b>Contractor</b>	Precision				<b>Report #</b>	23977	
<b>Inspector</b>	Charles Head				<b>Date/Time</b>	6/1/2021 9:44 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP		<b>Station Begin</b>	14546+75	
<b>State</b>	VA	<b>Inspection Area</b>	Full		<b>Station End</b>	14649+67	
<b>County</b>	Franklin	<b>Ground</b>	Dry		<b>Temperature (°F)</b>	74.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny		<b>Rain Gauge (in)</b>	0.00	
					<b>Rain Accumulation Time (days)</b>	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Rock Construction Entrance		Acceptable					
Sensitive Resource Buffer		Acceptable					
Sensitive Resource Signage		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
<b>5. Site Conditions</b>							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 9:44 AM	<b>Report #</b>	23977
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 9:44 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14599+00	<b>Field Station#</b>	14611+27		
<b>Pic 1 Desc.</b>	Approximately 14599+00. Overview of road crossing and RCEs.		<b>Pic 2 Desc.</b>	Approximately 14611+27. Overview of stream crossing, equipment bridge and ECDs at stream S-E14.	
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14618+00	<b>Field Station#</b>	14582+85		
<b>Pic 3 Desc.</b>	Approximately 14618+00. Overview of ROW.		<b>Pic 4 Desc.</b>	Approximately 14582+85. Overview of stream crossing, equipment bridge and ECDs at stream S-E17.	
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14568+10	<b>Field Station#</b>	14550+00		
<b>Pic 5 Desc.</b>	Approximately 14568+10. Overview of stream crossing, equipment bridge and ECDs at stream S-E18.		<b>Pic 6 Desc.</b>	Approximately 14550+00. Overview of ROW.	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 9:44 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 9:44 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	23979
<b>Inspector</b>	John White			<b>Date/Time</b>	6/1/2021 10:05 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15772+27
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15947+64
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Contractor repaired upon discovery			6/1/2021
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 10:05 AM	<b>Report #</b>	23979
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There was one issue identified and repaired upon discovery by the Contractor. Other than that there were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300139	<b>Date/Time</b>	6/1/2021 10:05 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15934+00	<b>Field Station#</b>	15923+49		
<b>Pic 1 Desc.</b>	Observing temporary stabilization,CWD outlet and ECD's	<b>Pic 2 Desc.</b>	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15786+00	<b>Field Station#</b>	15784+00		
<b>Pic 3 Desc.</b>	Observing temporary stabilization,CWD outlet and ECD's	<b>Pic 4 Desc.</b>	Observing p1 that required maintenance		
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15784+00	<b>Field Station#</b>	15794+77		
<b>Pic 5 Desc.</b>	Observing p1 that received maintenance	<b>Pic 6 Desc.</b>	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 10:05 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 10:05 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I	
<b>Contractor</b>	Precision			<b>Report #</b>	24006	
<b>Inspector</b>	Frank Craycroft			<b>Date/Time</b>	6/1/2021 8:46 PM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	0+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	0+00	
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00	
				<b>Rain Accumulation Time (days)</b>	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 8:46 PM	<b>Report #</b>	24006
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted SWPPP inspection of contractor's yards LY-032, -033, -048, and ANC-006. All portable equipment and hazardous material canisters were maintained within secondary containment. All perimeter ECDs were functional and in good condition. Housekeeping was well maintained with loose trash kept in bulk dumpsters. Dumpsters still have adequate capacity. Temporary seeding on northern side of LY-048 has begun sprouting through gravel. No issues were observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 8:46 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	0+00	<b>Field Station#</b>	0+00		
<b>Pic 1 Desc.</b>	LY-032 Secondary Containment	<b>Pic 2 Desc.</b>	LY-032 Housekeeping & Secondary containment		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	0+00	<b>Field Station#</b>	0+00		
<b>Pic 3 Desc.</b>	LY-033 Inlet Protection	<b>Pic 4 Desc.</b>	LY-033 RCE		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	0+00	<b>Field Station#</b>	0+00		
<b>Pic 5 Desc.</b>	ANC-006 Inlet protection	<b>Pic 6 Desc.</b>	ANC-006 Secondary containment		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 8:46 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	0+00	<b>Field Station#</b>	0+00		
<b>Pic 7 Desc.</b>	LY-48 Housekeeping & temporary seeding		<b>Pic 8 Desc.</b>	LY-48 Southwest perimeter CFS	
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/1/2021 8:46 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24040
<b>Inspector</b>	John White			<b>Date/Time</b>	6/2/2021 10:50 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15947+64
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	16027+46
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sump Pit	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:50 AM	<b>Report #</b>	24040
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	6/2/2021 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	16016+36	<b>Field Station#</b>	1608+00		
<b>Pic 1 Desc.</b>	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		<b>Pic 2 Desc.</b>	Observing temporary stabilization, sump and end treatment	
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	16004+00	<b>Field Station#</b>	16010+00		
<b>Pic 3 Desc.</b>	Observing temporary stabilization, signage, buffer and ECD's		<b>Pic 4 Desc.</b>	Observing temporary stabilization,CWD outlet and ECD's	
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15999+80	<b>Field Station#</b>	15970+00		
<b>Pic 5 Desc.</b>	Observing temporary stabilization, signage, buffer and ECD's		<b>Pic 6 Desc.</b>	Observing temporary stabilization,CWD outlet and ECD's	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-602 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-602 Pipeline Spread I	
<b>Contractor</b>	Precision			<b>Report #</b>	24039	
<b>Inspector</b>	John White			<b>Date/Time</b>	6/2/2021 10:45 AM	
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	00+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	19+25	
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	73.00	
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.50	
				<b>Rain Accumulation Time (days)</b>	7.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
<b>5. Site Conditions</b>						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:45 AM	<b>Report #</b>	24039
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:45 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	19+00	<b>Field Station#</b>	15+00		
<b>Pic 1 Desc.</b>	Observing temporary stabilization and ECD's		<b>Pic 2 Desc.</b>	Observing temporary stabilization	
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	12+65	<b>Field Station#</b>	6+00		
<b>Pic 3 Desc.</b>	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		<b>Pic 4 Desc.</b>	Observing temporary stabilization and access road	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 5 Desc.</b>			<b>Pic 6 Desc.</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:45 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:45 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24028
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	6/2/2021 8:41 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15063+85
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	15142+66
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	76.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>		<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Rock-lined Channel	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Plunge Pool	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>AFE</b>	124300139	<b>Date/Time</b>	6/2/2021 8:41 AM	<b>Report #</b>	24028
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -No items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/2/2021 8:41 AM	Report #	
Pictures					
					
36°57'44" N 79°35'24" W 332°NW COURSE 217' GPS Sandy Level, VA 24161, United States			36°57'39" N 79°35'11" W 4°N COURSE 281' GPS Sandy Level, VA 24161, United States		
06.02.2021 09:40:11 Accur +/-69.4 Ft ALT 871 Ft			06.02.2021 09:31:32 Accur +/-21.6 Ft ALT 868 Ft		
GPS Location	1		GPS Location	2	
Field Station#	15073+25		Field Station#	15085+93	
Pic 1 Desc.	Rock lined channel and perimeter SSF in place and functional		Pic 2 Desc.	Plunge pool performing intended function	
					
36°57'41" N 79°35'14" W 163°S COURSE -1' GPS Sandy Level, VA 24161, United States			36°57'7" N 79°34'49" W 259°W COURSE 196' GPS Sandy Level, VA 24161, United States		
06.02.2021 09:48:35 Accur +/-258.1 Ft ALT 877 Ft			06.02.2021 09:23:52 Accur +/-656.2 Ft ALT 884 Ft		
GPS Location	3		GPS Location	4	
Field Station#	15092+95		Field Station#	15102+84	
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing		Pic 4 Desc.	Perimeter CFS triple stack in place and functional	
					
36°57'23" N 79°34'59" W 177°S COURSE -1' GPS Sandy Level, VA 24161, United States			36°57'7" N 79°34'49" W 300°NW COURSE 11' GPS Sandy Level, VA 24161, United States		
06.02.2021 09:57:33 Accur +/-100.5 Ft ALT 877 Ft			06.02.2021 08:55:04 Accur +/-95.7 Ft ALT 887 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15110+00		Field Station#	15127+00	
Pic 5 Desc.	ROW stabilized and vegetated in temporary area. Minor wear of travel lane observed.		Pic 6 Desc.	Area seeded and stabilized after contractor performed environmental maintenance	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 8:41 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 8:41 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		




# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24034
<b>Inspector</b>	Logan Box			<b>Date/Time</b>	6/2/2021 3:48 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13748+30
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	13853+45
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	81.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe	Acceptable				
Plunge Pool	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Rock Construction Entrance	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Equipment Bridge	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>AFE</b>	124300139	<b>Date/Time</b>	6/2/2021 3:48 PM	<b>Report #</b>	24034
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles , inspected clean water diversions and plunge pools .</p> <p>Throughout today's inspections the EI noticed where a land owner has mowed inside a stream area close to stream crossing S-MM42 . EI noted that is was not project related and took photos , will continue to monitor the area.</p> <p>During inspection near MVP-FR-300 the EI noticed where a land owner cut hay on part of the work space inside the LOD. EI documented photos and noted that there was no project related activities involved.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	6/2/2021 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
	<b>North West Elevation</b> <small>126°SE (T) • 37.071809, -79.937326 ±5 m ▲ 304 m</small> 			<b>South Elevation</b> <small>358°N (T) • 37.070283, -79.93107 ±8 m ▲ 289 m</small> 	
<b>GPS Location</b>	00000	<b>GPS Location</b>	00000		
<b>Field Station#</b>	13767+00	<b>Field Station#</b>	13790+47		
<b>Pic 1 Desc.</b>	Inspected clean water diversion and plunge pool. All functioning properly at the time of inspection.		<b>Pic 2 Desc.</b>	Stream observation photo facing downstream during routine inspection today. No issues observed at the time of inspection.	
	<b>North Elevation</b> <small>186°S (T) • 37.070283, -79.93107 ±8 m ▲ 289 m</small> 			<b>South West Elevation</b> <small>65°NE (T) • 37.070789, -79.937006 ±4 m ▲ 303 m</small> 	
<b>GPS Location</b>	00000	<b>GPS Location</b>	0000		
<b>Field Station#</b>	13790+47	<b>Field Station#</b>	13770+69		
<b>Pic 3 Desc.</b>	Stream observation photo facing upstream during routine inspection today. No issues were observed at the time of inspection.		<b>Pic 4 Desc.</b>	Land owner mowed inside stream area close to row crossing. Documented as non project related activities.	
	<b>North Elevation</b> <small>166°SE (T) • 37.088935, -79.960955 ±3 m ▲ 322 m</small> 			<b>South East Elevation</b> <small>338°NW (T) • 37.070514, -79.936502 ±4 m ▲ 313 m</small> 	
<b>GPS Location</b>	000000	<b>GPS Location</b>	00000		
<b>Field Station#</b>	13759+70	<b>Field Station#</b>	13772+69		
<b>Pic 5 Desc.</b>	CFS outlet observed and functioning at the time of inspection.		<b>Pic 6 Desc.</b>	Monitored rock lined channel and ECDs as well as sump pit while checking row conditions. No issues observed at the time of inspection.	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
		Insert image here		Insert image here	
<b>GPS Location</b>	00000	<b>GPS Location</b>			
<b>Field Station#</b>	13784+35	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Land owner cut hay from part of work space at MVP-FR-300 . Documented as non project related activities.	<b>Pic 8 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24049
<b>Inspector</b>	Justin Burch			<b>Date/Time</b>	6/2/2021 1:05 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14171+36
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	14311+57
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	78.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	1.00
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Silt Fence (Reinforce Filter Fence)	Communication				
Other - Explain in Comments	Communication				
Erosion Control Blanket	Communication				
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 1:05 PM	<b>Report #</b>	24049
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). Five issues were submitted for the punch list consisting of two locations where livestock damaged P1 silt fence, two locations where livestock damaged temporary electric fencing, and one location where live stock damaged erosion control blanket. Other inspected ECDs were in compliance at the time of inspection.</li> <li>The EI observed that the contractor has worked in the inspection area and addressed punch list items submitted at the last SWPPP inspection.</li> <li>Since the last SWPPP inspection the area has received one rainfall event totaling 0.80" at Bonbrook Mill Road #1 and 1.00" at Farm View Road.</li> <li>The ROW ground condition is damp</li> <li>At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14258+00 to 14277+00.</li> <li>At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	6/2/2021 1:05 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0		<b>GPS Location</b>	0	
<b>Field Station#</b>	14295+00		<b>Field Station#</b>	14278+50	
<b>Pic 1 Desc.</b>	P1 silt fence damaged by livestock		<b>Pic 2 Desc.</b>	P1 silt fence damaged by livestock	
					
<b>GPS Location</b>	0		<b>GPS Location</b>	0	
<b>Field Station#</b>	14278+75		<b>Field Station#</b>	14278+00	
<b>Pic 3 Desc.</b>	Temporary electric fence damaged by livestock from 14277+00 to 14280+00		<b>Pic 4 Desc.</b>	Erosion control blanket damaged by livestock from 14277+00 to 14278+50	
					
<b>GPS Location</b>	0		<b>GPS Location</b>	0	
<b>Field Station#</b>	14220+00		<b>Field Station#</b>	14177+00	
<b>Pic 5 Desc.</b>	Temporary vegetative stabilization in acceptable condition		<b>Pic 6 Desc.</b>	Temporary electric fence damaged by livestock	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 1:05 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 1:05 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		







## Visual Site Inspection Report

<b>Project Name</b>	H-603 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-603 Pipeline Spread I
<b>Contractor</b>	Precision	<b>Report #</b>	24037		
<b>Inspector</b>	John White	<b>Date/Time</b>	6/2/2021 10:24 AM		
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	00+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	24+53
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.70
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Housekeeping		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Sump Pit		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar End Treatment		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:24 AM	<b>Report #</b>	24037
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:24 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	10+00	<b>Field Station#</b>	12+00		
<b>Pic 1 Desc.</b>	Observing temporary stabilization, sump and end treatment.		<b>Pic 2 Desc.</b>	Observing temporary stabilization	
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	18+83	<b>Field Station#</b>	15+73		
<b>Pic 3 Desc.</b>	Observing temporary stabilization, signage, buffer and ECD's.		<b>Pic 4 Desc.</b>	Observing temporary stabilization, signage, and buffer	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 5 Desc.</b>			<b>Pic 6 Desc.</b>		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:24 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 10:24 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24052
<b>Inspector</b>	Charles Head			<b>Date/Time</b>	6/2/2021 3:08 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14649+67
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	14694+77
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	79.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 3:08 PM	<b>Report #</b>	24052
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/2/2021 3:08 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14689+36	Field Station#	14694+50		
Pic 1 Desc.	Approximately 14689+36. Overview of stream crossing, equipment bridge and ECDs at stream S-H34.		Pic 2 Desc.	Approximately 14694+50. Overview of road crossing and RCE.	
GPS Location	0	GPS Location	0		
Field Station#	14680+40	Field Station#	14673+10		
Pic 3 Desc.	Approximately 14680+40. Overview of stream crossing, equipment bridge and ECDs at stream S-H36.		Pic 4 Desc.	Approximately 14673+10. Overview of stream crossing, equipment bridge and ECDs at stream S-H37.	
GPS Location	0	GPS Location	0		
Field Station#	14656+90	Field Station#	14652+00		
Pic 5 Desc.	Approximately 14656+90. Overview of stream crossing, equipment bridge and ECDs at stream S-H38.		Pic 6 Desc.	Approximately 14652+00. Overview of ROW.	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 3:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 3:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24115
<b>Inspector</b>	Ben Farmer			<b>Date/Time</b>	6/3/2021 6:58 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15142+60
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	15260+00
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	74.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00







- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)             | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)  |     |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			







<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 6:58 PM	<b>Report #</b>	24115
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 74F) Rain Gauge= 0.0" 15142+66-15260+00  -EI began inspection at Rockcreek Rd. -RCEs are in good condition at all road crossings. -Rock inlet/outlet is in good condition at 15165+57/15166+00. -P1 is in good condition at stream crossing. -Equipment bridge ECDs are in place and functioning. -Waterbars are in good condition throughout this section. -Slope drain remains in good condition and functioning at 15170+00. -Drainage ECDs are in good condition at 15195+00 -Sensitive resource buffer remains in good condition at 15230+00. -Vegetation continuing to fill in throughout this section.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 6:58 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15142+66		<b>Field Station#</b>	15165+57	
<b>Pic 1 Desc.</b>	RCE is in good condition at Rockcreek Rd.		<b>Pic 2 Desc.</b>	Rock inlet is in good condition along this drainage.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15166+00		<b>Field Station#</b>	15167+95	
<b>Pic 3 Desc.</b>	Rock outlet remains in good condition.		<b>Pic 4 Desc.</b>	P1 is in good condition at this stream buffer.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15167+95		<b>Field Station#</b>	15170+00	
<b>Pic 5 Desc.</b>	Equipment bridge ECDs are in place and functioning.		<b>Pic 6 Desc.</b>	Waterbars are functioning as intended throughout this section.	



<b>AFE</b>	124300139	<b>Date/Time</b>	6/3/2021 6:58 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15170+00		<b>Field Station#</b>	15195+00	
<b>Pic 7 Desc.</b>	Slope drain is functioning as intended.		<b>Pic 8 Desc.</b>	Drainage ECDs are in good condition at this location.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15209+00		<b>Field Station#</b>	15230+00	
<b>Pic 9 Desc.</b>	Vegetation continues to fill in throughout this section of ROW		<b>Pic 10 Desc.</b>	Sensitive resource buffer is in good condition around ground nest at this location.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15235+00		<b>Field Station#</b>	15260+00	
<b>Pic 11 Desc.</b>	Vegetation continues to fill in throughout this section of ROW		<b>Pic 12 Desc.</b>	Vegetation continues to fill in throughout this section of ROW	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 6:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24099
<b>Inspector</b>	Justin Burch			<b>Date/Time</b>	6/3/2021 12:58 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13853+45
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	13958+31
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	79.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Communication	Third party damaged			
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 12:58 PM	<b>Report #</b>	24099
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). An Environmental Straw Foreman from Precision walked with the EI on his inspection. Three issues were submitted for the punch list including two locations with CFS damaged by a third party and two locations where CFS had holes and was degraded. Other inspected ECDs were in compliance at the time of inspection. The contractor had an Environmental crew begin addressing the punch list items immediately.</li> <li>The EI observed that the contractor has worked in the inspection area since the last SWPPP inspection and addressed punch list items from a daily inspection.</li> <li>Since the last SWPPP inspection the area has received one rainfall event totaling 0.80" at Bonbrook Mill Road #1.</li> <li>The ROW ground condition is damp</li> <li>At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion.</li> <li>At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13940+00.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/3/2021 12:58 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	13936+00		Field Station#	13931+00	
Pic 1 Desc.	CFS has holes and is degraded from 13935+00 to 13936+50		Pic 2 Desc.	CFS damaged by third party from 13930+00 to 13935+00 (4 locations)	
					
GPS Location	0		GPS Location	0	
Field Station#	13939+50		Field Station#	13894+00	
Pic 3 Desc.	CFS with multiple holes on access road MVP-FR-305		Pic 4 Desc.	CFS damaged by farm equipment	
					
GPS Location	0		GPS Location	0	
Field Station#	13926+00		Field Station#	13955+00	
Pic 5 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 6 Desc.	P1 silt fence in acceptable condition	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 12:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 12:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24069
<b>Inspector</b>	Ben Farmer			<b>Date/Time</b>	6/2/2021 9:03 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15480+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	15584+23
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>AFE</b>	124300139	<b>Date/Time</b>	6/2/2021 9:03 PM	<b>Report #</b>	24069
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 70 F) Rain Gauge= 0.0" 15480+67-15584+23  -EI began inspection at Toshes Rd. -RCEs are in good condition at all road crossings. -3rd party ECDs appear to be in good condition with no evidence of sedimentation onto MVP ROW at 15510+00. EI will continue to monitor this area. -CWDs are in good condition throughout this section. -Equipment bridge ECDs are in place and in good condition. -Buffer P1 is in good condition at all stream and wetland crossings. -Waterbars are in good condition throughout this section. -CFS is in good condition at stream buffers. -Slope drain remains in good condition and functioning at 15575+00. -Vegetation continuing to fill in throughout this section.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	6/2/2021 9:03 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15495+00		<b>Field Station#</b>	15496+70	
<b>Pic 1 Desc.</b>	Vegetation continues to fill in throughout this section of ROW.		<b>Pic 2 Desc.</b>	RCEs are in good condition at all road crossings.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15503+00		<b>Field Station#</b>	15507+00	
<b>Pic 3 Desc.</b>	Vegetation continues to fill in throughout this section of ROW.		<b>Pic 4 Desc.</b>	P1 is in good condition at all stream and wetland buffers.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15510+00		<b>Field Station#</b>	15515+00	
<b>Pic 5 Desc.</b>	3rd party ECDs appear to be in good condition with no evidence of sedimentation onto MVP ROW.		<b>Pic 6 Desc.</b>	CWDs are in good condition and functioning.	



<b>AFE</b>	124300139	<b>Date/Time</b>	6/2/2021 9:03 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	15540+80	<b>Field Station#</b>	15546+31		
<b>Pic 7 Desc.</b>	Equipment bridge ECDs are in good condition.	<b>Pic 8 Desc.</b>	Waterbars are functioning as intended.		
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	15563+57	<b>Field Station#</b>	15575+27		
<b>Pic 9 Desc.</b>	CFS is in good condition at stream buffers.	<b>Pic 10 Desc.</b>	Slope drain is in good condition and functioning at this location.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300139	<b>Date/Time</b>	6/2/2021 9:03 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision	<b>Report #</b>	24097		
<b>Inspector</b>	Charles Head	<b>Date/Time</b>	6/3/2021 10:10 AM		
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14311+57
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	14454+22
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b>	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Communication	Repair damaged section		
Silt Fence (Reinforce Filter Fence)		Acceptable			
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 10:10 AM	<b>Report #</b>	24097
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on the daily punch list.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 10:10 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14319+00	<b>Field Station#</b>	14391+50		
<b>Pic 1 Desc.</b>	Approximately 14319+00. Overview of ROW.	<b>Pic 2 Desc.</b>	Approximately 14391+50. Overview of stream crossing, equipment bridge and ECDs at stream S-A41.		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14415+00	<b>Field Station#</b>	14434+01		
<b>Pic 3 Desc.</b>	Approximately 14415+00. Overview of ROW.	<b>Pic 4 Desc.</b>	Approximately 14434+01. Overview of stream crossing, equipment bridge and ECDs at stream S-GH40.		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14454+00	<b>Field Station#</b>	14352+75		
<b>Pic 5 Desc.</b>	Approximately 14454+00. Overview of road crossing and RCE.	<b>Pic 6 Desc.</b>	Approximately 14352+75. P-1 requires maintenance.		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 10:10 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 10:10 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24077
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	6/3/2021 11:41 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14694+77
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14802+19
<b>County</b>	Franklin	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Rock Construction Entrance	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Temporary Diversion Berm	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 11:41 AM	<b>Report #</b>	24077
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 - 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Observed field survey group checking road crossings during inspection -Continue to monitor ROW for signs of erosion -No items added to punch list					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 11:41 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<small>36°59'16" N 79°42'37" W 110°E COURSE 187' GPS 1559-2499 Jacks Creek Rd, Union Hall, VA 24176, United States 06.03.2021 12:13:17 Accur +/-38.9 Ft ALT 949 Ft</small>			<small>36°58'59" N 79°41'22" W 147°SE COURSE 292' GPS 06.03.2021 12:22:46 Accur +/-18.7 Ft ALT 958 Ft</small>		
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	14694+77	<b>Field Station#</b>	14761+00		
<b>Pic 1 Desc.</b>	RCE at Jacks Creek Rd in good condition.		<b>Pic 2 Desc.</b>	Sump pit and end treatment performing intended functions. Safety fence installed around sump pit.	
					
<small>36°59'3" N 79°41'26" W 268°W COURSE 168' GPS Sorry no results found 06.03.2021 12:31:23 Accur +/-46.0 Ft ALT 947 Ft</small>			<small>36°58'57" N 79°41'17" W 86°E COURSE 144' GPS Sorry no results found 06.03.2021 12:24:41 Accur +/-15.3 Ft ALT 946 Ft</small>		
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	14755+00	<b>Field Station#</b>	14765+00		
<b>Pic 3 Desc.</b>	ROW stabilized in temporary area. Water bars performing intended functions. Limited vegetation observed.		<b>Pic 4 Desc.</b>	Sumps, end treatments, and perimeter SSF performing intended functions. Limited vegetation observed.	
					
<small>36°58'37" N 79°40'44" W 224°SW COURSE 244' GPS 700-1080 Indian Cave Rd, Union Hall, VA 24176, United States 06.03.2021 12:53:59 Accur +/-44.7 Ft ALT 939 Ft</small>			<small>36°58'38" N 79°40'45" W 98°E COURSE 24' GPS 700-1080 Indian Cave Rd, Union Hall, VA 24176, United States 06.03.2021 12:54:45 Accur +/-15.5 Ft ALT 937 Ft</small>		
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	14801+00	<b>Field Station#</b>	14798+00		
<b>Pic 5 Desc.</b>	Temporary diversion berm stabilized and vegetated.		<b>Pic 6 Desc.</b>	Sump pit and end treatment in good condition and functional.	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 11:41 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 11:41 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		











# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24062
<b>Inspector</b>	John White			<b>Date/Time</b>	6/3/2021 9:28 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15584+23
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15647+03
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	74.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.90
				<b>Rain Accumulation Time (days)</b>	7.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 9:28 PM	<b>Report #</b>	24062
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There was one issue identified and added to the punch list. Other than that there were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	6/3/2021 9:28 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15608+00	<b>Field Station#</b>	15636+45		
<b>Pic 1 Desc.</b>	Observing safety fence that requires maintenance.	<b>Pic 2 Desc.</b>	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15630+00	<b>Field Station#</b>	15590+00		
<b>Pic 3 Desc.</b>	Observing temporary stabilization, erosion control blanket and cfs checks	<b>Pic 4 Desc.</b>	Observing temporary stabilization and water bars		
					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15617+00	<b>Field Station#</b>	15595+00		
<b>Pic 5 Desc.</b>	Observing temporary stabilization, sump and end treatment	<b>Pic 6 Desc.</b>	Observing temporary stabilization, CWD outlet, signage, buffer, equipment crossing and ECD's		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 9:28 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/3/2021 9:28 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24144
<b>Inspector</b>	John White			<b>Date/Time</b>	6/4/2021 10:44 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15647+03
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	15772+27
<b>County</b>	Pittsylvania	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	2.10
				<b>Rain Accumulation Time (days)</b>	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Compost Filter Sock	Communication	Contractor repaired upon discovery		6/4/2021	
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 10:44 AM	<b>Report #</b>	24144
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Checked rain gauges, Anderson Mill #2=1.4", Mill Creek =1.5", Transco =1.2". Performed SWPPP Inspection on this section. There were issues identified and repaired upon discovery by the Contractor. Other than that there were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 10:44 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15763+80	<b>Field Station#</b>	15768+00		
<b>Pic 1 Desc.</b>	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	<b>Pic 2 Desc.</b>	Observing temporary stabilization		
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15772+00	<b>Field Station#</b>	15772+00		
<b>Pic 3 Desc.</b>	Observing CFS that required maintenance.	<b>Pic 4 Desc.</b>	Observing CFS that received maintenance		
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15745+50	<b>Field Station#</b>	15745+50		
<b>Pic 5 Desc.</b>	Observing safety fence that required maintenance	<b>Pic 6 Desc.</b>	Observing safety fence that received maintenance		

<b>AFE</b>	124300139	<b>Date/Time</b>	6/4/2021 10:44 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>SE 120 150 180 210 SW 169°S (T) 36°52'19"N, 79°24'23"W ±134ft ▲ 831ft 04 Jun 2021 09:38:37</p>		 <p>N 0 30 60 90 120 57°NE (T) 36°52'20"N, 79°24'34"W ±3195ft ▲ 842ft 04 Jun 2021 09:33:48</p>			
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	15750+00	<b>Field Station#</b>	15755+00		
<b>Pic 7 Desc.</b>	Observing temporary stabilization and CFS checks	<b>Pic 8 Desc.</b>	Observing sump and end treatment		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 10:44 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24101
<b>Inspector</b>	Ben Davenport			<b>Date/Time</b>	6/4/2021 11:14 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14802+19
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	14928+15
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	80.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Equipment Bridge	Acceptable				
Sediment Filter Log	Acceptable				
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No





AFE	124300139	Date/Time	6/4/2021 11:14 AM	Report #	
Pictures					
					
36°58'34" N 79°40'38" W 332°NW COURSE 348° GPS 179-367 Listening Hill Rd, Penhook, VA 24137, United States 06.04.2021 09:04:34 Accur +/-49.8 Ft ALT 983 Ft			36°58'20" N 79°39'56" W 160°S COURSE 293° GPS 179-367 Listening Hill Rd, Penhook, VA 24137, United States 06.04.2021 09:00:07 Accur +/-22384.3 Ft ALT 983 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14804+99	Field Station#	14816+07		
Pic 1 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing	
					
36°58'34" N 79°40'39" W 145°SE COURSE -1° GPS Sorry no results found 06.04.2021 09:28:48 Accur +/-222.3 Ft ALT 914 Ft			36°58'23" N 79°40'10" W 27°NE COURSE -1° GPS Penhook, VA 24137, United States 06.04.2021 09:36:45 Accur +/-382.5 Ft ALT 914 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14823+54	Field Station#	14832+61		
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing	
					
36°58'18" N 79°39'41" W 154°SE COURSE 293° GPS 2201 Bar Ridge Rd, Penhook, VA 24137, United States 06.04.2021 08:37:24 Accur +/-131.6 Ft ALT 983 Ft			36°58'16" N 79°39'31" W 95°E COURSE -1° GPS 355 Listening Hill Rd, Penhook, VA 24137, United States 06.04.2021 10:14:16 Accur +/-20.3 Ft ALT 956 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14850+00	Field Station#	14864+00		
Pic 5 Desc.	CWD drain performing intended function		Pic 6 Desc.	ROW stabilized in temporary area. No vegetation along travel lane.	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 11:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 11:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24145
<b>Inspector</b>	Justin Burch			<b>Date/Time</b>	6/4/2021 11:20 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	13958+31
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	14062+17
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	7.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Slope Drain Pipe	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 11:20 AM	<b>Report #</b>	24145
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> <li>• The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). The contractor had an Environmental laborer and Straw Foreman walk with the EI on his inspection. No issues were submitted for the punch list because inspected ECDs were found to be in compliance at the time of inspection.</li> <li>• The EI has not observed that the contractor has worked in the inspection area since the last SWPPP inspection.</li> <li>• Since the last SWPPP inspection the area has received one rainfall event totaling 0.80" at Bonbrook Mill Road #1.</li> <li>• The ROW ground condition is damp</li> <li>• At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14011+00 to 14018+00.</li> <li>• At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.</li> </ul>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/4/2021 11:20 AM	Report #	
Pictures					
<div>167°S (M) 37°2'54"N, 79°53'34"W ±229ft ▲1120ft</div> <div></div>			<div>132°SE (M) 37°3'7"N, 79°53'20"W ±75ft ▲1095ft</div> <div></div>		
GPS Location	0		GPS Location	0	
Field Station#	13963+00		Field Station#	13984+00	
Pic 1 Desc.	Sump pit in acceptable condition		Pic 2 Desc.	Temporary vegetative stabilization in acceptable condition	
<div>202°S (M) 37°3'12"N, 79°53'3"W ±13ft ▲993ft</div> <div></div>			<div>206°SW (M) 37°3'25"N, 79°52'49"W ±232ft ▲1097ft</div> <div></div>		
GPS Location	0		GPS Location	0	
Field Station#	14000+00		Field Station#	14017+00	
Pic 3 Desc.	Super silt fence in acceptable condition		Pic 4 Desc.	Perimeter CFS in acceptable condition	
<div>257°W (M) 37°3'23"N, 79°52'53"W ±62ft ▲1084ft</div> <div></div>			<div>271°W (M) 37°3'59"N, 79°52'27"W ±1584ft ▲1201ft</div> <div></div>		
GPS Location	0		GPS Location	0	
Field Station#	14015+00		Field Station#	14058+00	
Pic 5 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 6 Desc.	Slope drain in acceptable condition	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 11:20 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 11:20 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		









# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24143
<b>Inspector</b>	Charles Head			<b>Date/Time</b>	6/4/2021 10:19 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	14454+22
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	14546+75
<b>County</b>	Franklin	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.25
				<b>Rain Accumulation Time (days)</b>	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. <b>E&amp;S BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>E&amp;S BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
3rd Party Damages	Communication	Repair livestock damage to P-1			
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Repair livestock damage			
Silt Fence (Reinforce Filter Fence)	Acceptable				
<b>5. Site Conditions</b>					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No



<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 10:19 AM	<b>Report #</b>	24143
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	6/4/2021 10:19 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14524+50	<b>Field Station#</b>	14510+00		
<b>Pic 1 Desc.</b>	Approximately 14524+50. Overview of road crossing and RCEs.	<b>Pic 2 Desc.</b>	Approximately 14510+00. Overview of ROW.		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14535+00	<b>Field Station#</b>	14546+33		
<b>Pic 3 Desc.</b>	Approximately 14535+00. Overview of ROW.	<b>Pic 4 Desc.</b>	Approximately 14546+33. Overview of ROW.		
					
<b>GPS Location</b>	0	<b>GPS Location</b>	0		
<b>Field Station#</b>	14470+00	<b>Field Station#</b>	14486+00		
<b>Pic 5 Desc.</b>	Approximately 14470+00. Overview of ROW.	<b>Pic 6 Desc.</b>	Approximately 14486+00. P-1 requires maintenance. Damaged by livestock.		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 10:19 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 10:19 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread I	<b>AFE</b>	124300139	<b>Spread</b>	H-600 Pipeline Spread I
<b>Contractor</b>	Precision			<b>Report #</b>	24138
<b>Inspector</b>	Ben Farmer			<b>Date/Time</b>	6/4/2021 8:44 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	15260+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	15370+62
<b>County</b>	Pittsylvania	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	CFS has been damaged by livestock		
Other - Explain in Comments	Communication	Temporary fence has been damage		
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300139	<b>Date/Time</b>	6/4/2021 8:44 AM	<b>Report #</b>	24138
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 67 F) Rain Gauge= 0.80 15260+00-15370+62  -EI began inspection at Oxford Rd. -RCEs are in good condition at all road crossings. -CWDs are in good condition throughout this section. -CFS has been damaged by livestock and needs to be replaced at 15309+00-15311+50. -Temporary fence has been damaged by livestock and needs to be repaired at 15311+50. -P1 is in good condition at all stream and wetland buffers -Equipment bridge ECDs are in place and functioning. -Waterbars are in good condition throughout this section. -Sensitive resource buffer remains in good condition at 15350+00. -MVP-PI-332 remains in good condition with controls in place. -Vegetation continuing to fill in throughout this section.  *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300139	<b>Date/Time</b>	6/4/2021 8:44 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15310+00		<b>Field Station#</b>	15310+00	
<b>Pic 1 Desc.</b>	CFS has been damaged by livestock and needs to be replaced.		<b>Pic 2 Desc.</b>	CFS has been damaged by livestock and needs to be replaced.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15311+50		<b>Field Station#</b>	15299+00	
<b>Pic 3 Desc.</b>	Temporary fence has been damaged by livestock and needs to be repaired.		<b>Pic 4 Desc.</b>	CWD outlets are in good condition after previous rain event.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15299+00		<b>Field Station#</b>	15311+78	
<b>Pic 5 Desc.</b>	CWD inlets are in good condition.		<b>Pic 6 Desc.</b>	P1 is in good condition around wetland buffer.	



<b>AFE</b>	124300139	<b>Date/Time</b>	6/4/2021 8:44 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15314+19		<b>Field Station#</b>	15323+24	
<b>Pic 7 Desc.</b>	Equipment bridge ECDs are in good condition and functioning.		<b>Pic 8 Desc.</b>	RCEs are in good condition at all road crossings.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15350+00		<b>Field Station#</b>	15350+00	
<b>Pic 9 Desc.</b>	Sensitive resource buffer is in good condition at this location.		<b>Pic 10 Desc.</b>	MVP-PI-332 is in good condition with controls in place.	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	15370+62		<b>Field Station#</b>	15360+00	
<b>Pic 11 Desc.</b>	Rain gauge showing .80" at Snowberry Rd.		<b>Pic 12 Desc.</b>	Vegetation continues to fill in throughout this section of ROW.	

<b>A/E</b>	124300139	<b>Date/Time</b>	6/4/2021 8:44 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	Transco Interconnect Station	<b>AFE</b>	124300113	<b>Spread</b>	Transco Interconnect Sta
<b>Contractor</b>	Kanahwa			<b>Report #</b>	24038
<b>Inspector</b>	John White			<b>Date/Time</b>	6/2/2021 10:35 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	00+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	00+00
<b>County</b>	Pittsylvania	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	Chatham	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	7.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Rock Check Dam	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300113	<b>Date/Time</b>	6/2/2021 10:35 AM	<b>Report #</b>	24038
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down. There were no issues to report at the time of Inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300113	<b>Date/Time</b>	6/2/2021 10:35 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	00+00	<b>Field Station#</b>	00+00		
<b>Pic 1 Desc.</b>	Observing temporary stabilization, rock drain and ECD's	<b>Pic 2 Desc.</b>	Observing temporary stabilization and sediment basin		
<b>GPS Location</b>	O	<b>GPS Location</b>	O		
<b>Field Station#</b>	00+00	<b>Field Station#</b>	00+00		
<b>Pic 3 Desc.</b>	Observing rock drain and ECD's	<b>Pic 4 Desc.</b>	Observing temporary stabilization, storm water pond and ECD's		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 5 Desc.</b>		<b>Pic 6 Desc.</b>			

<b>A/E</b>	124300113	<b>Date/Time</b>	6/2/2021 10:35 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300113	<b>Date/Time</b>	6/2/2021 10:35 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		