



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24519
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/14/2021 11:42 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 11:42 AM	<b>Report #</b>	24519
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area: LY26 Waste management is acceptable. Rock surface of the yard is maintained in acceptable condition. Secondary containment units are in acceptable condition. Spill kits and signage are available and visible House keeping is acceptable. CFS triple stack perimeter controls are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	6/14/2021 11:42 AM	Report #	
Pictures					
 <p>Date &amp; Time: Mon, Jun 14, 2021, 11:56:53 EDT Position: -809.315527° / -080.657351° (15.7ft) Altitude: 1727ft (+26.2ft) Datum: WGS 84 Azimuth/Heading: 052°/504E 3129mils True (+65°) Elevation Angle: -19° Horizon Angle: +00.8° Zoom: 1.0X LY-26- Gas cylinders secured and signage displayed.</p>		 <p>Date &amp; Time: Mon, Jun 14, 2021, 11:57:47 EDT Position: -809.315527° / -080.657351° (15.7ft) Altitude: 1727ft (+26.2ft) Datum: WGS 84 Azimuth/Heading: 170°/504E 3129mils True (+65°) Elevation Angle: -14.0° Horizon Angle: +01.8° Zoom: 1.0X LY-26- CFS triple stack perimeter controls.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	LY-26- Gas cylinders secured and signage visible.		Pic 2 Desc.	LY-26- CFS triple stack perimeter controls.	
 <p>Date &amp; Time: Mon, Jun 14, 2021, 12:00:43 EDT Position: -809.315527° / -080.657351° (15.7ft) Altitude: 1727ft (+26.2ft) Datum: WGS 84 Azimuth/Heading: 240°/540W 426mils True (+65°) Elevation Angle: -69.2° Horizon Angle: +00.8° Zoom: 1.0X LY-26- Spill kits, fire extinguishers, signage are available and visible.</p>		 <p>Date &amp; Time: Mon, Jun 14, 2021, 12:01:42 EDT Position: -809.315527° / -080.657351° (15.7ft) Altitude: 1727ft (+26.2ft) Datum: WGS 84 Azimuth/Heading: 239°/549W 407mils True (+65°) Elevation Angle: -65.2° Horizon Angle: +00.4° Zoom: 1.0X LY-26- Fuel tank in containment.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	LY-26- Spill kits, fire extinguishers, signage are available and visible.		Pic 4 Desc.	LY-26- Fuel storage tank in containment.	
 <p>Date &amp; Time: Mon, Jun 14, 2021, 12:02:27 EDT Position: -809.315527° / -080.657351° (15.7ft) Altitude: 1727ft (+26.2ft) Datum: WGS 84 Azimuth/Heading: 214°/534W 380mils True (+65°) Elevation Angle: -57.5° Horizon Angle: +00.2° Zoom: 1.0X LY-26- Waste containers.</p>		 <p>Date &amp; Time: Mon, Jun 14, 2021, 12:04:00 EDT Position: -809.315527° / -080.657351° (15.7ft) Altitude: 1727ft (+26.2ft) Datum: WGS 84 Azimuth/Heading: 100°/501E 320mils True (+65°) Elevation Angle: -57.5° Horizon Angle: +00.8° Zoom: 1.0X LY-26- Fuel additive tote and light plant in secondary containment unit.</p>			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	LZy-26- Waste containers.		Pic 6 Desc.	LY-26- Fuel additive tote and light plant in secondary containment unit.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 11:42 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 11:42 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24521
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/14/2021 12:31 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	84.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 12:31 PM	<b>Report #</b>	24521
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area: LY-28- west portion of the yard. RCE is in acceptable condition. Secondary containment units are in acceptable condition. Trucks & trailers stored, not in use. Waste management is acceptable. House keeping is acceptable. LY-28- East portion of the yard. Waste management is acceptable. House keeping is acceptable Secondary containment units are in acceptable condition. CFS perimeter controls are in acceptable condition. Rock surface of the yard is in acceptable condition. Overhead utility flagging is in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 12:31 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Jun 14, 2021 12:30:17 EDT  Position: +037.332828° / +080.802548° (+148.6ft)  Altitude: 1521.4ft (+461.7ft)  Datum: WGS-84  Azimuth/Bearing: 179° S17W 3102mils True (+50°)  Elevation Angle: -07.3°  Horizon Angle: +00.5°  Zoom: 1.0X  LY-28- West portion of the yard- Transport buses not in use.</p> 		<p>Date &amp; Time: Mon, Jun 14, 2021 12:30:58 EDT  Position: +037.332828° / +080.802548° (+148.6ft)  Altitude: 1521.4ft (+461.7ft)  Datum: WGS-84  Azimuth/Bearing: 179° S17W 3102mils True (+50°)  Elevation Angle: -07.3°  Horizon Angle: +00.5°  Zoom: 1.0X  LY-28- West portion of the yard- Trailers stored, not in use.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	LY-28- West portion of the yard,- transport buses stored, not in use.	<b>Pic 2 Desc.</b>	LY-28- west yard- Trailers not in use, stored.		
<p>Date &amp; Time: Mon, Jun 14, 2021 12:39:20 EDT  Position: +037.332828° / +080.802147° (+14.0ft)  Altitude: 1555ft (+472.2ft)  Datum: WGS-84  Azimuth/Bearing: 233° N76W 3787mils True (+10°)  Elevation Angle: -07.3°  Horizon Angle: +00.5°  Zoom: 1.0X  LY-28- west portion of the yard- RCE</p> 		<p>Date &amp; Time: Mon, Jun 14, 2021 12:44:02 EDT  Position: +037.332828° / +080.802147° (+14.0ft)  Altitude: 1555ft (+472.2ft)  Datum: WGS-84  Azimuth/Bearing: 230° N76W 3787mils True (+10°)  Elevation Angle: -07.3°  Horizon Angle: +00.5°  Zoom: 1.0X  LY-28- east portion of the yard- CFS perimeter controls.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY-28- West portion of the yard- RCE	<b>Pic 4 Desc.</b>	LY- 28- East portion of the yard- CFS perimeter controls.		
<p>Date &amp; Time: Mon, Jun 14, 2021 12:49:03 EDT  Position: +037.332828° / +080.803383° (+148.6ft)  Altitude: 1554ft (+44.9ft)  Datum: WGS-84  Azimuth/Bearing: 223° S43W 3924mils True (+30°)  Elevation Angle: -07.3°  Horizon Angle: +00.5°  Zoom: 1.0X  LY-28- East portion of the yard- Waste containers.</p> 		<p>Date &amp; Time: Mon, Jun 14, 2021 12:50:58 EDT  Position: +037.332828° / +080.803383° (+148.6ft)  Altitude: 1554ft (+44.9ft)  Datum: WGS-84  Azimuth/Bearing: 223° S43W 3924mils True (+30°)  Elevation Angle: -07.3°  Horizon Angle: +00.5°  Zoom: 1.0X  LY-28- West portion of the yard- Trucks not in use with containment under motors.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005-00		
<b>Pic 5 Desc.</b>	LY-28- East portion of the yard- waste containment.	<b>Pic 6 Desc.</b>	LY-28- West portion of the yard- Trucks not in use with containment under motors.		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 12:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 12:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24535
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	6/14/2021 5:53 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Craig	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.70
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar End Treatment	Communication	See comments		
Stone Inlet Protection	Communication	See comments		
Waterbar	Communication	See comments		
Sump Pit	Communication	See comments		
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sensitive Resource Signage	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 5:53 PM	<b>Report #</b>	24535
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to MP 219.70) Deficiencies found at the following station numbers: 11527+50 to 11533+00 Clean out sediment and refresh rock inlet 11527+50 to 11547+60 Clean sediment off of CFS triple stack end treatment Waterbars and sump pits already on 6/13/21 punch list as 72hr items -item # 850 11548+00 to 11489+70 waterbar maintenance needed -Item # 851 11548+00 to 11471+56 sump maintenance needed Active construction site; additional deficiencies may be identified by other EIs. ROW is wet and in stable condition up until JNF property line ST# 11553+66. This section of the ROW has been backfilled and restored to subgrade. Topsoil piles are stabilized. ROW is wet and stabilized throughout JNF with large areas of vegetation. Waterbars with end treatments and perimeter controls are in place. 50' buffers are in place at stream crossings S-PP22, S-PP21, S-PP20. Craig Creek rain gauge measured 0.7" of rain fall accumulated on 6/13/21 AR-258.02 and Craig Creek road crossing RCE are maintained in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 5:53 PM	<b>Report #</b>	
<b>Pictures</b>					
<p><small>Date &amp; Time: Mon, Jun 14, 2021, 07:53:11 EDT Position: +037.23255° / -080.42502° (±11.6m) Altitude: 2324ft (±15.0ft) Datum: WGS-84 Azimuth/Bearing: 117.543E 2080mils True (±12°) Elevation Angle: -02.1° Horizon Angle: -01.5° Zoom: 1.0X 11527+00</small></p> 		<p><small>Date &amp; Time: Mon, Jun 14, 2021, 08:23:04 EDT Position: +037.288419° / -080.416235° (±15.4m) Altitude: 2684ft (±11.5ft) Datum: WGS-84 Azimuth/Bearing: 177° 30'E 1147mils True (±12°) Elevation Angle: -01.8° Horizon Angle: -00.8° Zoom: 1.0X 11537+00</small></p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11527+00	<b>Field Station#</b>	11537+00		
<b>Pic 1 Desc.</b>	Clean water drainage feature in place	<b>Pic 2 Desc.</b>	P1 silt fence perimeter control in place		
<p><small>Date &amp; Time: Mon, Jun 14, 2021, 08:05:22 EDT Position: +037.21535° / -080.419803° (±15.0ft) Altitude: 2315ft (±15.0ft) Datum: WGS-84 Azimuth/Bearing: 291.146W 5173mils True (±12°) Elevation Angle: -26.1° Horizon Angle: -00.9° Zoom: 1.0X 11528+50</small></p> 		<p><small>Date &amp; Time: Mon, Jun 14, 2021, 08:36:55 EDT Position: +037.326896° / -080.417199° (±15.6ft) Altitude: 2597ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 223.563W 3964mils True (±12°) Elevation Angle: -39.2° Horizon Angle: -05.5° Zoom: 1.0X 11543+00</small></p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11528+50	<b>Field Station#</b>	11543+00		
<b>Pic 3 Desc.</b>	Rock inlet protection needs cleaned out	<b>Pic 4 Desc.</b>	CFS end treatment needs cleaned off		
<p><small>Date &amp; Time: Mon, Jun 14, 2021, 09:16:16 EDT Position: +037.21724° / -080.40662° (±15.3ft) Altitude: 2362ft (±11.4ft) Datum: WGS-84 Azimuth: -147.2613E (±12°) Elevation Angle: +18.4° Horizon Angle: +17.1° Zoom: 1.0X 11562+00</small></p> 		<p><small>Date &amp; Time: Mon, Jun 14, 2021, 09:31:41 EDT Position: +037.21724° / -080.40662° (±15.3ft) Altitude: 2362ft (±11.4ft) Datum: WGS-84 Azimuth: +011.0166E (±12°) Elevation Angle: +36.1° Horizon Angle: +18.1° Zoom: 1.0X 11586+00</small></p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11562+00	<b>Field Station#</b>	11586+00		
<b>Pic 5 Desc.</b>	Waterbars in place	<b>Pic 6 Desc.</b>	Stream buffer in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 5:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 5:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24528
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/14/2021 1:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.40
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 1:14 PM	<b>Report #</b>	24528
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area- LY29 AR-238.00 the access road serving LY-29 is maintained in acceptable condition. Waste management is acceptable. House keeping is acceptable. CFS triple stack perimeter controls are in acceptable condition. Culvert and drainage feature are in acceptable condition. Overhead utility flagging is in acceptable condition. Gas cylinders are secured and signage is visible. There is some welding taking place in the yard.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/14/2021 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Jun 14, 2021, 13:17:29 EDT  Position: -037.363782° / -080.672115° (±43.6ft)  Altitude: 1798ft (±76.8ft)  Datum: WGS-84  Azimuth/Bearing: 251° 571W 4462mils True (±71°)  Elevation Angle: -14.1°  Horizon Angle: -00.8°  Zoom: 1.0X  LY-29- AR-238.00 serving the yard.</p> 		<p>Date &amp; Time: Mon, Jun 14, 2021, 13:26:59 EDT  Position: -037.363807° / -080.675042° (±44.9ft)  Altitude: 1838ft (±76.8ft)  Datum: WGS-84  Azimuth/Bearing: 134° 00W 1601mils True (±50°)  Elevation Angle: -14.3°  Horizon Angle: -01.2°  Zoom: 1.0X  LY-29- Overview of the yard.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	LY-29- AR-238.00 is maintained in acceptable condition.		<b>Pic 2 Desc.</b>	LY-29- Overview of the yard.	
<p>Date &amp; Time: Mon, Jun 14, 2021, 13:28:00 EDT  Position: -037.363227° / -080.670389° (±48.1ft)  Altitude: 1713ft (±76.8ft)  Datum: WGS-84  Azimuth/Bearing: 247° 567W 4291mils True (±132°)  Elevation Angle: -14.5°  Horizon Angle: -00.5°  Zoom: 1.0X  LY-29- CFS triple stack perimeter controls.</p> 		<p>Date &amp; Time: Mon, Jun 14, 2021, 13:36:01 EDT  Position: -037.362572° / -080.673352° (±14.7ft)  Altitude: 1214ft (±26.4ft)  Datum: WGS-84  Azimuth/Bearing: 126° 554E 2260mils True (±8°)  Elevation Angle: -09.5°  Horizon Angle: -00.4°  Zoom: 1.0X  LY-29- Waste containment.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	LY29- CFS triple stack perimeter controls.		<b>Pic 4 Desc.</b>	LY-29- Waste containment.	
<p>Date &amp; Time: Mon, Jun 14, 2021, 13:32:04 EDT  Position: -037.362442° / -080.677163° (±42.0ft)  Altitude: 1709ft (±29.7ft)  Datum: WGS-84  Azimuth/Bearing: 264° 584W 4693mils True (±108°)  Elevation Angle: -05.7°  Horizon Angle: -00.7°  Zoom: 1.0X  LY-29- Side boom staged in the yard.</p> 		<p>Date &amp; Time: Mon, Jun 14, 2021, 13:34:08 EDT  Position: -037.362591° / -080.677807° (±14.6ft)  Altitude: 1708ft (±29.7ft)  Datum: WGS-84  Azimuth/Bearing: 348° N12W 6187mils True (±29°)  Elevation Angle: -29.3°  Horizon Angle: -01.7°  Zoom: 1.0X  LY-29- Culvert and drainage feature.</p> 			
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	LY-29- Side boom staged in the yard.		<b>Pic 6 Desc.</b>	LY-29- Culvert and drainage feature.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/14/2021 1:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24592
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	6/15/2021 2:31 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10656+15
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10759+25
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	76.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Repair/replace damaged CFS	24 Hours	
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Vegetative Stabilization (Temporary)	Communication	Repair and stabilize	24 Hours	
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Communication	Clean out	24 Hours	

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





AFE	124300137	Date/Time	6/15/2021 2:31 PM	Report #	
Pictures					
 <p>Date &amp; Time: Tue Jun 15, 2021, 09:29:36 EDT Position: +037.248310° / -080.648581° (±11.6m) Altitude: 2345ft (±13.1m) Datum: WGS-84 Azimuth/Bearing: 156° S24E 2773mils True (±12°) Elevation Grade: -093% Horizon Grade: +008% Zoom: 0.5X 10708+00 clean out sump</p>		 <p>Date &amp; Time: Tue Jun 15, 2021, 09:52:59 EDT Position: +037.257135191° / -080.660469° (±13.6m) Altitude: 2223ft (±9.3m) Datum: WGS-84 Azimuth/Bearing: 131° S49E 2329mils True (±12°) Elevation Grade: -046% Horizon Grade: +011% Zoom: 0.5X AR 240 - 10669+50</p>			
GPS Location	1	GPS Location	2		
Field Station#	10708+00	Field Station#	10669+50		
Pic 1 Desc.	Clean out sump.	Pic 2 Desc.	Repair/stabilize or add rock.		
 <p>Date &amp; Time: Tue Jun 15, 2021, 10:01:01 EDT Position: +037.350664° / -080.659571° (±11.6m) Altitude: 2175ft (±7.8m) Datum: WGS-84 Azimuth/Bearing: 104° N04E 0021mils True (±12°) Elevation Grade: -071% Horizon Grade: +033% Zoom: 0.5X 10676+35 repair and stabilize or create RCE</p>		 <p>Date &amp; Time: Tue Jun 15, 2021, 10:02:03 EDT Position: +037.350060° / -080.658895° (±15.4m) Altitude: 2104ft (±4.1m) Datum: WGS-84 Azimuth/Bearing: 122° S59E 2487mils True (±12°) Elevation Grade: -076% Horizon Grade: +001% Zoom: 0.5X PI-10677+61 to S&amp;F 10679+00 instal 18" CFS perimeter control</p>			
GPS Location	3	GPS Location	4		
Field Station#	10676+35	Field Station#	10677+61		
Pic 3 Desc.	Repair and stabilize or create RCE.	Pic 4 Desc.	EI recommend instal 18" CFS perimeter control not called for on E&S sheets.		
 <p>Date &amp; Time: Tue Jun 15, 2021, 10:47:32 EDT Position: +037.350775° / -080.668342° (±27.7m) Altitude: 2045ft (±12.2m) Datum: WGS-84 Azimuth/Bearing: 105° N55E 0078mils True (±12°) Elevation Grade: -088% Horizon Grade: +018% Zoom: 0.5X S 10679+00 cleanout (repair) CFS</p>		 <p>Date &amp; Time: Tue Jun 15, 2021, 10:48:54 EDT Position: +037.350289° / -080.668122° (±15.4m) Altitude: 2039ft (±11.3m) Datum: WGS-84 Azimuth/Bearing: 119° S41E 2146mils True (±12°) Elevation Grade: -089% Horizon Grade: -066% Zoom: 0.5X 10679+50 repair CFS</p>			
GPS Location	5	GPS Location	6		
Field Station#	10679+30	Field Station#	10679+50		
Pic 5 Desc.	Repair/clean out CFS.	Pic 6 Desc.	Repair/replace CFS.		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2021 2:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2021 2:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24600
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/15/2021 4:46 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+52
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10859+34
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	74.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Replace damaged silt fence	24 Hours	
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2021 4:46 PM	<b>Report #</b>	24600
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area: Sta#11064+53 to 10859+34. MP-209.56 to 205.67 The inspection area is a active construction site; additional deficiencies may be identified by other EI,'s There were multiple punch list items added yesterday, two environmental crews were working on punch list items. I added one punch list item today at sta#11056+00- silt fence down. The row is wet but in stable condition condition overall. Perimeter controls are in acceptable condition. Slope drains are in acceptable condition. CWD pipe and level spreaders are in acceptable condition. Streams and stream ECD's are in acceptable condition. Sensitive resource area ECD's are in acceptable condition. Access roads and RCE's are maintained in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2021 4:46 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10929+62		<b>Field Station#</b>	10960+00	
<b>Pic 1 Desc.</b>	Doe Creek RCE- Contractor loading out equipment.		<b>Pic 2 Desc.</b>	Rock encounter during grading.	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10964+00		<b>Field Station#</b>	10965+00	
<b>Pic 3 Desc.</b>	Drainage feature		<b>Pic 4 Desc.</b>	Sensitive resource area ECD's.	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	10977+00		<b>Field Station#</b>	10985+00	
<b>Pic 5 Desc.</b>	Multiple CWD pipes in this area.		<b>Pic 6 Desc.</b>	Stream S- E24	



<b>AFE</b>	124300137	<b>Date/Time</b>	6/15/2021 4:46 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Jun 15, 2021, 09:57:38 EDT  Position: +037.325422° / -080.554851° (±11.5m)  Altitude: 2372ft (±11.5m)  Datum: WGS-84  Azimuth/Bearing: 115° S65E 2044mils True (±13°)  Elevation Angle: -02.3°  Horizon Angle: -02.0°  Zoom: 1.0X  Staff: 10986+00 -Stream S-E25</p> 		<p>Date &amp; Time: Tue, Jun 15, 2021, 10:07:48 EDT  Position: +037.323844° / -080.555531° (±10.8m)  Altitude: 2508ft (±8.6m)  Datum: WGS-84  Azimuth/Bearing: 124° S54E 2204mils True (±13°)  Elevation Angle: -25.4°  Horizon Angle: -04.8°  Zoom: 1.0X  Staff: 11012+00 -Class B slope down to Stream S-RR5</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10986+00	<b>Field Station#</b>	11012+00		
<b>Pic 7 Desc.</b>	Stream S- E25	<b>Pic 8 Desc.</b>	Class B slope down to stream S-RR5		
<p>Date &amp; Time: Tue, Jun 15, 2021, 10:34:11 EDT  Position: +037.323493° / -080.552469° (±8.6m)  Altitude: 2394ft (±8.6m)  Datum: WGS-84  Azimuth/Bearing: 294° N46W 4220mils True (±13°)  Elevation Angle: -09.5°  Horizon Angle: -01.1°  Zoom: 1.0X  Staff: 11017+00-Stream PA07</p> 		<p>Date &amp; Time: Tue, Jun 15, 2021, 10:40:30 EDT  Position: +037.322737° / -080.552649° (±8.6m)  Altitude: 2410ft (±42.8m)  Datum: WGS-84  Azimuth/Bearing: 118° S42E 2098mils True (±13°)  Elevation Angle: -14.2°  Horizon Angle: -02.2°  Zoom: 1.0X  Staff: 11025+00-Stream S-IJ18</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11017+00	<b>Field Station#</b>	11025+00		
<b>Pic 9 Desc.</b>	Stream S- PA07	<b>Pic 10 Desc.</b>	Stream S-IJ18		
<p>Date &amp; Time: Tue, Jun 15, 2021, 10:44:01 EDT  Position: +037.322730° / -080.553332° (±10.3m)  Altitude: 2415ft (±26.0m)  Datum: WGS-84  Azimuth/Bearing: 208° N46W 5086mils True (±13°)  Elevation Angle: -11.0°  Horizon Angle: -03.8°  Zoom: 1.0X  Staff: 11023+00- Hoe addressing punch list items</p> 		<p>Date &amp; Time: Tue, Jun 15, 2021, 11:04:01 EDT  Position: +037.318368° / -080.545584° (±10.3m)  Altitude: 2343ft (±26.0m)  Datum: WGS-84  Azimuth/Bearing: 100° S59E 3245mils True (±13°)  Elevation Angle: -17.8°  Horizon Angle: -03.3°  Zoom: 1.0X  Staff: 11044+00- Signage depicting class A slope</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11023+00	<b>Field Station#</b>	11044+00		
<b>Pic 11 Desc.</b>	Hoe addressing punch list items.	<b>Pic 12 Desc.</b>	Clas A signage depicting slope		



<b>AFE</b>	124300137	<b>Date/Time</b>	6/15/2021 4:46 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Jun 15, 2021, 11:10:41 EDT Position: +037.318222° / -080.542773° (+97.6ft) Altitude: 2100ft (+57.2ft) Datum: WGS-84 Azimuth/Bearing: 099° S81E 1760mils True (+13°) Elevation Angle: -13.8° Horizon Angle: +00.3° Zoom: 1.0X Stail 11049+50- Stream S-IN16B</p> 		<p>Date &amp; Time: Tue, Jun 15, 2021, 11:21:43 EDT Position: +037.317295° / -080.546291° (+103.0ft) Altitude: 2172ft (+29.5ft) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mils True (+13°) Elevation Angle: -36.2° Horizon Angle: +08.9° Zoom: 1.0X Stail 11056+00- P1 silt fence down in Karst</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11049+50	<b>Field Station#</b>	11056+00		
<b>Pic 13 Desc.</b>	Stream S- IJ16B	<b>Pic 14 Desc.</b>	Silt fence down in Karst area, item added to the punch list.		
<p>Date &amp; Time: Tue, Jun 15, 2021, 11:58:55 EDT Position: +037.316136° / -080.596703° (+115.3ft) Altitude: 2150ft (+21.4ft) Datum: WGS-84 Azimuth/Bearing: 287° N27W 5102mils True (+12.0°) Elevation Angle: -15.8° Horizon Angle: +01.7° Zoom: 1.0X Stream S-A3- stail 10883+33</p> 		<p>Date &amp; Time: Tue, Jun 15, 2021, 12:00:38 EDT Position: +037.316136° / -080.596523° (+114.8ft) Altitude: 2150ft (+21.4ft) Datum: WGS-84 Azimuth/Bearing: 129° S55E 3208mils True (+16.4°) Elevation Angle: +05.1° Horizon Angle: -02.2° Zoom: 1.0X Stail 10883+68- Kow amp 2 RCE &amp; row</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	10883+33	<b>Field Station#</b>	10883+68		
<b>Pic 15 Desc.</b>	Stream S -A3	<b>Pic 16 Desc.</b>	Kow Camp two RCE and row.		
<p>Date &amp; Time: Tue, Jun 15, 2021, 12:08:11 EDT Position: +037.317273° / -080.606887° (+80.3ft) Altitude: 2313ft (+43.7ft) Datum: WGS-84 Azimuth/Bearing: 267° S72W 4510mils True (+15.7°) Elevation Angle: -08.8° Horizon Angle: +02.1° Zoom: 1.0X Kow Camp one RCE</p> 		<p>Insert image here</p>			
<b>GPS Location</b>	See photo GPS			<b>GPS Location</b>	
<b>Field Station#</b>	10859+34	<b>Field Station#</b>			
<b>Pic 17 Desc.</b>	Kow Camp one RCE.	<b>Pic 18 Desc.</b>			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24603
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	6/15/2021 5:56 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10759+25
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10859+34
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Communication			
Sump Pit	Communication			
Rock Construction Entrance	Communication			
Slope Drain Pipe	Communication			
Stone Inlet Protection	Communication			
Rock Filter Outlet	Communication			
Compost Filter Sock	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2021 5:56 PM	<b>Report #</b>	24603
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Met at LDY 26 office for morning EI meeting and daily construction conference call.</p> <p>Conducted VA SWPPP inspection from station number 10759+25 to station number 10859+34. (MP 203.77 to MP 205.67)</p> <p>During VA SWPPP inspection deficiencies located at station numbers;</p> <p>10759+25 - RCE at Big Branch Hollow Road needs refreshed.</p> <p>10805+10 to 10819+00 - sump pit need sediment removal.</p> <p>10857+50 - waterbar needed on travel lane. Slope drain with rock inlet and outlet needed over two-tone.</p> <p>10858+00 - waterbar needed on travel lane. Slope drain with rock inlet and outlet needed over two-tone.</p> <p>Observed environmental crew installing rock lined channel along driveway at station number 10767+40. Crew was also installing CWDP inlet in corrected location at station number 10767+32. CWDP inlet was previously installed at station number 10766+50.</p> <p>50' buffers in place at stream crossings S-A33, S-A34, S-Z14, S-Z7, S-Z9, S-SS4, and S-G35.</p> <p>AR-241.02, AR-241.03 Kow Camp #2, Cascade Drive, and Hendrickson crossing RCEs are maintained in acceptable condition.</p> <p>The ROW is dry and stable. No sensitive resources have been impacted.</p> <p>VA SWPPP was conducted during active construction, additional deficiencies may be located by other EIs.</p>					
<p><b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.</p>					



AFE		124300137		Date/Time		6/15/2021 5:56 PM		Report #							
Pictures															
															
<p>Date &amp; Time: Sat, Jun 15, 2021, 06:43:36 EDT Position: 1027.30667, -80.632823 (4362.5ft) Altitude: 2140ft (652.2m) Datum: WGS-84 Accuracy: 10.0m Azimuth: 257° SOW Azimuth: 257° SOW Elevation: 257° SOW Horizontal: 10.0m Vertical: 1.0m Zoom: 10 Jared Saunders</p>				<p>Date &amp; Time: Sat, Jun 15, 2021, 06:44:57 EDT Position: 1027.30667, -80.632823 (4362.5ft) Altitude: 2140ft (652.2m) Datum: WGS-84 Accuracy: 10.0m Azimuth: 257° SOW Azimuth: 257° SOW Elevation: 257° SOW Horizontal: 10.0m Vertical: 1.0m Zoom: 10 Jared Saunders</p>											
<b>GPS Location</b>				See photo for GPS location.				<b>GPS Location</b>				See photo for GPS location.			
<b>Field Station#</b>				10758+25				<b>Field Station#</b>				10767+40			
<b>Pic 1 Desc.</b>				RCE at Big Branch Hollow Road needs refreshed.				<b>Pic 2 Desc.</b>				Rock lined channel being installed.			
															
<p>Date &amp; Time: Sat, Jun 15, 2021, 06:44:57 EDT Position: 1027.30667, -80.632823 (4362.5ft) Altitude: 2140ft (652.2m) Datum: WGS-84 Accuracy: 10.0m Azimuth: 257° SOW Azimuth: 257° SOW Elevation: 257° SOW Horizontal: 10.0m Vertical: 1.0m Zoom: 10 Jared Saunders</p>				<p>Date &amp; Time: Sat, Jun 15, 2021, 06:45:57 EDT Position: 1027.30667, -80.632823 (4362.5ft) Altitude: 2140ft (652.2m) Datum: WGS-84 Accuracy: 10.0m Azimuth: 257° SOW Azimuth: 257° SOW Elevation: 257° SOW Horizontal: 10.0m Vertical: 1.0m Zoom: 10 Jared Saunders</p>											
<b>GPS Location</b>				See photo for GPS location.				<b>GPS Location</b>				See photo for GPS location.			
<b>Field Station#</b>				10775+40				<b>Field Station#</b>				10813+82			
<b>Pic 3 Desc.</b>				Sump pit and 18 inch CFS end treatment in place.				<b>Pic 4 Desc.</b>				Sump pit that needs sediment removal.			
															
<p>Date &amp; Time: Sat, Jun 15, 2021, 06:46:57 EDT Position: 1027.30667, -80.632823 (4362.5ft) Altitude: 2140ft (652.2m) Datum: WGS-84 Accuracy: 10.0m Azimuth: 257° SOW Azimuth: 257° SOW Elevation: 257° SOW Horizontal: 10.0m Vertical: 1.0m Zoom: 10 Jared Saunders</p>				<p>Date &amp; Time: Sat, Jun 15, 2021, 06:47:57 EDT Position: 1027.30667, -80.632823 (4362.5ft) Altitude: 2140ft (652.2m) Datum: WGS-84 Accuracy: 10.0m Azimuth: 257° SOW Azimuth: 257° SOW Elevation: 257° SOW Horizontal: 10.0m Vertical: 1.0m Zoom: 10 Jared Saunders</p>											
<b>GPS Location</b>				See photo for GPS location.				<b>GPS Location</b>				See photo for GPS location.			
<b>Field Station#</b>				10855+00				<b>Field Station#</b>				10858+00			
<b>Pic 5 Desc.</b>				Sensitive resource buffer in place at stream S-A33 and S-A34.				<b>Pic 6 Desc.</b>				Location that waterbar need to be installed in travel lane. Slope drains with rock inlet and outlet need to be installed over two-tone.			



<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2021 5:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/15/2021 5:56 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24631
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	6/16/2021 8:21 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+16
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	72.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Equipment Bridge	Communication			
Stone Inlet Protection	Communication			
Waterbar End Treatment	Communication			

## 5. Site Conditions







Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2021 8:21 AM	<b>Report #</b>	24631
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11254+99 to ST# 11524+16 (MP 213.16 to MP 218.26) Deficiencies found at the following station numbers: 11259+00 to 11262+00 Clean sediment out of inlet and refresh rock 11285+90, 11287+30 Clean sediment out of inlet and refresh rock 11293+00 Repair mining belt and clean off equipment bridge 11332+37 Clean sediment off of CFS triple stack end treatment All issues have been communicated to PPL contractor via punch list. Active construction site; additional deficiencies may be identified by other EIs. Observed: -Lowering-in and Backfill crews between ST# 11265+00 and ST# 11292+00 -Tie-in crew #1 at ST# 11363+00 backfilling trench -Tie-in crew #2 at 11432+88 lowering in section of pipe and building trench breakers -Environmental crew cleaning off equipment bridge at ST# 11451+08 over stream crossing S-0013 -Environmental crew at ST# 11498+50 stabilizing spoil piles and installing waterbars. Pipe has been lowered in and trench backfilled from ST# 11323+00 to ST# 11524+16 with the exceptions of stream crossings and Tie-ins. 50' buffers in place at stream crossings S-MM18, S-NN12, S-NN11, S-KL43, S-0014, S-0013, S-0012, S-CD14, S-PP3, and S-PP4 AR-253.03, 253.01, and 256.01 have not yet been constructed AR-253.02, 256, 256.02, 258.01, 258.02, and Stevers Gap road crossing RCE are maintained in acceptable condition. Rain gauge at Steele Acres measured 0.05" of rainfall accumulated on 6/15/21 The ROW is dry and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/16/2021 8:21 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11332+37	<b>Field Station#</b>	11293+00		
<b>Pic 1 Desc.</b>	Clean off CFS end treatment	<b>Pic 2 Desc.</b>	Repair mining belt and clean off bridge		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11285+90	<b>Field Station#</b>	11260+00		
<b>Pic 3 Desc.</b>	Clean sediment out of rock inlet	<b>Pic 4 Desc.</b>	End treatments in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11270+00	<b>Field Station#</b>	11324+00		
<b>Pic 5 Desc.</b>	Plunge pool in place	<b>Pic 6 Desc.</b>	Waterbars in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	6/16/2021 8:21 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed, Jun 16, 2021 09:58:40 EDT  Position: +037 300976 / -080 472655 (±19.0ft)  Altitude: 2160ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 233° S53W 4742mils True (±12°)  Elevation Angle: +36.8°  Horizon Angle: -01.0°  Zoom: 1.0X  11328+63</p> 		<p>Date &amp; Time: Wed, Jun 16, 2021 10:38:47 EDT  Position: +037 307382 / -080 466878 (±11.6ft)  Altitude: 1953ft (±9.8ft)  Datum: WGS-84  Azimuth/Bearing: 037° N37E 6658mils True (±12°)  Elevation Angle: +03.2°  Horizon Angle: -01.4°  Zoom: 1.0X  11363+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11328+63	<b>Field Station#</b>	11363+00		
<b>Pic 7 Desc.</b>	Stream buffer in place	<b>Pic 8 Desc.</b>	Stream buffer in place		
<p>Date &amp; Time: Wed, Jun 16, 2021 11:09:27 EDT  Position: +037 310146 / -080 456213 (±11.6ft)  Altitude: 2220ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 277° N83W 4926mils True (±13°)  Elevation Angle: +11.6°  Horizon Angle: -00.9°  Zoom: 1.0X  11391+50</p> 		<p>Date &amp; Time: Wed, Jun 16, 2021 12:15:10 EDT  Position: +037 325337 / -080 428312 (±11.7ft)  Altitude: 2270ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 248° S68W 4409mils True (±12°)  Elevation Angle: +13.0°  Horizon Angle: +03.3°  Zoom: 1.0X  11498+50</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11391+50	<b>Field Station#</b>	11498+50		
<b>Pic 9 Desc.</b>	End treatments in place	<b>Pic 10 Desc.</b>	CFS perimeter control in place		
<p>Date &amp; Time: Wed, Jun 16, 2021 12:30:30 EDT  Position: +037 328349 / -080 423113 (±11.6ft)  Altitude: 2237ft (±9.8ft)  Datum: WGS-84  Azimuth/Bearing: 121° S59E 2151mils True (±12°)  Elevation Angle: -01.2°  Horizon Angle: -01.9°  Zoom: 1.0X  11518+00</p> 		<p>Date &amp; Time: Wed, Jun 16, 2021 10:12:12 EDT  Position: +037 302164 / -080 470622 (±11.6ft)  Altitude: 2281ft (±13.1ft)  Datum: WGS-84  Azimuth/Bearing: 348° N12W 6187mils True (±12°)  Elevation Angle: -02.0°  Horizon Angle: -00.4°  Zoom: 1.0X  11337+50</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11518+00	<b>Field Station#</b>	11337+50		
<b>Pic 11 Desc.</b>	Stream buffer in place	<b>Pic 12 Desc.</b>	P1 perimeter control in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2021 8:21 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24645
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/16/2021 4:49 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	74.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.15
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable	Restake CFS	24 Hours	
Compost Filter Sock	Communication			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions







Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2021 4:49 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed Jun 16, 2021, 08:50:09 EDT Position: +037.315221 / +080.543111 (+42.10) Altitude: 2124ft (+64.4m) Datum: WGS-84 Azimuth Bearing: 282.1° NW 5013mils True (+14.1) Elevation Angle: +24.1 Horizon Angle: +02.4 Zoom: 1.0X Stat: 11065+00- Environmental crew equipment repaving punch list items</p>		 <p>Date &amp; Time: Wed Jun 16, 2021, 09:02:07 EDT Position: +037.315604 / +080.536978 (+43.30) Altitude: 2180ft (+66.3m) Datum: WGS-84 Azimuth Bearing: 100.5° SE 1938mils True (+13.1) Elevation Angle: +27.0 Horizon Angle: +02.0 Zoom: 1.0X Stat: 11079+00- Row rilling environmental crew making repairs</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11065+00	<b>Field Station#</b>	11079+00		
<b>Pic 1 Desc.</b>	Environmental crew equipment being used to address punch list items.	<b>Pic 2 Desc.</b>	Row rilling, environmental crew making repairs.		
 <p>Date &amp; Time: Wed Jun 16, 2021, 09:13:45 EDT Position: +037.310392 / +080.536594 (+41.62) Altitude: 2063ft (+62.8m) Datum: WGS-84 Azimuth Bearing: 111° S2E 3142mils True (+11.1) Elevation Angle: +03.0 Horizon Angle: +04.0 Zoom: 1.0X Stat: 11094+85- Environmental res. refreshing slope drain inlet rock</p>		 <p>Date &amp; Time: Wed Jun 16, 2021, 09:27:02 EDT Position: +037.313124 / +080.533164 (+39.40) Altitude: 2125ft (+64.6m) Datum: WGS-84 Azimuth Bearing: 226.5° SSW 4000mils True (+1.0) Elevation Angle: +03.0 Horizon Angle: +00.2 Zoom: 1.0X Stat: 11100+00- AR-245.02</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11094+85	<b>Field Station#</b>	11100+00		
<b>Pic 3 Desc.</b>	Environmental crew replacing slope drain inlet rock.	<b>Pic 4 Desc.</b>	AR-245.02- Drainage feature & equipment bridge.		
 <p>Date &amp; Time: Wed Jun 16, 2021, 09:39:23 EDT Position: +037.314392 / +080.531576 (+103.7m) Altitude: 2075ft (+63.2m) Datum: WGS-84 Azimuth Bearing: 153.5° S2E 2720mils True (+13.1) Elevation Angle: +22.5 Horizon Angle: +01.5 Zoom: 1.0X Stat: 11107+00- contaminated rock at slope drain inlet replaced, water bars reggraded</p>		 <p>Date &amp; Time: Wed Jun 16, 2021, 09:49:58 EDT Position: +037.315221 / +080.528408 (+53.4m) Altitude: 2084ft (+63.5m) Datum: WGS-84 Azimuth Bearing: 098.8° S2E 1742mils True (+13.1) Elevation Angle: +26.3 Horizon Angle: +03.0 Zoom: 1.0X Stat: 11118+00- water bars on slope have been reggraded after multiple rain events</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11107+00	<b>Field Station#</b>	11118+00		
<b>Pic 5 Desc.</b>	Contaminated slope drain inlet rock has been replaced and water bars reggraded.	<b>Pic 6 Desc.</b>	Water bars on slope reggraded after multiple rain events.		



AFE	124300137	Date/Time	6/16/2021 4:49 PM	Report #	
Pictures					
 <p>Date &amp; Time: Wed Jun 16 2021 10:05:32 EDT Position: +037 314710 / -080 523846 (+139.3m) Altitude: 2000ft (+58.8m) Datum: WGS-84 Azimuth/Bearing: 109° S31E 1938mils True (+13°) Elevation Angle: +35.3° Horizon Angle: +06.1° Zoom: 1.0X Staff: 11132+00- Marst ECD's &amp; signage</p>				 <p>Date &amp; Time: Wed Jun 16 2021 10:30:10 EDT Position: +037 314710 / -080 523846 (+139.3m) Altitude: 1810ft (+55.7m) Datum: WGS-84 Azimuth/Bearing: 109° S31E 1938mils True (+13°) Elevation Angle: +35.3° Horizon Angle: +06.1° Zoom: 1.0X AR-249.00- Restake CFS perimeter controls</p>	
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11132+00		Field Station#	11150+00	
Pic 7 Desc.	Karst ECD's & signage.		Pic 8 Desc.	AR-249.00- CFS perimeter controls on access road need to be reinstated and staked.	
 <p>Date &amp; Time: Wed Jun 16 2021 11:02:11 EDT Position: +037 314710 / -080 523846 (+139.3m) Altitude: 1810ft (+55.7m) Datum: WGS-84 Azimuth/Bearing: 167° S13E 2069mils True (+13°) Elevation Angle: +21.6° Horizon Angle: +02.9° Zoom: 1.0X Staff: 11184+00- CWD pipe &amp; plunge pool</p>				 <p>Date &amp; Time: Wed Jun 16 2021 11:08:27 EDT Position: +037 304932 / -080 510185 (+127.0m) Altitude: 1950ft (+59.4m) Datum: WGS-84 Azimuth/Bearing: 120° S45E 2133mils True (+13°) Elevation Angle: +15.2° Horizon Angle: +01.1° Zoom: 1.0X Staff: 11191+00- Sensitive resource drainage feature</p>	
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11184+00		Field Station#	11191+00	
Pic 9 Desc.	CWD pipe and plunge pool, slope drains.		Pic 10 Desc.	Sensitive resource ECD's/ drainage feature.	
 <p>Date &amp; Time: Wed Jun 16 2021 11:23:08 EDT Position: +037 304932 / -080 506741 (+110.8m) Altitude: 1979ft (+60.3m) Datum: WGS-84 Azimuth/Bearing: 159° S23E 2791mils True (+14°) Elevation Angle: +16.9° Horizon Angle: +00.4° Zoom: 1.0X Staff: 11206+00- Pipe carrying water from water bar across ditch to sump pit</p>				 <p>Date &amp; Time: Wed Jun 16 2021 11:42:14 EDT Position: +037 300936 / -080 504710 (+146.0m) Altitude: 2029ft (+61.8m) Datum: WGS-84 Azimuth/Bearing: 037° N23W 5991mils True (+13°) Elevation Angle: +08.4° Horizon Angle: +08.3° Zoom: 1.0X Staff: 11225+00- Rock channel</p>	
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11206+00		Field Station#	11225+00	
Pic 11 Desc.	Pipe carrying water from water bar across ditch to sump pit.		Pic 12 Desc.	Rock channel.	

<b>A/E</b>	124300137	<b>Date/Time</b>	6/16/2021 4:49 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24681
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	6/17/2021 2:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	71.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Replace worn silt fence	48 Hours	
Silt Fence (Reinforce Filter Fence)	Communication	Re-attach fabric to SSF	48 Hours	
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions



Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	6/17/2021 2:18 PM	<b>Report #</b>	24681
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a regular scheduled VADEQ SWPPP inspection on JNF and private lands at Brush Mountain today. The ROW is currently stable with no erosion located. Slope breakers continue to control stormwater runoff and were found in good condition. Sumps and end treatments are worn but compliant and functional. Resource buffers are stable. Equipment bridge ECDs are attached and functional. Perimeter ECDs are in place although worn in some areas and in need of repair or replacement. I identified 2 ECD maintenance items and 5 ECD replacement needs. The contractor was verbally informed today and will be given a punch list documenting the findings and locations tonight. No resources are in danger of impact in the meantime. RCEs are in good condition. No vandalism was discovered.</p> <p>Punch list items include;</p> <p>Re-attach fabric to chain link SSF          11632+50          11634+25          Replace worn P1          11627+70          11628+15          11658+25          11661+00          11666+00</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/17/2021 2:18 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11666+00	<b>Field Station#</b>	11634+25		
<b>Pic 1 Desc.</b>	Communication. Example of worn P1 to be replaced.	<b>Pic 2 Desc.</b>	Communication. Example of fabric to be re-attached to chain link SSF.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11659+00	<b>Field Station#</b>	11638+00		
<b>Pic 3 Desc.</b>	Perimeter controls in place.	<b>Pic 4 Desc.</b>	Perimeter controls are in place.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11616+04	<b>Field Station#</b>	11614+20		
<b>Pic 5 Desc.</b>	The S-HH18 crossing is stable.	<b>Pic 6 Desc.</b>	The S-RR14 crossing is stable.		



<b>AFE</b>	124300137	<b>Date/Time</b>	6/17/2021 2:18 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, Jun 17, 2021, 10:18:24 EDT Position: +037.313694° / -080.404511° (±98.4ft) Altitude: 1908ft (±105.0ft) Datum: WGS-84 Azimuth/Bearing: 235°/235M (±178mils Magnetic (±12°) Elevation Angle: 13.0° Horizon Angle: 90.7° Zoom: 1.0X 11608+17 S-006 crossing</small></p>		 <p><small>Date &amp; Time: Thu, Jun 17, 2021, 10:21:45 EDT Position: +037.308338° / -080.420459° (±10728.2ft) Altitude: 1917ft (±59.4ft) Datum: WGS-84 Azimuth/Bearing: 105°/215L (1847mils Magnetic (±12°) Elevation Angle: 26.7° Horizon Angle: 90.2° Zoom: 1.0X 11602+00</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11608+17	<b>Field Station#</b>	11602+00		
<b>Pic 7 Desc.</b>	The S-006 crossing is stable.	<b>Pic 8 Desc.</b>	ROW currently stable.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2021 2:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24686
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/17/2021 4:26 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+53
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Replace damaged sock	24 Hours	
Broad-Based Dip	Acceptable			
Culvert	Acceptable			
Rock Construction Entrance	Communication	Regrade AR-266.00	48 Hours	
Silt Fence (Filter Fabric Fence)	Communication	Replace damaged silt fence	24 Hours	
Rock Check Dam	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2021 4:26 PM	<b>Report #</b>	24686
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area: Sta#11788+53 to 12005+00. MP-223.3 to 227.3 The row is dry and in stable condition with very good vegetation. ( Restored row ). There were four punch listed items, three caused by bear and one from weather. (See photos). Perimeter controls are in acceptable condition. Water bars and level spreaders are in good condition. Karst's areas are in good condition, with good vegetation protection. Tabor RCE is maintained in acceptable condition. AR-266.03 is maintained in acceptable condition. AR-266.00- Rock surface washed from recent rain events, item added to the punch list.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time 6/17/2021 4:26 PM		Report #	
Pictures					
<p>Date &amp; Time: Thu Jun 17 2021 08:53:33 EDT Position: +037 234252+ / -080 345865+ (+225.0ft) Altitude: 2137ft (+68.9ft) Datum: WGS-84 Azimuth/Bearing: 100° S00E 3200mils True (+16°) Elevation Angle: +0.8 Horizon Angle: +0.3 Zoom: 1.0x Sta# 11786+53 - Level spreaders</p> 		<p>Date &amp; Time: Thu Jun 17 2021 09:02:45 EDT Position: +037 287254+ / -080 345706+ (+198.2ft) Altitude: 2145ft (+64.0ft) Datum: WGS-84 Azimuth/Bearing: 259° S4°W 3200mils True (+16°) Elevation Angle: +11.5 Horizon Angle: +01.9 Zoom: 1.0x Sta# 11786+00 - Level spreaders - row vegetation</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11788+53		Field Station#	11786+00	
Pic 1 Desc.	Tabor RCE		Pic 2 Desc.	Level spreaders and controls, row vegetation.	
<p>Date &amp; Time: Thu Jun 17 2021 09:19:39 EDT Position: +037 232526+ / -080 350750+ (+135.9ft) Altitude: 2234ft (+67.9ft) Datum: WGS-84 Azimuth/Bearing: 109° S14W 3240mils True (+16°) Elevation Angle: +10.1 Horizon Angle: +00.2 Zoom: 1.0x Sta# 11832+00 - Karst level spreaders perimeter controls</p> 		<p>Date &amp; Time: Thu Jun 17 2021 09:31:09 EDT Position: +037 287254+ / -080 345706+ (+199.0ft) Altitude: 2145ft (+63.0ft) Datum: WGS-84 Azimuth/Bearing: 109° S08W 3289mils True (+14°) Elevation Angle: +03.0 Horizon Angle: +03.6 Zoom: 1.0x Sta# 11846+00 - Row condition: very good vegetation</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11832+00		Field Station#	11846+00	
Pic 3 Desc.	Karst, level spreaders, perimeter controls.		Pic 4 Desc.	Row conditions, and very good vegetation.	
<p>Date &amp; Time: Thu Jun 17 2021 09:46:49 EDT Position: +037 208822+ / -080 344283+ (+59.0ft) Altitude: 2137ft (+52.2ft) Datum: WGS-84 Azimuth/Bearing: 032° N03E 0569mils True (+14°) Elevation Angle: +15.5 Horizon Angle: +01.3 Zoom: 1.0x Sta# 11864+00 - Wetland is muddy, no standing water</p> 		<p>Date &amp; Time: Thu Jun 17 2021 10:18:21 EDT Position: +037 209402+ / -080 320189+ (+43.0ft) Altitude: 2276ft (+67.2ft) Datum: WGS-84 Azimuth/Bearing: 306° NSW 3440mils True (+13°) Elevation Angle: +16.1 Horizon Angle: +04.8 Zoom: 1.0x AR-248-03 - Access road &amp; bar ditch ECD's</p> 			
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11864+00		Field Station#	11900+00	
Pic 5 Desc.	Wetland is muddy but no standing water.		Pic 6 Desc.	Access road and bar ditch ECD's.	





<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2021 4:26 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24677
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	6/17/2021 11:39 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	See comments		
Silt Fence (Reinforced Filter Fabric Fence)	Communication	See comments		
Waterbar End Treatment	Communication	See comments		
Cleanwater Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Housekeeping	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	6/17/2021 11:39 AM	<b>Report #</b>	24677
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 to ST# 11788+52 (MP 221.02 to MP 223.27) Deficiencies found at the following station numbers: 11679+15 Retrench and backfill P1 silt fence 11679+50 Repair/Replace multiple P1 silt fence broken stakes damaged by wildlife 11772+25 Restake CFS triple stack end treatment and repair supersilt perimeter control where it ties into end treatment Environmental crew has been through section of ROW and fixed punch list item #s 880 and 881 since last VA SWPPP inspection P1 silt fence is in place across travel lane of steep slopes before bridges for added protection to streams. Top soil stock piles, clean water diversion berms, and travel lane are stabilized. Waterbars are in place with sump pits and waterbar end treatments. 50' buffers in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCE are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/17/2021 11:39 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11672+00	<b>Field Station#</b>	11686+80		
<b>Pic 1 Desc.</b>	End treatments in place	<b>Pic 2 Desc.</b>	Stream buffer in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11788+00	<b>Field Station#</b>	11771+00		
<b>Pic 3 Desc.</b>	RCE in place	<b>Pic 4 Desc.</b>	Supersilt fence perimeter control in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11719+00	<b>Field Station#</b>	11723+50		
<b>Pic 5 Desc.</b>	P1 silt fence perimeter control in place	<b>Pic 6 Desc.</b>	Good vegetation on topsoil pile		



AFE 124300137		Date/Time	6/17/2021 11:39 AM	Report #	
Pictures					
<p><small>Date &amp; Time: Thu, Jun 17, 2021, 09:58:47 EDT Position: +037.295198 / -080.374258 (+58.30) Altitude: 2119ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 085° N68E 1134mils True (+12°) Elevation Angle: -10.0° Horizon Angle: -00.0° Zoom: 1.0X 11735+00</small></p> 		<p><small>Date &amp; Time: Thu, Jun 17, 2021, 09:54:34 EDT Position: +037.295933 / -080.375841 (+56.2ft) Altitude: 2010ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 221° S41W 3929mils True (+12°) Elevation Angle: -00.4° Horizon Angle: -00.4° Zoom: 1.0X 11740+79</small></p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11735+00		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		Waterbars in place		<b>Pic 8 Desc.</b>	
<p><small>Date &amp; Time: Thu, Jun 17, 2021, 09:58:39 EDT Position: +037.296138 / -080.369383 (+29.0ft) Altitude: 2123ft (+19.4ft) Datum: WGS-84 Azimuth/Bearing: 153° S27E 2720mils True (+12°) Elevation Angle: -14.2° Horizon Angle: -00.3° Zoom: 1.0X 11752+00</small></p> 		<p><small>Date &amp; Time: Thu, Jun 17, 2021, 10:11:11 EDT Position: +037.296073 / -080.365023 (+18.3ft) Altitude: 2046ft (+15.3ft) Datum: WGS-84 Azimuth/Bearing: 184° S71E 1847mils True (+12°) Elevation Angle: -41.3° Horizon Angle: -11.3° Zoom: 1.0X 11772+25</small></p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11752+00		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		CFS perimeter control in place		<b>Pic 10 Desc.</b>	
<p><small>Date &amp; Time: Thu, Jun 17, 2021, 09:58:05 EDT Position: +037.300264 / -080.393016 (+19.5ft) Altitude: 2623ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 162° S02W 3238mils True (+12°) Elevation Angle: -23.8° Horizon Angle: -00.9° Zoom: 1.0X 11679+50</small></p> 		<p><small>Date &amp; Time: Thu, Jun 17, 2021, 09:01:33 EDT Position: +037.301052 / -080.383017 (+24.9ft) Altitude: 2607ft (+24.2ft) Datum: WGS-84 Azimuth/Bearing: 201° S30W 3632mils True (+12°) Elevation Angle: -16.5° Horizon Angle: -00.5° Zoom: 1.0X 11679+15</small></p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11679+50		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		Multiple broken stakes		<b>Pic 12 Desc.</b>	
				Dirt washed out exposing P1 silt fence flap	



<b>A/E</b>	124300137	<b>Date/Time</b>	6/17/2021 11:39 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24709
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/18/2021 10:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	66.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 10:40 AM	<b>Report #</b>	24709
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area- LY-28 West portion of the yard. RCE is in acceptable condition. Trucks, buses and trailers currently not in use are stored here. This portion of the yard sees very little use. East portion of the yard. This portion of the yard is more heavily used, trucks are mostly out during work hours. Truck drivers personal vehicles are parked here during the day. Waste management is acceptable. House keeping is acceptable. Rock surface of the yard is acceptable. CFS perimeter controls are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/18/2021 10:40 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri Jun 18, 2021, 10:56:55 EDT Position: +4373.33603° / +480.83630° (+28.3m) Altitude: 1539ft (+43.2m) Datum: WGS-84 Azimuth/Bearing: 258° S78W 4387mils True (±68°) Elevation Angle: +11.5° Horizon Angle: -05.4° Zoom: 1.0X LY-28- West portion of the yard- RCE</p>		 <p>Date &amp; Time: Fri Jun 18, 2021, 10:58:01 EDT Position: +4373.33603° / +480.83630° (+28.3m) Altitude: 1539ft (+43.2m) Datum: WGS-84 Azimuth/Bearing: 019° N19E 0338mils True (±55°) Elevation Angle: -07.5° Horizon Angle: -05.4° Zoom: 1.0X LY-28- West portion of the yard- Buses trucks stored here.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	LY-28- west portion of the yard- RCE	<b>Pic 2 Desc.</b>	LY-28- West portion of the yard- Buses and trucks stored, not currently in use.		
 <p>Date &amp; Time: Fri Jun 18, 2021, 11:05:20 EDT Position: +4373.33603° / +480.83630° (+28.3m) Altitude: 1539ft (+43.2m) Datum: WGS-84 Azimuth/Bearing: 170° S170W 5991mils True (±180°) Elevation Angle: -09.0° Horizon Angle: -05.4° Zoom: 1.0X LY-28- West portion of the yard- Trailers stored, currently not in use.</p>		 <p>Date &amp; Time: Fri Jun 18, 2021, 11:10:13 EDT Position: +4373.33603° / +480.83630° (+28.3m) Altitude: 1539ft (+43.2m) Datum: WGS-84 Azimuth/Bearing: 320° N29W 5991mils True (±180°) Elevation Angle: -09.0° Horizon Angle: -05.4° Zoom: 1.0X LY-28- East portion of the yard- CFS perimeter controls at the entrance.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY-28- West portion of the yard- Trailers not in use stored here.	<b>Pic 4 Desc.</b>	LY-28- East portion of the yard- CFS perimeter controls at yard entrance.		
 <p>Date &amp; Time: Fri Jun 18, 2021, 11:16:45 EDT Position: +4373.33603° / +480.83630° (+28.3m) Altitude: 1539ft (+43.2m) Datum: WGS-84 Azimuth/Bearing: 161° S01W 3218mils True (±180°) Elevation Angle: -09.0° Horizon Angle: -02.3° Zoom: 1.0X LY-28- East portion of the yard- Waste containers.</p>		 <p>Date &amp; Time: Fri Jun 18, 2021, 11:16:45 EDT Position: +4373.33603° / +480.83630° (+28.3m) Altitude: 1539ft (+43.2m) Datum: WGS-84 Azimuth/Bearing: 200° S20W 3556mils True (±180°) Elevation Angle: -06.2° Horizon Angle: -00.4° Zoom: 1.0X LY-28- East portion of the yard- Trucks &amp; trailers not in use parked.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	LY-28- East portion of the yard- Waste containers.	<b>Pic 6 Desc.</b>	LY-28- East portion of the yard- Trucks and trailers not in use today parked.		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 10:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>AFE</b>	124300137	<b>Date/Time</b>	6/18/2021 10:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24713
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	6/18/2021 11:09 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11600+01
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Cleanwater Diversion Berm	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 11:09 AM	<b>Report #</b>	24713
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to MP 219.70) No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. ROW is dry and in stable condition up until JNF property line ST# 11553+66. Environmental crew has been through section of ROW since last VA SWPPP inspection and completed punch list item #s 850-868, 882, and 883. This section of the ROW has been backfilled and restored to subgrade. Topsoil piles are stabilized. Waterbars with end treatments are in place. ROW is dry and stabilized throughout JNF with large areas of vegetation. No crews actively working in JNF. Waterbars with end treatments and perimeter controls are in place. 50' buffers are in place at stream crossings S-PP22, S-PP21, S-PP20. AR-258.02 and Craig Creek road crossing RCE are maintained in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	6/18/2021 11:09 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11527+00	<b>Field Station#</b>	11543+00		
<b>Pic 1 Desc.</b>	Clean water drainage feature in place	<b>Pic 2 Desc.</b>	End treatments in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11569+00	<b>Field Station#</b>	11558+00		
<b>Pic 3 Desc.</b>	ECDs in place	<b>Pic 4 Desc.</b>	Waterbars in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11585+50	<b>Field Station#</b>	11592+00		
<b>Pic 5 Desc.</b>	Stream buffer in place	<b>Pic 6 Desc.</b>	P1 silt fence perimeter control in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 11:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 11:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24714
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/18/2021 11:24 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 11:24 AM	<b>Report #</b>	24714
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area: LY-29 LY-29 is used for all things pipeline welding. AR-238.00 and RCE are maintained in acceptable condition. CFS triple stack perimeter controls are in acceptable condition. Waste management is acceptable. House keeping is acceptable. Signage is visible. Culvert and drainage feature are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/18/2021 11:24 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Jun 18, 2021, 11:46:56 EDT Position: +037.344197° / -080.672122° (+53.0ft) Altitude: 1798ft (+78.5ft) Datum: WGS-84 Azimuth/Bearing: 264.564W 4338mils True (+78°) Elevation Angle: -07.8° Horizon Angle: -01.9° Zoom: 1.0X LY-29- AR-238.00 Access road and RCE serving LY-29</p>		 <p>Date &amp; Time: Fri, Jun 18, 2021, 11:50:02 EDT Position: +037.3438160° / -080.675000° (+54.0ft) Altitude: 1842ft (+82.0ft) Datum: WGS-84 Azimuth/Bearing: 406° S64W 4020mils True (+74°) Elevation Angle: -00.0° Horizon Angle: +00.0° Zoom: 1.0X LY-29- Overview of the yard.</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	LY-29- AR-238.00 access road and RCE serving LY-29	<b>Pic 2 Desc.</b>	LY-29 Overview of the yard.		
 <p>Date &amp; Time: Fri, Jun 18, 2021, 11:56:16 EDT Position: +037.362222° / -080.677379° (+14.7ft) Altitude: 1710ft (+39.3ft) Datum: WGS-84 Azimuth/Bearing: 342° N11W 6204mils True (+20°) Elevation Angle: -12.9° Horizon Angle: +01.3° Zoom: 1.0X LY-29- Triple stack perimeter controls</p>		 <p>Date &amp; Time: Fri, Jun 18, 2021, 11:56:08 EDT Position: +037.362328° / -080.677293° (+9.5ft) Altitude: 1710ft (+25.0ft) Datum: WGS-84 Azimuth/Bearing: 076° N34E 1318mils True (+20°) Elevation Angle: -29.4° Horizon Angle: +02.1° Zoom: 1.0X LY-29- Culvert and drainage feature</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY-29- CFS triple stack perimeter controls and signage.	<b>Pic 4 Desc.</b>	LY-29- Culvert and drainage feature.		
 <p>Date &amp; Time: Fri, Jun 18, 2021, 11:58:19 EDT Position: +037.362357° / -080.677393° (+11.0ft) Altitude: 1710ft (+26.9ft) Datum: WGS-84 Azimuth/Bearing: 127° S30E 2260mils True (+20°) Elevation Angle: -05.9° Horizon Angle: -00.4° Zoom: 1.0X LY-29- Waste containers with placards</p>		 <p>Date &amp; Time: Fri, Jun 18, 2021, 12:01:19 EDT Position: +037.363291° / -080.676691° (+31.5ft) Altitude: 1711ft (+25.9ft) Datum: WGS-84 Azimuth/Bearing: 344° N64W 5000mils True (+30°) Elevation Angle: -07.5° Horizon Angle: +00.0° Zoom: 1.0X LY-29- Parking for workers associated with welding</p>			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	LY-29- Waste containers with placards.	<b>Pic 6 Desc.</b>	LY -29- Parking for workers associated with welding.		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 11:24 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 11:24 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	24708
<b>Inspector</b>	Len Kruizenga			<b>Date/Time</b>	6/18/2021 10:06 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	66.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			
Secondary Containment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 10:06 AM	<b>Report #</b>	24708
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
SWPPP inspection area: LY26 Secondary containment units are maintained in acceptable condition. Rock surface of the yard is in acceptable condition. Spill kits, fire extinguishers, signage placed around the yard. Waste management is acceptable House keeping is acceptable. CFS triple stack perimeter controls are in acceptable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	6/18/2021 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri Jun 18, 2021 10:18:03 EDT  Position: +037 318437 / -080 655691 (±15.4ft)  Altitude: 1798ft (±27.5ft)  Datum: WGS-84  Azimuth/Bearing: 199° S19W 3538mils True (±22°)  Elevation Angle: -21.1°  Horizon Angle: +00.3°  Zoom: 1.0X  LY-26- CFS triple stack perimeter controls.</p> 		<p>Date &amp; Time: Fri Jun 18, 2021 10:20:55 EDT  Position: +037 318407 / -080 657331 (±15.4ft)  Altitude: 1795ft (±24.5ft)  Datum: WGS-84  Azimuth/Bearing: 256° S74W 4516mils True (±48°)  Elevation Angle: -00.8°  Horizon Angle: +00.7°  Zoom: 1.0X  LY-26- Tote containing fuel additive and light plant in secondary containment.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	LY-26- CFS triple stack perimeter controls.	<b>Pic 2 Desc.</b>	LY-26- Tote containing fuel additive and light plant in secondary containment.		
<p>Date &amp; Time: Fri Jun 18, 2021 10:23:39 EDT  Position: +037 318548 / -080 657349 (±12.2ft)  Altitude: 1796ft (±24.8ft)  Datum: WGS-84  Azimuth/Bearing: 001° N01E 0018mils True (±18°)  Elevation Angle: +02.0°  Horizon Angle: -01.5°  Zoom: 1.0X  LY-26- Spill kit, fire extinguisher, signage at main fuel tank.</p> 		<p>Date &amp; Time: Fri Jun 18, 2021 10:27:20 EDT  Position: +037 318436 / -080 657330 (±19.1ft)  Altitude: 1793ft (±26.7ft)  Datum: WGS-84  Azimuth/Bearing: 289° N72W 5120mils True (±32°)  Elevation Angle: -00.3°  Horizon Angle: -00.1°  Zoom: 1.0X  LY-26- main fuel tank in secondary containment.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	LY-26- Spill kits, fire extinguishers, signage visible	<b>Pic 4 Desc.</b>	LY-26- Main fuel tank in secondary containment.		
<p>Date &amp; Time: Fri Jun 18, 2021 10:30:15 EDT  Position: +037 318397 / -080 657462 (±15.1ft)  Altitude: 1791ft (±24.3ft)  Datum: WGS-84  Azimuth/Bearing: 217° S37W 3858mils True (±19°)  Elevation Angle: -05.4°  Horizon Angle: +00.0°  Zoom: 1.0X  LY-26- Gas cylinders secured and placarded.</p> 		<p>Date &amp; Time: Fri Jun 18, 2021 10:33:01 EDT  Position: +037 318547 / -080 657516 (±14.2ft)  Altitude: 1791ft (±28.8ft)  Datum: WGS-84  Azimuth/Bearing: 232° S52W 4124mils True (±48°)  Elevation Angle: -05.5°  Horizon Angle: -00.4°  Zoom: 1.0X  LY-26- waste containers for different types of waste.</p> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	LY-26- Gas cylinders secured and placarded.	<b>Pic 6 Desc.</b>	LY-26- Waste containers for the different types of waste.		

<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	6/18/2021 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		