



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24794
Inspector	John White			Date/Time	6/21/2021 10:17 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Dry	Temperature (°F)	82.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Contractor is working on repairs			
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Contractor is working on repairs			
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/21/2021 10:17 AM	Report #	24794
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/21/2021 10:17 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15584+23	Field Station#	15591+00		
Pic 1 Desc.	Observing road crossing and RCE's	Pic 2 Desc.	Observing temporary stabilization and water bar		
GPS Location	O	GPS Location	O		
Field Station#	15599+00	Field Station#	15609+00		
Pic 3 Desc.	Observing temporary stabilization and sump	Pic 4 Desc.	Observing P1 that requires maintenance (damaged by wildlife)		
GPS Location	O	GPS Location	O		
Field Station#	15620+00	Field Station#	15630+00		
Pic 5 Desc.	Observing P1 that requires maintenance	Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's		

AFE	124300139	Date/Time	6/21/2021 10:17 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15632+00	Field Station#	15636+45		
Pic 7 Desc.	Observing temporary stabilization, erosion control blanket and CFS checks.		Pic 8 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	
GPS Location	O	GPS Location	O		
Field Station#	15640+00	Field Station#	15645+39		
Pic 9 Desc.	Observing P1 that requires maintenance		Pic 10 Desc.	Observing CFS that requires maintenance. (3rd party damage)	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/21/2021 10:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24795
Inspector	Charles Head			Date/Time	6/21/2021 10:47 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/21/2021 10:47 AM	Report #	24795
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/21/2021 10:47 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14314+00	Field Station#	14333+50		
Pic 1 Desc.	Approximately 14314+00. Overview of ROW.	Pic 2 Desc.	Approximately 14333+50. Overview of road crossing and RCEs.		
					
GPS Location	0	GPS Location	0		
Field Station#	14347+00	Field Station#	14391+50		
Pic 3 Desc.	Approximately 14347+00. Overview of ROW.	Pic 4 Desc.	Approximately 14391+50. Overview of stream crossing, equipment bridge and ECDs at stream S-A41.		
					
GPS Location	0	GPS Location	0		
Field Station#	14396+00	Field Station#	14452+00		
Pic 5 Desc.	Approximately 14396+00. Overview of ROW.	Pic 6 Desc.	Approximately 14452+00. Overview of ROW.		

A/E	124300139	Date/Time	6/21/2021 10:47 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/21/2021 10:47 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24802
Inspector	Ben Farmer			Date/Time	6/21/2021 1:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	92.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)		Communication	P1 has been damaged and needs to be replaced	Addressed	6/21/2021
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Rock Filter		Acceptable			
Rock Filter Outlet		Acceptable			
Slope Drain Pipe		Acceptable			
Waterbar		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	6/21/2021 1:13 PM	Report #	24802
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 92 F) Rain Gauge= 0.0" 15142+66-15260+00 -EI began inspection at Rockcreek. -RCEs are in good condition at all road crossings. -P1 has been damaged and needs to be restaked at 15159+07. Environmental crew has corrected this issue. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00. -P1 is in good condition at all stream and wetland crossings. -Equipment bridge ECDs are in place and functioning. -Waterbars are in good condition throughout this section. -Slope drain is functioning as intended at 15170+00. -Drainage ECDs are in good condition at 15195+00. -Fence gap remains open by 3rd party allowing livestock onto ROW at 15195+50. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/21/2021 1:13 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15159+07		Field Station#	15159+07	
Pic 1 Desc.	P1 has been damaged and needs to be restaked.		Pic 2 Desc.	Environmental crew has corrected this issue.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15142+66		Field Station#	15165+57	
Pic 3 Desc.	RCEs are in good condition at all road crossings.		Pic 4 Desc.	Rock inlet remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15166+00		Field Station#	15167+95	
Pic 5 Desc.	Rock outlet remains in good condition.		Pic 6 Desc.	P1 is in good condition at all stream and wetland buffers.	

A/E	124300139	Date/Time	6/21/2021 1:13 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15167+95		Field Station#	15170+00	
Pic 7 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 8 Desc.	Waterbars are in good condition throughout this section.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15195+00	
Pic 9 Desc.	Slope drain is functioning as intended.		Pic 10 Desc.	Drainage ECDs are in good condition and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15195+50		Field Station#	15232+00	
Pic 11 Desc.	Fence gap remains open by 3rd party allowing livestock onto ROW.		Pic 12 Desc.	Vegetation continues to fill in throughout this section of ROW.	

A/E	124300139	Date/Time	6/21/2021 1:13 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location			
Field Station#	15260+00	Field Station#			
Pic 13 Desc.	Vegetation continues to fill in throughout this section of ROW.	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24796
Inspector	Justin Burch			Date/Time	6/21/2021 10:52 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Dry	Temperature (°F)	92.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)	Communication	Silt fence was repaired/replaced		Immediate	6/21/2021
Compost Filter Sock	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
Equipment Bridge	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/21/2021 10:52 AM	Report #	24796
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). An Environmental Straw Foreman from Precision walked with the EI on his inspection. Three issues were submitted for the punch list including one location where P1 silt fence had holes from unknown means, and two locations where P1 silt fence with holes at the ground line from wildlife damage. These items were repaired immediately by the contractor. Other inspected ECDs were in compliance at the time of inspection. The EI observed that the contractor has worked in the inspection area since the last SWPPP inspection and addressed punch list items submitted at that inspection. Since the last SWPPP inspection the area has not received any rainfall events. The ROW ground condition is dry. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13940+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/21/2021 10:52 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	13956+00	Field Station#	13956+00		
Pic 1 Desc.	P1 silt fence has holes in it, contractor addressed it immediately		Pic 2 Desc.	P1 silt fence after replacement	
GPS Location	0	GPS Location	0		
Field Station#	13903+00	Field Station#	13903+00		
Pic 3 Desc.	P1 silt fence with a hole at ground line, damaged by wildlife, contractor repaired immediately		Pic 4 Desc.	P1 silt fence after repair	
GPS Location	0	GPS Location	0		
Field Station#	13902+75	Field Station#	13902+75		
Pic 5 Desc.	P1 silt fence with a hole at ground line, damaged by wildlife, contractor repaired immediately		Pic 6 Desc.	P1 silt fence after repair	

AFE	124300139	Date/Time	6/21/2021 10:52 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13913+00	Field Station#	13889+00		
Pic 7 Desc.	Perimeter CFS in acceptable condition	Pic 8 Desc.	P1 silt fence in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	13861+00	Field Station#	13875+50		
Pic 9 Desc.	Waterbar in acceptable condition	Pic 10 Desc.	Equipment bridge in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	13859+00	Field Station#	13903+00		
Pic 11 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 12 Desc.	Permanent vegetative stabilization in acceptable condition		







A/E	124300139	Date/Time	6/21/2021 10:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24852
Inspector	Ben Farmer			Date/Time	6/22/2021 12:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Damp	Temperature (°F)	74.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/22/2021 12:21 PM	Report #	24852
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 74F) Rain Gauge= 0.0" 15260+00-15370+62 -EI began inspection at Snowberry Rd. -RCEs are in good condition at all road crossings. -MVP-PI-332 remains in good condition with controls in place. -P1 is in good condition at all stream and wetland crossings. -Equipment bridge ECDs are in place and functioning. -CWDs are functioning as intended. -Waterbars are in good condition throughout this section. -P1 remains in good condition around wetland buffer at 15311+78. -CFS is in good condition. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/22/2021 12:21 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15370+00		Field Station#	15350+00	
Pic 1 Desc.	Vegetation continues to fill in throughout this section of ROW.		Pic 2 Desc.	MVP-PI-332 remains in good condition with controls in place.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15346+90		Field Station#	15346+20	
Pic 3 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 4 Desc.	P1 is in good condition at all stream and wetland buffers.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15344+13		Field Station#	15338+00	
Pic 5 Desc.	Waterbars are in good condition in this area.		Pic 6 Desc.	CWDs are functioning as intended.	

AFE	124300139	Date/Time	6/22/2021 12:21 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15325+00		Field Station#	15323+24	
Pic 7 Desc.	Vegetation continues to fill in throughout this area.		Pic 8 Desc.	RCEs are in good condition at all road crossings.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15311+78		Field Station#	15310+00	
Pic 9 Desc.	P1 is in good condition around wetland.		Pic 10 Desc.	CFS is in good condition.	
		<p>Insert image here</p>			
GPS Location	See photo		GPS Location		
Field Station#	15299+00		Field Station#		
Pic 11 Desc.	CWD is functioning as intended.		Pic 12 Desc.		

A/E	124300139	Date/Time	6/22/2021 12:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24845
Inspector	John White			Date/Time	6/22/2021 9:55 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Dry	Temperature (°F)	78.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Contractor is working on repairs			
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/22/2021 9:55 AM	Report #	24845
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. There was one issue identified and repaired upon discovery by the Contractor. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/22/2021 9:55 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15678+57	Field Station#	15665+00		
Pic 1 Desc.	Observing P1 that requires maintenance (3rd party damage)	Pic 2 Desc.	Observing P1 that required maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15665+00	Field Station#	15693+80		
Pic 3 Desc.	Observing P1 that received maintenance	Pic 4 Desc.	Observing RCE and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15770+00	Field Station#	15764+50		
Pic 5 Desc.	Observing temporary vegetation	Pic 6 Desc.	Observing temporary vegetation, sump and end treatment		

AFE	124300139	Date/Time	6/22/2021 9:55 AM	Report #	
Pictures					
		Insert image here			
GPS Location	O				
Field Station#	15763+80	Field Station#			
Pic 7 Desc.	Observing signage, buffer, equipment crossing and ECD's	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/22/2021 9:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24867
Inspector	Charles Head			Date/Time	6/22/2021 4:12 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Damp	Temperature (°F)	78.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/22/2021 4:12 PM	Report #	24867
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/22/2021 4:12 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14456+50	Field Station#	14530+00		
Pic 1 Desc.	Approximately 14456+50. Overview of ROW.	Pic 2 Desc.	Approximately 14530+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14524+50	Field Station#	14520+00		
Pic 3 Desc.	Approximately 14524+50. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14520+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14542+00	Field Station#	14546+33		
Pic 5 Desc.	Approximately 14542+00. Overview of ROW.	Pic 6 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.		

A/E	124300139	Date/Time	6/22/2021 4:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/22/2021 4:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24849
Inspector	Justin Burch			Date/Time	6/22/2021 10:55 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Wet	Temperature (°F)	78.00
Municipality	N/A	Weather	Heavy Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	6/22/2021 10:55 AM	Report #	24849
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). The contractor had an Environmental Straw Foreman walk with the EI on his inspection. No issues were submitted for the punch because inspected ECDs were found to be in compliance at the time of inspection. The EI did not observe that the contractor has worked in the inspection area since the last inspection. Since the last SWPPP inspection the area has not received a rainfall event except that rain began this morning and the rain gauges will be read tomorrow. The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14011+00 to 14018+00. At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/22/2021 10:55 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	13969+00	Field Station#	13969+00		
Pic 1 Desc.	Waterbar in acceptable condition		Pic 2 Desc.	Waterbar end treatment in acceptable condition	
GPS Location	0	GPS Location	0		
Field Station#	14029+00	Field Station#	14052+00		
Pic 3 Desc.	Perimeter CFS in acceptable condition		Pic 4 Desc.	Super silt fence in acceptable condition	
GPS Location	0	GPS Location	0		
Field Station#	14050+00	Field Station#	14018+00		
Pic 5 Desc.	Equipment bridge in acceptable condition		Pic 6 Desc.	Permanent vegetative stabilization in acceptable condition	

A/E	124300139	Date/Time	6/22/2021 10:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	







A/E	124300139	Date/Time	6/22/2021 10:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		








Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24822
Inspector	Frank Craycroft			Date/Time	6/21/2021 10:23 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Full	Station End	14802+19
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	CFS @ SN 14750+50 needs repairs	Addressed	6/21/2021	
Erosion Control Blanket	Acceptable				
Plunge Pool	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/21/2021 10:23 PM	Report #	24822
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection between Jacks Creek Rd and access road MVP-FR-323. Vegetation was generally fair to moderate but other stabilizing mediums were still effective. No significant signs of erosion were observed. CFS along travel lane near SN 14750+50 had several holes in it, apparently from wildlife damage. Crew repaired area today. Otherwise all ECDs observed were functional and in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/21/2021 10:23 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14802+00	Field Station#	14792+00		
Pic 1 Desc.	ATWS stabilization	Pic 2 Desc.	Perimeter CFS and sump		
					
GPS Location	0	GPS Location	0		
Field Station#	14783+00	Field Station#	14767+50		
Pic 3 Desc.	GAS S-MM48 Travel lane	Pic 4 Desc.	S-MM44 Buffer zone		
					
GPS Location	0	GPS Location	0		
Field Station#	14754+00	Field Station#	14750+50		
Pic 5 Desc.	Travel lane stabilization	Pic 6 Desc.	Damaged CFS along travel lane.		

AFE	124300139	Date/Time	6/21/2021 10:23 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14742+00	Field Station#	14712+00		
Pic 7 Desc.	Plunge pool	Pic 8 Desc.	SSF and stabilization		
					
GPS Location	0	GPS Location	0		
Field Station#	14701+00	Field Station#	14695+00		
Pic 9 Desc.	S-H32 Buffer zone	Pic 10 Desc.	GAS Jacks Creek Rd RCE & ATWS		
		Insert image here			
GPS Location	0	GPS Location			
Field Station#	14711+50	Field Station#			
Pic 11 Desc.	Perimeter CFS	Pic 12 Desc.			

A/E	124300139	Date/Time	6/21/2021 10:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24879
Inspector	Ben Davenport			Date/Time	6/22/2021 8:39 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Wet	Temperature (°F)	72.00
Municipality	N/A	Weather	Heavy Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Culvert	Acceptable			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Rock Construction Entrance	Acceptable			
Temporary Diversion Berm	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	6/22/2021 8:39 AM	Report #	24879
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Heavy rain with wet ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14802+19 — 14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Checked environmental hot spots during rain event -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings -Observed condition of vegetation in section both permanent and temporary areas of ROW -Continue to monitor ROW for signs of erosion -No items added to punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/22/2021 8:39 AM	Report #	
Pictures					
					
36°58'20" N 79°39'55" W 90°E COURSE 97° GPS 1120 Listening Hill Rd, Penhook, VA 24137, United States 06.22.2021 13:08:23 Accur +/-15.4 Ft ALT 1000 Ft			36°58'20" N 79°39'55" W 144°SE COURSE 141° GPS 1120 Listening Hill Rd, Penhook, VA 24137, United States 06.22.2021 13:08:19 Accur +/-15.3 Ft ALT 989 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14838+00		Field Station#	14846+00	
Pic 1 Desc.	ROW stabilized and vegetated in temporary area.		Pic 2 Desc.	Spoil pile stabilized and vegetated.	
					
36°58'17" N 79°39'37" W 211°SW COURSE -1° GPS 2201 Bar Ridge Rd, Penhook, VA 24137, United States 06.22.2021 13:04:27 Accur +/-16.3 Ft ALT 988 Ft			36°58'18" N 79°39'37" W 13°N COURSE 107° GPS 2201 Bar Ridge Rd, Penhook, VA 24137, United States 06.22.2021 13:04:10 Accur +/-126.8 Ft ALT 879 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14861+31		Field Station#	14858+00	
Pic 3 Desc.	Culvert at road crossing in good condition.		Pic 4 Desc.	ROW stabilized in temporary area. Goalposts visible and I'm good condition at line crossings of ROW.	
					
36°58'4" N 79°38'18" W 78°E COURSE 296° GPS 2019 Ramsey Memorial Rd, Penhook, VA 24137, United States 06.22.2021 12:56:14 Accur +/-25.3 Ft ALT 881 Ft			36°58'4" N 79°38'17" W 168°S COURSE -1° GPS 2019 Ramsey Memorial Rd, Penhook, VA 24137, United States 06.22.2021 12:56:01 Accur +/-25.3 Ft ALT 879 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14925+00		Field Station#	14928+00	
Pic 5 Desc.	ROW vegetated in final cleanup area. Perimeter CFS in place and functional.		Pic 6 Desc.	ROW stabilized and vegetated in extra workspace. Goalposts in place and functional .	

A/E	124300139	Date/Time	6/22/2021 8:39 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/22/2021 8:39 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24905
Inspector	Logan Box			Date/Time	6/23/2021 4:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Damp	Temperature (°F)	76.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.70
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sump Pit	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Timber Mat	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2021 4:41 PM	Report #	24905
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/23/2021 4:41 PM	Report #	
Pictures					
	East Elevation <small>301°W (T) 37.087593, -79.949434 ±3 m ▲ 314 m</small> 			South Elevation <small>24°N (T) 37.082925, -79.946062 ±3 m ▲ 308 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13681+50	Field Station#	13702+70		
Pic 1 Desc.	Row photo showing equipment mats in place and good vegetation coverage.		Pic 2 Desc.	Monitored sump pit and end treatment while conducting row inspection. No issues observed at the time of inspection	
	South East Elevation <small>336°NW (T) 37.082887, -79.945687 ±7 m ▲ 303 m</small> 			North West Elevation <small>145°SE (T) 37.082959, -79.945606 ±6 m ▲ 311 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13704+90	Field Station#	13704+90		
Pic 3 Desc.	Stream observation photo facing upstream during routine inspection today. No issues observed at the time of inspection		Pic 4 Desc.	Stream observation photo facing downstream during routine inspection today. No issues observed at the time of inspection.	
	West Elevation <small>88°E (T) 37.082907, -79.945826 ±4 m ▲ 310 m</small> 			East Elevation <small>266°W (T) 37.08832, -79.94976 ±5 m ▲ 308 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13704+80	Field Station#	13678+89		
Pic 5 Desc.	Stream crossing monitored . No environmental issues observed at the time of inspection.		Pic 6 Desc.	Photo taken showing stream crossing with vegetation. Ecds in place and functioning at the time of inspection.	

A/E	124300139	Date/Time	6/23/2021 4:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/23/2021 4:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24925
Inspector	Charles Head			Date/Time	6/23/2021 3:38 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Damp	Temperature (°F)	78.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
Housekeeping	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2021 3:38 PM	Report #	24925
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/23/2021 3:38 PM	Report #	
Pictures					
GPS Location		0		GPS Location	
Field Station#		14582+85		Field Station#	
Pic 1 Desc.		Approximately 14582+85. Overview of stream crossing, equipment bridge and ECDs at stream S-E17.		Pic 2 Desc.	
GPS Location		0		GPS Location	
Field Station#		14548+00		Field Station#	
Pic 3 Desc.		Approximately 14548+00. Overview of ROW.		Pic 4 Desc.	
GPS Location		0		GPS Location	
Field Station#		14599+00		Field Station#	
Pic 5 Desc.		Approximately 14599+00. Overview of road crossing and RCEs.		Pic 6 Desc.	

A/E	124300139	Date/Time	6/23/2021 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/23/2021 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24914
Inspector	Ben Farmer			Date/Time	6/23/2021 1:29 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Damp	Temperature (°F)	65.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to be replaced	Addressed	6/23/2021
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Rock Filter	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300139	Date/Time	6/23/2021 1:29 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15425+00		Field Station#	15425+00	
Pic 1 Desc.	P1 has been damaged and needs to be replaced.		Pic 2 Desc.	Environmental crew has corrected this issue.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15475+00		Field Station#	15456+00	
Pic 3 Desc.	Rock outlet is in good condition within this drainage.		Pic 4 Desc.	No evidence of sedimentation from 3rd party rock outlet.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15460+81		Field Station#	15460+81	
Pic 5 Desc.	CWD inlet in good condition. No evidence of sedimentation from 3rd party disturbance.		Pic 6 Desc.	CWD in good condition.	

AFE	124300139	Date/Time	6/23/2021 1:29 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15457+00		Field Station#	15453+00	
Pic 7 Desc.	Drainage in good condition. No evidence of sedimentation from 3rd party disturbance.		Pic 8 Desc.	CWD in good condition condition. No evidence of sedimentation from 3rd party disturbance.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15445+00		Field Station#	15427+31	
Pic 9 Desc.	Vegetation continues to fill in throughout this section of ROW.		Pic 10 Desc.	Reinforced P1 remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15427+30		Field Station#	15400+00	
Pic 11 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 12 Desc.	Vegetation continues to fill in throughout this section of ROW.	







A/E	124300139	Date/Time	6/23/2021 1:29 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15385+00	Field Station#	15383+00		
Pic 13 Desc.	Sensitive resource buffer is in good condition.	Pic 14 Desc.	Waterbars are functioning as intended.		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	15375+00	Field Station#			
Pic 15 Desc.	Drainage ECDs are in good condition and functioning.	Pic 16 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24910
Inspector	Justin Burch			Date/Time	6/23/2021 11:14 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Wet	Temperature (°F)	77.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.60
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Plunge Pool	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2021 11:14 AM	Report #	24910
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). An Environmental Straw Foreman from Precision walked with the EI on his inspection. Inspected ECDs were found to be in compliance at the time of inspection so no issues were submitted for the punch. • The EI observed that the contractor has worked in the inspection area since the last SWPPP inspection addressing punch list items from that inspection. • Since the last SWPPP inspection the area has received one rainfall event totaling 0.60" at Bonbrook Mill Road #1 and 0.50" at Farm View Road. • The ROW ground condition is damp. • At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. • At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/23/2021 11:14 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14077+00	Field Station#	14069+00		
Pic 1 Desc.	Temporary vegetative stabilization in acceptable condition		Pic 2 Desc.	Clean water diversion plunge pool in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14109+50	Field Station#	14109+50		
Pic 3 Desc.	Waterbar in acceptable condition		Pic 4 Desc.	Waterbar end treatment in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14162+00	Field Station#	14163+00		
Pic 5 Desc.	Perimeter CFS in acceptable condition		Pic 6 Desc.	Permanent vegetative stabilization in acceptable condition	

A/E	124300139	Date/Time	6/23/2021 11:14 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/23/2021 11:14 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24881
Inspector	Ben Davenport			Date/Time	6/23/2021 9:09 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Muddy	Temperature (°F)	76.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Sediment Filter Log	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	6/23/2021 9:09 AM	Report #	24881
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Checked rain gauges in covered area -Received instruction from Lead EI for daily tasks -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14928+52 — 15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list -Indian Cave Rd rain gauge: 0.50 inches recorded -Armstrong Rd rain gauge: 0.50 inches recorded 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/23/2021 9:09 AM	Report #	
Pictures					
					
36°58'3" N 79°38'13" W 2°N COURSE 0° GPS 2082 Ramsey Memorial Rd, Penhook, VA 24137, United States 06.23.2021 07:49:02 Accur +/-43.3 Ft ALT 0 Ft			36°58'2" N 79°38'7" W 353°N COURSE 95° GPS Sorry no results found 06.23.2021 07:53:05 Accur +/-372.3 Ft ALT 840 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14931+00	Field Station#	14937+00		
Pic 1 Desc.	ROW stabilized in temporary area and water bars performing intended functions		Pic 2 Desc.	CWD drain tile performing intended function	
					
36°58'1" N 79°38'1" W 35°NE COURSE 99° GPS Sorry no results found 06.23.2021 07:55:43 Accur +/-32.4 Ft ALT 824 Ft			36°57'53" N 79°37'2" W 66°NE COURSE 101° GPS Penhook, VA 24137, United States 06.23.2021 08:23:28 Accur +/-97.5 Ft ALT 854 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14941+50	Field Station#	14990+00		
Pic 3 Desc.	ROW stabilized in temporary area. Limited vegetation observed		Pic 4 Desc.	Contractor replaced CFS check dams per punch list item	
					
36°57'52" N 79°36'52" W 142°SE COURSE 101° GPS Penhook, VA 24137, United States 06.23.2021 08:28:53 Accur +/-128.4 Ft ALT 854 Ft			36°57'56" N 79°36'17" W 285°W COURSE 92° GPS Sorry no results found 06.23.2021 08:44:07 Accur +/-138.2 Ft ALT 922 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14999+00	Field Station#	15027+97		
Pic 5 Desc.	Perimeter CFS triple stack and perimeter SSF performing intended functions		Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional	

A/E	124300139	Date/Time	6/23/2021 9:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/23/2021 9:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24908
Inspector	John White			Date/Time	6/23/2021 10:20 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Damp	Temperature (°F)	67.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Contractor is working on repairs			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/23/2021 10:20 AM	Report #	24908
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Checked rain gauges, Anderson Mill #2=.4", Mill Creek =.8", Transco =.8". Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/23/2021 10:20 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15878+08	Field Station#	15860+00		
Pic 1 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15827+00	Field Station#	15825+00		
Pic 3 Desc.	Observing P1 that requires maintenance (damaged by wildlife)	Pic 4 Desc.	Observing temporary stabilization, plunge pool and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15784+00	Field Station#	15793+00		
Pic 5 Desc.	Observing temporary stabilization, sump and end treatment	Pic 6 Desc.	Observing P1 that requires maintenance		

A/E	124300139	Date/Time	6/23/2021 10:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		













A/E	124300139	Date/Time	6/23/2021 10:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24980
Inspector	Charles Head			Date/Time	6/24/2021 3:33 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Dry	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2021 3:33 PM	Report #	24980
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2021 3:33 PM	Report #	
Pictures					
 		 			
GPS Location	0	GPS Location	0		
Field Station#	14694+50	Field Station#	14689+36		
Pic 1 Desc.	Approximately 14694+50. Overview of road crossing and RCE.	Pic 2 Desc.	Approximately 14689+36. Overview of stream crossing, equipment bridge and ECDs at stream S-H34.		
 		 			
GPS Location	0	GPS Location	0		
Field Station#	14691+00	Field Station#	14680+30		
Pic 3 Desc.	Approximately 14691+00. Overview of ROW.	Pic 4 Desc.	Approximately 14680+30. Overview of stream crossing, equipment bridge and ECDs at stream S-H36.		
 		 			
GPS Location	0	GPS Location	0		
Field Station#	14673+10	Field Station#	14651+00		
Pic 5 Desc.	Approximately 14673+10. Overview of stream crossing, equipment bridge and ECDs at stream S-H37.	Pic 6 Desc.	Approximately 14651+00. Overview of ROW.		

A/E	124300139	Date/Time	6/24/2021 3:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/24/2021 3:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24985
Inspector	Ben Farmer			Date/Time	6/24/2021 6:10 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Partial	Station End	15584+23
County	Pittsylvania	Ground	Dry	Temperature (°F)	72.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	6/24/2021 6:10 PM	Report #	24985
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 72 F) Rain Gauge= 0.0" 15480+67-15584+23 -EI began inspection at Toshes Rd. -RCEs are in good condition at all road crossings. -3rd party disturbance occurring next to MVP ROW at 15505+00. EI will continue to monitor for encroachment/damage to MVP ECDs from 3rd party activities. -P1 is in good condition at all stream and wetland buffers. -3rd party ECDs appear to be in good condition with no evidence of sedimentation onto MVP ROW. EI will continue to monitor area for changes. -CWDs are functioning as intended throughout this section. -Equipment bridge ECDs are in place and functioning. -3rd party disturbance occurring off ROW but directly up slope from stream S-CC9 (15556+83) with no ECDs in place. EI will continue to monitor this area for sedimentation from 3rd party. -Waterbars are functioning as intended. -Slope drain remains in good condition and functioning at 15574+87.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/24/2021 6:10 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15495+00		Field Station#	15496+70	
Pic 1 Desc.	Vegetation continues to fill in throughout this section.		Pic 2 Desc.	RCEs are in good condition at all road crossings.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15505+00		Field Station#	15506+41	
Pic 3 Desc.	3rd party disturbance occurring next to MVP ROW. EI will continue to monitor this area.		Pic 4 Desc.	P1 is in good condition at all stream and wetland buffers.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15510+00		Field Station#	15515+00	
Pic 5 Desc.	3rd party ECDs appear to be in good condition with no evidence of sedimentation onto MVP ROW.		Pic 6 Desc.	CWDs are functioning as intended.	

AFE 124300139		Date/Time 6/24/2021 6:10 PM		Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15521+50		Field Station#	15556+83	
Pic 7 Desc.	Equipment bridge ECDs are in good condition and functioning.		Pic 8 Desc.	3rd party disturbance occurring upslope of MVP ROW. EI will continue to monitor this area.	
GPS Location	See photo		GPS Location	See photo	
Field Station#	15568+00		Field Station#	15574+87	
Pic 9 Desc.	Waterbars are in good condition throughout this section.		Pic 10 Desc.	Slope drain is functioning as intended.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	6/24/2021 6:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24975
Inspector	John White			Date/Time	6/24/2021 1:34 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	79.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Berm	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2021 1:34 PM	Report #	24975
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/24/2021 1:34 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	16004+00	Field Station#	16010+00		
Pic 1 Desc.	Observing temporary stabilization, signage and buffer	Pic 2 Desc.	Observing temporary stabilization,CWD outlet and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15999+00	Field Station#	15983+00		
Pic 3 Desc.	Observing temporary stabilization,water bar,signage, buffer and ECD's	Pic 4 Desc.	Observing temporary stabilization,CWD outlet and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15972+00	Field Station#	15960+00		
Pic 5 Desc.	Observing temporary stabilization and CWD berm	Pic 6 Desc.	Observing equipment crossing and ECD's		

A/E	124300139	Date/Time	6/24/2021 1:34 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




A/E	124300139	Date/Time	6/24/2021 1:34 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	24969	
Inspector	John White			Date/Time	6/24/2021 1:17 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Dry	Temperature (°F)	79.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Housekeeping		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
Waterbar End Treatment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/24/2021 1:17 PM	Report #	24969
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2021 1:17 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	5+00	Field Station#	9+00		
Pic 1 Desc.	Observing temporary stabilization, water bar and end treatment		Pic 2 Desc.	Observing temporary stabilization	
					
GPS Location	O	GPS Location	O		
Field Station#	12+00	Field Station#	20+00		
Pic 3 Desc.	Observing temporary stabilization, sump and end treatment		Pic 4 Desc.	Observing temporary stabilization	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	6/24/2021 1:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/24/2021 1:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24924
Inspector	Ben Davenport			Date/Time	6/24/2021 12:27 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Partial	Station End	15142+66
County	Pittsylvania	Ground	Dry	Temperature (°F)	78.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Temporary Diversion Berm	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Rock Check Dam	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2021 12:27 PM	Report #	24924
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -No items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/24/2021 12:27 PM	Report #	
Pictures					
					
<small>36°57'46" N 79°35'32" W 102°E COURSE 0° GPS 1918-2164 Armstrong Rd, Penhook, VA 24137, United States 06.24.2021 08:18:20 Accur +/-49.5 Ft ALT 0 Ft</small>			<small>36°57'43" N 79°35'16" W 329°NW COURSE -1° GPS Sandy Level, VA 24161, United States 06.24.2021 10:02:33 Accur +/-114.4 Ft ALT 829 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	15065+00		Field Station#	15080+64	
Pic 1 Desc.	Row stabilized and vegetated in temporary area.		Pic 2 Desc.	Access road in good condition at ROW crossing.	
					
<small>36°57'42" N 79°35'15" W 14°N COURSE 143° GPS 1918-2164 Armstrong Rd, Penhook, VA 24137, United States 06.24.2021 08:29:05 Accur +/-46.2 Ft ALT 913 Ft</small>			<small>36°57'42" N 79°35'15" W 164°S COURSE 191° GPS Sandy Level, VA 24161, United States 06.24.2021 08:44:37 Accur +/-205.1 Ft ALT 890 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	15082+00		Field Station#	15101+00	
Pic 3 Desc.	CFS check dams and temporary diversion berm performing intended functions.		Pic 4 Desc.	ROW stabilized and vegetated in final cleanup area. Perimeter CFS in place and functional.	
					
<small>36°57'5" N 79°34'48" W 103°E COURSE -1° GPS Sandy Level, VA 24161, United States 06.24.2021 09:07:36 Accur +/-157.4 Ft ALT 882 Ft</small>			<small>36°57'4" N 79°34'48" W 205°SW COURSE 191° GPS Sandy Level, VA 24161, United States 06.24.2021 09:08:11 Accur +/-171.1 Ft ALT 912 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	15130+00		Field Station#	15133+00	
Pic 5 Desc.	Sump pit and end treatment performing intended function		Pic 6 Desc.	ROW stabilized in temporary area. Limited vegetation observed	

A/E	124300139	Date/Time	6/24/2021 12:27 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/24/2021 12:27 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24971
Inspector	Glenn Mike Renfro			Date/Time	6/24/2021 1:23 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00
State	VA	Inspection Area	Full	Station End	0000+00
County	Franklin	Ground	Dry	Temperature (°F)	73.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.60
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
Other - Explain in Comments	Acceptable	Inlet protection for catch basins			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2021 1:23 PM	Report #	24971
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspection of main laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have received .60" of rainfall since the last inspection and site conditions were dry. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were in acceptable condition. - All secondary containment structures were found to be in good condition at the time of inspection. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The RCE at LY-045 was found to be in good condition. - The General Construction permits and contact information are posted at the main entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/24/2021 1:23 PM	Report #	
Pictures					
					
GPS Location	000000000000	GPS Location	000000000000		
Field Station#	0000+00	Field Station#	0000+00		
Pic 1 Desc.	Perimeter ECD's on west side of LY-046 in good condition.		Pic 2 Desc.	Inlet protection and perimeter LY-046 near storage building in good condition	
					
GPS Location	000000000000	GPS Location	000000000000		
Field Station#	0000+00	Field Station#	0000+00		
Pic 3 Desc.	Perimeter secondary containment structure for fuel cell at LY-046 in good condition.		Pic 4 Desc.	RCE at LY-045 in good condition.	
		Insert image here			
GPS Location	000000000000	GPS Location			
Field Station#	0000+00	Field Station#			
Pic 5 Desc.	Perimeter ECD's on west of LY-045 near employee parking area in good condition.		Pic 6 Desc.		

A/E	124300139	Date/Time	6/24/2021 1:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/24/2021 1:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24965
Inspector	Justin Burch			Date/Time	6/24/2021 11:04 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Full	Station End	14311+57
County	Franklin	Ground	Damp	Temperature (°F)	80.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Equipment Bridge	Acceptable				
Other - Explain in Comments	Communication				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2021 11:04 AM	Report #	24965
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). The contractor had an Environmental Straw Foreman walk with the EI on his inspection. One issue was submitted for the punch list consisting of a location where electric fence was damaged by livestock. Other inspected ECDs were in compliance at the time of inspection. The EI observed the contractor has performed anode installation on buried pipe in the inspection area. The contractor was installing anode protection at 14237+00 on the GAS of Magodee Creek. The disturbed areas were temporarily stabilized. Since the last SWPPP inspection the area has received one rainfall event totaling 0.60" at Bonbrook Mill Road #1 and 0.50" at Farm View Road. The ROW ground condition is damp. At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14258+00 to 14277+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/24/2021 11:04 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14205+00	Field Station#	14205+00		
Pic 1 Desc.	Waterbar in acceptable condition		Pic 2 Desc.	Waterbar end treatment in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14209+50	Field Station#	14295+00		
Pic 3 Desc.	Equipment bridges in acceptable condition		Pic 4 Desc.	Electric fence damaged by livestock	
					
GPS Location	0	GPS Location	0		
Field Station#	14286+00	Field Station#	14305+00		
Pic 5 Desc.	Temporary vegetative stabilization in acceptable condition		Pic 6 Desc.	Perimeter CFS in acceptable condition	

A/E	124300139	Date/Time	6/24/2021 11:04 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/24/2021 11:04 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	24973	
Inspector	John White			Date/Time	6/24/2021 1:28 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Dry	Temperature (°F)	79.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable					
Equipment Bridge	Acceptable					
Housekeeping	Acceptable					
Sediment Filter Log	Acceptable					
Sensitive Resource Buffer	Acceptable					
Vegetative Stabilization (Temporary)	Acceptable					
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/24/2021 1:28 PM	Report #	24973
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2021 1:28 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	19+00	Field Station#	15+00		
Pic 1 Desc.	Observing temporary stabilization and ECD's	Pic 2 Desc.	Observing temporary stabilization and matt travel lane		
GPS Location	O	GPS Location	O		
Field Station#	12+65	Field Station#	6+00		
Pic 3 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization and access road		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	6/24/2021 1:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/24/2021 1:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24961
Inspector	Logan Box			Date/Time	6/24/2021 3:26 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Damp	Temperature (°F)	79.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Communication				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/24/2021 3:26 PM	Report #	24961
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections the EI noticed 2 sections of P1 that requires maintenance due to being weathered and torn with some damage from land owner activities.</p> <p>Documented the areas and talked with the contractor about the locations and repairs needed.</p> <p>Other than the items listed there were no other environmental issues observed at the time of inspection today.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/24/2021 3:26 PM	Report #	
Pictures					
					
GPS Location	0000	GPS Location	0000		
Field Station#	13813+02	Field Station#	13755+49		
Pic 1 Desc.	Additional photo showing P1 that requires maintenance due to being weathered and torn with some damage from land owner activities.		Pic 2 Desc.	Stream observation photo facing upstream during routine inspection today. No issues observed at the time of inspection.	
					
GPS Location	0000	GPS Location	00000		
Field Station#	13812+79	Field Station#	13755+71		
Pic 3 Desc.	Area observed where land owner has mowed inside the LOD. Noted that it was not project related. Will continue to monitor the area.		Pic 4 Desc.	Monitored stream buffer ECDs with checking row conditions throughout. No issues observed at the time of inspection.	
					
GPS Location	00000	GPS Location	00000		
Field Station#	13755+49	Field Station#	13813+02		
Pic 5 Desc.	Stream observation photo facing downstream during routine inspection today. No issues observed at the time of inspection.		Pic 6 Desc.	P1 requires maintenance due to being weathered and torn with some damage from land owner activities. Added to the punch list.	

A/E	124300139	Date/Time	6/24/2021 3:26 PM	Report #	
Pictures					
 <p>North Elevation <small>178°S (T) 37.068948, -79.924468 ±3 m ▲ 312 m</small></p>		<p>Insert image here</p>		<p>Insert image here</p>	
GPS Location	0000	GPS Location			
Field Station#	13812+06	Field Station#			
Pic 7 Desc.	P1 requires maintenance due to being weathered and torn. Documented and added to the punch list .		Pic 8 Desc.		
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 9 Desc.			Pic 10 Desc.		
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	6/24/2021 3:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25023
Inspector	Charles Head			Date/Time	6/25/2021 3:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Dry	Temperature (°F)	82.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	6/25/2021 3:41 PM	Report #	25023
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/25/2021 3:41 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14318+00	Field Station#	14328+00		
Pic 1 Desc.	Approximately 14318+00. Overview of ROW.	Pic 2 Desc.	Approximately 14328+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14333+00	Field Station#	14353+53		
Pic 3 Desc.	Approximately 14333+00. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14353+53. Overview of stream crossing, equipment bridge and ECDs at stream S-A38.		
					
GPS Location	0	GPS Location	0		
Field Station#	14428+00	Field Station#	14438+33		
Pic 5 Desc.	Approximately 14428+00. Overview of ROW.	Pic 6 Desc.	Approximately 14438+33. Overview of stream crossing, equipment bridge and ECDs at stream S-GH44.		

A/E	124300139	Date/Time	6/25/2021 3:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/25/2021 3:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	24998
Inspector	Ben Davenport			Date/Time	6/25/2021 9:26 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Dry	Temperature (°F)	81.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other - Explain in Comments	Communication	Routine maintenance- safety fence	Addressed	6/25/2021
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Rock Construction Entrance	Acceptable			
Equipment Bridge	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	6/25/2021 9:26 AM	Report #	24998
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 - 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECDs were inspected; 1 issue identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -1 item added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/25/2021 9:26 AM	Report #	
Pictures					
					
36°59'15" N 79°41'53" W 62°NE COURSE 144' GPS Sorry no results found			36°59'4" N 79°41'30" W 144°SE COURSE 141' GPS Union Hall, VA 24176, United States		
06.25.2021 09:03:35 Accur +/-376.1 Ft ALT 828 Ft			06.25.2021 09:14:03 Accur +/-32.1 Ft ALT 893 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14739+00	Field Station#	14755+00		
Pic 1 Desc.	Routine maintenance. Safety fence down around sump pit.		Pic 2 Desc.	Contractor repaired erosion rills and seeded and stabilized disturbed area per punch list item.	
					
36°59'17" N 79°42'15" W 31°NE COURSE -1' GPS 496 Holliday Ln, Union Hall, VA 24176, United States			36°59'16" N 79°42'9" W 278°W COURSE 183' GPS 496 Holliday Ln, Union Hall, VA 24176, United States		
06.25.2021 08:44:40 Accur +/-29.5 Ft ALT 937 Ft			06.25.2021 08:47:28 Accur +/-30.7 Ft ALT 909 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14712+33	Field Station#	14716+92		
Pic 3 Desc.	RCE at access road in good condition.		Pic 4 Desc.	Appropriate signage visible at stream crossing.	
					
36°59'16" N 79°42'9" W 5°N COURSE 139' GPS Sorry no results found			36°59'15" N 79°41'53" W 149°SE COURSE 139' GPS Sorry no results found		
06.25.2021 08:48:46 Accur +/-356.4 Ft ALT 908 Ft			06.25.2021 08:59:37 Accur +/-80.1 Ft ALT 908 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14723+00	Field Station#	14734+00		
Pic 5 Desc.	CFS check dams and P1 silt fence at resource buffer performing intended functions.		Pic 6 Desc.	New vegetation growing along travel lane where seeded.	

A/E	124300139	Date/Time	6/25/2021 9:26 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/25/2021 9:26 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	24996	
Inspector	Frank Craycroft			Date/Time	6/24/2021 10:07 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Dry	Temperature (°F)	75.00	
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Housekeeping		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/24/2021 10:07 PM	Report #	24996
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All perimeter ECDs were functional and in good condition. Inlet protections around Stormwater drains were in place and free of debris and vegetation build up. Housekeeping and waste management were in good order with no loose trash around and plenty of storage remaining in bulk dumpsters. No issues were observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	6/24/2021 10:07 PM	Report #	
Pictures					
 <p>SW 240 W 270 NW 330 N 0 30 291°W (T) 36.946879, -79.881614 ±24ft ▲ 955ft 24 Jun 2021 10:38:54</p>		 <p>E 60 SE 120 180 106°E (T) 36.946758, -79.880813 ±18ft ▲ 955ft 24 Jun 2021 10:37:51</p>			
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-032 Secondary containment	Pic 2 Desc.	LY-032 Light plant secondary containment		
 <p>SE 120 S 180 SW 240 W 270 190°S (T) 36.946354, -79.878978 ±38ft ▲ 1071ft 24 Jun 2021 10:41:33</p>		 <p>W 240 NW 300 360 292°W (T) 36.9463, -79.879364 ±19ft ▲ 1052ft 24 Jun 2021 10:41:00</p>			
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-033 Construction entrance	Pic 4 Desc.	LY-033 Inlet protection		
 <p>SE 150 S 180 SW 210 240 179°S (T) 36.953232, -79.87871 ±20ft ▲ 1100ft 24 Jun 2021 10:50:50</p>		 <p>S 150 SW 210 W 240 NW 300 330 264°W (T) 36.95353, -79.878114 ±14ft ▲ 1113ft 24 Jun 2021 10:52:40</p>			
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	ANC-006 Inlet protection	Pic 6 Desc.	ANC-006 Waste management		

A/E	124300139	Date/Time	6/24/2021 10:07 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-048 Equipment staging	Pic 8 Desc.	LY-048 South perimeter CFS		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	6/24/2021 10:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25019
Inspector	Justin Burch			Date/Time	6/25/2021 11:11 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Damp	Temperature (°F)	78.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.60
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)		Communication	Silt fence was maintained	Immediate	6/25/2021
Vegetative Stabilization (Permanent)		Acceptable			
Sump Pit		Acceptable			
Equipment Bridge		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Compost Filter Sock		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/25/2021 11:11 AM	Report #	25019
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). An Environmental Straw Foreman from Precision walked with the EI on his inspection. Two issues were submitted for the punch list including one location where P1 silt fence had holes from unknown means, and one location where P1 silt fence a hole at the ground line from wildlife damage. These items were repaired immediately by the contractor. Other inspected ECDs were in compliance at the time of inspection. The EI did not observe that the contractor has worked in the inspection area since the last inspection. Since the last SWPPP inspection the area has received one rainfall event totaling 0.60" at Bonbrook Mill Road #1 and 0.70" at Grassy Hill Road. The ROW ground condition is damp. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13940+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/25/2021 11:11 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	13957+00	Field Station#	13957+00		
Pic 1 Desc.	P1 silt fence with holes in it (multiple panels), contractor addressed immediately	Pic 2 Desc.	P1 silt fence after repair		
GPS Location	0	GPS Location	0		
Field Station#	13935+00	Field Station#	13905+00		
Pic 3 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 4 Desc.	P1 silt fence with a hole at the ground line, damaged by wildlife, contractor repaired immediately		
GPS Location	0	GPS Location	0		
Field Station#	13905+00	Field Station#	13896+00		
Pic 5 Desc.	P1 silt fence after maintenance	Pic 6 Desc.	Sump pit in acceptable condition		

AFE	124300139	Date/Time	6/25/2021 11:11 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	13888+50	Field Station#	13857+00		
Pic 7 Desc.	Equipment bridge in acceptable condition	Pic 8 Desc.	Waterbar in acceptable condition		
GPS Location	0	GPS Location	0		
Field Station#	13857+00	Field Station#	13853+50		
Pic 9 Desc.	Waterbar end treatment in acceptable condition	Pic 10 Desc.	Perimeter CFS in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/25/2021 11:11 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25014
Inspector	John White			Date/Time	6/25/2021 9:55 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/25/2021 9:55 AM	Report #	25014
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/25/2021 9:55 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15636+45	Field Station#	15632+00		
Pic 1 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing temporary stabilization, erosion control blanket and CFS Checks		
					
GPS Location	O	GPS Location	O		
Field Station#	15630+00	Field Station#	15619+48		
Pic 3 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 4 Desc.	Observing road crossing and RCE's		
					
GPS Location	O	GPS Location	O		
Field Station#	15605+00	Field Station#	15590+00		
Pic 5 Desc.	Observing temporary stabilization	Pic 6 Desc.	Observing temporary stabilization and water bars		

A/E	124300139	Date/Time	6/25/2021 9:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/25/2021 9:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		










Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	25018	
Inspector	Ben Farmer				Date/Time	6/25/2021 11:41 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	15142+66	
State	VA	Inspection Area	Partial		Station End	15260+00	
County	Pittsylvania	Ground	Dry		Temperature (°F)	61.00	
Municipality	Chatham	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Rock Construction Entrance		Acceptable					
Rock Construction Entrance		Acceptable					
Rock Filter		Acceptable					
Rock Filter Outlet		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Slope Drain Pipe		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	6/25/2021 11:41 AM	Report #	25018
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 61 F) Rain Gauge= 0.0" 15142+66-15260+00 -EI began inspection at Rockcreek. -RCEs are in good condition at all road crossings. -Previously replaced CFS is in good condition. -Areas disturbed during CFS install have been stabilized. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00. -P1 is in good condition at all stream and wetland crossings. -Equipment bridge ECDs are in place and functioning. -Waterbars are in good condition throughout this section. -Slope drain is functioning as intended at 15170+00. -Drainage ECDs are in good condition at 15195+00. -Fence gap remains open by 3rd party allowing livestock onto ROW at 15195+50. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/25/2021 11:41 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15142+66		Field Station#	15152+84	
Pic 1 Desc.	RCEs are in good condition condition at all road crossings.		Pic 2 Desc.	Areas disturbed during CFS install have been stabilized.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15155+00		Field Station#	15165+57	
Pic 3 Desc.	CFS is in good condition.		Pic 4 Desc.	Rock inlet remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15166+00		Field Station#	15167+95	
Pic 5 Desc.	Rock outlet remains in good condition.		Pic 6 Desc.	P1 is in good condition at this stream buffer.	

AFE	124300139	Date/Time	6/25/2021 11:41 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15167+95		Field Station#	15170+00	
Pic 7 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 8 Desc.	Waterbars are functioning as intended.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15195+00	
Pic 9 Desc.	Slope drain is in good condition at this location.		Pic 10 Desc.	Drainage feature ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15195+50		Field Station#	15209+00	
Pic 11 Desc.	Fence gap remains open by 3rd party allowing livestock onto ROW.		Pic 12 Desc.	Vegetation continues to fill in throughout this section.	

AFE	124300139	Date/Time	6/25/2021 11:41 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location			
Field Station#	15260+00	Field Station#			
Pic 13 Desc.	Vegetation continues to fill in throughout this section.	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	24972
Inspector	John White			Date/Time	6/24/2021 1:23 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	79.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Rock Filter	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sediment Basin	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	6/24/2021 1:23 PM	Report #	24972
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	6/24/2021 1:23 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 1 Desc.	Observing temporary stabilization and rock drain		Pic 2 Desc.	Observing storm water pond	
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 3 Desc.	Observing temporary stabilization and sediment basin		Pic 4 Desc.	Observing rock drain and CFS checks.	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300113	Date/Time	6/24/2021 1:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		

A/E	124300113	Date/Time	6/24/2021 1:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		