



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	26968
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/9/2021 6:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 6:18 PM	<b>Report #</b>	26968
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection of LDY-26 Yard is used to store various materials needed for construction. Both MVP and PPL employee personal vehicles are parked here. Large fuel island containment is maintained in acceptable condition. With secondary containments in place to be used when fueling vehicles. Waste management and housekeeping are acceptable. Dumpsters are in place with adequate signage to dispose of materials properly into correct bins. Rock surface of the yard is in acceptable condition. CFS perimeter controls and orange safety fence are in place. Light plants, porta potties, gas cans, and other hazardous materials are in secondary containment units. Spill kits and fire extinguishers are available on site.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300137		Date/Time		8/9/2021 6:18 PM		Report #							
Pictures															
<p>Date &amp; Time: Mon, Aug 09, 2021, 12:08:51 EDT Position: +037.318542 / -080.657281 (+15.5m) Altitude: 1765m (+39.4m) Datum: WGS-84 Azimuth/Bearing: 84° N23W 4027mils True (+12.1) Elevation Angle: -05.5° Horizon Angle: +00.4° Zoom: 1.0x 12005+00</p> 				<p>Date &amp; Time: Mon, Aug 09, 2021, 12:12:00 EDT Position: +037.318918 / -080.658484 (+15.5m) Altitude: 1765m (+39.4m) Datum: WGS-84 Azimuth/Bearing: 33° N21W 4027mils True (+12.1) Elevation Angle: -05.5° Horizon Angle: +00.5° Zoom: 1.0x 12005+00</p> 											
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 1 Desc.				Rock surface in acceptable condition				Pic 2 Desc.				Secondary containments in place			
<p>Date &amp; Time: Mon, Aug 09, 2021, 12:12:33 EDT Position: +037.318672 / -080.658544 (+15.1m) Altitude: 1790m (+11.7m) Datum: WGS-84 Azimuth/Bearing: 293° N67W 5209mils True (+12.1) Elevation Angle: -14.5° Horizon Angle: +05.3° Zoom: 1.0x 12005+00</p> 				<p>Date &amp; Time: Mon, Aug 09, 2021, 12:11:03 EDT Position: +037.318028 / -080.657703 (+15.5m) Altitude: 1802m (+3.2m) Datum: WGS-84 Azimuth/Bearing: 642° N42E 1102mils True (+3.2) Elevation Angle: -05.5° Horizon Angle: -10.0° Zoom: 1.0x 12005+00</p> 											
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 3 Desc.				CFS perimeter control in place				Pic 4 Desc.				Secondary containment in place			
<p>Date &amp; Time: Mon, Aug 09, 2021, 12:11:55 EDT Position: +037.317833 / -080.659232 (+15.5m) Altitude: 1844m (+13.1m) Datum: WGS-84 Azimuth/Bearing: 318° N42W 5653mils True (+12.1) Elevation Angle: +01.8° Horizon Angle: +01.0° Zoom: 1.0x 12005+00</p> 				<p>Date &amp; Time: Mon, Aug 09, 2021, 12:11:05 EDT Position: +037.317818 / -080.659271 (+22.7m) Altitude: 1833m (+39.4m) Datum: WGS-84 Azimuth/Bearing: 038° N38E 1036mils True (+12.1) Elevation Angle: +00.5° Horizon Angle: +03.5° Zoom: 1.0x 12005+00</p> 											
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 5 Desc.				Good housekeeping				Pic 6 Desc.				Dumpster in place			

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 6:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 6:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	26961
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/9/2021 3:24 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock				
Culvert				
Housekeeping				
Rock Construction Entrance				
Secondary Containment				
Waste Management				

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	8/9/2021 3:24 PM	<b>Report #</b>	26961
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection of LDY-29 AR-238.00 - Access road and RCE are maintained in acceptable condition. CFS triple stack perimeter controls and overhead utility flagging are in place. Waste management and housekeeping are acceptable. Culvert is in place and functional. Yard mainly used for 798 welders to store materials and equipment as well as park vehicles. Inspected fuel cell #47561 on site. No visible leaks or spills.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	8/9/2021 3:24 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Dumpsters in place	<b>Pic 2 Desc.</b>	Secondary containment in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	Rock surface in acceptable condition	<b>Pic 4 Desc.</b>	Culvert in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	Secondary containment in place	<b>Pic 6 Desc.</b>	Triple stack CFS perimeter control in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 3:24 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 3:24 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	26970
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/9/2021 6:30 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 6:30 PM	<b>Report #</b>	26970
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection of LDY 28 Western section of the yard: RCE is maintained in acceptable condition. Buses, trucks, and trailers not currently in use are being stored at this portion of the yard. Eastern section of the yard: This portion of the yard has heavy trucking activity throughout the workday. PPL truck drives and their escorts park their personal vehicles here. The RCE is maintained in acceptable condition. CFS perimeter controls and overhead utility flagging are in place. Rock surface of the yard is in acceptable condition. Waste management and housekeeping are acceptable.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	8/9/2021 6:30 PM	Report #	
Pictures					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	CFS perimeter control in place		<b>Pic 2 Desc.</b>	Dumpsters in place	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	Secondary containment in place		<b>Pic 4 Desc.</b>	Rock surface in acceptable condition	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	RCE in place		<b>Pic 6 Desc.</b>	Vehicles being stored at this portion of the yard	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 6:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 6:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	26966
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/9/2021 5:45 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+01
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			







## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 5:45 PM	<b>Report #</b>	26966
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to MP 219.70) No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. ROW is dry and in stable condition up until JNF property line ST# 11553+66. Final restoration has occurred between ST# 11526+50 and ST# 11548+00. Permanent waterbars with level spreaders are installed. Topsoil has been put back. Perimeter controls and end treatments are in place. Permanent seed and hydro mulch has been applied. Daylight drains with rock outlet protection and temporary CFS waterbars are in place. Proper signage has been posted to keep vehicle travel off of restored ROW. ROW is dry and stabilized throughout JNF with large areas of vegetation. Waterbars with end treatments and perimeter controls are in place. 50' buffers are in place at stream crossings S-PP22, S-PP21, S-PP20. AR-258.02 and Craig Creek road crossing RCEs are maintained in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/9/2021 5:45 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11598+50	<b>Field Station#</b>	11592+00		
<b>Pic 1 Desc.</b>	RCE in place	<b>Pic 2 Desc.</b>	P1 silt fence perimeter control		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11585+50	<b>Field Station#</b>	11583+50		
<b>Pic 3 Desc.</b>	Stream buffer in place	<b>Pic 4 Desc.</b>	P1 silt fence perimeter control in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11570+00	<b>Field Station#</b>	11563+00		
<b>Pic 5 Desc.</b>	ECDs in place	<b>Pic 6 Desc.</b>	Waterbars in place		



AFE 124300137		Date/Time	8/9/2021 5:45 PM	Report #	
Pictures					
					
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11548+00		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		Good vegetation on ROW		<b>Pic 8 Desc.</b>	
				CFS perimeter controls in place	
					
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11545+00		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		Level spreaders in place		<b>Pic 10 Desc.</b>	
				Permanent waterbars in place	
					
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11533+00		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		Temporary CFS waterbars in place		<b>Pic 12 Desc.</b>	
				Drainage feature restored	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/9/2021 5:45 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27020
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/10/2021 6:10 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10859+34
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication			
Slope Drain Pipe	Communication			
Waterbar	Communication			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Culvert	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

## 5. Site Conditions




Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2021 6:10 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Aug 10, 2021, 10:38:35 EDT  Position: +037.352992° / -080.636667° (±12.0ft)  Altitude: 2280ft (±13.1ft)  Datum: WGS-84  Azimuth/Bearing: 224° S44W 3982mils True (±12°)  Elevation Angle: -33.3°  Horizon Angle: -04.2°  Zoom: 1.0x  10748+12</p> 		<p>Date &amp; Time: Tue, Aug 10, 2021, 09:41:22 EDT  Position: +037.352988° / -080.637915° (±11.6ft)  Altitude: 2088ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 224° S44W 3982mils True (±13°)  Elevation Angle: -33.3°  Horizon Angle: -04.2°  Zoom: 1.0x  10680+42</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10748+12	<b>Field Station#</b>	10680+42		
<b>Pic 1 Desc.</b>	Clean sediment out of slope drain pipe	<b>Pic 2 Desc.</b>	Clean out throat of waterbar		
<p>Date &amp; Time: Tue, Aug 10, 2021, 09:38:16 EDT  Position: +037.352992° / -080.636667° (±14.0ft)  Altitude: 2075ft (±13.4ft)  Datum: WGS-84  Azimuth/Bearing: 159° S28E 3256mils True (±13°)  Elevation Angle: -18.5°  Horizon Angle: -04.2°  Zoom: 1.0x  10679+71</p> 		<p>Date &amp; Time: Tue, Aug 10, 2021, 09:41:22 EDT  Position: +037.352988° / -080.637915° (±11.6ft)  Altitude: 2430ft (±26.2ft)  Datum: WGS-84  Azimuth/Bearing: 159° S28E 3256mils True (±13°)  Elevation Angle: -18.5°  Horizon Angle: -04.2°  Zoom: 1.0x  10848+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10679+71	<b>Field Station#</b>	10848+00		
<b>Pic 3 Desc.</b>	Repair/Replace damaged CFS	<b>Pic 4 Desc.</b>	CFS perimeter control in place		
<p>Date &amp; Time: Tue, Aug 10, 2021, 12:16:22 EDT  Position: +037.352992° / -080.636667° (±12.0ft)  Altitude: 2547ft (±13.1ft)  Datum: WGS-84  Azimuth/Bearing: 144° S33E 3240mils True (±12°)  Elevation Angle: -18.5°  Horizon Angle: -04.2°  Zoom: 1.0x  10826+00</p> 		<p>Date &amp; Time: Tue, Aug 10, 2021, 12:24:27 EDT  Position: +037.352988° / -080.637915° (±11.6ft)  Altitude: 1940ft (±13.1ft)  Datum: WGS-84  Azimuth/Bearing: 122° S12E 3240mils True (±12°)  Elevation Angle: -18.5°  Horizon Angle: -04.2°  Zoom: 1.0x  10805+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10826+00	<b>Field Station#</b>	10805+00		
<b>Pic 5 Desc.</b>	Supersilt fence perimeter control in place	<b>Pic 6 Desc.</b>	Trench plugs in place		



AFE	124300137	Date/Time	8/10/2021 6:10 PM	Report #	
Pictures					
<p><small>Date &amp; Time: Tue, Aug 10, 2021, 11:35:14 EDT Position: +037.344172 / -080.626598 (+48 8ft) Altitude: 2078ft (+39 4ft) Datum: WGS-84 Azimuth/Bearing: 056° N86°E 1994mils True (+13 1) Elevation Angle: -02° Horizon Angle: -01° Zoom: 1.0X 10780+00</small></p> 				<p><small>Date &amp; Time: Tue, Aug 10, 2021, 11:11:52 EDT Position: +037.344152 / -080.629070 (+39 8ft) Altitude: 2161ft (+39 4ft) Datum: WGS-84 Azimuth/Bearing: 133° S21°E 2304mils True (+12 1) Elevation Angle: -23° Horizon Angle: -02° Zoom: 1.0X 10772+00</small></p> 	
GPS Location	See photo		GPS Location	See photo	
Field Station#	10780+00		Field Station#	10772+00	
Pic 7 Desc.	Stream buffer in place		Pic 8 Desc.	Clean water outlet protection in place	
<p><small>Date &amp; Time: Tue, Aug 10, 2021, 10:49:29 EDT Position: +037.342785 / -080.635638 (+26 2ft) Altitude: 2228ft (+39 8ft) Datum: WGS-84 Azimuth/Bearing: 099° S81°E 1760mils True (+12 1) Elevation Angle: -20.5° Horizon Angle: -00.0° Zoom: 1.0X 10753+00</small></p> 				<p><small>Date &amp; Time: Tue, Aug 10, 2021, 10:15:02 EDT Position: +037.348647 / -080.636645 (+28 5ft) Altitude: 2210ft (+39 8ft) Datum: WGS-84 Azimuth/Bearing: 299° N61°W 5310mils True (+12 1) Elevation Angle: -23° Horizon Angle: -01° Zoom: 1.0X 10704+00</small></p> 	
GPS Location	See photo		GPS Location	See photo	
Field Station#	10753+00		Field Station#	10704+00	
Pic 9 Desc.	Waterbars in place		Pic 10 Desc.	End treatments in place	
<p><small>Date &amp; Time: Tue, Aug 10, 2021, 11:42:25 EDT Position: +037.345552 / -080.635510 (+39 8ft) Altitude: 3323ft (+11 2ft) Datum: WGS-84 Azimuth/Bearing: 100° S30°E 1070mils True (+12 1) Elevation Angle: -03° Horizon Angle: -00° Zoom: 1.0X 10741+00</small></p> 				<p><small>Date &amp; Time: Tue, Aug 10, 2021, 11:40:04 EDT Position: +037.345552 / -080.635510 (+39 8ft) Altitude: 3323ft (+11 2ft) Datum: WGS-84 Azimuth/Bearing: 100° S30°E 1070mils True (+12 1) Elevation Angle: -03° Horizon Angle: -00° Zoom: 1.0X 10731+00</small></p> 	
GPS Location	See photo		GPS Location	See photo	
Field Station#	10741+50		Field Station#	10731+00	
Pic 11 Desc.	Clean water diversion berm in place		Pic 12 Desc.	Waterbars in place	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2021 6:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	26994
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	8/10/2021 7:32 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+34
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11064+53
<b>County</b>	Giles	<b>Ground</b>	Dusty	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Communication			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Communication			
Silt Fence (Filter Fabric Fence)	Communication			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions



Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2021 7:32 AM	<b>Report #</b>	26994
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10859+62 to ST# 11064+53 (MP 205.7 to MP 209.6) ACTIVE CONSTRUCTION AREA. Deficiencies found at the following station numbers: 11017+36, bridge needs cleaned. 11017+36, compressor needs put in containment. 10988+00, Hole in P1. 10978+00, slope drain needs cleaned. 11062+00, Slope drain needs repaired. 10963+33, bridge needs cleaned. All issues have been communicated to PPL contractor via punch list. Active construction site; additional deficiencies may be identified by other EIs. Observed: Padding and backfill crew working AR 245.01, moving to AR 244 station # 11023+80 Lowering in crew at station # 11000+00-11022+00 Trenching crew working in numerous locations from 10859+62-10970+00 -Tie-in crew # 3, ditching and welding at station # 10955+00-10985+00. Environmental crews are working throughout the area repairing ECDS as needed. Water bars are tore out daily but put back by the end of the day. Rock Road approaches at Kow Camp #2, 10859+62, Kow Camp #1 and Doe Creek Rd, station10929+71, were all clean and free of any loose rock. LOD ECDS were in place and functional. Water bars are being put back as specified.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		8/10/2021 7:32 AM		Report #							
Pictures															
				<p>Date &amp; Time: Tue, Aug 10, 2021, 10:15:01 EDT Position: +037.326401° / -080.568188° (+98.4ft) Altitude: 2429ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 160° S40E 2489mils True (+77°) Elevation Angle: -28.1° Horizon Angle: -00.6° Zoom: 1.0X seep area wood stockpiles station 10976+00</p>								<p>Date &amp; Time: Tue, Aug 10, 2021, 11:43:37 EDT Position: +037.325297° / -080.597184° (+16.4ft) Altitude: 2389ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 154° S26E 2738mils True (+13°) Elevation Angle: -16.0° Horizon Angle: -02.7° Zoom: 1.0X soil stockpiles re stabilized station 10876+00</p>			
GPS Location		See photo				GPS Location		see photo							
Field Station#		10976+67				Field Station#		10876+00							
Pic 1 Desc.		Seep area				Pic 2 Desc.		Soil stock piles stabilized							
				<p>Date &amp; Time: Tue, Aug 10, 2021, 11:45:46 EDT Position: +037.335299° / -080.607004° (+92.2ft) Altitude: 2137ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 112° S48E 1991mils True (+10°) Elevation Angle: -01.1° Horizon Angle: -01.8° Zoom: 2.0X Kow Camp pavement station 10884+00</p>								<p>Date &amp; Time: Tue, Aug 10, 2021, 11:45:46 EDT Position: +037.335299° / -080.607004° (+92.2ft) Altitude: 2137ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 112° S48E 1991mils True (+10°) Elevation Angle: -01.1° Horizon Angle: -01.8° Zoom: 2.0X Kow camp gravel downstream station 10859+00</p>			
GPS Location		see photo				GPS Location		see photo							
Field Station#		108884+00				Field Station#		10859+00							
Pic 3 Desc.		Trenching crew at Kow Camp, pavement				Pic 4 Desc.		Kow camp gravel							
				<p>Date &amp; Time: Tue, Aug 10, 2021, 11:47:09 EDT Position: +037.335342° / -080.598291° (+32.8ft) Altitude: 2321ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 108° S72E 1920mils True (+78°) Elevation Angle: -24.2° Horizon Angle: -01.7° Zoom: 1.0X water bars station 10879+00</p>								<p>Date &amp; Time: Tue, Aug 10, 2021, 11:34:54 EDT Position: +037.337034° / -080.603124° (+32.8ft) Altitude: 2321ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 143° S37E 2542mils True (+66°) Elevation Angle: -03.1° Horizon Angle: -00.9° Zoom: 1.0X diversion pipe station 10863+58</p>			
GPS Location		see photo				GPS Location		see photo							
Field Station#		10879+00				Field Station#		10863+58							
Pic 5 Desc.		Water bars				Pic 6 Desc.		Diversion pipe.							



<b>AFE</b>	124300137	<b>Date/Time</b>	8/10/2021 7:32 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Aug 10, 2021, 09:27:12 EDT  Position: +037.323433° / -080.554933° (±16.4ft)  Altitude: 2385ft (±9.8ft)  Datum: WGS-84  Azimuth/Bearing: 285° N75W 180.7mils True (±12°)  Elevation Angle: -11.5°  Horizon Angle: -102.3°  Zoom: 1.0X  SR-05, PA007 11017+36 bridge needs cleaned</p> 		<p>Date &amp; Time: Tue, Aug 10, 2021, 09:28:32 EDT  Position: +037.323485° / -080.554998° (±16.4ft)  Altitude: 2385ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 308° N72W 418.7mils True (±12°)  Elevation Angle: -14.9° / -15°  Horizon Angle: -101.2°  Zoom: 1.0X  compressor needs put in containment 11017+36</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11017+36	<b>Field Station#</b>	11017+36		
<b>Pic 7 Desc.</b>	Bridge needs cleaned	<b>Pic 8 Desc.</b>	Compressor needs containment		
<p>Date &amp; Time: Tue, Aug 10, 2021, 10:04:53 EDT  Position: +037.341620° / -080.557199° (±5568.6ft)  Altitude: 2408ft (±148.0ft)  Datum: WGS-84  Azimuth/Bearing: 038° N38E 104.6mils True (±12°)  Elevation Angle: -06.9°  Horizon Angle: -100.7°  Zoom: 1.0X  Station P-1 10988+00</p> 		<p>Date &amp; Time: Tue, Aug 10, 2021, 10:12:38 EDT  Position: +037.341620° / -080.557199° (±5568.6ft)  Altitude: 2408ft (±148.0ft)  Datum: WGS-84  Azimuth/Bearing: 212° S32W 376.9mils True (±7°)  Elevation Angle: -30.7°  Horizon Angle: -103.1°  Zoom: 1.0X  slope drain needs cleaned 10978+00</p> 			
<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	10988+00	<b>Field Station#</b>	10978+00		
<b>Pic 9 Desc.</b>	Hole in P1	<b>Pic 10 Desc.</b>	Slope drain needs cleaned		
<p>Date &amp; Time: Tue, Aug 10, 2021, 10:26:32 EDT  Position: +037.329333° / -080.572100° (±132.8ft)  Altitude: 2260ft (±78.2ft)  Datum: WGS-84  Azimuth/Bearing: 298° N65W 524.6mils True (±12°)  Elevation Angle: -26.5°  Horizon Angle: -100.4°  Zoom: 1.0X  bridge needs cleaned 10963+33</p> 		<p>Date &amp; Time: Tue, Aug 10, 2021, 09:55:54 EDT  Position: +037.323933° / -080.568833° (±132.8ft)  Altitude: 2508ft (±26.2ft)  Datum: WGS-84  Azimuth/Bearing: 111° S49E 197.3mils True (±12°)  Elevation Angle: -10.9°  Horizon Angle: -101.2°  Zoom: 2.0X  lower in station #1101+00</p> 			
<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	10963+33	<b>Field Station#</b>	11010+00		
<b>Pic 11 Desc.</b>	Bridge needs cleaned	<b>Pic 12 Desc.</b>	Lowering in crew		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/10/2021 7:32 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27070
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/11/2021 5:48 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11524+16
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	89.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Communication	See comments		
Plunge Pool	Communication	See comments		
Cleanwater Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			







<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	8/11/2021 5:48 PM	<b>Report #</b>	27070
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11254+99 to ST# 11524+16 (MP 213.16 to MP 218.26) Deficiencies found at the following station numbers: 11285+00 Remove old CFS from behind end treatment. 11279+00 Remove dirt clods from plunge pool. All issues have been communicated to PPL contractor via punch list. Active construction site; additional deficiencies may be identified by other EIs.. Observed: -Clean-up crew between ST# 11423+00 and ST# 11470+50 hauling at rock and hauling in dirt to be used to put ROW back to subgrade. -Bending crew at ST# 11366+00 welding joints of pipe. -Several pieces of equipment from both clean-up and Arnold's seeding tracking between Old furnace road crossing and Seven Oaks to be hauled out and moved around to another location. ROW has been restored between ST# 11367+00 and ST# 11422+75 50' buffers in place at stream crossings S-MM18, S-NN12, S-NN11, S-KL43, S-0014, S-0013, S-0012, S-CD14, S-PP3, and S-PP4 AR-253.03, 253.01, and 256.01 have not yet been constructed AR-253.02, 256, 256.02, 258.01, 258.02, and Stevers Gap road crossing RCE are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE		124300137		Date/Time		8/11/2021 5:48 PM		Report #							
Pictures															
															
<p>Date &amp; Time: Wed Aug 11, 2021 13:14:48 EDT Position: +037 295231 / -080 485128 / +26.20 Altitude: 2220ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 203° 52'30" 9509mils True (+12°) Elevation Angle: -33° Horizon Angle: -03.6° Zoom: 1.0X 11279+00</p>				<p>Date &amp; Time: Wed Aug 11, 2021 13:08:20 EDT Position: +037 295231 / -080 483758 / +26.20 Altitude: 2220ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 000° N/AE 1036mils True (+12°) Elevation Angle: -25.6° Horizon Angle: -03.6° Zoom: 1.0X 11285+00</p>											
<b>GPS Location</b>				See photo				<b>GPS Location</b>				See photo			
<b>Field Station#</b>				11279+00				<b>Field Station#</b>				11285+00			
<b>Pic 1 Desc.</b>				Remove dirt clods from plunge pool				<b>Pic 2 Desc.</b>				Remove old CFS			
															
<p>Date &amp; Time: Wed Aug 11, 2021 13:03:08 EDT Position: +037 295230 / -080 492150 / +11.70 Altitude: 2112ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 301° NSW 538mils True (+12°) Elevation Angle: -26.5° Horizon Angle: -01.6° Zoom: 1.0X 11259+50</p>				<p>Date &amp; Time: Wed Aug 11, 2021 13:00:13 EDT Position: +037 295993 / -080 483267 / +31.30 Altitude: 2262ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 260° S80W 4622mils True (+12°) Elevation Angle: -05.0° Horizon Angle: -05.3° Zoom: 1.0X 11287+00</p>											
<b>GPS Location</b>				See photo				<b>GPS Location</b>				See photo			
<b>Field Station#</b>				11259+50				<b>Field Station#</b>				11287+00			
<b>Pic 3 Desc.</b>				End treatments in place				<b>Pic 4 Desc.</b>				Fill slope stabilized			
															
<p>Date &amp; Time: Wed Aug 11, 2021 13:00:00 EDT Position: +037 295993 / -080 483267 / +31.30 Altitude: 2172ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 316° N44W 5618mils True (+12°) Elevation Angle: -23.7° Horizon Angle: +03.6° Zoom: 1.0X 11298+50</p>				<p>Date &amp; Time: Wed Aug 11, 2021 13:00:00 EDT Position: +037 297082 / -080 479173 / +03.30 Altitude: 2291ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 210° S30W 3733mils True (+12°) Elevation Angle: -16.6° Horizon Angle: +02.5° Zoom: 1.0X 11311+00</p>											
<b>GPS Location</b>				See photo				<b>GPS Location</b>				See photo			
<b>Field Station#</b>				11298+50				<b>Field Station#</b>				11311+00			
<b>Pic 5 Desc.</b>				RCE in place				<b>Pic 6 Desc.</b>				P1 silt fence perimeter control in place			



<b>AFE</b>	124300137	<b>Date/Time</b>	8/11/2021 5:48 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed Aug 11, 2021, 12:29:42 EDT Position: -837600599 / -80472316 (-138.7m) Altitude: 2216ft (-157.5m) Datum: WGS-84 Azimuth/Bearing: 228° S48W 405mils True (-12°) Elevation Angle: -02° Horizon Angle: -01.4° Zoom: 1.0X 11328+63</p>		 <p>Date &amp; Time: Wed Aug 11, 2021, 11:55:49 EDT Position: -837603524 / -80444504 (-138.7m) Altitude: 2216ft (-157.5m) Datum: WGS-84 Azimuth/Bearing: 182° N54E 570mils True (-13°) Elevation Angle: -02.7° Horizon Angle: -01.4° Zoom: 1.0X 11367+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11328+63	<b>Field Station#</b>	11367+00		
<b>Pic 7 Desc.</b>	Stream buffer in place	<b>Pic 8 Desc.</b>	P1 silt fence across travel lane to prevent vehicles from traveling on restored ROW		
 <p>Date &amp; Time: Wed Aug 11, 2021, 11:59:19 EDT Position: -837617407 / -80443640 (-138.7m) Altitude: 2218ft (-157.5m) Datum: WGS-84 Azimuth/Bearing: 302° N13W 580mils True (-12°) Elevation Angle: -12° Horizon Angle: -01.1° Zoom: 1.0X 11394+00</p>		 <p>Date &amp; Time: Wed Aug 11, 2021, 10:59:27 EDT Position: -837612782 / -804451647 (-138.7m) Altitude: 2227ft (-157.5m) Datum: WGS-84 Azimuth/Bearing: 104° N45E 572mils True (-12°) Elevation Angle: -05.6° Horizon Angle: -00.6° Zoom: 1.0X 11412+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11394+00	<b>Field Station#</b>	11412+00		
<b>Pic 9 Desc.</b>	Temporary CFS waterbars in place	<b>Pic 10 Desc.</b>	CFS perimeter controls and end treatments are in place		
 <p>Date &amp; Time: Wed Aug 11, 2021, 10:35:55 EDT Position: -837362136 / -804433378 (-137.7m) Altitude: 2224ft (-157.5m) Datum: WGS-84 Azimuth/Bearing: 207° S68W 627mils True (-12°) Elevation Angle: -02.2° Horizon Angle: -02.2° Zoom: 1.0X 11479+00</p>		 <p>Date &amp; Time: Wed Aug 11, 2021, 09:44:49 EDT Position: -837362518 / -804434433 (-137.4m) Altitude: 2350ft (-11.3m) Datum: WGS-84 Azimuth/Bearing: 100° S80E 1778mils True (-12°) Elevation Angle: -14.0° Horizon Angle: -07.8° Zoom: 1.0X 11478+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11479+00	<b>Field Station#</b>	11478+00		
<b>Pic 11 Desc.</b>	Clean water drainage feature in place	<b>Pic 12 Desc.</b>	Supersilt fence perimeter control in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2021 5:48 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27072
<b>Inspector</b>	Clint Sears			<b>Date/Time</b>	8/11/2021 6:10 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Dusty	<b>Temperature (°F)</b>	93.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sensitive Resource Signage	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





AFE		124300137		Date/Time		8/11/2021 6:10 PM		Report #			
Pictures											
											
GPS Location		See photo				GPS Location		See photo			
Field Station#		11113+85				Field Station#		11117+05			
Pic 1 Desc.		Stabilized subsoil, SSF and CFS functional				Pic 2 Desc.		Sump pit, CFS and SSF functional			
											
GPS Location		see photo				GPS Location		See photo			
Field Station#		11120+00				Field Station#		11122+30			
Pic 3 Desc.		Topsoil vegetation adequate				Pic 4 Desc.		Clean water diversion pipe supported and functional			
											
GPS Location		see photo				GPS Location		See photo			
Field Station#		11127+00				Field Station#		11133+00			
Pic 5 Desc.		P1 silt fence and erosion control blanket functional				Pic 6 Desc.		Perimeter controls at sensitive resource area functional			



AFE		124300137	Date/Time	8/11/2021 6:10 PM	Report #	
Pictures						
 <p>Date &amp; Time: Wed Aug 11, 2021 09:54:57 EDT Position: +037 310328 / -080 507492 (+50.8m) Altitude: 1960m (+33.3m) Datum: WGS-84 Azimuth/Bearing: 119° S61E 2116mils True (+12.1°) Elevation Angle: -05.9° Horizon Angle: -01.3° Zoom: 1.0X 11191+00</p>			 <p>Date &amp; Time: Wed Aug 11, 2021 09:21:04 EDT Position: +037 310279 / -080 514354 (+50.8m) Altitude: 1867m (+47.8m) Datum: WGS-84 Azimuth/Bearing: 264° S43W 4320mils True (+127°) Elevation Angle: +01.7° Horizon Angle: +01.7° Zoom: 1.0X 11159+50</p>			
GPS Location		See photo		GPS Location		See photo
Field Station#		11149+25		Field Station#		11168+50
Pic 7 Desc.		Construction materials staged on ROW for later use		Pic 8 Desc.		AR249.01 being graded and fresh stone applied
 <p>Date &amp; Time: Wed Aug 11, 2021 09:51:25 EDT Position: +037 310288 / -080 507492 (+50.8m) Altitude: 1960m (+33.3m) Datum: WGS-84 Azimuth/Bearing: 119° S61E 2116mils True (+12.1°) Elevation Angle: -05.9° Horizon Angle: -01.3° Zoom: 1.0X 11191+00</p>			 <p>Date &amp; Time: Wed Aug 11, 2021 11:06:42 EDT Position: +037 310208 / -080 544885 (+50.7m) Altitude: 2120m (+47.0m) Datum: WGS-84 Azimuth/Bearing: 135° N25W 590mils True (+13°) Elevation Angle: -20.5° Horizon Angle: -00.5° Zoom: 1.0X 11064+53</p>			
GPS Location		See photo		GPS Location		see photo
Field Station#		11191+00		Field Station#		11064+53
Pic 9 Desc.		P1, SSF and equipment bridge functional		Pic 10 Desc.		Subsoil prepped and ready for stabilization
 <p>Date &amp; Time: Wed Aug 11, 2021 10:15:53 EDT Position: +037 302574 / -080 000255 (+50.8m) Altitude: 2036m (+30.3m) Datum: WGS-84 Azimuth/Bearing: 121° S50E 1066mils True (+10°) Elevation Angle: +01.0° Horizon Angle: +04.5° Zoom: 1.0X 11212+00</p>			 <p>Date &amp; Time: Wed Aug 11, 2021 10:15:53 EDT Position: +037 257603 / -080 495777 (+50.1m) Altitude: 2098m (+36.8m) Datum: WGS-84 Azimuth/Bearing: 269° S50W 4322mils True (+13°) Elevation Angle: +03.6° Horizon Angle: +06.5° Zoom: 1.0X 11248+50</p>			
GPS Location		see photo		GPS Location		See photo
Field Station#		11212+00		Field Station#		11248+50
Pic 11 Desc.		Clean up crew prepping subsoil during restoration		Pic 12 Desc.		Subsoil stabilized

<b>A/E</b>	124300137	<b>Date/Time</b>	8/11/2021 6:10 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27127
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/12/2021 5:51 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	8/12/2021 5:51 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Aug 12, 2021 13:48:17 EDT  Position: +037.294144° / -080.391104° (-12.50)  Altitude: 2198ft (-67.18)  Datum: WGS-84  Azimuth/Bearing: 270° S90W 680mils True (-12)  Elevation Angle: -10.9°  Horizon Angle: +06.2°  Zoom: 1.0X  11812+00</p> 		<p>Date &amp; Time: Thu, Aug 12, 2021 13:53:00 EDT  Position: +037.295927° / -080.393601° (-12.50)  Altitude: 2291ft (-69.81)  Datum: WGS-84  Azimuth/Bearing: 180° S00W 330mils True (-12)  Elevation Angle: -07.1°  Horizon Angle: -00.4°  Zoom: 1.0X  11830+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11812+00	<b>Field Station#</b>	11830+00		
<b>Pic 1 Desc.</b>	Level spreader in place	<b>Pic 2 Desc.</b>	ECDs in place		
<p>Date &amp; Time: Thu, Aug 12, 2021 15:15:07 EDT  Position: +037.295252° / -080.395252° (-12.50)  Altitude: 2184ft (-66.24)  Datum: WGS-84  Azimuth/Bearing: 351° N09W 820mils True (-12)  Elevation Angle: -05.5°  Horizon Angle: -03.0°  Zoom: 1.0X  11845+00</p> 		<p>Date &amp; Time: Thu, Aug 12, 2021 15:05:45 EDT  Position: +037.294922° / -080.391922° (-12.50)  Altitude: 2254ft (-68.61)  Datum: WGS-84  Azimuth/Bearing: 180° S00W 330mils True (-12)  Elevation Angle: -05.7°  Horizon Angle: -00.5°  Zoom: 1.0X  11922+50</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11845+00	<b>Field Station#</b>	11922+50		
<b>Pic 3 Desc.</b>	Good vegetation on ROW	<b>Pic 4 Desc.</b>	Waterbars in place		
<p>Date &amp; Time: Thu, Aug 12, 2021 10:31:50 EDT  Position: +037.274592° / -080.326019° (-12.50)  Altitude: 2095ft (-63.56)  Datum: WGS-84  Azimuth/Bearing: 351° N09W 820mils True (-12)  Elevation Angle: +05.9°  Horizon Angle: +01.7°  Zoom: 1.0X  11950+00</p> 		<p>Date &amp; Time: Thu, Aug 12, 2021 10:52:59 EDT  Position: +037.274592° / -080.326019° (-12.50)  Altitude: 1938ft (-59.08)  Datum: WGS-84  Azimuth/Bearing: 347° N13W 616mils True (-12)  Elevation Angle: -05.3°  Horizon Angle: -05.7°  Zoom: 1.0X  11982+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11950+00	<b>Field Station#</b>	11982+00		
<b>Pic 5 Desc.</b>	CFS perimeter control in place	<b>Pic 6 Desc.</b>	P1 silt fence perimeter control in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2021 5:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2021 5:51 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27117
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	8/12/2021 12:21 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dusty	<b>Temperature (°F)</b>	83.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

### 5. Site Conditions


Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2021 12:21 PM	<b>Report #</b>	27117
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a regular scheduled VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The ROW is currently stable with no area of erosion discovered. Grasses are extremely dry due to drought. The Perimeter controls on JNF land are very worn but no maintenance is currently needed. All ECDs will need replacement before any ground disturbance occurs once construction resumes. The ECDs on private lands between the JNF property line at 11618+91 and Craig Creek Road (11600+01) are currently being replaced and the area is being stabilized. Slope breakers and end treatments are being refreshed as needed. The equipment bridge at access road 258.04 (11613+69) is being replaced. Other bridges in this area will be replaced when construction resumes. No sediment is currently moving on USFS or private lands. The stabilization and ECD replacement on private tracts should be completed tomorrow.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/12/2021 12:21 PM	Report #	
Pictures					
 <p>Date &amp; Time: Thu, Aug 12, 2021, 10:52:53 EDT Position: +037.336917° / -080.398534° (±5.0m) Altitude: 720m (±4.0m) Datum: WGS-84 Azimuth/Bearing: 342° 20.55' 0.00" (12.0°) Elevation Angle: -12.6° Horizon Angle: -100.2° Zoom: 1.0X 11667+50</p>		 <p>Date &amp; Time: Thu, Aug 12, 2021, 10:53:30 EDT Position: +037.336917° / -080.398534° (±5.0m) Altitude: 586m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 146° 11.74' 0.00" (12.0°) Elevation Angle: -10.4° Horizon Angle: -100.4° Zoom: 1.0X 11667+50</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11667+50		Field Station#	11661+50	
Pic 1 Desc.	ROW is stable on steep slopes. Slope breakers in place and functioning.		Pic 2 Desc.	Perimeter ECDs are in place. All CFS and SSF fabric is worn.	
 <p>Date &amp; Time: Thu, Aug 12, 2021, 10:52:27 EDT Position: +037.306930° / -080.397540° (±5.0m) Altitude: 720m (±4.0m) Datum: WGS-84 Azimuth/Bearing: 032° 42.75' 0.00" (12.0°) Elevation Angle: -21.1° Horizon Angle: -100.5° Zoom: 1.0X 11663+00</p>		 <p>Date &amp; Time: Thu, Aug 12, 2021, 10:55:03 EDT Position: +037.313741° / -080.398534° (±5.0m) Altitude: 586m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 108° 57.2E 1920mils Magnetic (±12.0°) Elevation Angle: -10.4° Horizon Angle: -100.4° Zoom: 1.0X 11663+35</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11653+00		Field Station#	11626+35	
Pic 3 Desc.	Perimeter ECDs are in place. Many are worn.		Pic 4 Desc.	Perimeter ECDs are in place.	
 <p>Date &amp; Time: Thu, Aug 12, 2021, 10:37:24 EDT Position: +037.314622° / -080.516917° (±5.0m) Altitude: 585m (±8.0m) Datum: WGS-84 Azimuth/Bearing: 107° 57.3E 1902mils Magnetic (±12.0°) Elevation Angle: -07.2° Horizon Angle: -102.2° Zoom: 1.0X 11626+04 S-HH18</p>		 <p>Date &amp; Time: Thu, Aug 12, 2021, 10:41:16 EDT Position: +037.314607° / -080.40126° (±10.0m) Altitude: 591m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 261° S81W 4640mils Magnetic (±18°) Elevation Angle: -01.4° Horizon Angle: -01.6° Zoom: 1.0X 11619+00</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11626+04		Field Station#	11619+00	
Pic 5 Desc.	The S-HH18 crossing is currently stable.		Pic 6 Desc.	Private lands are being stabilized with seed and mulch.	



<b>AFE</b>	124300137	<b>Date/Time</b>	8/12/2021 12:21 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 10:49:14 EDT Position: +037 213426 / -080 402426 (±5.0m) Altitude: 579m (±8.0m) Datum: WGS-84 Azimuth/Bearing: 198° N22W 800mils Magnetic (±12°) Elevation Angle: -11.5° Horizon Angle: -03.7° Zoom: 1.0X 11613+69 on MN-258.04</small></p>		 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 11:31:14 EDT Position: +037 213423 / -080 402424 (±5.0m) Altitude: 580m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 004° N04E 0071mils Magnetic (±12°) Elevation Angle: -11.5° Horizon Angle: -03.7° Zoom: 1.0X 11609+00</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11613+69	<b>Field Station#</b>	11609+00		
<b>Pic 7 Desc.</b>	Equipment bridge repaired at S-RR13 on access road MN-258.04.	<b>Pic 8 Desc.</b>	End treatments are being replaced where needed.		
 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 11:32:09 EDT Position: +037 213422 / -080 404517 (±5.0m) Altitude: 585m (±4.0m) Datum: WGS-84 Azimuth/Bearing: 200° S20W 3556mils Magnetic (±12°) Elevation Angle: -04.0° Horizon Angle: -00.9° Zoom: 1.0X 11608+17, S-006</small></p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>			
<b>Field Station#</b>	11608+17	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	ECDs have been replaced south side of the S-006 crossing.	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2021 12:21 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27147
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	8/12/2021 5:33 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Dusty	<b>Temperature (°F)</b>	91.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2021 5:33 PM	<b>Report #</b>	27147
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Attended daily construction conference call. Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last VA SWPPP inspection environmental crew has continued replacing all old controls, rebuilding waterbars, adding waterbars where needed, removing logs from LOD to be hauled off, and will stabilize area once completed. Sensitive resource buffer were in place at stream S-IJ52, S-EF62, S-EF65, S-MN22, and S-MN21. RCE's we're in place at Main Line Valve 26 entrance and Mount Tabor Road crossing. Crew recently replaced geotextile fabric and cap mats at timber mat bridge over stream S-MN22. Due to length in time since last rain event dust became an issue. Crews are currently watering ROW travel lane to minimize dust. No deficiencies were located during VA SWPPP inspection.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/12/2021 5:33 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 12:55:53 EDT Position: +037.294833° / -080.350418° (±29981.8m) Altitude: 2027ft (±32.0m) Datum: WGS-84 Azimuth/Bearing: 103° N10E 2000mils True (±15°) Elevation Angle: +04.5° Horizon Angle: 90.0° Zoom: 1.0x 11674+00 Sump Pit</small></p>		 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 12:55:53 EDT Position: +037.294833° / -080.350418° (±29981.8m) Altitude: 2027ft (±32.0m) Datum: WGS-84 Azimuth/Bearing: 103° N10E 2000mils True (±15°) Elevation Angle: +04.5° Horizon Angle: 90.0° Zoom: 1.0x 11674+00 Sump Pit</small></p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11674+00		<b>Field Station#</b>	11687+00	
<b>Pic 1 Desc.</b>	Sump pit, waterbar, and end treatment in place.		<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-MN21.	
 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 12:56:53 EDT Position: +037.294833° / -080.350418° (±29981.8m) Altitude: 2027ft (±32.0m) Datum: WGS-84 Azimuth/Bearing: 103° N10E 2000mils True (±15°) Elevation Angle: +04.5° Horizon Angle: 90.0° Zoom: 1.0x 11722+00 Triple Stack CFS</small></p>		 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 12:56:53 EDT Position: +037.294833° / -080.350418° (±29981.8m) Altitude: 2027ft (±32.0m) Datum: WGS-84 Azimuth/Bearing: 103° N10E 2000mils True (±15°) Elevation Angle: +04.5° Horizon Angle: 90.0° Zoom: 1.0x 11761+00 Top Soil Stabilized</small></p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11722+00		<b>Field Station#</b>	11761+00	
<b>Pic 3 Desc.</b>	Triple stack CFS in place along LOD.		<b>Pic 4 Desc.</b>	Top soil stabilized and CFS checks in place.	
 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 15:53:01 EDT Position: +037.294833° / -080.351408° (±29981.8m) Altitude: 2027ft (±32.0m) Datum: WGS-84 Azimuth/Bearing: 103° N10E 2000mils True (±15°) Elevation Angle: +04.5° Horizon Angle: 90.0° Zoom: 1.0x 11767+00 Waterbar</small></p>		 <p><small>Date &amp; Time: Thu, Aug 12, 2021, 09:23:02 EDT Position: +037.294833° / -080.349711° (±29981.8m) Altitude: 2137ft (±39.4m) Datum: WGS-84 Azimuth/Bearing: 345° N15W 6133mils True (±15°) Elevation Angle: +04.5° Horizon Angle: 90.0° Zoom: 1.0x 11788+00 Logs Staged</small></p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11767+00		<b>Field Station#</b>	11788+00	
<b>Pic 5 Desc.</b>	Waterbar being installed at end of day.		<b>Pic 6 Desc.</b>	Logs being staged at road crossing to be hauled off.	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2021 5:33 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/12/2021 5:33 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27197
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/13/2021 5:06 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	87.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 5:06 PM	<b>Report #</b>	27197
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection of LDY 28 Western section of the yard: RCE is maintained in acceptable condition. Buses, trucks, and trailers not currently in use are being stored at this portion of the yard. Eastern section of the yard: This portion of the yard has heavy trucking activity throughout the workday. PPL truck drives and their escorts park their personal vehicles here. The RCE is maintained in acceptable condition. CFS perimeter controls and overhead utility flagging are in place. Rock surface of the yard is in acceptable condition. Waste management and housekeeping are acceptable.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time	8/13/2021 5:06 PM	Report #	
Pictures					
<p>Date &amp; Time: Fri Aug 13, 2021 11:56:02 EDT Position: +037.333845° / -080.808190° (-0.0011°) Altitude: 1568ft (+11.2ft) Datum: WGS 84 Azimuth Bearing: 010° N15E 0178mils True (+21°) Elevation Angle: +01.4° Horizon Angle: +00.5° Zoom: 1.0X 12005+00</p> 		<p>Date &amp; Time: Fri Aug 13, 2021 11:56:02 EDT Position: +037.333845° / -080.808190° (-0.0011°) Altitude: 1568ft (+11.2ft) Datum: WGS 84 Azimuth Bearing: 010° N15E 0178mils True (+21°) Elevation Angle: +01.4° Horizon Angle: +00.5° Zoom: 1.0X 12005+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Vehicles not in use being stored at yard		<b>Pic 2 Desc.</b>	
<p>Date &amp; Time: Fri Aug 13, 2021 12:00:10 EDT Position: +037.333845° / -080.808190° (-0.0011°) Altitude: 1568ft (+11.2ft) Datum: WGS 84 Azimuth Bearing: 027° N27E 0480mils True (+15°) Elevation Angle: +07.6° Horizon Angle: +00.0° Zoom: 1.0X 12005+00</p> 		<p>Date &amp; Time: Fri Aug 13, 2021 12:00:10 EDT Position: +037.333845° / -080.808190° (-0.0011°) Altitude: 1568ft (+11.2ft) Datum: WGS 84 Azimuth Bearing: 027° N27E 1013mils True (+15°) Elevation Angle: +01.1° Horizon Angle: +00.4° Zoom: 1.0X 12005+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Rock surface in acceptable condition		<b>Pic 4 Desc.</b>	
<p>Date &amp; Time: Fri Aug 13, 2021 12:05:52 EDT Position: +037.333845° / -080.808190° (-0.0011°) Altitude: 1568ft (+11.2ft) Datum: WGS 84 Azimuth Bearing: 070° N70E 1702mils True (+12.4°) Elevation Angle: +01.1° Horizon Angle: +00.0° Zoom: 1.0X 12005+00</p> 		<p>Date &amp; Time: Fri Aug 13, 2021 12:02:07 EDT Position: +037.333845° / -080.808190° (-0.0011°) Altitude: 1568ft (+11.2ft) Datum: WGS 84 Azimuth Bearing: 294° N06W 522mils True (+13.4°) Elevation Angle: +12.2° Horizon Angle: +02.6° Zoom: 1.0X 12005+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		CFS perimeter control in place		<b>Pic 6 Desc.</b>	
				Secondary containment in place	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 5:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 5:06 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27193
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/13/2021 4:44 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+01
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	85.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.10
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 4:44 PM	<b>Report #</b>	27193
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to MP 219.70) No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. ROW is dry and in stable condition up until JNF property line ST# 11553+66. Final restoration has occurred between ST# 11526+50 and ST# 11548+00. Permanent waterbars with level spreaders are installed. Topsoil has been put back. Perimeter controls and end treatments are in place. Permanent seed and hydro mulch has been applied. Daylight drains with rock outlet protection and temporary CFS waterbars are in place. Proper signage has been posted to keep vehicle travel off of restored ROW. ROW is dry and stabilized throughout JNF with large areas of vegetation. Waterbars with end treatments and perimeter controls are in place. 50' buffers are in place at stream crossings S-PP22, S-PP21, S-PP20. AR-258.02 and Craig Creek road crossing RCEs are maintained in acceptable condition. Craig Creek rain gauge measured 0.1" of rainfall accumulated on 8/12/21. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		8/13/2021 4:44 PM		Report #			
Pictures											
<p>Date &amp; Time: Fri, Aug 13, 2021, 08:38:57 EDT Position: +037.325497° / +080.426574° (+21.2M) Altitude: 2282ft (+13.2M) Datum: WGS-84 Azimuth/Bearing: 066° N05E 1138mils True (+2°) Elevation Angle: +33.0° Horizon Angle: -01.1° Zoom: 1.0X 11528+00</p> 								<p>Date &amp; Time: Fri, Aug 13, 2021, 08:44:38 EDT Position: +037.326507° / +080.436117° (+21.2M) Altitude: 2283ft (+13.2M) Datum: WGS-84 Azimuth/Bearing: 100° S04E 2036mils True (+2°) Elevation Angle: +37.5° Horizon Angle: 01.2° Zoom: 1.0X 11533+00</p> 			
GPS Location		See photo				GPS Location		See photo			
Field Station#		11528+00				Field Station#		11533+00			
Pic 1 Desc.		Temporary CFS waterbars in place				Pic 2 Desc.		Good vegetation on ROW			
<p>Date &amp; Time: Fri, Aug 13, 2021, 09:15:49 EDT Position: +037.336177° / +080.416597° (+15.1M) Altitude: 2390ft (+13.1M) Datum: WGS-84 Azimuth/Bearing: 145° S09E 3394mils True (+2°) Elevation Angle: +35.8° Horizon Angle: -00.5° Zoom: 1.0X 11543+00</p> 				<p>Date &amp; Time: Fri, Aug 13, 2021, 09:16:05 EDT Position: +037.336177° / +080.416597° (+15.1M) Altitude: 2391ft (+13.1M) Datum: WGS-84 Azimuth/Bearing: 141° S09E 3395mils True (+2°) Elevation Angle: +35.8° Horizon Angle: -02.8° Zoom: 1.0X 11545+00</p> 							
GPS Location		See photo				GPS Location		See photo			
Field Station#		11543+00				Field Station#		11545+00			
Pic 3 Desc.		Level spreaders in place				Pic 4 Desc.		CFS perimeter controls in place			
<p>Date &amp; Time: Fri, Aug 13, 2021, 09:44:30 EDT Position: +037.336577° / +080.416594° (+15.1M) Altitude: 2351ft (+12.6M) Datum: WGS-84 Azimuth/Bearing: 153° S27E 2720mils True (+12.1) Elevation Angle: -03.0° Horizon Angle: -00.5° Zoom: 1.0X 11563+00</p> 				<p>Date &amp; Time: Fri, Aug 13, 2021, 09:44:50 EDT Position: +037.33710579° / +080.436226° (+17.1M) Altitude: 2094ft (+26.2M) Datum: WGS-84 Azimuth/Bearing: 156° S24E 2773mils True (+12) Elevation Angle: -21.2° Horizon Angle: -02.8° Zoom: 1.0X 11583+00</p> 							
GPS Location		See photo				GPS Location		See photo			
Field Station#		11563+00				Field Station#		11583+00			
Pic 5 Desc.		Waterbars in place				Pic 6 Desc.		P1 silt fence perimeter control			



<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 4:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 4:44 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	27196
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	8/13/2021 5:00 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	87.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 5:00 PM	<b>Report #</b>	27196
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection of LDY-26 Yard is used to store various materials needed for construction. Both MVP and PPL employee personal vehicles are parked here. Large fuel island containment is maintained in acceptable condition. With secondary containments in place to be used when fueling vehicles. Waste management and housekeeping are acceptable. Dumpsters are in place with adequate signage to dispose of materials properly into correct bins. Rock surface of the yard is in acceptable condition. CFS perimeter controls and orange safety fence are in place. Light plants, porta potties, gas cans, and other hazardous materials are in secondary containment units. Spill kits and fire extinguishers are available on site.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	8/13/2021 5:00 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Aug 13, 2021, 12:20:49 EDT Position: +037319522 / -880.65767 / +15.5 ft Altitude: 1805ft (+15.5 ft) Datum: WGS-84 Azimuth Bearing: 232° S52W 12.2mils True (+12.2°) Elevation Angle: -48.8° Horizon Angle: -02.9° Zoom: 1.0X 12005+00</p>		 <p>Date &amp; Time: Fri, Aug 13, 2021, 12:25:21 EDT Position: +037319522 / -880.65767 / +15.5 ft Altitude: 1805ft (+15.5 ft) Datum: WGS-84 Azimuth Bearing: 232° S52W 12.2mils True (+12.2°) Elevation Angle: -48.8° Horizon Angle: -02.9° Zoom: 1.0X 12005+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Dumpsters in place	<b>Pic 2 Desc.</b>	Secondary containment in place		
 <p>Date &amp; Time: Fri, Aug 13, 2021, 12:41:07 EDT Position: +037319522 / -880.65767 / +15.5 ft Altitude: 1805ft (+15.5 ft) Datum: WGS-84 Azimuth Bearing: 211° S21W 3751mils True (+12.1°) Elevation Angle: -13.3° Horizon Angle: -03.0° Zoom: 1.0X 12005+00</p>		 <p>Date &amp; Time: Fri, Aug 13, 2021, 12:41:08 EDT Position: +037319522 / -880.65767 / +15.5 ft Altitude: 1805ft (+15.5 ft) Datum: WGS-84 Azimuth Bearing: 109° S71E 4990mils True (+12.1°) Elevation Angle: -10.7° Horizon Angle: -02.5° Zoom: 1.0X 12005+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	Secondary containment in place	<b>Pic 4 Desc.</b>	Secondary containments place		
 <p>Date &amp; Time: Fri, Aug 13, 2021, 12:41:38 EDT Position: +037319522 / -880.65767 / +15.5 ft Altitude: 1298ft (+11.8 ft) Datum: WGS-84 Azimuth Bearing: 075° N75E 1333mils True (+12.1°) Elevation Angle: -13.2° Horizon Angle: -00.7° Zoom: 1.0X 12005+00</p>		 <p>Date &amp; Time: Fri, Aug 13, 2021, 12:41:38 EDT Position: +037319522 / -880.65767 / +15.5 ft Altitude: 1298ft (+11.8 ft) Datum: WGS-84 Azimuth Bearing: 331° N29W 5884mils True (+12.1°) Elevation Angle: -12.2° Horizon Angle: -00.5° Zoom: 1.0X 12005+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	Orange construction safety fence in place	<b>Pic 6 Desc.</b>	CFS perimeter control in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 5:00 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/13/2021 5:00 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		