









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	27186	
Inspector	Ben Davenport				Date/Time	8/16/2021 9:06 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	14694+77	
State	VA	Inspection Area	Partial		Station End	14802+19	
County	Franklin	Ground	Muddy		Temperature (°F)	81.00	
Municipality	N/A	Weather	Cloudy		Rain Gauge (in)	1.30	
					Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)		Acceptable					
Waterbar		Acceptable					
Equipment Bridge		Acceptable					
Compost Filter Sock		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Sediment Filter Log		Acceptable					
Temporary Diversion Berm		Acceptable					
Sump Pit		Acceptable					
Waterbar End Treatment		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

AFE	124300139	Date/Time	8/16/2021 9:06 AM	Report #	27186
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Checked rain gauges in covered area -Received instruction from Lead EI for daily tasks -Cloudy weather with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 — 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW with environmental crew making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section -Continue to monitor ROW for signs of erosion -No items added to punch list -Rain Gauge Totals: +Indian Cave: 1.10 inches recorded +Armstrong: 1.30 inches recorded					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/16/2021 9:06 AM	Report #	
Pictures					
					
36°59'17" N 79°42'24" W 274°W COURSE 267° GPS Sorry no results found			36°59'16" N 79°42'1" W 276°W COURSE 307° GPS Sorry no results found		
08.16.2021 10:17:48 Accur +/-52.9 Ft ALT 892 Ft			08.16.2021 10:10:06 Accur +/-24.7 Ft ALT 891 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14705+50		Field Station#	14722+60	
Pic 1 Desc.	ROW stabilized and vegetated in temporary area		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer as well as perimeter of ROW	
					
36°59'15" N 79°41'53" W 2°N COURSE 314° GPS Union Hall, VA 24176, United States			36°59'11" N 79°41'45" W 280°W COURSE 314° GPS Union Hall, VA 24176, United States		
08.16.2021 10:07:04 Accur +/-154.3 Ft ALT 934 Ft			08.16.2021 10:03:52 Accur +/-175.7 Ft ALT 934 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14731+00		Field Station#	14739+00	
Pic 3 Desc.	Sump pit and CFS end treatment in good condition and properly filtering water off ROW		Pic 4 Desc.	ROW stabilized and vegetated in temporary area	
					
36°58'40" N 79°40'50" W 6°N COURSE 298° GPS Union Hall, VA 24176, United States			36°58'37" N 79°40'45" W 332°NW COURSE 0° GPS Union Hall, VA 24176, United States		
08.16.2021 09:48:51 Accur +/-656.2 Ft ALT 940 Ft			08.16.2021 09:35:50 Accur +/-56.0 Ft ALT 0 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14772+00		Field Station#	14799+00	
Pic 5 Desc.	Temporary diversion berm stabilized and vegetated		Pic 6 Desc.	ROW stabilized and vegetated in temporary area	

A/E	124300139	Date/Time	8/16/2021 9:06 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	8/16/2021 9:06 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27279
Inspector	Ben Farmer			Date/Time	8/16/2021 2:43 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Damp	Temperature (°F)	75.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Communication	CFS needs to be restaked.	Addressed	8/16/2021
Equipment Bridge		Acceptable			
Rock Filter		Acceptable			
Rock Filter Outlet		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Slope Drain Pipe		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/16/2021 2:43 PM	Report #	27279
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 75F) Rain Gauge= 1.0" 15142+66-15260+00 -EI began inspection at Rockcreek Rd. -RCEs are in good condition at all road crossings. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00. -Equipment bridge ECDs are in place and functioning. -P1 is in good condition at all stream and wetland crossings. -Turbid water entering ROW from upstream source at stream S-C7. Turbid water is not from ROW activity. -Slope drain is functioning as intended at 15170+00. -CFS needs to be maintained and restaked at 15194+00. Environmental crew has corrected this issue. -CFS needs to be maintained and restaked at 15195+00. Environmental crew has corrected this issue. -Drainage ECDs are in good condition at 15195+00. -Waterbars are in good condition throughout this section. -Drainage features and permanent waterbars are in good condition throughout restored area of ROW. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/16/2021 2:43 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15142+66		Field Station#	15165+57	
Pic 1 Desc.	RCE is in good condition at Rockcreek Rd.		Pic 2 Desc.	Rock inlet remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15166+00		Field Station#	15167+95	
Pic 3 Desc.	Rock outlet remains in good condition.		Pic 4 Desc.	P1 is in good condition at stream buffer.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15167+95		Field Station#	15168+00	
Pic 5 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 6 Desc.	Turbid water flowing in stream S-C7 from unknown upstream source outside LOD.	

AFE	124300139	Date/Time	8/16/2021 2:43 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15172+00	
Pic 7 Desc.	Slope drain is in good condition and functioning as intended.		Pic 8 Desc.	Waterbars are in good condition and functioning throughout this section.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15194+00		Field Station#	15194+00	
Pic 9 Desc.	CFS needs to be cleared of sediment and restaked.		Pic 10 Desc.	Environmental crew has corrected this issue.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15195+00		Field Station#	15195+00	
Pic 11 Desc.	CFS needs to be maintained and restaked.		Pic 12 Desc.	Environmental crew has corrected this issue.	







A/E	124300139	Date/Time	8/16/2021 2:43 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27276
Inspector	John White			Date/Time	8/16/2021 1:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Wet	Temperature (°F)	78.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	2.50
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Communication	Contractor removed trash from RCE			
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/16/2021 1:28 PM	Report #	27276
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There was one issue identified and repaired by the Contractor (3rd party damage). Checked rain gauges, Anderson Mill #2=.9", Mill Creek =.9", Transco =1.9". Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/16/2021 1:28 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15619+48	Field Station#	15619+48		
Pic 1 Desc.	Observing trash that needs to be removed from the RCE (3rd party damage)	Pic 2 Desc.	Observing clean RCE		
					
GPS Location	O	GPS Location	O		
Field Station#	15645+00	Field Station#	15632+00		
Pic 3 Desc.	Observing temporary stabilization, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15595+00	Field Station#	15595+60		
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 6 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's		

AFE	124300139	Date/Time	8/16/2021 1:28 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location			
Field Station#	15590+00	Field Station#			
Pic 7 Desc.	Observing temporary stabilization and water bar	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	8/16/2021 1:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27274
Inspector	Justin Burch			Date/Time	8/16/2021 12:10 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Wet	Temperature (°F)	75.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	2.20
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Plunge Pool	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Fabric was attached to the fence	Immediate	8/16/2021	
Sump Pit	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	8/16/2021 12:10 PM	Report #	27274
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). One issue was submitted for the punch list which consisted of a super silt fence at which the fabric was detached from the wire fence. The contractor addressed this issue immediately. Other inspected ECDs were in compliance at the time of inspection. The EI did not observe that the contractor has worked in the inspection area since the last inspection. Since the last SWPPP inspection the area has received five rainfall events with totals of 3.50" at Grassy Hill Road and 3.20" at Bonbrook Mill Road #1. Intermittent rain fell throughout the morning. The ROW ground condition is wet. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13910+00 and from 13921+00 to 13940+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/16/2021 12:10 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	13949+00		Field Station#	13943+00	
Pic 1 Desc.	Waterbar end treatment and super silt fence in acceptable conditions		Pic 2 Desc.	Clean water diversion plunge pool in acceptable condition	
					
GPS Location	0		GPS Location	0	
Field Station#	13920+00		Field Station#	13893+00	
Pic 3 Desc.	P1 silt fence and permanent vegetative stabilization in acceptable conditions		Pic 4 Desc.	Fabric detached from wire fence on super silt fence, contractor repaired it immediately	
					
GPS Location	0		GPS Location	0	
Field Station#	13893+00		Field Station#	13890+00	
Pic 5 Desc.	Super silt fence after maintenance		Pic 6 Desc.	Sump pit and slope drain pipe in acceptable conditions	

A/E	124300139	Date/Time	8/16/2021 12:10 PM	Report #	
Pictures					
North West Elevation 132°SE (T) 37°3'18"N, 79°54'51"W ±3061ft ▲ 1129ft 		Insert image here			
GPS Location	0	GPS Location			
Field Station#	13883+00	Field Station#			
Pic 7 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	8/16/2021 12:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27282
Inspector	Charles Head			Date/Time	8/16/2021 4:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Wet	Temperature (°F)	82.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	2.10
				Rain Accumulation Time (days)	2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	CFS requires maintenance		
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	8/16/2021 4:25 PM	Report #	27282
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/16/2021 4:25 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14434+01	Field Station#	14415+00		
Pic 1 Desc.	Approximately 14434+01. Overview of stream crossing, equipment bridge and ECDs at stream S-GH40.		Pic 2 Desc.	Approximately 14415+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14382+00	Field Station#	14360+00		
Pic 3 Desc.	Approximately 14382+00. Overview of ROW.		Pic 4 Desc.	Approximately 14360+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14333+50	Field Station#	14315+60		
Pic 5 Desc.	Approximately 14333+50. Overview of road crossing and RCEs.		Pic 6 Desc.	Approximately 14315+60. CFS requires maintenance.	

A/E	124300139	Date/Time	8/16/2021 4:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	8/16/2021 4:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27337
Inspector	Ben Farmer			Date/Time	8/17/2021 2:40 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Damp	Temperature (°F)	72.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/17/2021 2:40 PM	Report #	27337
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 72 F) Rain Gauge= 0.0" 15260+00-15370+62 -EI began inspection at Snowberry Rd. -RCEs are in good condition at all road crossings. -MVP-PI-332 is in good condition with controls in place. -Equipment bridge ECDs are in place and functioning at all stream and wetland crossings. -CWDs are functioning as intended throughout this section. -CWD inlets are in good condition. -Perimeter P1 is in good condition throughout this section. -Waterbars and end treatments are in good condition and functioning. -Wetland buffer P1 is in good condition at 15311+78. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/17/2021 2:40 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15370+62		Field Station#	15370+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings.		Pic 2 Desc.	Vegetation continues to fill in throughout this section.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15350+00		Field Station#	15346+90	
Pic 3 Desc.	MVP-PI-332 remains in good condition with controls in place.		Pic 4 Desc.	Equipment bridge ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15346+00		Field Station#	15344+13	
Pic 5 Desc.	P1 is in good condition at all stream and wetland buffers.		Pic 6 Desc.	Waterbars are functioning as intended.	

AFE	124300139	Date/Time	8/17/2021 2:40 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15338+00		Field Station#	15338+00	
Pic 7 Desc.	CWDs are in good condition and functioning.		Pic 8 Desc.	CWD inlets are in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15336+00		Field Station#	15311+78	
Pic 9 Desc.	Perimeter P1 is in good condition.		Pic 10 Desc.	Wetland buffer P1 remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15310+00		Field Station#	15299+00	
Pic 11 Desc.	Perimeter CFS is in good condition throughout this section.		Pic 12 Desc.	CWD is functioning as intended.	







A/E	124300139	Date/Time	8/17/2021 2:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27339
Inspector	Charles Head			Date/Time	8/17/2021 4:12 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Wet	Temperature (°F)	77.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/17/2021 4:12 PM	Report #	27339
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/17/2021 4:12 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14456+50	Field Station#	14518+50		
Pic 1 Desc.	Approximately 14456+50. Overview of ROW.	Pic 2 Desc.	Approximately 14518+50. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14526+00	Field Station#	14530+00		
Pic 3 Desc.	Approximately 14526+00. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14530+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14546+33	Field Station#	14542+00		
Pic 5 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.	Pic 6 Desc.	Approximately 14542+00. Overview of ROW.		

A/E	124300139	Date/Time	8/17/2021 4:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






A/E	124300139	Date/Time	8/17/2021 4:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27328
Inspector	Justin Burch			Date/Time	8/17/2021 11:04 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Wet	Temperature (°F)	77.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	2.90
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Reinforce Filter Fence)	Communication				
Equipment Bridge	Communication				
Waterbar	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar End Treatment	Acceptable				
Sump Pit	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	8/17/2021 11:04 AM	Report #	27328
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). Five issues were submitted for the punch list consisting of four locations where P1 silt fence required maintenance (one of which appeared to be damaged by wildlife) and one location where the geotech fabric was detached from equipment bridge at the sideboard. Other ECDs were in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the inspection area since the last inspection. • Since the last SWPPP inspection the area has received five rainfall events with totals of 3.40" at Grassy Hill Road, 2.90" at Bonbrook Mill Road #1 and 2.95" at Farm View Road. • The ROW ground condition is wet. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14011+00 to 14018+00. • Temporary vegetative stabilization was adequately established to inhibit erosion at the time of inspection 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/17/2021 11:04 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14057+00	Field Station#	14046+00		
Pic 1 Desc.	P1 silt fence has broken stakes	Pic 2 Desc.	P1 silt fence has a broken stake		
					
GPS Location	0	GPS Location	0		
Field Station#	14045+71	Field Station#	14042+80		
Pic 3 Desc.	Geotech fabric is detached from the equipment bridge	Pic 4 Desc.	Hole in P1 silt fence, appears to be damaged by wildlife		
					
GPS Location	0	GPS Location	0		
Field Station#	14043+00	Field Station#	13087+00		
Pic 5 Desc.	P1 silt fence has broken stakes	Pic 6 Desc.	Waterbar and temporary vegetative stabilization in acceptable conditions		

AFE	124300139	Date/Time	8/17/2021 11:04 AM	Report #	
Pictures					
 <p>348°N (T) 17S NB 98982 01201 ±42ft ▲ 1017ft</p> <p>13090+00 17 Aug 2021, 10:00:34</p>		 <p>1°N (T) 17S NB 98974 01226 ±213ft ▲ 1011ft</p> <p>13090+00 17 Aug 2021, 10:00:17</p>			
GPS Location	0	GPS Location	0		
Field Station#	13090+00	Field Station#	13090+00		
Pic 7 Desc.	Waterbar in acceptable condition		Pic 8 Desc.	Waterbar end treatment in acceptable condition	
 <p>119°SE (T) 17S NB 98413 00591 ±272ft ▲ 1134ft</p> <p>13063+00 17 Aug 2021, 10:16:39</p>		 <p>117°SE (T) 17S NB 98340 00823 ±236ft ▲ 1145ft</p> <p>13060+00 17 Aug 2021, 10:18:51</p>			
GPS Location	0	GPS Location	0		
Field Station#	13063+00	Field Station#	13060+00		
Pic 9 Desc.	Sump pit in acceptable condition		Pic 10 Desc.	Clean water diversion pipe in acceptable condition	
 <p>287°W (T) 17S PB 03042 05133 ±6971ft ▲ 1188ft</p> <p>14011+00 17 Aug 2021, 10:28:15</p>		 <p>0°N (T) 17S NB 99378 01682 ±29ft ▲ 1043ft</p> <p>14012+00 17 Aug 2021, 10:28:46</p>			
GPS Location	0	GPS Location	0		
Field Station#	14011+00	Field Station#	14012+00		
Pic 11 Desc.	P1 silt fence in acceptable condition		Pic 12 Desc.	Permanent vegetative stabilization in acceptable condition	

A/E	124300139	Date/Time	8/17/2021 11:04 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27278
Inspector	Ben Davenport			Date/Time	8/17/2021 11:09 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Muddy	Temperature (°F)	81.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.10
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Equipment Bridge	Acceptable				
Sediment Filter Log	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/17/2021 11:09 AM	Report #	27278
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Checked rain gauges in covered area -Received instruction from Lead EI for daily tasks -Cloudy with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14802+19 — 14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Walked ROW with environmental foreman looking for potential environmental issues or maintenance requirements -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed condition of stabilization and vegetation in section both permanent and temporary areas of ROW; no issues observed -Continue to monitor ROW for signs of erosion -No items added to punch -Rain Gauge Totals +Indian Cave: 0.60 inches recorded +Armstrong: 1.10 inches recorded 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/17/2021 11:09 AM	Report #	
Pictures					
					
36°58'35" N 79°40'41" W 196°S COURSE 321° GPS 08.17.2021 09:30:44 Accur +/-46.2 Ft ALT 935 Ft			36°58'35" N 79°40'39" W 146°SE COURSE 180° GPS 08.17.2021 09:31:24 Penhook, VA 24137, United States Accur +/-15.3 Ft ALT 923 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14803+00		Field Station#	14804+99	
Pic 1 Desc.	Perimeter CFS, SSF, and P1 silt fence in place and functional		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer	
					
36°58'29" N 79°40'28" W 129°SE COURSE 158° GPS 08.17.2021 09:36:34 Penhook, VA 24137, United States Accur +/-285.7 Ft ALT 950 Ft			36°58'29" N 79°40'28" W 128°SE COURSE 158° GPS 08.17.2021 09:39:21 Penhook, VA 24137, United States Accur +/-2628.9 Ft ALT 950 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14816+07		Field Station#	14823+54	
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer	
					
36°58'16" N 79°39'28" W 111°E COURSE 82° GPS 08.17.2021 10:00:50 1760 Bar Ridge Rd, Penhook, VA 24137, United States Accur +/-20.1 Ft ALT 928 Ft			36°58'15" N 79°39'28" W 185°S COURSE 138° GPS 08.17.2021 10:01:02 1760 Bar Ridge Rd, Penhook, VA 24137, United States Accur +/-19.6 Ft ALT 925 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14868+00		Field Station#	14870+43	
Pic 5 Desc.	Slope drain tile and CFS checks in good condition		Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer	

A/E	124300139	Date/Time	8/17/2021 11:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	8/17/2021 11:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27326
Inspector	John White			Date/Time	8/17/2021 10:15 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Wet	Temperature (°F)	74.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	2.70
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/17/2021 10:15 AM	Report #	27326
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Checked rain gauges, Anderson Mill #2=.2", Mill Creek =1.0", Transco =.5". Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/17/2021 10:15 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15735+00	Field Station#	15730+00		
Pic 1 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 2 Desc.	Observing temporary stabilization and water bar		
					
GPS Location	O	GPS Location	O		
Field Station#	15720+00	Field Station#	15713+52		
Pic 3 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 4 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15706+00	Field Station#	15700+40		
Pic 5 Desc.	Observing temporary stabilization,water bar, erosion control blanket and cfs checks	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

A/E	124300139	Date/Time	8/17/2021 10:15 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



A/E	124300139	Date/Time	8/17/2021 10:15 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27381
Inspector	Justin Burch			Date/Time	8/18/2021 11:25 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Wet	Temperature (°F)	86.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	3.60
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Sump Pit	Acceptable				
Slope Drain Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/18/2021 11:25 AM	Report #	27381
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). An environmental laborer from Precision Pipeline accompanied the EI on this inspection. No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the inspection area since the last inspection. • Since the last SWPPP inspection the area has received five rainfall events with totals 3.60" at Bonbrook Mill Road #1 and 2.85" at Farm View Road. • The ROW ground condition is wet. • At the time of inspection temporary vegetative was observed as sufficiently established to inhibit erosion. • At the time of inspection permanent vegetative stabilization was observed as sufficiently established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/18/2021 11:25 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14169+00	Field Station#	14169+00		
Pic 1 Desc.	Permanent vegetative stabilization and waterbar in acceptable conditions		Pic 2 Desc.	Waterbar end treatment in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14156+00	Field Station#	14153+00		
Pic 3 Desc.	Sump pit and slope drain pipe in acceptable conditions		Pic 4 Desc.	Waterbar and waterbar end treatment in acceptable conditions	
					
GPS Location	0	GPS Location	0		
Field Station#	14109+00	Field Station#	14106+00		
Pic 5 Desc.	Waterbar end treatment and perimeter CFS in acceptable conditions		Pic 6 Desc.	Super silt fence and P1 silt fence in acceptable conditions	

AFE	124300139	Date/Time	8/18/2021 11:25 AM	Report #	
Pictures					
GPS Location	0		GPS Location	0	
Field Station#	14114+00		Field Station#	14103+00	
Pic 7 Desc.	Permanent vegetative stabilization and perimeter CFS in acceptable conditions		Pic 8 Desc.	Temporary vegetative stabilization and waterbar in acceptable conditions	
			Insert image here		
GPS Location	0		GPS Location		
Field Station#	14150+00		Field Station#		
Pic 9 Desc.	Temporary vegetative stabilization and perimeter CFS in acceptable conditions		Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	8/18/2021 11:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27404
Inspector	Charles Head			Date/Time	8/18/2021 5:00 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Wet	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/18/2021 5:00 PM	Report #	27404
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/18/2021 5:00 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14648+00	Field Station#	14642+00		
Pic 1 Desc.	Approximately 14648+00. Overview of ROW.	Pic 2 Desc.	Approximately 14642+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14599+25	Field Station#	14582+85		
Pic 3 Desc.	Approximately 14599+25. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14582+85. Overview of stream crossing, equipment bridge and ECDs at stream S-E17.		
					
GPS Location	0	GPS Location	0		
Field Station#	14568+10	Field Station#	14575+00		
Pic 5 Desc.	Approximately 14568+10. Overview of stream crossing, equipment bridge and ECDs at stream S-E18.	Pic 6 Desc.	Approximately 14575+00. Overview of ROW.		







A/E	124300139	Date/Time	8/18/2021 5:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	8/18/2021 5:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27388
Inspector	Ben Farmer			Date/Time	8/18/2021 1:53 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Damp	Temperature (°F)	80.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	8/18/2021 1:53 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15480+00		Field Station#	15475+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings.		Pic 2 Desc.	Rock outlet appears to be in good condition along this drainage.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15465+00		Field Station#	15460+81	
Pic 3 Desc.	No evidence of sedimentation from 3rd party disturbance.		Pic 4 Desc.	No evidence of sedimentation from 3rd party rock outlet. CWD is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15460+81		Field Station#	15457+00	
Pic 5 Desc.	CWD in good condition. No evidence of sedimentation.		Pic 6 Desc.	Drainage feature is in good condition with no evidence of sedimentation from 3rd party disturbance.	

AFE	124300139	Date/Time	8/18/2021 1:53 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15453+00		Field Station#	15445+00	
Pic 7 Desc.	CWD is in good condition. No evidence of sedimentation from 3rd party disturbance.		Pic 8 Desc.	Vegetation continues to fill in throughout this section of ROW.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15427+00		Field Station#	15427+30	
Pic 9 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 10 Desc.	Stream buffers remain well vegetated and ECDs are in good condition and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15400+00		Field Station#	15380+00	
Pic 11 Desc.	Vegetation continues to fill in throughout this section.		Pic 12 Desc.	Waterbars are functioning as intended.	







AFE	124300139	Date/Time	8/18/2021 1:53 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location			
Field Station#	15375+00	Field Station#			
Pic 13 Desc.	Drainage ECDs are in good condition and functioning.	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27376
Inspector	Logan Box			Date/Time	8/18/2021 4:18 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Wet	Temperature (°F)	86.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sump Pit	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/18/2021 4:18 PM	Report #	27376
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Traveled to rain gauge locations checking rain amounts as rain continues. Documented and sent in results.</p> <p>Traveled road crossings checking streams and ECDs that were accessible. Monitored RCEs to be sure they were clean and clear from mud and debris. Monitored bar ditches near the row to be sure no environmental issues from the project were entering the ditches.</p> <p>Conducted vegetation observation as well as checking sump pits and end treatment after recent rain events. Monitored equipment bridges and protection.</p> <p>Total measurable rainfall for today was 0.5" , row conditions were saturated.</p> <p>No environmental issues observed were observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/18/2021 4:18 PM	Report #	
Pictures					
					
GPS Location	0000	GPS Location	0000		
Field Station#	13746+56	Field Station#	13745+90		
Pic 1 Desc.	Saturated row photo taken while checking row conditions after recent rain events.		Pic 2 Desc.	Vegetation photo taken near sump pit showing good stabilization. No issues observed at the time of inspection.	
					
GPS Location	0000	GPS Location	0000		
Field Station#	13738+20	Field Station#	13692+64		
Pic 3 Desc.	Vegetation observation photo taken while monitoring row after recent rain events. No issues noted .		Pic 4 Desc.	Stream observation photo facing downstream during routine inspection today after recent rain events. No environmental issues observed at the time of inspection.	
					
GPS Location	0000	GPS Location	0000		
Field Station#	13692+64	Field Station#	13740+00		
Pic 5 Desc.	Stream observation photo facing upstream during routine inspection today. No issues observed at the time of inspection.		Pic 6 Desc.	Additional vegetation observation photo. Good coverage noted with no environmental issues observed at the time inspection.	

A/E	124300139	Date/Time	8/18/2021 4:18 PM	Report #	
Pictures					
					
GPS Location	0000	GPS Location	0000		
Field Station#	13730+00	Field Station#	13743+00		
Pic 7 Desc.	Monitored sump pit and end treatment while checking row conditions after recent rain events. No issues observed at the time of inspection.		Pic 8 Desc.	Monitored ECDs along LOD boundary. No issues observed at the time of inspection. Ecds in place and functioning.	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	8/18/2021 4:18 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27348
Inspector	Ben Davenport			Date/Time	8/18/2021 9:52 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Muddy	Temperature (°F)	81.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Communication	Routine maintenance		
Silt Fence (Filter Fabric Fence)		Communication	Routine maintenance		
Sediment Filter Log		Communication	Routine maintenance		
Vegetative Stabilization (Temporary)		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Equipment Bridge		Acceptable			
Waterbar		Acceptable			
Temporary Diversion Berm		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/18/2021 9:52 AM	Report #	27348
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Checked rain gauges in covered area -Received instruction from Lead EI for daily tasks -Cloudy with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14928+52 — 15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Walked ROW with environmental foreman looking for potential environmental issues or maintenance requirements -Perimeter controls and ECD's were inspected; 3 issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings -Observed condition of vegetation in section both permanent and temporary areas of ROW -Continue to monitor ROW for signs of erosion -3 items added to environmental punch list -Rain Gauge Totals: +Indian Cave: 0.50 inches recorded +Armstrong: 0.50 inches recorded 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/18/2021 9:52 AM	Report #	
Pictures					
					
36°57'53" N 79°37'0" W 330°NW COURSE 7° GPS Penhook, VA 24137, United States 08.18.2021 10:03:59 Accur +/-47.0 Ft ALT 927 Ft			36°57'56" N 79°36'17" W 269°W COURSE 295° GPS Sorry no results found 08.18.2021 09:39:04 Accur +/-15.7 Ft ALT 798 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14992+00	Field Station#	15027+97		
Pic 1 Desc.	Routine maintenance. Repair/replace damaged CFS triple stack from cattle damage.		Pic 2 Desc.	Routine maintenance. Sediment accumulation more than half full on bridge wattle.	
					
36°57'55" N 79°36'17" W 327°NW COURSE -1° GPS Sorry no results found 08.18.2021 09:38:45 Accur +/-31.9 Ft ALT 806 Ft			36°57'58" N 79°37'28" W 339°NW COURSE 158° GPS Penhook, VA 24137, United States 08.18.2021 10:15:01 Accur +/-48.9 Ft ALT 905 Ft		
GPS Location	3	GPS Location	4		
Field Station#	15028+25	Field Station#	14966+00		
Pic 3 Desc.	Routine maintenance. Replace damaged P1 silt fence more than half full of sediment.		Pic 4 Desc.	View of ROW through final cleanup area. No issues observed.	
					
36°57'55" N 79°36'4" W 71°E COURSE 286° GPS Penhook, VA 24137, United States 08.18.2021 09:31:53 Accur +/-29.4 Ft ALT 825 Ft			36°57'55" N 79°36'4" W 151°SE COURSE 177° GPS Penhook, VA 24137, United States 08.18.2021 09:31:49 Accur +/-47.8 Ft ALT 884 Ft		
GPS Location	5	GPS Location	6		
Field Station#	15040+00	Field Station#	15037+00		
Pic 5 Desc.	Water bars performing intended function. ROW stabilized and vegetated in temporary area.		Pic 6 Desc.	Perimeter SSF in place and functional.	

A/E	124300139	Date/Time	8/18/2021 9:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	8/18/2021 9:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27379
Inspector	John White			Date/Time	8/18/2021 10:36 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Wet	Temperature (°F)	80.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	2.90
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/18/2021 10:36 AM	Report #	27379
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Checked rain gauges, Anderson Mill #2=.5", Mill Creek =.5", Transco =.3". Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/18/2021 10:36 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15850+00	Field Station#	15840+00		
Pic 1 Desc.	Observing temporary stabilization, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization, CWD pipe, outlet and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15826+77	Field Station#	15825+00		
Pic 3 Desc.	Observing road crossing and RCE's	Pic 4 Desc.	Observing temporary stabilization, plunge pool and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15794+77	Field Station#	15781+22		
Pic 5 Desc.	Observing temporary stabilization, water bar, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

AFE	124300139	Date/Time	8/18/2021 10:36 AM	Report #	
Pictures					
		<div>Insert image here</div>			
GPS Location	O	GPS Location			
Field Station#	15777+00	Field Station#			
Pic 7 Desc.	Observing temporary stabilization, sump and end treatment.	Pic 8 Desc.			
<div>Insert image here</div>		<div>Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<div>Insert image here</div>		<div>Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			


A/E	124300139	Date/Time	8/18/2021 10:36 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	27442	
Inspector	John White			Date/Time	8/19/2021 8:54 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Damp	Temperature (°F)	75.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	3.50	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	8/19/2021 8:54 AM	Report #	27442
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/19/2021 8:54 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	19+00	Field Station#	15+00		
Pic 1 Desc.	Observing temporary stabilization and ECD's	Pic 2 Desc.	Observing temporary stabilization and signage		
					
GPS Location	O	GPS Location	O		
Field Station#	12+65	Field Station#	6+00		
Pic 3 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization and access road		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	8/19/2021 8:54 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	8/19/2021 8:54 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 18 Desc.	



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27457
Inspector	Ben Farmer			Date/Time	8/19/2021 1:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Partial	Station End	15584+23
County	Pittsylvania	Ground	Damp	Temperature (°F)	82.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	8/19/2021 1:59 PM	Report #	27457
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 82F) Rain Gauge= 0.0" 15480+67-15584+23 -EI began inspection at Toshes Rd. -RCEs are in good condition at all road crossings. -No evidence of sedimentation from 3rd party disturbance at 15505+00. -P1 is in good condition at all stream and wetland buffers. -3rd party ECDs appear to be in good condition at 15510+00. 3rd party currently grading this area. EI will continue to monitor. -CWDs are functioning as intended throughout this area. -Waterbars are in good condition throughout this section. -No evidence of sedimentation from 3rd party disturbance above stream S-CC9. EI will continue to monitor this area. -Previously repaired equipment bridge is in good condition with controls in place at 15573+22. -Sediment needs to be removed from slope drain sump and rock outlet at 15574+87. Environmental crew has corrected this issue. -Sediment spoils and disturbed areas from sump maintenance have been stabilized. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/19/2021 1:59 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15495+00		Field Station#	15496+70	
Pic 1 Desc.	Vegetation continues to fill in throughout this section.		Pic 2 Desc.	RCEs are in good condition at all road crossings.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15500+00		Field Station#	15501+00	
Pic 3 Desc.	Vegetation continues to fill in throughout this section.		Pic 4 Desc.	No evidence of sedimentation from 3rd party disturbance.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15506+41		Field Station#	15510+00	
Pic 5 Desc.	P1 is in good condition at all stream and wetland crossings.		Pic 6 Desc.	3rd party ECDs appear to be in good condition with no evidence of sedimentation onto MVP ROW.	

AFE	124300139	Date/Time	8/19/2021 1:59 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15515+00		Field Station#	15540+00	
Pic 7 Desc.	CWDs are functioning as intended.		Pic 8 Desc.	Equipment bridge ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15547+37		Field Station#	15556+83	
Pic 9 Desc.	Waterbars are in good condition throughout this section.		Pic 10 Desc.	No evidence of sedimentation from 3rd party disturbance.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15574+87		Field Station#	15584+00	
Pic 11 Desc.	Recently maintained slope drain is in good condition. Vegetation is filling in throughout disturbed area.		Pic 12 Desc.	P1 is in good condition at road culvert outlet.	







A/E	124300139	Date/Time	8/19/2021 1:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27464
Inspector	Charles Head			Date/Time	8/19/2021 4:43 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Damp	Temperature (°F)	87.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
3rd Party Damages		Communication	Repair damaged P-1		
Compost Filter Sock		Communication	Remove sediment from waddle		
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Communication	Repair third party damage		
Silt Fence (Reinforce Filter Fence)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	8/19/2021 4:43 PM	Report #	27464
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/19/2021 4:43 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14694+30	Field Station#	14689+36		
Pic 1 Desc.	Approximately 14694+30. Overview of road crossing and RCE.		Pic 2 Desc.	Approximately 14689+36. Overview of stream crossing, equipment bridge and ECDs at stream S-H34.	
					
GPS Location	0	GPS Location	0		
Field Station#	14677+00	Field Station#	14660+00		
Pic 3 Desc.	Approximately 14677+00 overview of ROW.		Pic 4 Desc.	Approximately 14660+00. Overview of ROW. Third party atv track's observed on the ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14656+50	Field Station#	14673+25		
Pic 5 Desc.	Approximately 14656+50. P-1 requires maintenance. Stake broken due to third party atv activities.		Pic 6 Desc.	Approximately 14673+25. Sediment build up on waddle.	

A/E	124300139	Date/Time	8/19/2021 4:43 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14676+70	Field Station#	14672+00		
Pic 7 Desc.	14676+70. Observed during inspection, contractor for power company chopping down and spraying trees along transmission line ROW.		Pic 8 Desc.	Approximately 14672+00. Observed during inspection, contractor for power company chopping down and spraying trees along transmission line ROW.	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	8/19/2021 4:43 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27380
Inspector	Ben Davenport			Date/Time	8/19/2021 9:55 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Partial	Station End	15142+66
County	Pittsylvania	Ground	Muddy	Temperature (°F)	88.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Rock Check Dam	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/19/2021 9:55 AM	Report #	27380
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection made note of temporary and permanent vegetation areas in section -Continue to monitor ROW for signs of erosion -No items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/19/2021 9:55 AM	Report #	
Pictures					
					
<small>36°57'44" N 79°35'22" W 282°W COURSE 337° GPS Sandy Level, VA 24161, United States</small>			<small>36°57'43" N 79°35'18" W 4°N COURSE 36° GPS Sandy Level, VA 24161, United States</small>		
<small>08.19.2021 10:57:37 Accur +/-94.4 Ft ALT 907 Ft</small>			<small>08.19.2021 10:55:56 Accur +/-25.2 Ft ALT 908 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	15075+00		Field Station#	15079+00	
Pic 1 Desc.	CFS check dams performing intended function		Pic 2 Desc.	Plunge pool in good condition	
					
<small>36°57'34" N 79°35'11" W 20°N COURSE 291° GPS Sandy Level, VA 24161, United States</small>			<small>36°57'31" N 79°35'6" W 298°NW COURSE 323° GPS Sandy Level, VA 24161, United States</small>		
<small>08.19.2021 10:49:41 Accur +/-137.6 Ft ALT 879 Ft</small>			<small>08.19.2021 10:47:19 Accur +/-121.5 Ft ALT 930 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	15090+50		Field Station#	15098+00	
Pic 3 Desc.	Picture of temporary stabilization and vegetation along ROW		Pic 4 Desc.	Picture of permanent stabilization and vegetation along ROW	
					
<small>36°57'19" N 79°34'55" W 342°N COURSE 319° GPS 8850-8968 Museville Rd, Sandy Level, VA 24161, United States</small>			<small>36°56'55" N 79°34'44" W 312°NW COURSE 59° GPS 337-521 Rockcreek Rd, Sandy Level, VA 24161, United States</small>		
<small>08.19.2021 10:40:12 Accur +/-23.0 Ft ALT 929 Ft</small>			<small>08.19.2021 10:27:25 Accur +/-74.1 Ft ALT 0 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	15113+00		Field Station#	15137+00	
Pic 5 Desc.	RCE at Museville Rd in good condition		Pic 6 Desc.	Sump pit and CFS end treatment in place and functional	

A/E	124300139	Date/Time	8/19/2021 9:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	8/19/2021 9:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	27440	
Inspector	John White			Date/Time	8/19/2021 8:41 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Damp	Temperature (°F)	75.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	3.50	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Housekeeping		Acceptable				
Compost Filter Sock		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
Waterbar End Treatment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	8/19/2021 8:41 AM	Report #	27440
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/19/2021 8:41 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	10+00		
Pic 1 Desc.	Observing temporary stabilization, water bar, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization and water bar		
GPS Location	O	GPS Location	O		
Field Station#	12+50	Field Station#	22+00		
Pic 3 Desc.	Observing temporary stabilization, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	8/19/2021 8:41 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	8/19/2021 8:41 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Field Station#		Field Station#		Pic 18 Desc.	



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27462
Inspector	Logan Box			Date/Time	8/19/2021 3:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13784+35
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Wet	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Rock Construction Entrance	Acceptable				
Compost Filter Sock	Communication				
Equipment Bridge	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/19/2021 3:59 PM	Report #	27462
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections the EI noticed a land owner has damaged CFS along access road MVP-FR-300 , EI Documented and sent in to be added to the punch list for maintenance repairs by the contractor.</p> <p>Other than the item listed there were no other environmental issues observed today.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/19/2021 3:59 PM	Report #	
Pictures					
					
GPS Location	0000	GPS Location	0000		
Field Station#	13805+90	Field Station#	13832+00		
Pic 1 Desc.	Monitored equipment bridge and protection along with all ECDs , no environmental issues observed at the time of inspection.		Pic 2 Desc.	Row photo showing stabilization on hill side. No environmental issues observed at the time of inspection.	
					
GPS Location	0000	GPS Location	00000		
Field Station#	13806+70	Field Station#	13826+95		
Pic 3 Desc.	Photo showing vegetation and stabilization on hill side above stream crossing. Good coverage. No environmental issues observed at the time of inspection.		Pic 4 Desc.	Vegetation observation while monitoring row conditions. No environmental issues observed at the time of inspection.	
					
GPS Location	0000	GPS Location	0000		
Field Station#	13784+35	Field Station#	13784+35		
Pic 5 Desc.	Additional photo showing land owner damage to CFS along access rd MVP-FR-300		Pic 6 Desc.	CFS along access rd MVP-FR-300 has been damaged from land owner , documented and sent in to be added to the punch list for maintenance repair.	

A/E	124300139	Date/Time	8/19/2021 3:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	8/19/2021 3:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27444
Inspector	John White			Date/Time	8/19/2021 9:00 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Damp	Temperature (°F)	75.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	3.50
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/19/2021 9:00 AM	Report #	27444
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/19/2021 9:00 AM	Report #	
Pictures					
GPS Location	O		GPS Location	O	
Field Station#	16026+00		Field Station#	16008+00	
Pic 1 Desc.	Observing temporary stabilization		Pic 2 Desc.	Observing temporary stabilization and water bar	
GPS Location	O		GPS Location	O	
Field Station#	16006+00		Field Station#	16004+00	
Pic 3 Desc.	Observing temporary stabilization, water bar, sump and end treatment		Pic 4 Desc.	Observing temporary stabilization, signage and buffer	
GPS Location	O		GPS Location	O	
Field Station#	16010+00		Field Station#	16016+36	
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's		Pic 6 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's	

A/E	124300139	Date/Time	8/19/2021 9:00 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	8/19/2021 9:00 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27452
Inspector	Justin Burch			Date/Time	8/19/2021 12:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Full	Station End	14311+57
County	Franklin	Ground	Wet	Temperature (°F)	86.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	2.85
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Plunge Pool	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	8/19/2021 12:03 PM	Report #	27452
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). An Environmental Laborer from Precision Pipeline accompanied the EI on this inspection. No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the inspection area since the last inspection. • Since the last SWPPP inspection the area has received four rainfall events with totals of 3.40" at Bonbrook Mill Road #1 and 2.85" at Farm View Road. • The ROW ground condition is wet. • At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14258+00 to 14277+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/19/2021 12:03 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14175+00	Field Station#	14175+00		
Pic 1 Desc.	Waterbar in acceptable condition		Pic 2 Desc.	Waterbar end treatment and super silt fence in acceptable conditions	
					
GPS Location	0	GPS Location	0		
Field Station#	14190+00	Field Station#	14190+50		
Pic 3 Desc.	Equipment bridge in acceptable condition		Pic 4 Desc.	P1 silt fence in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14220+00	Field Station#	14203+00		
Pic 5 Desc.	Temporary vegetative stabilization in acceptable condition		Pic 6 Desc.	Temporary vegetative stabilization and perimeter CFS in acceptable conditions	

AFE	124300139	Date/Time	8/19/2021 12:03 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14258+00	Field Station#	14289+00		
Pic 7 Desc.	Permanent vegetative stabilization and perimeter CFS in acceptable conditions		Pic 8 Desc.	Clean water diversion plunge pool in acceptable condition	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	8/19/2021 12:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27455
Inspector	Glenn Mike Renfro			Date/Time	8/19/2021 1:10 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00
State	VA	Inspection Area	Full	Station End	0000+00
County	Franklin	Ground	Damp	Temperature (°F)	88.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	3.50
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					Yes
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
Other - Explain in Comments	Acceptable	Inlet protection for catch basins			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/19/2021 1:10 PM	Report #	27455
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspection of Spread I main laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have received 3.5" of rainfall since the last inspection and site conditions were damp at the time of inspection. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were in good condition. - All secondary containment structures were found to be in good condition at the time of inspection. - All equipment at both locations was inspected and no leaks were observed at the time of inspection. - The RCE at LY-045 was in good condition. - The General Construction permits and contact information are posted at the main entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/19/2021 1:10 PM	Report #	
Pictures					
GPS Location	000000000000	GPS Location	000000000000		
Field Station#	0000+00	Field Station#	0000+00		
Pic 1 Desc.	Perimeter ECD's on west side of LY-046 in good condition	Pic 2 Desc.	Perimeter ECD's on south end of LY-046 in good condition.		
GPS Location	000000000000	GPS Location	000000000000		
Field Station#	0000+00	Field Station#	0000+00		
Pic 3 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.	Pic 4 Desc.	Perimeter ECD's on north end of LY-045 in good condition.		
GPS Location	000000000000	GPS Location	000000000000		
Field Station#	0000+00	Field Station#	0000+00		
Pic 5 Desc.	Secondary containment structure behind box trailer at LY-045 in good condition.	Pic 6 Desc.	Equipment inspected at LY-045 and no leaks observed during inspection.		

A/E	124300139	Date/Time	8/19/2021 1:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






A/E	124300139	Date/Time	8/19/2021 1:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27503
Inspector	Justin Burch			Date/Time	8/20/2021 11:02 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Wet	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)		Communication			
Silt Fence (Reinforced Filter Fabric Fence)		Communication			
Waterbar		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Compost Filter Sock		Acceptable			
Plunge Pool		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Sump Pit		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/20/2021 11:02 AM	Report #	27503
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). Four issues were submitted for the punch list which consisted of one location where P1 silt fence was damaged and deteriorated with replacement required, and two locations where P1 silt fence at the top of a cut was deteriorated and was to be removed on a temporary basis per DEQ approval, and another location where super silt fence was undermined at the top of cut and was to be removed on a temporary basis per DEQ approval. The contractor began addressing these items immediately. Other inspected ECDs were in compliance at the time of inspection. The EI did not observe that the contractor has worked in the inspection area since the last inspection. Since the last SWPPP inspection the area has received three rainfall events with totals of 1.20" at Grassy Hill Road and 1.00" at Bonbrook Mill Road #1. The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13910+00 and from 13921+00 to 13940+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/20/2021 11:02 AM	Report #	
Pictures					
					
GPS Location		0			
Field Station#		13890+00			
Pic 1 Desc.		P1 silt fence is damaged and deteriorated requiring replacement			
					
GPS Location		0			
Field Station#		13891+00			
Pic 3 Desc.		P1 silt fence is deteriorated from 13891+00 to 13891+75, to be removed temporarily per DEQ approval			
					
GPS Location		0			
Field Station#		13957+00			
Pic 5 Desc.		Waterbar in acceptable condition			
					
GPS Location		0			
Field Station#		13950+00			
Pic 2 Desc.		P1 silt fence is undermined and deteriorated from 13890+25 to 13891+00, to be removed temporarily per DEQ approval			
					
GPS Location		0			
Field Station#		13890+50			
Pic 4 Desc.		Super silt fence is undermined from 13890+50 to 13891+00, to be removed temporarily per DEQ approval			
					
GPS Location		0			
Field Station#		13954+00			
Pic 6 Desc.		P1 silt fence and perimeter CFS in acceptable conditions			

AFE	124300139	Date/Time	8/20/2021 11:02 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	13944+00	Field Station#	13912+50		
Pic 7 Desc.	Clean water diversion plunge pool in acceptable condition	Pic 8 Desc.	Permanent vegetative stabilization and perimeter CFS in acceptable conditions		
GPS Location	0	GPS Location	0		
Field Station#	13899+00	Field Station#	13855+00		
Pic 9 Desc.	Sump pit in acceptable condition	Pic 10 Desc.	Temporary vegetative stabilization in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	8/20/2021 11:02 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27505
Inspector	John White			Date/Time	8/20/2021 11:23 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Damp	Temperature (°F)	80.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.70
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Vegetative Stabilization (Temporary)	Communication	Contractor reseeded and stabilized		8/20/2021	
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/20/2021 11:23 AM	Report #	27505
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor has repaired the identified issues. Checked rain gauges, Anderson Mill #2=.10", Mill Creek =0, Transco =.10". Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/20/2021 11:23 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15600+50	Field Station#	15600+50		
Pic 1 Desc.	Observing location that requires additional stabilization	Pic 2 Desc.	Observing additional stabilization		
GPS Location	O	GPS Location	O		
Field Station#	15635+50	Field Station#	15635+50		
Pic 3 Desc.	Observing location that requires additional stabilization	Pic 4 Desc.	Observing additional stabilization and erosion control blanket.		
GPS Location	O	GPS Location	O		
Field Station#	15632+00	Field Station#	15636+45		
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

AFE	124300139	Date/Time	8/20/2021 11:23 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15616+00	Field Station#	15619+48		
Pic 7 Desc.	Observing temporary stabilization, sump and end treatment		Pic 8 Desc.	Observing road crossing and RCE's	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	8/20/2021 11:23 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27516
Inspector	Ben Farmer			Date/Time	8/20/2021 3:23 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Damp	Temperature (°F)	78.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	CFS needs to be repaired and resta			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	8/20/2021 3:23 PM	Report #	27516
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 78F) Rain Gauge= Trace 15142+66-15260+00 -EI began inspection at Rockcreek Rd. -RCEs are in good condition at all road crossings. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00. -Equipment bridge ECDs are in place and functioning. -P1 is in good condition at all stream and wetland crossings. -Slope drain is functioning as intended at 15170+00. -CFS has been damaged by livestock and needs to be repaired and restaked at 15195+00. -Waterbars are in good condition throughout this section. -Drainage features and permanent waterbars are in good condition throughout restored area of ROW. -Vegetation continuing to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/20/2021 3:23 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15142+66		Field Station#	15153+00	
Pic 1 Desc.	RCE is in good condition at Rockcreek Rd.		Pic 2 Desc.	Perimeter CFS is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15165+57		Field Station#	15166+00	
Pic 3 Desc.	Rock filter remains in good condition.		Pic 4 Desc.	Rock outlet is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15169+58		Field Station#	15169+58	
Pic 5 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 6 Desc.	P1 is in good condition at stream buffer.	

AFE	124300139	Date/Time	8/20/2021 3:23 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15172+00	
Pic 7 Desc.	Slope drain is in good condition and functioning as intended.		Pic 8 Desc.	Waterbars are in good condition throughout this section.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15187+00		Field Station#	15195+00	
Pic 9 Desc.	Vegetation continues to fill in throughout this section.		Pic 10 Desc.	CFS along drainage has been damaged by livestock and needs to be repaired and restaked.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15209+00		Field Station#	15230+00	
Pic 11 Desc.	Vegetation continues to fill in throughout this section.		Pic 12 Desc.	Vegetation continues to fill in throughout this section.	

A/E	124300139	Date/Time	8/20/2021 3:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27480
Inspector	Frank Craycroft			Date/Time	8/19/2021 10:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00
State	VA	Inspection Area	Full	Station End	0+00
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Timber Mat	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	8/19/2021 10:25 PM	Report #	27480
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All perimeter ECDs were functional and in good condition. All trash and construction waste was within bulk dumpsters. Stormwater drain inlet protections were free of debris and excessive vegetation. No issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	8/19/2021 10:25 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 1 Desc.	LY-032 Secondary containment		Pic 2 Desc.	LY-032 Secondary containment	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 3 Desc.	LY-033 Rock construction entrance		Pic 4 Desc.	LY-033 Stormwater drain inlet protection	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 5 Desc.	ANC-006 Secondary containment		Pic 6 Desc.	ANC-006 Stormwater drain inlet protection	







AFE	124300139	Date/Time	8/19/2021 10:25 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-048 Equipment staging	Pic 8 Desc.	LY-048 South perimeter CFS		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	8/19/2021 10:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27459
Inspector	Ben Davenport			Date/Time	8/20/2021 11:23 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Muddy	Temperature (°F)	82.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Compost Filter Sock	Acceptable				
Sediment Filter Log	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Rock Construction Entrance	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	8/20/2021 11:23 AM	Report #	
Pictures					
					
36°59'16" N 79°41'56" W 206°SW COURSE 287' GPS Sorry no results found 08.20.2021 12:23:29 Accur +/-468.3 Ft ALT 827 Ft			36°59'15" N 79°41'54" W 306°NW COURSE 244' GPS Sorry no results found 08.20.2021 12:22:19 Accur +/-130.2 Ft ALT 892 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14726+00		Field Station#	14729+19	
Pic 1 Desc.	Perimeter SSF in good condition along ROW		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer	
					
36°59'5" N 79°41'30" W 311°NW COURSE 244' GPS Sorry no results found 08.20.2021 12:16:43 Accur +/-321.1 Ft ALT 892 Ft			36°59'5" N 79°41'29" W 323°NW COURSE 219' GPS 701-1081 Indian Cave Rd, Union Hall, VA 24176, United States 08.20.2021 12:12:52 Accur +/-39.2 Ft ALT 889 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14741+50		Field Station#	14752+00	
Pic 3 Desc.	Picture of temporary stabilization and vegetation along ROW		Pic 4 Desc.	CFS triple stack at resource buffer in good condition	
					
36°59'11" N 79°41'23" W 328°NW COURSE 0' GPS 701-1081 Indian Cave Rd, Union Hall, VA 24176, United States 08.20.2021 12:09:45 Accur +/-51.5 Ft ALT 0 Ft			36°59'9" N 79°41'41" W 102°E COURSE 94' GPS Union Hall, VA 24176, United States 08.20.2021 12:39:43 Accur +/-393.5 Ft ALT 829 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14758+16		Field Station#	14765+00	
Pic 5 Desc.	RCE at Indian Cave Rd in good condition		Pic 6 Desc.	Sump pit and CFS end treatment in place and functional	

A/E	124300139	Date/Time	8/20/2021 11:23 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	8/20/2021 11:23 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	27518
Inspector	Charles Head			Date/Time	8/20/2021 4:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Damp	Temperature (°F)	82.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	8/20/2021 4:59 PM	Report #	27518
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	8/20/2021 4:59 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14314+79	Field Station#	14333+50		
Pic 1 Desc.	Approximately 14314+79. Overview of stream crossing, equipment bridge and ECDs at stream S-GG4.		Pic 2 Desc.	Approximately 14333+50. Overview of road crossing and RCEs.	
					
GPS Location	0	GPS Location	0		
Field Station#	14360+00	Field Station#	14391+50		
Pic 3 Desc.	Approximately 14360+00. Overview of ROW.		Pic 4 Desc.	Approximately 14391+50. Overview of stream crossing, equipment bridge and ECDs at stream S-A41.	
					
GPS Location	0	GPS Location	0		
Field Station#	14414+00	Field Station#	14451+00		
Pic 5 Desc.	Approximately 14414+00. Overview of ROW.		Pic 6 Desc.	Approximately 14451+00. Overview of ROW.	

A/E	124300139	Date/Time	8/20/2021 4:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	8/20/2021 4:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	27441
Inspector	John White			Date/Time	8/19/2021 8:49 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Damp	Temperature (°F)	75.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	3.50
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Filter	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	8/19/2021 8:49 AM	Report #	27441
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	8/19/2021 8:49 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 1 Desc.	Observing temporary stabilization, storm water pond and ECD's		Pic 2 Desc.	Observing temporary stabilization and sediment basin	
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 3 Desc.	Observing temporary stabilization, rock drain and ECD's		Pic 4 Desc.	Observing lay down yard	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300113	Date/Time	8/19/2021 8:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	8/19/2021 8:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		