



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33551	
Inspector Jared Saunders		Date/Time 1/24/2022 1:22 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11353+67
State VA	Inspection Area Partial	Station End	11471+56
County Giles	Ground Frozen	Temperature (°F)	40.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300137	Date/Time	1/24/2022 1:22 PM	Report #	33551
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11353+67 (Old Furnace) to ST# 11471+56 (Steele Acres) MP 215.04 to MP 217.26
 No deficiencies were located during inspection.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed since last VA SWPP inspection Environmental maintenance crew has repaired previous punch list items.
 ST# 11353+67 to ST# 11367+00 and ST# 11443+50 to ST# 11471+56 have undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Triple protection ECDs are in place at karst feature.
 Final restoration has occurred between ST# 11367+00 and ST# 11443+50. CFS perimeter controls, permanent waterbars (section 6 other) with level spreaders are in place.
 Sensitive resource buffers are in place at stream crossings S-KL43, S-0014, S-0013, S-0012, and S-CD14.
 AR-256 and 258.01 RCEs are maintained in acceptable condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/24/2022 1:22 PM	Report #	
Pictures					
<p>Date & Time: Mon, Jan 24, 2022, 08:14:18 EST Position: -037.312264 / -080.421882 (±1490.5ft) Altitude: 2298ft (±77.1ft) Datum: WGS-84 Azimuth/Bearing: 308° S34W 547mils True (±14°) Elevation Angle: -35.2° Horizon Angle: -00.7° Zoom: 1.0X 11453+00</p>			<p>Date & Time: Mon, Jan 24, 2022, 08:23:38 EST Position: -037.312264 / -080.427378 (±4490.5ft) Altitude: 2298ft (±77.1ft) Datum: WGS-84 Azimuth/Bearing: 308° N52W 547mils True (±14°) Elevation Angle: -31.7° Horizon Angle: -00.7° Zoom: 1.0X 11453+00</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11471+00		Field Station#	11453+00	
Pic 1 Desc.	Rock inlet in place at slope drain inlet.		Pic 2 Desc.	Slope drain over fill slope, sump pit, and end treatment in place.	
<p>Date & Time: Mon, Jan 24, 2022, 08:17:31 EST Position: -037.320599 / -080.436399 (±1666.2ft) Altitude: 2246ft (±114.8ft) Datum: WGS-84 Azimuth/Bearing: 287° N73W 5102mils True (±14°) Elevation Angle: -25.8° Horizon Angle: -01.5° Zoom: 1.0X 11468+00</p>			<p>Date & Time: Mon, Jan 24, 2022, 08:33:24 EST Position: -037.316958 / -080.445831 (±1513ft) Altitude: 2153ft (±113.1ft) Datum: WGS-84 Azimuth/Bearing: 210° S44W 3900mils True (±14°) Elevation Angle: -10.0° Horizon Angle: -02.1° Zoom: 1.0X 11433+00</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11468+00		Field Station#	11433+00	
Pic 3 Desc.	Plunge pool and clean water drainage pipe in place.		Pic 4 Desc.	Permanent waterbars with level spreaders in place.	
<p>Date & Time: Mon, Jan 24, 2022, 08:39:51 EST Position: -037.316958 / -080.445831 (±1513ft) Altitude: 2056ft (±101.9ft) Datum: WGS-84 Azimuth/Bearing: 276° N84W 3226mils True (±14°) Elevation Angle: -23.6° Horizon Angle: -04.1° Zoom: 1.0X 11353+00</p>			<p>Date & Time: Mon, Jan 24, 2022, 08:48:33 EST Position: -037.316958 / -080.445831 (±1513ft) Altitude: 2056ft (±101.9ft) Datum: WGS-84 Azimuth/Bearing: 182° S02W 3226mils True (±15°) Elevation Angle: -09.5° Horizon Angle: -01.4° Zoom: 1.0X 11353+00</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11394+00		Field Station#	11353+00	
Pic 5 Desc.	ROW permanently stabilized with ECB.		Pic 6 Desc.	RCE in place at Old Furnace Road.	

AFE 124300137	Date/Time 1/24/2022 1:22 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	1/24/2022 1:22 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33547	
Inspector Clint Sears		Date/Time 1/24/2022 12:13 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11471+56	
State VA	Inspection Area Partial	Station End 11524+16	
County Giles	Ground Frozen	Temperature (°F) 43.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Housekeeping	Acceptable			
Equipment Bridge	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Plunge Pool	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/24/2022 12:13 PM	Report # 33547
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Met with environmental staff.
 Completed VA SWPPP inspection, from MP 217.26 (11471+56) and MP 218.26 (11524+16)
 Fellow EI Chris Burns accompanied.
 No deficiencies were found at time of inspection
 This section of Row has no current construction activity.
 All perimeter controls, ECDs and BMPs functional at time of inspection.
 Temporary Vegetation, stabilization are acceptable.
 KARST ECD'S are in place and acceptable.
 Row is frozen and some areas are snow covered.
 No impact to sensitive resources observed.
 Assessed AR 258.02 Stevers Gap and the Steele Acres access rd.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/24/2022 12:13 PM	Report #	
Pictures					
					
GPS Location	see photo	GPS Location	see photo		
Field Station#	11520+00	Field Station#	11518+32		
Pic 1 Desc.	Section of Row showing conditions and controls	Pic 2 Desc.	S-PP4		
					
GPS Location	See photo	GPS Location	see photo		
Field Station#	11507+78	Field Station#	11504+00		
Pic 3 Desc.	S-PP3	Pic 4 Desc.	Rock lined channel is in acceptable condition		
					
GPS Location	See photo	GPS Location	see photo		
Field Station#	11490+00	Field Station#	11487+25		
Pic 5 Desc.	RCE is maintained and in acceptable condition	Pic 6 Desc.	Plunge pool is in place		

AFE 124300137		Date/Time 1/24/2022 12:13 PM		Report #	
Pictures					
GPS Location		See photo		GPS Location	
Field Station#		11478+80		Field Station#	
Pic 7 Desc.		Section of Row showing conditions and controls		Pic 8 Desc.	
		Karst ECD's are in place			
Insert image here			Insert image here		
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 9 Desc.				Pic 10 Desc.	
Insert image here			Insert image here		
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 11 Desc.				Pic 12 Desc.	

AFE	124300137	Date/Time	1/24/2022 12:13 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name		H-600 Pipeline Spread G		AFE	124300137	Spread	H-600 Pipeline Spread G	
Contractor		Precision				Report #	33557	
Inspector		Daniel Fortune				Date/Time	1/24/2022 2:53 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	11524+16		
State	VA	Inspection Area	Partial		Station End	11600+01		
County	Craig	Ground	Frozen		Temperature (°F)	27.00		
Municipality	N/A	Weather	Below Freezing Temp		Rain Gauge (in)	0.00		
						Rain Accumulation Time (days)	0.00	

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Waterbar End Treatment	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/24/2022 2:53 PM	Report # 33557
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)


Completed a VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to MP 219.70)
 The Row received 0.0 of precipitation in the last 24 hours. The row remains stable at this time. No Deficiencies have been observed today. This section of row has been final stabilized from 11524+16 to station 11551+88. PCSM BMP's have been installed and functioning as intended. There is visible annual grasses throughout the final restored areas aforementioned. The visible vegetation coverage is uniform at approximately 20% to 30% as vegetation has died off in the area, with sparse areas where CC4 ECB has been installed over the permanent water bars. Perennial vegetation will presumably lay dormant until early spring when area will be revisited and assessed. Final restoration did not start until summer of 2021. A full growing season has not been established at this time. No rilling observed, and permanent water bars remain stable and functioning as intended.
 There is temporary stabilization between 11551+88 to 11600+01. No erosion issues observed today in this area. This section is in the JNF and permits have not been released for construction advancement. There are temporary water bars, BMP's and ECDs applied and installed throughout this area that remain functioning as intended. There are weathered ECDs that have been in place for a while. The ECDs appear to be functioning according to design. Until permits are released for the JNF, no equipment of any kind are to be allowed in this area. Temporary vegetation has well been established throughout. No rilling or erosion issues have been observed today. There are (4) four sensitive resources and one point of interest between stations 11567+22 and 11590+00, according to alignment sheet 240 of 329 Rev 7.
 (Existing Water Well - ST# 11567+22) - History unknown to EI. Location-outside MVP NE LOD. No Inspection today. Stream (S-PP22 - ST# 11568+22) - Encroaches row from outside NE perimeter LOD. Light trickling water flow from NE to SW. No visible Impacts. (Stream S-PP21 - ST# 1158548) - Vegetated buffer zones north and south stream banks. No visible Impacts. Light stream flow from NE to SW. (Stream S-PP20 - ST# 11588+41) - Vegetated buffer zones north and south stream banks. No visible Impacts. Light stream flow from NE to SW. (W-CD46 - ST# 11590+00) - Wetland boundaries outside of the MVP perimeter LOD to the SW

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/24/2022 2:53 PM	Report #	
Pictures					
 <p><small>Date & Time: Mon, Jan 24, 2022, 10:52:50 EST Position: 43373118662, -080.406227, 15.11.9m Altitude: 2071ft (=19.7m) Datum: WGS 84 Azimuth/Bearing: 326, N34W 5796mils True (=77) Elevation Grade: +019 Horizon Grade: -001 Zoom: 0.5X 11570+00</small></p>		 <p><small>Date & Time: Mon, Jan 24, 2022, 10:58:02 EST Position: 43373118303, -080.407724, 15.18.1m Altitude: 2069ft (=19.9m) Datum: WGS 84 Azimuth/Bearing: 321, N39W 5707mils True (=12) Elevation Grade: +002 Horizon Grade: -002 Zoom: 0.5X 11581+00</small></p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11570+00	Field Station#	11581+00		
Pic 1 Desc.	Current row conditions. (Temporary stabilization).	Pic 2 Desc.	Temporary vegetation on stabilized row.		
 <p><small>Date & Time: Mon, Jan 24, 2022, 11:01:07 EST Position: 4337317542, -080.409589, 15.01.8m Altitude: 2196ft (=20.9m) Datum: WGS 84 Azimuth/Bearing: 307, N53W 5458mils True (=13) Elevation Grade: +007 Horizon Grade: -001 Zoom: 0.5X 11583+55</small></p>		 <p><small>Date & Time: Mon, Jan 24, 2022, 11:02:52 EST Position: 4337317656, -080.409383, 15.15.3m Altitude: 2071ft (=19.9m) Datum: WGS 84 Azimuth/Bearing: 310, N22W 5683mils True (=12) Elevation Grade: +022 Horizon Grade: -006 Zoom: 0.5X 11582+00</small></p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11583+55	Field Station#	11582+00		
Pic 3 Desc.	Perimeter P1 silt fencing	Pic 4 Desc.	Temporary vegetation over top soil pile and perimeter super silt fence.		
 <p><small>Date & Time: Mon, Jan 24, 2022, 11:01:33 EST Position: 4337317426, -080.409530, 15.15.3m Altitude: 2174ft (=19.9m) Datum: WGS 84 Azimuth/Bearing: 072, N72E 1280mils True (=12) Elevation Grade: 069 Horizon Grade: -007 Zoom: 0.5X 11584+02</small></p>		 <p><small>Date & Time: Mon, Jan 24, 2022, 11:02:55 EST Position: 4337317656, -080.409383, 15.15.3m Altitude: 2071ft (=19.9m) Datum: WGS 84 Azimuth/Bearing: 142, S38E 2520mils True (=1) Elevation Grade: 022 Horizon Grade: -001 Zoom: 0.5X 11584+92 S-PP21</small></p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11584+02	Field Station#	11584+92		
Pic 5 Desc.	Double sump pit with functional water bar end treatment.	Pic 6 Desc.	Equipment bridge condition		


AFE	124300137	Date/Time	1/24/2022 2:53 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

 <p><small>Date & Time: Mon, Jan 24, 2022, 11:09:55 EST Position: +037.318541° / -080.109224° (-15.49') Altitude: 2080ft (+634.0m) Datum: WGS-84 Azimuth Bearing: 210° S37W 3893mils True (+13°) Elevation Grade: -005% Horizon Grade: +005% Zoom: 0.5X 11585+39</small></p>		 <p><small>Date & Time: Mon, Jan 24, 2022, 11:10:05 EST Position: +037.318541° / -080.109224° (-15.49') Altitude: 2047ft (+624.0m) Datum: WGS-84 Azimuth Bearing: 160° S40E 2489mils True (+12°) Elevation Grade: -027% Horizon Grade: -005% Zoom: 0.5X 11587+42 S-PP20</small></p>	
GPS Location	See Photo	GPS Location	See Photo
Field Station#	11585+39	Field Station#	11587+42
Pic 7 Desc.	S-PP21 View Looking down stream	Pic 8 Desc.	Equipment bridge condition
 <p><small>Date & Time: Mon, Jan 24, 2022, 11:12:55 EST Position: +037.318541° / -080.109224° (-15.49') Altitude: 2084ft (+635.0m) Datum: WGS-84 Azimuth Bearing: 210° S37W 3893mils True (+13°) Elevation Grade: -034% Horizon Grade: -002% Zoom: 0.5X 11587+42 S-PP20</small></p>		 <p><small>Date & Time: Mon, Jan 24, 2022, 15:02:43 EST Position: +037.323337° / -080.117410° (-15.40') Altitude: 2337ft (+712.0m) Datum: WGS-84 Azimuth Bearing: 159° S24E 2333mils True (+13°) Elevation Grade: +123% Horizon Grade: -003% Zoom: 0.5X 11550+00</small></p>	
GPS Location	See Photo	GPS Location	See Photo
Field Station#	11587+42	Field Station#	11550+00
Pic 9 Desc.	View looking down stream	Pic 10 Desc.	Temporary stabilized row. Slope covered in ice and snow.
 <p><small>Date & Time: Mon, Jan 24, 2022, 12:00:02 EST Position: +037.322343° / -080.418795° (-15.51') Altitude: 2356ft (+718.0m) Datum: WGS-84 Azimuth Bearing: 160° S32E 2631mils True (+13°) Elevation Grade: +017% Horizon Grade: -004% Zoom: 0.5X 11535+00</small></p>		 <p><small>Date & Time: Mon, Jan 24, 2022, 12:05:07 EST Position: +037.328318° / -080.419848° (-15.50') Altitude: 2297ft (+700.0m) Datum: WGS-84 Azimuth Bearing: 051° N51E 0907mils True (+13°) Elevation Grade: +003% Horizon Grade: -006% Zoom: 0.5X 11538+33</small></p>	
GPS Location	See Photo	GPS Location	See Photo
Field Station#	11535+00	Field Station#	11538+33
Pic 11 Desc.	Frozen row conditions. Final Restoration Area	Pic 12 Desc.	Final Restoration Area. Fallen tree removed.

AFE 124300137	Date/Time 1/24/2022 2:53 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See Photo	GPS Location	See Photo
Field Station#	11528+50	Field Station#	11529+45
Pic 13 Desc.	Permanent water bar condition Final Restoration Area	Pic 14 Desc.	Final Restoration Area



GPS Location	See Photo	GPS Location	See Photo
Field Station#	11527+31	Field Station#	11526+57
Pic 15 Desc.	Rock level spreader Final Restoration Area	Pic 16 Desc.	Drainage Feature Final Restoration Area



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33546	
Inspector Joe Sweeden		Date/Time 1/24/2022 12:02 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11254+99	
State VA	Inspection Area Partial	Station End 11353+67	
County Giles	Ground Frozen	Temperature (°F) 30.00	
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300137	Date/Time	1/24/2022 12:02 PM	Report #	33546
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed Virginia SWPP inspection from station # 11254+99-11353+67 (MP 213.6-215.04) Rte 42 - Old Furnace, with El David Schoolcraft
 No Deficiencies found today.
 Observances:
 The ROW is still mainly snow covered, frozen on top, soft underneath.
 No snow or rain overnight.
 The ROW has been temporarily stabilized.
 Karst areas have occurred in sumps at station 11348+00.areas are protected with ECDs.
 The water bars and compost sock are in good condition.
 Steep slopes have had erosion control fabric placed on them.
 Vegetation is sufficient.
 Slope drains are functioning as designed.
 ECs at streams are in compliance.
 No trash on the ROW.
 No sensitive resources were impacted.
 All perimeter controls, ECDs and BMPs were functional at time of inspection. No other crews were working in the area.
 Rock Road approaches are clean and free of loose rock.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE	124300137	Date/Time	1/24/2022 12:02 PM	Report #	
Pictures					
 <p>Date & Time: Mon, Jan 24, 2022, 09:28:33 EST Position: +037.305538 / -080.427185 (±16.4ft) Altitude: 2030ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 814.534W 380mils True (±12) Elevation Angle: -14.2 Horizon Angle: +01.8 Zoom: 1.0X S-NN 11 station # 11353+50 Spread G</p>		 <p>Date & Time: Mon, Jan 24, 2022, 09:26:22 EST Position: +037.305076 / -080.467720 (±16.4ft) Altitude: 2076ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 889.1104W 4293mils True (±16) Elevation Angle: -38.9 Horizon Angle: +09.4 Zoom: 1.0X GPS 31 level, station # 11351+50 Spread G</p>			
GPS Location	See photo		GPS Location	see photo	
Field Station#	11353+50		Field Station#	11351+50	
Pic 1 Desc.	S-NN 11		Pic 2 Desc.	ECDs at Karst	
 <p>Date & Time: Mon, Jan 24, 2022, 09:18:06 EST Position: +037.301357 / -080.472437 (±16.4ft) Altitude: 2237ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 087.1N35E 0563mils True (±12) Elevation Angle: +10.8 Horizon Angle: +39.4 Zoom: 1.0X Stabilized ROW station # 11336+00 Spread G</p>		 <p>Date & Time: Mon, Jan 24, 2022, 09:12:40 EST Position: +037.302568 / -080.473123 (±16.4ft) Altitude: 2168ft (±9.4ft) Datum: WGS-84 Azimuth/Bearing: 057.1N57E 1013mils True (±104) Elevation Angle: -21.7 Horizon Angle: +00.1 Zoom: 1.0X S-NN 12 station # 11327+50 Spread G</p>			
GPS Location	see photo		GPS Location	see photo	
Field Station#	11336+00		Field Station#	11327+50	
Pic 3 Desc.	Stabilized ROW		Pic 4 Desc.	S-NN 12	
 <p>Date & Time: Mon, Jan 24, 2022, 09:06:16 EST Position: +037.297458 / -080.475030 (±16.4ft) Altitude: 2319ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 243.583W 14670mils True (±16) Elevation Angle: -24.1 Horizon Angle: -02.7 Zoom: 1.0X Perimeter ECDs sensitive area station # 11314+00 Spread G</p>		 <p>Date & Time: Mon, Jan 24, 2022, 08:56:52 EST Position: +037.296594 / -080.479681 (±16.4ft) Altitude: 2182ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 341.1N19W 6102mils True (±16) Elevation Angle: -24.6 Horizon Angle: +05.0 Zoom: 1.0X Spread G station # 11297+89 Spread G</p>			
GPS Location	see photo		GPS Location	see photo	
Field Station#	11314+00		Field Station#	11297+89	
Pic 5 Desc.	Perimeter ECDs in sensitive area		Pic 6 Desc.	AR Seven Oaks	

AFE 124300137	Date/Time 1/24/2022 12:02 PM	Report #
----------------------	-------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	11292+60	Field Station#	11270+00
Pic 7 Desc.	S MM-18	Pic 8 Desc.	Slope drain



GPS Location	see photo	GPS Location	
Field Station#	11259+00	Field Station#	
Pic 9 Desc.	Erosion control blanket	Pic 10 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	1/24/2022 12:02 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33592	
Inspector Chris Burns		Date/Time 1/25/2022 12:10 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11788+52	
State VA	Inspection Area Partial	Station End 11899+89	
County Montgomery	Ground Muddy	Temperature (°F) 44.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/25/2022 12:10 PM	Report # 33592
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable			
Level Spreader	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection, from MP 223.27 (11788+52) and MP 225.37 (11899+89).
 Fellow EI Clint Sears accompanied during SWPPP inspection.
 This section of RoW has no current construction.
 Temporary controls within this area are partially removed, remaining temporary controls to be removed once ground/weather conditions improve.
 All perimeter controls, ECDs and BMPs functional at time of inspection.
 Vegetation or stabilization sufficient.
 No impact to sensitive resources observed.
 Unauthorized vehicle travel within the permanent restoration area, between 11792+00 and 11831+75, on 1/18/2022 resulted in minor disturbance/vegetation damage between 11824+00 and 118 31+75. Further assessment of this area to take place once snow melt occurs allowing the observation of the impact. (Update) Snow cover still present, monitoring to continue.
 Assessed AR 266.03.
 Section 6- Waterbars (other).

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE 124300137		Date/Time 1/25/2022 12:10 PM		Report #			
Pictures							
 <p>Date & Time: Tue, Jan 25, 2022, 09:09:10 EST Position: 143872.038 E / 355329.288 N (±15.41) Altitude: 22218 (±11.24) Datum: WGS-84 Azimuth/Bearing: 033° N33E 1476mils True (±12°) Elevation Angle: +02.0° Horizon Angle: -02.0° Zoom: 0.5X 11792+00</p>		 <p>Date & Time: Tue, Jan 25, 2022, 09:18:20 EST Position: 1451284.808 E / 355117.826 N (±15.41) Altitude: 22218 (±11.24) Datum: WGS-84 Azimuth/Bearing: 145° S35E 2896mils True (±12°) Elevation Angle: +02.5° Horizon Angle: -01.5° Zoom: 0.5X 11818+00</p>		 <p>Date & Time: Tue, Jan 25, 2022, 09:26:56 EST Position: 1451028.829 E / 355169.837 N (±15.41) Altitude: 22218 (±11.24) Datum: WGS-84 Azimuth/Bearing: 225° S25W 3013mils True (±12°) Elevation Angle: +02.2° Horizon Angle: -02.6° Zoom: 0.5X 11825+25</p>		 <p>Date & Time: Tue, Jan 25, 2022, 09:26:56 EST Position: 1451028.829 E / 355169.837 N (±15.41) Altitude: 22218 (±11.24) Datum: WGS-84 Azimuth/Bearing: 083° N83E 3440mils True (±12°) Elevation Angle: -22.4° Horizon Angle: -02.6° Zoom: 0.5X 11831+75</p>	
GPS Location 1		GPS Location 2		GPS Location 3			
Field Station# 11792+00		Field Station# 11818+00		Field Station# 11825+25			
Pic 1 Desc. Section of RoW showing conditions and controls.		Pic 2 Desc. Section of RoW showing conditions and controls.		Pic 3 Desc. Representational photo of waterbar and level spreader.			
 <p>Date & Time: Tue, Jan 25, 2022, 09:32:48 EST Position: 1422230.591 E / 355166.063 N (±15.41) Altitude: 22076 (±11.24) Datum: WGS-84 Azimuth/Bearing: 157° S57E 3791mils True (±12°) Elevation Angle: +02.2° Horizon Angle: +00.7° Zoom: 0.5X 11841+00</p>		 <p>Date & Time: Tue, Jan 25, 2022, 09:38:33 EST Position: 1452230.591 E / 355166.063 N (±15.41) Altitude: 22076 (±11.24) Datum: WGS-84 Azimuth/Bearing: 304° N56W 5404mils True (±12°) Elevation Angle: -01.2° Horizon Angle: -01.2° Zoom: 0.5X 11856+00</p>		 <p>Date & Time: Tue, Jan 25, 2022, 09:32:48 EST Position: 1422230.591 E / 355166.063 N (±15.41) Altitude: 22076 (±11.24) Datum: WGS-84 Azimuth/Bearing: 157° S57E 3791mils True (±12°) Elevation Angle: +02.2° Horizon Angle: +00.7° Zoom: 0.5X 11841+00</p>			
GPS Location 5		GPS Location 6		GPS Location 5			
Field Station# 11841+00		Field Station# 11856+00		Field Station# 11841+00			
Pic 5 Desc. Section of RoW showing conditions and controls.		Pic 6 Desc. Section of RoW showing conditions and controls.		Pic 5 Desc. Section of RoW showing conditions and controls.			

AFE 124300137	Date/Time 1/25/2022 12:10 PM	Report #
----------------------	-------------------------------------	-----------------


Pictures



GPS Location 7	GPS Location 8
Field Station# 11863+65	Field Station# 11886+00
Pic 7 Desc. P-KL2 and controls.	Pic 8 Desc. Section of RoW showing conditions and controls.



GPS Location 9	GPS Location 10
Field Station# 11899+89	Field Station# 11899+89
Pic 9 Desc. Section of RoW showing conditions and controls.	Pic 10 Desc. AR 266.03 conditions and controls.



GPS Location	GPS Location
Field Station#	Field Station#
Pic 11 Desc.	Pic 12 Desc.

A/E	124300137	Date/Time	1/25/2022 12:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Pic 13 Desc.		Pic 14 Desc.		Pic 14 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Pic 15 Desc.		Pic 16 Desc.		Pic 16 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Pic 17 Desc.		Pic 18 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33602	
Inspector Jared Saunders		Date/Time 1/25/2022 2:01 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11670+00
State VA	Inspection Area Partial	Station End	11788+52
County Giles	Ground Wet	Temperature (°F)	45.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/25/2022 2:01 PM	Report # 33602
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11670+00 (Brush Mt) to ST# 11788+52 (Mt Tabor)
 MP 221.02 to MP 223.27
 No deficiencies were located during inspection.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed no crews actively working on this section of ROW at time of inspection.
 This section of ROW has undergone temporary stabilization. Topsoil stock piles and clean water diversion berms have been stabilized.
 Slope drains with stone inlet protection are in place where needed.
 Perimeter controls and waterbars with end treatments are in place.
 Sensitive resource buffers are in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52.
 MLV-AR-26 and MT. Tabor road crossing RCEs are maintained in acceptable condition.
 No sensitive resources have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/25/2022 2:01 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	11687+40	Field Station#	11711+00
Pic 1 Desc.	Sensitive resource buffer in place at stream S-MN21.	Pic 2 Desc.	ROW temporarily stabilized with ECB.



GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	11780+00	Field Station#	11776+00
Pic 3 Desc.	Clean water drainage feature in place.	Pic 4 Desc.	Clean water diversion pipe in place.



GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	11766+00	Field Station#	11758+00
Pic 5 Desc.	RCE in place at MLV 26.	Pic 6 Desc.	Super silt fence in place along LOD.

AFE 124300137	Date/Time 1/25/2022 2:01 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 1/25/2022 2:01 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33624	
Inspector Daniel Fortune		Date/Time 1/25/2022 6:43 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11899+89	
State VA	Inspection Area Partial	Station End 12005+00	
County Montgomery	Ground Wet	Temperature (°F) 30.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar Outlet Protection	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/25/2022 6:43 PM	Report # 33624
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00).
 This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time.
 Permanent water bars have been installed and appear to be functioning as intended.
 Precision Crews: No crews on site or activity observed.
 All other perimeter controls, ECDs and BMPs functional at time of inspection.
 Vegetation or stabilization sufficient.
 No impact to sensitive resources observed.
 Assessed Ar 266.03 and AR 266.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 1/25/2022 6:43 PM		Report #			
Pictures							
 <p><small>Date & Time: Tue Jan 25 2022 10:24:00 EST Position: +397 232742 / -080 314897 (+20.21h) Altitude: 1459ft (+105.0ft) Datum: WGS 84 Azimuth Bearing: 328° S32W 400mils True (+12°) Elevation Grade: -0.23 Horizon Grade: -0.01 Zoom: 0.5x 12005+00</small></p>		 <p><small>Date & Time: Tue Jan 25 2022 10:24:05 EST Position: +397 232742 / -080 314127 (+20.21h) Altitude: 1459ft (+105.0ft) Datum: WGS 84 Azimuth Bearing: 326° N36W 370mils True (+12°) Elevation Grade: -0.23 Horizon Grade: -0.02 Zoom: 0.5x 12007+00</small></p>		 <p><small>Date & Time: Tue Jan 25 2022 11:16:55 EST Position: +397 232824 / -080 322601 (+20.21h) Altitude: 1721ft (+526.0ft) Datum: WGS 84 Azimuth Bearing: 102° S78E 150mils True (+16°) Elevation Grade: +0.15 Horizon Grade: -0.08 Zoom: 1.5x 11965+41</small></p>		 <p><small>Date & Time: Tue Jan 25 2022 11:54:15 EST Position: +397 232817 / -080 322894 (+20.21h) Altitude: 1730ft (+529.0ft) Datum: WGS 84 Azimuth Bearing: 102° S78W 160mils True (+16°) Elevation Grade: +0.22 Horizon Grade: -0.05 Zoom: 0.5x 11945+00</small></p>	
GPS Location See Photo		GPS Location See Photo		GPS Location See Photo			
Field Station# 12005+00		Field Station# 12002+00		Field Station# 11965+41			
Pic 1 Desc. Frozen row conditions.		Pic 2 Desc. Super silt fencing adjacent to flood plain.		Pic 3 Desc. P1 silt fencing conditions. No Issues. Final Restoration Area			
 <p><small>Date & Time: Tue Jan 25 2022 09:24:30 EST Position: +397 237395 / -080 333242 (+20.21h) Altitude: 2111ft (+640.0ft) Datum: WGS 84 Azimuth Bearing: 089° N89E 1592mils True (+16°) Elevation Grade: +0.23 Horizon Grade: +0.35 Zoom: 0.5x 11904+22</small></p>		 <p><small>Date & Time: Tue Jan 25 2022 09:19:44 EST Position: +397 237634 / -080 334457 (+20.21h) Altitude: 2249ft (+682.0ft) Datum: WGS 84 Azimuth Bearing: 102° S78E 1813mils True (+16°) Elevation Grade: +0.08 Horizon Grade: -0.01 Zoom: 1.5x 11900+81</small></p>		GPS Location See Photo			
Field Station# 11904+22		Field Station# 11900+81		Field Station# 11904+22			
Pic 5 Desc. Rock level spreader Final Restoration Area		Pic 6 Desc. Vegetated row conditions. Final Restoration Area		Pic 5 Desc. Rock level spreader Final Restoration Area			

AFE 124300137	Date/Time 1/25/2022 6:43 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 1/25/2022 6:43 PM	Report #
----------------------	------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33587	
Inspector Eric Hanlon		Date/Time 1/25/2022 9:51 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Full	Station End	12005+00
County Giles	Ground Wet	Temperature (°F)	40.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
Rain Accumulation Time (days)			1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/25/2022 9:51 AM	Report # 33587
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a VA SWPPP inspection on yard 28
 No compliance issues noted.
 Observance:
 Yard 28 has reduced activity during the winter curtailment.
 Aged Perimeter controls have been replaced & functioning as designed.
 RCE was clean, no mud or other debris on road.
 All other ECDs and BMPs functional at time of inspection.
 No impact to sensitive resources observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 1/25/2022 9:51 AM		Report #			
Pictures							
							
GPS Location	See photo	GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	AR in good condition	Pic 2 Desc.	CFS perimeter controls functional	Pic 3 Desc.	Housekeeping trash in place		
							
GPS Location	See photo	GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	RCE functional	Pic 6 Desc.	CFS perimeter controls functional	Pic 7 Desc.	RCE functional		
Pic 8 Desc.		Pic 8 Desc.		Pic 8 Desc.			

AFE 124300137	Date/Time 1/25/2022 9:51 AM	Report #
----------------------	------------------------------------	-----------------

Pictures



GPS Location	See photo	GPS Location	
---------------------	-----------	---------------------	--

Field Station#	12005+00	Field Station#	
-----------------------	----------	-----------------------	--

Pic 7 Desc.	CFS perimeter controls & safety fence in place	Pic 8 Desc.	
--------------------	--	--------------------	--

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300137	Date/Time 1/25/2022 9:51 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33601	
Inspector Rob Robertson		Date/Time 1/25/2022 1:20 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11600+01
State VA	Inspection Area Partial	Station End	11670+00
County Montgomery	Ground Frozen	Temperature (°F)	37.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/25/2022 1:20 PM	Report # 33601
----------------------	------------------------------------	-----------------------

6. **PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a regular scheduled VADEQ SWPPP inspection on JNF and private lands at Brush Mountain today. The ROW still has several inches of snow on the ground. No slips or issues associated with runoff were located. Slope breakers, sumps and end treatments are in acceptable condition. No problems caused by freezing conditions or snow melt runoff were discovered. Perimeter ECDs are in place with no visible maintenance needs identified. Stream crossings remain stable with no impact apparent. RCEs and access road MN-258.04 (11613+69) are in good condition. No evidence of trespass was noticed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/25/2022 1:20 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	On photo	GPS Location	On photo
Field Station#	11670+00	Field Station#	11661+00
Pic 1 Desc.	ROW stable at top of Brush Mountain.	Pic 2 Desc.	Perimeter ECDs are in place. ROW is stable.



GPS Location	On photo	GPS Location	On photo
Field Station#	11655+00	Field Station#	11653+00
Pic 3 Desc.	Perimeter ECDs are in place. No movement of sediment discovered.	Pic 4 Desc.	ECDs along perimeter are in place. No maintenance needs were identified.



GPS Location	On photo	GPS Location	On photo
Field Station#	11652+00	Field Station#	11641+00
Pic 5 Desc.	Perimeter ECDs are in place. No issues caused by runoff.	Pic 6 Desc.	Slope breakers functional. ROW stable.

AFE 124300137	Date/Time 1/25/2022 1:20 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	On photo	GPS Location	On photo
Field Station#	11626+04	Field Station#	11614+20
Pic 7 Desc.	ECDs at the S-HH18 crossing are in good condition.	Pic 8 Desc.	The S-RR14 crossing is currently stable.



GPS Location	On photo	GPS Location	On photo
Field Station#	11613+69	Field Station#	11608+17
Pic 9 Desc.	The S-RR13 equipment bridge and ECDs are in good condition on access road MN-258.04.	Pic 10 Desc.	The S-006 crossing is currently stable.



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	1/25/2022 1:20 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33594	
Inspector Clint Sears		Date/Time 1/25/2022 12:21 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Partial	Station End	12005+00
County Giles	Ground Wet	Temperature (°F)	45.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/25/2022 12:21 PM	Report # 33594
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed VA SWPPP inspection of LDY-29
 They were no deficiencies found at this time.
 There are no crews currently working at this location.
 AR-238.00 - Access road and RCE are maintained in acceptable condition.
 Triple stack CFS perimeter controls and overhead utility flagging are in place.
 Waste management and housekeeping are acceptable.
 Culvert is in place and functional.
 Equipment has been inspected and no visible leaks or spills at this time
 Yard mainly used for 798 welders to store materials and equipment as well as park vehicles.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/25/2022 12:21 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	12005+00	Field Station#	12005+00
-----------------------	----------	-----------------------	----------

Pic 1 Desc.	Culvert in place	Pic 2 Desc.	Equipment checked no visible leaks or spills
--------------------	------------------	--------------------	--



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	12005+00	Field Station#	12005+00
-----------------------	----------	-----------------------	----------

Pic 3 Desc.	Secondary containment in place	Pic 4 Desc.	Dumpsters in place
--------------------	--------------------------------	--------------------	--------------------



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	12005+00	Field Station#	12005+00
-----------------------	----------	-----------------------	----------

Pic 5 Desc.	Rock surface of RCE is in acceptable condition	Pic 6 Desc.	CFS perimeter controls are in acceptable condition
--------------------	--	--------------------	--

AFE 124300137	Date/Time 1/25/2022 12:21 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	1/25/2022 12:21 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33530	
Inspector Eric Hanlon		Date/Time 1/25/2022 8:45 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Full	Station End	12005+00
County Giles	Ground Wet	Temperature (°F)	36.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/25/2022 8:45 AM	Report # 33530
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a VA SWPPP inspection on yard 26.
 No compliance issues noted.
 Observance:
 Yard 26 has reduced activity during the winter curtailment.
 Perimeter controls in place & functioning as designed.
 RCE was clean, no mud or other debris on road.
 Secondary containment in place & functional as designed.
 All other ECDs and BMPs functional at time of inspection.
 No impact to sensitive resources observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/25/2022 8:45 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	12005+00	Field Station#	12005+00
Pic 1 Desc.	CFS perimeter controls in place	Pic 2 Desc.	CFS Inlet protection in place



GPS Location	See photo	GPS Location	See photo
Field Station#	12005+00	Field Station#	12005+00
Pic 3 Desc.	CFS perimeter controls in place	Pic 4 Desc.	Secondary containment in place



GPS Location	See photo	GPS Location	See photo
Field Station#	12005+00	Field Station#	12005+00
Pic 5 Desc.	Housekeeping trash in place	Pic 6 Desc.	Secondary containment in place

AFE 124300137	Date/Time 1/25/2022 8:45 AM	Report #
----------------------	------------------------------------	-----------------

Pictures



Insert image here

GPS Location	See photo	GPS Location	
---------------------	-----------	---------------------	--

Field Station#	12005+00	Field Station#	
-----------------------	----------	-----------------------	--

Pic 7 Desc.	RCE in good condition	Pic 8 Desc.	
--------------------	-----------------------	--------------------	--

Insert image here

Insert image here

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--

Insert image here

Insert image here

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300137	Date/Time 1/25/2022 8:45 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33648	
Inspector Joe Sweeden		Date/Time 1/26/2022 11:30 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 10859+46	
State VA	Inspection Area Partial	Station End 10929+80	
County Giles	Ground Frozen	Temperature (°F) 20.00	
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/26/2022 11:30 AM	Report # 33648
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed Virginia SWPP inspection from station # 10859+46-10929+80.(MP 205.67-207.00) Kow Camp gravel to Doe Creek, with El Daniel Fortune.
 No Deficiencies found today.
 Observances:
 Freezing temperatures
 ROW conditions are frozen with small areas of snow remaining on the ROW.
 Water bodies were flowing water.
 Environmental controls at water bodies are in place and functioning as designed.
 The ROW has been temporarily stabilized.
 Soil piles are stabilized.
 No trash on the ROW.
 No sensitive resources were impacted.
 All perimeter controls, ECDs and BMPs were functional at time of inspection.
 An Environmental crew was working in the area, walking the ROW.
 Rock Road approaches are clean and free of loose rock.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 1/26/2022 11:30 AM		Report #			
Pictures							
 <p>Date & Time: Wed, Jan 26, 2022, 09:34:51 EST Position: +037.337207° / -080.609897° (-936.11ft) Altitude: 2451ft (-9.9ft) Datum: WGS-84 Azimuth/Bearing: 338° N25W 43.20mils True (-14°) Elevation Angle: -8.8° Horizon Angle: -01° Zoom: 1.0X Stabilized ROW: 10859+00 Spread G</p>		 <p>Date & Time: Wed, Jan 26, 2022, 08:06:01 EST Position: +037.336597° / -080.608837° (-934.40ft) Altitude: 2482ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 119° S61E 211.6mils True (-14°) Elevation Angle: -17.0° Horizon Angle: -00.4° Zoom: 1.0X Stabilized ROW: 10868+00 Spread G</p>		<p>GPS Location See photo</p> <p>Field Station# 10859+46</p> <p>Pic 1 Desc. Kow camp RCE</p>		<p>GPS Location see photo</p> <p>Field Station# 10868+00</p> <p>Pic 2 Desc. Stabilized ROW</p>	
 <p>Date & Time: Wed, Jan 26, 2022, 08:59:21 EST Position: +037.339823° / -080.603373° (-916.4ft) Altitude: 2665ft (-7.8ft) Datum: WGS-84 Azimuth/Bearing: 358° N02W 63.64mils True (-10°) Elevation Angle: 33.6° Horizon Angle: -03° Zoom: 1.0X Level spreader: 10872+00 Spread G</p>		 <p>Date & Time: Wed, Jan 26, 2022, 09:40:12 EST Position: +037.333531° / -080.585974° (-916.4ft) Altitude: 2448ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 122° S68E 21.69mils True (-15°) Elevation Angle: -27.9° Horizon Angle: -01.5° Zoom: 1.0X Stabilized ROW, daylight drain, sumps: 10918+00 Spread G</p>		<p>GPS Location see photo</p> <p>Field Station# 10872+00</p> <p>Pic 3 Desc. Level spreader</p>		<p>GPS Location see photo</p> <p>Field Station# 10918+00</p> <p>Pic 4 Desc. Stabilized ROW, daylight drain, sumps</p>	
 <p>Date & Time: Wed, Jan 26, 2022, 09:05:47 EST Position: +037.335076° / -080.596662° (-910.4ft) Altitude: 2179ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 305° N55W 54.22mils True (-16°) Elevation Angle: -19.5° Horizon Angle: +00.6° Zoom: 1.0X S-A32, Kow camp pavement: 10883+00 Spread G</p>		 <p>Date & Time: Wed, Jan 26, 2022, 09:18:42 EST Position: +037.334519° / -080.594901° (-908.4ft) Altitude: 2318ft (-9.4ft) Datum: WGS-84 Azimuth/Bearing: 290° N70W 51.56mils True (-10°) Elevation Angle: -37.2° Horizon Angle: +00.1° Zoom: 1.0X Water bars, sumps, ETs: 10890+00 Spread G</p>		<p>GPS Location see photo</p> <p>Field Station# 10883+00</p> <p>Pic 5 Desc. S-A 32, Kow Camp pavement</p>		<p>GPS Location see photo</p> <p>Field Station# 10890+00</p> <p>Pic 6 Desc. Water bars sumps, ETs</p>	


AFE 124300137	Date/Time 1/26/2022 11:30 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures




GPS Location	See photo	GPS Location	see photo
Field Station#	10899+00	Field Station#	10925+00

Pic 7 Desc.	Stabilized Soil piles	Pic 8 Desc.	Erosion control blanket, sumps.
--------------------	-----------------------	--------------------	---------------------------------



GPS Location	see photo	GPS Location	see photo
Field Station#	10928+00	Field Station#	10929+00
Pic 9 Desc.	S-Y 3	Pic 10 Desc.	S-Y 2, Doe Creek



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 1/26/2022 11:30 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33642	
Inspector Clint Sears		Date/Time 1/26/2022 10:59 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10749+92
State VA	Inspection Area Partial	Station End	10798+92
County Giles	Ground Frozen	Temperature (°F)	27.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sump Pit	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/26/2022 10:59 AM	Report # 33642
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Met with Environmental staff.
 Completed VA SWPPP inspection from Sta#10749+92 to Sta#10798+92 (MP 203.6 to MP 204.53)
 Fellow EI Chris Burns accompanied during SWPPP inspection.
 No deficiencies were found at time of inspection.
 This section of Row has undergone temporary vegetation and stabilization.
 All other perimeter controls, ECD'S and BMPs were functional at time of inspection.
 There are no crews actively working on this section of Row.
 Row is in stable condition.
 No sensitive resource have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 1/26/2022 10:59 AM		Report #			
Pictures							
 <p>Date & Time: Wed Jan 26 2022 10:59 EST Position: +037 342886 / -080 631130 Altitude: 2180ft (663m) Datum: WGS 84 Azimuth Bearing: 088.188E 1544mils True (+16) Elevation Angle: 119.7 Horizon Angle: 01.1 Zoom: 1.0x 10750+50</p>		 <p>Date & Time: Wed Jan 26 2022 09:14:2 EST Position: +037 342886 / -080 631130 Altitude: 2180ft (663m) Datum: WGS 84 Azimuth Bearing: 088.188E 1544mils True (+16) Elevation Angle: 119.7 Horizon Angle: 01.1 Zoom: 1.0x 10756+88</p>		<p>GPS Location See photo</p> <p>Field Station# 10750+50</p> <p>Pic 1 Desc. RCE is maintained in acceptable condition</p>		<p>GPS Location See photo</p> <p>Field Station# 10756+88</p> <p>Pic 2 Desc. Section of Row showing conditions and controls</p>	
 <p>Date & Time: Wed Jan 26 2022 09:03:57 EST Position: +037 342886 / -080 631130 Altitude: 2078ft (633m) Datum: WGS 84 Azimuth Bearing: 092.103E 050mils True (+16) Elevation Angle: 111.7 Horizon Angle: 00.7 Zoom: 1.0x 10758+35</p>		 <p>Date & Time: Wed Jan 26 2022 09:09:17 EST Position: +037 342886 / -080 631130 Altitude: 2177ft (663m) Datum: WGS 84 Azimuth Bearing: 290.020W 3160mils True (+15) Elevation Angle: 92.3 Horizon Angle: 00.31 Zoom: 1.0x 10764+95</p>		<p>GPS Location See photo</p> <p>Field Station# 10758+35</p> <p>Pic 3 Desc. S-G35 showing conditions and controls</p>		<p>GPS Location See photo</p> <p>Field Station# 10764+95</p> <p>Pic 4 Desc. S-SS4 showing conditions and controls</p>	
 <p>Date & Time: Wed Jan 26 2022 09:11:48 EST Position: +037 342886 / -080 631130 Altitude: 2165ft (659m) Datum: WGS 84 Azimuth Bearing: 162.518E 2680mils True (+12.1) Elevation Angle: -19.7 Horizon Angle: -01.6 Zoom: 1.0x 10771+75</p>		 <p>Date & Time: Wed Jan 26 2022 09:10:58 EST Position: +037 342886 / -080 631130 Altitude: 2171ft (661m) Datum: WGS 84 Azimuth Bearing: 097.138E 0699mils True (+2) Elevation Angle: 97.2 Horizon Angle: -06.5 Zoom: 1.0x 10773+73</p>		<p>GPS Location See photo</p> <p>Field Station# 10771+75</p> <p>Pic 5 Desc. Clean water diversion pipe and level spreader</p>		<p>GPS Location See photo</p> <p>Field Station# 10773+73</p> <p>Pic 6 Desc. S-Z9 showing conditions and controls</p>	

AFE 124300137	Date/Time 1/26/2022 10:59 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	10780+40	Field Station#	10792+00
Pic 7 Desc.	S-Z7 showing conditions and controls	Pic 8 Desc.	Section of Row showing conditions and controls

Insert image here

Insert image here

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here

Insert image here

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 1/26/2022 10:59 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33634	
Inspector Eric Hanlon		Date/Time 1/26/2022 7:28 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10655+00
State VA	Inspection Area Full	Station End	10749+92
County Giles	Ground Frozen	Temperature (°F)	25.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/26/2022 7:28 AM	Report # 33634
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a VA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6).
 No Compliance issues noted:
 Observance:
 Crew 1704 was dressing up AR 241.01 & 241.04 with skid steer.
 Perimeter controls in place & functioning as designed.
 ROW has been temporary stabilized.
 No areas with open ditch.
 All other ECDs and BMPs functional at time of inspection.
 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11.
 AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition.
 The ROW was frozen but in stable condition.
 No sensitive resources have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 1/26/2022 7:28 AM		Report #	
Pictures					
					
GPS Location See photo		GPS Location See photo			
Field Station# 10708+22		Field Station# 10712+73			
Pic 1 Desc. Skid steer dressing up AR 241.04		Pic 2 Desc. Equipment bridge functional			
					
GPS Location See photo		GPS Location See photo			
Field Station# 10712+73		Field Station# 10703+00			
Pic 3 Desc. 50' buffers in place		Pic 4 Desc. ET functional			
					
GPS Location See photo		GPS Location See photo			
Field Station# 10698+00		Field Station# 10695+00			
Pic 5 Desc. Wattles in place		Pic 6 Desc. Clean water drainage feature functional			

AFE	124300137	Date/Time	1/26/2022 7:28 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo
Field Station#	10692+00
Pic 7 Desc.	AR 241 in good condition

GPS Location	See photo
Field Station#	10733+24
Pic 8 Desc.	Equipment bridge functional



GPS Location	See photo
Field Station#	10686+00
Pic 9 Desc.	Water bars in place

GPS Location	See photo
Field Station#	10742+69
Pic 10 Desc.	Clean water drainage feature functional



GPS Location	See photo
Field Station#	10679+39
Pic 11 Desc.	P1 in place

GPS Location	See photo
Field Station#	10676+00
Pic 12 Desc.	Erosion control blanket & water bars in place

AFE 124300137	Date/Time 1/26/2022 7:28 AM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	10658+00	Field Station#	10665+00
Pic 13 Desc.	Water bars in place	Pic 14 Desc.	SSF functional



GPS Location	See photo	GPS Location	See photo
Field Station#	10667+00	Field Station#	10670+00
Pic 15 Desc.	Clean water drainage pipe in place	Pic 16 Desc.	RCE functional



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33653	
Inspector Jared Saunders		Date/Time 1/26/2022 1:32 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10798+92
State VA	Inspection Area Partial	Station End	10859+46
County Giles	Ground Frozen	Temperature (°F)	30.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/26/2022 1:32 PM	Report # 33653
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 10798+92 (Cascade) to ST# 10859+46 (Kow Camp Gravel) MP 204.53 to MP 205.67
 No deficiencies were located during inspection.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed environmental maintenance crew hauling in equipment and staging up straws bales for future stabilization at AR-241.02.
 Perimeter controls and end treatments are in place.
 This section of ROW has undergone temporary stabilization. Topsoil piles and clean water diversion berms have been stabilized.
 Sensitive resource buffers are in place at stream crossings S-A33, S-A34, and S-Z14.
 AR-241.02, 241.03, and Cascade Drive road crossing RCEs are maintained in acceptable condition.
 No sensitive resources have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/26/2022 1:32 PM	Report #
Pictures				
 <p><small>Date & Time: Wed Jan 26 2022 08:19:54 EST Position: +097.332773° -1080.237712° -16421.0in Altitude: 1707ft (-412.95) Datum: WGS-84 Azimuth/Bearing: 311° N65W 5527mils True (-18) Elevation Angle: -27.1 Horizon Angle: -00.6 Zoom: 1.0X 10858+00</small></p>		 <p><small>Date & Time: Wed Jan 26 2022 08:21:00 EST Position: +037.339427° -1080.604771° -12629.0in Altitude: 2291ft (-216.8ft) Datum: WGS-84 Azimuth/Bearing: 284° N76W 5049mils True (-18) Elevation Angle: -09.7 Horizon Angle: -00.3 Zoom: 1.0X 10855+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	10858+00	Field Station#	10855+00	
Pic 1 Desc.	Slope drains in place over two-tone.	Pic 2 Desc.	Sensitive resource buffer in place at streams S-A33 and S-A34.	
 <p><small>Date & Time: Wed Jan 26 2022 08:30:06 EST Position: +097.332773° -1080.562381° -14100.0in Altitude: 2131ft (-327.9) Datum: WGS-84 Azimuth/Bearing: 304° N64W 3800mils True (-18) Elevation Angle: -17.2 Horizon Angle: -03.2 Zoom: 1.0X 10847+00</small></p>		 <p><small>Date & Time: Wed Jan 26 2022 08:31:10 EST Position: +097.332773° -1080.510331° -12192.0in Altitude: 2160ft (-302.0) Datum: WGS-84 Azimuth/Bearing: 278° N82W 4942mils True (-14) Elevation Angle: -17.5 Horizon Angle: -04.5 Zoom: 1.0X 10833+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	10847+00	Field Station#	10833+00	
Pic 3 Desc.	Clean water diversion pipe and level spreader in place.	Pic 4 Desc.	ROW temporarily stabilized. Waterbars in place.	
 <p><small>Date & Time: Wed Jan 26 2022 08:37:29 EST Position: +097.332773° -1080.520021° -15312.0in Altitude: 2171ft (-107.9) Datum: WGS-84 Azimuth/Bearing: 320° N32W 3381mils True (-14) Elevation Angle: -12.5 Horizon Angle: -03.1 Zoom: 1.0X 10816+00</small></p>		 <p><small>Date & Time: Wed Jan 26 2022 08:38:25 EST Position: +097.332773° -1080.533131° -15529.0in Altitude: 1941ft (-131.9) Datum: WGS-84 Azimuth/Bearing: 321° N30W 4707mils True (-12) Elevation Angle: -17.2 Horizon Angle: -01.7 Zoom: 1.0X 10803+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	10816+00	Field Station#	10803+00	
Pic 5 Desc.	Waterbar, end treatment, sump pit, and super silt fence in place.	Pic 6 Desc.	RCE in place at Acher Trail access.	

AFE 124300137	Date/Time 1/26/2022 1:32 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	1/26/2022 1:32 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33689	
Inspector Chris Burns		Date/Time 1/27/2022 1:33 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10929+80
State VA	Inspection Area Partial	Station End	11023+80
County Giles	Ground Frozen	Temperature (°F)	36.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/27/2022 1:33 PM	Report # 33689
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection from MP 207 (10929+80) and MP 208.78 (11023+80).
 Accompanied by fellow EI Clint Sears.
 This section of RoW has no current construction.
 A portion of this section of RoW has been permanently restored.
 Assessed AR 242.01.
 AR 242.01 is partially completed, incomplete portions are stabilized.
 No issues were identified.
 All perimeter controls, ECDs and BMPs functional at time of inspection.
 Vegetation or stabilization sufficient less.
 Stream buffers and controls in place at the time of inspection.
 No impact to sensitive resources observed.
 Section 6 - CFS waterbars (other).

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/27/2022 1:33 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	1	GPS Location	2
Field Station#	11016+79	Field Station#	11015+52
Pic 1 Desc.	S-PA07.	Pic 2 Desc.	S-RR5.




GPS Location	3	GPS Location	4
Field Station#	11088+50	Field Station#	11004+00
Pic 3 Desc.	SSF perimeter controls functional.	Pic 4 Desc.	CWDP outlet protection functional.



GPS Location	5	GPS Location	6
Field Station#	10987+45	Field Station#	10985+95
Pic 5 Desc.	S-E25.	Pic 6 Desc.	S-E24.

AFE	124300137	Date/Time	1/27/2022 1:33 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

 <p><small>Date & Time: Thu, Jan 27, 2022, 10:12:49 EST Position: 1898633239 E / 3687030728 N (+13.01) Altitude: 2393ft (+73.21m) Datum: WGS-84 Azimuth/Bearing: 198° S10W 3669mils True (+12°) Elevation Angle: +20.2° Horizon Angle: +04.6° Zoom: 0.5X 10976+00</small></p>		 <p><small>Date & Time: Thu, Jan 27, 2022, 10:17:48 EST Position: 1898637272 E / 368688281 N (+15.11) Altitude: 2393ft (+73.21m) Datum: WGS-84 Azimuth/Bearing: 215° S34W 3820mils True (+12°) Elevation Angle: +12.2° Horizon Angle: +00.2° Zoom: 0.5X AR 242.01 10971+74</small></p>	
GPS Location	7	GPS Location	8
Field Station#	10976+00	Field Station#	10971+74
Pic 7 Desc.	Clear water drainage.	Pic 8 Desc.	AR 242.01 showing conditions and controls.
 <p><small>Date & Time: Thu, Jan 27, 2022, 10:22:56 EST Position: 13977527771 E / 365887925 N (+12.21) Altitude: 2344ft (+71.24m) Datum: WGS-84 Azimuth/Bearing: 330° N24W 5973mils True (+12°) Elevation Angle: +19.2° Horizon Angle: +05.5° Zoom: 0.5X 10966+25</small></p>		 <p><small>Date & Time: Thu, Jan 27, 2022, 10:26:02 EST Position: 1401777230 E / 373610352 N (+5958.3ft) Altitude: 2268ft (+69.21m) Datum: WGS-84 Azimuth/Bearing: 287° N73W 5102mils True (+12°) Elevation Angle: +03.9° Horizon Angle: +05.1° Zoom: 0.5X 10961+76</small></p>	
GPS Location	9	GPS Location	10
Field Station#	10966+25	Field Station#	10961+76
Pic 9 Desc.	Karst feature protection functional.	Pic 10 Desc.	Section of restored RoW showing conditions and controls.
 <p><small>Date & Time: Thu, Jan 27, 2022, 10:33:40 EST Position: 1396161865 E / 369209567 N (+15.5ft) Altitude: 2201ft (+67.11m) Datum: WGS-84 Azimuth/Bearing: 280° N80W 4978mils True (+12°) Elevation Angle: +06.4° Horizon Angle: +01.4° Zoom: 0.5X 10949+00</small></p>		 <p><small>Date & Time: Thu, Jan 27, 2022, 10:38:43 EST Position: 1395177978 E / 369580773 N (+174.2ft) Altitude: 2242ft (+68.71m) Datum: WGS-84 Azimuth/Bearing: 305° N55W 5422mils True (+12°) Elevation Angle: +05.9° Horizon Angle: +00.2° Zoom: 0.5X 10934+00</small></p>	
GPS Location	11	GPS Location	12
Field Station#	10949+00	Field Station#	10934+00
Pic 11 Desc.	Section of restored RoW showing conditions and controls.	Pic 12 Desc.	P-1 perimeter controls functional.

AFE 124300137	Date/Time 1/27/2022 1:33 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33675	
Inspector Eric Hanlon		Date/Time 1/27/2022 7:46 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11184+85
State VA	Inspection Area Full	Station End	11254+99
County Giles	Ground Frozen	Temperature (°F)	13.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Stone Inlet Protection	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/27/2022 7:46 AM	Report # 33675
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6).
 No Compliance issues noted:
 Observance:
 Perimeter controls in place & functioning as designed
 Permanent & temporary stabilization in place.
 - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. No maintenance is needed;
 - Temporary stabilization near 11222+50 to near 11253+50. Temporary vegetation remains visible. This section of row has been stabilized for the winter months. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. No deficiencies observed today.
 AR-249.02 & 244 RCE's are maintained in acceptable condition.
 The ROW frozen but is in stable condition.
 No sensitive resources have been impacted.


Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/27/2022 7:46 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

<p><small>Date & Time: Thu Jan 27 2022 09:21:27 EST Position: +037.309700 / -080.501988 (+37.30) Altitude: 2055ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 135 S45E 2000mils True (+10.1) Elevation Angle: -15.2 Horizon Angle: -03.0 Zoom: 1.0X winding way</small></p> 	<p><small>Date & Time: Thu Jan 27 2022 09:09:23 EST Position: +037.309556 / -080.503442 (+37.31ft) Altitude: 1982ft (+31.7ft) Datum: WGS-84 Azimuth/Bearing: 268 S68W 4409mils True (+10.1) Elevation Angle: -03.0 Horizon Angle: -03.0 Zoom: 1.0X winding way</small></p> 
--	---

GPS Location	See photo	GPS Location	See photo
Field Station#	11227+59	Field Station#	11227+59
Pic 1 Desc.	SSF functional	Pic 2 Desc.	RCE functional

<p><small>Date & Time: Thu Jan 27 2022 09:09:07 EST Position: +037.309326 / -080.503340 (+37.31ft) Altitude: 1968ft (+38.8ft) Datum: WGS-84 Azimuth/Bearing: 217 S37W 3856mils True (+10.1) Elevation Angle: -05.2 Horizon Angle: -03.2 Zoom: 1.0X winding way</small></p> 	<p><small>Date & Time: Thu Jan 27 2022 09:05:48 EST Position: +037.307310 / -080.511854 (+37.22ft) Altitude: 1974ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 090° N90E 1600mils True (+12.1) Elevation Angle: -11.2 Horizon Angle: -06.3 Zoom: 0.5X 11185+00</small></p> 
---	--

GPS Location	See photo	GPS Location	See photo
Field Station#	11227+59	Field Station#	11185+00
Pic 3 Desc.	CFS controls functional	Pic 4 Desc.	AR 249.02 functional

<p><small>Date & Time: Thu Jan 27 2022 09:03:06 EST Position: +037.304922 / -080.510543 (+37.27ft) Altitude: 1995ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 304 N54W 5440mils True (+12.1) Elevation Angle: -03.0 Horizon Angle: -03.9 Zoom: 0.5X 11188+00</small></p> 	<p><small>Date & Time: Thu Jan 27 2022 09:03:06 EST Position: +037.304922 / -080.510543 (+37.27ft) Altitude: 1995ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 188 S08W 3342mils True (+12.1) Elevation Angle: -08.2 Horizon Angle: -03.9 Zoom: 0.5X 11191+02</small></p> 
---	--

GPS Location	See photo	GPS Location	See photo
Field Station#	11188+00	Field Station#	11191+02
Pic 5 Desc.	Stabilization in place	Pic 6 Desc.	Clean water drainage feature functional

AFE	124300137	Date/Time	1/27/2022 7:46 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo
Field Station#	11251+00
Pic 7 Desc.	Water bars in place



GPS Location	See photo
Field Station#	11196+50
Pic 8 Desc.	CFS controls in place



GPS Location	See photo
Field Station#	11245+00
Pic 9 Desc.	Stabilization in place



GPS Location	See photo
Field Station#	11244+00
Pic 10 Desc.	CFS perimeter controls functional



GPS Location	See photo
Field Station#	11205+00
Pic 11 Desc.	CFS controls in place



GPS Location	See photo
Field Station#	11208+00
Pic 12 Desc.	Permanent water bars in place

AFE 124300137		Date/Time 1/27/2022 7:46 AM		Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11218+00	Field Station#	11237+00		
Pic 13 Desc.	Permanent level spreader in place	Pic 14 Desc.	Stone inlet in place		
GPS Location	See photo	GPS Location	See photo		
Field Station#	11233+50	Field Station#	11233+00		
Pic 15 Desc.	ET in place	Pic 16 Desc.	P1 perimeter controls functional		
GPS Location	See photo	GPS Location			
Field Station#	11227+00	Field Station#			
Pic 17 Desc.	Water bars in place	Pic 18 Desc.			



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33685	
Inspector Daniel Fortune		Date/Time 1/27/2022 11:16 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11023+80	
State VA	Inspection Area Partial	Station End 11098+47	
County Giles	Ground Frozen	Temperature (°F) 17.00	
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in) 0.00	
Rain Accumulation Time (days)			0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/27/2022 11:16 AM	Report # 33685
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

UNKNOWN TO EI AT THIS TIME OF INSPECTION.

Comments (Reference above questions as appropriate.)

Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02.
 No deficiencies found or documented today.
 Other deficiencies may be found and reported by other EI's/and or MBP personnel.
 Station numbers are approximate.

ROW CONDITIONS:

The ROW in that area received 0.00" of precipitation overnight. The ROW is intermittently and frozen throughout with below freezing temperatures around 17*
 The ROW from AR 244 to AR 245.01 has been temporarily stabilized. The ROW from 245.01 to 245.02 has been restored. The restored area is in good shape and the vegetation is sufficient.
 The water bars (other), in the restored area are in place and functioning as designed.
 The environmental controls are functional. No construction being performed in the area.
 One area of open ditch in the area. Rock Road approaches were cleaned and functioning as designed.
 The EC's at the WB's in this area are in place and functioning as designed.
 LOD ECDs were in place and functional. Water bars have been installed to specifications.
 No sensitive resources have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 1/27/2022 11:16 AM		Report #			
Pictures							
<p>Date & Time: Thu Jan 27, 2022, 10:05:46 EST Position: +037.312977 / -080.533621 (-14.7ft) Altitude: 1938ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 337° N23W 5991mils True (+13°) Elevation Grade: +004° Horizon Grade: -004° Zoom: 0.5X 11098+33</p> 		<p>Date & Time: Thu Jan 27, 2022, 09:56:41 EST Position: +037.315126 / -080.532642 (-12.2ft) Altitude: 2145ft (-26.2ft) Datum: WGS-84 Azimuth/Bearing: 130° S59E 2311mils True (+13°) Elevation Grade: +030° Horizon Grade: -004° Zoom: 0.5X 11084+19</p> 		<p>Date & Time: Thu Jan 27, 2022, 09:56:11 EST Position: +037.315356 / -080.538107 (-14.32 ft) Altitude: 2157ft (-630.0ft) Datum: WGS-84 Azimuth/Bearing: 229° S53E 2288mils True (+13°) Elevation Grade: +020° Horizon Grade: +001° Zoom: 0.5X 11081+38</p> 		<p>Date & Time: Thu Jan 27, 2022, 09:53:01 EST Position: +037.315406 / -080.532242 (-16.8ft) Altitude: 2218ft (-19.7ft) Datum: WGS-84 Azimuth/Bearing: 088° N88E 1544mils True (+13°) Elevation Grade: -153° Horizon Grade: -015° Zoom: 0.5X 11078+44</p> 	
GPS Location SEE PHOTO		GPS Location SEE PHOTO		GPS Location SEE PHOTO			
Field Station# 11098+33		Field Station# 11084+19		Field Station# 11081+38			
Pic 1 Desc. AR 245.02		Pic 2 Desc. Row conditions. Final Restoration Area. Annual grasses visible. (Other = CFS water bar). No erosion issues.		Pic 3 Desc. Row conditions. Final Restoration Area. Annual grasses visible. (Other = CFS water bar). No erosion issues.			
GPS Location SEE PHOTO		GPS Location SEE PHOTO		GPS Location SEE PHOTO			
Field Station# 11081+38		Field Station# 11078+44		Field Station# 11078+44			
Pic 3 Desc. Row conditions. Final Restoration Area. Annual grasses visible. (Other = CFS water bar). No erosion issues.		Pic 4 Desc. Approximately 6" corrugated surface drain tile outlet to perimeter CFS. Drain tile extends from surface upslope across the final restored		Pic 5 Desc. Row conditions. Final Restoration Area. Annual grasses visible. (Other = CFS water bar). No erosion issues.			
<p>Date & Time: Thu Jan 27, 2022, 09:51:31 EST Position: +037.315442 / -080.539629 (-13.36.2ft) Altitude: 2226ft (-178.7ft) Datum: WGS-84 Azimuth/Bearing: 093° S87E 1653mils True (+13°) Elevation Grade: -013° Horizon Grade: +033° Zoom: 0.5X 11078+44</p> 		<p>Date & Time: Thu Jan 27, 2022, 09:47:48 EST Position: +037.315249 / -080.541799 (-11.7ft) Altitude: 2226ft (-13.1ft) Datum: WGS-84 Azimuth/Bearing: 071° N71E 1262mils True (+13°) Elevation Grade: -003° Horizon Grade: -008° Zoom: 1.0X 11072+00</p> 		GPS Location SEE PHOTO			
Field Station# 11078+44		Field Station# 11072+00		Field Station# 11072+00			
Pic 5 Desc. Row conditions. Final Restoration Area. Annual grasses visible. (Other = CFS water bar). No erosion issues.		Pic 6 Desc. Row conditions. Final Restoration Area. Annual grasses visible. (Other = CFS water bar). No erosion issues.		Pic 6 Desc. Row conditions. Final Restoration Area. Annual grasses visible. (Other = CFS water bar). No erosion issues.			

AFE 124300137	Date/Time 1/27/2022 11:16 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures



GPS Location	SEE PHOTO	GPS Location	SEE PHOTO
Field Station#	11068+00	Field Station#	11065+00
Pic 7 Desc.	Temporary stabilized row and water bar conditions.	Pic 8 Desc.	Drainage feature conditions. Limited growth where the CC4 ECB is installed.



GPS Location	SEE PHOTO	GPS Location	SEE PHOTO
Field Station#	11061+83	Field Station#	11056+00
Pic 9 Desc.	Open ditch line for future valve site.	Pic 10 Desc.	Perimeter P1, triple stacked 18", and super silt fence protecting sensitive resource area located outside LOD.



GPS Location	SEE PHOTO	GPS Location	SEE PHOTO
Field Station#	11053+00	Field Station#	11050+00
Pic 11 Desc.	Perimeter P1 silt fencing conditions.	Pic 12 Desc.	View looking down stream

AFE 124300137	Date/Time 1/27/2022 11:16 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures



GPS Location	SEE PHOTO
---------------------	-----------

GPS Location	SEE PHOTO
---------------------	-----------

Field Station#	11050+00
-----------------------	----------

Field Station#	11040+27
-----------------------	----------

Pic 13 Desc.	View of stream buffer zones, temporary stabilization of row and stable water bar conditions.
---------------------	--

Pic 14 Desc.	TSP to sump pit conditions.
---------------------	-----------------------------



GPS Location	SEE PHOTO
---------------------	-----------

GPS Location	SEE PHOTO
---------------------	-----------

Field Station#	11040+27
-----------------------	----------

Field Station#	11035+00
-----------------------	----------

Pic 15 Desc.	Stone inlet protection conditions
---------------------	-----------------------------------

Pic 16 Desc.	Temporary diversion dike and perimeter CFS.
---------------------	---



GPS Location	SEE PHOTO
---------------------	-----------

GPS Location	SEE PHOTO
---------------------	-----------

Field Station#	11037+00
-----------------------	----------

Field Station#	11025+50
-----------------------	----------

Pic 17 Desc.	Temporary stabilization
---------------------	-------------------------

Pic 18 Desc.	Equipment bridge condition
---------------------	----------------------------



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33697	
Inspector Jared Saunders		Date/Time 1/27/2022 3:55 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11098+47
State VA	Inspection Area Partial	Station End	11184+85
County Giles	Ground Frozen	Temperature (°F)	32.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/27/2022 3:55 PM	Report # 33697
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11098+47 (AR-245.02) to ST# 11184+85 (AR-249.02)
 MP 210.2 to MP 211.83
 No deficiencies were located during inspection.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed no crews actively working on this section of ROW at time of inspection.
 ST# 11445+50 to ST# 11170+00 has undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place.
 Final restoration has occurred between ST# 11098+47 and ST# 11145+50 and between ST# 11170+00 and ST# 11184+85. CFS perimeter controls, end treatments and temporary waterbars are in place. Daylight drains with outlet protection and Permanent waterbars (other in section 6) with level spreaders are in place.
 AR-245.02, 249, 249.03, 249.01 and 249.02 RCEs are maintained in acceptable condition.
 No sensitive resources have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/27/2022 3:55 PM	Report #
Pictures				
<p>Date & Time: Thu Jan 27 2022 09:08:59 EST Position: -037.313749 / -080.532391 (+37.0h) Altitude: 2022ft (+36.5h) Datum: WGS-84 Azimuth/Bearing: 027° N47E 0836mils True (±14.1) Elevation Angle: -09.1 Horizon Angle: -04.9 Zoom: 1.0X 11105+00</p> 		<p>Date & Time: Thu Jan 27 2022 09:11:00 EST Position: -037.313749 / -080.532391 (+37.0h) Altitude: 2138ft (+36.4h) Datum: WGS-84 Azimuth/Bearing: 068° N48E 1209mils True (±17.1) Elevation Angle: -20.2 Horizon Angle: -06.5 Zoom: 1.0X 11112+00</p> 		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11105+00	Field Station#	11112+00	
Pic 1 Desc.	ROW permanently stabilized.	Pic 2 Desc.	Triple stack 18 inch CFS in place along LOD.	
<p>Date & Time: Thu Jan 27 2022 09:28:09 EST Position: -037.312908 / -080.519319 (+15.4h) Altitude: 2108ft (+27.8h) Datum: WGS-84 Azimuth/Bearing: 161° S19E 2842mils True (±12.1) Elevation Angle: -27.9 Horizon Angle: -04.3 Zoom: 1.0X 11144+20</p> 		<p>Date & Time: Thu Jan 27 2022 09:55:03 EST Position: -037.3807631 / -080.5261674 (+39.7h) Altitude: 2002ft (+32.0h) Datum: WGS-84 Azimuth/Bearing: 172° S08E 3098mils True (±12.1) Elevation Angle: -26.2 Horizon Angle: -01.1 Zoom: 1.0X 11148+50</p> 		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11146+20	Field Station#	11148+50	
Pic 3 Desc.	Clean water diversion pipe and level spreader in place.	Pic 4 Desc.	Super silt fence in place along LOD.	
<p>Date & Time: Thu Jan 27 2022 09:48:01 EST Position: -037.312312 / -080.514297 (+26.2h) Altitude: 1853ft (+24.3h) Datum: WGS-84 Azimuth/Bearing: 214° S33W 3822mils True (±12.1) Elevation Angle: -06.7 Horizon Angle: -12.7 Zoom: 1.0X 11168+00</p> 		<p>Date & Time: Thu Jan 27 2022 09:52:03 EST Position: -037.320611 / -080.524444 (+26.0h) Altitude: 1869ft (+18.1h) Datum: WGS-84 Azimuth/Bearing: 195° S15W 3467mils True (±12.1) Elevation Angle: -14.7 Horizon Angle: -02.8 Zoom: 1.0X 11176+00</p> 		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11168+00	Field Station#	11176+00	
Pic 5 Desc.	RCE in place at AR 249.02.	Pic 6 Desc.	Permanent waterbar with level spreader in place.	

AFE 124300137	Date/Time 1/27/2022 3:55 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	1/27/2022 3:55 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33735	
Inspector Clint Sears		Date/Time 1/28/2022 1:52 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11471+56	
State VA	Inspection Area Partial	Station End 11524+16	
County Giles	Ground Frozen	Temperature (°F) 37.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock-lined Channel	Acceptable			
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300137	Date/Time	1/28/2022 1:52 PM	Report #	33735
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Met with environmental staff.
 Completed VA SWPPP inspection, from MP 217.26 (11471+56) and MP 218.26 (11524+16)
 Fellow EI Chris Burns accompanied.
 No deficiencies were found at time of inspection
 This section of Row has no current construction activity.
 All perimeter controls, ECDs and BMPs functional at time of inspection.
 Temporary Vegetation, stabilization are acceptable.
 KARST ECD'S are in place and acceptable.
 Row is frozen and some areas are snow covered.
 No impact to sensitive resources observed.
 Assessed AR 258.02 Stevers Gap and the Steele Acres access rd.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/28/2022 1:52 PM	Report #	
Pictures					
<p>Date & Time: Fri, Jan 28, 2022, 09:56:53 EST Position: +48.261937° / +80.45833° (+19.0) Altitude: 2237ft (+68.0m) Datum: WGS-84 Azimuth/Bearing: 35° N04E 632mils True (+16°) Elevation Angle: -8.2° Horizon Angle: -03.3° Zoom: 1.0X 11472+80</p>			<p>Date & Time: Fri, Jan 28, 2022, 09:56:54 EST Position: +48.261937° / +80.45833° (+19.0) Altitude: 2237ft (+68.0m) Datum: WGS-84 Azimuth/Bearing: 35° N04E 632mils True (+16°) Elevation Angle: -8.2° Horizon Angle: -03.3° Zoom: 1.0X 11478+79</p>		
GPS Location	See photo		GPS Location	see photo	
Field Station#	11472+80		Field Station#	11478+79	
Pic 1 Desc.	Section of Row showing conditions and controls		Pic 2 Desc.	Section of Row showing conditions and controls	
<p>Date & Time: Fri, Jan 28, 2022, 09:46:17 EST Position: +48.325598° / -080.432293° (+452.8ft) Altitude: 2168ft (+66.2ft) Datum: WGS-84 Azimuth/Bearing: 354° N04W 632mils True (+16°) Elevation Angle: -17.3° Horizon Angle: -01.3° Zoom: 1.0X 11488+75</p>			<p>Date & Time: Fri, Jan 28, 2022, 09:46:11 EST Position: +48.326228° / +80.45833° (+219.8ft) Altitude: 2150ft (+65.2ft) Datum: WGS-84 Azimuth/Bearing: 35° N04E 1060mils True (+16°) Elevation Angle: -03.2° Horizon Angle: +01.2° Zoom: 1.0X 11490+00</p>		
GPS Location	see photo		GPS Location	See photo	
Field Station#	11488+75		Field Station#	11490+00	
Pic 3 Desc.	Plunge pool is in acceptable condition		Pic 4 Desc.	RCE is maintained and in acceptable condition	
<p>Date & Time: Fri, Jan 28, 2022, 09:56:53 EST Position: +48.261937° / +80.45833° (+19.0) Altitude: 2245ft (+68.0m) Datum: WGS-84 Azimuth/Bearing: 012° N12E 0213mils True (+16°) Elevation Angle: -13.5° Horizon Angle: +01.8° Zoom: 1.0X 11504+00</p>			<p>Date & Time: Fri, Jan 28, 2022, 09:56:53 EST Position: +48.261937° / +80.45833° (+19.0) Altitude: 2245ft (+68.0m) Datum: WGS-84 Azimuth/Bearing: 332° N28W 5902mils True (+16°) Elevation Angle: -10.7° Horizon Angle: +02.7° Zoom: 1.0X 11507+78 S-PP3</p>		
GPS Location	See photo		GPS Location	see photo	
Field Station#	11504+00		Field Station#	11507+78	
Pic 5 Desc.	Rock lined channel		Pic 6 Desc.	Controls at S-PP3	

AFE 124300137	Date/Time 1/28/2022 1:52 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	11518+32	Field Station#	11522+00
-----------------------	----------	-----------------------	----------


Pic 7 Desc.	S-PP4 showing conditions and controls	Pic 8 Desc.	P1 silt fence and equipment bridge are in acceptable condition
--------------------	---------------------------------------	--------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

Pictures			
-----------------	--	--	--

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33730	
Inspector Joe Sweeden		Date/Time 1/28/2022 8:31 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11254+99	
State VA	Inspection Area Partial	Station End 11353+67	
County Giles	Ground Frozen	Temperature (°F) 28.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/28/2022 8:31 AM	Report # 33730
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed Virginia SWPP inspection from station # 11254+99-11353+67 (MP 213.6-215.04) Rte 42 - Old Furnace, with EI, Daniel Fortune.
 No Deficiencies found today.
 Observances:
 The ROW is partially snow covered, frozen on top, soft underneath.
 No precipitation over the last 24 hours.
 The ROW has been temporarily stabilized.
 Karst areas have occurred in sumps at station 11348+00.areas are protected with ECDs.
 The water bars and compost sock are in good condition.
 Steep slopes have had erosion control fabric placed on them. Vegetation is sufficient.
 Slope drains are functioning as designed.
 ECs at streams are in compliance.
 No trash on the ROW.
 No sensitive resources were impacted.
 All perimeter controls, ECDs and BMPs were functional at time of inspection.
 No other crews were working in the area.
 Rock Road approaches are clean and free of loose rock.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/28/2022 8:31 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	see photo
Field Station#	11258+00	Field Station#	11278+00
Pic 1 Desc.	Erosion blanket water bars	Pic 2 Desc.	Rock Basin, clean water diversion, sump



GPS Location	see photo	GPS Location	see photo
Field Station#	11292+66	Field Station#	11299+00
Pic 3 Desc.	SMM-18	Pic 4 Desc.	Stabilized ROW



GPS Location	see photo	GPS Location	see photo
Field Station#	11318+00	Field Station#	11328+00
Pic 5 Desc.	ECDs at sensitive area	Pic 6 Desc.	S-NN 12

AFE 124300137	Date/Time 1/28/2022 8:31 AM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	see photo	GPS Location	see photo
---------------------	-----------	---------------------	-----------

Field Station#	11351+00	Field Station#	11353+50
-----------------------	----------	-----------------------	----------


Pic 7 Desc.	ECDs at sensitive area	Pic 8 Desc.	S-NN 11
--------------------	------------------------	--------------------	---------



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300137	Date/Time 1/28/2022 8:31 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33729	
Inspector Jared Saunders		Date/Time 1/28/2022 10:34 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11353+67
State VA	Inspection Area Partial	Station End	11471+56
County Giles	Ground Frozen	Temperature (°F)	32.00
Municipality N/A	Weather Below Freezing Temp	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/28/2022 10:34 AM	Report # 33729
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11353+67 (Old Furnace) to ST# 11471+56 (Steele Acres) MP 215.04 to MP 217.26
 No deficiencies were located during inspection.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed since last VA SWPP inspection Environmental maintenance crew has repaired previous punch list items.
 ST# 11353+67 to ST# 11367+00 and ST# 11443+50 to ST# 11471+56 have undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Triple protection ECDs are in place at karst feature.
 Final restoration has occurred between ST# 11367+00 and ST# 11443+50. CFS perimeter controls, permanent waterbars (section 6 other) with level spreaders are in place.
 Sensitive resource buffers are in place at stream crossings S-KL43, S-0014, S-0013, S-0012, and S-CD14.
 AR-256 and 258.01 RCEs are maintained in acceptable condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	1/28/2022 10:34 AM	Report #	
Pictures					
 <p><small>Date & Time: Fri, Jan 28, 2022, 06:00:12 EST Position: -037.318683 / -080.443347 (+7114.2ft) Altitude: 2167ft (+659.1ft) Datum: WGS-84 Azimuth/Bearing: 237° S57W 4213mils True (+13°) Elevation Angle: -12.2° Horizon Angle: -07.3° Zoom: 1.0X 11451+00</small></p>		 <p><small>Date & Time: Fri, Jan 28, 2022, 06:00:12 EST Position: -037.318683 / -080.443347 (+7114.2ft) Altitude: 2144ft (+652.2ft) Datum: WGS-84 Azimuth/Bearing: 231° S61W 3229mils True (+13°) Elevation Angle: -11.2° Horizon Angle: -00.4° Zoom: 1.0X 11448+00</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11451+00		Field Station#	11448+00	
Pic 1 Desc.	Sensitive resource buffer in place at streams S-0012 and S-0013.		Pic 2 Desc.	Clean water diversion berm in place.	
 <p><small>Date & Time: Fri, Jan 28, 2022, 08:44:19 EST Position: -037.318683 / -080.443347 (+7114.2ft) Altitude: 2246ft (+684.9ft) Datum: WGS-84 Azimuth/Bearing: 305° N55W 5422mils True (+12°) Elevation Angle: +23.7° Horizon Angle: -01.2° Zoom: 1.0X 11467+00</small></p>		 <p><small>Date & Time: Fri, Jan 28, 2022, 09:38:57 EST Position: -037.308883 / -080.465394 (+15.5ft) Altitude: 2018ft (+615.1ft) Datum: WGS-84 Azimuth/Bearing: 336° N26W 5988mils True (+21°) Elevation Angle: -34.5° Horizon Angle: -01.4° Zoom: 1.0X 11365+00</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11467+00		Field Station#	11365+00	
Pic 3 Desc.	Plunge pool and clean water diversion pipe in place.		Pic 4 Desc.	Slope drain in place over fill slope.	
 <p><small>Date & Time: Fri, Jan 28, 2022, 09:20:16 EST Position: -037.306337 / -080.467057 (+195.3ft) Altitude: 2005ft (+610.5ft) Datum: WGS-84 Azimuth/Bearing: 205° S25W 3644mils True (+16°) Elevation Angle: -13.6° Horizon Angle: -01.5° Zoom: 1.0X 11397+00</small></p>		 <p><small>Date & Time: Fri, Jan 28, 2022, 09:45:36 EST Position: -037.306337 / -080.467057 (+195.3ft) Altitude: 2005ft (+610.5ft) Datum: WGS-84 Azimuth/Bearing: 205° S25W 3644mils True (+16°) Elevation Angle: -13.6° Horizon Angle: -01.5° Zoom: 1.0X 11397+00</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11397+00		Field Station#	11363+60	
Pic 5 Desc.	ROW permanently restored. Waterbar and level spreader in place.		Pic 6 Desc.	RCE in place at Old Furnace Road.	

AFE 124300137	Date/Time 1/28/2022 10:34 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 1/28/2022 10:34 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 33716	
Inspector Eric Hanlon		Date/Time 1/28/2022 7:52 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11524+16	
State VA	Inspection Area Full	Station End 11600+01	
County Giles	Ground Frozen	Temperature (°F) 30.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
Rain Accumulation Time (days)			1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 1/28/2022 7:52 AM	Report # 33716
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to 219.70)
 No Deficiencies noted:
 The ROW from 258.02 to the JNF Forest has been fully restored. Permanent waterbars(other) and level spreaders are installed as per the approved plan and are functioning as designed. No maintenance is needed; Vegetation growth is currently acceptable. The Forest has been temporarily stabilized
 Observed:
 The aged P1 on the JNF from the top of the Mtn down to Craig Creek road has been replaced.
 The restored area is in good shape and the vegetation is sufficient. The environmental controls in the forest are aged, but functional.
 The ECDs at WBs, S-PP 20,21,22 are new and in good shape.
 No construction being performed in the area.
 RCE's functional, highway at Craig Creek station 11600+01, was clean and free of any loose rock.
 LOD ECDs were in place and functional.
 Water bars have been installed to specifications.
 The ROW ground is frozen but in stable condition.
 No sensitive resources have been impacted

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 1/28/2022 7:52 AM		Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11535+00	Field Station#	11528+33		
Pic 1 Desc.	Showing condition of row ECD's in place	Pic 2 Desc.	Permanent level spreader in place		
GPS Location	See photo	GPS Location	See photo		
Field Station#	11526+25	Field Station#	11527+54		
Pic 3 Desc.	Clean water drainage feature in place & permanent stabilization.	Pic 4 Desc.	Permanent water bars & erosion control blanket in place		
GPS Location	See photo	GPS Location	See photo		
Field Station#	11593+00	Field Station#	11593+00		
Pic 5 Desc.	Water bars in place	Pic 6 Desc.	Perimeter P1 in place		

AFE	124300137	Date/Time	1/28/2022 7:52 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location See photo

Field Station# 11588+17

Pic 7 Desc. Buffers in place



GPS Location See photo

Field Station# 11588+17

Pic 8 Desc. Wattles in place



GPS Location See photo

Field Station# 11585+50

Pic 9 Desc. Equipment bridge functional



GPS Location See photo

Field Station# 11585+50

Pic 10 Desc. Buffers in place



GPS Location See photo

Field Station# 11585+00

Pic 11 Desc. ET functional



GPS Location See photo

Field Station# 11600+00

Pic 12 Desc. RCE functional

A/E	124300137	Date/Time	1/28/2022 7:52 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	