



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33771
Inspector	Eric Hanlon			Date/Time	1/31/2022 8:18 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Frozen	Temperature (°F)	27.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	1/31/2022 8:18 AM	Report #	33771
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 28 No compliance issues noted. Observance: Yard 28 has reduced activity during the winter curtailment. Aged Perimeter controls have been replaced & functioning as designed. RCE was clean, no mud or other debris on road. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		1/31/2022 8:18 AM		Report #							
Pictures															
															
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 1 Desc.				AR in good condition				Pic 2 Desc.				CFS perimeter controls functional			
															
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 3 Desc.				Housekeeping in good order no trash or debris in Y28				Pic 4 Desc.				RCE functional			
															
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 5 Desc.				CFS perimeter controls functional				Pic 6 Desc.				Safety fence & CFS in good condition			

A/E	124300137	Date/Time	1/31/2022 8:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	1/31/2022 8:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report





Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33811
Inspector	Rob Robertson			Date/Time	1/31/2022 12:27 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Partial	Station End	11670+00
County	Montgomery	Ground	Frozen	Temperature (°F)	27.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Communication	Repair SSF fabric		
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	1/31/2022 12:27 PM	Report #	33811
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection was completed today on JNF and private lands on Brush Mountain. The ROW was found stable with no sediment movement discovered. ECDs are in place and were checked for maintenance needs. There were three locations where the fabric needs to be re attached to the SSF chainlink. The locations are 11634+50, 11658+50 and 11660+00. The contractor will be notified via punch list. Slope breakers, sumps and end treatments are functional with no issues from runoff discovered. There were no rills or slips located anywhere. Resource crossings are stable with no visible impact occurring in buffers or streams. RCEs are in acceptable condition. There were no housekeeping issues identified. No evidence of vandalism was located.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	1/31/2022 12:27 PM	Report #	
Pictures					
 <p>Date & Time: Mon, Jan 31, 2022, 09:19:09 EST Position: +437.29287° / -080.39594° (+30.0m) Altitude: 853m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 12° S 85E 4373mils Magnetic (+15.1°) Elevation Angle: -28.6° Horizon Angle: -06.9° Zoom: 1.0X 11670+00</p>		 <p>Date & Time: Mon, Jan 31, 2022, 09:31:48 EST Position: +437.30287° / -080.39594° (+30.0m) Altitude: 853m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 246° S 66W 4373mils Magnetic (+13.1°) Elevation Angle: -28.6° Horizon Angle: -06.9° Zoom: 1.0X 11664+00</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11670+00		Field Station#	11664+00	
Pic 1 Desc.	The ROW is stable top of Brush Mountain.		Pic 2 Desc.	ECDs are in place along perimeter of LOD. No sediment migration located.	
 <p>Date & Time: Mon, Jan 31, 2022, 09:43:37 EST Position: +437.30517° / -080.39627° (+30.0m) Altitude: 768m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 133° S 47E 3307mils Magnetic (+12.1°) Elevation Angle: -01.3° Horizon Angle: -01.3° Zoom: 1.0X 11659+00</p>		 <p>Date & Time: Mon, Jan 31, 2022, 09:45:50 EST Position: +437.30873° / -080.39811° (+30.0m) Altitude: 768m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 133° S 47E 3364mils Magnetic (+12.1°) Elevation Angle: -01.3° Horizon Angle: -01.3° Zoom: 1.0X 11657+50</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11659+00		Field Station#	11657+50	
Pic 3 Desc.	Perimeter ECDs were checked for maintenance needs.		Pic 4 Desc.	Perimeter ECDs are in place and functional.	
 <p>Date & Time: Mon, Jan 31, 2022, 09:49:27 EST Position: +437.31144° / -080.39714° (+30.0m) Altitude: 577m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 022° S 86E 1336mils Magnetic (+14.1°) Elevation Angle: -24.0° Horizon Angle: -06.1° Zoom: 1.0X 11636+50</p>		 <p>Date & Time: Mon, Jan 31, 2022, 10:04:23 EST Position: +437.31251° / -080.39735° (+30.0m) Altitude: 577m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 022° S 86E 1336mils Magnetic (+14.1°) Elevation Angle: -24.0° Horizon Angle: -06.1° Zoom: 1.0X 11634+50</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11656+50		Field Station#	11634+50	
Pic 5 Desc.	End treatment functional.		Pic 6 Desc.	Communication for ECD maintenance need identified. One of three locations where fabric to be reattached to chainlink SSF.	

AFE	124300137	Date/Time	1/31/2022 12:27 PM	Report #	
Pictures					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11626+04	Field Station#	11614+20		
Pic 7 Desc.	The S-HH18 crossing is stable.	Pic 8 Desc.	The S-RR14 crossing is stable.		
GPS Location	On photo	GPS Location	On photo		
Field Station#	11613+69	Field Station#	11608+17		
Pic 9 Desc.	Access road MN-258.04 and S-RR13 crossing are in good condition.	Pic 10 Desc.	The S-006 crossing is currently stable.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	1/31/2022 12:27 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33836
Inspector	Daniel Fortune			Date/Time	1/31/2022 4:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+89
State	VA	Inspection Area	Partial	Station End	12005+00
County	Montgomery	Ground	Damp	Temperature (°F)	31.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Added to punch list		
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			




5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	1/31/2022 4:21 PM	Report #	33836
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted. Unknown to EI at this time of inspection.					
Comments (Reference above questions as appropriate.) See photos for GPS coordinates. Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). Deficiencies documented for repairs at the following locations: Station # 11913+00 - P1 silt fencing requires maintenance Station # 11943+88 - P1 silt fencing requires maintenance This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time. Permanent water bars have been installed and appear to be functioning as intended. Precision Crews: No crews on site or activity observed. All other perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed Ar 266.03 and AR 266.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	1/31/2022 4:21 PM	Report #	
Pictures					
<p>Date & Time: Mon Jan 31, 2022 09:06:52 EST Position: +37.237912 / -80.334416 (+20.1ft) Altitude: 2263ft (+29.6ft) Datum: WGS-84 Azimuth/Bearing: 092° N38E 1740mils True (+0.0°) Elevation Grade: +003° Horizon Grade: +003° Zoom: 0.5X 11900+81</p> 		<p>Date & Time: Mon Jan 31, 2022 09:06:52 EST Position: +37.237912 / -80.334416 (+20.1ft) Altitude: 2263ft (+29.6ft) Datum: WGS-84 Azimuth/Bearing: 099° S81E 1740mils True (+0.0°) Elevation Grade: +003° Horizon Grade: +003° Zoom: 0.5X 11900+81</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11900+81	Field Station#	11900+81		
Pic 1 Desc.	AR 266.03	Pic 2 Desc.	AR 266.03 and vegetated row conditions.		
<p>Date & Time: Mon Jan 31, 2022 09:10:45 EST Position: +37.2873627 / -80.336931 (+16.6ft) Altitude: 2364ft (+66.2ft) Datum: WGS-84 Azimuth/Bearing: 062° N38E 1102mils True (+1.6°) Elevation Grade: +000° Horizon Grade: +000° Zoom: 0.5X 11704+40</p> 		<p>Date & Time: Mon Jan 31, 2022 09:10:45 EST Position: +37.2872997 / -80.336938 (+15.6ft) Altitude: 2322ft (+11.1ft) Datum: WGS-84 Azimuth/Bearing: 102° S48E 3260mils True (+1.7°) Elevation Grade: +053° Horizon Grade: +003° Zoom: 0.5X 11904+40</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11904+40	Field Station#	11904+40		
Pic 3 Desc.	Permanent rock level spreader	Pic 4 Desc.	Perimeter P1 silt fencing.		
<p>Date & Time: Mon Jan 31, 2022 09:10:32 EST Position: +37.237294 / -80.333180 (+15.5ft) Altitude: 2315ft (+10.1ft) Datum: WGS-84 Azimuth/Bearing: 063° N38E 1120mils True (+1.5°) Elevation Grade: +005° Horizon Grade: +000° Zoom: 0.5X 11904+40</p> 		<p>Date & Time: Mon Jan 31, 2022 09:10:38 EST Position: +37.2359707 / -80.336937 (+11.1ft) Altitude: 2301ft (+9.7ft) Datum: WGS-84 Azimuth/Bearing: 286° N30W 5000mils True (+0.0°) Elevation Grade: +018° Horizon Grade: +000° Zoom: 1.0X 11911+21</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11904+40	Field Station#	11911+21		
Pic 5 Desc.	Vegetated row conditions. Final Restoration Area.	Pic 6 Desc.	Permanent vegetated water bar into permanent rock level spreader.		

AFE 124300137		Date/Time	1/31/2022 4:21 PM	Report #	
Pictures					
<p> <small> Date & Time: Mon, Jan 31, 2022 10:53:55 Position: +38°28393" / -98°03310" (±11.30) Altitude: 1537M (±15.10) Datum: WGS-84 Geoid Heighting: 100° NAD 83 Geoid: 100M Horizontal Grade: 0.00 Zoom: 0.5X Near: 11913+00 </small> </p> 		<p> <small> Date & Time: Mon, Jan 31, 2022 10:54:00 Position: +38°28393" / -98°03310" (±11.30) Altitude: 1537M (±15.10) Datum: WGS-84 Geoid Heighting: 100° NAD 83 Geoid: 100M Horizontal Grade: 0.00 Zoom: 0.5X Near: 11942+00 </small> </p> 			
GPS Location		See Photo		GPS Location	
Field Station#		11913+00		Field Station#	
Pic 7 Desc.		View of P1 silt fence requiring maintenance.		Pic 8 Desc.	
				Final Restoration Area. View of permanent grasses and perimeter CFS.	
<p> <small> Date & Time: Mon, Jan 31, 2022 10:53:55 Position: +38°28393" / -98°03310" (±11.30) Altitude: 1537M (±15.10) Datum: WGS-84 Geoid Heighting: 100° NAD 83 Geoid: 100M Horizontal Grade: 0.00 Zoom: 0.5X Near: 11943+00 </small> </p> 		<p> <small> Date & Time: Mon, Jan 31, 2022 10:54:00 Position: +38°28393" / -98°03310" (±11.30) Altitude: 1537M (±15.10) Datum: WGS-84 Geoid Heighting: 100° NAD 83 Geoid: 100M Horizontal Grade: 0.00 Zoom: 0.5X Near: 11943+88 </small> </p> 			
GPS Location		See Photo		GPS Location	
Field Station#		11943+00		Field Station#	
Pic 9 Desc.		Perimeter super silt fence and snow covered CFS protecting sensitive resource area.		Pic 10 Desc.	
				P1 silt fence requiring maintenance.	
<p> <small> Date & Time: Mon, Jan 31, 2022 10:54:00 Position: +38°28393" / -98°03310" (±11.30) Altitude: 1537M (±15.10) Datum: WGS-84 Geoid Heighting: 100° NAD 83 Geoid: 100M Horizontal Grade: 0.00 Zoom: 0.5X Near: 11946+50 </small> </p> 		<p> <small> Date & Time: Mon, Jan 31, 2022 10:54:00 Position: +38°28393" / -98°03310" (±11.30) Altitude: 1537M (±15.10) Datum: WGS-84 Geoid Heighting: 100° NAD 83 Geoid: 100M Horizontal Grade: 0.00 Zoom: 0.5X Near: 11978+86 </small> </p> 			
GPS Location		See Photo		GPS Location	
Field Station#		11946+50		Field Station#	
Pic 11 Desc.		Water bar conditions after snow melt		Pic 12 Desc.	
				Protected sensitive resource areas in Final Restoration Area	

AFE	124300137	Date/Time	1/31/2022 4:21 PM	Report #	
Pictures					
 <p><small>Date & Time Mon, Jan 31, 2022 10:09:18 EST Position: +38° 53'44.4" N / -88° 52'33.4" W (+16.00) Altitude: 18970 (+16.00) Datum: WGS-84 Azimuth/Bearing: 100° 18'27" W (000°/0° True (+16°)) Horizontal Grade: +000% Vertical Grade: +000% Zoom: 2.0X Near: 11978+86</small></p>		 <p><small>Date & Time Mon, Jan 31, 2022 10:09:18 EST Position: +38° 53'55.1" N / -88° 52'33.4" W (+16.00) Altitude: 18970 (+16.00) Datum: WGS-84 Azimuth/Bearing: 101° 19'57" W (000°/0° True (+16°)) Horizontal Grade: +000% Vertical Grade: +000% Zoom: 2.0X Near: 11990+00</small></p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11978+86	Field Station#	11990+00		
Pic 13 Desc.	Final Restoration Area. Existing perimeter controls and P1 fencing remain.	Pic 14 Desc.	View of row conditions after the snow melt. Final Restoration Area		
 <p><small>Date & Time Mon, Jan 31, 2022 10:09:18 EST Position: +38° 53'44.4" N / -88° 52'33.4" W (+16.00) Altitude: 18970 (+16.00) Datum: WGS-84 Azimuth/Bearing: 100° 18'27" W (000°/0° True (+16°)) Horizontal Grade: +000% Vertical Grade: +000% Zoom: 2.0X Near: 12005+00</small></p>		<p style="text-align: center;">Insert image here</p>			
GPS Location	See Photo	GPS Location			
Field Station#	12005+00	Field Station#			
Pic 15 Desc.	View of un-restored row. Temporary stabilized with no issues at this time.	Pic 16 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33809
Inspector	Clint Sears			Date/Time	1/31/2022 12:05 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Frozen	Temperature (°F)	39.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	1/31/2022 12:05 PM	Report #	33809
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection of LDY-29 They were no deficiencies found at this time. There are no crews currently working at this location. AR-238.00 - Access road and RCE are maintained in acceptable condition. Triple stack CFS perimeter controls and overhead utility flagging are in place. Waste management and housekeeping are acceptable. Culvert is in place and functional. Equipment has been inspected and no visible leaks or spills at this time Yard mainly used for 798 welders to store materials and equipment as well as park vehicles.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 1/31/2022 12:05 PM	Report #
Pictures			
			
GPS Location	See photo	GPS Location	See photo
Field Station#	12005+00	Field Station#	12005+00
Pic 1 Desc.	Culvert in place	Pic 2 Desc.	Equipment with no visible leaks or spills
			
GPS Location	See photo	GPS Location	See photo
Field Station#	12005+00	Field Station#	12005+00
Pic 3 Desc.	RCE is maintained in acceptable condition	Pic 4 Desc.	Secondary containment in place
			
GPS Location	See photo	GPS Location	See photo
Field Station#	12005+00	Field Station#	12005+00
Pic 5 Desc.	CFS perimeter controls are in acceptable condition	Pic 6 Desc.	Dumpsters are in place

A/E	124300137	Date/Time	1/31/2022 12:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	1/31/2022 12:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33815
Inspector	Chris Burns			Date/Time	1/31/2022 1:01 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+89
County	Montgomery	Ground	Frozen	Temperature (°F)	42.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	1/31/2022 1:01 PM	Report #	33815
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection, from MP 223.27 (11788+52) and MP 225.37 (11899+89). Fellow EI Clint Sears accompanied during SWPPP inspection. This section of RoW has no current construction. Temporary controls within this area are partially removed, remaining temporary controls to be removed once ground/weather conditions improve. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Unauthorized vehicle travel within the permanent restoration area, between 11792+00 and 11831+75, on 1/18/2022 resulted in minor disturbance/vegetation damage between 11824+00 and 118 31+75. Further assessment of this area to take place once snow melt occurs allowing the observation of the impact. (Update) Snow cover still present, monitoring to continue. Assessed AR 266.03. Section 6- Waterbars (other).					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	1/31/2022 1:01 PM	Report #	
Pictures					
<p>Date & Time: Mon, Jan 31, 2022, 05:42:24 EST Position: 1456557.588 E / 352552.525 N (-118.81) Altitude: 21491 (-118.81) Datum: WGS-84 Azimuth/Bearing: 352° 283W 424mils True (-12°) Elevation Angle: +00.2° Machon Angle: +00.2° Zoom: 0.5X 11833+00</p> 		<p>Date & Time: Mon, Jan 31, 2022, 05:43:09 EST Position: 1456561.907 E / 352552.080 N (-118.81) Altitude: 21491 (-118.81) Datum: WGS-84 Azimuth/Bearing: 352° 335W 424mils True (-12°) Elevation Angle: +00.3° Machon Angle: +01.1° Zoom: 0.5X 11833+00</p> 			
GPS Location	1	GPS Location	2		
Field Station#	11899+00	Field Station#	11876+00		
Pic 1 Desc.	Section of restored RoW showing conditions and controls.	Pic 2 Desc.	Section of restored RoW showing conditions and controls.		
<p>Date & Time: Mon, Jan 31, 2022, 05:43:09 EST Position: 1456561.907 E / 352552.080 N (-118.81) Altitude: 21491 (-118.81) Datum: WGS-84 Azimuth/Bearing: 352° 335W 424mils True (-12°) Elevation Angle: +00.3° Machon Angle: +01.1° Zoom: 0.5X 11833+00</p> 		<p>Date & Time: Mon, Jan 31, 2022, 05:43:16 EST Position: 1456561.907 E / 352552.080 N (-118.81) Altitude: 21491 (-118.81) Datum: WGS-84 Azimuth/Bearing: 352° 335W 424mils True (-12°) Elevation Angle: +00.3° Machon Angle: +01.1° Zoom: 0.5X 11833+00</p> 			
GPS Location	3	GPS Location	4		
Field Station#	11863+65	Field Station#	11856+00		
Pic 3 Desc.	P-KL2 and controls.	Pic 4 Desc.	Section of restored RoW showing conditions and controls.		
<p>Date & Time: Mon, Jan 31, 2022, 05:43:33 EST Position: 1456561.907 E / 352552.080 N (-118.81) Altitude: 21491 (-118.81) Datum: WGS-84 Azimuth/Bearing: 352° 335W 424mils True (-12°) Elevation Angle: +00.3° Machon Angle: +01.1° Zoom: 0.5X 11833+00</p> 		<p>Date & Time: Mon, Jan 31, 2022, 05:43:16 EST Position: 1456561.907 E / 352552.080 N (-118.81) Altitude: 21491 (-118.81) Datum: WGS-84 Azimuth/Bearing: 352° 335W 424mils True (-12°) Elevation Angle: +00.3° Machon Angle: +01.1° Zoom: 0.5X 11833+00</p> 			
GPS Location	5	GPS Location	6		
Field Station#	11840+00	Field Station#	11833+50		
Pic 5 Desc.	Representational photo of permanent waterbar and level spreader.	Pic 6 Desc.	Section of restored RoW showing conditions and controls.		

AFE	124300137	Date/Time	1/31/2022 1:01 PM	Report #	
Pictures					
<small>Date & Time: Mon, Jan 31, 2022, 10:09:12 EST Position: 165011.6752 E, 355591.6780 N (44.850) Altitude: 212.11 (m) (695 ft) Datum: WGS 84 Azimuth Bearing: 067° NAVE 1227mils True (at 0°) Elevation Angle: 0.1° Horizon Angle: 400.8° Zoom: 9.33 11805+00</small> 		<small>Date & Time: Mon, Jan 31, 2022, 10:09:27 EST Position: 1658815.027 E, 355793.297 N (44.80) Altitude: 212.11 (m) (695 ft) Datum: WGS 84 Azimuth Bearing: 135° S20E 2655mils True (at 0°) Elevation Angle: 0.3° Horizon Angle: 102.1° Zoom: 9.33 11792+00</small> 			
GPS Location	7	GPS Location	8		
Field Station#	11805+00	Field Station#	11792+00		
Pic 7 Desc.	Section of restored RoW showing conditions and controls.		Pic 8 Desc.	Section of restored RoW showing conditions and controls.	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	1/31/2022 1:01 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33812
Inspector	Eric Hanlon			Date/Time	1/31/2022 12:40 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Frozen	Temperature (°F)	30.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	1/31/2022 12:40 PM	Report #	33812
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 26. No compliance issues noted. Observance: Yard 26 has reduced activity during the winter curtailment. Perimeter controls in place & functioning as designed. RCE was clean, no mud or other debris on road. Secondary containment in place & functional as designed. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	1/31/2022 12:40 PM	Report #	
Pictures					
 <p>Date & Time: Mon, Jan 31, 2022, 09:22:45 EST Position: +037.319427° / -080.658174° (±15.1m) Altitude: 1803ft (±3.7m) Datum: WGS-84 Azimuth/Bearing: 270° N90W 4800mils True (±12°) Elevation Angle: -22.9° Horizon Angle: +05.6° Zoom: 1.0X Y26</p>			 <p>Date & Time: Mon, Jan 31, 2022, 09:22:45 EST Position: +037.319427° / -080.658174° (±15.1m) Altitude: 1803ft (±3.7m) Datum: WGS-84 Azimuth/Bearing: 270° N90W 4800mils True (±12°) Elevation Angle: -22.9° Horizon Angle: +05.6° Zoom: 1.0X Y26</p>		
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Safety fence & CFS in good condition		Pic 2 Desc.	CFS inlet protection in place	
 <p>Date & Time: Mon, Jan 31, 2022, 09:21:58 EST Position: +037.318565° / -080.657617° (±21.7m) Altitude: 1787ft (±3.7m) Datum: WGS-84 Azimuth/Bearing: 252° S72W 4430mils True (±14°) Elevation Angle: -00.3° Horizon Angle: +05.7° Zoom: 1.0X Y26</p>			 <p>Position: +037.318565° / -080.657617° (±21.7m) Altitude: 1787ft (±3.7m) Datum: WGS-84 Azimuth/Bearing: 252° S72W 4430mils True (±14°) Elevation Angle: -00.3° Horizon Angle: +05.7° Zoom: 1.0X Y26</p>		
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Secondary containment in place		Pic 4 Desc.	Housekeeping in good condition	
 <p>Date & Time: Mon, Jan 31, 2022, 09:19:02 EST Position: +037.318565° / -080.657617° (±21.7m) Altitude: 1787ft (±3.7m) Datum: WGS-84 Azimuth/Bearing: 252° S72W 4430mils True (±14°) Elevation Angle: -00.3° Horizon Angle: +05.7° Zoom: 1.0X Y26</p>			 <p>Date & Time: Mon, Jan 31, 2022, 09:19:02 EST Position: +037.318565° / -080.657617° (±21.7m) Altitude: 1787ft (±3.7m) Datum: WGS-84 Azimuth/Bearing: 252° S72W 4430mils True (±14°) Elevation Angle: -00.3° Horizon Angle: +05.7° Zoom: 1.0X Y26</p>		
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Secondary containment in place		Pic 6 Desc.	RCE functional	

A/E	124300137	Date/Time	1/31/2022 12:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	1/31/2022 12:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33835
Inspector	Patrick Shields			Date/Time	1/31/2022 4:08 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Full	Station End	11788+52
County	Montgomery	Ground	Frozen	Temperature (°F)	35.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	1/31/2022 4:08 PM	Report #	33835
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 (Brush Mt) to ST# 11788+52 (Mt Tabor) MP 221.02 to MP 223.27 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection are in place where needed. Perimeter controls and waterbars with end treatments are in place. Sensitive resource buffers are in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCEs are maintained in acceptable condition. The ROW is frozen/snow covered and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	1/31/2022 4:08 PM	Report #	
Pictures					
 <p>Date & Time: Mon, Jan 31, 2022, 10:43:55 EST Position: +437.301674° / -900.393270° (±12.40) Altitude: 2400ft (±19.30) Datum: WGS-84 Azimuth Bearing: 140° S200° 3544mils True (±12°) Elevation Grade: -002° Horizon Grade: +003° Zoom: 1.0X 11677+50</p>		 <p>Date & Time: Mon, Jan 31, 2022, 10:48:41 EST Position: +437.301674° / -900.393270° (±12.40) Altitude: 2400ft (±19.30) Datum: WGS-84 Azimuth Bearing: 140° S200° 3544mils True (±12°) Elevation Grade: -002° Horizon Grade: +003° Zoom: 1.0X 11682+50</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11677+50	Field Station#	11682+50		
Pic 1 Desc.	End treatments in place	Pic 2 Desc.	Slope drain in place		
 <p>Date & Time: Mon, Jan 31, 2022, 10:47:55 EST Position: +437.301674° / -900.393270° (±12.40) Altitude: 2400ft (±19.30) Datum: WGS-84 Azimuth Bearing: 140° S200° 3544mils True (±12°) Elevation Grade: -002° Horizon Grade: +003° Zoom: 1.0X 11688+00</p>		 <p>Date & Time: Mon, Jan 31, 2022, 11:04:31 EST Position: +437.301674° / -900.393270° (±12.40) Altitude: 2400ft (±19.30) Datum: WGS-84 Azimuth Bearing: 140° S200° 3544mils True (±12°) Elevation Grade: -002° Horizon Grade: +003° Zoom: 1.0X 11715+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11688+00	Field Station#	11715+00		
Pic 3 Desc.	Erosion control blanket in place	Pic 4 Desc.	Waterbars in place		
 <p>Date & Time: Mon, Jan 31, 2022, 11:04:31 EST Position: +437.301674° / -900.393270° (±12.40) Altitude: 2400ft (±19.30) Datum: WGS-84 Azimuth Bearing: 140° S200° 3544mils True (±12°) Elevation Grade: -002° Horizon Grade: +003° Zoom: 1.0X 11720+00</p>		 <p>Date & Time: Mon, Jan 31, 2022, 11:01:23 EST Position: +437.301674° / -900.393270° (±12.40) Altitude: 2400ft (±19.30) Datum: WGS-84 Azimuth Bearing: 140° S200° 3544mils True (±12°) Elevation Grade: -002° Horizon Grade: +003° Zoom: 1.0X 11741+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11720+00	Field Station#	11741+00		
Pic 5 Desc.	CFS triple stack perimeter control in place	Pic 6 Desc.	Stream buffer in place		

AFE 124300137		Date/Time	1/31/2022 4:08 PM	Report #	
Pictures					
<p>Date & Time: Mon, Jan 31, 2022, 11:43:44 EST Position: +037.296912° / -080.370359° (±15.4M) Altitude: 2205ft (±19.7M) Datum: WGS-84 Azimuth/Bearing: 190° S90E 190mils True (±12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11750+00</p> 		<p>Date & Time: Mon, Jan 31, 2022, 11:57:43 EST Position: +037.296920° / -080.370284° (±14.7M) Altitude: 2205ft (±19.7M) Datum: WGS-84 Azimuth/Bearing: 190° S90E 190mils True (±12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11750+00</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11750+00		Field Station#	
Pic 7 Desc.		End treatments in place		Pic 8 Desc.	
				Supersilt fence perimeter control in place	
<p>Date & Time: Mon, Jan 31, 2022, 11:43:22 EST Position: +037.296977° / -080.368997° (±13.3M) Altitude: 1997ft (±16.7M) Datum: WGS-84 Azimuth/Bearing: 094° S86E 167mils True (±12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 1.0X 11766+00</p> 		<p>Date & Time: Mon, Jan 31, 2022, 10:09:21 EST Position: +037.296977° / -080.364043° (±76.5M) Altitude: 2040ft (±52.5M) Datum: WGS-84 Azimuth/Bearing: 232° S52W 412mils True (±12°) Elevation Grade: +02% Horizon Grade: +012% Zoom: 1.0X 11775+00</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11766+00		Field Station#	
Pic 9 Desc.		RCE in place		Pic 10 Desc.	
				Supersilt fence perimeter control in place	
<p>Date & Time: Mon, Jan 31, 2022, 11:08:42 EST Position: +037.296361° / -080.361997° (±25.7M) Altitude: 2015ft (±15.7M) Datum: WGS-84 Azimuth/Bearing: 230° S50W 408mils True (±12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 1.0X 11778+00</p> 		<p>Date & Time: Mon, Jan 31, 2022, 10:48:42 EST Position: +037.294911° / -080.362195° (±15.4M) Altitude: 2120ft (±16.9M) Datum: WGS-84 Azimuth/Bearing: 250° N40W 467mils True (±12°) Elevation Grade: +07% Horizon Grade: +001% Zoom: 1.0X 11782+50</p> 			
GPS Location		See photo		GPS Location	
Field Station#		11778+00		Field Station#	
Pic 11 Desc.		P1 silt fence perimeter control in place		Pic 12 Desc.	
				Cleanwater drainage feature in place	

A/E	124300137	Date/Time	1/31/2022 4:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33883
Inspector	Joe Sweeden			Date/Time	2/1/2022 11:38 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10859+46
State	VA	Inspection Area	Partial	Station End	10929+80
County	Giles	Ground	Frozen	Temperature (°F)	21.00
Municipality	N/A	Weather	Below Freezing Temp	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	P 1 needs maintenance		
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Cleanwater Diversion Pipe	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	2/1/2022 11:38 AM	Report #	33883
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed Virginia SWPP inspection from station # 10859+46-10929+80.(MP 205.67-207.00) Kow Camp gravel to Doe Creek, with El Daniel Fortune. Deficiencies found today: P 1 needs maintenance, Station # 10882+26. Observances: Freezing temperatures ROW conditions are frozen with small areas of snow remaining on the ROW. Water bodies were flowing water. There is an area of ditch subsidence, where there are cracks in the water bars from station # 10896+00-10899+00. The area is being monitored and will need repaired, when conditions allow. Mike Perry, with Precision, has been notified of needed repairs. He is dispatching an Environmental Foreman to the area to assess the repairs needed. Environmental controls at water bodies are in place and functioning as designed. The ROW has been temporarily stabilized. Soil piles are stabilized. No trash on the ROW. No sensitive resources were impacted. All perimeter controls, ECDs and BMPs were functional at time of inspection. An Environmental crew was performing maintenance on EC's along ROW. Rock Road approaches are clean and free of loose rock.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		2/1/2022 11:38 AM		Report #			
Pictures											
											
GPS Location		See photo				GPS Location		see photo			
Field Station#		10882+26				Field Station#		10899+00			
Pic 1 Desc.		P 1 needs maintenance PL				Pic 2 Desc.		Ditch subsidence, with cracks in water bars.			
											
GPS Location		see photo				GPS Location		see photo			
Field Station#		10862+00				Field Station#		10872+00			
Pic 3 Desc.		Water bars, open ditch, Kow camp				Pic 4 Desc.		Stabilized ROW, clean water diversion pipe			
											
GPS Location		see photo				GPS Location		see photo			
Field Station#		10880+00				Field Station#		10883+10			
Pic 5 Desc.		Stabilized ROW, water bars, sumps				Pic 6 Desc.		S-A 32			

AFE	124300137	Date/Time	2/1/2022 11:38 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	see photo		
Field Station#	10884+00	Field Station#	10903+00		
Pic 7 Desc.	Kow camp RCE	Pic 8 Desc.	Stabilized ROW and soil piles		
					
GPS Location	see photo	GPS Location	see photo		
Field Station#	10925+00	Field Station#	10927+50		
Pic 9 Desc.	Perimeter ECDs, water bars	Pic 10 Desc.	S-Y 3		
		<p>Insert image here</p>			
GPS Location	see photo	GPS Location			
Field Station#	10929+00	Field Station#			
Pic 11 Desc.	S-Y 2, Doe Creek RCE	Pic 12 Desc.			

A/E	124300137	Date/Time	2/1/2022 11:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33892
Inspector	Clint Sears			Date/Time	2/1/2022 2:26 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10749+92
State	VA	Inspection Area	Partial	Station End	10798+92
County	Giles	Ground	Frozen	Temperature (°F)	41.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/1/2022 2:26 PM	Report #	33892
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from Sta#10749+92 to Sta#10798+92 (MP 203.6 to MP 204.53) Fellow EI Chris Burns accompanied during SWPPP inspection. No deficiencies were found at time of inspection. This section of Row has undergone temporary vegetation and stabilization. All other perimeter controls, ECD'S and BMPs were functional at time of inspection. There are no crews actively working on this section of Row. Row is in stable condition. No sensitive resource have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/1/2022 2:26 PM	Report #	
Pictures					
					
GPS Location	see photo	GPS Location	See photo		
Field Station#	10751+00	Field Station#	10758+32		
Pic 1 Desc.	Section of Row showing conditions and controls	Pic 2 Desc.	S-G35		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10765+95	Field Station#	10771+75		
Pic 3 Desc.	S-SS4 showing conditions and controls	Pic 4 Desc.	Clean water diversion pipe and level spreader		
					
GPS Location	see photo	GPS Location	See photo		
Field Station#	10773+73	Field Station#	10780+40		
Pic 5 Desc.	S-Z9	Pic 6 Desc.	S-Z7		

A/E	124300137	Date/Time	2/1/2022 2:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	2/1/2022 2:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33893
Inspector	Patrick Shields			Date/Time	2/1/2022 2:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10798+92
State	VA	Inspection Area	Full	Station End	10859+46
County	Giles	Ground	Frozen	Temperature (°F)	38.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Slope Drain Pipe	Acceptable			
Sensitive Resource Signage	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/1/2022 2:41 PM	Report #	33893
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10798+92 (Cascade) to ST# 10859+46 (Kow Camp Gravel) MP 204.53 to MP 205.67 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. Perimeter controls and end treatments are in place. This section of ROW has undergone temporary stabilization. Topsoil piles and cleanwater diversion berms have been stabilized. Sensitive resource buffers are in place at stream crossings S-A33, S-A34, and S-Z14. AR-241.02, 241.03, and Cascade Drive road crossing RCEs are maintained in acceptable condition. The ROW is frozen and in stable condition. No sensitive resources have been impacted,					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/1/2022 2:41 PM	Report #	
Pictures					
 <p>Date & Time: Tue, Feb 01, 2022, 10:44:09 EST Position: +037 341727° / +000 019697° (+24.80) Altitude: 1954ft (+24.80) Datum: WGS-84 Azimuth/Bearing: 000° N00E 010mils True (+0.0°) Elevation Grade: -011% Horizon Grade: -080% Zoom: 1.0X 10803+00</p>		 <p>Date & Time: Tue, Feb 01, 2022, 10:44:09 EST Position: +037 341727° / +000 019697° (+24.80) Altitude: 1954ft (+24.80) Datum: WGS-84 Azimuth/Bearing: 000° N00E 010mils True (+0.0°) Elevation Grade: -011% Horizon Grade: -080% Zoom: 1.0X 10805+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10803+00	Field Station#	10805+00		
Pic 1 Desc.	RCE in place	Pic 2 Desc.	P1 silt fence in place at sensitive resource buffer		
 <p>Date & Time: Tue, Feb 01, 2022, 15:05:10 EST Position: +037 340362° / +000 018501° (+18.30) Altitude: 2298ft (+18.30) Datum: WGS-84 Azimuth/Bearing: 267° S87W 474mils True (+1.1°) Elevation Grade: -023% Horizon Grade: -082% Zoom: 1.0X 10812+00</p>		 <p>Date & Time: Tue, Feb 01, 2022, 16:05:14 EST Position: +037 340362° / +000 018501° (+18.30) Altitude: 2298ft (+18.30) Datum: WGS-84 Azimuth/Bearing: 267° S87W 474mils True (+1.1°) Elevation Grade: -023% Horizon Grade: -082% Zoom: 1.0X 10815+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10812+50	Field Station#	10815+00		
Pic 3 Desc.	Cleanwater diversion outlet protection in place	Pic 4 Desc.	Erosion control blanket in place		
 <p>Date & Time: Tue, Feb 01, 2022, 16:24:30 EST Position: +037 340411° / +000 011927° (+21.80) Altitude: 2494ft (+21.80) Datum: WGS-84 Azimuth/Bearing: 065° N06E 115mils True (+0.2°) Elevation Grade: -007% Horizon Grade: -092% Zoom: 1.0X 10820+00</p>		 <p>Date & Time: Tue, Feb 01, 2022, 09:47:20 EST Position: +037 340411° / +000 011927° (+21.80) Altitude: 2494ft (+21.80) Datum: WGS-84 Azimuth/Bearing: 065° N06E 115mils True (+0.2°) Elevation Grade: -007% Horizon Grade: -092% Zoom: 1.0X 10833+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10820+00	Field Station#	10833+00		
Pic 5 Desc.	CFS perimeter control in place	Pic 6 Desc.	Waterbars in place		

AFE	124300137	Date/Time	2/1/2022 2:41 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10831+50	Field Station#	10837+25		
Pic 7 Desc.	Triple protection ECDs in place at karst feature	Pic 8 Desc.	Slope drain in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10840+00	Field Station#	10843+75		
Pic 9 Desc.	Waterbars in place	Pic 10 Desc.	Cleanwater diversion berm in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10855+00	Field Station#	10859+00		
Pic 11 Desc.	Stream buffer in place	Pic 12 Desc.	Supersilt fence perimeter control in place		

A/E	124300137	Date/Time	2/1/2022 2:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33865
Inspector	David Schoolcraft			Date/Time	2/1/2022 10:07 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10655+00
State	VA	Inspection Area	Full	Station End	10749+92
County	Giles	Ground	Damp	Temperature (°F)	40.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/1/2022 10:07 AM	Report #	33865
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental team Preformed VA SWPPP inspection from 10655+00 (MP 201.6) to 10749+92 (MP 203.6) Assisted by fellow EI Eric Hanlon This section of ROW has no current construction. No deficiencies found. Maintenance crews were in the area. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/1/2022 10:07 AM	Report #	
Pictures					
 <p>Date & Time: Tue, Feb 01, 2022, 08:47:49 EST Position: -037.344997° / -080.636391° (±16.8ft) Altitude: 2333ft (±11.1ft) Datum: WGS-84 Azimuth/Bearing: 000° 000E 1564mils True (±12°) Elevation Angle: -04.3° Horizon Angle: -03.9° Zoom: 1.0X 10748+25</p>		 <p>Date & Time: Tue, Feb 01, 2022, 08:48:34 EST Position: -037.344997° / -080.636391° (±16.8ft) Altitude: 2333ft (±11.1ft) Datum: WGS-84 Azimuth/Bearing: 293° N47W 5209mils True (±13°) Elevation Angle: -07.8° Horizon Angle: -02.6° Zoom: 1.0X 10745+67</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10748+25	Field Station#	10745+67		
Pic 1 Desc.	RCE	Pic 2 Desc.	Outlet		
 <p>Date & Time: Tue, Feb 01, 2022, 08:52:35 EST Position: -037.345816° / -080.638563° (±15.5ft) Altitude: 2333ft (±11.1ft) Datum: WGS-84 Azimuth/Bearing: 053° N53E 0942mils True (±12°) Elevation Angle: -04.4° Horizon Angle: -05.5° Zoom: 0.5X 10742+69</p>		 <p>Date & Time: Tue, Feb 01, 2022, 08:56:54 EST Position: -037.350235° / -080.657004° (±15.1ft) Altitude: 2133ft (±11.7ft) Datum: WGS-84 Azimuth/Bearing: 877° N72E 1369mils True (±12°) Elevation Angle: -00.8° Horizon Angle: -03.6° Zoom: 1.0X 10683+00</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10742+69	Field Station#	10683+00		
Pic 3 Desc.	Equipment	Pic 4 Desc.	Clean water diversion pipe		
 <p>Date & Time: Tue, Feb 01, 2022, 09:05:38 EST Position: -037.349117° / -080.652018° (±15.4ft) Altitude: 2074ft (±11.1ft) Datum: WGS-84 Azimuth/Bearing: 101° S79E 1796mils True (±12°) Elevation Angle: -15° Horizon Angle: -08.6° Zoom: 1.0X 10699+00</p>		 <p>Date & Time: Tue, Feb 01, 2022, 09:07:08 EST Position: -037.350189° / -080.657002° (±15.1ft) Altitude: 2133ft (±11.7ft) Datum: WGS-84 Azimuth/Bearing: 175° S05E 3111mils True (±12°) Elevation Angle: -23.2° Horizon Angle: -01.9° Zoom: 1.0X 10683+00</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10699+00	Field Station#	10683+00		
Pic 5 Desc.	Stream super silt	Pic 6 Desc.	Outlet		

AFE	124300137	Date/Time	2/1/2022 10:07 AM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10687+00	Field Station#	10710+00		
Pic 7 Desc.	Crews working on stabilization	Pic 8 Desc.	Perimeter controls		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	2/1/2022 10:07 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33885
Inspector	Bradley Ingram			Date/Time	2/1/2022 12:56 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10799+00
State	VA	Inspection Area	Full	Station End	10859+50
County	Giles	Ground	Frozen	Temperature (°F)	25.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/1/2022 12:56 PM	Report #	33885
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Assisted Patrick Shields VA SWPPP inspection from ST# 10798+92 (Cascade) to ST# 10859+46 (Kow Camp Gravel) MP 204.53 to MP 205.67 No deficiencies were located during inspection. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crew hauling in equipment and staging up straws bales for future stabilization at AR-241.02. Perimeter controls and end treatments are in place. This section of ROW has undergone temporary stabilization. Topsoil piles and clean water diversion berms have been stabilized. Sensitive resource buffers are in place at stream crossings S-A33, S-A34, and S-Z14. AR-241.02, 241.03, and Cascade Drive road crossing RCEs are maintained in acceptable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/1/2022 12:56 PM	Report #	
Pictures					
<p>Date & Time: Tue, Feb 01, 2022, 10:45:02 EST Position: +037.341889 / -080.619481 (+22.8ft) Altitude: 1920ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 313 N47W 556mils True (+12.1) Elevation Angle: -14.7 Horizon Angle: -01.1 Zoom: 0.5X 10803+00 MVP: Spread G</p> 		<p>Date & Time: Tue, Feb 01, 2022, 10:32:30 EST Position: +037.341889 / -080.619481 (+22.8ft) Altitude: 2050ft (+20.8ft) Datum: WGS-84 Azimuth/Bearing: 022 N08E 124mils True (+1.3) Elevation Angle: -14.7 Horizon Angle: -00.8 Zoom: 0.5X 10818+00 MVP: Spread G</p> 			
GPS Location	In photo	GPS Location	In photo		
Field Station#	10803+00	Field Station#	10818+00		
Pic 1 Desc.	Rce	Pic 2 Desc.	Super silt fence		
<p>Date & Time: Tue, Feb 01, 2022, 10:09:48 EST Position: +037.337637 / -080.606002 (+14.8ft) Altitude: 2207ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 081 S08E 172mils True (+18.1) Elevation Angle: -11.4 Horizon Angle: -00.4 Zoom: 0.5X 10855+00 MVP: Spread G</p> 		<p>Date & Time: Tue, Feb 01, 2022, 10:04:11 EST Position: +037.338839 / -080.607627 (+21.1ft) Altitude: 2414ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 009 N00E 162mils True (+1.3) Elevation Angle: -04.2 Horizon Angle: -04.7 Zoom: 0.5X 10848+00 MVP: Spread G</p> 			
GPS Location	In photo	GPS Location	In photo		
Field Station#	10855+00	Field Station#	10848+00		
Pic 3 Desc.	Equipment bridge	Pic 4 Desc.	CFS		
<p>Date & Time: Tue, Feb 01, 2022, 09:57:07 EST Position: +037.340370 / -080.609684 (+241.4ft) Altitude: 2680ft (+28.9ft) Datum: WGS-84 Azimuth/Bearing: 195 S15W 3467mils True (+14.1) Elevation Angle: -43.8 Horizon Angle: +03.5 Zoom: 0.5X 10839+00 MVP: Spread G</p> 		<p>Date & Time: Tue, Feb 01, 2022, 09:47:56 EST Position: +037.340701 / -080.611634 (+15.1ft) Altitude: 2573ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 077 N77E 1369mils True (+14.1) Elevation Angle: -09.9 Horizon Angle: -01.3 Zoom: 0.5X 10830+00 MVP: Spread G</p> 			
GPS Location	In photo	GPS Location	In photo		
Field Station#	10839+00	Field Station#	10830+00		
Pic 5 Desc.	Slope drain	Pic 6 Desc.	Row stabilized		

A/E	124300137	Date/Time	2/1/2022 12:56 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	2/1/2022 12:56 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33933
Inspector	David Schoolcraft			Date/Time	2/2/2022 11:49 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11184+85
State	VA	Inspection Area	Full	Station End	11254+99
County	Giles	Ground	Damp	Temperature (°F)	41.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/2/2022 11:49 AM	Report #	33933
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental team Preformed VA SWPPP inspection from 11184+85 (MP 211.83) to 11254+99 (MP 213.6) Assisted by fellow EI Eric Hanlon This section of ROW has no current construction. No deficiencies found. Water bars (other) All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		Date/Time	2/2/2022 11:49 AM	Report #	
Pictures					
<p>Date & Time: Wed Feb 02, 2022, 08:43:47 EST Position: +037.307362 / -080.511922 (±18.4ft) Altitude: 1897ft (±36.1ft) Datum: WGS-84 Azimuth/Bearing: 066 N48E 3209mils True (±15.1) Elevation Angle: +18.2 Horizon Angle: -01.1 Zoom: 0.5X 11185+00</p> 		<p>Date & Time: Wed Feb 02, 2022, 08:44:13 EST Position: +037.308887 / -080.510147 (±18.6ft) Altitude: 1899ft (±36.1ft) Datum: WGS-84 Azimuth/Bearing: 066 N48E 3220mils True (±15.1) Elevation Angle: +26.9 Horizon Angle: -01.1 Zoom: 0.5X 11191+02</p> 			
GPS Location		See Photo		GPS Location	
Field Station#		11185+00		Field Station#	
Pic 1 Desc.		Access road 249.02		Pic 2 Desc.	
<p>Date & Time: Wed Feb 02, 2022, 09:55:55 EST Position: +037.306008 / -080.508372 (±13.5ft) Altitude: 2038ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 066 N44E 1138mils True (±12.1) Elevation Angle: +23.9 Horizon Angle: -06.9 Zoom: 1.0X 11194+00</p> 		<p>Date & Time: Wed Feb 02, 2022, 09:55:55 EST Position: +037.306008 / -080.508372 (±13.5ft) Altitude: 2038ft (±19.7ft) Datum: WGS-84 Azimuth/Bearing: 066 N44E 1138mils True (±12.1) Elevation Angle: +23.9 Horizon Angle: -06.9 Zoom: 1.0X 11196+00</p> 			
GPS Location		See Photo		GPS Location	
Field Station#		11194+00		Field Station#	
Pic 3 Desc.		Level Spreader		Pic 4 Desc.	
<p>Date & Time: Wed Feb 02, 2022, 09:54:40 EST Position: +037.295904 / -080.494379 (±36.6ft) Altitude: 2073ft (±36.3ft) Datum: WGS-84 Azimuth/Bearing: 055 N55E 0978mils True (±12.1) Elevation Angle: -21.8 Horizon Angle: -01.1 Zoom: 0.5X 11249+00</p> 		<p>Date & Time: Wed Feb 02, 2022, 09:16:00 EST Position: +037.301293 / -080.500993 (±23.5ft) Altitude: 2083ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 351 N09W 6240mils True (±12.1) Elevation Angle: -07.9 Horizon Angle: -01.6 Zoom: 0.5X 11228+00</p> 			
GPS Location		See Photo		GPS Location	
Field Station#		11249+00		Field Station#	
Pic 5 Desc.		Erosion controls blanked		Pic 6 Desc.	

A/E	124300137	Date/Time	2/2/2022 11:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	2/2/2022 11:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33944
Inspector	Patrick Shields			Date/Time	2/2/2022 3:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11098+47
State	VA	Inspection Area	Full	Station End	11184+85
County	Giles	Ground	Frozen	Temperature (°F)	44.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/2/2022 3:25 PM	Report #	33944
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11098+47 (AR-245.02) to ST# 11184+85 (AR-249.02) MP 210.2 to MP 211.83 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews activity working on this section of ROW at time of inspection. ST# 11445+50 to ST# 11170+00 has undergone temporary stabilization. Cleanwater diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Final restoration has occurred between ST# 11098+47 and ST# 11145+50 and between ST# 11170+00 and ST# 11184+85. CFS perimeter controls, end treatments and temporary waterbars are in place. Daylight drains with outlet protection and Permanent waterbars (section 6-other) with level spreaders are in place. AR-245.02, 249, 249.03, 249.01 and 249.02 RCEs are maintained in acceptable condition. The ROW is frozen and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/2/2022 3:25 PM	Report #	
Pictures					
<p>Date & Time: Wed Feb 02, 2022, 09:41:19 EST Position: +037.314324° / -080.526959° (±11.6M) Altitude: 1927ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 282° N72W 5120mils True (±12°) Elevation Grade: +003° Horizon Grade: -013° Zoom: 1.0X 11106+00</p> 		<p>Date & Time: Wed Feb 02, 2022, 09:41:19 EST Position: +037.314324° / -080.526959° (±11.6M) Altitude: 1927ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 282° N72W 5120mils True (±12°) Elevation Grade: +003° Horizon Grade: -013° Zoom: 1.0X 11112+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11106+00	Field Station#	11112+00		
Pic 1 Desc.	CFS end treatments in place	Pic 2 Desc.	CFS triple stack perimeter control in place		
<p>Date & Time: Wed Feb 02, 2022, 09:51:55 EST Position: +037.315424° / -080.526959° (±11.6M) Altitude: 1927ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 282° N72W 5120mils True (±12°) Elevation Grade: +023° Horizon Grade: -003° Zoom: 1.0X 11120+00</p> 		<p>Date & Time: Wed Feb 02, 2022, 10:04:47 EST Position: +037.314004° / -080.522011° (±11.6M) Altitude: 2076ft (±9.6M) Datum: WGS-84 Azimuth/Bearing: 294° N44W 5220mils True (±12°) Elevation Grade: +003° Horizon Grade: -009° Zoom: 1.0X 11135+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11120+00	Field Station#	11135+00		
Pic 3 Desc.	CFS temporary waterbars in place	Pic 4 Desc.	Level spreader in place		
<p>Date & Time: Wed Feb 02, 2022, 10:13:10 EST Position: +037.314324° / -080.526959° (±11.6M) Altitude: 2076ft (±9.6M) Datum: WGS-84 Azimuth/Bearing: 113° S40E 2009mils True (±12°) Elevation Grade: +003° Horizon Grade: -003° Zoom: 1.0X 11141+00</p> 		<p>Date & Time: Wed Feb 02, 2022, 10:19:55 EST Position: +037.314324° / -080.519938° (±11.6M) Altitude: 2076ft (±9.6M) Datum: WGS-84 Azimuth/Bearing: 150° N34E 1990mils True (±12°) Elevation Grade: +003° Horizon Grade: -003° Zoom: 1.0X 11146+80</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11141+00	Field Station#	11146+80		
Pic 5 Desc.	Permanent vegetation present	Pic 6 Desc.	Cleanwater diversion berm in place		

AFE	124300137	Date/Time	2/2/2022 3:25 PM	Report #	
Pictures					
<p>Date & Time: Wed, Feb 02, 2022, 10:19:18 EST Position: +407.210322° / -80.511687° (s13.40) Altitude: +2040 (s13.20) Datum: WGS-84 Azimuth/Heading: 156° Head, 350mils True (s12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11148+50</p> 		<p>Date & Time: Wed, Feb 02, 2022, 10:26:26 EST Position: +407.211222° / -80.512311° (s13.40) Altitude: +1620 (s13.30) Datum: WGS-84 Azimuth/Heading: 112° Head, 350mils True (s12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11163+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11148+50	Field Station#	11163+00		
Pic 7 Desc.	Supersilt fence perimeter control in place	Pic 8 Desc.	P1 silt fence perimeter control in place		
<p>Date & Time: Wed, Feb 02, 2022, 10:26:13 EST Position: +407.210322° / -80.511687° (s13.40) Altitude: +2040 (s13.20) Datum: WGS-84 Azimuth/Heading: 200° Head, 350mils True (s12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 1.0X 11167+00</p> 		<p>Date & Time: Wed, Feb 02, 2022, 10:26:26 EST Position: +407.211222° / -80.512311° (s13.40) Altitude: +1620 (s13.30) Datum: WGS-84 Azimuth/Heading: 211° Head, 370mils True (s12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11168+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11167+00	Field Station#	11168+00		
Pic 9 Desc.	Cleanwater diversion outlet protection in place	Pic 10 Desc.	RCE in place		
<p>Date & Time: Wed, Feb 02, 2022, 10:43:16 EST Position: +407.208146° / -80.512062° (s13.19) Altitude: +1930 (s13.40) Datum: WGS-84 Azimuth/Heading: 300° Head, 547mils True (s12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11177+00</p> 		<p>Date & Time: Wed, Feb 02, 2022, 10:47:18 EST Position: +407.207449° / -80.511963° (s13.58) Altitude: +1930 (s13.40) Datum: WGS-84 Azimuth/Heading: 211° Head, 570mils True (s12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11184+75</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11177+00	Field Station#	11184+75		
Pic 11 Desc.	Permanent waterbars in place	Pic 12 Desc.	Daylight drain in place		

A/E	124300137	Date/Time	2/2/2022 3:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33950
Inspector	Daniel Fortune			Date/Time	2/2/2022 7:26 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11098+47
County	Giles	Ground	Damp	Temperature (°F)	34.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	2/2/2022 7:26 PM	Report #	33950
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. No deficiencies found or documented today.</p> <p>Other deficiencies may be found and reported by other EI's/and or MBP personnel.</p> <p>Station numbers are approximate.</p> <p>ROW CONDITIONS:</p> <p>The ROW in that area received 0.00" of precipitation overnight. The ROW can be described as permeable as the majority of the snow has melted and the soil does have an unmeasurable porosity at this time.</p> <p>The ROW from AR 244 to AR 245.01 has been temporarily stabilized. The ROW from 245.01 to 245.02 has been restored. The restored area is in good shape and the vegetation is sufficient.</p> <p>The water bars (other), in the restored area are in place and functioning as designed.</p> <p>The environmental controls are functional. No construction being performed in the area.</p> <p>One area of open ditch in the area. Rock Road approaches were cleaned and functioning as designed. The EC's at the WB's in this area are in place and functioning as designed.</p> <p>LOD ECDs were in place and functional. Water bars have been installed to specifications.</p> <p>No sensitive resources have been impacted.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/2/2022 7:26 PM	Report #	
Pictures					
<p>Date & Time: Wed Feb 02, 2022 09:45:23 EST Position: +037.312939 / -080.533581 (+41.1ft) Altitude: 1968ft (+52.5ft) Datum: WGS-84 Azimuth/Bearing: 361° N19W 6062mils True (+13.1°) Elevation Grade: +001% Horizon Grade: +002% Horizon: 1.0X Zoom: 1.0X 11098+93</p> 		<p>Date & Time: Wed Feb 02, 2022 09:38:49 EST Position: +037.315454 / -080.536978 (+32.9ft) Altitude: 1998ft (+52.5ft) Datum: WGS-84 Azimuth/Bearing: 103° S7E 1831mils True (+3.3°) Elevation Grade: +002% Horizon Grade: +003% Horizon: 1.0X Zoom: 1.0X 11087+00</p> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11098+93		Field Station#	11087+00	
Pic 1 Desc.	AR 244 conditions		Pic 2 Desc.	Final Restoration Area	
<p>Date & Time: Wed Feb 02, 2022 09:29:41 EST Position: +037.315354 / -080.541235 (+11.6ft) Altitude: 2206ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 084° N84E 1493mils True (+12.7°) Elevation Grade: +009% Horizon Grade: +006% Horizon: 1.0X Zoom: 1.0X 11073+00</p> 		<p>Date & Time: Wed Feb 02, 2022 09:23:09 EST Position: +037.315455 / -080.542011 (+18.4ft) Altitude: 2171ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 041° N40E 8711mils True (+12.7°) Elevation Grade: +022% Horizon Grade: +003% Horizon: 1.0X Zoom: 1.0X 11064+50</p> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11073+00		Field Station#	11064+50	
Pic 3 Desc.	Final Restoration Area		Pic 4 Desc.	Drainage feature condition.	
<p>Date & Time: Wed Feb 02, 2022 09:17:22 EST Position: +037.315354 / -080.545681 (+29.8ft) Altitude: 2210ft (+18.4ft) Datum: WGS-84 Azimuth/Bearing: 023° S57E 2187mils True (+12.1°) Elevation Grade: +031% Horizon Grade: +003% Horizon: 1.0X Zoom: 1.0X 11060+00</p> 		<p>Date & Time: Wed Feb 02, 2022 09:14:17 EST Position: +037.315354 / -080.545681 (+29.8ft) Altitude: 2210ft (+18.4ft) Datum: WGS-84 Azimuth/Bearing: 013° N35E 0231mils True (+12.1°) Elevation Grade: +012% Horizon Grade: +003% Horizon: 1.0X Zoom: 1.0X 11056+00</p> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11060+00		Field Station#	11056+00	
Pic 5 Desc.	View of open ditch to future valve site.		Pic 6 Desc.	Super silt fence, P1 silt fence and CFS protecting the sensitive resource area.	

AFE	124300137	Date/Time	2/2/2022 7:26 PM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11050+20	Field Station#	11050+20		
Pic 7 Desc.	View looking downstream	Pic 8 Desc.	S-IJ16&17 equipment bridge condition		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11046+92	Field Station#	11045+00		
Pic 9 Desc.	Daylight drain out let to a water bar.	Pic 10 Desc.	Current temporary water bar conditions.		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11040+27	Field Station#	11040+27		
Pic 11 Desc.	Stone inlet protection condition	Pic 12 Desc.	temporary slope drain pipe condition.		

A/E	124300137	Date/Time	2/2/2022 7:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33942
Inspector	Chris Burns			Date/Time	2/2/2022 3:07 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10929+80
State	VA	Inspection Area	Partial	Station End	11023+80
County	Giles	Ground	Muddy	Temperature (°F)	46.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	2/2/2022 3:07 PM	Report #	33942
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 207 (10929+80) and MP 208.78 (11023+80). Accompanied by fellow EI Clint Sears. This section of RoW has no current construction. A portion of this section of RoW has been permanently restored. Assessed AR 242.01. AR 242.01 is partially completed, incomplete portions are stabilized. No issues were identified. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient less. Stream buffers and controls in place at the time of inspection. No impact to sensitive resources observed. Assessed potential locations for future dewatering excavations. Section 6 - CFS waterbars (other).					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/2/2022 3:07 PM	Report #	
Pictures					
GPS Location	1	GPS Location	2		
Field Station#	10971+74	Field Station#	10971+00		
Pic 1 Desc.	AR 242.01 conditions and controls.	Pic 2 Desc.	Section of RoW showing conditions and controls. (Staged equipment).		
GPS Location	3	GPS Location	4		
Field Station#	10975+50	Field Station#	10992+00		
Pic 3 Desc.	Section of RoW showing conditions and controls.	Pic 4 Desc.	P-1 perimeter controls functional.		
GPS Location	5	GPS Location	6		
Field Station#	11004+00	Field Station#	11015+52		
Pic 5 Desc.	CWDP outlet protection functional.	Pic 6 Desc.	S-RR5.		

AFE	124300137	Date/Time	2/2/2022 3:07 PM	Report #	
Pictures					
GPS Location	7	GPS Location	8		
Field Station#	11016+78	Field Station#	11023+80		
Pic 7 Desc.	S-PA07.	Pic 8 Desc.	Section of RoW showing conditions and controls.		
GPS Location	9	GPS Location	10		
Field Station#	10935+00	Field Station#	10940+50		
Pic 9 Desc.	SSF perimeter controls functional.	Pic 10 Desc.	Section of restored RoW showing conditions and controls.		
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	2/2/2022 3:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33990
Inspector	Patrick Shields			Date/Time	2/3/2022 2:56 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+67
State	VA	Inspection Area	Full	Station End	11471+56
County	Giles	Ground	Wet	Temperature (°F)	42.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.60
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/3/2022 2:56 PM	Report #	33990
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11353+67 (Old Furnace) to ST# 11471+56 (Steele Acres) MP 215.04 to MP 217.26 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews on this section of ROW at time of inspection. ST# 11353+67 to ST# 11367+00 and ST# 11443+50 to ST# 11471+56 have undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Triple protection ECDs are in place at karst feature. Final restoration has occurred between ST# 11367+00 and ST# 11443+50. CFS perimeter controls, end treatments and temporary waterbars are in place. Permanent waterbars(section 6-other) with level spreaders are in place. Sensitive resource buffers are in place at stream crossings S-KL43, S-0014, S-0013, S-0012, and S-CD14. AR-256 and 258.01 RCEs are maintained in acceptable condition. Steele Acres rain gauge measured 0.6" of rainfall accumulated on 2/2/22. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/3/2022 2:56 PM	Report #	
Pictures					
<p>Date & Time: Thu, Feb 03, 2022, 11:59:26 EST Position: +037.305191° / -080.467033° (±11.6ft) Altitude: 2094ft (±9.8m) Datum: WGS-84 Azimuth/Bearing: 215° S35W 3822mils True (±12°) Elevation Grade: -02% Horizon Grade: +001% Zoom: 1.0X 11353+50</p> 		<p>Date & Time: Thu, Feb 03, 2022, 11:00:47 EST Position: +037.304777° / -080.466902° (±11.6ft) Altitude: 1990ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 030° M00E 0364mils True (±12°) Elevation Grade: -000% Horizon Grade: +001% Zoom: 1.0X 11362+50</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11353+50		Field Station#	11362+50	
Pic 1 Desc.	RCE in place		Pic 2 Desc.	Erosion control blanket in place	
<p>Date & Time: Thu, Feb 03, 2022, 11:43:18 EST Position: +037.308054° / -080.466401° (±14.2ft) Altitude: 2009ft (±9.7ft) Datum: WGS-84 Azimuth/Bearing: 163° S17E 2898mils True (±12°) Elevation Grade: -01% Horizon Grade: -013% Zoom: 1.0X 11363+00</p> 		<p>Date & Time: Thu, Feb 03, 2022, 11:34:57 EST Position: +037.309942° / -080.468193° (±11.6ft) Altitude: 2009ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 251° N25W 4018mils True (±12°) Elevation Grade: -00% Horizon Grade: -00% Zoom: 1.0X 11397+00</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11363+00		Field Station#	11397+00	
Pic 3 Desc.	End treatments in place		Pic 4 Desc.	Level spreader in place	
<p>Date & Time: Thu, Feb 03, 2022, 11:17:33 EST Position: +037.311647° / -080.468292° (±14.2ft) Altitude: 2231ft (±9.7ft) Datum: WGS-84 Azimuth/Bearing: 044° N46E 0618mils True (±12°) Elevation Grade: +012% Horizon Grade: +000% Zoom: 1.0X 11412+00</p> 		<p>Date & Time: Thu, Feb 03, 2022, 11:05:49 EST Position: +037.314889° / -080.468977° (±13.1ft) Altitude: 2153ft (±11.7ft) Datum: WGS-84 Azimuth/Bearing: 030° S20W 4124mils True (±12°) Elevation Grade: +00% Horizon Grade: -00% Zoom: 1.0X 11433+50</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11412+00		Field Station#	11433+50	
Pic 5 Desc.	Temporary CFS waterbars in place		Pic 6 Desc.	Permanent waterbars in place	

AFE	124300137	Date/Time	2/3/2022 2:56 PM	Report #	
Pictures					
<p>Date & Time: Thu, Feb 03, 2022, 10:49:13 EST Position: +037.317543° / -080.444591° (±11.60) Altitude: 2156ft (±9.80) Datum: WGS-84 Azimuth/Bearing: 203° S27°W 3460mils True (±12°) Elevation Grade: -013% Horizon Grade: -003% Zoom: 1.0X 11437+00</p> 		<p>Date & Time: Thu, Feb 03, 2022, 10:54:02 EST Position: +037.318594° / -080.442134° (±15.10) Altitude: 2138ft (±11.70) Datum: WGS-84 Azimuth/Bearing: 213° S33°W 3360mils True (±12°) Elevation Grade: +003% Horizon Grade: +003% Zoom: 1.0X 11448+00</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11437+00		Field Station#	11448+00	
Pic 7 Desc.	Permanent vegetation present		Pic 8 Desc.	Cleanwater diversion berm in place	
<p>Date & Time: Thu, Feb 03, 2022, 10:48:29 EST Position: +037.319377° / -080.440492° (±11.58) Altitude: 2159ft (±12.70) Datum: WGS-84 Azimuth/Bearing: 244° S44°W 4338mils True (±12°) Elevation Grade: -022% Horizon Grade: +003% Zoom: 1.0X 11452+00</p> 		<p>Date & Time: Thu, Feb 03, 2022, 10:51:12 EST Position: +037.317421° / -080.437427° (±12.00) Altitude: 2200ft (±12.20) Datum: WGS-84 Azimuth/Bearing: 242° S82°W 4658mils True (±12°) Elevation Grade: -030% Horizon Grade: -008% Zoom: 1.0X 11461+00</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11452+00		Field Station#	11461+00	
Pic 9 Desc.	Stream buffer in place		Pic 10 Desc.	CFS perimeter control in place	
<p>Date & Time: Thu, Feb 03, 2022, 10:38:54 EST Position: +037.312061° / -080.436773° (±18.10) Altitude: 2266ft (±26.20) Datum: WGS-84 Azimuth/Bearing: 288° S88°W 4764mils True (±12°) Elevation Grade: -042% Horizon Grade: -006% Zoom: 1.0X 11467+00</p> 		<p>Date & Time: Thu, Feb 03, 2022, 10:49:13 EST Position: +037.311404° / -080.443356° (±15.0240) Altitude: 2266ft (±15.20) Datum: WGS-84 Azimuth/Bearing: 200° W0°W 5754mils True (±12°) Elevation Grade: -027% Horizon Grade: -000% Zoom: 1.0X 11469+00</p> 			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11467+00		Field Station#	11469+00	
Pic 11 Desc.	Plunge pool in place		Pic 12 Desc.	Triple protection ECDs in place at karst feature	

A/E	124300137	Date/Time	2/3/2022 2:56 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	34002
Inspector	David Schoolcraft			Date/Time	2/3/2022 10:34 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Full	Station End	11600+01
County	Giles	Ground	Wet	Temperature (°F)	43.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Stone Inlet Protection	Acceptable			
Slope Drain Pipe	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/3/2022 10:34 PM	Report #	34002
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental team Preformed VA SWPPP inspection from 11524+16 (MP 218.26) to 11600+01 (MP 219.70) assisted by fellow EI Eric Hanlon. This section of ROW has no current construction. No deficiencies found. Water bars (other) All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/3/2022 10:34 PM	Report #	
Pictures					
<div><div><div>Date & Time Thu, Feb 03, 2022, 09:16:36 EST Position: 4889.2148887° / -83.0428377° (-17.07) Altitude: 1537.12 (-1537.00) Datum: WGS-84 Azimuth Bearing: 124.742E 224mils True (+12.1) Elevation Angle: -03.7 Horizon Angle: +02.4 Zoom: 1.0X 11527+00</div><div></div></div></div>			<div><div><div>Date & Time Thu, Feb 03, 2022, 09:16:36 EST Position: 4889.2148887° / -83.0428377° (-17.07) Altitude: 1537.12 (-1537.00) Datum: WGS-84 Azimuth Bearing: 124.742E 224mils True (+12.1) Elevation Angle: -03.7 Horizon Angle: +02.4 Zoom: 1.0X 11527+54</div><div></div></div></div>		
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11527+00		Field Station#	11527+54	
Pic 1 Desc.	Restoration		Pic 2 Desc.	Level Spreader	
<div><div><div>Date & Time Thu, Feb 03, 2022, 09:16:36 EST Position: 4889.2148887° / -83.0428377° (-17.07) Altitude: 1537.12 (-1537.00) Datum: WGS-84 Azimuth Bearing: 126.554E 224mils True (+12.1) Elevation Angle: -07.1 Horizon Angle: +03.7 Zoom: 1.0X 11535+00</div><div></div></div></div>			<div><div><div>Date & Time Thu, Feb 03, 2022, 09:16:36 EST Position: 4889.2148887° / -83.0428377° (-17.07) Altitude: 1537.12 (-1537.00) Datum: WGS-84 Azimuth Bearing: 126.554E 224mils True (+12.1) Elevation Angle: -07.1 Horizon Angle: +03.7 Zoom: 1.0X 11584+00</div><div></div></div></div>		
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11535+00		Field Station#	11584+00	
Pic 3 Desc.	Perimeter controls		Pic 4 Desc.	P1 Checks	
<div><div><div>Date & Time Thu, Feb 03, 2022, 08:54:24 EST Position: 4889.2148887° / -83.0428377° (-17.07) Altitude: 1537.12 (-1537.00) Datum: WGS-84 Azimuth Bearing: 167.513E 276mils True (+12.1) Elevation Angle: -13.6 Horizon Angle: -02.4 Zoom: 0.5X 11588+50</div><div></div></div></div>			<div><div><div>Date & Time Thu, Feb 03, 2022, 09:16:36 EST Position: 4889.2148887° / -83.0428377° (-17.07) Altitude: 1537.12 (-1537.00) Datum: WGS-84 Azimuth Bearing: 157.817E 276mils True (+12.1) Elevation Angle: -13.6 Horizon Angle: -02.4 Zoom: 0.5X 116200+01</div><div></div></div></div>		
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11588+50		Field Station#	116200+01	
Pic 5 Desc.	Slope Drain		Pic 6 Desc.	RCE	

AFE	124300137	Date/Time	2/3/2022 10:34 PM	Report #	
Pictures					
 <p>Photo 7: Equipment Bridge Position: 35.951125, -83.000000 (s14.00) Altitude: 205.00 (s14.00) Datum: WGS-84 Azimuth Bearing: 210.530W 37.00 (s14.00) Elevation Angle: -01.9 Horizon Angle: -01.9 Zoom: 0.5X 11585+00</p>		 <p>Photo 8: Buffer and stream Position: 35.951125, -83.000000 (s14.00) Altitude: 205.00 (s14.00) Datum: WGS-84 Azimuth Bearing: 210.530W 37.00 (s14.00) Elevation Angle: -01.9 Horizon Angle: -01.9 Zoom: 0.5X 11588+20</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11585+00	Field Station#	11588+20		
Pic 7 Desc.	Equipment Bridge	Pic 8 Desc.	Buffer and stream		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	2/3/2022 10:34 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	33981
Inspector	Chris Burns			Date/Time	2/3/2022 12:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11471+56
State	VA	Inspection Area	Partial	Station End	11524+16
County	Giles	Ground	Wet	Temperature (°F)	47.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.60
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/3/2022 12:28 PM	Report #	33981
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 217.26 (11471+56) and MP 218.26 (11524+16). Fellow EI Clint Sears accompanied during inspection. This section of RoW has no current construction. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed AR 258.02 and Steele Acres. Assessed dewatering locations for future excavations.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/3/2022 12:28 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11524+16	Field Station#	11472+50		
Pic 1 Desc.	AR 258.02 conditions and controls.		Pic 2 Desc.	Karst feature protection functional.	
					
GPS Location	3	GPS Location	4		
Field Station#	11478+00	Field Station#	11487+25		
Pic 3 Desc.	Section of RoW showing conditions and controls.		Pic 4 Desc.	Plunge pool functional.	
					
GPS Location	5	GPS Location	6		
Field Station#	11490+00	Field Station#	11502+00		
Pic 5 Desc.	Rain gauge indicating 0.6" of accumulation.		Pic 6 Desc.	Section of RoW showing conditions and controls.	

AFE	124300137	Date/Time	2/3/2022 12:28 PM	Report #	
Pictures					
GPS Location	7	GPS Location	8		
Field Station#	11505+75	Field Station#	11507+78		
Pic 7 Desc.	Plunge pool functional.		Pic 8 Desc.	Overview of S-PP3.	
		<div style="text-align: center;">Insert image here</div>			
GPS Location	9	GPS Location			
Field Station#	11518+32	Field Station#			
Pic 9 Desc.	S-PP4.		Pic 10 Desc.		
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	2/3/2022 12:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	34032
Inspector	Chris Burns			Date/Time	2/4/2022 1:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+89
County	Montgomery	Ground	Muddy	Temperature (°F)	53.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/4/2022 1:41 PM	Report #	34032
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Rain gauge at Mt Tabor rd. Indicated 1.0" of accumulation Performed SWPPP inspection, from MP 223.27 (11788+52) and MP 225.37 (11899+89). Fellow EI Clint Sears accompanied during SWPPP inspection. This section of RoW has no current construction. Temporary controls within this area are partially removed, remaining temporary controls to be removed once ground/weather conditions improve. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Unauthorized vehicle travel within the permanent restoration area, between 11792+00 and 11831+75, on 1/18/2022 resulted in minor disturbance/vegetation damage between 11824+00 and 11831+75. Monitoring of this area to continue. Assessed AR 266.03. Section 6- Waterbars (other).					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/4/2022 1:41 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11789+00	Field Station#	11798+00		
Pic 1 Desc.	Rain gauge indicating 1.0" of accumulation.		Pic 2 Desc.	Section of restored RoW showing conditions and controls.	
					
GPS Location	3	GPS Location	4		
Field Station#	11821+00	Field Station#	11842+00		
Pic 3 Desc.	Representational photo of permanent waterbar and level spreader.		Pic 4 Desc.	Section of restored RoW showing conditions and controls.	
					
GPS Location	5	GPS Location	6		
Field Station#	11856+00	Field Station#	11863+65		
Pic 5 Desc.	Section of restored RoW showing conditions and controls.		Pic 6 Desc.	P-KL2.	

A/E	124300137	Date/Time	2/4/2022 1:41 PM	Report #	
Pictures					
GPS Location	7	GPS Location	8		
Field Station#	11870+00	Field Station#	11866+00		
Pic 7 Desc.	Section of restored RoW showing conditions and controls.	Pic 8 Desc.	Section of restored RoW showing conditions and controls.		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	2/4/2022 1:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	34045
Inspector	Joe Sweeden			Date/Time	2/4/2022 11:41 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	37.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.65
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	2/4/2022 11:41 AM	Report #	34045
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed VA SWPP at Yard 29. No deficiencies found. Observances: No activity in the Yard. Equipment in the yard was free of leaks. The perimeter compost sock was in place and functioning as designed. The rock road approach was clean, no mud or other debris on road. The yard was free of debris. No trash was seen. Trash receptacles in the Yard were clearly labeled. Yard 29 had received 0.65" of precipitation over the last 24					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/4/2022 11:41 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Equipment yard 29		Pic 2 Desc.	Equipment yard 29	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Yard 29		Pic 4 Desc.	Compost sock	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	Trash receptacles		Pic 6 Desc.	Yard 29 RCE	

A/E	124300137	Date/Time	2/4/2022 11:41 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	2/4/2022 11:41 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	34024
Inspector	Daniel Fortune			Date/Time	2/4/2022 11:57 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+89
State	VA	Inspection Area	Partial	Station End	12005+00
County	Montgomery	Ground	Wet	Temperature (°F)	36.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/4/2022 11:57 AM	Report #	34024
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted. P1 Silt fence repairs between 11913+00 to 11978+86.					
Comments (Reference above questions as appropriate.) See photos for GPS coordinates. Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). No Deficiencies documented for repairs today. This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time. Permanent water bars have been installed and appear to be functioning as intended. (Other) Level Spreader functional Precision Crews: No crews on site or activity observed. All other perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed Ar 266.03 and AR 266.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/4/2022 11:57 AM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11978+88		Field Station#	11976+00	
Pic 1 Desc.	Perimeter ECDs in functional condition. P1 silt fence, triple stacked CFS 18", and super silt fence		Pic 2 Desc.	Final Restoration Area	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11946+92		Field Station#	11943+00	
Pic 3 Desc.	Vegetated water bar bar condition.		Pic 4 Desc.	Replaced perimeter P1 silt fencing	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11918+64		Field Station#	11918+64	
Pic 5 Desc.	Final Restoration Area		Pic 6 Desc.	Perimeter CFS and row vegetation. Downed tree over CFS. No damage.	

AFE	124300137	Date/Time	2/4/2022 11:57 AM	Report #	
Pictures					
<small> Date & Time: Fri, Feb 04, 2022, 09:14:58 EST Position: +487.23742° / -98.22948° (±1.00) Altitude: 2297 (±5.00) Datum: WGS-84 Azimuth/Bearing: 101° 30'51" 328mils True (±12°) Heading Grade: +00% Pitch Grade: +00% Zoom: 0.2X 11918+64 </small> 		<small> Date & Time: Fri, Feb 04, 2022, 09:14:19 EST Position: +487.23742° / -98.22944° (±1.00) Altitude: 2297 (±5.00) Datum: WGS-84 Azimuth/Bearing: 101° 30'51" 328mils True (±12°) Heading Grade: +00% Pitch Grade: +00% Zoom: 0.2X 11913+00 </small> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11918+64		Field Station#	11913+00	
Pic 7 Desc.	Final Restoration Area		Pic 8 Desc.	Repaired P1 silt fencing.	
<small> Date & Time: Fri, Feb 04, 2022, 09:10:49 EST Position: +487.23742° / -98.22951° (±1.00) Altitude: 2297 (±5.00) Datum: WGS-84 Azimuth/Bearing: 103° 31'55" 328mils True (±12°) Heading Grade: +00% Pitch Grade: +00% Zoom: 0.2X 11907+00 </small> 		<small> Date & Time: Fri, Feb 04, 2022, 09:10:16 EST Position: +487.23742° / -98.22951° (±1.00) Altitude: 2297 (±5.00) Datum: WGS-84 Azimuth/Bearing: 101° 30'51" 328mils True (±12°) Heading Grade: +00% Pitch Grade: +00% Zoom: 0.2X 11900+81 </small> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11907+00		Field Station#	11900+81	
Pic 9 Desc.	Final Restoration Conditions		Pic 10 Desc.	Functioning Level spreader	
<small> Date & Time: Fri, Feb 04, 2022, 09:10:19 EST Position: +487.23742° / -98.22951° (±1.00) Altitude: 2297 (±5.00) Datum: WGS-84 Azimuth/Bearing: 103° 31'55" 328mils True (±12°) Heading Grade: +00% Pitch Grade: +00% Zoom: 0.2X 11900+81 </small> 		<small> Date & Time: Fri, Feb 04, 2022, 09:10:20 EST Position: +487.23742° / -98.22944° (±1.00) Altitude: 2297 (±5.00) Datum: WGS-84 Azimuth/Bearing: 103° 31'55" 328mils True (±12°) Heading Grade: +00% Pitch Grade: +00% Zoom: 0.2X 11900+81 </small> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11900+81		Field Station#	11900+81	
Pic 11 Desc.	AR 266.		Pic 12 Desc.	Vegetated water bar into level spreader.	

A/E	124300137	Date/Time	2/4/2022 11:57 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	34022
Inspector	Rob Robertson			Date/Time	2/4/2022 11:33 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Wet	Temperature (°F)	42.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/4/2022 11:33 AM	Report #	34022
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection was completed today on JNF and private lands at Brush Mountain. Approximately one inch of rain has fell in the area in the past 24 hours. This area of ROW remains stable with no erosion or impact to resources observed. ECDs are in place along the perimeter of LOD. No maintenance needs were identified. Slope breakers, sumps and end treatments are effectively controlling stormwater runoff. No sediment migration or rilling occurring. Stream crossing buffers are stable. Adequate ECDs are in place. Housekeeping is acceptable. Equipment bridges appear sound. CFS will have to be replaced before any ground disturbance occurs. Access road MN-258.04 and S-RR13 are stable. RCEs are in acceptable condition.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/4/2022 11:33 AM	Report #	
Pictures					
<p>Date & Time: Fri, Feb 04, 2022, 09:35:59 EST Position: +427.304999° / -660.399497° (±5.0m) Altitude: 627m (±5.0m) Datum: WGS-84 Azimuth/Bearing: 115.545E 202mils Magnetic (±12°) Elevation Angle: +05.9° Horizon Angle: +00.0° Zoom: 1.0X 11666+50</p> 		<p>Date & Time: Fri, Feb 04, 2022, 09:35:39 EST Position: +427.304999° / -660.399497° (±5.0m) Altitude: 627m (±5.0m) Datum: WGS-84 Azimuth/Bearing: 131° 349E 230mils Magnetic (±13°) Elevation Angle: +08.1° Horizon Angle: +00.0° Zoom: 1.0X 11666+00</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11666+50	Field Station#	11666+00		
Pic 1 Desc.	ROW at top of Brush Mountain is stable. No evidence of vandalism discovered.	Pic 2 Desc.	Perimeter ECDs are in place and functional.		
<p>Date & Time: Fri, Feb 04, 2022, 09:36:18 EST Position: +427.304999° / -660.399497° (±5.0m) Altitude: 703m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 142.538E 252mils Magnetic (±12°) Elevation Angle: +02.0° Horizon Angle: +10.0° Zoom: 1.0X 11658+00</p> 		<p>Date & Time: Fri, Feb 04, 2022, 09:36:13 EST Position: +427.304999° / -660.399497° (±5.0m) Altitude: 629m (±5.0m) Datum: WGS-84 Azimuth/Bearing: 130° 330E 246mils Magnetic (±13°) Elevation Angle: +05.4° Horizon Angle: +00.0° Zoom: 1.0X 11655+00</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11658+00	Field Station#	11655+00		
Pic 3 Desc.	Perimeter ECDs are in place.	Pic 4 Desc.	Perimeter ECDs are in place.		
<p>Date & Time: Fri, Feb 04, 2022, 09:36:47 EST Position: +427.304999° / -660.399497° (±5.0m) Altitude: 724m (±5.0m) Datum: WGS-84 Azimuth/Bearing: 149.570W 325mils Magnetic (±12°) Elevation Angle: +05.2° Horizon Angle: +00.0° Zoom: 1.0X 11654+00</p> 		<p>Date & Time: Fri, Feb 04, 2022, 09:36:44 EST Position: +427.304999° / -660.399497° (±5.0m) Altitude: 626m (±5.0m) Datum: WGS-84 Azimuth/Bearing: 173° 307E 307mils Magnetic (±12°) Elevation Angle: +07.0° Horizon Angle: +00.0° Zoom: 1.0X 11646+00</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11654+00	Field Station#	11646+00		
Pic 5 Desc.	CFS will be replaced before any ground disturbance occurs.	Pic 6 Desc.	Perimeter ECDs in place.		

AFE	124300137	Date/Time	2/4/2022 11:33 AM	Report #	
Pictures					
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11626+04	Field Station#	11618+00		
Pic 7 Desc.	The S-HH18 crossing is stable.	Pic 8 Desc.	Slope drain and sump functioning properly.		
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11614+20	Field Station#	11613+69		
Pic 9 Desc.	The S-RR14 crossing is stable.	Pic 10 Desc.	Access road MN-258.04 and S-RR13 are in good condition.		
					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11608+17	Field Station#	11601+00		
Pic 11 Desc.	S-006 crossing is stable.	Pic 12 Desc.	Perimeter ECDs in place, effective.		

A/E	124300137	Date/Time	2/4/2022 11:33 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	34026
Inspector	Patrick Shields			Date/Time	2/4/2022 12:15 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Full	Station End	11788+52
County	Montgomery	Ground	Wet	Temperature (°F)	48.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	2/4/2022 12:15 PM	Report #	34026
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 (Brush Mt) to ST# 11788+52 (Mt Tabor) MP 221.02 to MP 223.27 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection are in place where needed. Perimeter controls and waterbars with end treatments are in place. Sensitive resource buffers are in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted. MT. Tabor rain gauge measured 1.0" of rainfall accumulated on 2/3/22.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/4/2022 12:15 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11670+00	Field Station#	11677+50		
Pic 1 Desc.	P1 silt fence perimeter control in place	Pic 2 Desc.	CFS triple stack end treatments in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11683+50	Field Station#	11688+00		
Pic 3 Desc.	Stone inlet protection in place	Pic 4 Desc.	Erosion control blanket in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11704+80	Field Station#	11712+00		
Pic 5 Desc.	Sediment filter logs in place	Pic 6 Desc.	Waterbars in place		

AFE	124300137	Date/Time	2/4/2022 12:15 PM	Report #	
Pictures					
<p><small>Date & Time: Fri, Feb 04, 2022, 14:08:35 EST Position: +037.294419° / -080.374030° (±39.9M) Altitude: 1009M (±62.2M) Datum: WGS-84 Azimuth/Bearing: 110° S49E 1500mils True (±12°) Elevation Grade: +000 Horizon Grade: +000 Zoom: 1.0X 11720+00</small></p> 		<p><small>Date & Time: Fri, Feb 04, 2022, 14:08:35 EST Position: +037.294419° / -080.374030° (±39.9M) Altitude: 1009M (±62.2M) Datum: WGS-84 Azimuth/Bearing: 110° S49E 1500mils True (±12°) Elevation Grade: +000 Horizon Grade: +000 Zoom: 1.0X 11741+50</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11720+00	Field Station#	11741+50		
Pic 7 Desc.	CFS triple stack perimeter control in place	Pic 8 Desc.	Stream buffer in place		
<p><small>Date & Time: Fri, Feb 04, 2022, 16:26:37 EST Position: +037.294419° / -080.374030° (±39.9M) Altitude: 1009M (±62.2M) Datum: WGS-84 Azimuth/Bearing: 110° S49E 1500mils True (±12°) Elevation Grade: +000 Horizon Grade: +000 Zoom: 1.0X 11749+00</small></p> 		<p><small>Date & Time: Fri, Feb 04, 2022, 16:40:02 EST Position: +037.294597° / -080.387975° (±11.0M) Altitude: 1196M (±13.1M) Datum: WGS-84 Azimuth/Bearing: 111° S49E 1500mils True (±12°) Elevation Grade: +027 Horizon Grade: +003 Zoom: 1.0X 11766+25</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11749+00	Field Station#	11766+25		
Pic 9 Desc.	CFS triple stack end treatments in place	Pic 10 Desc.	RCE in place		
<p><small>Date & Time: Fri, Feb 04, 2022, 11:04:13 EST Position: +037.294407° / -080.363942° (±12.1M) Altitude: 2099M (±26.2M) Datum: WGS-84 Azimuth/Bearing: 229° S49W 4071mils True (±12°) Elevation Grade: +024 Horizon Grade: +010 Zoom: 1.0X 11775+00</small></p> 		<p><small>Date & Time: Fri, Feb 04, 2022, 12:42:00 EST Position: +037.294614° / -080.364330° (±12.3M) Altitude: 2123M (±15.3M) Datum: WGS-84 Azimuth/Bearing: 233° S49W 5081mils True (±12°) Elevation Grade: +020 Horizon Grade: +004 Zoom: 1.0X 11782+00</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11775+00	Field Station#	11782+00		
Pic 11 Desc.	Supersilt fence perimeter control in place	Pic 12 Desc.	Cleanwater drainage feature in place		

A/E	124300137	Date/Time	2/4/2022 12:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	34013
Inspector	Eric Hanlon			Date/Time	2/4/2022 7:24 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	47.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/4/2022 7:24 AM	Report #	34013
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 26. No compliance issues noted. Observance: Yard 26 has reduced activity during the winter curtailment. Perimeter controls in place & functioning as designed. RCE was clean, no mud or other debris on road. Secondary containment in place & functional as designed. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/4/2022 7:24 AM	Report #	
Pictures					
 <p>Date & Time: Fri, Feb 04, 2022, 06:50:53 EST Position: +489.316628° / +88.65792° (±1.5m) Altitude: 1790' (±1.3m) Datum: WGS-84 Azimuth/Heading: 331° 331W 430mils True (±10°) Elevation Angle: +8.3° Horizon Angle: +81.4° Zoom: 1.0X Y26</p>		 <p>Date & Time: Fri, Feb 04, 2022, 06:50:53 EST Position: +489.316628° / +88.65792° (±1.5m) Altitude: 1790' (±1.3m) Datum: WGS-84 Azimuth/Heading: 331° 331W 430mils True (±10°) Elevation Angle: +8.3° Horizon Angle: +81.4° Zoom: 1.0X Y26</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	RCE functional	Pic 2 Desc.	CFS perimeter controls functional		
 <p>Date & Time: Fri, Feb 04, 2022, 06:50:53 EST Position: +489.316628° / +88.65792° (±1.5m) Altitude: 1790' (±1.3m) Datum: WGS-84 Azimuth/Heading: 331° 331W 430mils True (±10°) Elevation Angle: +8.3° Horizon Angle: +81.4° Zoom: 1.0X Y26</p>		 <p>Date & Time: Fri, Feb 04, 2022, 06:50:53 EST Position: +489.316628° / +88.65792° (±1.5m) Altitude: 1790' (±1.3m) Datum: WGS-84 Azimuth/Heading: 331° 331W 430mils True (±10°) Elevation Angle: +8.3° Horizon Angle: +81.4° Zoom: 1.0X Y26</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	Housekeeping in good condition	Pic 4 Desc.	Secondary containment in place		
 <p>Date & Time: Fri, Feb 04, 2022, 06:50:53 EST Position: +489.316628° / +88.65792° (±1.5m) Altitude: 1790' (±1.3m) Datum: WGS-84 Azimuth/Heading: 331° 331W 430mils True (±10°) Elevation Angle: +8.3° Horizon Angle: +81.4° Zoom: 1.0X Y26</p>		 <p>Date & Time: Fri, Feb 04, 2022, 06:50:53 EST Position: +489.316628° / +88.65792° (±1.5m) Altitude: 1790' (±1.3m) Datum: WGS-84 Azimuth/Heading: 331° 331W 430mils True (±10°) Elevation Angle: +8.3° Horizon Angle: +81.4° Zoom: 1.0X Y26</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	Secondary containment in place	Pic 6 Desc.	CFS perimeter controls functional		

A/E	124300137	Date/Time	2/4/2022 7:24 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	2/4/2022 7:24 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	34034
Inspector	Eric Hanlon			Date/Time	2/4/2022 2:24 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	40.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.65
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	2/4/2022 2:24 PM	Report #	34034
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 28 No compliance issues noted. Observance: Yard 28 has reduced activity during the winter curtailment. Aged Perimeter controls have been replaced & functioning as designed. RCE was clean, no mud or other debris on road. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/4/2022 2:24 PM	Report #	
Pictures					
 <p>Date & Time: Fri, Feb 04, 2022, 06:01:23 EST Position: +48° 29' 24.92" / -90.93371° (-90.93) Altitude: 18470 (-11.50) Datum: WGS-84 Admbr/Bearing: 165° 28' 33" (304m True (-10°) Elevation Angle: -35.1° Horizon Angle: -00.0° Zoom: 1.0X Y28</p>		 <p>Date & Time: Fri, Feb 04, 2022, 06:01:11 EST Position: +48° 29' 24.92" / -90.93371° (-90.93) Altitude: 18470 (-11.50) Datum: WGS-84 Admbr/Bearing: 165° 28' 33" (304m True (-10°) Elevation Angle: -35.1° Horizon Angle: -00.0° Zoom: 1.0X Y28</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	AR in good condition	Pic 2 Desc.	CFS perimeter controls in place		
 <p>Date & Time: Fri, Feb 04, 2022, 06:00:57 EST Position: +48° 29' 24.92" / -90.93371° (-90.93) Altitude: 18470 (-11.50) Datum: WGS-84 Admbr/Bearing: 165° 28' 33" (304m True (-10°) Elevation Angle: -35.1° Horizon Angle: -00.0° Zoom: 1.0X Y28</p>		 <p>Date & Time: Fri, Feb 04, 2022, 06:00:57 EST Position: +48° 29' 24.92" / -90.93371° (-90.93) Altitude: 18470 (-11.50) Datum: WGS-84 Admbr/Bearing: 165° 28' 33" (304m True (-10°) Elevation Angle: -35.1° Horizon Angle: -00.0° Zoom: 1.0X Y28</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	CFS perimeter controls in place	Pic 4 Desc.	Housekeeping in good condition		
 <p>Date & Time: Fri, Feb 04, 2022, 06:00:57 EST Position: +48° 29' 24.92" / -90.93371° (-90.93) Altitude: 18470 (-11.50) Datum: WGS-84 Admbr/Bearing: 165° 28' 33" (304m True (-10°) Elevation Angle: -35.1° Horizon Angle: -00.0° Zoom: 1.0X Y28</p>		 <p>Date & Time: Fri, Feb 04, 2022, 06:00:57 EST Position: +48° 29' 24.92" / -90.93371° (-90.93) Altitude: 18470 (-11.50) Datum: WGS-84 Admbr/Bearing: 165° 28' 33" (304m True (-10°) Elevation Angle: -35.1° Horizon Angle: -00.0° Zoom: 1.0X Y28</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	CFS perimeter controls functional	Pic 6 Desc.	RCE functional		

AFE	124300137	Date/Time	2/4/2022 2:24 PM	Report #	
Pictures					
				Insert image here	
GPS Location	See photo	GPS Location			
Field Station#	12005+00	Field Station#			
Pic 7 Desc.	CFS perimeter & safety fence in place	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	2/4/2022 2:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		