



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34636
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/21/2022 7:29 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11471+56
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+16
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	57.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/21/2022 7:29 AM	<b>Report #</b>	34636
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 217.26 (11471+56) and MP 218.26 (11524+16). Fellow EI Jared Saunders accompanied during inspection. This section of RoW has no current construction. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed AR 258.02 and Steele Acres. PPL crews were performing maintenance to controls and stabilizing the RoW in this area.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/21/2022 7:29 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11524+16	<b>Field Station#</b>	11472+50		
<b>Pic 1 Desc.</b>	S-QQ2 along AR 258.02.		<b>Pic 2 Desc.</b>	Karst feature protection functional.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11487+00	<b>Field Station#</b>	11498+00		
<b>Pic 3 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	Crimping in straw.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11502+00	<b>Field Station#</b>	11505+50		
<b>Pic 5 Desc.</b>	PPL crews performing maintenance.		<b>Pic 6 Desc.</b>	Plunge pool functional.	

<b>AFE</b>	124300137	<b>Date/Time</b>	2/21/2022 7:29 AM	<b>Report #</b>	
<b>Pictures</b>					
<small>           Date &amp; Time: Mon, Feb 21, 2022, 08:47:41 EST            Position: 1540860 190 E / 367881 536 N (+15.5ft)            Altitude: 2221ft (+11.1ft)            Datum: WGS-84            Azimuth/Bearing: 117° S63E 2080mils True (+12°)            Elevation Angle: -00.6°            Horizon Angle: +00.2°            Zoom: 0.5X            11507+78.5-PP3         </small> 				<small>           Date &amp; Time: Mon, Feb 21, 2022, 08:50:47 EST            Position: 1540808 177 E / 367910 774 N (+11.6ft)            Altitude: 2269ft (+9.8ft)            Datum: WGS-84            Azimuth/Bearing: 069° N69E 1227mils True (+12°)            Elevation Angle: +01.2°            Horizon Angle: -01.4°            Zoom: 0.5X            11518+32.5-PP4         </small> 	
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	11507+78	<b>Field Station#</b>	11518+32		
<b>Pic 7 Desc.</b>	S-PP3.	<b>Pic 8 Desc.</b>	Overview S-PP4.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/21/2022 7:29 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34639
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/21/2022 7:48 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	30.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sediment Filter Log	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	2/21/2022 7:48 AM	<b>Report #</b>	34639
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to 219.70) No Deficiencies noted: The ROW from 258.02 to the JNF Forest has been fully restored. Permanent waterbars(other) and level spreaders are installed as per the approved plan and are functioning as designed. No maintenance is needed; Vegetation growth is currently acceptable. The Forest has been temporarily stabilized Observed: The aged P1 on the JNF from the top of the Mtn down to Craig Creek road has been replaced. The restored area is in good shape and the vegetation is sufficient. The environmental controls in the forest are aged, but functional. The ECDs at WBs, S-PP 20,21,22 are new and in good shape. No construction being performed in the area. RCE's functional, highway at Craig Creek station 11600+01, was clean and free of any loose rock. LOD ECDs were in place and functional. Water bars have been installed to specifications. The ROW ground is frozen but in stable condition. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/21/2022 7:48 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Feb 21, 2022 07:48:44 EST  Position: +037.912557° / +080.419987° (s:11.21)  Altitude: 2328ft (s:39.4ft)  Datum: WGS-84  Azimuth Bearing: 272° N35W 4836mils True (±12°)  Elevation Angle: +15.9°  Horizon Angle: +08.8°  Zoom: 1.0X  11526+00</p> 		<p>Date &amp; Time: Mon, Feb 21, 2022 07:48:44 EST  Position: +037.912557° / +080.419987° (s:11.21)  Altitude: 2328ft (s:39.4ft)  Datum: WGS-84  Azimuth Bearing: 272° N35W 4836mils True (±12°)  Elevation Angle: +15.9°  Horizon Angle: +08.8°  Zoom: 1.0X  11526+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11526+00		<b>Field Station#</b>	11528+00	
<b>Pic 1 Desc.</b>	Drainage feature functional		<b>Pic 2 Desc.</b>	Permanent water bars & level spreader in place	
<p>Date &amp; Time: Mon, Feb 21, 2022 08:01:19 EST  Position: +037.912557° / +080.419987° (s:11.21)  Altitude: 2328ft (s:39.4ft)  Datum: WGS-84  Azimuth Bearing: 145° S35E 2578mils True (±12°)  Elevation Angle: +05.4°  Horizon Angle: +01.2°  Zoom: 1.0X  11531+00</p> 		<p>Date &amp; Time: Mon, Feb 21, 2022 08:01:19 EST  Position: +037.912557° / +080.419987° (s:11.21)  Altitude: 2328ft (s:39.4ft)  Datum: WGS-84  Azimuth Bearing: 145° S35E 2578mils True (±12°)  Elevation Angle: +05.4°  Horizon Angle: +01.2°  Zoom: 1.0X  11531+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11531+00		<b>Field Station#</b>	11600+01	
<b>Pic 3 Desc.</b>	CFS perimeter controls functional		<b>Pic 4 Desc.</b>	Culvert functional	
<p>Date &amp; Time: Mon, Feb 21, 2022 08:50:44 EST  Position: +037.912557° / +080.427882° (s:15.1ft)  Altitude: 2331ft (s:39.7ft)  Datum: WGS-84  Azimuth Bearing: 152° S35E 2738mils True (±12°)  Elevation Angle: +02.9°  Horizon Angle: +02.1°  Zoom: 1.0X  11592+00</p> 		<p>Date &amp; Time: Mon, Feb 21, 2022 08:50:44 EST  Position: +037.912557° / +080.427882° (s:15.1ft)  Altitude: 2331ft (s:39.7ft)  Datum: WGS-84  Azimuth Bearing: 152° S35E 2738mils True (±12°)  Elevation Angle: +02.9°  Horizon Angle: +02.1°  Zoom: 1.0X  11592+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11592+00		<b>Field Station#</b>	11588+00	
<b>Pic 5 Desc.</b>	Water bars in place		<b>Pic 6 Desc.</b>	Wattles in place	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/21/2022 7:48 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p> <small> Date &amp; Time: Mon, Feb 21, 2022, 09:45:53 EST  Position: -027.517343, 41.580209543, 11585.00  Altitude: 2096ft (+1120)  Datum: WGS-84  Azimuth: Bearing: 168° S12E 298ft mls True (+19)  Elevation Angle: +11.5°  Horizon Angle: +02.6°  Zoom: 2.0X  11585+00 </small> </p>				 <p> <small> Date &amp; Time: Mon, Feb 21, 2022, 09:45:53 EST  Position: -027.517343, 41.580209543, 11585.00  Altitude: 2096ft (+1120)  Datum: WGS-84  Azimuth: Bearing: 168° S12E 298ft mls True (+19)  Elevation Angle: +11.5°  Horizon Angle: +02.6°  Zoom: 2.0X  11585+00 </small> </p>	
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11585+00	<b>Field Station#</b>	11585+00		
<b>Pic 7 Desc.</b>	Resource buffers in place	<b>Pic 8 Desc.</b>	ET in place		
 <p> <small> Date &amp; Time: Mon, Feb 21, 2022, 09:45:20 EST  Position: -027.517343, 41.580209543, 11582.00  Altitude: 2096ft (+1120)  Datum: WGS-84  Azimuth: Bearing: 168° S12E 298ft mls True (+19)  Elevation Angle: +11.5°  Horizon Angle: +02.6°  Zoom: 2.0X  11582+00 </small> </p>				Insert image here	
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	11582+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Temporary stabilization in place	<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	2/21/2022 7:48 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34645
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	2/21/2022 11:37 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	24.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Sump Pit	Communication			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/21/2022 11:37 AM	<b>Report #</b>	34645
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>           Performed Virginia SWPP inspection from station # 11254+99-11353+67 (MP 213.6-215.04) Rte 42 - Old Furnace, with El, Daniel Fortune            One deficiency found today.            Station 11351+00, Sump liner needs repaired.            Observances:            The ROW is damp.            The ROW received no precipitation over the last 24 hours.            The ROW has been temporarily stabilized.            There are areas of ditch subsidence at station 11333+00 and station 11348+00.            Karst areas have occurred in sumps at station 11348+00 areas are protected with ECDs.            The water bars and compost sock are in good condition.            Steep slopes have had erosion control fabric placed on them. Vegetation is sufficient.            Slope drains are functioning as designed. ECs at streams are in compliance.            No trash on the ROW.            No sensitive resources were impacted.            All perimeter controls, ECDs and BMPs, with the exception of any deficiencies noted were functional at time of inspection.            No other crews were working in the area. Rock Road approaches are clean and free of loose rock.         </p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/21/2022 11:37 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11351+00		<b>Field Station#</b>	11258+00	
<b>Pic 1 Desc.</b>	Sump liner needs repaired		<b>Pic 2 Desc.</b>	Erosion blanket, sump	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11268+00		<b>Field Station#</b>	11289+00	
<b>Pic 3 Desc.</b>	Slope drain, stabilized ROW		<b>Pic 4 Desc.</b>	Erosion blanket, perimeter ECDs in sensitive area	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11293+00		<b>Field Station#</b>	11297+89	
<b>Pic 5 Desc.</b>	S-MM 18		<b>Pic 6 Desc.</b>	AR seven Oaks	



AFE	124300137	Date/Time	2/21/2022 11:37 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	see photo	
Field Station#	11316+00		Field Station#	11328+00	
Pic 7 Desc.	Perimeter ECDs in sensitive area		Pic 8 Desc.	S-NN 12	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	11333+00		Field Station#	11348+00	
Pic 9 Desc.	Ditch subsidence		Pic 10 Desc.	Ditch subsidence	
		<div>Insert image here</div>			
GPS Location	see photo		GPS Location		
Field Station#	11354+00		Field Station#		
Pic 11 Desc.	S-NN 11		Pic 12 Desc.		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/21/2022 11:37 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34659
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/21/2022 4:09 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11471+56
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	43.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/21/2022 4:09 PM	<b>Report #</b>	34659
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11353+67 (Old Furnace) to ST# 11471+56 (Steele Acres) MP 215.04 to MP 217.26 Accompanied on inspection by fellow EI Clint Sears. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. ST# 11353+67 to ST# 11367+00 and ST# 11443+50 to ST# 11471+56 have undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Triple protection ECDs are in place at karst feature. Final restoration has occurred between ST# 11367+00 and ST# 11443+50. CFS perimeter controls, end treatments and temporary waterbars are in place. Permanent waterbars(section 6-other) with level spreaders are in place. Sensitive resource buffers are in place at stream crossings S-KL43, S-0014, S-0013, S-0012, and S-CD14. AR-256 and 258.01 RCEs are maintained in acceptable condition. The ROW is frozen and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/21/2022 4:09 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11353+50	<b>Field Station#</b>	11363+00		
<b>Pic 1 Desc.</b>	RCE in place	<b>Pic 2 Desc.</b>	End treatments in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11397+00	<b>Field Station#</b>	11410+00		
<b>Pic 3 Desc.</b>	Level spreader in place	<b>Pic 4 Desc.</b>	CFS temporary waterbars in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11432+00	<b>Field Station#</b>	11437+00		
<b>Pic 5 Desc.</b>	Permanent waterbar in place	<b>Pic 6 Desc.</b>	Permanent vegetation present		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/21/2022 4:09 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11448+00	<b>Field Station#</b>	11452+00		
<b>Pic 7 Desc.</b>	Cleanwater diversion berm in place	<b>Pic 8 Desc.</b>	Stream buffer in place		
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11457+00	<b>Field Station#</b>	11461+00		
<b>Pic 9 Desc.</b>	Stone inlet protection in place	<b>Pic 10 Desc.</b>	CFS perimeter control in place		
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11466+00	<b>Field Station#</b>	11469+00		
<b>Pic 11 Desc.</b>	Plunge pool in place	<b>Pic 12 Desc.</b>	Triple protection ECDs in place at karst feature		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/21/2022 4:09 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34681
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/22/2022 7:15 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+89
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	58.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			


## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 7:15 AM	<b>Report #</b>	34681
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection, from MP 223.27 (11788+52) and MP 225.37 (11899+89). Fellow EI Jared Saunders accompanied during SWPPP inspection. This section of RoW has no current construction. Temporary controls within this area are currently being removed by PPL crews. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed AR 266.03. Section 6- Waterbars (other). Inspection performed during ongoing rain event.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 7:15 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11899+00	<b>Field Station#</b>	11887+00		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11876+00	<b>Field Station#</b>	11863+65		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.	<b>Pic 4 Desc.</b>	P-KL2.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11855+50	<b>Field Station#</b>	11848+00		
<b>Pic 5 Desc.</b>	Representative photo of permanent waterbar and level spreaders installed.	<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.		

<b>AFE</b>	124300137	<b>Date/Time</b>	2/22/2022 7:15 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	7		<b>GPS Location</b>	8	
<b>Field Station#</b>	11833+50		<b>Field Station#</b>	11819+00	
<b>Pic 7 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 8 Desc.</b>	Section of restored RoW showing conditions and controls.	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 7:15 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34734
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	2/22/2022 4:53 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+89
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	48.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 4:53 PM	<b>Report #</b>	34734
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>See photos for GPS coordinates.</p> <p>Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). No Deficiencies documented for repairs today.</p> <p>This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time. Permanent water bars have been installed and appear to be functioning as intended. (Other)</p> <p>Level Spreaders appear to be functional</p> <p>Precision Crews: (1710) Has been in the area replacing P1 perimeter silt fencing between 11940+00 to near 11961+00</p> <p>All other perimeter controls, ECDs and BMPs are weathered but appear to be functional at time of inspection. Vegetation or stabilization sufficient.</p> <p>No impact to sensitive resources observed. Assessed Ar 266.03</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	2/22/2022 4:53 PM	Report #	
Pictures					
					
<b>GPS Location</b>		See Photo		<b>GPS Location</b>	
<b>Field Station#</b>		11978+86		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Perimeter ECDs near AR 266		<b>Pic 2 Desc.</b>	
					
<b>GPS Location</b>		See Photo		<b>GPS Location</b>	
<b>Field Station#</b>		11972+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Final Restoration Area		<b>Pic 4 Desc.</b>	
					
<b>GPS Location</b>		See Photo		<b>GPS Location</b>	
<b>Field Station#</b>		11945+78		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Final Restoration Area. Vegetated water bar conditions		<b>Pic 6 Desc.</b>	
				Super silt fence and CFS along downslope side perimeter. Possible karst area off LOD	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/22/2022 4:53 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 09:55:38 EST Position: +437.28036° / -68.07619° (±14.51) Altitude: 2272ft (±7.81) Datum: WGS-84 Azimuth/Bearing: 147° 53'E 2613mils True (±14°) Elevation Angle: -23.5° Horizon Angle: +03.5° Zoom: 1.0X 11936+00 Spread G</small></p>		 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 09:56:11 EST Position: +437.28036° / -68.07619° (±14.51) Altitude: 2269ft (±7.81) Datum: WGS-84 Azimuth/Bearing: 67° 51'E 3004mils True (±15°) Elevation Angle: -04.1° Horizon Angle: -01.4° Zoom: 1.0X 11923+00 Spread G</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11936+00	<b>Field Station#</b>	11923+00		
<b>Pic 7 Desc.</b>	Final Restoration Area	<b>Pic 8 Desc.</b>	Level spreader condition		
 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 09:57:49 EST Position: +400.20938° / -68.07717° (±14.44) Altitude: 2284ft (±7.81) Datum: WGS-84 Azimuth/Bearing: 097° 53'E 1724mils True (±106°) Elevation Angle: -14.3° Horizon Angle: +00.7° Zoom: 1.0X 11916+00 Spread G</small></p>		 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 09:58:48 EST Position: +407.28538° / -68.07642° (±14.41) Altitude: 2281ft (±7.81) Datum: WGS-84 Azimuth/Bearing: 83° 30'E 1690mils True (±128°) Elevation Angle: -34.0° Horizon Angle: -00.4° Zoom: 1.0X 11900+81 Spread G</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11916+00	<b>Field Station#</b>	11900+81		
<b>Pic 9 Desc.</b>	Additional repairs to P1 silt fencing	<b>Pic 10 Desc.</b>	Permanent vegetation in final Restoration Area		
 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 09:16:04 EST Position: +487.28575° / -68.07133° (±13.51) Altitude: 183ft (±3.51) Datum: WGS-84 Azimuth/Bearing: 327° 23'W 879mils True (±10°) Elevation Grade: +011% Horizon Grade: +001% Zoom: 0.5X 12005+00</small></p>		 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 09:16:48 EST Position: +487.28575° / -68.07133° (±13.51) Altitude: 183ft (±3.51) Datum: WGS-84 Azimuth/Bearing: 327° 23'W 879mils True (±10°) Elevation Grade: +011% Horizon Grade: +001% Zoom: 4.0X 12000+00</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12000+00		
<b>Pic 11 Desc.</b>	Temporary stabilization of row at spread break.	<b>Pic 12 Desc.</b>	Temporary stabilization of row near spread break.		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 4:53 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34699
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/22/2022 12:30 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 12:30 PM	<b>Report #</b>	34699
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 28 No compliance issues noted. Observance: Yard 28 has reduced activity during the winter curtailment. Aged Perimeter controls have been replaced & functioning as designed. RCE was clean, no mud or other debris on road. All other ECDs and BMPs functional at time of inspection. Light rain at the time of inspection. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	2/22/2022 12:30 PM	Report #	
Pictures					
 <p>Date &amp; Time Tue Feb 22 2022 12:30 PM EST Position: +027.336110° / -030.803123° (+10.0m) Altitude: 1565ft (+11.0m) Datum: WGS-84 Azimuth/Bearing: 267° 53'W 263mils True (+10°) Elevation Angle: -03.9° Horizon Angle: -02.4° Zoom: 1.0x FPS: 28</p>		 <p>Date &amp; Time Tue Feb 22 2022 12:30 PM EST Position: +027.336110° / -030.803123° (+10.0m) Altitude: 1565ft (+11.0m) Datum: WGS-84 Azimuth/Bearing: 267° 53'W 263mils True (+10°) Elevation Angle: -03.9° Horizon Angle: -02.4° Zoom: 1.0x FPS: 28</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	RCE functional Permanent vegetation in good condition	Pic 2 Desc.	CFS perimeter controls functional		
 <p>Date &amp; Time Tue Feb 22 2022 12:30 PM EST Position: +027.336110° / -030.803123° (+10.0m) Altitude: 1565ft (+11.0m) Datum: WGS-84 Azimuth/Bearing: 137° 24'W 243mils True (+10°) Elevation Angle: -07.5° Horizon Angle: -03.1° Zoom: 1.0x FPS: 28</p>		 <p>Date &amp; Time Tue Feb 22 2022 12:30 PM EST Position: +027.336110° / -030.803123° (+10.0m) Altitude: 1565ft (+11.0m) Datum: WGS-84 Azimuth/Bearing: 137° 24'W 243mils True (+10°) Elevation Angle: -07.5° Horizon Angle: -03.1° Zoom: 1.0x FPS: 28</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	Housekeeping in good condition	Pic 4 Desc.	CFS perimeter controls in place		
 <p>Date &amp; Time Tue Feb 22 2022 12:30 PM EST Position: +027.336110° / -030.803123° (+10.0m) Altitude: 1565ft (+11.0m) Datum: WGS-84 Azimuth/Bearing: 267° 53'W 263mils True (+10°) Elevation Angle: -03.9° Horizon Angle: -02.4° Zoom: 1.0x FPS: 28</p>		 <p>Date &amp; Time Tue Feb 22 2022 12:30 PM EST Position: +027.336110° / -030.803123° (+10.0m) Altitude: 1565ft (+11.0m) Datum: WGS-84 Azimuth/Bearing: 009° N09E 0160mils True (+10°) Elevation Angle: -13.0° Horizon Angle: -01.0° Zoom: 1.0x FPS: 28</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	CFS perimeter controls in place	Pic 6 Desc.	Permanent vegetation in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 12:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 12:30 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34709
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/22/2022 3:16 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	53.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Stone Inlet Protection	Acceptable			






<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 3:16 PM	<b>Report #</b>	34709
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div style="height: 100px;"></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 (Brush Mt) to ST# 11788+52 (Mt Tabor) MP 221.02 to MP 223.27 Accompanied on inspection by fellow EI Clint Sears. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection are in place where needed. Perimeter controls and waterbars with end treatments are in place. Sensitive resource buffers are in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted. Light rainfall during duration of inspection. Rain gauges to be checked tomorrow 2/23/22.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 3:16 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Feb 22, 2022, 09:16:02 EST  Position: +037.202442° / -086.294501° (±12.1m)  Altitude: 2037ft (±19.3ft)  Datum: WGS-84  Azimuth/Bearing: 180° S00W 304mils True (±12°)  Elevation Grade: -017%  Horizontal Grade: +000%  Zoom: 1.0x  11670+00</p> 		<p>Date &amp; Time: Tue, Feb 22, 2022, 09:16:02 EST  Position: +037.201674° / -086.293310° (±12.6m)  Altitude: 2009ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 177° S01E 316mils True (±12°)  Elevation Grade: -022%  Horizontal Grade: +000%  Zoom: 1.0x  11677+50</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11670+00	<b>Field Station#</b>	11677+50		
<b>Pic 1 Desc.</b>	P1 silt fence perimeter control in place	<b>Pic 2 Desc.</b>	End treatments in place		
<p>Date &amp; Time: Tue, Feb 22, 2022, 09:22:07 EST  Position: +037.229996° / -086.302403° (±12.3m)  Altitude: 2523ft (±19.4ft)  Datum: WGS-84  Azimuth/Bearing: 074° N74E 1316mils True (±12°)  Elevation Grade: -050%  Horizontal Grade: +000%  Zoom: 1.0x  11682+00</p> 		<p>Date &amp; Time: Tue, Feb 22, 2022, 09:23:07 EST  Position: +037.2299510° / -086.301459° (±25.8m)  Altitude: 2570ft (±19.4ft)  Datum: WGS-84  Azimuth/Bearing: 177° S01E 300mils True (±12°)  Elevation Grade: -000%  Horizontal Grade: +000%  Zoom: 1.0x  11688+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11682+00	<b>Field Station#</b>	11688+00		
<b>Pic 3 Desc.</b>	Stone inlet protection in place	<b>Pic 4 Desc.</b>	Erosion control blanket in place		
<p>Date &amp; Time: Tue, Feb 22, 2022, 09:32:34 EST  Position: +037.240715° / -086.304797° (±24.2ft)  Altitude: ±1110±105.0m  Datum: WGS-84  Azimuth/Bearing: 302° N80W 536mils True (±12°)  Elevation Grade: -61%  Horizontal Grade: +000%  Zoom: 1.0x  11704+75</p> 		<p>Date &amp; Time: Tue, Feb 22, 2022, 09:34:01 EST  Position: +037.2410990° / -086.304007° (±12.1m)  Altitude: 2554ft (±19.3ft)  Datum: WGS-84  Azimuth/Bearing: 177° S03E 2613mils True (±12°)  Elevation Grade: -020%  Horizontal Grade: +000%  Zoom: 1.0x  11714+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11704+75	<b>Field Station#</b>	11714+00		
<b>Pic 5 Desc.</b>	Sediment filter logs in place	<b>Pic 6 Desc.</b>	Waterbars in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/22/2022 3:16 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11720+00	<b>Field Station#</b>	11741+00		
<b>Pic 7 Desc.</b>	CFS perimeter control in place	<b>Pic 8 Desc.</b>	Stream buffer in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11749+00	<b>Field Station#</b>	11759+00		
<b>Pic 9 Desc.</b>	End treatments in place	<b>Pic 10 Desc.</b>	Supersilt fence perimeter control in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11766+25	<b>Field Station#</b>	11782+50		
<b>Pic 11 Desc.</b>	RCE in place	<b>Pic 12 Desc.</b>	Cleanwater drainage feature in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 3:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34688
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	2/22/2022 10:23 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 10:23 AM	<b>Report #</b>	34688
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>           Performed VA SWPP at Yard 29.            Yard 29 was receiving a light rain at the time of inspection. No accumulation.            No deficiencies found.            Observances:            The Perimeter controls had been upgraded from a single row of 18" compost sock to a triple stack since last inspection.            No activity in the Yard.            Equipment in the yard was free of leaks.            The perimeter compost sock was in place and functioning as designed. The rock road approach was clean, no mud or other debris on road.            The yard was free of debris. No trash was seen.            Trash receptacles in the Yard were clearly labeled.            Temporary stabilization was sufficient.         </p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/22/2022 10:23 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>           Date &amp; Time: Tue, Feb 22, 2022, 10:45:44 EST            Position: +037.240277° / -083.403777° (±14.4m)            Altitude: 1711ft (±19.7ft)            Datum: WGS-84            Azimuth/Bearing: 329° S83W 488mils True (±10°)            Elevation Angle: -03.5°            Horizon Angle: -01.7°            Zoom: 1.0X            Yard 29: 12005+00            Spread G         </p>		 <p>           Date &amp; Time: Tue, Feb 22, 2022, 10:45:54 EST            Position: +037.240277° / -083.403777° (±14.4m)            Altitude: 1711ft (±19.7ft)            Datum: WGS-84            Azimuth/Bearing: 243° S83W 467mils True (±10°)            Elevation Angle: -12.1°            Horizon Angle: -01.4°            Zoom: 1.0X            Yard 29: 12005+00            Spread G         </p>		<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00	<b>GPS Location</b>	see photo
<b>Pic 1 Desc.</b>	Waste containers	<b>Pic 2 Desc.</b>	Temporary stabilization	<b>Field Station#</b>	12005+00
 <p>           Date &amp; Time: Tue, Feb 22, 2022, 10:46:11 EST            Position: +037.240277° / -083.403777° (±14.4m)            Altitude: 1698ft (±19.7ft)            Datum: WGS-84            Azimuth/Bearing: 89° S88E 167mils True (±10°)            Elevation Angle: -05.4°            Horizon Angle: -05.4°            Zoom: 1.0X            Yard 29: 12005+00            Spread G         </p>		 <p>           Date &amp; Time: Tue, Feb 22, 2022, 10:46:19 EST            Position: +037.240277° / -083.403777° (±14.4m)            Altitude: 1712ft (±19.7ft)            Datum: WGS-84            Azimuth/Bearing: 340° N20W 404mils True (±10°)            Elevation Angle: -10.2°            Horizon Angle: -01.0°            Zoom: 1.0X            Yard 29: 12005+00            Spread G         </p>		<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00	<b>GPS Location</b>	see photo
<b>Pic 3 Desc.</b>	Yard 29	<b>Pic 4 Desc.</b>	Perimeter controls	<b>Field Station#</b>	12005+00
 <p>           Date &amp; Time: Tue, Feb 22, 2022, 10:46:19 EST            Position: +037.240277° / -083.403777° (±14.4m)            Altitude: 1712ft (±19.7ft)            Datum: WGS-84            Azimuth/Bearing: 340° N20W 404mils True (±10°)            Elevation Angle: -10.2°            Horizon Angle: -01.0°            Zoom: 1.0X            Yard 29: 12005+00            Spread G         </p>		 <p>           Date &amp; Time: Tue, Feb 22, 2022, 10:46:24 EST            Position: +037.240277° / -083.403777° (±14.4m)            Altitude: 1698ft (±19.7ft)            Datum: WGS-84            Azimuth/Bearing: 304° S20W 342mils True (±10°)            Elevation Angle: -02.1°            Horizon Angle: -00.7°            Zoom: 1.0X            Yard 29: 12005+00            Spread G         </p>		<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00	<b>GPS Location</b>	see photo
<b>Pic 5 Desc.</b>	Perimeter controls	<b>Pic 6 Desc.</b>	RCE	<b>Field Station#</b>	12005+00

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 10:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 10:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34696
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	2/22/2022 12:13 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 12:13 PM	<b>Report #</b>	34696
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection was completed on private and JNF lands at Brush Mountain today. The ROW remains stable with appropriate ECDs installed. Existing vegetation and/or mulch is preventing erosion from occurring. Resource buffers are stable. Perimeter ECDs are in place with no maintenance needs identified. Slope breakers, sumps and end treatments are in acceptable condition.</p> <p>Note. All CFS will be replaced and other ECD enhancements will be completed before construction earth disturbance occurs. It would not be advisable at this time due to current stable conditions.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	2/22/2022 12:13 PM	Report #	
Pictures					
GPS Location	On photo		GPS Location	On photo	
Field Station#	11663+00		Field Station#	11662+00	
Pic 1 Desc.	Perimeter ECDs are in acceptable condition.		Pic 2 Desc.	Perimeter ECD in place. Slope breakers functional.	
GPS Location	On photo		GPS Location	On photo	
Field Station#	11661+00		Field Station#	11657+00	
Pic 3 Desc.	Perimeter ECDs are in place. ROW is stable.		Pic 4 Desc.	Perimeter ECDs are in place. ROW surface is stable.	
GPS Location	On photo		GPS Location	On photo	
Field Station#	11649+00		Field Station#	11648+00	
Pic 5 Desc.	Sumps and end treatments functional.		Pic 6 Desc.	Erosion matting has been replaced on two-tone area.	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/22/2022 12:13 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 10:51:14 EST Position: +037.314017, -080.398511 (+30.0m) Altitude: 597m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 92.1° N33W 3573mils Magnetic (+12°) Elevation Angle: -15.0° Horizon Angle: +01.6° Zoom: 1.0X S-HH18</small></p>		 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 10:58:58 EST Position: +037.313426, -080.392263 (+30.0m) Altitude: 591m (+12.0m) Datum: WGS-84 Azimuth/Bearing: 99.0° S16E 1600mils Magnetic (+12°) Elevation Angle: -11.6° Horizon Angle: +00.3° Zoom: 1.0X S-RR14</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+20		
<b>Pic 7 Desc.</b>	The S-HH18 crossing is stable.	<b>Pic 8 Desc.</b>	The S-RR14 crossing is stable.		
 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 11:10:40 EST Position: +037.313199, -080.404535 (+30.0m) Altitude: 560m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 201° S21W 3573mils Magnetic (+12°) Elevation Angle: -08.3° Horizon Angle: +01.9° Zoom: 1.0X S-006</small></p>		 <p><small>Date &amp; Time: Tue, Feb 22, 2022, 07:49:57 EST Position: +037.314560, -080.202624 (+30.0m) Altitude: 589m (+12.0m) Datum: WGS-84 Azimuth/Bearing: 201° S21W 3573mils Magnetic (+12°) Elevation Angle: -15.0° Horizon Angle: +01.9° Zoom: 1.0X S-RR13 at MN-258.04</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11608+17	<b>Field Station#</b>	11613+69		
<b>Pic 9 Desc.</b>	The S-006 crossing is stable.	<b>Pic 10 Desc.</b>	S-RR13 crossing on access road MN-258.04 is in acceptable condition.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 12:13 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34682
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/22/2022 7:23 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Berm	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			


## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 7:23 AM	<b>Report #</b>	34682
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 26. No compliance issues noted. Observance: Yard 26 has reduced activity during the winter curtailment. Perimeter controls in place & functioning as designed. RCE was clean, no mud or other debris on road. Secondary containment in place & functional as designed. All other ECDs and BMPs functional at time of inspection. Light rain at the time of inspections. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/22/2022 7:23 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	CFS perimeter controls functional	<b>Pic 2 Desc.</b>	RCE and CFS perimeter controls functional		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	Housekeeping in good condition	<b>Pic 4 Desc.</b>	Secondary containment in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	Secondary containment in place	<b>Pic 6 Desc.</b>	Perimeter triple stack CFS in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 7:23 AM	<b>Report #</b>	
<b>Pictures</b>					
		<p>Insert image here</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	12005+00	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	RCE functional	<b>Pic 8 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
<p>Insert image here</p>		<p>Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/22/2022 7:23 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34761
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	2/23/2022 12:08 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+46
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Communication			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Slope Drain Pipe	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 12:08 PM	<b>Report #</b>	34761
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Performed Virginia SWPP inspection from station # 10859+46-10929+80.(MP 205.67-207.00) Kow Camp gravel to Doe Creek, with El Daniel Fortune.</p> <p>One deficiency found today.</p> <p>10899+00, soil pile needs re-stabilized.</p> <p>Observances:</p> <p>The ROW received 0.80" Of precipitation overnight.</p> <p>ROW conditions are wet. Water bodies were flowing water.</p> <p>There is water standing in multiple locations along ROW, where the ditch line is subsided.</p> <p>Environmental controls at water bodies are in place and functioning as designed.</p> <p>The ROW has been temporarily stabilized. Stabilization of the ROW is an on going process.</p> <p>There are areas of ditch subsidence, from station # 10875+00-10880+00 and 10896+00-10899+00.</p> <p>These areas are being monitored and will need repaired, when conditions allow. Precision has been made aware.</p> <p>Soil piles are stabilized.</p> <p>No trash on the ROW.</p> <p>No sensitive resources were impacted.</p> <p>All perimeter controls, ECDs and BMPs were functional at time of inspection. Rock Road approaches are clean and free of loose rock.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 12:08 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10889+00		<b>Field Station#</b>	10893+00	
<b>Pic 1 Desc.</b>	PL item, soil pile needs restabilized		<b>Pic 2 Desc.</b>	Former PL item, debris removed from sump	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10860+00		<b>Field Station#</b>	10860+00	
<b>Pic 3 Desc.</b>	Open ditch		<b>Pic 4 Desc.</b>	Kow camp RCE	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10874+00		<b>Field Station#</b>	10880+00	
<b>Pic 5 Desc.</b>	Ditch subsidence		<b>Pic 6 Desc.</b>	Ditch subsidence, holding water over ditch line.	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 12:08 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Feb 23, 2022, 09:00:53 EST Position: +037.339283° / -080.597093° (±16.4m) Altitude: 2130ft (±10m) Datum: WGS-84 Azimuth/Bearing: 140° S00E 2459mils True (±13°) Elevation Angle: -02° Horizon Angle: -03.1° Zoom: 1.0X S-A32, 10883+00 Spread G</p>		 <p>Date &amp; Time: Wed, Feb 23, 2022, 09:00:23 EST Position: +037.339281° / -080.597093° (±16.4m) Altitude: 2130ft (±10m) Datum: WGS-84 Azimuth/Bearing: 107° S08E 1908mils True (±13°) Elevation Angle: +09.2° Horizon Angle: -03.1° Zoom: 1.0X Kow Camp, 10885+00 Spread G</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10883+00		<b>Field Station#</b>	10885+00	
<b>Pic 7 Desc.</b>	S-A 32		<b>Pic 8 Desc.</b>	Kow Camp	
 <p>Date &amp; Time: Wed, Feb 23, 2022, 09:02:40 EST Position: +037.339073° / -080.587920° (±16.4m) Altitude: 2586ft (±39.4m) Datum: WGS-84 Azimuth/Bearing: 292° N61W 5316mils True (±14°) Elevation Angle: -02° Horizon Angle: -03.0° Zoom: 1.0X 10904+00 Spread G</p>		 <p>Date &amp; Time: Wed, Feb 23, 2022, 09:42:34 EST Position: +037.332675° / -080.583866° (±16.4m) Altitude: 2212ft (±78.7m) Datum: WGS-84 Azimuth/Bearing: 157° S23E 2707mils True (±108°) Elevation Angle: -01° Horizon Angle: -01.4° Zoom: 1.0X 10924+00 Spread G</p>			
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10904+00		<b>Field Station#</b>	10924+00	
<b>Pic 9 Desc.</b>	Stabilized ROW		<b>Pic 10 Desc.</b>	Water bars, erosion blanket, perimeter ECDs	
 <p>Date &amp; Time: Wed, Feb 23, 2022, 09:45:42 EST Position: +037.330387° / -080.580019° (±16.4m) Altitude: 2137ft (±10m) Datum: WGS-84 Azimuth/Bearing: 180° S00W 3200mils True (±14°) Elevation Angle: -08.4° Horizon Angle: -00.1° Zoom: 1.0X S-Y 3, 10928+00 Spread G</p>		 <p>Date &amp; Time: Wed, Feb 23, 2022, 09:47:24 EST Position: +037.331531° / -080.583191° (±16.4m) Altitude: 2139ft (±10m) Datum: WGS-84 Azimuth/Bearing: 155° S25E 2750mils True (±14°) Elevation Angle: -00.4° Horizon Angle: -01.4° Zoom: 1.0X S-Y 2, Doe Creek RCE, 10929+00 Spread G</p>			
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10928+00		<b>Field Station#</b>	10929+00	
<b>Pic 11 Desc.</b>	S-Y 3		<b>Pic 12 Desc.</b>	S-Y 2 doe creek RCE	



<b>A/E</b>	124300137	<b>Date/Time</b>	2/23/2022 12:08 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34729
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/23/2022 6:18 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10798+92
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 6:18 AM	<b>Report #</b>	34729
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 203.6 (10749+92) to MP 204.53 (10798+92). Accompanied by fellow EI Jared Saunders. Inspection completed during ongoing rain event. This section of RoW has no current construction. No issues were identified. All perimeter controls, ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed. PPL environmental crews were in this area performing maintenance as needed. Updated SWPPP documents.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 6:18 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Feb 23, 2022, 07:41:42 EST Position: 180758.928 N / 375561.100 E (a18.94) Altitude: 2027ft (a11.41) Datum: WGS-84 Azimuth/Bearing: 004° N04E 0071mils True (a13°) Elevation Angle: -15.8° Horizon Angle: -01.1° Zoom: 0.5X 10758+35</p>		 <p>Date &amp; Time: Wed, Feb 23, 2022, 07:44:49 EST Position: 180763.888 N / 375593.592 E (a15.51) Altitude: 2073ft (a11.11) Datum: WGS-84 Azimuth/Bearing: 258° N88W 422mils True (a12°) Elevation Angle: -05.8° Horizon Angle: -01.2° Zoom: 0.5X 10763+25</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	10758+35	<b>Field Station#</b>	10763+25		
<b>Pic 1 Desc.</b>	S-G35.	<b>Pic 2 Desc.</b>	Section of RoW showing conditions and controls.		
 <p>Date &amp; Time: Wed, Feb 23, 2022, 07:46:08 EST Position: 180764.928 N / 375593.592 E (a15.51) Altitude: 2073ft (a11.11) Datum: WGS-84 Azimuth/Bearing: 120° N20E 335mils True (a12°) Elevation Angle: -09.0° Horizon Angle: -03.5° Zoom: 0.5X 10764+95</p>		 <p>Date &amp; Time: Wed, Feb 23, 2022, 07:47:41 EST Position: 180767.208 N / 375611.308 E (a16.51) Altitude: 2179ft (a11.11) Datum: WGS-84 Azimuth/Bearing: 105° S65E 204mils True (a12°) Elevation Angle: -09.5° Horizon Angle: -03.5° Zoom: 0.5X 10767+00</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	10764+95	<b>Field Station#</b>	10767+00		
<b>Pic 3 Desc.</b>	S-SS4.	<b>Pic 4 Desc.</b>	Section of RoW showing conditions and controls.		
 <p>Date &amp; Time: Wed, Feb 23, 2022, 07:49:08 EST Position: 180771.588 N / 375613.519 E (a16.51) Altitude: 2145ft (a11.11) Datum: WGS-84 Azimuth/Bearing: 135° S85W 288mils True (a13°) Elevation Angle: -10.1° Horizon Angle: -02.4° Zoom: 0.5X 10771+75</p>		 <p>Date &amp; Time: Wed, Feb 23, 2022, 07:51:41 EST Position: 180773.208 N / 375623.519 E (a16.51) Altitude: 2145ft (a11.11) Datum: WGS-84 Azimuth/Bearing: 102° N02E 109mils True (a12°) Elevation Angle: -07.2° Horizon Angle: -03.4° Zoom: 0.5X 10773+73</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	10771+75	<b>Field Station#</b>	10773+73		
<b>Pic 5 Desc.</b>	CWDP outlet protection functional.	<b>Pic 6 Desc.</b>	S-Z9.		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 6:18 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	10780+40	<b>Field Station#</b>	10791+25		
<b>Pic 7 Desc.</b>	S-Z7.	<b>Pic 8 Desc.</b>	Section of RoW showing conditions and controls.		
<b>GPS Location</b>	9	<b>GPS Location</b>			
<b>Field Station#</b>	10798+92	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	RCE off of Cascade drive.	<b>Pic 10 Desc.</b>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/23/2022 6:18 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34749
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/23/2022 11:28 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10859+46
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	58.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Stone Inlet Protection	Communication	See comments		
Waterbar End Treatment	Communication	See comments		
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions






Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 11:28 AM	<b>Report #</b>	34749
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10798+92 (Cascade) to ST# 10859+46 (Kow Camp Gravel) MP 204.53 to MP 205.67 Accompanied on inspection by fellow EI Clint Sears. Deficiencies found at the following station numbers: 10811+25 end treatment undermined repair/stabilize 10811+45 inlet overwhelmed needs cleaned out and also being bypassed repair/stabilize 10814+20 end treatment undermined repair/stabilize All issues have been communicated to PPL contractor via punch list. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. Perimeter controls and end treatments are in place. This section of ROW has undergone temporary stabilization. Topsoil piles and cleanwater diversion berms have been stabilized. Sensitive resource buffers are in place at stream crossings S-A33, S-A34, and S-Z14. AR-241.02, 241.03, Cascade Drive, and Kow Camp #2 road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted, Kow Camp rain gauge measured 0.8" of rainfall accumulated on 2/22/22.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 11:28 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed Feb 23, 2022, 10:50:55 EST Position: +407.341748° / -880.618034° (±13.1m) Altitude: 2220ft (±13.1m) Datum: WGS-84 Azimuth/Bearing: 020° N20E 0336mils True (±12°) Elevation Grade: -0631 Horizon Grade: +0100 Zoom: 1.0X 10811+45</p>		 <p>Date &amp; Time: Wed Feb 23, 2022, 10:17:12 EST Position: +407.341748° / -880.618034° (±13.1m) Altitude: 2112ft (±13.1m) Datum: WGS-84 Azimuth/Bearing: 020° N20E 0336mils True (±12°) Elevation Grade: -0631 Horizon Grade: +0100 Zoom: 1.0X 10811+45</p>		<b>GPS Location</b>	See photo
<b>Field Station#</b>	10814+20	<b>Field Station#</b>	10811+45	<b>GPS Location</b>	See photo
<b>Pic 1 Desc.</b>	End treatment undermined	<b>Pic 2 Desc.</b>	Inlet overwhelmed and water bypassing	<b>GPS Location</b>	See photo
 <p>Date &amp; Time: Wed Feb 23, 2022, 10:54:38 EST Position: +407.341748° / -880.618034° (±13.1m) Altitude: 1920ft (±13.1m) Datum: WGS-84 Azimuth/Bearing: 007° N07E 0124mils True (±12°) Elevation Grade: -0002 Horizon Grade: +0002 Zoom: 1.0X 10803+00</p>		 <p>Date &amp; Time: Wed Feb 23, 2022, 10:54:38 EST Position: +407.341748° / -880.618034° (±13.1m) Altitude: 1920ft (±13.1m) Datum: WGS-84 Azimuth/Bearing: 007° N07E 0124mils True (±12°) Elevation Grade: -0002 Horizon Grade: +0002 Zoom: 1.0X 10805+00</p>		<b>GPS Location</b>	See photo
<b>Field Station#</b>	10803+00	<b>Field Station#</b>	10805+00	<b>GPS Location</b>	See photo
<b>Pic 3 Desc.</b>	RCE in place	<b>Pic 4 Desc.</b>	P1 Silt fence in place at sensitive resource	<b>GPS Location</b>	See photo
 <p>Date &amp; Time: Wed Feb 23, 2022, 10:12:49 EST Position: +407.341748° / -880.618034° (±13.1m) Altitude: 1920ft (±13.1m) Datum: WGS-84 Azimuth/Bearing: 012° N12E 0338mils True (±12°) Elevation Grade: -0002 Horizon Grade: +0002 Zoom: 1.0X 10812+00</p>		 <p>Date &amp; Time: Wed Feb 23, 2022, 10:12:49 EST Position: +407.341748° / -880.618034° (±13.1m) Altitude: 2299ft (±13.1m) Datum: WGS-84 Azimuth/Bearing: 278° N82W 4942mils True (±12°) Elevation Grade: -0345 Horizon Grade: -0051 Zoom: 1.0X 10815+00</p>		<b>GPS Location</b>	See photo
<b>Field Station#</b>	10812+00	<b>Field Station#</b>	10815+00	<b>GPS Location</b>	See photo
<b>Pic 5 Desc.</b>	Cleanwater diversion outlet protection in place	<b>Pic 6 Desc.</b>	Erosion control blanket in place	<b>GPS Location</b>	See photo



<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 11:28 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed, Feb 23, 2022, 09:48:30 EST  Position: +437.349281° / -90.61022° (s=0.00)  Altitude: 2458 ft (s=0.00)  Datum: WGS 84  Geotagging: 107° 54' 00" 000mils True (s=0.00)  Camera: 3400x (s=0.00)  Horizon Grade: +005  Zoom: 1.0X  10831+50</p> 		<p>Date &amp; Time: Wed, Feb 23, 2022, 09:53:21 EST  Position: +437.341709° / -90.609943° (s=0.00)  Altitude: 2467 ft (s=19.70)  Datum: WGS 84  Geotagging: 107° 54' 00" 000mils True (s=0.00)  Camera: 3400x (s=0.00)  Horizon Grade: +005  Zoom: 1.0X  10833+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10831+50	<b>Field Station#</b>	10833+00		
<b>Pic 7 Desc.</b>	Triple protection ECDs in place at karst feature	<b>Pic 8 Desc.</b>	Waterbars in place		
<p>Date &amp; Time: Wed, Feb 23, 2022, 09:48:13 EST  Position: +437.349281° / -90.61022° (s=0.00)  Altitude: 2458 ft (s=0.00)  Datum: WGS 84  Geotagging: 107° 54' 00" 000mils True (s=0.00)  Camera: 3400x (s=0.00)  Horizon Grade: +005  Zoom: 1.0X  10843+75</p> 		<p>Date &amp; Time: Wed, Feb 23, 2022, 09:57:10 EST  Position: +437.341709° / -90.609943° (s=0.00)  Altitude: 2467 ft (s=19.70)  Datum: WGS 84  Geotagging: 107° 54' 00" 000mils True (s=0.00)  Camera: 3400x (s=0.00)  Horizon Grade: +005  Zoom: 1.0X  10856+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10843+75	<b>Field Station#</b>	10856+00		
<b>Pic 9 Desc.</b>	Cleanwater diversion berm in place	<b>Pic 10 Desc.</b>	Stream buffer in place		
<p>Date &amp; Time: Wed, Feb 23, 2022, 09:58:01 EST  Position: +437.341709° / -90.609943° (s=0.00)  Altitude: 2467 ft (s=19.70)  Datum: WGS 84  Geotagging: 107° 54' 00" 000mils True (s=0.00)  Camera: 3400x (s=0.00)  Horizon Grade: +005  Zoom: 1.0X  10858+00</p> 		<p>Date &amp; Time: Wed, Feb 23, 2022, 09:58:01 EST  Position: +437.341709° / -90.609943° (s=0.00)  Altitude: 2467 ft (s=19.70)  Datum: WGS 84  Geotagging: 107° 54' 00" 000mils True (s=0.00)  Camera: 3400x (s=0.00)  Horizon Grade: +005  Zoom: 1.0X  10859+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10858+00	<b>Field Station#</b>	10859+00		
<b>Pic 11 Desc.</b>	End treatments in place	<b>Pic 12 Desc.</b>	Supersilt fence perimeter control in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	2/23/2022 11:28 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34735
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/23/2022 7:09 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10749+92
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	54.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.80
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Communication			
Silt Fence (Reinforce Filter Fence)	Communication			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar End Treatment	Acceptable			
Sediment Filter Log	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 7:09 AM	<b>Report #</b>	34735
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). Compliance issues noted: @ 10708+22 rilling in throat of water bar & @ 10711+64 SSF needs repaired. Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. The ROW was muddy but in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 7:09 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	10708+22		<b>Field Station#</b>	10711+64	
<b>Pic 1 Desc.</b>	Rilling in throat of water bar needs repaired		<b>Pic 2 Desc.</b>	SSF needs repaired	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	10712+73		<b>Field Station#</b>	10697+78	
<b>Pic 3 Desc.</b>	Wattles in place		<b>Pic 4 Desc.</b>	Equipment bridge functional	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	10729+00		<b>Field Station#</b>	10733+18	
<b>Pic 5 Desc.</b>	Water bars and ET functional		<b>Pic 6 Desc.</b>	Resource buffers in place	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/23/2022 7:09 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p> <small>             Date &amp; Time Wed, Feb 23, 2022, 09:03:57 EST              Position: 4337.310157° / -68.658708° (±15.4m)              Altitude: 2078ft (±11.2m)              Datum: WGS-84              Azimuth/Bearing: 183° (±2°) 2720mils True (±12°)              Elevation Angle: -013°              Horizon Angle: -022°              Zoom: 1.0X              10678+82           </small> </p>		 <p> <small>             Date &amp; Time Wed, Feb 23, 2022, 09:04:46 EST              Position: 4337.344937° / -68.658957° (±14.8m)              Altitude: 2373ft (±11.2m)              Datum: WGS-84              Azimuth/Bearing: 085° N85E 1511mils True (±12°)              Elevation Angle: -163°              Horizon Angle: -035°              Zoom: 1.0X              10739+00           </small> </p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10678+82	<b>Field Station#</b>	10739+00		
<b>Pic 7 Desc.</b>	Equipment bridge functional	<b>Pic 8 Desc.</b>	Rock inlet functional		
 <p> <small>             Date &amp; Time Wed, Feb 23, 2022, 09:05:55 EST              Position: 4337.249937° / -68.659211° (±15.4m)              Altitude: 2018ft (±11.2m)              Datum: WGS-84              Azimuth/Bearing: 832° N83W 8900mils True (±12°)              Elevation Angle: -013°              Horizon Angle: -015°              Zoom: 1.0X              10749+00           </small> </p>		 <p> <small>             Date &amp; Time Wed, Feb 23, 2022, 09:06:46 EST              Position: 4337.262937° / -68.659467° (±15.4m)              Altitude: 2018ft (±11.2m)              Datum: WGS-84              Azimuth/Bearing: 085° N85E 1533mils True (±12°)              Elevation Angle: -013°              Horizon Angle: -021°              Zoom: 1.0X              10656+46           </small> </p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10749+00	<b>Field Station#</b>	10656+46		
<b>Pic 9 Desc.</b>	RCE functional	<b>Pic 10 Desc.</b>	Temporary stabilization in place		
<div>Insert image here</div>		<div>Insert image here</div>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/23/2022 7:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34804
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/24/2022 10:50 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11098+47
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11184+85
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	44.00
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			






## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/24/2022 10:50 AM	<b>Report #</b>	34804
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed VA SWPPP inspection from ST# 11098+47 (AR-245.02) to ST# 11184+85 (AR-249.02) MP 210.2 to MP 211.83          Accompanied on inspection by fellow EI Clint Sears.          No compliance issues found.          Active construction site; additional deficiencies may be identified by other EIs.          Observed no Environmental maintenance crews actively working on this section of ROW at time of inspection.          ST# 11445+50 to ST# 11170+00 has undergone temporary stabilization. Cleanwater diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place.          Final restoration has occurred between ST# 11098+47 and ST# 11145+50 and between ST# 11170+00 and ST# 11184+85. CFS perimeter controls, end treatments and temporary waterbars are in place. Daylight drains with outlet protection and Permanent waterbars (section 6-other) with level spreaders are in place.          AR-245.02, 249, 249.03, 249.01 and 249.02 RCEs are maintained in acceptable condition.          The ROW is wet and in stable condition. No sensitive resources have been impacted.          Moderate to heavy rainfall throughout duration of inspection. Rain gauges to be checked tomorrow 2/25/22.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/24/2022 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Feb 24, 2022, 08:43:17 EST  Position: +437.3159117° / -080.526127° (±28.00)  Altitude: 19348 (±19.70)  Datum: WGS-84  Azimuth/Bearing: 289° N071W 5130mils True (±12°)  Elevation Grade: +01%  Horizon Grade: +002%  Zoom: 1.0X  11112+00</p> 		<p>Date &amp; Time: Thu, Feb 24, 2022, 08:48:17 EST  Position: +437.3153497° / -080.530190° (±28.20)  Altitude: 21438 (±24.20)  Datum: WGS-84  Azimuth/Bearing: 070° N20E 1220mils True (±12°)  Elevation Grade: +34%  Horizon Grade: -01%  Zoom: 1.0X  11112+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11107+00	<b>Field Station#</b>	11112+00		
<b>Pic 1 Desc.</b>	CFS end treatments in place	<b>Pic 2 Desc.</b>	CFS triple stack perimeter control in place		
<p>Date &amp; Time: Thu, Feb 24, 2022, 09:54:53 EST  Position: +437.315379° / -080.526854° (±13.10)  Altitude: 19348 (±19.70)  Datum: WGS-84  Azimuth/Bearing: 289° N071W 5130mils True (±12°)  Elevation Grade: +01%  Horizon Grade: +002%  Zoom: 1.0X  11121+00</p> 		<p>Date &amp; Time: Thu, Feb 24, 2022, 09:01:19 EST  Position: +437.314477° / -080.523670° (±11.60)  Altitude: 19858 (±19.70)  Datum: WGS-84  Azimuth/Bearing: 147° S33E 2613mils True (±12°)  Elevation Grade: +012%  Horizon Grade: -00%  Zoom: 1.0X  11133+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11121+00	<b>Field Station#</b>	11133+00		
<b>Pic 3 Desc.</b>	CFS temporary waterbars in place	<b>Pic 4 Desc.</b>	Permanent waterbars in place		
<p>Date &amp; Time: Thu, Feb 24, 2022, 09:04:56 EST  Position: +437.3153531° / -080.521792° (±40.10)  Altitude: 20008 (±20.40)  Datum: WGS-84  Azimuth/Bearing: 172° S22W 3460mils True (±12°)  Elevation Grade: +0%  Horizon Grade: -01%  Zoom: 1.0X  11141+00</p> 		<p>Date &amp; Time: Thu, Feb 24, 2022, 09:09:13 EST  Position: +437.312780° / -080.519597° (±23.00)  Altitude: 20308 (±20.40)  Datum: WGS-84  Azimuth/Bearing: 300° S22W 3891mils True (±12°)  Elevation Grade: +24%  Horizon Grade: -01%  Zoom: 1.0X  11147+15</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11141+00	<b>Field Station#</b>	11147+15		
<b>Pic 5 Desc.</b>	Permanent vegetation present	<b>Pic 6 Desc.</b>	Cleanwater diversion berm in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/24/2022 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, Feb 24, 2022, 09:11:07 EST Position: +037.312481° / -080.517770° (±44.60) Altitude: 20790 (±32.80) Datum: WGS-84 Azimuth/Bearing: 349° S31E 3247mils True (±12°) Elevation Grade: -036% Horizon Grade: +001% Zoom: 1.0X 11152+00</small></p>		 <p><small>Date &amp; Time: Thu, Feb 24, 2022, 09:21:19 EST Position: +037.311412° / -080.514245° (±133.90) Altitude: 18339 (±39.40) Datum: WGS-84 Azimuth/Bearing: 118° S40E 2044mils True (±12°) Elevation Grade: -014% Horizon Grade: +000% Zoom: 1.0X 11163+00</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11152+00	<b>Field Station#</b>	11163+00		
<b>Pic 7 Desc.</b>	Supersilt fence perimeter control in place	<b>Pic 8 Desc.</b>	Silt fence perimeter control in place		
 <p><small>Date &amp; Time: Thu, Feb 24, 2022, 09:24:51 EST Position: +037.310444° / -080.516531° (±131.20) Altitude: 18205 (±44.60) Datum: WGS-84 Azimuth/Bearing: 200° N70W 3034mils True (±12°) Elevation Grade: -020% Horizon Grade: -004% Zoom: 1.0X 11165+00</small></p>		 <p><small>Date &amp; Time: Thu, Feb 24, 2022, 09:24:17 EST Position: +037.310380° / -080.514352° (±15.10) Altitude: 17608 (±11.70) Datum: WGS-84 Azimuth/Bearing: 200° S20W 3854mils True (±12°) Elevation Grade: -004% Horizon Grade: -003% Zoom: 1.0X 11166+00</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11162+50	<b>Field Station#</b>	11168+00		
<b>Pic 9 Desc.</b>	Cleanwater outlet protection in place	<b>Pic 10 Desc.</b>	RCE in place		
 <p><small>Date &amp; Time: Thu, Feb 24, 2022, 09:27:19 EST Position: +037.305872° / -080.513899° (±11.60) Altitude: 18750 (±9.80) Datum: WGS-84 Azimuth/Bearing: 112° S88E 1991mils True (±12°) Elevation Grade: +014% Horizon Grade: -005% Zoom: 1.0X 11178+00</small></p>		<div style="text-align: center; height: 150px;">Insert image here</div>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	11178+00	<b>Field Station#</b>			
<b>Pic 11 Desc.</b>	Level spreaders in place	<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/24/2022 10:50 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34785
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/24/2022 7:34 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11184+85
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	47.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Check Dam	Acceptable			
Stone Inlet Protection	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/24/2022 7:34 AM	<b>Report #</b>	34785
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). No Compliance issues noted: Observance: Perimeter controls in place & functioning as designed Permanent & temporary stabilization in place. - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. No maintenance is needed; - Temporary stabilization near 11222+50 to near 11253+50. This section of row has been stabilized for the winter months. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. AR-249.02 & 244 RCE's are maintained in acceptable condition. The ROW is wet but is in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/24/2022 7:34 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Feb 24, 2022, 09:45:37 EST Position: +437.5447° / -680.51377° (+63.71°) Altitude: 1926ft (+39.00) Datum: WGS-84 Azimuth/Bearing: 022.542E 0727mils True (+12°) Elevation Angle: -04.5 Horizon Angle: -00.3 Zoom: 1.0X AP: 2/29/85</p>		 <p>Date &amp; Time: Thu, Feb 24, 2022, 09:46:49 EST Position: +437.5447° / -680.51377° (+63.71°) Altitude: 1926ft (+39.00) Datum: WGS-84 Azimuth/Bearing: 124.554E 2204mils True (+12°) Elevation Angle: -11.4 Horizon Angle: -02.5 Zoom: 1.0X</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11184+79	<b>Field Station#</b>	11190+00		
<b>Pic 1 Desc.</b>	Rock check dams in place and RCE functional	<b>Pic 2 Desc.</b>	Clean water drainage feature functional		
 <p>Date &amp; Time: Thu, Feb 24, 2022, 09:13:40 EST Position: +437.5447° / -680.51377° (+63.71°) Altitude: 1926ft (+39.00) Datum: WGS-84 Azimuth/Bearing: 124.554E 2204mils True (+12°) Elevation Angle: -11.4 Horizon Angle: -02.5 Zoom: 1.0X 11193+00</p>		 <p>Date &amp; Time: Thu, Feb 24, 2022, 09:13:40 EST Position: +437.5447° / -680.51377° (+63.71°) Altitude: 1926ft (+39.00) Datum: WGS-84 Azimuth/Bearing: 124.554E 2204mils True (+12°) Elevation Angle: -11.4 Horizon Angle: -02.5 Zoom: 1.0X</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11193+00	<b>Field Station#</b>	11227+00		
<b>Pic 3 Desc.</b>	Permanent water bars and level spreader in place	<b>Pic 4 Desc.</b>	Water bars and inlets in place		
 <p>Date &amp; Time: Thu, Feb 24, 2022, 09:09:50 EST Position: +437.5447° / -680.51377° (+63.71°) Altitude: 2072ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 207.527W 3680mils True (+12°) Elevation Angle: -19.0 Horizon Angle: -00.3 Zoom: 1.0X winding way</p>		 <p>Date &amp; Time: Thu, Feb 24, 2022, 09:09:50 EST Position: +437.5447° / -680.51377° (+63.71°) Altitude: 2122ft (+39.11ft) Datum: WGS-84 Azimuth/Bearing: 123.557E 2187mils True (+12°) Elevation Angle: -04.2 Horizon Angle: -00.5 Zoom: 4.0X 11251+50</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11227+59	<b>Field Station#</b>	11251+50		
<b>Pic 5 Desc.</b>	RCE functional and SSF in place	<b>Pic 6 Desc.</b>	Erosion control blanket in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/24/2022 7:34 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	2/24/2022 7:34 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34805
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	2/24/2022 11:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11098+47
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	34.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	2/24/2022 11:31 AM	<b>Report #</b>	34805
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. No deficiencies documented for repairs today. There is an ongoing rain event that has started early morning and will continue throughout the day today.</p> <p>Other deficiencies may be found and reported by other EI's/and or MBP personnel.</p> <p>Station numbers are approximate.</p> <p>ROW CONDITIONS:</p> <p>The ROW is wet with no erosion issues at this time.</p> <p>The ROW from AR 244 to AR 245.01 has been temporarily stabilized. There are annual grasses visible as well. The temporary water bars are functioning as intended at this time. There is slight settling over the ditch line in various locations, all of which have been previously documented. The Precision contractor is aware of the settlement areas.</p> <p>The ROW from 245.01 to 245.02 has been restored. The restored area is in good shape and the vegetation is sufficient.</p> <p>The water bars ( other ), in the restored area are in place and functioning as designed.</p> <p>The environmental controls are functional. No construction being performed in the area.</p> <p>One area of open ditch in the area near 11061+00.</p> <p>Rock Road approaches were cleaned and functioning as designed. The perimeter ECD's are in place and functioning as designed. Sump pits and water bar end treatments are also functioning as intended.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/24/2022 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11098+43	<b>Field Station#</b>	11090+00		
<b>Pic 1 Desc.</b>	AR 245.01 conditions	<b>Pic 2 Desc.</b>	Final Restoration Area		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11068+00	<b>Field Station#</b>	11063+00		
<b>Pic 3 Desc.</b>	Temporary stabilization of row	<b>Pic 4 Desc.</b>	Temporary stabilization of row		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11065+00	<b>Field Station#</b>	11065+00		
<b>Pic 5 Desc.</b>	Equipment bridge condition over drainage feature.	<b>Pic 6 Desc.</b>	Stabilized Drainage feature conditions		



A/E	124300137	Date/Time	2/24/2022 11:31 AM	Report #	
Pictures					
Insert image here		<div><div><div>Date &amp; Time: Thu, Feb 24, 2022 09:38:09 EST Position: +037.322270° / -080.551286° (+15.8ft) Altitude: 2421ft (+11.0ft) Datum: WGS-84 Azimuth/Bearing: 235° S55W 4178mils True (+12°) Elevation Grade: -0.3% Horizon Grade: +002% Zoom: 2.0X 11032+00</div><div></div></div></div>			
GPS Location		GPS Location	See Photo		
Field Station#		Field Station#	11032+00		
Pic 7 Desc.		Pic 8 Desc.	Slope drain pipe, sump pit, water bar end treatment conditions.		
<div><div><div>Date &amp; Time: Thu, Feb 24, 2022 09:37:06 EST Position: +037.322261° / -080.551286° (+15.8ft) Altitude: 2423ft (+11.0ft) Datum: WGS-84 Azimuth/Bearing: 182° S02W 3236mils True (+12°) Elevation Grade: -0.37% Horizon Grade: -0.05% Zoom: 2.0X 11034+00</div><div></div></div></div>		<div><div><div>Date &amp; Time: Thu, Feb 24, 2022 09:36:37 EST Position: +037.322267° / -080.551288° (+15.8ft) Altitude: 2426ft (+10.7ft) Datum: WGS-84 Azimuth/Bearing: 156° S24E 2773mils True (+12°) Elevation Grade: -0.19% Horizon Grade: -0.02% Zoom: 4.0X 11035+00</div><div></div></div></div>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11034+00	Field Station#	11036+00		
Pic 9 Desc.	Perimeter CFS and diversion berm conditions.	Pic 10 Desc.	Temporary water bars and row conditions.		
<div><div><div>Date &amp; Time: Thu, Feb 24, 2022 09:36:13 EST Position: +037.322267° / -080.551301° (+14.8ft) Altitude: 2423ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 216° S00W 3590mils True (+13°) Elevation Grade: -0.03% Horizon Grade: +0.01% Zoom: 0.5X 11034+00</div><div></div></div></div>		<div><div><div>Date &amp; Time: Thu, Feb 24, 2022 09:35:08 EST Position: +037.322267° / -080.551301° (+14.8ft) Altitude: 2423ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 023° S07E 1650mils True (+12°) Elevation Grade: -0.2% Horizon Grade: -0.10% Zoom: 0.5X 11032+00</div><div></div></div></div>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11032+00	Field Station#	11032+00		
Pic 11 Desc.	Water bar throat conditions	Pic 12 Desc.	Temporary water bar condition		

<b>AFE</b>	124300137	<b>Date/Time</b>	2/24/2022 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
<small>Date &amp; Time: Thu Feb 24 2022 09:32:45 EST  Position: +03° 32'28.77" N -080° 55'25.34" W (-155.91°)  Altitude: 2175ft (-420m)  Datum: WGS-84  Azimuth/Bearing: 100° N50E 0889mils True (±12°)  Elevation Grade: -005%  Horizon Grade: -004%  Zoom: 1.0X  11025+02</small> 		<small>Date &amp; Time: Thu Feb 24 2022 09:38:04 EST  Position: +03° 32'29.71" N -080° 55'25.75" W (-155.91°)  Altitude: 2400ft (-420m)  Datum: WGS-84  Azimuth/Bearing: 109° S71E 1938mils True (±12°)  Elevation Grade: -002%  Horizon Grade: -002%  Zoom: 0.5X  11025+50 S-IJ18</small> 			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11025+02	<b>Field Station#</b>	11025+50		
<b>Pic 13 Desc.</b>	Repaired P1 silt fencing	<b>Pic 14 Desc.</b>	S-IJ Stream equipment bridge condition		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34797
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/24/2022 10:06 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10929+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11023+80
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	46.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	See punch list		
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/24/2022 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	10971+74	<b>Field Station#</b>	10971+74		
<b>Pic 1 Desc.</b>	AR 242.01 showing conditions and controls.		<b>Pic 2 Desc.</b>	Punch list item. Upgrade Perimeter controls.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	10971+00	<b>Field Station#</b>	10965+50		
<b>Pic 3 Desc.</b>	Staged equipment.		<b>Pic 4 Desc.</b>	Karst feature protection functional.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	10955+00	<b>Field Station#</b>	10934+75		
<b>Pic 5 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b>	CWDP outlet protection functional.	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/24/2022 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	7		<b>GPS Location</b>	8	
<b>Field Station#</b>	10940+25		<b>Field Station#</b>	10929+80	
<b>Pic 7 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 8 Desc.</b>	RCE off of Craig Creel rd.	
<b>GPS Location</b>	9		<b>GPS Location</b>	10	
<b>Field Station#</b>	10987+50		<b>Field Station#</b>	11015+50	
<b>Pic 9 Desc.</b>	Overview S-E24/S-E25.		<b>Pic 10 Desc.</b>	Overview S-RR5/S-PA07.	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/24/2022 10:06 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34861
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/25/2022 3:45 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11471+56
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Stone Inlet Protection	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Permanent)	Communication	See comments		

## 5. Site Conditions







Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/25/2022 3:45 PM	<b>Report #</b>	34861
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed VA SWPPP inspection from ST# 11353+67 (Old Furnace) to ST# 11471+56 (Steele Acres) MP 215.04 to MP 217.26          Accompanied on inspection by fellow EI Clint Sears.          Deficiencies found at the following station numbers:          11361+00 to 11396+00 stabilize areas damaged by livestock.          All issues have been communicated to PPL contractor via punch list.          Active construction site; additional deficiencies may be identified by other EIs.          ST# 11353+67 to ST# 11367+00 and ST# 11443+50 to ST# 11471+56 have undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Triple protection ECDs are in place at karst feature.          Final restoration has occurred between ST# 11367+00 and ST# 11443+50. CFS perimeter controls, end treatments and temporary waterbars are in place. Permanent waterbars(section 6-other) with level spreaders are in place.          Sensitive resource buffers are in place at stream crossings S-KL43, S-0014, S-0013, S-0012, and S-CD14.          AR-256 and 258.01 RCEs are maintained in acceptable condition.          The ROW is wet and in stable condition. No sensitive resources have been impacted.          Steele Acres rain gauge measured 1.6" of rainfall accumulated on 2/24/22.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	2/25/2022 3:45 PM	Report #	
Pictures					
<p>Date &amp; Time: Fri, Feb 25, 2022 10:45:18 EST  Position: +037 312591° / -080 456557° (±11.6ft)  Altitude: 2122ft (±13.1ft)  Datum: WGS-84  Azimuth Bearing: 302° North: 451mils True (±12°)  Elevation Grade: -02%  Horizon Grade: -002%  Zoom: 1.0X  11387+00</p> 		<p>Date &amp; Time: Fri, Feb 25, 2022 10:45:10 EST  Position: +037 309470° / -080 456510° (±20.1ft)  Altitude: 2000ft (±14.2ft)  Datum: WGS-84  Azimuth Bearing: 302° North: 432mils True (±12°)  Elevation Grade: -001%  Horizon Grade: -002%  Zoom: 1.0X  11374+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11387+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Area damaged by livestock		<b>Pic 2 Desc.</b>	
<p>Date &amp; Time: Fri, Feb 25, 2022 11:10:39 EST  Position: +037 306903° / -080 457192° (±101ft, 40ft)  Altitude: 1921ft (±107.3ft)  Datum: WGS-84  Azimuth Bearing: 212° S32W: 374mils True (±12°)  Elevation Grade: -021%  Horizon Grade: -002%  Zoom: 1.0X  11353+75</p> 		<p>Date &amp; Time: Fri, Feb 25, 2022 11:04:27 EST  Position: +037 307984° / -080 466325° (±22.9ft)  Altitude: 1968ft (±39.4ft)  Datum: WGS-84  Azimuth Bearing: 169° S11E: 3004mils True (±12°)  Elevation Grade: -029%  Horizon Grade: -015%  Zoom: 1.0X  11363+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11353+75		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		RCE in place		<b>Pic 4 Desc.</b>	
<p>Date &amp; Time: Fri, Feb 25, 2022 10:36:30 EST  Position: +037 309597° / -080 465224° (±11.4ft)  Altitude: 2001ft (±13.1ft)  Datum: WGS-84  Azimuth Bearing: 302° North: 437mils True (±12°)  Elevation Grade: -02%  Horizon Grade: -002%  Zoom: 1.0X  11397+00</p> 		<p>Date &amp; Time: Fri, Feb 25, 2022 10:26:48 EST  Position: +037 311844° / -080 462212° (±11.6ft)  Altitude: 2257ft (±15.8ft)  Datum: WGS-84  Azimuth Bearing: 302° North: 432mils True (±12°)  Elevation Grade: -002%  Horizon Grade: -002%  Zoom: 1.0X  11411+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11397+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Level spreader in place		<b>Pic 6 Desc.</b>	
				Temporary CFS waterbars in place	



AFE 124300137		Date/Time	2/25/2022 3:45 PM	Report #	
Pictures					
<p>Date &amp; Time: Fri, Feb 25, 2022, 10:07:53 EST  Position: +037 318423° -080 44394° (s=30.79)  Altitude: 2151ft (s=24ft)  Datum: WGS 84  Azimuth/Bearing: 330° N40E 1115mils True (s=12°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 1.0X  11437+00</p> 		<p>Date &amp; Time: Fri, Feb 25, 2022, 10:04:09 EST  Position: +037 318130° -080 443026° (s=17.5ft)  Altitude: 2191ft (s=23ft)  Datum: WGS 84  Azimuth/Bearing: 165° N22E 105mils True (s=12°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 1.0X  11446+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11437+00		<b>Field Station#</b>	11446+75	
<b>Pic 7 Desc.</b>	Permanent vegetation present		<b>Pic 8 Desc.</b>	Stone inlet protection in place	
<p>Date &amp; Time: Fri, Feb 25, 2022, 10:01:01 EST  Position: +037 318471° -080 44311° (s=11.4ft)  Altitude: 2143ft (s=9.6ft)  Datum: WGS 84  Azimuth/Bearing: 206° S26W 3662mils True (s=12°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 1.0X  11448+00</p> 		<p>Date &amp; Time: Fri, Feb 25, 2022, 10:05:42 EST  Position: +037 318453° -080 44304° (s=10.4ft)  Altitude: 2141ft (s=9.6ft)  Datum: WGS 84  Azimuth/Bearing: 243° S43W 3502mils True (s=12°)  Elevation Grade: +03%  Horizon Grade: +00%  Zoom: 1.0X  11452+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11448+00		<b>Field Station#</b>	11452+00	
<b>Pic 9 Desc.</b>	Cleanwater diversion berm in place		<b>Pic 10 Desc.</b>	Stream buffer in place	
<p>Date &amp; Time: Fri, Feb 25, 2022, 10:02:01 EST  Position: +037 318458° -080 44304° (s=10.4ft)  Altitude: 2220ft (s=10.7ft)  Datum: WGS 84  Azimuth/Bearing: 260° S60W 4899mils True (s=12°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 1.0X  11461+00</p> 		<p>Date &amp; Time: Fri, Feb 25, 2022, 10:02:01 EST  Position: +037 318458° -080 44304° (s=10.4ft)  Altitude: 2220ft (s=10.7ft)  Datum: WGS 84  Azimuth/Bearing: 260° S60W 4899mils True (s=12°)  Elevation Grade: +00%  Horizon Grade: +00%  Zoom: 1.0X  11469+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11461+00		<b>Field Station#</b>	11469+00	
<b>Pic 11 Desc.</b>	CFS perimeter control in place		<b>Pic 12 Desc.</b>	Triple protection ECDs in place at karst feature	



<b>A/E</b>	124300137	<b>Date/Time</b>	2/25/2022 3:45 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34834
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/25/2022 6:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	40.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.30
				<b>Rain Accumulation Time (days)</b>	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Culvert	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	2/25/2022 6:38 AM	<b>Report #</b>	34834
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to 219.70) No Deficiencies noted: The ROW from 258.02 to the JNF Forest has been fully restored. Permanent waterbars(other) and level spreaders are installed as per the approved plan and are functioning as designed. No maintenance is needed; Vegetation growth is currently acceptable. The Forest has been temporarily stabilized Observed: The aged P1 on the JNF from the top of the Mtn down to Craig Creek road has been replaced. The restored area is in good shape and the vegetation is sufficient. The environmental controls in the forest are aged, but functional. The ECDs at WBs, S-PP 20,21,22 are new and in good shape. No construction being performed in the area. RCE's functional, highway at Craig Creek station 11600+01, was clean and free of any loose rock. LOD ECDs were in place and functional. Water bars have been installed to specifications. The ROW is muddy but in stable condition. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	2/25/2022 6:38 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11533+00	<b>Field Station#</b>	11528+33		
<b>Pic 1 Desc.</b>	Perimeter controls in place	<b>Pic 2 Desc.</b>	Permanent water bar and level spreader in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11526+00	<b>Field Station#</b>	11600+01		
<b>Pic 3 Desc.</b>	Clean water drainage feature functional	<b>Pic 4 Desc.</b>	Culvert functional		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11593+00	<b>Field Station#</b>	11588+00		
<b>Pic 5 Desc.</b>	Water bars in place	<b>Pic 6 Desc.</b>	Equipment bridge functional		

<b>AFE</b>	124300137	<b>Date/Time</b>	2/25/2022 6:38 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Feb 25, 2022, 07:45:45 EST  Position: +037.317341, -080.409376, ±21.11ft  Altitude: 2048ft (±39.4ft)  Datum: WGS-84  Azimuth/Bearing: 143° S37E 2542mils True (±12°)  Elevation Angle: -08.9°  Horizon Angle: +08.4°  Zoom: 2.0X  11585+00</p>		 <p>Date &amp; Time: Fri, Feb 25, 2022, 07:45:45 EST  Position: +037.317341, -080.409376, ±21.11ft  Altitude: 2048ft (±39.4ft)  Datum: WGS-84  Azimuth/Bearing: 143° S37E 2542mils True (±12°)  Elevation Angle: -08.9°  Horizon Angle: +08.4°  Zoom: 2.0X  11585+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11585+00	<b>Field Station#</b>	11600+01		
<b>Pic 7 Desc.</b>	Resource buffers in place	<b>Pic 8 Desc.</b>	RCE functional		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/25/2022 6:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34849
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	2/25/2022 10:57 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Erosion Control Blanket	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Plunge Pool	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



AFE		124300137		Date/Time		2/25/2022 10:57 AM		Report #			
Pictures											
											
GPS Location		See photo				GPS Location		see photo			
Field Station#		11260+00				Field Station#		11268+00			
Pic 1 Desc.		Erosion blanket				Pic 2 Desc.		Plunge pool			
											
GPS Location		see photo				GPS Location		see photo			
Field Station#		11279+00				Field Station#		11292+66			
Pic 3 Desc.		Slope drain				Pic 4 Desc.		S-MM 18			
											
GPS Location		see photo				GPS Location		see photo			
Field Station#		11297+00				Field Station#		11328+00			
Pic 5 Desc.		Stabilized ROW				Pic 6 Desc.		S-NN 12			



<b>AFE</b>	124300137	<b>Date/Time</b>	2/25/2022 10:57 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11328+00	<b>Field Station#</b>	11331+00		
<b>Pic 7 Desc.</b>	S-NN 12	<b>Pic 8 Desc.</b>	Sump		
				Insert image here	
<b>GPS Location</b>	see photo	<b>GPS Location</b>			
<b>Field Station#</b>	11353+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	S-NN 11	<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/25/2022 10:57 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34847
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/25/2022 6:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11471+56
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+16
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	47.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	1.60
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Communication	Repair damage/undermine x2	24 Hours	
Compost Filter Sock	Communication	Repair undermine	24 Hours	
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Repair undermine	24 Hours	
Slope Drain Pipe	Communication	Repair undermine	24 Hours	
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/25/2022 6:56 AM	<b>Report #</b>	34847
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 217.26 (11471+56) and MP 218.26 (11524+16). Fellow EI Jared Saunders accompanied during inspection. This section of RoW has no current construction. Four locations of weather impact to controls were identified and added to the punch list following proper notifications. All other perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed AR 258.02 and Steele Acres.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/25/2022 6:56 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11524+16	<b>Field Station#</b>	11472+50		
<b>Pic 1 Desc.</b>	AR 258.02.	<b>Pic 2 Desc.</b>	Karst feature protection functional.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11477+00	<b>Field Station#</b>	11486+86		
<b>Pic 3 Desc.</b>	Repair undermined slope drain.	<b>Pic 4 Desc.</b>	Repair undermined and damaged CWDP.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11489+75	<b>Field Station#</b>	11490+00		
<b>Pic 5 Desc.</b>	Stevens Gap crossing.	<b>Pic 6 Desc.</b>	Rain gauge at Stevens Gap indicating 1.6" of accumulation.		



AFE	124300137	Date/Time	2/25/2022 6:56 AM	Report #	
Pictures					
<p><small>Date &amp; Time: Fri, Feb 25, 2022, 06:54:57 EST Position: 1428481.710 E / 366797.190 N (±11.4M) Altitude: 2174ft (±1.5M) Datum: WGS-84 Azimuth/Bearing: 146° 534E 2596mils True (±3°) Elevation Angle: -21.7° Horizon Angle: -05.0° Zoom: 0.5X 11490+00 Repair undermined P-1 and CFS</small></p> 		<p><small>Date &amp; Time: Fri, Feb 25, 2022, 06:54:58 EST Position: 1428482.152 E / 366797.226 N (±11.4M) Altitude: 2174ft (±1.5M) Datum: WGS-84 Azimuth/Bearing: 072° 093E 1887mils True (±13°) Elevation Angle: +04.3° Horizon Angle: +05.2° Zoom: 0.5X 11492+00</small></p> 			
<b>GPS Location</b> 7		<b>GPS Location</b> 8			
<b>Field Station#</b> 11490+00		<b>Field Station#</b> 11492+00			
<b>Pic 7 Desc.</b> Repair undermined CFS and P-1.		<b>Pic 8 Desc.</b> Section of RoW showing conditions and controls.			
<p><small>Date &amp; Time: Fri, Feb 25, 2022, 06:54:59 EST Position: 1428533.431 E / 366797.437 N (±12.0M) Altitude: 2244ft (±1.7M) Datum: WGS-84 Azimuth/Bearing: 088° 068E 1081mils True (±13°) Elevation Angle: -05.8° Horizon Angle: -08.5° Zoom: 0.5X 11502+00</small></p> 		<p><small>Date &amp; Time: Fri, Feb 25, 2022, 06:55:02 EST Position: 1428771.000 E / 366797.777 N (±11.4M) Altitude: 2218ft (±1.7M) Datum: WGS-84 Azimuth/Bearing: 245° 209W 302mils True (±12°) Elevation Angle: +14.5° Horizon Angle: -08.5° Zoom: 0.5X 11505+00</small></p> 			
<b>GPS Location</b> 9		<b>GPS Location</b> 10			
<b>Field Station#</b> 11502+00		<b>Field Station#</b> 11505+00			
<b>Pic 9 Desc.</b> Section of RoW showing conditions and controls.		<b>Pic 10 Desc.</b> Plunge pool functional.			
<p><small>Date &amp; Time: Fri, Feb 25, 2022, 06:55:47 EST Position: 1440523.839 E / 367335.272 N (±11.4M) Altitude: 2271ft (±1.7M) Datum: WGS-84 Azimuth/Bearing: 138° 542E 2453mils True (±12°) Elevation Angle: -18.3° Horizon Angle: -01.0° Zoom: 0.5X S-PP3 11507.78</small></p> 		<p><small>Date &amp; Time: Fri, Feb 25, 2022, 06:56:22 EST Position: 1441710.210 E / 367365.202 N (±11.4M) Altitude: 2289ft (±1.7M) Datum: WGS-84 Azimuth/Bearing: 091° 888E 1818mils True (±12°) Elevation Angle: +05.4° Horizon Angle: +01.1° Zoom: 0.5X S-PP4 11518.92</small></p> 			
<b>GPS Location</b> 11		<b>GPS Location</b> 121			
<b>Field Station#</b> 11507+77		<b>Field Station#</b> 11518+33			
<b>Pic 11 Desc.</b> S-PP3.		<b>Pic 12 Desc.</b> Overview of S-PP4.			



<b>A/E</b>	124300137	<b>Date/Time</b>	2/25/2022 6:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		