



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34121
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/7/2022 11:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10798+92
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	31.00
<b>Municipality</b>	N/A	<b>Weather</b>	Snow/Sleet	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 11:38 AM	<b>Report #</b>	34121
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 203.6 (10749+92) to MP 204.53 (10798+92). Accompanied by fellow EI Jared Saunders. This section of RoW has no current construction. No issues were identified. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Updated SWPPP documents.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		2/7/2022 11:38 AM		Report #			
Pictures											
											
GPS Location		1		GPS Location		2					
Field Station#		10758+35		Field Station#		10764+95					
Pic 1 Desc.		S-G35.		Pic 2 Desc.		S-SS4.					
											
GPS Location		3		GPS Location		4					
Field Station#		10771+75		Field Station#		10773+73					
Pic 3 Desc.		CWDP outlet protection functional.		Pic 4 Desc.		S-Z9.					
											
GPS Location		5		GPS Location		6					
Field Station#		10780+40		Field Station#		10790+50					
Pic 5 Desc.		S-Z7.		Pic 6 Desc.		Section of RoW showing conditions and controls.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 11:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 11:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34123
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	2/7/2022 11:43 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+46
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	21.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Flume Pipe	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	2/7/2022 11:43 AM	<b>Report #</b>	34123
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed Virginia SWPP inspection from station # 10859+46-10929+80.(MP 205.67-207.00) Kow Camp gravel to Doe Creek, with El Daniel Fortune. No deficiencies found today:  Observances: Freezing temperatures ROW conditions are frozen. Water bodies were flowing water.  There are areas of ditch subsidence, from station # 10875+00-10880+00 and 10896+00-10899+00. These areas are being monitored and will need repaired, when conditions allow. Precision has been made aware.  Environmental controls at water bodies are in place and functioning as designed. The ROW has been temporarily stabilized. Soil piles are stabilized. No trash on the ROW. No sensitive resources were impacted. All perimeter controls, ECDs and BMPs were functional at time of inspection. An Environmental crew was performing maintenance on EC's along ROW. Rock Road approaches are clean and free of loose rock.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/7/2022 11:43 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10859+87		<b>Field Station#</b>	10967+00	
<b>Pic 1 Desc.</b>	Kow Camp gravel RCE		<b>Pic 2 Desc.</b>	Stabilized ROW	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10875+00		<b>Field Station#</b>	10883+10	
<b>Pic 3 Desc.</b>	Area of ditch subsidence		<b>Pic 4 Desc.</b>	S-A 32	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10890+00		<b>Field Station#</b>	10900+00	
<b>Pic 5 Desc.</b>	Perimeter ECDs slope drains		<b>Pic 6 Desc.</b>	Stabilized ROW	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/7/2022 11:43 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	10924+00	<b>Field Station#</b>	10927+80		
<b>Pic 7 Desc.</b>	Erosion blanket, perimeter ECDs	<b>Pic 8 Desc.</b>	S-Y 3		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	see photo	<b>GPS Location</b>			
<b>Field Station#</b>	10929+45	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	S-Y 2, Doe Creek RCE	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 11:43 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34141
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/7/2022 2:46 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10859+46
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	29.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 2:46 PM	<b>Report #</b>	34141
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10798+92 (Cascade) to ST# 10859+46 (Kow Camp Gravel) MP 204.53 to MP 205.67 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. Perimeter controls and end treatments are in place. This section of ROW has undergone temporary stabilization. Topsoil piles and cleanwater diversion berms have been stabilized. Sensitive resource buffers are in place at stream crossings S-A33, S-A34, and S-Z14. AR-241.02, 241.03, and Cascade Drive road crossing RCEs are maintained in acceptable condition. The ROW is frozen and in stable condition. No sensitive resources have been impacted,					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 2:46 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Feb 07, 2022, 11:11:12 EST  Position: +037.341743° / -080.619377° (±18.170)  Altitude: 1931ft (±11.370)  Datum: WGS-84  Azimuth/Bearing: 298° N62W 5290mils True (±1.1°)  Elevation Grade: -010%  Horizon Grade: -000%  Zoom: 1.0x  10803+00</p> 		<p>Date &amp; Time: Mon, Feb 07, 2022, 11:10:09 EST  Position: +037.341743° / -080.619377° (±22.870)  Altitude: 1930ft (±15.710)  Datum: WGS-84  Azimuth/Bearing: 180° N00W 5400mils True (±1.2°)  Elevation Grade: -010%  Horizon Grade: -000%  Zoom: 1.0x  10805+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10803+00	<b>Field Station#</b>	10805+00		
<b>Pic 1 Desc.</b>	RCE in place	<b>Pic 2 Desc.</b>	P1 silt fence in place at sensitive resource buffer		
<p>Date &amp; Time: Mon, Feb 07, 2022, 11:08:21 EST  Position: +037.340855° / -080.618304° (±18.200)  Altitude: 1897ft (±15.370)  Datum: WGS-84  Azimuth/Bearing: 310° N10W 5000mils True (±1.2°)  Elevation Grade: -030%  Horizon Grade: -010%  Zoom: 1.0x  10808+15</p> 		<p>Date &amp; Time: Mon, Feb 07, 2022, 11:08:01 EST  Position: +037.340855° / -080.618304° (±11.100)  Altitude: 1897ft (±15.370)  Datum: WGS-84  Azimuth/Bearing: 310° N10W 5000mils True (±1.2°)  Elevation Grade: -030%  Horizon Grade: -010%  Zoom: 1.0x  10812+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10808+15	<b>Field Station#</b>	10812+00		
<b>Pic 3 Desc.</b>	Stone inlet protection in place	<b>Pic 4 Desc.</b>	Cleanwater diversion outlet protection in place		
<p>Date &amp; Time: Mon, Feb 07, 2022, 10:46:04 EST  Position: +037.340106° / -080.616667° (±18.100)  Altitude: 2394ft (±26.200)  Datum: WGS-84  Azimuth/Bearing: 269° S89W 4782mils True (±1.2°)  Elevation Grade: -032%  Horizon Grade: -001%  Zoom: 1.0x  10815+00</p> 		<p>Date &amp; Time: Mon, Feb 07, 2022, 10:46:04 EST  Position: +037.340106° / -080.616667° (±24.910)  Altitude: 2394ft (±26.200)  Datum: WGS-84  Azimuth/Bearing: 310° S20W 5000mils True (±1.1°)  Elevation Grade: -032%  Horizon Grade: -001%  Zoom: 1.0x  10831+50</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10815+00	<b>Field Station#</b>	10831+50		
<b>Pic 5 Desc.</b>	Erosion control blanket in place	<b>Pic 6 Desc.</b>	Triple protection ECDs in place at karst feature		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/7/2022 2:46 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, Feb 07, 2022, 10:45:34 CST  Position: +037.340948° / -080.610185° (s=1.59)  Altitude: 24380 (s=105.00)  Datum: WGS 84  Azimuth/Bearing: 247° S87W 4991 mile True (s=12°)  Elevation Grade: -039°  Horizon Grade: +002°  Zoom: 1.0X  10833+00</p> 		<p>Date &amp; Time: Mon, Feb 07, 2022, 10:39:24 CST  Position: +037.339248° / -080.608826° (s=11.49)  Altitude: 24199 (s=9.80)  Datum: WGS 84  Azimuth/Bearing: 327° N22W 8591 mile True (s=12°)  Elevation Grade: -051°  Horizon Grade: +001°  Zoom: 1.0X  10843+75</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10833+00	<b>Field Station#</b>	10843+75		
<b>Pic 7 Desc.</b>	Waterbars in place	<b>Pic 8 Desc.</b>	Cleanwater diversion berm in place		
<p>Date &amp; Time: Mon, Feb 07, 2022, 10:47:07 CST  Position: +037.338798° / -080.607745° (s=12.44)  Altitude: 22809 (s=18.79)  Datum: WGS 84  Azimuth/Bearing: 138° S42E 2653 mile True (s=12°)  Elevation Grade: -030°  Horizon Grade: +006°  Zoom: 1.0X  10848+50</p> 		<p>Date &amp; Time: Mon, Feb 07, 2022, 10:16:38 CST  Position: +037.324414° / -080.604317° (s=12.04)  Altitude: 22441 (s=16.04)  Datum: WGS 84  Azimuth/Bearing: 308° S22W 8533 mile True (s=12°)  Elevation Grade: -012°  Horizon Grade: +005°  Zoom: 1.0X  10855+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10848+50	<b>Field Station#</b>	10855+00		
<b>Pic 9 Desc.</b>	CFS perimeter control in place	<b>Pic 10 Desc.</b>	Stream buffer in place		
<p>Date &amp; Time: Mon, Feb 07, 2022, 10:12:21 CST  Position: +037.337381° / -080.604389° (s=11.41)  Altitude: 22641 (s=16.81)  Datum: WGS 84  Azimuth/Bearing: 001° N29W 8886 mile True (s=12°)  Elevation Grade: +058°  Horizon Grade: +006°  Zoom: 1.0X  10858+00</p> 		<p>Date &amp; Time: Mon, Feb 07, 2022, 10:14:43 CST  Position: +037.337244° / -080.604332° (s=16.50)  Altitude: 22441 (s=16.04)  Datum: WGS 84  Azimuth/Bearing: 307° N01E 8524 mile True (s=12°)  Elevation Grade: -006°  Horizon Grade: +005°  Zoom: 1.0X  10859+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10858+00	<b>Field Station#</b>	10859+00		
<b>Pic 11 Desc.</b>	End treatments in place	<b>Pic 12 Desc.</b>	Supersilt fence perimeter control in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 2:46 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34106
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/7/2022 7:48 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10749+92
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	21.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication			
Vegetative Stabilization (Temporary)	Communication			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Stone Inlet Protection	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 7:48 AM	<b>Report #</b>	34106
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). Compliance issues noted: @ 10728+00 to 10726+00 re-stabilization needed & @ 10729+00 P1 needs replaced Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. The ROW was frozen but in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 7:48 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10728+00	<b>Field Station#</b>	10729+00		
<b>Pic 1 Desc.</b>	Construction berm needs re-stabilized	<b>Pic 2 Desc.</b>	P1 needs replaced		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10712+73	<b>Field Station#</b>	10697+90		
<b>Pic 3 Desc.</b>	Equipment bridge functional & buffers in place	<b>Pic 4 Desc.</b>	Wattles in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10679+25	<b>Field Station#</b>	10733+18		
<b>Pic 5 Desc.</b>	Equipment bridge functional	<b>Pic 6 Desc.</b>	P1 in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/7/2022 7:48 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, Feb 07, 2022, 09:25:34 EST Position: +487.34677° / -988.49948° (±18.1ft) Altitude: 2343ft (±11.7ft) Datum: WGS-84 Azimuth/Bearing: 112° S68E 1091mils True (±12°) Elevation Angle: +12.7° Horizon Angle: +01.0° Zoom: 1.0X 10740+00</p>		 <p>Date &amp; Time: Mon, Feb 07, 2022, 09:28:32 EST Position: +487.34677° / -988.49948° (±18.1ft) Altitude: 2343ft (±11.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S74W 4516mils True (±12°) Elevation Angle: +23.0° Horizon Angle: +04.1° Zoom: 1.0X 10738+00</p>			
<b>GPS Location</b>	See	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10740+00	<b>Field Station#</b>	10738+00		
<b>Pic 7 Desc.</b>	Stone inlets in place	<b>Pic 8 Desc.</b>	ET functional		
 <p>Date &amp; Time: Mon, Feb 07, 2022, 09:25:34 EST Position: +487.34677° / -988.49948° (±18.1ft) Altitude: 2228ft (±10.0ft) Datum: WGS-84 Azimuth/Bearing: 120° S40E 2133mils True (±13°) Elevation Angle: +11.0° Horizon Angle: +00.5° Zoom: 0.5X 10667+25</p>		 <p>Date &amp; Time: Mon, Feb 07, 2022, 09:25:34 EST Position: +487.34677° / -988.49948° (±18.1ft) Altitude: 2300ft (±11.5ft) Datum: WGS-84 Azimuth/Bearing: 138° S42E 2453mils True (±13°) Elevation Angle: +15.0° Horizon Angle: +02.7° Zoom: 1.0X 10749+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10667+25	<b>Field Station#</b>	10749+00		
<b>Pic 9 Desc.</b>	Level spreader in place	<b>Pic 10 Desc.</b>	RCE functional		
 <p>Date &amp; Time: Mon, Feb 07, 2022, 09:25:34 EST Position: +487.34677° / -988.49948° (±18.1ft) Altitude: 2323ft (±11.5ft) Datum: WGS-84 Azimuth/Bearing: 112° S68E 1091mils True (±12°) Elevation Angle: +12.7° Horizon Angle: +01.0° Zoom: 1.0X 10656+67</p>		<div>Insert image here</div>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	10656+67	<b>Field Station#</b>			
<b>Pic 11 Desc.</b>	CFS perimeter controls functional	<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/7/2022 7:48 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34171
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	2/8/2022 12:07 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11098+47
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	34.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Communication	Added to punch list		

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 12:07 PM	<b>Report #</b>	34171
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. There has been minor deficiencies found and documented today for repairs.</p> <p>Station Number 11046+92 - Water bar will not drain to sump pit. This has been communicated to the contractor and the LEI as well as added to the punch list. Other deficiencies may be found and reported by other EI's/and or MBP personnel.</p> <p>"Station numbers are approximate".</p> <p>ROW CONDITIONS:</p> <p>The ROW in that area received 0.00" of precipitation overnight. The ROW is intermittently damp throughout.</p> <p>The ROW from AR 244 near 11025+02 to near 11070+21 has been temporarily stabilized. No erosion issues. Temporary vegetation is visible. There is ditch line settling in various locations on the slopes of the temporary stabilized areas. This has been communicated to the contractor and LEI. These areas are continually monitored by the EI staff and Precision contractor personnel for worsening conditions. The ROW from station 11070+21 to near 11098+00 has had final Restoration completed. There are 12" CFS that are being used as water bars at this time. There are no erosion issues visible in the final restored areas.</p> <p>The perimeter controls appear to be functional at this time. No construction being performed in the area.</p> <p>One area of open ditch (approximately 270') near 11061+00. Rock Road approaches were cleaned and functioning as intended.</p> <p>No sensitive resources have been impacted.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					







<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 12:07 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Feb 08, 2022, 09:59:58 EST  Position: +037.312913° / -080.533599° (±15.6ft)  Altitude: 1948ft (±10.9ft)  Datum: WGS-84  Azimuth/Bearing: 336° N24W 5973mils True (±13°)  Elevation Grade: +002%  Horizon Grade: -004%  Zoom: 0.5X  11098+00</p> 		<p>Date &amp; Time: Tue, Feb 08, 2022, 09:59:12 EST  Position: +037.312982° / -080.533590° (±16.1ft)  Altitude: 1950ft (±26.2ft)  Datum: WGS-84  Azimuth/Bearing: 279° N81W 4960mils True (±13°)  Elevation Grade: +010%  Horizon Grade: -000%  Zoom: 0.5X  11097+00</p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11098+00		<b>Field Station#</b>	11097+00	
<b>Pic 1 Desc.</b>	AR 245.02		<b>Pic 2 Desc.</b>	Final Restoration Area	
<p>Date &amp; Time: Tue, Feb 08, 2022, 09:51:42 EST  Position: +037.315142° / -080.537902° (±24.0ft)  Altitude: 2113ft (±26.2ft)  Datum: WGS-84  Azimuth/Bearing: 117° S49E 1973mils True (±13°)  Elevation Grade: +029%  Horizon Grade: -007%  Zoom: 0.5X  11084+00</p> 		<p>Date &amp; Time: Tue, Feb 08, 2022, 09:47:01 EST  Position: +037.315504° / -080.540742° (±23.5ft)  Altitude: 2202ft (±13.1ft)  Datum: WGS-84  Azimuth/Bearing: 091° N81E 1440mils True (±13°)  Elevation Grade: -009%  Horizon Grade: -005%  Zoom: 0.5X  11074+00</p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11084+00		<b>Field Station#</b>	11074+00	
<b>Pic 3 Desc.</b>	Final Restoration Area		<b>Pic 4 Desc.</b>	Final Restoration Area	
<p>Date &amp; Time: Tue, Feb 08, 2022, 09:33:50 EST  Position: +037.312986° / -080.544321° (±16.0ft)  Altitude: 2101ft (±10.9ft)  Datum: WGS-84  Azimuth/Bearing: 022° S88E 1626mils True (±13°)  Elevation Grade: +049%  Horizon Grade: -012%  Zoom: 0.5X  11065+00</p> 		<p>Date &amp; Time: Tue, Feb 08, 2022, 09:35:11 EST  Position: +037.314107° / -080.544620° (±15.9ft)  Altitude: 2192ft (±19.7ft)  Datum: WGS-84  Azimuth/Bearing: 345° N15W 6133mils True (±12°)  Elevation Grade: +010%  Horizon Grade: -006%  Zoom: 0.5X  11061+00</p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11065+00		<b>Field Station#</b>	11061+00	
<b>Pic 5 Desc.</b>	Ditch line settling in the drainage feature area		<b>Pic 6 Desc.</b>	Open ditch line for possible future MLV.	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/8/2022 12:07 PM	<b>Report #</b>	
<b>Pictures</b>					
<small>           Date &amp; Time: Tue Feb 08, 2022 09:53:52 EST            Position: +037.318248 / -080.548336 / +26.2ft            Altitude: 2177ft (+39.4ft)            Datum: WGS-84            Azimuth/Bearing: 089 / S89E 2044mils True (+12°)            Elevation Grade: -53%            Horizon Grade: +00%            Zoom: 0.5X            11055+00         </small>		<small>           Date &amp; Time: Tue Feb 08, 2022 09:53:52 EST            Position: +037.318248 / -080.548336 / +26.2ft            Altitude: 2177ft (+39.4ft)            Datum: WGS-84            Azimuth/Bearing: 089 / S89E 2044mils True (+12°)            Elevation Grade: -53%            Horizon Grade: +00%            Zoom: 0.5X            11055+00         </small>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11055+00	<b>Field Station#</b>	11050+00		
<b>Pic 7 Desc.</b>	Off LOD sensitive resource area protected with super silt fencing, triple stacked 18" CFS, and P1 silt fencing.	<b>Pic 8 Desc.</b>	S-IJ 16 & 17 equipment bridge condition.		
<small>           Date &amp; Time: Tue Feb 08, 2022 09:27:01 EST            Position: +037.318248 / -080.548336 / +26.2ft            Altitude: 2099ft (+26.2ft)            Datum: WGS-84            Azimuth/Bearing: 089 / N89E 1562mils True (+13°)            Elevation Grade: -02%            Horizon Grade: -00%            Zoom: 1.0X            11050+00         </small>		<small>           Date &amp; Time: Tue Feb 08, 2022 09:23:58 EST            Position: +037.318248 / -080.548336 / +26.2ft            Altitude: 2099ft (+26.2ft)            Datum: WGS-84            Azimuth/Bearing: 089 / N89E 1562mils True (+13°)            Elevation Grade: -02%            Horizon Grade: -00%            Zoom: 1.0X            11049+42         </small>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11050+00	<b>Field Station#</b>	11049+42		
<b>Pic 9 Desc.</b>	Looking upstream at the S-IJ 16 stream resource.	<b>Pic 10 Desc.</b>	S-IJ 16 & 17 stream resource buffer zones.		
<small>           Date &amp; Time: Tue Feb 08, 2022 09:21:42 EST            Position: +037.318512 / -080.548824 / +27.7ft            Altitude: 2221ft (+26.2ft)            Datum: WGS-84            Azimuth/Bearing: 099 / S84E 1707mils True (+13°)            Elevation Grade: -65%            Horizon Grade: -00%            Zoom: 1.0X            11046+92         </small>		<small>           Date &amp; Time: Tue Feb 08, 2022 09:19:05 EST            Position: +037.318448 / -080.548824 / +18.2ft            Altitude: 2316ft (+26.2ft)            Datum: WGS-84            Azimuth/Bearing: 165 / S75E 1807mils True (+13°)            Elevation Grade: -05%            Horizon Grade: -00%            Zoom: 0.5X            11044+40         </small>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11046+92	<b>Field Station#</b>	11044+40		
<b>Pic 11 Desc.</b>	View of low spot in the water bar throat. This was the deficiency documented for repair. Ditch line settling also visible.	<b>Pic 12 Desc.</b>	View of temporary stabilization of water bar conditions.		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/8/2022 12:07 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11040+00	<b>Field Station#</b>	11040+00		
<b>Pic 13 Desc.</b>	TSDP and sump pit conditions. Water bar end treatment remains in a functional manner.	<b>Pic 14 Desc.</b>	Stone inlet protection condition		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11034+00	<b>Field Station#</b>	11025+50		
<b>Pic 15 Desc.</b>	Temporary stabilization and temporary stabilized diversion berm.	<b>Pic 16 Desc.</b>	Equipment bridge condition over the S-IJ18 stream resource.		
<div>Insert image here</div>		<div>Insert image here</div>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34235
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	2/8/2022 1:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10929+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11023+80
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	47.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 1:18 PM	<b>Report #</b>	34235
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Assisted EI Chris Burns with SWPPP inspection from MP 207 (10929+80) and MP 208.78 (11023+80). This section of RoW has no current construction. A portion of this section of RoW has been permanently restored. Assessed AR 242.01. AR 242.01 is partially completed, incomplete portions are stabilized. No issues were identified. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No impact to sensitive resources observed. Assessed potential locations for future dewatering of excavations. Section 6 - CFS waterbars (other)					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		2/8/2022 1:18 PM		Report #			
Pictures											
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11010+00						Field Station#		11015+52	
Pic 1 Desc.		Rock inlet in place at slope drain pipe.						Pic 2 Desc.		Sensitive resource buffer in place at stream S-RR5.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		10971+00						Field Station#		10989+50	
Pic 3 Desc.		Equipment staged.						Pic 4 Desc.		Plunge pool replaced with rock level spreader.	
											
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		11012+25						Field Station#		10941+00	
Pic 5 Desc.		Super silt fence in place along LOD.						Pic 6 Desc.		ROW permanently restored. ROW stabilized with seed and mulch. CFS waterbars in place.	

<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 1:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 1:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34179
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/8/2022 2:11 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11098+47
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11184+85
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	39.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Stone Inlet Protection	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 2:11 PM	<b>Report #</b>	34179
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11098+47 (AR-245.02) to ST# 11184+85 (AR-249.02) MP 210.2 to MP 211.83 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crew at ST# 11167+83 refreshing the rock surface on AR-249.01. ST# 11445+50 to ST# 11170+00 has undergone temporary stabilization. Cleanwater diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Final restoration has occurred between ST# 11098+47 and ST# 11145+50 and between ST# 11170+00 and ST# 11184+85. CFS perimeter controls, end treatments and temporary waterbars are in place. Daylight drains with outlet protection and Permanent waterbars (section 6-other) with level spreaders are in place. AR-245.02, 249, 249.03, 249.01 and 249.02 RCEs are maintained in acceptable condition. The ROW is frozen and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/8/2022 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time Tue Feb 08 2022 09:47:16 EST  Position: +037.315468° / -080.527111° (+12.3m)  Altitude: 1971ft (+19.7m)  Datum: WGS-84  Azimuth/Bearing: 076° N76E 0762mils True (+12°)  Elevation Grade: -00m  Horizon Grade: -00m  Zoom: 1.0X  11105+00</p> 		<p>Date &amp; Time Tue Feb 08 2022 09:55:45 EST  Position: +037.315467° / -080.527127° (+12.3m)  Altitude: 2153ft (+19.7m)  Datum: WGS-84  Azimuth/Bearing: 076° N76E 1351mils True (+12°)  Elevation Grade: -00m  Horizon Grade: -00m  Zoom: 1.0X  11112+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11105+00	<b>Field Station#</b>	11112+00		
<b>Pic 1 Desc.</b>	CFS end treatments in place	<b>Pic 2 Desc.</b>	CFS triple stack perimeter control in place		
<p>Date &amp; Time Tue Feb 08 2022 10:02:28 EST  Position: +037.315468° / -080.527111° (+12.3m)  Altitude: 1971ft (+19.7m)  Datum: WGS-84  Azimuth/Bearing: 281° N79W 4996mils True (+12°)  Elevation Grade: -02m  Horizon Grade: -00m  Zoom: 1.0X  11120+00</p> 		<p>Date &amp; Time Tue Feb 08 2022 10:15:45 EST  Position: +037.315467° / -080.527157° (+12.3m)  Altitude: 2017ft (+19.7m)  Datum: WGS-84  Azimuth/Bearing: 228° N32W 5801mils True (+12°)  Elevation Grade: -01m  Horizon Grade: -00m  Zoom: 1.0X  11133+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11120+00	<b>Field Station#</b>	11133+00		
<b>Pic 3 Desc.</b>	CFS temporary waterbars in place	<b>Pic 4 Desc.</b>	Level spreaders in place		
<p>Date &amp; Time Tue Feb 08 2022 10:18:26 EST  Position: +037.315467° / -080.527157° (+12.3m)  Altitude: 2037ft (+19.7m)  Datum: WGS-84  Azimuth/Bearing: 124° S30E 2206mils True (+12°)  Elevation Grade: -01m  Horizon Grade: -01m  Zoom: 1.0X  11141+00</p> 		<p>Date &amp; Time Tue Feb 08 2022 10:21:06 EST  Position: +037.315467° / -080.517657° (+19.7m)  Altitude: 2037ft (+19.7m)  Datum: WGS-84  Azimuth/Bearing: 176° S16W 3086mils True (+12°)  Elevation Grade: -04m  Horizon Grade: -01m  Zoom: 1.0X  11147+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11141+00	<b>Field Station#</b>	11147+00		
<b>Pic 5 Desc.</b>	Permanent vegetation present	<b>Pic 6 Desc.</b>	Stone inlet protection in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/8/2022 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Tue, Feb 08, 2022, 10:21:49 EST  Position: +33° 51'25.93" / -82° 01'58.99" (s15.93)  Altitude: 2050ft (s11.1ft)  Datum: WGS-84  Azimuth/Heading: 152° (NADN 495m/side True (s12°)  Elevation Grade: +553%  Horizon Grade: +004%  Zoom: 1.0X  11148+50</p> 		<p>Date &amp; Time: Tue, Feb 08, 2022, 10:25:19 EST  Position: +33° 50'59.92" / -82° 02'01.91" (s15.90)  Altitude: 1861ft (s115.3ft)  Datum: WGS-84  Azimuth/Heading: 164° (NADN 352m/side True (s12°)  Elevation Grade: +018%  Horizon Grade: +003%  Zoom: 1.0X  11163+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11148+50	<b>Field Station#</b>	11163+00		
<b>Pic 7 Desc.</b>	Supersilt fence perimeter control in place	<b>Pic 8 Desc.</b>	P1 silt fence perimeter control in place		
<p>Date &amp; Time: Tue, Feb 08, 2022, 11:04:18 EST  Position: +33° 51'04.07" / -82° 01'02.50" (s15.94)  Altitude: 1000ft (s119.0ft)  Datum: WGS-84  Azimuth/Heading: 201° (NADN 495m/side True (s12°)  Elevation Grade: +022%  Horizon Grade: +006%  Zoom: 1.0X  11167+00</p> 		<p>Date &amp; Time: Tue, Feb 08, 2022, 11:04:48 EST  Position: +33° 50'54.17" / -82° 01'07.97" (s15.90)  Altitude: 1000ft (s119.0ft)  Datum: WGS-84  Azimuth/Heading: 164° (NADN 352m/side True (s12°)  Elevation Grade: +018%  Horizon Grade: +003%  Zoom: 1.0X  11168+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11167+00	<b>Field Station#</b>	11168+00		
<b>Pic 9 Desc.</b>	Cleanwater diversion outlet protection in place	<b>Pic 10 Desc.</b>	RCE in place		
<p>Date &amp; Time: Tue, Feb 08, 2022, 11:45:05 EST  Position: +33° 50'52.91" / -82° 01'39.94" (s15.94)  Altitude: 1931ft (s139.4ft)  Datum: WGS-84  Azimuth/Heading: 319° (NADN 591m/side True (s12°)  Elevation Grade: +011%  Horizon Grade: +008%  Zoom: 1.0X  11178+00</p> 		<p>Date &amp; Time: Tue, Feb 08, 2022, 11:45:42 EST  Position: +33° 50'52.44" / -82° 01'39.21" (s15.94)  Altitude: 1930ft (s139.4ft)  Datum: WGS-84  Azimuth/Heading: 164° (NADN 352m/side True (s12°)  Elevation Grade: +018%  Horizon Grade: +003%  Zoom: 1.0X  11184+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11178+00	<b>Field Station#</b>	11184+00		
<b>Pic 11 Desc.</b>	Permanent waterbars in place	<b>Pic 12 Desc.</b>	Daylight drain in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 2:11 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34163
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/8/2022 7:45 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11184+85
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	30.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Communication			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Stone Inlet Protection	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions




Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 7:45 AM	<b>Report #</b>	34163
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). Compliance issues noted: @ 11252+72 re-stabilization needed. Observance: Perimeter controls in place & functioning as designed Permanent & temporary stabilization in place. - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. No maintenance is needed; - Temporary stabilization near 11222+50 to near 11253+50. This section of row has been stabilized for the winter months. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. AR-249.02 & 244 RCE's are maintained in acceptable condition. The ROW frozen but is in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/8/2022 7:45 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue, Feb 08, 2022, 09:48:09 EST Position: +037 216876 / +080 496556 (±18.3m) Altitude: 1936ft (±19.7m) Datum: WGS-84 Azimuth/Bearing: 264° S84W 4693mils True (±12°) Elevation Angle: +00.4° Horizon Angle: +07.4° Zoom: 1.0X 11252+72</p>		 <p>Date &amp; Time: Tue, Feb 08, 2022, 09:48:09 EST Position: +037 216876 / +080 496556 (±18.3m) Altitude: 1936ft (±19.7m) Datum: WGS-84 Azimuth/Bearing: 180° S00E 3200mils True (±12°) Elevation Angle: -09.6° Horizon Angle: +07.7° Zoom: 1.0X 11252+72</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11252+72		<b>Field Station#</b>	11252+72	
<b>Pic 1 Desc.</b>	Re-stabilization needed		<b>Pic 2 Desc.</b>	SSF functional	
 <p>Date &amp; Time: Tue, Feb 08, 2022, 09:48:09 EST Position: +037 216876 / +080 496556 (±18.3m) Altitude: 2188ft (±11.7m) Datum: WGS-84 Azimuth/Bearing: 152° S28E 2702mils True (±12°) Elevation Angle: +14.7° Horizon Angle: +03.5° Zoom: 1.0X 11245+00</p>		 <p>Date &amp; Time: Tue, Feb 08, 2022, 09:48:09 EST Position: +037 216876 / +080 496556 (±18.3m) Altitude: 2240ft (±11.7m) Datum: WGS-84 Azimuth/Bearing: 236° S54W 4160mils True (±12°) Elevation Angle: +04.3° Horizon Angle: +09.4° Zoom: 1.0X 11237+00</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11245+00		<b>Field Station#</b>	11237+00	
<b>Pic 3 Desc.</b>	Water bars in place		<b>Pic 4 Desc.</b>	Inlet in place	
 <p>Date &amp; Time: Tue, Feb 08, 2022, 09:48:09 EST Position: +037 216876 / +080 496556 (±18.3m) Altitude: 2123ft (±11.7m) Datum: WGS-84 Azimuth/Bearing: 116° S44E 2062mils True (±12°) Elevation Angle: +00.0° Horizon Angle: +01.6° Zoom: 1.0X 11232+00</p>		 <p>Date &amp; Time: Tue, Feb 08, 2022, 09:48:09 EST Position: +037 216876 / +080 496556 (±18.3m) Altitude: 2123ft (±11.7m) Datum: WGS-84 Azimuth/Bearing: 116° S44E 2062mils True (±12°) Elevation Angle: +00.0° Horizon Angle: +01.6° Zoom: 1.0X 11232+00</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11232+00		<b>Field Station#</b>	11200+00	
<b>Pic 5 Desc.</b>	Perimeter P1 controls in place		<b>Pic 6 Desc.</b>	Permanent water bars/ level spreader in place CFS perimeter controls functional	



<b>AFE</b> 124300137		<b>Date/Time</b> 2/8/2022 7:45 AM		<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Tue, Feb 08, 2022 08:37:35 EST Position: -037.306557° / -080.509857° (-15.8°) Altitude: 7429ft (-26.2m) Datum: WGS-84 Azimuth Bearing: 189° S22E 2807mils True (-12°) Elevation Angle: -15.0° Horizon Angle: -10.7° Zoom: 10X 11185+00</small></p>			 <p><small>Date &amp; Time: Tue, Feb 08, 2022 08:37:35 EST Position: -037.307341° / -080.511905° (-15.5°) Altitude: 8945ft (-11.1m) Datum: WGS-84 Azimuth Bearing: 087° N87E 1547mils True (-12°) Elevation Angle: 06.1° Horizon Angle: 100.2° Zoom: 10X 11185+00</small></p>		
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11191+02		<b>Field Station#</b>	11185+00	
<b>Pic 7 Desc.</b>	Clean water drainage feature		<b>Pic 8 Desc.</b>	P1, CFS & RCE functional	
 <p><small>Date &amp; Time: Tue, Feb 08, 2022 08:37:35 EST Position: -037.307341° / -080.511905° (-15.5°) Altitude: 8945ft (-11.1m) Datum: WGS-84 Azimuth Bearing: 169° S17E 2987mils True (-13°) Elevation Angle: -17.2° Horizon Angle: -34.0° Zoom: 10X 11185+00</small></p>			Insert image here		
<b>GPS Location</b>	See photo		<b>GPS Location</b>		
<b>Field Station#</b>	11184+79		<b>Field Station#</b>		
<b>Pic 9 Desc.</b>	Rock check dams in place		<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 7:45 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34181
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/8/2022 2:23 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10929+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11023+80
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	42.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	2/8/2022 2:23 PM	<b>Report #</b>	34181
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 207 (10929+80) and MP 208.78 (11023+80). Accompanied by fellow EI Jared Saunders. This section of RoW has no current construction. A portion of this section of RoW has been permanently restored. Assessed AR 242.01. AR 242.01 is partially completed, incomplete portions are stabilized. No issues were identified. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No impact to sensitive resources observed. Assessed potential locations for future dewatering of excavations. Section 6 - CFS waterbars (other).					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/8/2022 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11021+00	<b>Field Station#</b>	11016+78		
<b>Pic 1 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	S-PA07.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11015+52	<b>Field Station#</b>	11004+00		
<b>Pic 3 Desc.</b>	S-RR5.	<b>Pic 4 Desc.</b>	CWDP outlet protection functional.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	10995+00	<b>Field Station#</b>	10976+00		
<b>Pic 5 Desc.</b>	P-1 perimeter controls.	<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/8/2022 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	10971+74	<b>Field Station#</b>	10970+00		
<b>Pic 7 Desc.</b>	AR 242.01.	<b>Pic 8 Desc.</b>	Section of RoW showing conditions and controls.		
<b>GPS Location</b>	9	<b>GPS Location</b>	10		
<b>Field Station#</b>	10955+00	<b>Field Station#</b>	10935+00		
<b>Pic 9 Desc.</b>	Section of restored RoW showing conditions and controls.	<b>Pic 10 Desc.</b>	SSF perimeter controls functional.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	2/8/2022 2:23 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34212
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/9/2022 7:24 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	30.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions




Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	2/9/2022 7:24 AM	<b>Report #</b>	34212
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to 219.70) No Deficiencies noted: The ROW from 258.02 to the JNF Forest has been fully restored. Permanent waterbars(other) and level spreaders are installed as per the approved plan and are functioning as designed. No maintenance is needed; Vegetation growth is currently acceptable. The Forest has been temporarily stabilized Observed: The aged P1 on the JNF from the top of the Mtn down to Craig Creek road has been replaced. The restored area is in good shape and the vegetation is sufficient. The environmental controls in the forest are aged, but functional. The ECDs at WBs, S-PP 20,21,22 are new and in good shape. No construction being performed in the area. RCE's functional, highway at Craig Creek station 11600+01, was clean and free of any loose rock. LOD ECDs were in place and functional. Water bars have been installed to specifications. The ROW ground is frozen but in stable condition. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/9/2022 7:24 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed Feb 09 2022 09:45:42 EST  Position: +037 329131 / -080 419624 (x14.87ft)  Altitude: 21530 ft (6557m)  Datum: WGS 84  Azimuth Bearing: 151° S24E 266mils True (±12°)  Elevation Angle: +12.0°  Horizon Angle: +03.9°  Zoom: 1.0x  11545+00</p> 		<p>Date &amp; Time: Wed Feb 09 2022 09:46:20 EST  Position: +037 329131 / -080 419624 (x14.87ft)  Altitude: 21530 ft (6557m)  Datum: WGS 84  Azimuth Bearing: 151° S24E 266mils True (±12°)  Elevation Angle: +12.0°  Horizon Angle: +03.9°  Zoom: 1.0x  11530+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11545+00		<b>Field Station#</b>	11530+00	
<b>Pic 1 Desc.</b>	Picture showing condition of row & ECD's		<b>Pic 2 Desc.</b>	Permanent water bars & level spreader in place	
<p>Date &amp; Time: Wed Feb 09 2022 09:45:19 EST  Position: +037 321555 / -080 418374 (x14.87ft)  Altitude: 22624 ft (6897m)  Datum: WGS 84  Azimuth Bearing: 028° N31W 556mils True (±12°)  Elevation Angle: +11.6°  Horizon Angle: +01.9°  Zoom: 1.0x  11528+33</p> 		<p>Date &amp; Time: Wed Feb 09 2022 09:46:21 EST  Position: +037 329100 / -080 420790 (x14.87ft)  Altitude: 21834 ft (6655m)  Datum: WGS 84  Azimuth Bearing: 069° N49E 1209mils True (±12°)  Elevation Angle: +04.9°  Horizon Angle: +03.9°  Zoom: 1.0x  11525+00</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11528+33		<b>Field Station#</b>	11525+00	
<b>Pic 3 Desc.</b>	Erosion control blanket in place		<b>Pic 4 Desc.</b>	Clean water drainage feature in place	
<p>Date &amp; Time: Wed Feb 09 2022 09:46:00 EST  Position: +037 319761 / -080 407887 (x14.87ft)  Altitude: 20514 ft (6252m)  Datum: WGS 84  Azimuth Bearing: 101° S24E 277mils True (±12°)  Elevation Angle: +10.0°  Horizon Angle: +00.9°  Zoom: 1.0x  11591+00</p> 		<p>Date &amp; Time: Wed Feb 09 2022 09:04:09 EST  Position: +037 319423 / -080 408289 (x14.87ft)  Altitude: 20274 ft (6180m)  Datum: WGS 84  Azimuth Bearing: 101° N54W 516mils True (±12°)  Elevation Angle: +10.0°  Horizon Angle: +02.9°  Zoom: 1.0x  11588+50</p> 			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11591+00		<b>Field Station#</b>	11588+50	
<b>Pic 5 Desc.</b>	Water bars in place		<b>Pic 6 Desc.</b>	Equipment bridge functional	



<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 7:24 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11585+00		<b>Field Station#</b>	11585+00	
<b>Pic 7 Desc.</b>	Wattles in place		<b>Pic 8 Desc.</b>	Recourse buffers in place	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11584+00		<b>Field Station#</b>	11600+01	
<b>Pic 9 Desc.</b>	ET in place		<b>Pic 10 Desc.</b>	RCE functional	
<p>Insert image here</p>			<p>Insert image here</p>		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 7:24 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34228
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/9/2022 11:39 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11471+56
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+16
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	51.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock-lined Channel	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			



## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 11:39 AM	<b>Report #</b>	34228
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 217.26 (11471+56) and MP 218.26 (11524+16). Fellow EI Jared Saunders accompanied during inspection. This section of RoW has no current construction. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed AR 258.02 and Steele Acres. PPL Environmental Coordinator Mike Perry stated an excavator will be tracked from Stevers Gap to the coming in side of Steele acres. Recommendations made to Mr Perry to perform preventative maintenance in any location tracked through. LEI Brian Shields notified of discussions.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 11:39 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, Feb 09, 2022, 08:58:11 EST Position: 1438703.065 E / 370170.874 N (±7836.5ft) Altitude: 2023ft (±342.5ft) Datum: WGS-84 Azimuth/Bearing: 041° N41E 0729mils True (±10°) Elevation Angle: -02.2° Horizon Angle: -02.2° Zoom: 0.5X 114258.02 11524+16</p>		 <p>Date &amp; Time: Wed, Feb 09, 2022, 09:16:50 EST Position: 1437148.602 E / 365687.818 N (±25.9ft) Altitude: 2214ft (±78.7ft) Datum: WGS-84 Azimuth/Bearing: 103° S77E 1881mils True (±12°) Elevation Angle: -17.8° Horizon Angle: -01.7° Zoom: 0.5X 114722+58</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11524+16	<b>Field Station#</b>	11472+50		
<b>Pic 1 Desc.</b>	AR 258.02 conditions and controls.		<b>Pic 2 Desc.</b>	Karst feature protection functional.	
 <p>Date &amp; Time: Wed, Feb 09, 2022, 09:19:34 EST Position: 1437713.397 E / 366019.286 N (±137.2ft) Altitude: 2233ft (±210.0ft) Datum: WGS-84 Azimuth/Bearing: 081° N81E 1440mils True (±13°) Elevation Angle: -09.4° Horizon Angle: -00.5° Zoom: 0.5X 114728+00</p>		 <p>Date &amp; Time: Wed, Feb 09, 2022, 09:29:50 EST Position: 1439588.366 E / 367037.830 N (±26.6ft) Altitude: 2244ft (±39.6ft) Datum: WGS-84 Azimuth/Bearing: 053° N53E 0942mils True (±13°) Elevation Angle: -01.3° Horizon Angle: -00.5° Zoom: 0.5X 115002+00</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11478+00	<b>Field Station#</b>	11502+00		
<b>Pic 3 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 4 Desc.</b>	Section of RoW showing conditions and controls.	
 <p>Date &amp; Time: Wed, Feb 09, 2022, 09:31:07 EST Position: 1439787.081 E / 367224.920 N (±19.5ft) Altitude: 2203ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 007° N73E 0120mils True (±12°) Elevation Angle: -10.2° Horizon Angle: -00.8° Zoom: 0.5X 115005+00</p>		 <p>Date &amp; Time: Wed, Feb 09, 2022, 09:32:28 EST Position: 1440005.167 E / 367353.975 N (±15.6ft) Altitude: 2212ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 073° N73E 1298mils True (±12°) Elevation Angle: -03.7° Horizon Angle: -00.0° Zoom: 0.5X 11507+78 S-PP3</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11505+00	<b>Field Station#</b>	11507+78		
<b>Pic 5 Desc.</b>	Rock lined channel and plunge pool functional.		<b>Pic 6 Desc.</b>	Overview of S-PP3.	



<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 11:39 AM	<b>Report #</b>	
<b>Pictures</b>					
<small>Date &amp; Time: Wed, Feb 09, 2022, 09:33:41 EST  Position: 1440206.310 E / 367528.220 N (=14.9m)  Altitude: 2184ft (=19.7m)  Datum: WGS-84  Azimuth/Bearing: 060° N60E 1067mils True (=12°)  Elevation Angle: +00.4°  Horizon Angle: +00.4°  Zoom: 0.5X  11511+00</small> 		<small>Date &amp; Time: Wed, Feb 09, 2022, 09:34:23 EST  Position: 1440869.023 E / 367940.621 N (=15.1m)  Altitude: 2219ft (=11.7m)  Datum: WGS-84  Azimuth/Bearing: 075° N75E 1333mils True (=12°)  Elevation Angle: +05.5°  Horizon Angle: +01.7°  Zoom: 0.5X  11518+32.5-PP4</small> 			
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	11511+00	<b>Field Station#</b>	11518+32		
<b>Pic 7 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 8 Desc.</b>	Overview of S-PP4.	
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 11:39 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34241
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/9/2022 2:47 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11471+56
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Communication	See comments		
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Stone Inlet Protection	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			







<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 2:47 PM	<b>Report #</b>	34241
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed VA SWPPP inspection from ST# 11353+67 (Old Furnace) to ST# 11471+56 (Steele Acres) MP 215.04 to MP 217.26          Accompanied on inspection by fellow EI Trey Ingram.          Deficiencies found at the following station numbers:          11464+00 Cut needs stabilized.          All issues have been communicated to PPL contractor via punch list.          Active construction site; additional deficiencies may be identified by other EIs.          Observed no environmental maintenance crews working on this section of ROW at time of inspection.          ST# 11353+67 to ST# 11367+00 and ST# 11443+50 to ST# 11471+56 have undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Triple protection ECDs are in place at karst feature.          Final restoration has occurred between ST# 11367+00 and ST# 11443+50. CFS perimeter controls, end treatments and temporary waterbars are in place. Permanent waterbars(section 6-other) with level spreaders are in place.          Sensitive resource buffers are in place at stream crossings S-KL43, S-0014, S-0013, S-0012, and S-CD14.          AR-256 and 258.01 RCEs are maintained in acceptable condition.          The ROW is frozen and in stable condition. No sensitive resources have been impacted.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 2/9/2022 2:47 PM	Report #
Pictures			
			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11464+00	<b>Field Station#</b>	11470+00
<b>Pic 1 Desc.</b>	Cut needs stabilized	<b>Pic 2 Desc.</b>	Stone inlet protection in place
			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11469+00	<b>Field Station#</b>	11467+00
<b>Pic 3 Desc.</b>	Triple protection ECDs in place at karst feature	<b>Pic 4 Desc.</b>	Plunge pool in place
			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11461+00	<b>Field Station#</b>	11452+00
<b>Pic 5 Desc.</b>	CFS perimeter control in place	<b>Pic 6 Desc.</b>	Stream buffer in place



AFE 124300137		Date/Time	2/9/2022 2:47 PM	Report #	
Pictures					
<p>Date &amp; Time: Wed, Feb 09, 2022, 10:47:45 EST  Position: +037°31'52.0" / -080°44'59.0" (+11448)  Altitude: 2164ft (+26.2ft)  Datum: WGS-84  Azimuth/Bearing: 212° S32W 3769mils True (+12°)  Elevation Grade: +000%  Horizon Grade: +004%  Zoom: 1.0X  11448+00</p> 		<p>Date &amp; Time: Wed, Feb 09, 2022, 10:13:29 EST  Position: +037°31'53.0" / -080°44'59.0" (+11437)  Altitude: 2157ft (+24.5ft)  Datum: WGS-84  Azimuth/Bearing: 228° S40W 4000mils True (+12°)  Elevation Grade: +013%  Horizon Grade: +003%  Zoom: 1.0X  11437+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11448+00		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		Cleanwater diversion berm in place		<b>Pic 8 Desc.</b>	
				Permanent vegetation present	
<p>Date &amp; Time: Wed, Feb 09, 2022, 10:39:15 EST  Position: +037°31'52.0" / -080°45'28.0" (+11412)  Altitude: 2304ft (+19.7ft)  Datum: WGS-84  Azimuth/Bearing: 090° N50E 10809mils True (+12°)  Elevation Grade: +002%  Horizon Grade: +002%  Zoom: 1.0X  11412+00</p> 		<p>Date &amp; Time: Wed, Feb 09, 2022, 11:45:00 EST  Position: +037°31'52.0" / -080°45'27.0" (+11397)  Altitude: 2314ft (+19.9ft)  Datum: WGS-84  Azimuth/Bearing: 339° N63W 10420mils True (+12°)  Elevation Grade: +002%  Horizon Grade: +008%  Zoom: 1.0X  11397+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11412+00		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		Temporary CFS waterbars		<b>Pic 10 Desc.</b>	
				Permanent waterbar with level spreader in place	
<p>Date &amp; Time: Wed, Feb 09, 2022, 11:01:21 EST  Position: +037°30'18.1" / -080°46'30.4" (+11363)  Altitude: 2000ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 159° S22E 2809mils True (+12°)  Elevation Grade: +026%  Horizon Grade: +012%  Zoom: 1.0X  11363+00</p> 		<p>Date &amp; Time: Wed, Feb 09, 2022, 11:05:28 EST  Position: +037°30'27.0" / -080°46'19.8" (+11362)  Altitude: 1983ft (+24.5ft)  Datum: WGS-84  Azimuth/Bearing: 044° N44E 9818mils True (+12°)  Elevation Grade: +011%  Horizon Grade: +002%  Zoom: 1.0X  11362+00</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11363+00		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		End treatments in place		<b>Pic 12 Desc.</b>	
				Erosion control blanket in place	



<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 2:47 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34230
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	2/9/2022 11:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Frozen	<b>Temperature (°F)</b>	21.00
<b>Municipality</b>	N/A	<b>Weather</b>	Below Freezing Temp	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions





Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





AFE		124300137		Date/Time		2/9/2022 11:38 AM		Report #			
Pictures											
											
GPS Location		See photo				GPS Location		see photo			
Field Station#		11257+00				Field Station#		11274+00			
Pic 1 Desc.		Erosion blanket				Pic 2 Desc.		Stabilized ROW, water bars, slope drain			
											
GPS Location		see photo				GPS Location		see photo			
Field Station#		11287+50				Field Station#		11293+05			
Pic 3 Desc.		ECDs at sensitive area				Pic 4 Desc.		S-MM 18			
											
GPS Location		see photo				GPS Location		see photo			
Field Station#		11297+87				Field Station#		11321+00			
Pic 5 Desc.		Seven Oaks				Pic 6 Desc.		Stabilized ROW			



<b>AFE</b>	124300137	<b>Date/Time</b>	2/9/2022 11:38 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11328+00	<b>Field Station#</b>	11349+00		
<b>Pic 7 Desc.</b>	S-NN 12	<b>Pic 8 Desc.</b>	Karst area		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11352+97	<b>Field Station#</b>	11349+00		
<b>Pic 9 Desc.</b>	S-NN11	<b>Pic 10 Desc.</b>	Sump		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/9/2022 11:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34257
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/10/2022 7:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	50.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 7:38 AM	<b>Report #</b>	34257
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 26. No compliance issues noted. Observance: Yard 26 has reduced activity during the winter curtailment. Perimeter controls in place & functioning as designed. RCE was clean, no mud or other debris on road. Secondary containment in place & functional as designed. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		2/10/2022 7:38 AM		Report #							
Pictures															
<p>Date &amp; Time: Thu, Feb 10, 2022, 11:37:40 EST Position: +037 318597 / -080 656970 (±15.6ft) Altitude: 1795ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 271° N89W 4818mils True (±10°) Elevation Angle: -02.3° Horizon Angle: +01.5° Zoom: 1.0X Y26</p> 				<p>Date &amp; Time: Thu, Feb 10, 2022, 11:36:36 EST Position: +037 318610 / -080 656993 (±15.6ft) Altitude: 1792ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 267° S89W 4891mils True (±10°) Elevation Angle: -07.8° Horizon Angle: +00.7° Zoom: 1.0X Y26</p> 											
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 1 Desc.				CFS perimeter controls functional				Pic 2 Desc.				Housekeeping in good condition			
<p>Date &amp; Time: Thu, Feb 10, 2022, 11:34:21 EST Position: +037 318597 / -080 656970 (±15.6ft) Altitude: 1797ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 271° N89W 4818mils True (±10°) Elevation Angle: -02.3° Horizon Angle: +01.5° Zoom: 1.0X Y26</p> 				<p>Date &amp; Time: Thu, Feb 10, 2022, 11:33:15 EST Position: +037 318610 / -080 656993 (±15.6ft) Altitude: 1795ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 269° S28W 3688mils True (±10°) Elevation Angle: -01.4° Horizon Angle: +00.3° Zoom: 2.0X Y26</p> 											
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 3 Desc.				Secondary containment in place				Pic 4 Desc.				Secondary containment in place			
<p>Date &amp; Time: Thu, Feb 10, 2022, 11:33:52 EST Position: +037 318222 / -080 656577 (±15.1ft) Altitude: 1795ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 064° N54E 1138mils True (±10°) Elevation Angle: +03.6° Horizon Angle: -00.3° Zoom: 1.0X Y26</p> 				<p>Date &amp; Time: Thu, Feb 10, 2022, 11:33:52 EST Position: +037 318222 / -080 656577 (±15.1ft) Altitude: 1795ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 320° S50W 4800mils True (±10°) Elevation Angle: -07.3° Horizon Angle: -00.1° Zoom: 1.0X Y26</p> 											
GPS Location				See photo				GPS Location				See photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 5 Desc.				RCE in good condition				Pic 6 Desc.				CFS controls in place			



<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 7:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 7:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34273
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/10/2022 11:56 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+89
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			



## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 11:56 AM	<b>Report #</b>	34273
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
Level Spreader	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection, from MP 223.27 (11788+52) and MP 225.37 (11899+89). Fellow EI Jared Saunders accompanied during SWPPP inspection. This section of RoW has no current construction. Temporary controls within this area are partially removed, remaining temporary controls to be removed once ground/weather conditions improve. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Unauthorized vehicle travel within the permanent restoration area, between 11792+00 and 11831+75, on 1/18/2022 resulted in minor disturbance/vegetation damage between 11824+00 and 11831+75. Monitoring of this area to continue. Assessed AR 266.03. Section 6- Waterbars (other).					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/10/2022 11:56 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Feb 10, 2022, 09:42:42 EST Position: 1457694.721 E / 328562.974 N (±10186.2ft) Altitude: 2236ft (±148.5ft) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (±12°) Elevation Angle: -01.9° Horizon Angle: -01.6° Zoom: 0.5X 11865+00</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022, 09:50:48 EST Position: 1462905.629 E / 352062.249 N (±15.5ft) Altitude: 2184ft (±11.1ft) Datum: WGS-84 Azimuth/Bearing: 010° N108° N179mils True (±12°) Elevation Angle: -02.8° Horizon Angle: -01.6° Zoom: 0.5X 11863+65</p>			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11886+00	<b>Field Station#</b>	11863+65		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	P-KL2 and controls.		
 <p>Date &amp; Time: Thu, Feb 10, 2022, 09:59:28 EST Position: 1459895.599 E / 335720.521 N (±15.4ft) Altitude: 2159ft (±11.8ft) Datum: WGS-84 Azimuth/Bearing: 308° S88W 8657mils True (±12°) Elevation Angle: -01.3° Horizon Angle: +03.5° Zoom: 0.5X 11841+00</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:05:46 EST Position: 1461490.300 E / 336615.365 N (±15.4ft) Altitude: 2209ft (±11.2ft) Datum: WGS-84 Azimuth/Bearing: 222° S42W 3947mils True (±12°) Elevation Angle: -03.7° Horizon Angle: +03.7° Zoom: 0.5X 11826+00</p>			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11841+00	<b>Field Station#</b>	11826+00		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.	<b>Pic 4 Desc.</b>	Section of restored RoW showing conditions and controls.		
 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:08:04 EST Position: 1461400.117 E / 335104.311 N (±15.5ft) Altitude: 2225ft (±11.2ft) Datum: WGS-84 Azimuth/Bearing: 050° N50E 0960mils True (±12°) Elevation Angle: -12.1° Horizon Angle: -01.2° Zoom: 0.5X 11821+00</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:14:17 EST Position: 1460153.098 E / 355809.144 N (±15.5ft) Altitude: 2178ft (±11.1ft) Datum: WGS-84 Azimuth/Bearing: 048° N68E 1209mils True (±12°) Elevation Angle: -04.1° Horizon Angle: -03.3° Zoom: 0.5X 11804+00</p>			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11821+00	<b>Field Station#</b>	11804+00		
<b>Pic 5 Desc.</b>	Representational photo of waterbar and level spreader installed.	<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 11:56 AM	<b>Report #</b>	
<b>Pictures</b>					
<small>Date &amp; Time: Thu, Feb 10, 2022, 10:16:21 EST Position: 1459571.558 E / 355929.313 N (+22.6ft) Altitude: 2186ft (+52.5ft) Datum: WGS-84 Azimuth/Bearing: 108.572E, 1920mils True (+12%) Elevation Angle: +05.4° Horizon Angle: -01.2° Zoom: 0.3X 11798+50</small> 		<small>Date &amp; Time: Thu, Feb 10, 2022, 10:20:53 EST Position: 1459710.824 E / 355810.073 N (+11.6ft) Altitude: 2123ft (+64.8ft) Datum: WGS-84 Azimuth/Bearing: 111.569E, 1973mils True (+12%) Elevation Angle: -00.4° Horizon Angle: -00.7° Zoom: 0.3X 11788+52</small> 			
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	11798+50	<b>Field Station#</b>	11788+52		
<b>Pic 7 Desc.</b>	Permanent controls.	<b>Pic 8 Desc.</b>	RCE off of Mt Tabor rd.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 11:56 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34278
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	2/10/2022 12:58 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	47.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 12:58 PM	<b>Report #</b>	34278
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>A VADEQ SWPPP inspection was completed on private and JNF lands on Brush Mountain today. The ROW surface remains stable with no area of erosion located. No sediment is migrating beyond LOD and no activity is taking place beyond approved limits. Slope breakers are functioning as designed. Sumps and end treatments are working properly. No issues are being created by runoff. Perimeter ECDs are in place. All P1 silt fence has been replaced, is being maintained and is functional. CFS is worn and will be replaced before any ground disturbance occurs. Resource crossing buffers are stable with ECDs in place. RCEs are in acceptable condition. No additional ECDs are needed at this time. No ECD maintenance needs or environmental concerns were identified today.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	2/10/2022 12:58 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Feb 10, 2022 11:55:55 EST Position: +037.304185° / +080.376591° (+5.0m) Altitude: 830m (+4.0m) Datum: WGS-84 Azimuth/Bearing: 177° 50W 4591mils Magnetic (+12°) Elevation Angle: +0.2° Horizon Angle: -05.2° Zoom: 1.0X 11665+00</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022 10:27:11 EST Position: +037.304562° / +080.376591° (+5.0m) Altitude: 810m (+4.0m) Datum: WGS-84 Azimuth/Bearing: 254° 57W 4551mils Magnetic (+12°) Elevation Angle: -36.2° Horizon Angle: -05.0° Zoom: 1.0X 11663+00</p>			
<b>GPS Location</b>	On photo		<b>GPS Location</b>	On photo	
<b>Field Station#</b>	11665+00		<b>Field Station#</b>	11663+00	
<b>Pic 1 Desc.</b>	Slope breakers are functioning.		<b>Pic 2 Desc.</b>	Sumps and end treatments are controlling runoff.	
 <p>Date &amp; Time: Thu, Feb 10, 2022 11:46:01 EST Position: +037.304185° / +080.377187° (+5.0m) Altitude: 840m (+4.0m) Datum: WGS-84 Azimuth/Bearing: 154° 52W 2738mils Magnetic (+12°) Elevation Angle: -01.8° Horizon Angle: -05.2° Zoom: 1.0X 11657+00</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022 10:33:41 EST Position: +037.307095° / +080.377401° (+5.0m) Altitude: 727m (+4.0m) Datum: WGS-84 Azimuth/Bearing: 245° 54W 4036mils Magnetic (+12°) Elevation Angle: -34.4° Horizon Angle: -04.5° Zoom: 1.0X 11650+00</p>			
<b>GPS Location</b>	On photo		<b>GPS Location</b>	On photo	
<b>Field Station#</b>	11657+00		<b>Field Station#</b>	11650+00	
<b>Pic 3 Desc.</b>	End treatment functional.		<b>Pic 4 Desc.</b>	Sumps and end treatments are functional.	
 <p>Date &amp; Time: Thu, Feb 10, 2022 11:25:02 EST Position: +037.311629° / +080.382775° (+5.0m) Altitude: 860m (+12.0m) Datum: WGS-84 Azimuth/Bearing: 168° 51E 2987mils Magnetic (+12°) Elevation Angle: -02.1° Horizon Angle: -02.4° Zoom: 1.0X S-HH18 crossing</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022 11:01:05 EST Position: +037.311629° / +080.382626° (+5.0m) Altitude: 860m (+12.0m) Datum: WGS-84 Azimuth/Bearing: 073° N 5E 1003mils Magnetic (+12°) Elevation Angle: -03.1° Horizon Angle: -02.4° Zoom: 1.0X S-RR14 crossing</p>			
<b>GPS Location</b>	On photo		<b>GPS Location</b>	On photo	
<b>Field Station#</b>	11626+04		<b>Field Station#</b>	11614+20	
<b>Pic 5 Desc.</b>	The S-HH18 crossing is stable with appropriate ECDs in place.		<b>Pic 6 Desc.</b>	The S-RR14 crossing is stable. Appropriate ECDs are in place.	

<b>AFE</b>	124300137	<b>Date/Time</b>	2/10/2022 12:58 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11608+17	<b>Field Station#</b>	11606+00		
<b>Pic 7 Desc.</b>	The S-006 crossing is currently stable. No additional ECDs are needed.		<b>Pic 8 Desc.</b>	ROW surface is stable.	
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 12:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34270
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	2/10/2022 11:10 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+89
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	51.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions


Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 11:10 AM	<b>Report #</b>	34270
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Perimeter P1 silt fencing has been replaced in various locations.					
<b>Comments</b> (Reference above questions as appropriate.) See photos for GPS coordinates. Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). No Deficiencies documented for repairs today. This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time. Permanent water bars have been installed and appear to be functioning as intended. (Other) Level Spreaders appear to be functional Precision Crews: (1710) Has been in the area replacing P1 perimeter silt fencing between 11940+00 to near 11961+00 All other perimeter controls, ECDs and BMPs are weathered but appear to be functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed Ar 266.03					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/10/2022 11:10 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, Feb 10, 2022, 10:10:57 EST  Position: +037.259447° / -080.313439° (+15.6ft)  Altitude: 1159ft (+11.0ft)  Datum: WGS-84  Azimuth/Bearing: 185° S05W 3289mils True (+13°)  Elevation Grade: -002%  Horizon Grade: -002%  Horizon: 0.5X  Zoom: 0.5X  112005+00</p> 		<p>Date &amp; Time: Thu, Feb 10, 2022, 10:04:31 EST  Position: +037.267804° / -080.320039° (+15.7ft)  Altitude: 1423ft (+10.9ft)  Datum: WGS-84  Azimuth/Bearing: 123° S57E 2187mils True (+12°)  Elevation Grade: -025%  Horizon Grade: -004%  Horizon: 0.5X  Zoom: 0.5X  11990+29</p> 			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	11990+29		
<b>Pic 1 Desc.</b>	Temporary stabilization of row near the spread break.	<b>Pic 2 Desc.</b>	Row conditions at Catawba.		
<p>Date &amp; Time: Thu, Feb 10, 2022, 11:05:40 EST  Position: +037.269562° / -080.308572° (+15.2ft)  Altitude: 1133ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 102° S78E 1813mils True (+12°)  Elevation Grade: -013%  Horizon Grade: -002%  Horizon: 2.0X  Zoom: 2.0X  11994+00</p> 		<p>Date &amp; Time: Thu, Feb 10, 2022, 09:59:18 EST  Position: +037.269588° / -080.322740° (+16.9ft)  Altitude: 1781ft (+19.7ft)  Datum: WGS-84  Azimuth/Bearing: 091° N81E 1440mils True (+13°)  Elevation Grade: -019%  Horizon Grade: -002%  Horizon: 1.0X  Zoom: 1.0X  11978+86</p> 			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11994+00	<b>Field Station#</b>	11978+86		
<b>Pic 3 Desc.</b>	Final Restoration Area	<b>Pic 4 Desc.</b>	AR 266 conditions		
<p>Date &amp; Time: Thu, Feb 10, 2022, 09:54:56 EST  Position: +037.271031° / -080.324318° (+15.5ft)  Altitude: 1850ft (+11.2ft)  Datum: WGS-84  Azimuth/Bearing: 330° N30W 5967mils True (+12°)  Elevation Grade: +005%  Horizon Grade: -001%  Horizon: 1.0X  Zoom: 1.0X  11968+34</p> 		<p>Date &amp; Time: Thu, Feb 10, 2022, 09:54:08 EST  Position: +037.271034° / -080.324045° (+15.3ft)  Altitude: 1836ft (+13.1ft)  Datum: WGS-84  Azimuth/Bearing: 128° S52E 2276mils True (+12°)  Elevation Grade: -039%  Horizon Grade: -004%  Horizon: 1.0X  Zoom: 1.0X  11968+34</p> 			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11968+34	<b>Field Station#</b>	11968+34		
<b>Pic 5 Desc.</b>	Final Restoration Area	<b>Pic 6 Desc.</b>	Replaced P1 silt fencing along perimeter		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/10/2022 11:10 AM	<b>Report #</b>	
<b>Pictures</b>					
<p><small>Date &amp; Time: Thu, Feb 10, 2022, 09:42:57 EST Position: +037.277537° / -080.334397° (±25.7ft) Altitude: 2140ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 186° S12E 2951mils True (±12°) Elevation Grade: -003° Horizon Grade: -0003° Zoom: 1.0X 11946+69</small></p> 		<p><small>Date &amp; Time: Thu, Feb 10, 2022, 09:41:19 EST Position: +037.280222° / -080.328333° (±19.7ft) Altitude: 2221ft (±3.62ft) Datum: WGS-84 Azimuth/Bearing: 224° E07W 4124mils True (±12°) Elevation Grade: -015° Horizon Grade: -010° Zoom: 1.0X 11935+00</small></p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11946+69		<b>Field Station#</b>	11935+00	
<b>Pic 7 Desc.</b>	Final Restoration Area Vegetated water bar and row conditions		<b>Pic 8 Desc.</b>	Replaced P1 Silt fence	
<p><small>Date &amp; Time: Thu, Feb 10, 2022, 09:28:44 EST Position: +037.283864° / -080.328826° (±11.6ft) Altitude: 2330ft (±3.9ft) Datum: WGS-84 Azimuth/Bearing: 000° N10E 0170mils True (±12°) Elevation Grade: -0023° Horizon Grade: -0023° Zoom: 1.0X 11933+00</small></p> 		<p><small>Date &amp; Time: Thu, Feb 10, 2022, 09:26:55 EST Position: +037.281638° / -080.329238° (±11.6ft) Altitude: 2350ft (±3.1ft) Datum: WGS-84 Azimuth/Bearing: 250° S70W 4444mils True (±12°) Elevation Grade: -003° Horizon Grade: -003° Zoom: 1.0X 11930+18</small></p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11933+00		<b>Field Station#</b>	11930+18	
<b>Pic 9 Desc.</b>	Example of weathered CFS in final restoration area.		<b>Pic 10 Desc.</b>	AR 266 entry to row.	
<p><small>Date &amp; Time: Thu, Feb 10, 2022, 09:21:50 EST Position: +037.283379° / -080.331037° (±11.6ft) Altitude: 2343ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 126° S54E 2240mils True (±15°) Elevation Grade: -000° Horizon Grade: -000° Zoom: 1.0X 11922+00</small></p> 		<p><small>Date &amp; Time: Thu, Feb 10, 2022, 09:12:41 EST Position: +037.287757° / -080.334296° (±25.7ft) Altitude: 2221ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 097° S83E 1724mils True (±15°) Elevation Grade: -013° Horizon Grade: -000° Zoom: 0.5X 11900+81</small></p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11922+00		<b>Field Station#</b>	11900+81	
<b>Pic 11 Desc.</b>	Vegetated water bars in final restoration area.		<b>Pic 12 Desc.</b>	Permanent level spreader condition in final restoration area.	

<b>AFE</b>	124300137	<b>Date/Time</b>	2/10/2022 11:10 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>		See Photo		<b>GPS Location</b>	
<b>Field Station#</b>		11901+80		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		Replaced CFS.		<b>Pic 14 Desc.</b>	
Insert image here		Insert image here			
<b>GPS Location</b>				<b>GPS Location</b>	
<b>Field Station#</b>				<b>Field Station#</b>	
<b>Pic 15 Desc.</b>				<b>Pic 16 Desc.</b>	
Insert image here		Insert image here			
<b>GPS Location</b>				<b>GPS Location</b>	
<b>Field Station#</b>				<b>Field Station#</b>	
<b>Pic 17 Desc.</b>				<b>Pic 18 Desc.</b>	



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34256
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	2/10/2022 7:38 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	45.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 7:38 AM	<b>Report #</b>	34256
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 28 No compliance issues noted. Observance: Yard 28 has reduced activity during the winter curtailment. Aged Perimeter controls have been replaced & functioning as designed. RCE was clean, no mud or other debris on road. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	2/10/2022 7:38 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, Feb 10, 2022, 11:17:22 EST Position: +037.335745, -080.808119 (+100.0ft) Altitude: 1605ft (+210.0ft) Datum: WGS-84 Azimuth/Bearing: 151° S29E 2684mils True (+12°) Elevation Angle: -05.7 Horizon Angle: -00.9 Zoom: 1.0X Y2B:</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022, 11:19:45 EST Position: +037.335945, -080.808233 (+100.0ft) Altitude: 1607ft (+112.0ft) Datum: WGS-84 Azimuth/Bearing: 304° N56W 9404mils True (+12°) Elevation Angle: -09.2 Horizon Angle: +05.0 Zoom: 1.0X Y2B:</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 1 Desc.</b>	CFS perimeter controls & safety fence in place		<b>Pic 2 Desc.</b>	CFS perimeter controls in place	
 <p>Date &amp; Time: Thu, Feb 10, 2022, 11:17:40 EST Position: +037.335724, -080.808126 (+100.0ft) Altitude: 1548ft (+13.4ft) Datum: WGS-84 Azimuth/Bearing: 235° N26W 5759mils True (+12°) Elevation Angle: -02.0 Horizon Angle: +03.4 Zoom: 4.6X Y2B:</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022, 11:20:29 EST Position: +037.336243, -080.801840 (+15.1ft) Altitude: 1568ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 256° S76W 4551mils True (+12°) Elevation Angle: -00.5 Horizon Angle: +04.6 Zoom: 1.0X Y2B:</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 3 Desc.</b>	RCE in good condition		<b>Pic 4 Desc.</b>	CFS perimeter controls in place	
 <p>Date &amp; Time: Thu, Feb 10, 2022, 11:21:05 EST Position: +037.336227, -080.805700 (+100.0ft) Altitude: 1564ft (+33.4ft) Datum: WGS-84 Azimuth/Bearing: 189° S59W 3360mils True (+13°) Elevation Angle: -04.5 Horizon Angle: +00.7 Zoom: 1.0X Y2B:</p>		 <p>Date &amp; Time: Thu, Feb 10, 2022, 11:21:44 EST Position: +037.336236, -080.802785 (+120.0ft) Altitude: 1575ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 151° S29E 2684mils True (+12°) Elevation Angle: -00.1 Horizon Angle: -02.7 Zoom: 1.0X Y2B:</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	12005+00		<b>Field Station#</b>	12005+00	
<b>Pic 5 Desc.</b>	CFS perimeter controls functional in place		<b>Pic 6 Desc.</b>	Housekeeping in place	

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 7:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 7:38 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34280
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/10/2022 3:31 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Erosion Control Blanket	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 3:31 PM	<b>Report #</b>	34280
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 (Brush Mt) to ST# 11788+52 (Mt Tabor) MP 221.02 to MP 223.27 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection are in place where needed. Perimeter controls and waterbars with end treatments are in place. Sensitive resource buffers are in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCEs are maintained in acceptable condition. The ROW is damp and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE	124300137	Date/Time	2/10/2022 3:31 PM	Report #	
Pictures					
	 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:25:55 EST Position: +037.200907° / -080.394630° (-037.200° / -80.394630°) Altitude: 2222ft (-676.20m) Datum: WGS-84 Azimuth/Bearing: 149° 53'31" (264° True) (s12°) Elevation Grade: -0203 Horizon Grade: -0203 Zoom: 1.0x 11670+00</p>			 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:11:06 EST Position: +037.201707° / -080.393803° (-037.201° / -80.393803°) Altitude: 2422ft (-739.40m) Datum: WGS-84 Azimuth/Bearing: 100° 53'31" (280° True) (s13°) Elevation Grade: -0382 Horizon Grade: -0021 Zoom: 1.0x 11678+00</p>	
GPS Location	See photo		GPS Location	See photo	
Field Station#	11670+00		Field Station#	11678+00	
Pic 1 Desc.	P1 silt fence perimeter control in place		Pic 2 Desc.	End treatments in place	
	 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:24:22 EST Position: +037.200907° / -080.392169° (-037.200° / -80.392169°) Altitude: 2522ft (-768.60m) Datum: WGS-84 Azimuth/Bearing: 049° N48E 120° True (s12°) Elevation Grade: -0270 Horizon Grade: -0270 Zoom: 1.0x 11682+00</p>			 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:25:18 EST Position: +037.200907° / -080.392265° (-037.200° / -80.392265°) Altitude: 2522ft (-768.60m) Datum: WGS-84 Azimuth/Bearing: 049° N48E 120° True (s12°) Elevation Grade: -0270 Horizon Grade: -0270 Zoom: 1.0x 11682+50</p>	
GPS Location	See photo		GPS Location	See photo	
Field Station#	11682+00		Field Station#	11682+50	
Pic 3 Desc.	Slope drain in place		Pic 4 Desc.	Stone inlet protection in place	
	 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:27:40 EST Position: +037.200907° / -080.391068° (-037.200° / -80.391068°) Altitude: 2422ft (-739.40m) Datum: WGS-84 Azimuth/Bearing: 119° 53'31" (264° True) (s13°) Elevation Grade: -0011 Horizon Grade: -0021 Zoom: 1.0x 11688+00</p>			 <p>Date &amp; Time: Thu, Feb 10, 2022, 10:40:12 EST Position: +037.201207° / -080.388662° (-037.201° / -80.388662°) Altitude: 2422ft (-739.40m) Datum: WGS-84 Azimuth/Bearing: 100° N50W 50° True (s13°) Elevation Grade: -0097 Horizon Grade: -0000 Zoom: 1.0x 11705+00</p>	
GPS Location	See photo		GPS Location	See photo	
Field Station#	11688+00		Field Station#	11705+00	
Pic 5 Desc.	Erosion control blanket in place		Pic 6 Desc.	Sediment filter logs in place	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/10/2022 3:31 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu Feb 10 2022 11:42:39 EST  Position: +037.296827 / -88.398716 (±35.79)  Altitude: 2111ft (±32.8ft)  Datum: WGS-84  Azimuth/Bearing: 197° S43E 364ft/mile True (±12°)  Elevation Grade: -005%  Horizon Grade: -000%  Zoom: 1.0X  11712+00</p> 		<p>Date &amp; Time: Thu Feb 10 2022 11:43:05 EST  Position: +037.296822 / -88.398234 (±17.90)  Altitude: 2244ft (±13.1ft)  Datum: WGS-84  Azimuth/Bearing: 197° S43E 243ft/mile True (±12°)  Elevation Grade: -026%  Horizon Grade: +007%  Zoom: 1.0X  11720+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11712+00	<b>Field Station#</b>	11720+00		
<b>Pic 7 Desc.</b>	Waterbars in place	<b>Pic 8 Desc.</b>	CFS triple stack perimeter control in place		
<p>Date &amp; Time: Thu Feb 10 2022 11:42:17 EST  Position: +037.296875 / -88.399932 (±17.94)  Altitude: 2018ft (±14.7ft)  Datum: WGS-84  Azimuth/Bearing: 226° S44W 401ft/mile True (±12°)  Elevation Grade: -012%  Horizon Grade: -001%  Zoom: 1.0X  11741+00</p> 		<p>Date &amp; Time: Thu Feb 10 2022 11:43:05 EST  Position: +037.296827 / -88.398234 (±17.90)  Altitude: 2020ft (±19.0ft)  Datum: WGS-84  Azimuth/Bearing: 104° S05E 100ft/mile True (±12°)  Elevation Grade: +013%  Horizon Grade: -008%  Zoom: 1.0X  11749+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11741+00	<b>Field Station#</b>	11749+00		
<b>Pic 9 Desc.</b>	Stream buffer in place	<b>Pic 10 Desc.</b>	End treatments in place		
<p>Date &amp; Time: Thu Feb 10 2022 11:42:57 EST  Position: +037.296827 / -88.398115 (±15.81)  Altitude: 2142ft (±37.7ft)  Datum: WGS-84  Azimuth/Bearing: 151° S27E 272ft/mile True (±12°)  Elevation Grade: -06%  Horizon Grade: -002%  Zoom: 1.0X  11759+00</p> 		<p>Date &amp; Time: Thu Feb 10 2022 11:43:35 EST  Position: +037.296908 / -88.398938 (±10.81)  Altitude: 2068ft (±13.1ft)  Datum: WGS-84  Azimuth/Bearing: 107° S05E 196ft/mile True (±12°)  Elevation Grade: -00%  Horizon Grade: -000%  Zoom: 1.0X  11766+35</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11759+00	<b>Field Station#</b>	11766+35		
<b>Pic 11 Desc.</b>	Supersilt fence perimeter control in place	<b>Pic 12 Desc.</b>	RCE in place		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 3:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34276
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	2/10/2022 12:02 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	32.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 12:02 PM	<b>Report #</b>	34276
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed VA SWPP at Yard 29. Yard 29 has received no precipitation in the last 24 hours. No deficiencies found. Observances: No activity in the Yard. Equipment in the yard was free of leaks. The perimeter compost sock was in place and functioning as designed. The rock road approach was clean, no mud or other debris on road. The yard was free of debris. No trash was seen. Trash receptacles in the Yard were clearly labeled.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		2/10/2022 12:02 PM		Report #							
Pictures															
				<p>Date &amp; Time: Thu, Feb 10, 2022, 11:42:40 EST Position: +037.247221° / -080.497101° (-16.4M) Altitude: 1705ft (-16.3M) Datum: WGS-84 Azimuth/Bearing: 203° S23W 366mils True (-105°) Elevation Angle: -12.1° Horizon Angle: -01.6° Zoom: 1.0X yard 29 Spread G</p>								<p>Date &amp; Time: Thu, Feb 10, 2022, 11:42:45 EST Position: +037.247221° / -080.497101° (-16.4M) Altitude: 1705ft (-16.3M) Datum: WGS-84 Azimuth/Bearing: 033° N33E 488mils True (-65°) Elevation Angle: -09.4° Horizon Angle: -01.8° Zoom: 1.0X yard 29 Spread G</p>			
GPS Location				See photo				GPS Location				see photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 1 Desc.				Yard 29 perimeter compost sock				Pic 2 Desc.				Yard 29 perimeter compost sock			
				<p>Date &amp; Time: Thu, Feb 10, 2022, 11:33:25 EST Position: +037.243045° / -080.477008° (-16.4M) Altitude: 1705ft (-16.3M) Datum: WGS-84 Azimuth/Bearing: 292° N68W 519mils True (-105°) Elevation Angle: -08.6° Horizon Angle: -02.4° Zoom: 1.0X yard 29 Spread G</p>								<p>Date &amp; Time: Thu, Feb 10, 2022, 11:33:36 EST Position: +037.241001° / -080.676112° (-16.4M) Altitude: 1704ft (-16.3M) Datum: WGS-84 Azimuth/Bearing: 204° S24W 3627mils True (-10°) Elevation Angle: -01.8° Horizon Angle: -08.1° Zoom: 1.0X yard 29 Spread G</p>			
GPS Location				see photo				GPS Location				see photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 3 Desc.				Yard 29 perimeter compost sock				Pic 4 Desc.				Equipment trash receptacles			
				<p>Date &amp; Time: Thu, Feb 10, 2022, 11:34:14 EST Position: +037.243558° / -080.496416° (-16.4M) Altitude: 1693ft (-16.3M) Datum: WGS-84 Azimuth/Bearing: 273° N87W 4853mils True (-10°) Elevation Angle: -08.5° Horizon Angle: -01.6° Zoom: 1.0X yard 29 Spread G</p>								<p>Date &amp; Time: Thu, Feb 10, 2022, 11:34:44 EST Position: +037.243947° / -080.676110° (-16.4M) Altitude: 1693ft (-16.3M) Datum: WGS-84 Azimuth/Bearing: 210° S69W 3840mils True (-10°) Elevation Angle: -10.6° Horizon Angle: -01.0° Zoom: 1.0X yard 29 Spread G</p>			
GPS Location				see photo				GPS Location				see photo			
Field Station#				12005+00				Field Station#				12005+00			
Pic 5 Desc.				Yard 29 perimeter compost sock				Pic 6 Desc.				Stored pipe			



<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 12:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	2/10/2022 12:02 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34327
<b>Inspector</b>	Patrick Shields			<b>Date/Time</b>	2/11/2022 3:58 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10859+46
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	59.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	2/11/2022 3:58 PM	<b>Report #</b>	34327
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10798+92 (Cascade) to ST# 10859+46 (Kow Camp Gravel) MP 204.53 to MP 205.67 Accompanied on inspection by fellow EI Trey Ingram. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. Perimeter controls and end treatments are in place. This section of ROW has undergone temporary stabilization. Topsoil piles and cleanwater diversion berms have been stabilized. Sensitive resource buffers are in place at stream crossings S-A33, S-A34, and S-Z14. AR-241.02, 241.03, and Cascade Drive road crossing RCEs are maintained in acceptable condition. The ROW is damp and in stable condition. No sensitive resources have been impacted,					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 3:58 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10803+00	<b>Field Station#</b>	10804+00		
<b>Pic 1 Desc.</b>	RCE in place	<b>Pic 2 Desc.</b>	End treatment in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10805+00	<b>Field Station#</b>	10815+00		
<b>Pic 3 Desc.</b>	P1 silt fence in place at sensitive resource	<b>Pic 4 Desc.</b>	Erosion control blanket in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10831+50	<b>Field Station#</b>	10833+00		
<b>Pic 5 Desc.</b>	Triple protection ECDs in place at karst feature	<b>Pic 6 Desc.</b>	Waterbars in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/11/2022 3:58 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Feb 11, 2022, 3:52:57 EST Position: -83° 58'04.95" W - 48° 09'59.97" N Altitude: 2227m (7321ft) Datum: WGS 84 Azimuth/Bearing: 102° 11'04" N Elevation/Bearing: 102° 11'04" N Horizon Grade: -029° Zoom: 1.0x 10840+30</p>		 <p>Date &amp; Time: Fri, Feb 11, 2022, 3:53:57 EST Position: -83° 58'04.95" W - 48° 09'59.97" N Altitude: 2227m (7321ft) Datum: WGS 84 Azimuth/Bearing: 102° 11'04" N Elevation/Bearing: 102° 11'04" N Horizon Grade: -029° Zoom: 1.0x 10843+75</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10840+30	<b>Field Station#</b>	10843+75		
<b>Pic 7 Desc.</b>	Daylight drain in place	<b>Pic 8 Desc.</b>	Cleanwater diversion berm in place		
 <p>Date &amp; Time: Fri, Feb 11, 2022, 3:53:57 EST Position: -83° 58'04.95" W - 48° 09'59.97" N Altitude: 2227m (7321ft) Datum: WGS 84 Azimuth/Bearing: 102° 11'04" N Elevation/Bearing: 102° 11'04" N Horizon Grade: -029° Zoom: 1.0x 10848+50</p>		 <p>Date &amp; Time: Fri, Feb 11, 2022, 3:54:57 EST Position: -83° 58'04.95" W - 48° 09'59.97" N Altitude: 2227m (7321ft) Datum: WGS 84 Azimuth/Bearing: 102° 11'04" N Elevation/Bearing: 102° 11'04" N Horizon Grade: -029° Zoom: 1.0x 10855+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10848+50	<b>Field Station#</b>	10855+00		
<b>Pic 9 Desc.</b>	CFS perimeter control in place	<b>Pic 10 Desc.</b>	Stream buffer in place		
 <p>Date &amp; Time: Fri, Feb 11, 2022, 3:55:57 EST Position: -83° 58'04.95" W - 48° 09'59.97" N Altitude: 2227m (7321ft) Datum: WGS 84 Azimuth/Bearing: 102° 11'04" N Elevation/Bearing: 102° 11'04" N Horizon Grade: -029° Zoom: 1.0x 10858+00</p>		 <p>Date &amp; Time: Fri, Feb 11, 2022, 3:56:57 EST Position: -83° 58'04.95" W - 48° 09'59.97" N Altitude: 2227m (7321ft) Datum: WGS 84 Azimuth/Bearing: 102° 11'04" N Elevation/Bearing: 102° 11'04" N Horizon Grade: -029° Zoom: 1.0x 10859+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10858+00	<b>Field Station#</b>	10859+00		
<b>Pic 11 Desc.</b>	End treatments in place	<b>Pic 12 Desc.</b>	Supersilt fence perimeter control in place		



<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 3:58 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34319
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	2/11/2022 11:24 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+46
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	28.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			




<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	2/11/2022 11:24 AM	<b>Report #</b>	34319
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed Virginia SWPP inspection from station # 10859+46-10929+80.(MP 205.67-207.00) Kow Camp gravel to Doe Creek, with El Daniel Fortune. No Deficiencies found today. Observances:  ROW conditions are frozen in spots, damp in other locations. Water bodies were flowing water. Environmental controls at water bodies are in place and functioning as designed. The ROW has been temporarily stabilized.  There are areas of ditch subsidence, from station # 10875+00-10880+00 and 10896+00-10899+00. These areas are being monitored and will need repaired, when conditions allow. Precision has been made aware.  Soil piles are stabilized. No trash on the ROW. No sensitive resources were impacted. All perimeter controls, ECDs and BMPs were functional at time of inspection. An Environmental crew was working in the area, walking the ROW. Rock Road approaches are clean and free of loose rock.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time	2/11/2022 11:24 AM	Report #	
Pictures					
 <p>Date &amp; Time: Fri, Feb 11, 2022, 08:45:58 EST Position: +037.334789 / -080.575548 (±32.8ft) Altitude: 2300ft (±105.0ft) Datum: WGS-84 Azimuth/Bearing: 105.575E-1867mils True (±103.1) Elevation Angle: +02.4 Horizon Angle: -00.7 Zoom: 1.0X stabilized ROW, water bars, station: 10886+00 Spread G</p>		 <p>Date &amp; Time: Fri, Feb 11, 2022, 08:41:14 EST Position: +037.337247 / -080.624173 (±16.4ft) Altitude: 2307ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 026. N206.6642mils True (±68) Elevation Angle: +25.1 Horizon Angle: +07.1 Zoom: 1.0X sump, perimeter EGGS pattern, 10860+00 Spread G</p>			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		10886+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Stabilized ROW		<b>Pic 2 Desc.</b>	
 <p>Date &amp; Time: Fri, Feb 11, 2022, 08:42:29 EST Position: +037.338634 / -080.579197 (±16.4ft) Altitude: 2211ft (±31.8ft) Datum: WGS-84 Azimuth/Bearing: 349. N14W-160mils True (±12.1) Elevation Angle: +26.8 Horizon Angle: +02.8 Zoom: 1.0X clean water pipe sump, station: 10864+00 Spread G</p>		 <p>Date &amp; Time: Fri, Feb 11, 2022, 08:58:33 EST Position: +037.335297 / -080.575227 (±32.8ft) Altitude: 2207ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 105.575E-1867mils True (±39.1) Elevation Angle: -26.2 Horizon Angle: -01.5 Zoom: 1.0X stabilized ROW, water bars, S-A 32, station: 10883+00 Spread G</p>			
<b>GPS Location</b>		see photo		<b>GPS Location</b>	
<b>Field Station#</b>		10864+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Clean water diversion pipe		<b>Pic 4 Desc.</b>	
 <p>Date &amp; Time: Fri, Feb 11, 2022, 09:19:59 EST Position: +037.334670 / -080.591520 (±32.8ft) Altitude: 2554ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 072. N72E-1280mils True (±41.1) Elevation Angle: +15.4 Horizon Angle: -00.7 Zoom: 1.0X stabilized ROW, water bars, perimeter EGGS pattern, station: 10900+00 Spread G</p>		 <p>Date &amp; Time: Fri, Feb 11, 2022, 09:24:33 EST Position: +037.334622 / -080.588607 (±16.4ft) Altitude: 2526ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 081. N81E-1440mils True (±12.1) Elevation Angle: -17.3 Horizon Angle: -01.8 Zoom: 1.0X stabilized ROW, water bars, perimeter EGGS pattern, station: 10909+00 Spread G</p>			
<b>GPS Location</b>		see photo		<b>GPS Location</b>	
<b>Field Station#</b>		10900+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Water bars, ETs		<b>Pic 6 Desc.</b>	



<b>AFE</b>	124300137	<b>Date/Time</b>	2/11/2022 11:24 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, Feb 11, 2022, 09:39:20 EST  Position: +037.332661° / -080.584037° (±16.4m)  Altitude: 2190ft (±9.4m)  Datum: WGS-84  Azimuth/Bearing: 170° S10E 3022mils True (±9°)  Elevation Angle: -47.9°  Horizon Angle: -02.7°  Zoom: 1.0X  S-Y2 Doe Creek RCE-10925+00  Spread G</p>		 <p>Date &amp; Time: Fri, Feb 11, 2022, 09:36:26 EST  Position: +037.331933° / -080.583981° (±16.4m)  Altitude: 2192ft (±9.8m)  Datum: WGS-84  Azimuth/Bearing: 172° S08E 3058mils True (±12°)  Elevation Angle: -15.4°  Horizon Angle: -03.6°  Zoom: 1.0X  S-Y3 Doe Creek RCE-10928+00  Spread G</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	10925+00	<b>Field Station#</b>	10928+00		
<b>Pic 7 Desc.</b>	Erosion blanket, water bars ETs	<b>Pic 8 Desc.</b>	S-Y 3		
 <p>Date &amp; Time: Fri, Feb 11, 2022, 09:48:00 EST  Position: +037.331042° / -080.583177° (±16.4m)  Altitude: 2142ft (±9.4m)  Datum: WGS-84  Azimuth/Bearing: 155° S23E 2791mils True (±12°)  Elevation Angle: -18.2°  Horizon Angle: -00.2°  Zoom: 1.0X  S-Y2 Doe Creek RCE-10929+50  Spread G</p>		<div style="text-align: center;">Insert image here</div>			
<b>GPS Location</b>	see photo	<b>GPS Location</b>			
<b>Field Station#</b>	10929+50	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	S-Y 2, Doe Creek	<b>Pic 10 Desc.</b>			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 11:24 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34314
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	2/11/2022 10:47 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10798+92
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	59.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 10:47 AM	<b>Report #</b>	34314
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 203.6 (10749+92) to MP 204.53 (10798+92). Accompanied by fellow EI Jared Saunders. This section of RoW has no current construction. No issues were identified. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. PPL environmental crews were in this area performing maintenance as needed. Updated SWPPP documents.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 10:47 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Fri, Feb 11, 2022, 08:49:49 EST  Position: 137922.54575 E / 375192.522 N (416.11m)  Altitude: 222.6ft (67.8m)  Datum: WGS-84  Azimuth Bearing: 032.583E 103.6mils True ±12°  Elevation Angle: 10.4°  Horizon Angle: 01.6°  Zoom: 0.5X  10751+75</p> 		<p>Date &amp; Time: Fri, Feb 11, 2022, 08:49:49 EST  Position: 138016.8807 E / 374888.359 N (479.53m)  Altitude: 203.0ft (61.9m)  Datum: WGS-84  Azimuth Bearing: 016.240E 128.6mils True ±12°  Elevation Angle: 18.7°  Horizon Angle: 10.4°  Zoom: 0.5X  10758+35</p> 			
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	10751+75	<b>Field Station#</b>	10758+35		
<b>Pic 1 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	S-G35.		
<p>Date &amp; Time: Fri, Feb 11, 2022, 08:50:10 EST  Position: 137922.54575 E / 375192.522 N (416.11m)  Altitude: 222.6ft (67.8m)  Datum: WGS-84  Azimuth Bearing: 345.124W 61.5mils True ±12°  Elevation Angle: 19.5°  Horizon Angle: 11.1°  Zoom: 0.5X  10764+95</p> 		<p>Date &amp; Time: Fri, Feb 11, 2022, 08:50:31 EST  Position: 138103.834 E / 375005.720 N (474.0m)  Altitude: 217.0ft (66.1m)  Datum: WGS-84  Azimuth Bearing: 237.657W 42.3mils True ±12°  Elevation Angle: 14.5°  Horizon Angle: 9.6°  Zoom: 0.5X  10771+75</p> 			
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	10764+95	<b>Field Station#</b>	10771+75		
<b>Pic 3 Desc.</b>	S-SS4.	<b>Pic 4 Desc.</b>	CWDP outlet protection functional.		
<p>Date &amp; Time: Fri, Feb 11, 2022, 09:00:09 EST  Position: 138135.174 E / 375066.692 N (456.6m)  Altitude: 207.9ft (63.4m)  Datum: WGS-84  Azimuth Bearing: 034.183E 104.0mils True ±12°  Elevation Angle: 11.8°  Horizon Angle: 10.1°  Zoom: 0.5X  10773+73</p> 		<p>Date &amp; Time: Fri, Feb 11, 2022, 09:00:47 EST  Position: 138184.9207 E / 375062.083 N (442.6m)  Altitude: 205.1ft (62.5m)  Datum: WGS-84  Azimuth Bearing: 338.182W 60.9mils True ±12°  Elevation Angle: 13.0°  Horizon Angle: 10.0°  Zoom: 0.5X  10780+40</p> 			
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	10773+73	<b>Field Station#</b>	10780+40		
<b>Pic 5 Desc.</b>	S-Z9.	<b>Pic 6 Desc.</b>	S-Z7.		



<b>AFE</b>	124300137	<b>Date/Time</b>	2/11/2022 10:47 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	10791+00	<b>Field Station#</b>	10798+50		
<b>Pic 7 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 8 Desc.</b>	RCE off of Cascade dr.	
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 10:47 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	34331
<b>Inspector</b>	David Schoolcraft			<b>Date/Time</b>	2/11/2022 10:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10749+92
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	46.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 10:14 PM	<b>Report #</b>	34331
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental team Performed SWPPP inspection from 10655+00 (MP 201.6) to 10749+92 (MP 203.6) This section of ROW has no current construction. No issues found All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 2/11/2022 10:14 PM		Report #	
Pictures					
<p>Date &amp; Time: Fri, Feb 11, 2022 08:42:57 EST Position: +037.244922 / -80.432590 (+29.4ft) Altitude: 2330ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 350° N10W 6222mils True (+12.1) Elevation Angle: +15.3 Horizon Angle: -00.5 Zoom: 0.5x 10748+00</p> 				<p>Date &amp; Time: Fri, Feb 11, 2022 08:44:49 EST Position: +037.244922 / -80.431154 (+29.1ft) Altitude: 2330ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 283° N27W 6091mils True (+12.1) Elevation Angle: +09.5 Horizon Angle: -02.4 Zoom: 0.5x 10745+50</p> 	
GPS Location		See Photo		GPS Location	
Field Station#		10748+00		Field Station#	
Pic 1 Desc.		RCE		Pic 2 Desc.	
				Outlet	
<p>Date &amp; Time: Fri, Feb 11, 2022 09:03:46 EST Position: +037.348777 / -80.447805 (+19.5ft) Altitude: 2310ft (+31.1ft) Datum: WGS-84 Azimuth/Bearing: 070° N70E 1404mils True (+12.1) Elevation Angle: -00.7 Horizon Angle: -02.4 Zoom: 2.0x S-G33 10712+40</p> 				<p>Date &amp; Time: Fri, Feb 11, 2022 09:05:03 EST Position: +037.348084 / -80.446844 (+19.4ft) Altitude: 2277ft (+24.1ft) Datum: WGS-84 Azimuth/Bearing: 055° N55E 6978mils True (+12.1) Elevation Angle: +11.5 Horizon Angle: -02.8 Zoom: 0.5x 10698+00</p> 	
GPS Location		See Photo		GPS Location	
Field Station#		10712+40		Field Station#	
Pic 3 Desc.		S-G33		Pic 4 Desc.	
				Equipment bridge	
<p>Date &amp; Time: Fri, Feb 11, 2022 09:15:47 EST Position: +037.242222 / -80.453182 (+15.1ft) Altitude: 2059ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 309° N51W 5493mils True (+11.1) Elevation Angle: +01.6 Horizon Angle: -00.7 Zoom: 0.5x 10694+00</p> 				<p>Date &amp; Time: Fri, Feb 11, 2022 09:32:24 EST Position: +037.259199 / -80.461116 (+27.8ft) Altitude: 2320ft (+28.7ft) Datum: WGS-84 Azimuth/Bearing: 055° N55E 6978mils True (+12.1) Elevation Angle: +11.5 Horizon Angle: -02.8 Zoom: 0.5x 10667+00</p> 	
GPS Location		See Photo		GPS Location	
Field Station#		10694+00		Field Station#	
Pic 5 Desc.		Buffer zone		Pic 6 Desc.	
				Clean water diversion out let	

<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 10:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	2/11/2022 10:14 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		