









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33542
Inspector	Charles Head			Date/Time	1/24/2022 11:07 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Wet	Temperature (°F)	37.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/24/2022 11:07 AM	Report #	33542
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/24/2022 11:07 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14647+00	Field Station#	14551+00		
Pic 1 Desc.	Approximately 14647+00. Overview of ROW. 14644+90-14649+50 ROW has permanent vegetation.		Pic 2 Desc.	Approximately 14551+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14648+00	Field Station#	14611+25		
Pic 3 Desc.	Approximately 14548+00. Overview of ROW.		Pic 4 Desc.	Approximately 14611+25. Overview of stream crossing, equipment bridge and ECDs at stream S-E14.	
					
GPS Location	0	GPS Location	0		
Field Station#	14599+00	Field Station#	14596+00		
Pic 5 Desc.	Approximately 14599+00. Overview of road crossing and RCEs.		Pic 6 Desc.	Approximately 14596+00. Overview of ROW.	

A/E	124300139	Date/Time	1/24/2022 11:07 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/24/2022 11:07 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33544
Inspector	Justin Burch			Date/Time	1/24/2022 11:52 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Wet	Temperature (°F)	46.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/24/2022 11:52 AM	Report #	33544
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area received one precipitation event with totals of 0.10" at Bonbrook Mill Road and 0.10" at Farm View Road #1. • The ROW ground condition is wet and snow/ice covered. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. • At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/24/2022 11:52 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14076+00	Field Station#	14076+00		
Pic 1 Desc.	Waterbar in acceptable condition	Pic 2 Desc.	Waterbar end treatment in acceptable condition		
GPS Location	0	GPS Location	0		
Field Station#	14123+00	Field Station#	14117+00		
Pic 3 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 4 Desc.	Permanent vegetative stabilization and perimeter CFS in acceptable conditions		
GPS Location	0	GPS Location	0		
Field Station#	14126+00	Field Station#	14141+62		
Pic 5 Desc.	P1 silt fence in acceptable condition	Pic 6 Desc.	Equipment bridge in acceptable condition		

A/E	124300139	Date/Time	1/24/2022 11:52 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14141+00	Field Station#	14133+00		
Pic 7 Desc.	Super silt fence in acceptable condition	Pic 8 Desc.	Sump pit in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/24/2022 11:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Field Station#		Field Station#		Pic 18 Desc.	








Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33543
Inspector	Frank Craycroft			Date/Time	1/24/2022 11:11 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Wet	Temperature (°F)	40.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Plunge Pool	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/24/2022 11:11 AM	Report #	33543
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of ROW from Dual Track Rd to Chalk Level Rd. Remaining snow within ROW is slowly melting but no signs of erosion or runoff were observed. All waterbars and sumps are still functioning properly and have additional storage capacity. All resource buffers within area are intact and bridges are free of sediment accumulation. All perimeter ECDs were functional and in good condition. All clean water inlets are free of debris or vegetation buildup. No issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/24/2022 11:11 AM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	15924+00		Field Station#	15911+50	
Pic 1 Desc.	GAS S-GG11 ECDs and buffer zone		Pic 2 Desc.	CIS S-H55 Vegetation and ECDs	
					
GPS Location	0		GPS Location	0	
Field Station#	15900+00		Field Station#	15884+00	
Pic 3 Desc.	Temporary stabilization		Pic 4 Desc.	Clean water diversion inlet	
					
GPS Location	0		GPS Location	0	
Field Station#	15884+00		Field Station#	15865+00	
Pic 5 Desc.	Clean water outlet		Pic 6 Desc.	Waterbar checks	




AFE 124300139		Date/Time 1/24/2022 11:11 AM		Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	15853+00		Field Station#	15845+00	
Pic 7 Desc.	W-G2 buffer zone		Pic 8 Desc.	Dry swale ECDs	
				<p>Insert image here</p>	
GPS Location	0		GPS Location	0	
Field Station#	15845+00		Field Station#	15845+00	
Pic 9 Desc.	CFS Checks		Pic 10 Desc.	Clean water diversion channel	
		<p>Insert image here</p>			
GPS Location	0		GPS Location		
Field Station#	15828+00		Field Station#		
Pic 11 Desc.	GAS Mill Creek Rd Perimeter ECDs		Pic 12 Desc.		




A/E	124300139	Date/Time	1/24/2022 11:11 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33549
Inspector	Ben Farmer			Date/Time	1/24/2022 12:47 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Frozen	Temperature (°F)	33.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/24/2022 12:47 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15371+00		Field Station#	15375+00	
Pic 1 Desc.	ROW remains stabilized. Vegetation continues to fill in throughout this section.		Pic 2 Desc.	Drainage ECDs are in good condition and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15380+00		Field Station#	15384+00	
Pic 3 Desc.	Waterbars are functioning as intended.		Pic 4 Desc.	P1 is in good condition at all stream and wetland buffers.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15384+74		Field Station#	15346+00	
Pic 5 Desc.	Equipment bridge ECDs are in place and functioning. Stream buffers remain in good condition.		Pic 6 Desc.	P1 needs to be restaked.	

AFE	124300139	Date/Time	1/24/2022 12:47 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15443+00		Field Station#	15453+00	
Pic 7 Desc.	Perimeter CFS is in good condition.		Pic 8 Desc.	CWD remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15457+00		Field Station#	15460+81	
Pic 9 Desc.	No evidence of sedimentation from 3rd party disturbance within drainage feature.		Pic 10 Desc.	CWD remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15460+81		Field Station#	15465+00	
Pic 11 Desc.	No evidence of sedimentation from 3rd party disturbance into CWD inlet.		Pic 12 Desc.	No evidence of sedimentation from 3rd party disturbance.	







A/E	124300139	Date/Time	1/24/2022 12:47 PM	Report #	
Pictures					
					
GPS Location		See photo		GPS Location	
Field Station#		15475+00		Field Station#	
Pic 13 Desc.		3rd party rock outlet appears to be in good condition along this drainage.		Pic 14 Desc.	
Insert image here		Insert image here			
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 15 Desc.				Pic 16 Desc.	
Insert image here		Insert image here			
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 17 Desc.				Pic 18 Desc.	




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	33532		
Inspector	Logan Box	Date/Time	1/24/2022 3:19 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Frozen	Temperature (°F)	43.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge		Acceptable			
Erosion Control Blanket		Acceptable			
Rock Construction Entrance		Acceptable			
Compost Filter Sock		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/24/2022 3:19 PM	Report #	33532
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row.</p> <p>Inspected all stream and wetland crossings that were accessible due to frozen row conditions that impacted travel ,checked equipment bridges and protection.</p> <p>Monitored RCEs as they were still covered in snow/ice , some which were un accessible due to ice/snow in the areas that were inspected today.</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/24/2022 3:19 PM	Report #	
Pictures					
	South Elevation <small>31°N (T) • 37.085793, -79.948233 ±3 m ▲ 314 m</small> 			West Elevation <small>85°E (T) • 37.085277, -79.947999 ±3 m ▲ 304 m</small> 	
GPS Location	0000	GPS Location	0000		
Field Station#	13691+30	Field Station#	13692+69		
Pic 1 Desc.	Monitored ECDs around wetland area inside work space, no environmental issues observed at the time of inspection Flow conditions were still frozen		Pic 2 Desc.	Stream observation photo facing downstream during routine inspection today, no environmental issues observed at the time of inspection as snow/ice begins to slowly melt	
	North East Elevation <small>233°SW (T) • 37.088536, -79.950262 ±3 m ▲ 317 m</small> 			South West Elevation <small>36°NE (T) • 37.088561, -79.950255 ±3 m ▲ 317 m</small> 	
GPS Location	0000	GPS Location	0000		
Field Station#	13678+71	Field Station#	13678+71		
Pic 3 Desc.	Stream observation photo facing downstream during routine inspection today, no environmental issues observed at the time of inspection as snow/ice begins to melt from the		Pic 4 Desc.	Stream observation photo facing upstream during routine inspection today, no environmental issues observed at the time of inspection	
	North East Elevation <small>232°SW (T) • 37.088559, -79.950461 ±3 m ▲ 317 m</small> 			North West Elevation <small>159°SE (T) • 37.085491, -79.947952 ±7 m ▲ 276 m</small> 	
GPS Location	0000	GPS Location	0000		
Field Station#	13678+51	Field Station#	13692+69		
Pic 5 Desc.	Monitored stream buffer ECDs , no environmental issues observed at the time of inspection		Pic 6 Desc.	Monitored stream crossings, observed ECDs on stream banks. No environmental issues observed at the time of inspection	

AFE	124300139	Date/Time	1/24/2022 3:19 PM	Report #	
Pictures					
		<p>Insert image here</p>		<p>Insert image here</p>	
GPS Location	0000	GPS Location			
Field Station#	13692+69	Field Station#			
Pic 7 Desc.	Stream observation photo facing upstream during routine inspection today, no environmental issues observed at the time of inspection.		Pic 8 Desc.		
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/24/2022 3:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33498
Inspector	Ben Davenport			Date/Time	1/24/2022 11:51 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Frozen	Temperature (°F)	45.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance			
Equipment Bridge	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sediment Filter Log	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/24/2022 11:51 AM	Report #	33498
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with frozen/snowy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14928+52 —15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Walked ROW looking for potential environmental issues or maintenance requirements -Perimeter controls and ECD's were inspected; 1 issue identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed of stabilization and vegetation in section both permanent and temporary areas of ROW; ROW remains frozen/covered in snow; no issues observed -Continue to monitor ROW for signs of erosion -1 item added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/24/2022 11:51 AM	Report #	
Pictures					
					
36°57'47" N 79°35'36" W 163°S COURSE -1° GPS 1923-2165 Armstrong Rd, Penhook, VA 24137, United States 01.24.2022 10:57:40 Accur +/-68.0 Ft ALT 909 Ft			36°58'3" N 79°38'12" W 122°SE COURSE 109° GPS 2082 Ramsey Memorial Rd, Penhook, VA 24137, United States 01.24.2022 12:55:25 Accur +/-35.2 Ft ALT 824 Ft		
GPS Location	1		GPS Location	2	
Field Station#	15063+85		Field Station#	14932+89	
Pic 1 Desc.	Routine maintenance. Replace damaged P1 silt fence.		Pic 2 Desc.	Equipment bridge and surrounding ECDs appear to be in place and functional at stream crossing and resource buffer; snow/ice continues to cover ROW.	
					
36°58'3" N 79°38'9" W 186°S COURSE 169° GPS 2082 Ramsey Memorial Rd, Penhook, VA 24137, United States 01.24.2022 12:57:06 Accur +/-152.9 Ft ALT 824 Ft			36°58'1" N 79°37'52" W 142°SE COURSE 169° GPS Sorry no results found 01.24.2022 13:06:06 Accur +/-222.2 Ft ALT 824 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14934+46		Field Station#	14950+47	
Pic 3 Desc.	Perimeter SSF and CFS in good condition.		Pic 4 Desc.	Equipment bridge and surrounding ECDs appear to be in place and functional at stream crossing and resource buffer; snow/ice continues to cover ROW.	
					
36°57'55" N 79°35'54" W 263°W COURSE -1° GPS Penhook, VA 24137, United States 01.24.2022 10:06:49 Accur +/-141.7 Ft ALT 905 Ft			36°57'54" N 79°35'51" W 162°S COURSE 164° GPS Penhook, VA 24137, United States 01.24.2022 10:11:06 Accur +/-354.6 Ft ALT 860 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15044+86		Field Station#	15055+88	
Pic 5 Desc.	Equipment bridge and surrounding ECDs appear to be in place and functional at stream crossing and resource buffer; snow/ice continues to cover ROW.		Pic 6 Desc.	Equipment bridge and surrounding ECDs appear to be in place and functional at stream crossing and resource buffer; snow/ice continues to cover ROW.	

A/E	124300139	Date/Time	1/24/2022 11:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/24/2022 11:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33604
Inspector	Charles Head			Date/Time	1/25/2022 2:31 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Wet	Temperature (°F)	52.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/25/2022 2:31 PM	Report #	33604
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/25/2022 2:31 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	14694+50	Field Station#	14689+36	Field Station#	14680+30
Pic 1 Desc.	Approximately 14694+50. Overview of road crossing and RCE.	Pic 2 Desc.	Approximately 14689+36. Overview of stream crossing, equipment bridge and ECDs at stream S-H34.	Pic 3 Desc.	Approximately 14680+30. Overview of stream crossing, equipment bridge and ECDs at stream S-H36.
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	14673+10	Field Station#	14655+00	Field Station#	14655+00
Pic 5 Desc.	Approximately 14673+10. Overview of stream crossing, equipment bridge and ECDs at stream S-H37	Pic 6 Desc.	Approximately 14655+00. Overview of ROW. 14689+82-14656+87 ROW has permanent vegetation.		

A/E	124300139	Date/Time	1/25/2022 2:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/25/2022 2:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33606
Inspector	Ben Farmer			Date/Time	1/25/2022 2:53 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Partial	Station End	15584+23
County	Pittsylvania	Ground	Damp	Temperature (°F)	42.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Communication	ROW has been damaged and needs			
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/25/2022 2:53 PM	Report #	33606
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 42F) Rain Gauge= 0.0" 15480+67-15584+23 -EI began inspection at Toshes Rd. -RCEs are in good condition at all road crossings. -Perimeter CFS is in good condition throughout this section. -No evidence of sedimentation from 3rd party disturbance at 15501+00. -P1 is in good condition at all stream and wetland buffers. -3rd party ECDs appear to be in good condition at 15510+00. -CWDs are functioning as intended throughout this area. -Equipment bridge ECDs are in good condition and functioning. -S-MM8 entering ROW contains turbid water. This is a result of 3rd party disturbance up stream and not pipeline construction. -S-CC5 entering ROW contains turbid water. This is a result of upstream disturbance and not pipeline construction. -Waterbars are in good condition throughout this area. -ROW has been damaged and needs to be stabilized at 15572+50. -Slope drain is in good condition at 15575+00 -P1 is in good condition around road pipe outlet at 15584+20. -Vegetation continuing to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/25/2022 2:53 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15490+00	Field Station#	15495+00		
Pic 1 Desc.	Perimeter CFS is in good condition throughout this area.	Pic 2 Desc.	Vegetation continues to fill in throughout this section.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15496+00	Field Station#	15501+00		
Pic 3 Desc.	RCEs are in good condition at all road crossings.	Pic 4 Desc.	No evidence of sedimentation from 3rd party disturbance.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15507+00	Field Station#	15510+00		
Pic 5 Desc.	P1 is in good condition at all stream and wetland buffers.	Pic 6 Desc.	3rd party ECDs appear to be in good condition.		

AFE	124300139	Date/Time	1/25/2022 2:53 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15515+00	Field Station#	15521+00		
Pic 7 Desc.	CWD is in good condition and functioning.	Pic 8 Desc.	S-MM8 entering ROW containing turbid water from upstream disturbance. Not pipeline related.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15521+00	Field Station#	15540+00		
Pic 9 Desc.	S-MM8 entering ROW containing turbid water from upstream disturbance. Not pipeline related.	Pic 10 Desc.	Equipment bridge ECDs are in place and functioning.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15542+11	Field Station#	15548+00		
Pic 11 Desc.	S-CC5 entering ROW containing turbid water from upstream disturbance. Not pipeline related.	Pic 12 Desc.	Waterbars are in good condition.		

A/E	124300139	Date/Time	1/25/2022 2:53 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15572+50	Field Station#	15575+00		
Pic 13 Desc.	ROW has been damaged and needs to be stabilized.	Pic 14 Desc.	Slope drain is in good condition and functioning.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33589
Inspector	Justin Burch			Date/Time	1/25/2022 11:53 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Full	Station End	14311+57
County	Franklin	Ground	Wet	Temperature (°F)	51.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)		Acceptable			
Compost Filter Sock		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar		Acceptable			
Equipment Bridge		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Plunge Pool		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Waterbar End Treatment		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/25/2022 11:53 AM	Report #	33589
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. The EI observed that the contractor has worked in the area since the last SWPPP inspection to install an anode bed and test station at approximately 14183+00. The disturbed areas were seeded and stabilized. Since the last SWPPP inspection the area received one precipitation event with totals of 0.10" at Bonbrook Mill Road #1 and 0.10" at Farm View Road. The ROW ground condition is wet and partially snow/ice covered. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14258+00 to 14277+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/25/2022 11:53 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14294+00	Field Station#	14255+00		
Pic 1 Desc.	P1 silt fence in acceptable condition	Pic 2 Desc.	Perimeter CFS and temporary vegetative stabilization in acceptable conditions		
					
GPS Location	0	GPS Location	0		
Field Station#	14253+00	Field Station#	14213+00		
Pic 3 Desc.	Waterbars in acceptable conditions	Pic 4 Desc.	Equipment bridge in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	14179+00	Field Station#	14240+00		
Pic 5 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions	Pic 6 Desc.	Super silt fence in acceptable condition		

AFE	124300139	Date/Time	1/25/2022 11:53 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14185+00	Field Station#	14307+00		
Pic 7 Desc.	Waterbar end treatment in acceptable condition	Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			





A/E	124300139	Date/Time	1/25/2022 11:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	33612	
Inspector	Frank Craycroft			Date/Time	1/25/2022 3:42 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Muddy	Temperature (°F)	45.00	
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	1/25/2022 3:42 PM	Report #	33612
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All stormwater drain inlets had proper perimeter protection and were free of debris and vegetation. All debris and trash was being kept within bulk dumpsters on-site. All perimeter ECDs were functional and in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/25/2022 3:42 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-048 Temporary vegetation		Pic 2 Desc.	LY-048 South perimeter CFS	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-032 Equipment staging		Pic 4 Desc.	LY-032 Secondary containment	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	LY-033 Staging area		Pic 6 Desc.	LY-033 Equipment staging	

AFE	124300139	Date/Time	1/25/2022 3:42 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	ANC-006 Secondary containment	Pic 8 Desc.	ANC-006 Stormwater drain inlet		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	1/25/2022 3:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33554
Inspector	Ben Davenport			Date/Time	1/25/2022 11:35 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Partial	Station End	15142+66
County	Pittsylvania	Ground	Muddy	Temperature (°F)	49.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Sump Pit	Acceptable				
Compost Filter Sock	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Rock Construction Entrance	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/25/2022 11:35 AM	Report #	33554
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with snowy/muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -Walked ROW looking for potential environmental issues or maintenance requirements -ROW still partially covered in snow in areas -Verified the completion of punch list items from previous inspection -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed of stabilization and vegetation in section both permanent and temporary areas of ROW; no issues observed -Continue to monitor ROW for signs of erosion -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/25/2022 11:35 AM	Report #	
Pictures					
					
36°57'46" N 79°35'35" W 144°SE COURSE 0° GPS 1923-2165 Armstrong Rd, Penhook, VA 24137, United States			01.25.2022 09:42:27 Accur +/-76.1 Ft ALT 0 Ft		
36°57'44" N 79°35'26" W 270°W COURSE 186° GPS Sandy Level, VA 24161, United States			01.25.2022 09:44:52 Accur +/-15.2 Ft ALT 873 Ft		
GPS Location	1	GPS Location	2		
Field Station#	15066+00	Field Station#	15070+00		
Pic 1 Desc.	ROW stabilized and vegetated in temporary area; most snow cover has melted along ROW.		Pic 2 Desc.	Sump pit and CFS end treatment performing intended functions; perimeter P1 silt fence in good condition.	
					
36°57'44" N 79°35'26" W 161°S COURSE -1° GPS Sandy Level, VA 24161, United States			01.25.2022 09:44:39 Accur +/-56.4 Ft ALT 879 Ft		
36°57'18" N 79°34'57" W 355°N COURSE 276° GPS 8776 Museville Rd, Sandy Level, VA 24161, United States			01.25.2022 11:17:01 Accur +/-15.3 Ft ALT 929 Ft		
GPS Location	3	GPS Location	4		
Field Station#	15072+86	Field Station#	15113+25		
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 4 Desc.	Contractor repaired damaged P1 silt fence per punch list item.	
					
36°57'17" N 79°34'53" W 154°SE COURSE 199° GPS 8776 Museville Rd, Sandy Level, VA 24161, United States			01.25.2022 11:18:22 Accur +/-15.2 Ft ALT 892 Ft		
36°56'53" N 79°34'42" W 337°NW COURSE 143° GPS 337-521 Rockcreek Rd, Sandy Level, VA 24161, United States			01.25.2022 10:36:11 Accur +/-15.2 Ft ALT 872 Ft		
GPS Location	5	GPS Location	6		
Field Station#	15119+00	Field Station#	15142+66		
Pic 5 Desc.	Temporary diversion berm stabilized and vegetated.		Pic 6 Desc.	RCE at Rock Creek Rd in good condition.	

A/E	124300139	Date/Time	1/25/2022 11:35 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






A/E	124300139	Date/Time	1/25/2022 11:35 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	33622	
Inspector	Glenn Mike Renfro			Date/Time	1/25/2022 8:42 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00	
State	VA	Inspection Area	Full	Station End	0000+00	
County	Franklin	Ground	Wet	Temperature (°F)	50.00	
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Other - Explain in Comments		Acceptable	Inlet protection for catch basins			
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	1/25/2022 8:42 PM	Report #	33622
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations received .10" of rainfall and site conditions were wet due to melting ice. - All perimeter ECD's were inspected and no problems were found. - The inlet protection for the catch basins at LY-046 were found to be in good condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE, at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/25/2022 8:42 PM	Report #
Pictures				
				
GPS Location	See picture		GPS Location	See picture
Field Station#	0000+00		Field Station#	0000+00
Pic 1 Desc.	Inlet protection for catch basin on south end of LY-046 in good condition.		Pic 2 Desc.	Perimeter ECD's on south end of LY-046 in good condition.
				
GPS Location	See picture		GPS Location	See picture
Field Station#	0000+00		Field Station#	00000+00
Pic 3 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.		Pic 4 Desc.	Perimeter ECD's on north end of LY-045 in acceptable condition.
		<p data-bbox="1040 1539 1250 1566">Insert image here</p>		
GPS Location	See picture		GPS Location	
Field Station#	0000+00		Field Station#	
Pic 5 Desc.	Secondary containment structure for generator behind tent at LY-045 in good condition.		Pic 6 Desc.	

A/E	124300139	Date/Time	1/25/2022 8:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/25/2022 8:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		












Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33607
Inspector	Frank Craycroft			Date/Time	1/25/2022 3:06 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Muddy	Temperature (°F)	45.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Plunge Pool	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/25/2022 3:06 PM	Report #	33607
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of ROW from Chalk Level Rd to Transco. ROW was muddy from on-going snow melt, no signs of erosion were observed. Buffer zones at resources in area are intact and bridges are free of sediment. Waterbars and sumps are draining properly and have additional storage. Vegetation is moderate to good, but stabilizing mediums are still present. All perimeter ECDs were functional and in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/25/2022 3:06 PM	Report #	
Pictures					
	 <p>GPS photo showing CIS S-H5 Buffer zone and ECDs. The photo includes a compass rose at the top with bearings SE, S, SW, W, and NW. The coordinates displayed are 186°S (T) • 36.83352, -79.359803 ±12ft ▲ 509ft. The date and time stamp at the bottom right is 25 Jan 2022 09:47:39.</p>			 <p>GPS photo showing GAS S-H5 ECDs. The photo includes a compass rose at the top with bearings S, SW, W, and NW. The coordinates displayed are 254°SW (T) • 36.833257, -79.359687 ±12ft ▲ 516ft. The date and time stamp at the bottom right is 25 Jan 2022 09:48:03.</p>	
GPS Location	0	GPS Location	0		
Field Station#	15692+00	Field Station#	15963+00		
Pic 1 Desc.	CIS S-H5 Buffer zone and ECDs	Pic 2 Desc.	GAS S-H5 ECDs		
	 <p>GPS photo showing Clean water diversion inlet. The photo includes a compass rose at the top with bearings S, SW, W, and NW. The coordinates displayed are 232°SW (T) • 36.831582, -79.358462 ±12ft ▲ 553ft. The date and time stamp at the bottom right is 25 Jan 2022 09:52:08.</p>			 <p>GPS photo showing Clean water diversion outlet. The photo includes a compass rose at the top with bearings N, NE, E, and SE. The coordinates displayed are 63°NE (T) • 36.831723, -79.358191 ±12ft ▲ 549ft. The date and time stamp at the bottom right is 25 Jan 2022 09:52:59.</p>	
GPS Location	0	GPS Location	0		
Field Station#	15970+00	Field Station#	15970+00		
Pic 3 Desc.	Clean water diversion inlet	Pic 4 Desc.	Clean water diversion outlet		
	 <p>GPS photo showing CIS W-MM3 Buffer zones and Perimeter CFS. The photo includes a compass rose at the top with bearings E, SE, S, and SW. The coordinates displayed are 158°SE (T) • 36.830485, -79.356822 ±12ft ▲ 530ft. The date and time stamp at the bottom right is 25 Jan 2022 09:55:31.</p>			 <p>GPS photo showing S-OO1 Channel and Buffer zones. The photo includes a compass rose at the top with bearings E, SE, S, and SW. The coordinates displayed are 170°S (T) • 36.830342, -79.356585 ±12ft ▲ 502ft. The date and time stamp at the bottom right is 25 Jan 2022 09:55:50.</p>	
GPS Location	0	GPS Location	0		
Field Station#	15975+00	Field Station#	15977+35		
Pic 5 Desc.	CIS W-MM3 Buffer zones and Perimeter CFS	Pic 6 Desc.	S-OO1 Channel and Buffer zones		

AFE	124300139	Date/Time	1/25/2022 3:06 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	15982+00	Field Station#	15985+00	Field Station#	15985+00
Pic 7 Desc.	Temporary vegetation	Pic 8 Desc.	Sump	Pic 8 Desc.	Sump
					
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	15989+00	Field Station#	15998+00	Field Station#	15998+00
Pic 9 Desc.	GAS S-OO2 Buffer zone	Pic 10 Desc.	CIS W-IJ22-PFO Temporary vegetation and perimeter ECDs	Pic 10 Desc.	CIS W-IJ22-PFO Temporary vegetation and perimeter ECDs
					
GPS Location	0	GPS Location		GPS Location	
Field Station#	15997+00	Field Station#		Field Station#	
Pic 11 Desc.	CFS Checks and Waterbar	Pic 12 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	1/25/2022 3:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	33609	
Inspector	Frank Craycroft			Date/Time	1/25/2022 3:11 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Muddy	Temperature (°F)	45.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Sensitive Resource Buffer		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Silt Fence (Reinforce Filter Fence)		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	1/25/2022 3:11 PM	Report #	33609
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed SWPPP inspection of referenced area. All ECDs observed were functional and in good condition. Buffer zone at S-H42 are intact and bridge is free of sediment buildup. Waterbars and sumps are functioning and have additional storage. No signs of erosion or runoff from recent snow melt were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/25/2022 3:11 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	19+00	Field Station#	18+00		
Pic 1 Desc.	Temporary vegetation	Pic 2 Desc.	Perimeter CFS		
					
GPS Location	0	GPS Location	0		
Field Station#	14+00	Field Station#	12+65		
Pic 3 Desc.	GAS S-H42 perimeter ECDs	Pic 4 Desc.	S-H42 Channel and buffer zones		
					
GPS Location	0	GPS Location	0		
Field Station#	12+00	Field Station#	11+00		
Pic 5 Desc.	CIS S-H42 Buffer zone and perimeter ECDs	Pic 6 Desc.	Perimeter CFS		

A/E	124300139	Date/Time	1/25/2022 3:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/25/2022 3:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	33586		
Inspector	Logan Box	Date/Time	1/25/2022 4:34 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Frozen	Temperature (°F)	48.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)		Communication			
Silt Fence (Reinforce Filter Fence)		Communication			
Sump Pit		Communication			
Vegetative Stabilization (Temporary)		Acceptable			
Compost Filter Sock		Acceptable			
Rock Construction Entrance		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/25/2022 4:34 PM	Report #	33586
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections the EI observed locations of P1 that requires routine maintenance, documented and added to the punch list for repairs.</p> <p>Throughout inspection area today the EI observed safety fence around a sump pit that requires maintenance, added to the punch list for repair.</p> <p>Row conditions throughout the inspection area still had amounts of snow as higher temps began to thaw the row.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/25/2022 4:34 PM	Report #	
Pictures					
	East Elevation 			West Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13847+43	Field Station#	13817+55		
Pic 1 Desc.	P1 requires routine maintenance due to being weathered and torn, documented and added to the punch list.		Pic 2 Desc.	Wire backed silt fence requires maintenance, documented and added to the punch list for repairs.	
	East Elevation 				
GPS Location	0000	GPS Location	00000		
Field Station#	13806+90	Field Station#	13847+43		
Pic 3 Desc.	P1 requires maintenance due to fallen debris from recent snow events, documented and added to the punch list for repair.		Pic 4 Desc.	P1 requires routine maintenance due to being weathered and torn, documented and added to the punch list.	
	East Elevation 			North East Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13846+78	Field Station#	13782+44		
Pic 5 Desc.	Stream observation photo facing upstream during routine inspection today. No environmental issues observed at the time of inspection.		Pic 6 Desc.	P1 requires routine maintenance due to being weathered and torn, documented and added to the punch list for repair.	

A/E	124300139	Date/Time	1/25/2022 4:34 PM	Report #	
Pictures					
 <p>North Elevation <small>196°S (T) • 37.069907, -79.932752 ±3 m ▲ 313 m</small></p>		 <p>West Elevation <small>110°E (T) • 37.060637, -79.921094 ±3 m ▲ 291 m</small></p>			
GPS Location	0000	GPS Location	0000		
Field Station#	13785+00	Field Station#	13846+78		
Pic 7 Desc.	Safety fence around sump pit requires maintenance, documented and added to the punch list.		Pic 8 Desc.	Stream observation photo facing downstream during routine inspection today, no environmental issues observed at the time of inspection.	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	1/25/2022 4:34 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I
Contractor	Precision			Report #	33610
Inspector	Frank Craycroft			Date/Time	1/25/2022 3:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00
State	VA	Inspection Area	Full	Station End	24+53
County	Pittsylvania	Ground	Muddy	Temperature (°F)	40.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Plunge Pool		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Sump Pit		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/25/2022 3:13 PM	Report #	33610
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed SWPPP inspection of referenced area. All perimeter ECDs were functional and in good condition. No signs of erosion or runoff from recent snow melt were observed. Waterbars and sumps were functioning properly and have additional storage. Buffer zones at resources in area have not been impacted. No issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/25/2022 3:13 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	2+50	Field Station#	7+50		
Pic 1 Desc.	Temporary stabilization	Pic 2 Desc.	Perimeter CFS		
					
GPS Location	0	GPS Location	0		
Field Station#	8+00	Field Station#	10+00		
Pic 3 Desc.	Sump	Pic 4 Desc.	Temporary vegetation and perimeter CFS		
					
GPS Location	0	GPS Location	0		
Field Station#	15+00	Field Station#	20+00		
Pic 5 Desc.	CIS W-EF6 Vegetation	Pic 6 Desc.	GAS W-IJ21 Vegetation and CFS		

A/E	124300139	Date/Time	1/25/2022 3:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/25/2022 3:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33647
Inspector	Ben Farmer			Date/Time	1/26/2022 11:51 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Frozen	Temperature (°F)	30.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/26/2022 11:51 AM	Report #	33647
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 31F) Rain Gauge= 0.0" 15142+66-15260+00 -EI began inspection at Rockcreek Rd. -RCEs are in good condition at all road crossings. -Perimeter CFS/P1 is in good condition. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00 -P1 is in good condition at stream buffer. -Equipment bridge ECDs are in place and functioning at 15168+19. -Slope drain is functioning as intended at 15170+00. -Waterbars are in good condition throughout this section. -Drainage feature ECDs are in good condition and functioning at 15195+00. -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/26/2022 11:51 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15142+66	Field Station#	15150+00		
Pic 1 Desc.	RCE is in good condition at Rockcreek Rd.	Pic 2 Desc.	Perimeter CFS is in good condition.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15160+00	Field Station#	15165+57		
Pic 3 Desc.	Perimeter P1 is in good condition.	Pic 4 Desc.	Rock inlet remains in good condition.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15166+00	Field Station#	15167+68		
Pic 5 Desc.	Rock outlet remains in good condition.	Pic 6 Desc.	P1 is in good condition at stream buffer.		

AFE	124300139	Date/Time	1/26/2022 11:51 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15167+68		Field Station#	15167+68	
Pic 7 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 8 Desc.	Stream buffer remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15170+00	
Pic 9 Desc.	Slope drain is functioning as intended.		Pic 10 Desc.	Waterbars are in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15195+00		Field Station#	15221+11	
Pic 11 Desc.	Drainage ECDs are in place and functioning.		Pic 12 Desc.	Permanent vegetation remains in good condition.	



A/E	124300139	Date/Time	1/26/2022 11:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33641
Inspector	Justin Burch			Date/Time	1/26/2022 10:20 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Wet	Temperature (°F)	37.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Plunge Pool	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/26/2022 10:20 AM	Report #	33641
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area received one precipitation event with totals of 0.10" at Grassy Hill Road and 0.10" at Bonbrook Mill Road #1. • The ROW ground condition is wet and partially snow/ice covered. • At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13910+00 and from 13921+00 to 13940+00. • At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/26/2022 10:20 AM	Report #	
Pictures					
					
GPS Location			0		
Field Station#			13924+00		
Pic 1 Desc.			Permanent vegetative stabilization in acceptable condition		
GPS Location			0		
Field Station#			13941+00		
Pic 2 Desc.			Clean water diversion pipe and plunge pool in acceptable conditions		
					
GPS Location			0		
Field Station#			13946+00		
Pic 3 Desc.			Waterbar in acceptable condition		
GPS Location			0		
Field Station#			13946+00		
Pic 4 Desc.			Waterbar end treatment in acceptable condition		
					
GPS Location			0		
Field Station#			13943+00		
Pic 5 Desc.			Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		
GPS Location			0		
Field Station#			13853+45		
Pic 6 Desc.			Perimeter CFS and temporary vegetative stabilization in acceptable conditions		

A/E	124300139	Date/Time	1/26/2022 10:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/26/2022 10:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33649
Inspector	Charles Head			Date/Time	1/26/2022 12:05 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Wet	Temperature (°F)	33.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Repair/replace as needed			
3rd Party Damages	Communication	Repair livestock damage to CFS			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to fence			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/26/2022 12:05 PM	Report #	33649
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/26/2022 12:05 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14391+50	Field Station#	14434+01		
Pic 1 Desc.	Approximately 14391+50. Overview of stream crossing, equipment bridge and ECDs at stream S-A41.		Pic 2 Desc.	Approximately 14434+01. Overview of stream crossing, equipment bridge and ECDs at stream S-GH40.	
GPS Location	0	GPS Location	0		
Field Station#	14333+50	Field Station#	14325+00		
Pic 3 Desc.	Approximately 14333+50. Overview of road crossing and RCEs.		Pic 4 Desc.	Approximately 14325+00. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14405+00	Field Station#	14441+00		
Pic 5 Desc.	Approximately 14400+00-14409+00. CFS requires maintenance. Weathered and torn in places and damaged by livestock in places. Replace as needed.		Pic 6 Desc.	Approximately 14441+00. SSF requires maintenance. Reattach fabric to chain link.	

A/E	124300139	Date/Time	1/26/2022 12:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/26/2022 12:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33644
Inspector	John White			Date/Time	1/26/2022 11:21 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Frozen	Temperature (°F)	37.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Contractor is working on repairs			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/26/2022 11:21 AM	Report #	33644
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/26/2022 11:21 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15585+00	Field Station#	15590+00		
Pic 1 Desc.	Observing temporary stabilization,water bar, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization and water bars		
					
GPS Location	O	GPS Location	O		
Field Station#	15619+48	Field Station#	15630+00		
Pic 3 Desc.	Observing road crossing and RCE's	Pic 4 Desc.	Observing temporary stabilization,CWD outlet and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15636+45	Field Station#	15637+50		
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing P1 that requires maintenance		

A/E	124300139	Date/Time	1/26/2022 11:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/26/2022 11:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33654
Inspector	Ben Davenport			Date/Time	1/26/2022 11:18 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Muddy	Temperature (°F)	37.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/26/2022 11:18 AM	Report #	33654
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with snowy/muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 — 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No issues identified at the time of inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/26/2022 11:18 AM	Report #	
Pictures					
					
36°59'17" N 79°42'8" W 283°W COURSE 310° GPS Union Hall, VA 24176, United States 01.26.2022 13:12:02 Accur +/-21.2 Ft ALT 916 Ft			36°59'17" N 79°42'8" W 272°W COURSE 72° GPS Union Hall, VA 24176, United States 01.26.2022 13:11:35 Accur +/-56.0 Ft ALT 925 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14716+15		Field Station#	14716+92	
Pic 1 Desc.	Contractor replaced perimeter CFS in resource buffer per punch list item.		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	
					
36°59'16" N 79°42'5" W 134°SE COURSE 67° GPS Union Hall, VA 24176, United States 01.26.2022 13:13:52 Accur +/-82.6 Ft ALT 911 Ft			36°58'55" N 79°41'13" W 136°SE COURSE 233° GPS Union Hall, VA 24176, United States 01.26.2022 13:26:12 Accur +/-26.8 Ft ALT 920 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14721+00		Field Station#	14769+52	
Pic 3 Desc.	Water bar performing intended function; ROW stabilized and vegetated in temporary area.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	
					
36°58'46" N 79°41'6" W 243°SW COURSE 289° GPS 423 Zeigler Ln, Union Hall, VA 24176, United States 01.26.2022 13:34:48 Accur +/-175.3 Ft ALT 870 Ft			36°58'45" N 79°41'3" W 130°SE COURSE 156° GPS 423 Zeigler Ln, Union Hall, VA 24176, United States 01.26.2022 13:33:30 Accur +/-127.3 Ft ALT 939 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14778+00		Field Station#	14782+25	
Pic 5 Desc.	Sump pit and CFS end treatment performing intended functions.		Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	

A/E	124300139	Date/Time	1/26/2022 11:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/26/2022 11:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33655
Inspector	Ben Davenport			Date/Time	1/27/2022 11:28 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Muddy	Temperature (°F)	34.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Equipment Bridge	Acceptable				
Sediment Filter Log	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Compost Filter Sock	Acceptable				
Sump Pit	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/27/2022 11:28 AM	Report #	33655
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Performed SWPPP inspection on portion of MVP Spread I project -Inspection covered area between station# 14802+19–14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Sunny with muddy/snowy ground conditions during inspection -Contractor digging up pipe and installing anode beds between Bar Ridge Rd and Ramsey Memorial Rd -Contractor seeded and straw mulched areas of disturbance -Many ECDs along ROW still under snow; inspected those visible; no issues observed -Inspection observed condition of perimeter controls and ECDs in section; no issues observed -Inspection observed condition of equipment bridges and ECDs around stream crossings and resource buffers; no issues observed -Inspection observed condition of RCEs and culverts at road crossings in section; no issues observed -No items added to environmental punch list -No issues observed at the time of inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/27/2022 11:28 AM	Report #	
Pictures					
					
36°58'9" N 79°38'49" W 267°W COURSE 216° GPS Penhook, VA 24137, United States 01.27.2022 11:38:13 Accur +/-224.7 Ft ALT 841 Ft			36°58'9" N 79°38'49" W 6°N COURSE -1° GPS Penhook, VA 24137, United States 01.27.2022 11:56:21 Accur +/-93.2 Ft ALT 839 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14901+00	Field Station#	14912+00		
Pic 1 Desc.	Contractor installing anode beds; areas of disturbance were seeded and stabilized.		Pic 2 Desc.	Contractor installing anode beds; areas of disturbance were seeded and stabilized.	
					
36°58'8" N 79°38'41" W 294°W COURSE 288° GPS Sorry no results found 01.27.2022 11:32:15 Accur +/-93.1 Ft ALT 773 Ft			36°58'7" N 79°38'32" W 53°NE COURSE 256° GPS Sorry no results found 01.27.2022 11:28:18 Accur +/-26.8 Ft ALT 771 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14907+52	Field Station#	14915+96		
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; much of ROW still covered in snow.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; much of ROW still covered in snow.	
					
36°58'9" N 79°38'50" W 345°N COURSE 216° GPS Penhook, VA 24137, United States 01.27.2022 11:44:15 Accur +/-176.5 Ft ALT 841 Ft			36°58'6" N 79°38'25" W 138°SE COURSE 92° GPS Penhook, VA 24137, United States 01.27.2022 12:01:04 Accur +/-216.5 Ft ALT 847 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14890+00	Field Station#	14924+00		
Pic 5 Desc.	Sump pit and CFS end treatment performing intended functions.		Pic 6 Desc.	ROW stabilized and vegetated in temporary and permanent areas; much snow cover still observed.	

A/E	124300139	Date/Time	1/27/2022 11:28 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/27/2022 11:28 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33684
Inspector	Justin Burch			Date/Time	1/27/2022 11:01 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Frozen	Temperature (°F)	41.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Slope Drain Pipe	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
Waterbar	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Communication				
Vegetative Stabilization (Permanent)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/27/2022 11:01 AM	Report #	33684
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). One issue was submitted for the punch list consisting of a location where P1 silt fence fabric was deteriorated. Other inspected ECDs were observed as being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has not received a precipitation event. The ROW ground condition is frozen and partially snow/ice covered. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14011+00 to 14018+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/27/2022 11:01 AM	Report #	
Pictures					
 <p>279°W (T) 37°3'58"N, 79°52'36"W ±62ft ▲1151ft</p> <p>14057+00 01-27-2022, 09:06:12</p>			 <p>318°NW (T) 37°3'56"N, 79°52'38"W ±65ft ▲1167ft</p> <p>14054+00 01-27-2022, 09:07:58</p>		
GPS Location	00		GPS Location	0	
Field Station#	14057+00		Field Station#	14054+00	
Pic 1 Desc.	Slope drain pipe and sump pit in acceptable conditions		Pic 2 Desc.	Waterbar end treatment in acceptable condition	
 <p>253°W (T) 37°3'51"N, 79°52'38"W ±118ft ▲1171ft</p> <p>14049+00 01-27-2022, 09:11:52</p>			 <p>152°SE (T) 37°3'48"N, 79°52'41"W ±36ft ▲1158ft</p> <p>14045+71 01-27-2022, 09:35:24</p>		
GPS Location	0		GPS Location	0	
Field Station#	14049+00		Field Station#	14045+71	
Pic 3 Desc.	Waterbar in acceptable condition		Pic 4 Desc.	Equipment bridge in acceptable condition	
 <p>133°SE (T) 37°3'39"N, 79°52'51"W ±154ft ▲1083ft</p> <p>14035+00 01-27-2022, 09:56:29</p>			 <p>244°SW (T) 37°3'22"N, 79°52'56"W ±88ft ▲1043ft</p> <p>14011+00 01-27-2022, 10:35:44</p>		
GPS Location	0		GPS Location	0	
Field Station#	14035+00		Field Station#	14011+00	
Pic 5 Desc.	Super silt fence in acceptable condition		Pic 6 Desc.	P1 silt fence is deteriorated (4 panels)	

A/E	124300139	Date/Time	1/27/2022 11:01 AM	Report #	
Pictures					
  <p>14014+00 01-27-2022, 10:11:13</p>		  <p>13963+00 01-27-2022, 10:56:33</p>			
GPS Location	0	GPS Location	0		
Field Station#	14014+00	Field Station#	13963+00		
Pic 7 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	1/27/2022 11:01 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33687
Inspector	Ben Farmer			Date/Time	1/27/2022 12:12 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Frozen	Temperature (°F)	24.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Livestock			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Livestock			
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/27/2022 12:12 PM	Report #	33687
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 24F) Rain Gauge= 0.0" 15260+00-15370+62 -EI began inspection at Oxford Rd. -RCEs are in good condition at all road crossings. -CWD is in good condition at 15299+00. -Perimeter P1 has been damaged by livestock and needs to be replaced at 15310+90. -CFS has been displaced by livestock and needs to be restaked at 15311+00. -P1 remains in good condition at 15311+87. -P1 is in good condition at all stream buffers. -Resource buffers remain in good condition. -CWD is in good condition at 15338+00. -Waterbars are in good condition. -Equipment bridge ECDs are in place and functioning -MVP-PI-332 is in good condition with controls in place. -Vegetation continues to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/27/2022 12:12 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15296+00		Field Station#	15299+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings.		Pic 2 Desc.	CWD is in good condition and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15310+90		Field Station#	15311+87	
Pic 3 Desc.	Perimeter P1 has been damaged by livestock and needs to be replaced		Pic 4 Desc.	Perimeter CFS has been displaced by livestock and needs to be restaked.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15311+87		Field Station#	15314+50	
Pic 5 Desc.	Wetland buffer P1 is in good condition.		Pic 6 Desc.	P1 is in good condition at all stream buffers.	

AFE	124300139	Date/Time	1/27/2022 12:12 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15338+00		Field Station#	15345+00	
Pic 7 Desc.	CWD is functioning as intended.		Pic 8 Desc.	Waterbars are in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15346+90		Field Station#	15346+87	
Pic 9 Desc.	Resource buffers remain in good condition.		Pic 10 Desc.	Equipment bridge ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15350+00		Field Station#	15360+00	
Pic 11 Desc.	MVP-PI-332 is in good condition with controls in place.		Pic 12 Desc.	Vegetation continues to fill in throughout this section.	

A/E	124300139	Date/Time	1/27/2022 12:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33686
Inspector	John White			Date/Time	1/27/2022 11:45 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Frozen	Temperature (°F)	37.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Contractor is working on repairs			
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Vegetative Stabilization (Temporary)	Communication	Third party caused rutting along RO			
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/27/2022 11:45 AM	Report #	33686
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/27/2022 11:45 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15740+00	Field Station#	15738+00		
Pic 1 Desc.	Observing temporary stabilization, sump and end treatment	Pic 2 Desc.	Observing CFS that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15720+00	Field Station#	15713+52		
Pic 3 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 4 Desc.	Observing temporary stabilization, water bar, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15693+89	Field Station#	15671+93		
Pic 5 Desc.	Observing road crossing and RCE's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

A/E	124300139	Date/Time	1/27/2022 11:45 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15699+00	Field Station#	15734+00		
Pic 7 Desc.	Observing ruts that need to be repaired and restabilized	Pic 8 Desc.	Observing safety fence that requires maintenance		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	1/27/2022 11:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33690
Inspector	Charles Head			Date/Time	1/27/2022 1:37 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Wet	Temperature (°F)	37.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/27/2022 1:37 PM	Report #	33690
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection. Some areas of ROW clear of snow and ice and some areas are still covered by solid ice.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/27/2022 1:37 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14546+33	Field Station#	14524+75		
Pic 1 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.		Pic 2 Desc.	Approximately 14524+75. Overview of road crossing and RCEs.	
GPS Location	0	GPS Location	0		
Field Station#	14528+00	Field Station#	14518+00		
Pic 3 Desc.	Approximately 14528+00. Overview of ROW.		Pic 4 Desc.	Approximately 14518+00. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14486+60	Field Station#	14470+00		
Pic 5 Desc.	Approximately 14486+60. Overview of stream crossing, equipment bridge and ECDs at stream S-G20.		Pic 6 Desc.	Approximately 14470+00. Overview of ROW.	

A/E	124300139	Date/Time	1/27/2022 1:37 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/27/2022 1:37 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	33680		
Inspector	Logan Box	Date/Time	1/28/2022 3:47 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Frozen	Temperature (°F)	43.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Rock Construction Entrance		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Equipment Bridge		Acceptable			
Sump Pit		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/28/2022 3:47 PM	Report #	33680
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p> <p>Rain/snow events in the forecast for today, all ECDs were functioning prior to the the events .</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/28/2022 3:47 PM	Report #	
Pictures					
	 <p>South Elevation <small>24°N (T) • 37.075597, -79.94013 ±3 m ▲ 325 m</small></p>			 <p>South West Elevation <small>59°NE (T) • 37.086083, -79.948684 ±3 m ▲ 311 m</small></p>	
GPS Location	00000	GPS Location	0000		
Field Station#	13746+20	Field Station#	13690+00		
Pic 1 Desc.	Monitored ECDs along the edge of row. No environmental issues observed at the time of inspection I		Pic 2 Desc.	Row photo showing equipment mats and vegetation. No environmental issues observed at the time of inspection.	
	 <p>South West Elevation <small>72°NE (T) • 37.078717, -79.941336 ±3 m ▲ 332 m</small></p>			 <p>South East Elevation <small>342°NW (T) • 37.077836, -79.939433 ±4 m ▲ 339 m</small></p>	
GPS Location	0000	GPS Location	00000		
Field Station#	13729+00	Field Station#	13738+00		
Pic 3 Desc.	Observed ECDs on hill side above stream crossing, all functioning at the time of inspection.		Pic 4 Desc.	Monitored ECDs along the edge of row. No environmental issues observed at the time of inspection I	
	 <p>South Elevation <small>15°N (T) • 37.078563, -79.940827 ±4 m ▲ 331 m</small></p>			 <p>South West Elevation <small>49°NE (T) • 37.078751, -79.941317 ±6 m ▲ 322 m</small></p>	
GPS Location	0000	GPS Location	0000		
Field Station#	13732+80	Field Station#	13729+99		
Pic 5 Desc.	Monitored ECDs along the edge of row. No environmental issues observed at the time of inspection I		Pic 6 Desc.	Row photo up hill from stream crossing, ECDs and equipment bridge in place, no environmental issues observed at the time of inspection	

A/E	124300139	Date/Time	1/28/2022 3:47 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/28/2022 3:47 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33695
Inspector	Ben Davenport			Date/Time	1/28/2022 10:48 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Frozen	Temperature (°F)	36.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Routine maintenance; landowner da			
Compost Filter Sock	Communication	Routine maintenance; cattle damage			
Other - Explain in Comments	Communication	Routine maintenance; cattle damage			
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Plunge Pool	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/28/2022 10:48 AM	Report #	33695
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Cloudy with snowy/muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14928+52 —15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Walked ROW looking for potential environmental issues or maintenance requirements -Contractor installing anode beds near Ramsey Memorial Rd during inspection -Verified the completion of punch list item from previous inspection -Perimeter controls and ECD's were inspected; 3 issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed of stabilization and vegetation in section both permanent and temporary areas of ROW; ROW remains frozen/covered in snow in some areas; no issues observed -Continue to monitor ROW for signs of erosion -3 items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/28/2022 10:48 AM	Report #	
Pictures					
					
36°57'56" N 79°37'12" W 300°NW COURSE 312' GPS 19100-19382 Snow Creek Rd, Penhook, VA 24137, United States 01.28.2022 08:59:20 Accur +/-23.7 Ft ALT 942 Ft			36°57'54" N 79°37'4" W 101°E COURSE 52' GPS 101-119 Ashworth Rd, Penhook, VA 24137, United States 01.28.2022 08:54:10 Accur +/-27.6 Ft ALT 929 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14982+50	Field Station#	14988+00		
Pic 1 Desc.	Routine maintenance. Replace damaged perimeter CFS from landowner damage.		Pic 2 Desc.	Routine maintenance. Replace damaged CFS triple stack from cattle damage.	
					
36°57'53" N 79°37'3" W 60°NE COURSE 172' GPS 101-119 Ashworth Rd, Penhook, VA 24137, United States 01.28.2022 08:56:04 Accur +/-406.9 Ft ALT 935 Ft			36°57'53" N 79°37'2" W 101°E COURSE 106' GPS 101-119 Ashworth Rd, Penhook, VA 24137, United States 01.28.2022 08:55:08 Accur +/-68.6 Ft ALT 929 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14988+50	Field Station#	14991+62		
Pic 3 Desc.	Routine maintenance. Repair damaged cattle fence from cattle damage.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	
					
36°57'55" N 79°37'10" W 90°E COURSE 98' GPS 19101-19383 Snow Creek Rd, Penhook, VA 24137, United States 01.28.2022 08:51:47 Accur +/-15.4 Ft ALT 940 Ft			36°57'57" N 79°37'17" W 229°SW COURSE -1' GPS Penhook, VA 24137, United States 01.28.2022 08:49:25 Accur +/-21.1 Ft ALT 942 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14983+25	Field Station#	14973+00		
Pic 5 Desc.	Plunge pool performing intended function.		Pic 6 Desc.	ROW stabilized and vegetated in final cleanup and temporary areas; some snow still covering portions of ROW.	

A/E	124300139	Date/Time	1/28/2022 10:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/28/2022 10:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33732
Inspector	John White			Date/Time	1/28/2022 12:04 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Frozen	Temperature (°F)	37.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Contractor is working on repairs			
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/28/2022 12:04 PM	Report #	33732
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/28/2022 12:04 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15826+77	Field Station#	15816+00		
Pic 1 Desc.	Observing road crossing and RCE's	Pic 2 Desc.	Observing CFS that requires maintenance		
					
GPS Location	O	GPS Location	O		
Field Station#	15816+00	Field Station#	15794+77		
Pic 3 Desc.	Observing CFS that requires maintenance	Pic 4 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15825+00	Field Station#	15781+22		
Pic 5 Desc.	Observing temporary stabilization,plunge pool and ECD's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

AFE	124300139	Date/Time	1/28/2022 12:04 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15858+00	Field Station#	15860+00		
Pic 7 Desc.	Observing temporary stabilization, water bar and CFS checks	Pic 8 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15924+00	Field Station#	15851+55		
Pic 9 Desc.	Observing tree that needs to be removed and CFS that requires maintenance	Pic 10 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/28/2022 12:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33731
Inspector	Charles Head			Date/Time	1/28/2022 12:00 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Damp	Temperature (°F)	39.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/28/2022 12:00 PM	Report #	33731
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/28/2022 12:00 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14646+00	Field Station#	14599+00		
Pic 1 Desc.	Approximately 14646+00. Overview of ROW.		Pic 2 Desc.	Approximately 14599+00. Overview of road crossing and RCEs.	
					
GPS Location	0	GPS Location	0		
Field Station#	14582+85	Field Station#	14576+00		
Pic 3 Desc.	Approximately 14582+85. Overview of stream crossing, equipment bridge and ECDs at stream S-E17.		Pic 4 Desc.	Approximately 14576+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14568+10	Field Station#	14555+00		
Pic 5 Desc.	Approximately 14568+10. Overview of stream crossing, equipment bridge and ECDs at stream S-E18.		Pic 6 Desc.	Approximately 14555+00. Overview of ROW.	


A/E	124300139	Date/Time	1/28/2022 12:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/28/2022 12:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33733
Inspector	Ben Farmer			Date/Time	1/28/2022 12:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Frozen	Temperature (°F)	28.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/28/2022 12:22 PM	Report #	
Pictures					
					
GPS Location		See photo			
Field Station#		15371+00			
Pic 1 Desc.		This area remains stabilized.			
					
GPS Location		See photo			
Field Station#		15380+00			
Pic 3 Desc.		Waterbars are in good condition.			
					
GPS Location		See photo			
Field Station#		15384+74			
Pic 5 Desc.		Equipment bridge ECDs are in good condition.			
					
GPS Location		See photo			
Field Station#		15375+00			
Pic 2 Desc.		Drainage ECDs are in good condition and functioning.			
					
GPS Location		See photo			
Field Station#		15384+74			
Pic 4 Desc.		P1 is in good condition at all stream and wetland buffers.			
					
GPS Location		See photo			
Field Station#		15426+70			
Pic 6 Desc.		Resource buffers remain in good condition.			

AFE	124300139	Date/Time	1/28/2022 12:22 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15445+00		Field Station#	15453+00	
Pic 7 Desc.	Perimeter CFS is in good condition.		Pic 8 Desc.	CWD is functioning as intended.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15457+00		Field Station#	15460+81	
Pic 9 Desc.	No evidence of sedimentation from 3rd party disturbance within drainage feature.		Pic 10 Desc.	CWD is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15460+81		Field Station#	15465+00	
Pic 11 Desc.	No evidence of sedimentation from 3rd party disturbance into CWD inlet.		Pic 12 Desc.	No evidence of sedimentation from 3rd party disturbance.	







AFE	124300139	Date/Time	1/28/2022 12:22 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location			
Field Station#	15475+00	Field Station#			
Pic 13 Desc.	3rd party rock outlet appears to be in good condition along this drainage.	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33734
Inspector	Justin Burch			Date/Time	1/28/2022 12:26 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Wet	Temperature (°F)	41.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Sump Pit	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/28/2022 12:26 PM	Report #	33734
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area has not received a precipitation event. • The ROW ground condition is wet and partially snow/ice covered. • At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/28/2022 12:26 PM	Report #			
Pictures							
							
GPS Location		0		GPS Location		0	
Field Station#		14082+00		Field Station#		14082+00	
Pic 1 Desc.		Waterbar in acceptable condition		Pic 2 Desc.		Waterbar end treatment in acceptable condition	
							
GPS Location		0		GPS Location		0	
Field Station#		14095+00		Field Station#		14128+00	
Pic 3 Desc.		Temporary vegetative stabilization in acceptable condition		Pic 4 Desc.		Clean water diversion berm and temporary vegetative stabilization in acceptable conditions	
							
GPS Location		0		GPS Location		0	
Field Station#		14090+00		Field Station#		14128+00	
Pic 5 Desc.		Sump pit in acceptable condition		Pic 6 Desc.		Perimeter CFS in acceptable condition	

A/E	124300139	Date/Time	1/28/2022 12:26 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14094+00	Field Station#	14157+00		
Pic 7 Desc.	Super silt fence in acceptable condition	Pic 8 Desc.	Slope drain pipe and sump pit in acceptable conditions		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	0	GPS Location			
Field Station#	14164+00	Field Station#			
Pic 9 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 10 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	1/28/2022 12:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	33645
Inspector	John White			Date/Time	1/25/2022 11:44 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Frozen	Temperature (°F)	46.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	1/25/2022 11:44 AM	Report #	33645
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	1/25/2022 11:44 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 1 Desc.	Observing RCE	Pic 2 Desc.	Observing temporary stabilization and rock check dam		
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 3 Desc.	Observing temporary stabilization and lay down yard	Pic 4 Desc.	Observing temporary stabilization, storm water pond and ECD's		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300113	Date/Time	1/25/2022 11:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	1/25/2022 11:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		