



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34654
Inspector	Ben Farmer			Date/Time	2/21/2022 2:45 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Partial	Station End	15947+64
County	Pittsylvania	Ground	Dry	Temperature (°F)	40.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/21/2022 2:45 PM	Report #	34654
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 33F) Rain Gauge= 0.0" 15772+27-15947+64 -EI began inspection at Dual Track Rd. -RCEs are in good condition at all road crossings. -Drainage ECDs are in place and functioning -Waterbars are functioning as intended throughout this section. -Equipment bridge ECDs are in place and in good condition. -Stream and wetland buffers remain well vegetated. -Perimeter CFS is in good condition. -CWDs are in good condition and functioning. -Vegetation continues to fill in throughout this section of ROW					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/21/2022 2:45 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15772+27		Field Station#	15775+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings.		Pic 2 Desc.	Drainage ECDs are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15781+22		Field Station#	15782+00	
Pic 3 Desc.	P1 is in good condition at all stream and wetland buffers		Pic 4 Desc.	Waterbars are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15826+77		Field Station#	15835+00	
Pic 5 Desc.	Perimeter P1 is in good condition		Pic 6 Desc.	Drainage ECDs are in good condition and functioning	

AFE	124300139	Date/Time	2/21/2022 2:45 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15836+00	Field Station#	15852+00		
Pic 7 Desc.	CFS checks are functioning as intended	Pic 8 Desc.	Resource buffers remain well vegetated		
GPS Location	See photo	GPS Location	See photo		
Field Station#	15934+00	Field Station#	15935+00		
Pic 9 Desc.	CWDs are functioning as intended	Pic 10 Desc.	Vegetation continues to fill in throughout this section		
		Insert image here			
GPS Location	See photo	GPS Location			
Field Station#	15941+00	Field Station#			
Pic 11 Desc.	Perimeter CFS is in good condition	Pic 12 Desc.			


A/E	124300139	Date/Time	2/21/2022 2:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34644
Inspector	Logan Box			Date/Time	2/21/2022 4:00 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Damp	Temperature (°F)	48.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication				
Vegetative Stabilization (Temporary)	Acceptable				
Rock Construction Entrance	Acceptable				
Timber Mat	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/21/2022 4:00 PM	Report #	34644
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspection the EI observed several locations of P1 that requires maintenance due to broken stakes and wildlife damage, EI Documented and added to the punch list for repair.</p> <p>During inspection today the EI observed 2 sections of P1 that was damaged from 3rd party activities , documented and added to the punch list for repair by the contractor.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/21/2022 4:00 PM	Report #	
Pictures					
	South West Elevation <small>45°NE (T) • 37.084599, -79.947618 ±3 m ▲ 311 m</small> 			West Elevation <small>88°E (T) • 37.084575, -79.947571 ±3 m ▲ 311 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13695+22	Field Station#	13695+95		
Pic 1 Desc.	Photo showing ECDs and vegetation, no environmental issues observed at the time of inspection.		Pic 2 Desc.	P1 requires maintenance due to wildlife damage, documented and added to the punch list for repair.	
	South West Elevation <small>58°NE (T) • 37.082892, -79.946043 ±3 m ▲ 308 m</small> 			South West Elevation <small>43°NE (T) • 37.084437, -79.947506 ±3 m ▲ 314 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13705+07	Field Station#	13696+03		
Pic 3 Desc.	P1 requires maintenance due to 3rd party damages, documented and added to the punch list.		Pic 4 Desc.	P1 requires maintenance due to broken stakes, documented and added to the punch list for repair.	
	West Elevation <small>118°E (T) • 37.079027, -79.941876 ±3 m ▲ 303 m</small> 			South East Elevation <small>318°NW (T) • 37.079034, -79.941873 ±4 m ▲ 302 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13728+11	Field Station#	13728+11		
Pic 5 Desc.	Stream observation photo facing downstream during routine inspection today. No environmental issues observed at the time of inspection.		Pic 6 Desc.	Stream observation photo facing upstream during routine inspection today, no environmental issues observed at the time of inspection.	

A/E	124300139	Date/Time	2/21/2022 4:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/21/2022 4:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	34646		
Inspector	Justin Burch	Date/Time	2/21/2022 12:34 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Wet	Temperature (°F)	63.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.30
			Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Compost Filter Sock		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Equipment Bridge		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/21/2022 12:34 PM	Report #	34646
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed the items on the punch list. Since the last SWPPP inspection the area has received one precipitation event with totals of 0.30" at Bonbrook Mill Road #1 and 0.50" at Farm View Road. The ROW ground condition is wet. At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/21/2022 12:34 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14152+00	Field Station#	14152+00		
Pic 1 Desc.	Waterbar in acceptable condition	Pic 2 Desc.	Waterbar end treatment in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	14150+00	Field Station#	14145+00		
Pic 3 Desc.	Temporary vegetative stabilization and perimeter CFS in acceptable conditions	Pic 4 Desc.	Super silt fence in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	14105+28	Field Station#	14118+00		
Pic 5 Desc.	P1 silt fence and equipment bridge in acceptable conditions	Pic 6 Desc.	Permanent vegetative stabilization in acceptable condition		

A/E	124300139	Date/Time	2/21/2022 12:34 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/21/2022 12:34 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34620
Inspector	Ben Davenport			Date/Time	2/21/2022 11:36 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Damp	Temperature (°F)	61.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Routine maintenance			
Compost Filter Sock	Communication	Routine maintenance			
Plunge Pool	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/21/2022 11:36 AM	Report #	34620
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14928+52 —15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Walked ROW looking for potential environmental issues or maintenance requirements -Verified the completion of punch list items in covered area from previous inspection -Perimeter controls and ECDs were inspected; 2 issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed of stabilization and vegetation in section both permanent and temporary areas of ROW; no issues observed -Continue to monitor ROW for signs of erosion -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/21/2022 11:36 AM	Report #	
Pictures					
					
36°57'55" N 79°36'4" W 287°W COURSE 346° GPS Penhook, VA 24137, United States 02.21.2022 10:51:35 Accur +/-771.1 Ft ALT 799 Ft			36°57'55" N 79°36'4" W 187°S COURSE 81° GPS Penhook, VA 24137, United States 02.21.2022 10:52:19 Accur +/-24.2 Ft ALT 818 Ft		
GPS Location	1		GPS Location	2	
Field Station#	15039+00		Field Station#	15040+00	
Pic 1 Desc.	Routine maintenance. Reattach geotextile fabric to SSF fencing.		Pic 2 Desc.	Routine maintenance. Repair/replace damaged CFS triple stack.	
					
36°57'57" N 79°37'21" W 266°W COURSE 12° GPS Penhook, VA 24137, United States 02.21.2022 11:29:02 Accur +/-15.4 Ft ALT 916 Ft			36°57'56" N 79°36'16" W 285°W COURSE -1° GPS Penhook, VA 24137, United States 02.21.2022 10:56:54 Accur +/-43.1 Ft ALT 804 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14975+00		Field Station#	15025+98	
Pic 3 Desc.	Plunge pool and perimeter controls performing intended functions.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	
					
36°57'55" N 79°35'55" W 319°NW COURSE 8° GPS Penhook, VA 24137, United States 02.21.2022 10:46:44 Accur +/-122.9 Ft ALT 863 Ft			36°57'51" N 79°35'45" W 182°S COURSE 8° GPS Penhook, VA 24137, United States 02.21.2022 10:42:42 Accur +/-388.6 Ft ALT 863 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15044+86		Field Station#	15053+00	
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 6 Desc.	Perimeter P1 silt fence in good condition. ROW stabilized and vegetated in temporary area.	

A/E	124300139	Date/Time	2/21/2022 11:36 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/21/2022 11:36 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34648
Inspector	Charles Head			Date/Time	2/21/2022 1:52 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
3rd Party Damages	Communication	Repair P-1 damaged by wildlife			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Repair weathered and damaged fen			
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to chain link			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	2/21/2022 1:52 PM	Report #	34648
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/21/2022 1:52 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14576+00	Field Station#	14599+00		
Pic 1 Desc.	Approximately 14576+00. Overview of ROW.		Pic 2 Desc.	Approximately 14599+00. Overview of road crossing and RCEs.	
					
GPS Location	0	GPS Location	0		
Field Station#	14582+85	Field Station#	14611+25		
Pic 3 Desc.	Approximately 14582+85. Overview of stream crossing, equipment bridge and ECDs at stream S-E17.		Pic 4 Desc.	Approximately 14611+25. Overview of stream crossing, equipment bridge and ECDs at stream S-E14.	
					
GPS Location	0	GPS Location	0		
Field Station#	14547+50	Field Station#	14583+60		
Pic 5 Desc.	Approximately 14547+50. SSF requires maintenance.		Pic 6 Desc.	Approximately 14583+60. P-1 requires maintenance. Weathered and damaged by wildlife.	

A/E	124300139	Date/Time	2/21/2022 1:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/21/2022 1:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34651
Inspector	Ben Farmer			Date/Time	2/21/2022 2:27 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Dry	Temperature (°F)	33.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	P1 is degraded and needs to be rep			
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	2/21/2022 2:27 PM	Report #	34651
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 33F) Rain Gauge= 0.0" 15370+62-15480+67 -El began inspection at Snowberry Rd. -RCEs are in good condition at all road crossings. -Drainage ECDs are in place and functioning at 15375+00. -P1 is degraded and needs to be replaced with CFS at 15375+00-15377+00. -Waterbars are functioning as intended throughout this section. -Equipment bridge ECDs are in place and in good condition. -Stream and wetland buffers remain well vegetated. -Perimeter CFS is in good condition. -Buffer P1 is degraded and needs to be replaced at 15447+50 and 15448+00. -CWD is in good condition at 15453+00 with no evidence of sedimentation from 3rd party disturbance. -Drainage ECDs are in good condition at 15457+00 with no evidence of sedimentation from 3rd party disturbance. -CWD is in good condition at 15460+81. No evidence of sedimentation from 3rd party rock outlet into CWD inlet. -No evidence of sedimentation from 3rd party rock outlet at 15465+00. -3rd party rock outlet appears to be in good condition along drainage feature at 15475+00. -Vegetation continues to fill in throughout this section of ROW *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/21/2022 2:27 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15370+62		Field Station#	15375+00	
Pic 1 Desc.	RCEs are in good condition at all stream and wetland buffers		Pic 2 Desc.	Drainage ECDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15375+00		Field Station#	15380+00	
Pic 3 Desc.	Perimeter P1 is degraded and needs to be replaced with CFS		Pic 4 Desc.	Waterbars are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15384+74		Field Station#	15427+43	
Pic 5 Desc.	Equipment bridge ECDs are in place and functioning		Pic 6 Desc.	Resource buffers remain well vegetated	

AFE	124300139	Date/Time	2/21/2022 2:27 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15439+00		Field Station#	15445+00	
Pic 7 Desc.	Vegetation continues to fill in throughout this section		Pic 8 Desc.	Perimeter CFS is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15447+50		Field Station#	15448+00	
Pic 9 Desc.	P1 is degraded and needs to be replaced		Pic 10 Desc.	P1 is degraded and needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15453+00		Field Station#	15457+00	
Pic 11 Desc.	CWD remains in good condition		Pic 12 Desc.	No evidence of sedimentation from 3rd party disturbance within drainage feature	

AFE	124300139	Date/Time	2/21/2022 2:27 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15460+81	Field Station#	15460+81		
Pic 13 Desc.	CWD is functioning as intended	Pic 14 Desc.	No evidence of sedimentation from 3rd party disturbance into CWD inlet		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	15465+00	Field Station#			
Pic 15 Desc.	No evidence of sedimentation from 3rd party disturbance.	Pic 16 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	34690		
Inspector	Logan Box	Date/Time	2/22/2022 4:19 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Wet	Temperature (°F)	62.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
			Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Rock Construction Entrance		Acceptable			
Compost Filter Sock		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/22/2022 4:19 PM	Report #	34690
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row where accessible during rain events,, monitored vegetation growth throughout.</p> <p>Inspected stream and wetland areas that were accessible during light rain events.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspection there were no environmental issues observed at the time of inspection.</p> <p>Light rain events continued throughout the day.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/22/2022 4:19 PM	Report #	
Pictures					
	West Elevation 91°E (T) • 37.069016, -79.924063 ±3 m ▲ 311 m 			East Elevation 282°W (T) • 37.065967, -79.922519 ±3 m ▲ 317 m 	
GPS Location	0000	GPS Location	0000		
Field Station#	13814+43	Field Station#	13826+90		
Pic 1 Desc.	Monitored RCEs and row conditions during light rain events throughout today, no environmental issues observed at the time of inspection.		Pic 2 Desc.	Monitored RCEs and row conditions during light rain events throughout today, no environmental issues observed at the time of inspection.	
	East Elevation 260°W (T) • 37.058405, -79.922349 ±3 m ▲ 310 m 			South West Elevation 73°NE (T) • 37.068788, -79.932824 ±8 m ▲ 318 m 	
GPS Location	0000	GPS Location	0000		
Field Station#	13852+46	Field Station#	13784+35		
Pic 3 Desc.	Monitored RCEs and row conditions during light rain events throughout today, no environmental issues observed at the time of inspection.		Pic 4 Desc.	Row photo of work space during light rain events today. No environmental issues observed at the time of inspection.	
	East Elevation 298°W (T) • 37.065842, -79.932329 ±3 m ▲ 330 m 			South East Elevation 322°NW (T) • 37.06597, -79.922519 ±3 m ▲ 316 m 	
GPS Location	0000	GPS Location	0000		
Field Station#	13784+35	Field Station#	13826+95		
Pic 5 Desc.	Monitored ECDs along access roads during light rain events today, all functioning at the time of inspection.		Pic 6 Desc.	Row photo during light rain events, photo showing vegetation, no environmental issues observed at the time of inspection.	

A/E	124300139	Date/Time	2/22/2022 4:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/22/2022 4:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34667
Inspector	Ben Davenport			Date/Time	2/22/2022 11:25 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Partial	Station End	15142+66
County	Pittsylvania	Ground	Muddy	Temperature (°F)	64.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Routine maintenance			
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Temporary Diversion Berm	Acceptable				
Waterbar	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/22/2022 11:25 AM	Report #	34667
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Light with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -Walked ROW looking for potential environmental issues or maintenance requirements -Perimeter controls and ECD's were inspected; 1 issue identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed of stabilization and vegetation in section both permanent and temporary areas of ROW; no issues observed -Continue to monitor ROW for signs of erosion -1 item added to environmental punch list (via Precision environmental foreman) -No other issues observed at time of inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/22/2022 11:25 AM	Report #	
Pictures					
<div style="text-align: center; height: 150px;"> Insert image here </div>					
			<div> <div> GPS Location </div> <div> Field Station# </div> <div> Pic 1 Desc. </div> </div>		
<div> <div> GPS Location </div> <div> Field Station# </div> <div> Pic 3 Desc. </div> </div>			<div> <div> GPS Location </div> <div> Field Station# </div> <div> Pic 4 Desc. </div> </div>		
<div> <div> GPS Location </div> <div> Field Station# </div> <div> Pic 5 Desc. </div> </div>			<div> <div> GPS Location </div> <div> Field Station# </div> <div> Pic 6 Desc. </div> </div>		

A/E	124300139	Date/Time	2/22/2022 11:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/22/2022 11:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34711
Inspector	Ben Farmer			Date/Time	2/22/2022 3:47 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Partial	Station End	16027+46
County	Pittsylvania	Ground	Wet	Temperature (°F)	56.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Equipment Bridge	Acceptable			
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	2/22/2022 3:47 PM	Report #	34711
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 56F) Rain Gauge= 0.0" 15947+64-16027+46 -EI began inspection at Chalk Level Rd. -RCEs are in good condition at all road crossings. -Perimeter P1 is in good condition throughout this section. -CWDs are functioning as intended throughout this area. -Equipment bridge ECDs are in good condition and functioning. -CFS remains in good condition throughout this area. -Resource buffers remain well vegetated -Waterbars are in good condition throughout this area. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/22/2022 3:47 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15947+65	Field Station#	15950+00		
Pic 1 Desc.	RCEs are in good condition at all road crossings	Pic 2 Desc.	P1 is in good condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15955+00	Field Station#	15962+00		
Pic 3 Desc.	Wetland buffer ECDs are in place and functioning	Pic 4 Desc.	P1 is in good condition at resource buffer		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15962+00	Field Station#	15962+00		
Pic 5 Desc.	Equipment bridge ECDs are in place and functioning	Pic 6 Desc.	CFS is in good condition		

AFE	124300139	Date/Time	2/22/2022 3:47 PM	Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	16014+00		Field Station#	16016+36	
Pic 7 Desc.	CWD is functioning as intended		Pic 8 Desc.	Resource buffer remains well vegetated	
GPS Location	See photo		GPS Location	See photo	
Field Station#	16017+00		Field Station#	16020+00	
Pic 9 Desc.	SSF is in good condition		Pic 10 Desc.	Waterbars in good condition and functioning.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	2/22/2022 3:47 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	34748	
Inspector	Frank Craycroft			Date/Time	2/22/2022 5:07 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Partial	Station End	0+00	
County	Franklin	Ground	Wet	Temperature (°F)	55.00	
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	2/22/2022 5:07 PM	Report #	34748
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All perimeter CFS was functional and in good condition. All stormwater drain inlets had proper perimeter protection and were free of debris and vegetation. All construction waste was maintained within bulk dumpsters on-site which had additional storage capacity. No issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/22/2022 5:07 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-048 West perimeter CFS		Pic 2 Desc.	LY-048 Housekeeping	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-032 Equipment staging area		Pic 4 Desc.	LY-032 Secondary containment	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	LY-033 Rock entrance		Pic 6 Desc.	LY-033 Stormwater drain inlet protection	

A/E	124300139	Date/Time	2/22/2022 5:07 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	ANC-006 Southeast perimeter CFS	Pic 8 Desc.	ANC-006 Secondary containment		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	2/22/2022 5:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34704
Inspector	Charles Head			Date/Time	2/22/2022 1:04 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Wet	Temperature (°F)	59.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/22/2022 1:04 PM	Report #	34704
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/22/2022 1:04 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14694+50	Field Station#	14689+36		
Pic 1 Desc.	Approximately 14694+50. Overview of road crossing and RCE.	Pic 2 Desc.	Approximately 14689+36. Overview of stream crossing, equipment bridge and ECDs at stream S-H34.		
					
GPS Location	0	GPS Location	0		
Field Station#	14680+30	Field Station#	14675+00		
Pic 3 Desc.	Approximately 14680+30. Overview of stream crossing, equipment bridge and ECDs at stream S-H36.	Pic 4 Desc.	Approximately 14675+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14673+10	Field Station#	14655+00		
Pic 5 Desc.	Approximately 14673+10. Overview of stream crossing, equipment bridge and ECDs at stream S-H37.	Pic 6 Desc.	Approximately 14655+00. Overview of ROW. Permanent vegetation.		

A/E	124300139	Date/Time	2/22/2022 1:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/22/2022 1:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	34712	
Inspector	Ben Farmer			Date/Time	2/22/2022 3:56 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Wet	Temperature (°F)	56.00	
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sensitive Resource Buffer		Acceptable				
Equipment Bridge		Acceptable				
Compost Filter Sock		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	2/22/2022 3:56 PM	Report #	34712
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 56F) Rain Gauge= 0.0" 00+00-19+25 (H-602) -Vegetation continues to fill in throughout this area. -P1 is in good condition at stream buffer. -Equipment bridge ECDs are in place and functioning. -Resource buffer remains well vegetated -CFS is in good condition throughout this area.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/22/2022 3:56 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	00+00	Field Station#	12+15		
Pic 1 Desc.	Vegetation continues to fill in throughout this section	Pic 2 Desc.	P1 is in good condition at stream buffer		
GPS Location	See photo	GPS Location	See photo		
Field Station#	12+65	Field Station#	12+65		
Pic 3 Desc.	Resource buffer remains well vegetated	Pic 4 Desc.	Equipment bridge ECDs are in place and functioning		
		Insert image here			
GPS Location	See photo	GPS Location			
Field Station#	14+00	Field Station#			
Pic 5 Desc.	Perimeter CFS is in good condition.	Pic 6 Desc.			

A/E	124300139	Date/Time	2/22/2022 3:56 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/22/2022 3:56 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34698
Inspector	Justin Burch			Date/Time	2/22/2022 12:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Full	Station End	14311+57
County	Franklin	Ground	Wet	Temperature (°F)	62.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Communication				
Other - Explain in Comments	Communication				
Slope Drain Pipe	Acceptable				
Sump Pit	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/22/2022 12:21 PM	Report #	34698
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). Three issues were submitted for the punch list including one location where P1 silt fence was damaged by livestock and two locations where electric fence was damaged by livestock. Other inspected ECDs were observed as in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has received one rain event with totals of 0.30" at Bonbrook Mill Road #1 and 0.50" at Farm View Road. The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14258+00 to 14277+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/22/2022 12:21 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14178+00	Field Station#	14178+00		
Pic 1 Desc.	Waterbar in acceptable condition	Pic 2 Desc.	Waterbar end treatment in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	14211+00	Field Station#	14295+50		
Pic 3 Desc.	Perimeter P1 silt fence in acceptable condition	Pic 4 Desc.	P1 silt fence damaged by livestock from 14295+00 to 14296+50 (4 panels)		
					
GPS Location	0	GPS Location	0		
Field Station#	14303+00	Field Station#	14295+00		
Pic 5 Desc.	Electric fence damaged by livestock	Pic 6 Desc.	Electric fence damaged by livestock		

A/E	124300139	Date/Time	2/22/2022 12:21 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14232+00	Field Station#	14248+00		
Pic 7 Desc.	Slope drain pipe and sump pit in acceptable conditions		Pic 8 Desc.	Perimeter CFS and temporary vegetative stabilization in acceptable conditions	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	2/22/2022 12:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		








Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34710
Inspector	Ben Farmer			Date/Time	2/22/2022 3:38 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Partial	Station End	15584+23
County	Pittsylvania	Ground	Wet	Temperature (°F)	56.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	P1 is degraded and needs to be rep			
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	2/22/2022 3:38 PM	Report #	34710
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 56F) Rain Gauge= 0.0" 15480+67-15584+23 -EI began inspection at Toshes Rd. -RCEs are in good condition at all road crossings. -Perimeter CFS is in good condition throughout this section. -No evidence of sedimentation from 3rd party disturbance at 15501+00. -3rd party ECDs appear to be in good condition at 15510+00. -CWDs are functioning as intended throughout this area. -Equipment bridge ECDs are in good condition and functioning. -P1 is degraded and needs to be replaced at 15541+50 -Resource buffers remain well vegetated -Waterbars are in good condition throughout this area. -Slope drain is in good condition at 15575+00 -P1 is in good condition around road pipe outlet at 15584+20. -Vegetation continuing to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/22/2022 3:38 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15490+00		Field Station#	15495+00	
Pic 1 Desc.	Perimeter CFS is in good condition		Pic 2 Desc.	Vegetation continues to fill in throughout this area	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15496+70		Field Station#	15501+00	
Pic 3 Desc.	RCEs are in good condition at all road crossings		Pic 4 Desc.	No evidence of sedimentation from 3rd party disturbance	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15510+00		Field Station#	15515+00	
Pic 5 Desc.	No evidence of sedimentation from 3rd party disturbance		Pic 6 Desc.	CWDs are functioning as intended	

AFE	124300139	Date/Time	2/22/2022 3:38 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15540+00		Field Station#	15541+50	
Pic 7 Desc.	Equipment bridge ECDs are in place and functioning		Pic 8 Desc.	P1 is degraded and needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15547+00		Field Station#	15556+83	
Pic 9 Desc.	Waterbars are in good condition		Pic 10 Desc.	Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15575+00		Field Station#	15584+00	
Pic 11 Desc.	Slope drain is in good condition and functioning		Pic 12 Desc.	P1 is in good condition at road pipe outlet	

A/E	124300139	Date/Time	2/22/2022 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I		AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision				Report #	34713	
Inspector	Ben Farmer				Date/Time	2/22/2022 4:02 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	00+00	
State	VA	Inspection Area	Full		Station End	24+53	
County	Pittsylvania	Ground	Wet		Temperature (°F)	56.00	
Municipality	Chatham	Weather	Light Rain		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)		Acceptable					
Waterbar		Acceptable					
Waterbar End Treatment		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Compost Filter Sock		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	2/22/2022 4:02 PM	Report #	34713
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 56F) Rain Gauge= 0.0" 00+00-24+53 (H-603) -Vegetation continues to fill in throughout this area. -Stockpiles remain temporarily stabilized. -Waterbars are in good condition throughout this area. -Waterbar end treatments are in good condition and functioning. -CFS is in good condition throughout this area -P1 is in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/22/2022 4:02 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	00+00	Field Station#	02+00		
Pic 1 Desc.	Vegetation continues to fill in throughout this area	Pic 2 Desc.	Stockpiles remain stabilized		
GPS Location	See photo	GPS Location	See photo		
Field Station#	10+00	Field Station#	10+00		
Pic 3 Desc.	Waterbars are functioning as intended	Pic 4 Desc.	End treatments are functioning as intended		
GPS Location	See photo	GPS Location	See photo		
Field Station#	12+78	Field Station#	13+75		
Pic 5 Desc.	CFS is in good condition	Pic 6 Desc.	P1 is in good condition		

A/E	124300139	Date/Time	2/22/2022 4:02 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/22/2022 4:02 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	34706	
Inspector	Glenn Mike Renfro			Date/Time	2/22/2022 2:08 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00	
State	VA	Inspection Area	Full	Station End	0000+00	
County	Franklin	Ground	Wet	Temperature (°F)	57.00	
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Rock Construction Entrance		Acceptable				
Other - Explain in Comments		Acceptable	Inlet protection for catch basins			
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	2/22/2022 2:08 PM	Report #	34706
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations were receiving rain at the time of inspection and site conditions were wet. - All perimeter ECD's were inspected and no problems were found. - The inlet protection for the catch basins at LY-046 were found to be in good condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE, at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/22/2022 2:08 PM	Report #	
Pictures					
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 1 Desc.	Perimeter ECD's on north end of LY-046 in good condition.	Pic 2 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.		
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 3 Desc.	Perimeter ECD's on west side of LY-046 in good condition.	Pic 4 Desc.	RCE at LY-045 in good condition.		
GPS Location	See picture	GPS Location	See		
Field Station#	0000+00	Field Station#	0000+00		
Pic 5 Desc.	Perimeter ECD's on north end of LY-045 in good condition.	Pic 6 Desc.	Equipment at LY-045 inspected and no leaks observed at the time of inspection.		

A/E	124300139	Date/Time	2/22/2022 2:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	2/22/2022 2:08 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34754
Inspector	Ben Farmer			Date/Time	2/23/2022 2:05 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Partial	Station End	15647+03
County	Pittsylvania	Ground	Wet	Temperature (°F)	55.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/23/2022 2:05 PM	Report #	34754
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div></div>					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 55F) Rain Gauge= 0.3" 15584+23-15647+03 -EI began inspection at Anderson Mill #1 -RCEs are in good condition condition at all road crossings. -Perimeter P1/CFS/SSF is in good condition. -Safety fence needs to be reattached at 15587+50. -Waterbars are in good condition and functioning. -CWDs are functioning as intended. -P1 is in good condition at stream buffer. -Equipment bridge ECDs are in place and functioning. -Stockpiles remain stabilized. -Drainage feature ECDs are in good condition. -Vegetation continues to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/23/2022 2:05 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15584+23	Field Station#	15584+50		
Pic 1 Desc.	RCEs are in good condition at all road crossings	Pic 2 Desc.	Perimeter P1 is in good condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15587+50	Field Station#	15595+50		
Pic 3 Desc.	Safety fence needs to be reattached	Pic 4 Desc.	CWDs are functioning as intended		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15596+00	Field Station#	15596+70		
Pic 5 Desc.	Equipment bridge ECDs are in place and functioning	Pic 6 Desc.	Resource buffers remain well vegetated		

AFE	124300139	Date/Time	2/23/2022 2:05 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15600+00		Field Station#	15605+00	
Pic 7 Desc.	P1 is in good condition at all stream and wetland buffers		Pic 8 Desc.	Perimeter SSF is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15610+00		Field Station#	15621+00	
Pic 9 Desc.	Perimeter CFS is in good condition		Pic 10 Desc.	Stockpiles remain stabilized	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15630+00		Field Station#	15363+45	
Pic 11 Desc.	CWD is functioning as intended at this location		Pic 12 Desc.	Resource buffer remains well vegetated.	







A/E	124300139	Date/Time	2/23/2022 2:05 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	34752		
Inspector	Justin Burch	Date/Time	2/23/2022 1:30 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Wet	Temperature (°F)	68.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.60
			Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Sump Pit		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Cleanwater Diversion Berm		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Slope Drain Pipe		Communication			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/23/2022 1:30 PM	Report #	34752
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). One issue was submitted for the punch list consisting of a location where a tree fell on a slope drain pipe and crushed it. Other inspected ECDs were observed as in compliance at the time of inspection. The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed the items on the punch list. Since the last SWPPP inspection the area received two precipitation events with totals of 0.60" at Grassy Hill Road and Bonbrook Mill Road #1. The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13910+00 and from 13921+00 to 13940+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/23/2022 1:30 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13955+00	Field Station#	13954+00		
Pic 1 Desc.	Sump pit in acceptable condition	Pic 2 Desc.	Waterbar in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	13954+00	Field Station#	13942+00		
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		
					
GPS Location	0	GPS Location	0		
Field Station#	13901+00	Field Station#	13887+00		
Pic 5 Desc.	Permanent vegetative stabilization and perimeter P1 silt fence in acceptable conditions	Pic 6 Desc.	Slope drain crushed by fallen tree		

A/E	124300139	Date/Time	2/23/2022 1:30 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/23/2022 1:30 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34753
Inspector	Ben Farmer			Date/Time	2/23/2022 1:44 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Wet	Temperature (°F)	55.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300139	Date/Time	2/23/2022 1:44 PM	Report #	34753
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 55F) Rain Gauge= 0.4" 15142+66-15260+00 -EI began inspection at Rockcreek Rd. -Perimeter P1/CFS is in good condition. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00 -P1 is in good condition at stream buffer. -Equipment bridge ECDs are in place and functioning. -Slope drain is functioning as intended at 15170+00. -Waterbars are in good condition throughout this section. -Drainage feature ECDs are in good condition and functioning at 15195+00. -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/23/2022 1:44 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15142+66		Field Station#	15160+00	
Pic 1 Desc.	RCE is in good condition		Pic 2 Desc.	Perimeter P1 is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15164+00		Field Station#	15165+57	
Pic 3 Desc.	Perimeter CFS is in good condition		Pic 4 Desc.	Rock filter remains in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15166+00		Field Station#	15168+00	
Pic 5 Desc.	Rock outlet remains in good condition		Pic 6 Desc.	P1 is in good condition at stream buffer	

AFE	124300139	Date/Time	2/23/2022 1:44 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15168+00		Field Station#	15168+50	
Pic 7 Desc.	Equipment bridge ECDs are in place and functioning		Pic 8 Desc.	Resource buffer remains well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15170+00	
Pic 9 Desc.	Waterbars are functioning as intended		Pic 10 Desc.	Slope drain is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15195+00		Field Station#	15230+00	
Pic 11 Desc.	Drainage ECDs are in place and functioning		Pic 12 Desc.	Vegetation continues to fill in throughout this section	

A/E	124300139	Date/Time	2/23/2022 1:44 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34741
Inspector	Charles Head			Date/Time	2/23/2022 9:40 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Wet	Temperature (°F)	56.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
3rd Party Damages	Communication	Repair damaged P-1			
Compost Filter Sock	Communication	Replace weathered and torn section			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Repair third party damage			
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to chain link			
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/23/2022 9:40 AM	Report #	34741
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/23/2022 9:40 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	14391+50	Field Station#	14409+26	Field Station#	14353+40
Pic 1 Desc.	Approximately 14391+50. Overview of stream crossing, equipment bridge and ECDs at stream S-A41.	Pic 2 Desc.	Approximately 14409+26. P-1 appears to have been damaged by third party.	Pic 3 Desc.	Approximately 14353+40. SSF requires maintenance. Reattach fabric to chain link.
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	14353+40	Field Station#	14338+56	Field Station#	14333+50
Pic 4 Desc.	Approximately 14338+56. Overview of stream crossing, equipment bridge and ECDs at stream S-A36.	Pic 5 Desc.	Approximately 14333+50. Overview of road crossing and RCEs.	Pic 6 Desc.	Approximately 14353+75. CFS requires maintenance. Weathered and torn.

A/E	124300139	Date/Time	2/23/2022 9:40 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	







A/E	124300139	Date/Time	2/23/2022 9:40 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34703
Inspector	Ben Davenport			Date/Time	2/23/2022 10:19 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Muddy	Temperature (°F)	65.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance	Addressed	2/23/2022	
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance	Addressed	2/23/2022	
Compost Filter Sock	Communication	Ineffective ESC measure	Addressed	2/23/2022	
Other - Explain in Comments	Communication	Routine maintenance- Safety fence	Addressed	2/23/2022	
Other - Explain in Comments	Communication	Routine maintenance- safety fence	Addressed	2/23/2022	
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	2/23/2022 10:19 AM	Report #	34703
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Checked rain gauges in covered area -Light rain with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 — 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; multiple issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; 1 issue identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -5 items added to environmental punch list -Rain Gauge Totals: +Indian Cave: 0.40 inches recorded +Armstrong: 0.40 inches recorded					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/23/2022 10:19 AM	Report #	
Pictures					
					
36°58'57" N 79°41'17" W 84°E COURSE -1' GPS Sorry no results found 02.23.2022 10:08:03 Accur +/-43.8 Ft ALT 942 Ft			36°58'57" N 79°41'16" W 258°W COURSE 0' GPS Sorry no results found 02.23.2022 09:32:23 Accur +/-92.6 Ft ALT 0 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14764+00	Field Station#	14766+15		
Pic 1 Desc.	Routine maintenance. Repair safety fence around sump pit.	Pic 2 Desc.	Ineffective ESC measure. CFS triple stack undermining in resource buffer.		
					
36°58'56" N 79°41'15" W 246°SW COURSE 315' GPS 245 Zeigler Ln, Union Hall, VA 24176, United States 02.23.2022 10:06:57 Accur +/-39.3 Ft ALT 914 Ft			36°58'54" N 79°41'12" W 239°SW COURSE -1' GPS Sorry no results found 02.23.2022 09:36:57 Accur +/-32.4 Ft ALT 926 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14768+00	Field Station#	14771+68		
Pic 3 Desc.	Routine maintenance. Replace perimeter P1 silt fence beyond effective lifespan.	Pic 4 Desc.	Routine maintenance. Repair safety fence around sump pit.		
					
36°58'44" N 79°41'2" W 264°W COURSE -1' GPS 245 Zeigler Ln, Union Hall, VA 24176, United States 02.23.2022 09:44:09 Accur +/-25.3 Ft ALT 864 Ft			36°58'42" N 79°40'55" W 306°NW COURSE 283' GPS Penhook, VA 24137, United States 02.23.2022 09:55:25 Accur +/-38.2 Ft ALT 857 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14782+35	Field Station#	14788+77		
Pic 5 Desc.	Routine maintenance. Replace perimeter P1 silt fence beyond effective lifespan.	Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		

A/E	124300139	Date/Time	2/23/2022 10:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/23/2022 10:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34811
Inspector	Ben Farmer			Date/Time	2/24/2022 12:33 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Partial	Station End	15772+27
County	Pittsylvania	Ground	Wet	Temperature (°F)	39.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/24/2022 12:33 PM	Report #	34811
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 39F) Rain Gauge= 0.0" 15647+03-15772+27 -EI began inspection at Anderson Mill #3. -RCEs are in good condition at all road crossings. -Stockpiles remain stabilized. -Equipment bridge ECDs are in place and functioning -Resource buffers remain in good condition. -P1 is in good condition at all stream and wetland buffers. -Waterbars/waterbar end treatments are in good condition and functioning. -CWDs are functioning as intended throughout this section. -Perimeter CFS/P1/SSF is in good condition throughout this section. -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/24/2022 12:33 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15647+03		Field Station#	15648+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings		Pic 2 Desc.	Stockpiles remain stabilized	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15658+43		Field Station#	15678+57	
Pic 3 Desc.	Resource buffers are well vegetated		Pic 4 Desc.	CWD is functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15693+83		Field Station#	15697+00	
Pic 5 Desc.	Perimeter P1 is in good condition		Pic 6 Desc.	Waterbar end treatments are functioning as intended	

AFE	124300139	Date/Time	2/24/2022 12:33 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15735+00	Field Station#	15762+00		
Pic 7 Desc.	CWD is functioning as intended	Pic 8 Desc.	Perimeter SSF remains in good condition		
GPS Location	See photo	GPS Location	See photo		
Field Station#	15763+80	Field Station#	15764+00		
Pic 9 Desc.	Equipment bridge ECDs are in place and functioning	Pic 10 Desc.	P1 is in good condition at all stream and wetland buffers		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	2/24/2022 12:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34770
Inspector	Ben Davenport			Date/Time	2/24/2022 9:29 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Muddy	Temperature (°F)	40.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Secondary Containment	Acceptable				
Sediment Filter Log	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/24/2022 9:29 AM	Report #	34770
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Performed SWPPP inspection on portion of MVP Spread I project -Inspection covered area between station# 14802+19–14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Light rain with muddy ground conditions during inspection -Inspection observed condition of perimeter controls and ECDs in section; no issues observed -Inspection observed condition of equipment bridges and ECDs around stream crossings and resource buffers; no issues observed -Inspection observed condition of RCEs and culverts at road crossings in section; no issues observed -Inspection observed condition of temporary and permanent vegetation throughout section; no issues observed -No items added to environmental punch list -No issues observed at the time of inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/24/2022 9:29 AM	Report #	
Pictures					
					
<small>36°58'26" N 79°40'26" W 226°SW COURSE 247' GPS Sorry no results found</small>			<small>36°58'23" N 79°40'22" W 297°NW COURSE 244' GPS Accur +/-35.6 Ft ALT 872 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	14818+00		Field Station#	14823+54	
Pic 1 Desc.	ROW stabilized and vegetated in temporary area. No signs of erosion observed.		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	
					
<small>36°58'17" N 79°39'37" W 269°W COURSE 183' GPS 2201 Bar Ridge Rd, Penhook, VA 24137, United States 02.24.2022 10:39:29 Accur +/-15.7 Ft ALT 985 Ft</small>			<small>36°58'17" N 79°39'37" W 53°NE COURSE 183' GPS 2201 Bar Ridge Rd, Penhook, VA 24137, United States 02.24.2022 10:39:36 Accur +/-35.7 Ft ALT 985 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	14861+00		Field Station#	14859+00	
Pic 3 Desc.	Portajon properly contained on ROW.		Pic 4 Desc.	ROW stabilized and vegetated in temporary area. Perimeter CFS in good condition.	
					
<small>36°58'4" N 79°38'18" W 321°NW COURSE 302' GPS 2019 Ramsey Memorial Rd, Penhook, VA 24137, United States 02.24.2022 10:47:34 Accur +/-15.4 Ft ALT 876 Ft</small>			<small>36°58'4" N 79°38'18" W 59°NE COURSE 49' GPS 2019 Ramsey Memorial Rd, Penhook, VA 24137, United States 02.24.2022 10:47:49 Accur +/-15.3 Ft ALT 876 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	14920+00		Field Station#	14926+00	
Pic 5 Desc.	ROW stabilized and vegetated in final cleanup area.		Pic 6 Desc.	Perimeter CFS in place and functional.	

A/E	124300139	Date/Time	2/24/2022 9:29 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/24/2022 9:29 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34814
Inspector	Ben Farmer			Date/Time	2/24/2022 1:31 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Wet	Temperature (°F)	39.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	2/24/2022 1:31 PM	Report #	34814
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 39F) Rain Gauge= 0.0" 15260+00-15370+62 -EI began inspection at Snowberry. -RCEs are in good condition at all road crossings. -MVP-PI-332 is in good condition with controls in place. -Equipment bridge ECDs are in place and functioning -Resource buffers remain in good condition. -P1 is in good condition at all stream and wetland buffers. -Waterbars are in good condition. -CWDs are functioning as intended throughout this section. -P1 remains in good condition around wetland buffer at 15311+87. -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/24/2022 1:31 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15370+62		Field Station#	15370+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings		Pic 2 Desc.	Vegetation continues to fill in throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15350+00		Field Station#	15346+87	
Pic 3 Desc.	MVP-PI-332 remains in good condition with controls in place		Pic 4 Desc.	Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15346+87		Field Station#	15315+00	
Pic 5 Desc.	Equipment bridge ECDs are in place and functioning		Pic 6 Desc.	Waterbars are in good condition throughout this section	

AFE	124300139	Date/Time	2/24/2022 1:31 PM	Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15314+50		Field Station#	15311+78	
Pic 7 Desc.	P1 is in good condition at all stream and wetland buffers		Pic 8 Desc.	P1 is in good condition at this wetland buffer	
GPS Location	See photo		GPS Location	See photo	
Field Station#	15310+00		Field Station#	15299+00	
Pic 9 Desc.	Perimeter CFS is in good condition		Pic 10 Desc.	CWDs are functioning as intended.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	2/24/2022 1:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34795
Inspector	Justin Burch			Date/Time	2/24/2022 9:22 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Wet	Temperature (°F)	40.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Plunge Pool	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	2/24/2022 9:22 AM	Report #	34795
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area received one rain event with totals of 0.30" at Grassy Hill Road, 0.30" at Bonbrook Mill Road #1, and 0.40" at Farm View Road. A rain event began this morning and continued throughout the day. Rain gauges will be checked tomorrow morning for this event. The ROW ground condition is wet. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14011+00 to 14018+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	2/24/2022 9:22 AM	Report #	
Pictures					
142°SE (T) 37°3'12"N, 79°53'4"W ±16ft ▲990ft  13998+15 02-24-2022, 09:09:00		193°S (T) 37°2'55"N, 79°53'37"W ±22ft ▲1106ft  13961+00 02-24-2022, 09:35:01			
GPS Location	0	GPS Location	0		
Field Station#	13998+15	Field Station#	13961+00		
Pic 1 Desc.	Equipment bridge in acceptable condition	Pic 2 Desc.	Waterbar in acceptable condition		
162°S (T) 37°2'54"N, 79°53'37"W ±13ft ▲1105ft  13961+00 02-24-2022, 09:34:33		11°N (T) 37°2'45"N, 79°53'29"W ±272ft ▲1132ft  13963+00 02-24-2022, 09:36:45			
GPS Location	0	GPS Location	0		
Field Station#	13961+00	Field Station#	13963+00		
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions		
217°SW (T) 37°3'25"N, 79°52'50"W ±55ft ▲1095ft  14018+00 02-24-2022, 11:29:16		306°NW (T) 37°3'28"N, 79°52'48"W ±13ft ▲1122ft  14021+00 02-24-2022, 11:30:36			
GPS Location	0	GPS Location	0		
Field Station#	14018+00	Field Station#	14021+00		
Pic 5 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 6 Desc.	Temporary vegetative stabilization and perimeter CFS in acceptable conditions		

A/E	124300139	Date/Time	2/24/2022 9:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/24/2022 9:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	34807
Inspector	Charles Head			Date/Time	2/24/2022 11:34 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Wet	Temperature (°F)	37.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	2/24/2022 11:34 AM	Report #	34807
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	2/24/2022 11:34 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14460+00	Field Station#	14527+00		
Pic 1 Desc.	Approximately 14460+00. Overview of ROW.	Pic 2 Desc.	Approximately 14527+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14524+50	Field Station#	14520+00		
Pic 3 Desc.	Approximately 14524+50. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14520+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14546+75	Field Station#	14541+00		
Pic 5 Desc.	Approximately 14546+75. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.	Pic 6 Desc.	Approximately 14541+00. Overview of ROW.		

A/E	124300139	Date/Time	2/24/2022 11:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	2/24/2022 11:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	34489
Inspector	John White			Date/Time	2/16/2022 3:32 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	64.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	2/16/2022 3:32 PM	Report #	34489
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	2/16/2022 3:32 PM	Report #	
Pictures					
GPS Location		O		GPS Location	
Field Station#		00+00		Field Station#	
Pic 1 Desc.		Observing temporary stabilization, storm water pond and ECD's		Pic 2 Desc.	
GPS Location		O		GPS Location	
Field Station#		00+00		Field Station#	
Pic 3 Desc.		Observing temporary stabilization, rock drain and ECD's		Pic 4 Desc.	
Insert image here			Insert image here		
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 5 Desc.				Pic 6 Desc.	

A/E	124300113	Date/Time	2/16/2022 3:32 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	2/16/2022 3:32 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		