









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35664
Inspector	Justin Burch			Date/Time	3/21/2022 10:18 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Full	Station End	15480+67
County	Pittsylvania	Ground	Damp	Temperature (°F)	72.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.90
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Sump Pit	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/21/2022 10:18 AM	Report #	35664
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI observed that the solar farm ECDs adjacent to the ROW on the CIS of Toshes Road appeared to be in acceptable condition and that no sediment from solar farm activities was entering the clean water diversion pipes. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has received one rain event with totals of 0.90" at Snowberry Road and 0.80" at Anderson Mill Road 2 The ROW ground condition is damp. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15438+00 to 15445+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/21/2022 10:18 AM	Report #	
Pictures					
 <p>357°N (T) 36°55'19"N, 79°30'36"W ±95ft ▲ 778ft 15372+00 03-21-2022, 09:02:57</p>		 <p>91°E (T) 36°55'16"N, 79°30'23"W ±13ft ▲ 774ft 15383+00 03-21-2022, 09:52:43</p>			
GPS Location	0	GPS Location	0		
Field Station#	15372+00	Field Station#	15383+00		
Pic 1 Desc.	Sump pit in acceptable condition	Pic 2 Desc.	Super silt fence in acceptable condition		
 <p>7°N (T) 36°55'13"N, 79°30'19"W ±55ft ▲ 775ft 15387+00 03-21-2022, 10:01:48</p>		 <p>11°N (T) 36°55'14"N, 79°30'19"W ±91ft ▲ 772ft 15387+00 03-21-2022, 10:01:17</p>			
GPS Location	0	GPS Location	0		
Field Station#	15387+00	Field Station#	15387+00		
Pic 3 Desc.	Waterbar in acceptable condition	Pic 4 Desc.	Waterbar end treatment in acceptable condition		
 <p>113°SE (T) 36°55'7"N, 79°30'0"W ±82ft ▲ 840ft 15404+00 03-21-2022, 10:14:20</p>		 <p>319°NW (T) 36°56'10"N, 79°28'57"W ±6423ft ▲ 825ft 15408+00 03-21-2022, 10:24:13</p>			
GPS Location	0	GPS Location	0		
Field Station#	15404+00	Field Station#	15408+00		
Pic 5 Desc.	Clean water diversion berm in acceptable condition	Pic 6 Desc.	Temporary vegetative stabilization in acceptable condition		

A/E	124300139	Date/Time	3/21/2022 10:18 AM	Report #	
Pictures					
 <p>15440+00 03-21-2022, 10:59:47</p>		 <p>15454+00 03-21-2022, 11:15:53</p>			
GPS Location	0	GPS Location	0		
Field Station#	15440+00	Field Station#	15454+00		
Pic 7 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 8 Desc.	Clean water diversion pipe in acceptable condition	
 <p>15448+00 03-21-2022, 12:26:43</p>		 <p>15461+00 03-21-2022, 11:24:29</p>			
GPS Location	0	GPS Location	0		
Field Station#	15448+00	Field Station#	15461+00		
Pic 9 Desc.	P1 silt fence in acceptable condition		Pic 10 Desc.	Temporary vegetative stabilization in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	3/21/2022 10:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35641
Inspector	Ben Davenport			Date/Time	3/21/2022 10:35 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Partial	Station End	14649+67
County	Franklin	Ground	Damp	Temperature (°F)	68.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Routine maintenance			
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance			
Other - Explain in Comments	Communication	Safety fence; routine maintenance			
Waterbar End Treatment	Communication	Routine maintenance			
Plunge Pool	Communication	CFS; routine maintenance			
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Equipment Bridge	Acceptable				
Temporary Diversion Berm	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/21/2022 10:35 AM	Report #	35641
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14546+77 — 14649+67 (Tobacco Rd to Hwy 40) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; 4 issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; 1 issue identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -5 items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/21/2022 10:35 AM	Report #	
Pictures					
					
37°0'1" N 79°44'30" W 168°S COURSE 121° GPS 03.21.2022 10:38:49 Sorry no results found Accur +/-63.7 Ft ALT 862 Ft			37°0'3" N 79°44'30" W 34°NE COURSE 114° GPS 03.21.2022 10:37:40 753 Simmons Creek Rd, Union Hall, VA 24176, United States Accur +/-108.7 Ft ALT 863 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14585+00	Field Station#	14584+00		
Pic 1 Desc.	Routine maintenance. Replace damaged/missing stakes in CFS.		Pic 2 Desc.	Routine maintenance. Replace damaged row of P1 silt fence in extra workspace.	
					
37°0'1" N 79°44'33" W 289°W COURSE 313° GPS 03.21.2022 10:42:03 Glade Hill, VA 24092, United States Accur +/-185.4 Ft ALT 843 Ft			37°0'1" N 79°44'37" W 142°SE COURSE 313° GPS 03.21.2022 10:43:23 Glade Hill, VA 24092, United States Accur +/-116.5 Ft ALT 843 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14580+00	Field Station#	14577+00		
Pic 3 Desc.	Routine maintenance. Repair perimeter safety fence.		Pic 4 Desc.	Routine maintenance. CFS end treatment beginning to fall into sump pit.	
					
37°0'1" N 79°44'37" W 221°SW COURSE -1° GPS 03.21.2022 10:44:47 Glade Hill, VA 24092, United States Accur +/-656.2 Ft ALT 858 Ft			37°0'3" N 79°44'50" W 351°N COURSE 257° GPS 03.21.2022 10:52:55 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-656.2 Ft ALT 884 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14576+00	Field Station#	14558+01		
Pic 5 Desc.	Routine maintenance. Replace damaged/worn CFS in plunge pool.		Pic 6 Desc.	Natural drainage area and equipment bridge crossing in place and functional.	

A/E	124300139	Date/Time	3/21/2022 10:35 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	3/21/2022 10:35 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35673
Inspector	John White			Date/Time	3/21/2022 12:06 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Dry	Temperature (°F)	62.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Perform maintenance			
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Perform maintenance			
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Perform maintenance			
Sensitive Resource Buffer	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/21/2022 12:06 PM	Report #	35673
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/21/2022 12:06 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15826+77	Field Station#	15825+00		
Pic 1 Desc.	Observing road crossing and RCE's	Pic 2 Desc.	Observing plunge pool and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15794+77	Field Station#	15794+17		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing P1 that requires maintenance		
					
GPS Location	O	GPS Location	O		
Field Station#	15784+50	Field Station#	15776+00		
Pic 5 Desc.	Observing P1 that requires maintenance	Pic 6 Desc.	Observing CFS that requires maintenance		

AFE	124300139	Date/Time	3/21/2022 12:06 PM	Report #	
Pictures					
 <p>GPS: 265°W (T) 36°51'1"N, 79°22'55"W ±124ft ▲ 757ft</p> <p>21 Mar 2022, 10:08:51</p>		 <p>GPS: 123°SE (T) 36°50'57"N, 79°22'41"W ±173ft ▲ 721ft</p> <p>21 Mar 2022, 10:12:07</p>			
GPS Location	O	GPS Location	O		
Field Station#	15860+00	Field Station#	15878+08		
Pic 7 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 8 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
 <p>GPS: 246°SW (T) 36°50'44"N, 79°22'15"W ±22ft ▲ 698ft</p> <p>21 Mar 2022, 10:17:30</p>		 <p>GPS: 284°W (T) 36°50'36"N, 79°22'8"W ±16ft ▲ 664ft</p> <p>21 Mar 2022, 10:23:11</p>			
GPS Location	O	GPS Location	O		
Field Station#	15920+00	Field Station#	15912+00		
Pic 9 Desc.	Observing temporary stabilization and water bars	Pic 10 Desc.	Observing P1 that requires maintenance		
 <p>GPS: 116°SE (T) 36°50'10"N, 79°22'3"W ±6459ft ▲ 721ft</p> <p>21 Mar 2022, 10:55:21</p>		 <p>GPS: 116°SE (T) 36°50'20"N, 79°21'53"W ±49ft ▲ 658ft</p> <p>21 Mar 2022, 10:55:21</p>			
GPS Location	O	GPS Location	O		
Field Station#	15934+00	Field Station#	15934+00		
Pic 11 Desc.	Observing CFS that requires maintenance	Pic 12 Desc.	Observing P1 that requires maintenance		







AFE	124300139	Date/Time	3/21/2022 12:06 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15933+00	Field Station#	15930+00		
Pic 13 Desc.	Observing SSF that requires maintenance	Pic 14 Desc.	Observing CFS that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15924+50	Field Station#	15920+00		
Pic 15 Desc.	Observing SSF that requires maintenance	Pic 16 Desc.	Observing CFS that requires maintenance		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35681
Inspector	Ben Farmer			Date/Time	3/21/2022 3:35 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Partial	Station End	14171+36
County	Pittsylvania	Ground	Dry	Temperature (°F)	47.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/21/2022 3:35 PM	Report #	35681
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 47F) Rain Gauge= 0.0" 14062+17-14171+36 -EI began inspection at Bonbrook Mill #2. -Equipment bridge ECDs are in place and functioning. -MVP-FR-309.05 is in good condition with controls in place. -CWD/CWD inlets are in good condition and functioning as intended -CFS is in good condition throughout this section. -Perimeter P1 is in good condition throughout this section. -Topsoil berm remains stabilized. -SSF is in good condition. -Waterbars are functioning as intended. -Resource buffers remain well vegetated at all stream and wetland crossings. -RCEs are in good condition at all road crossings. -P1 is in good condition at all stream and wetland buffers. -Slope drain is in good condition and functioning at 14157+00 -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/21/2022 3:35 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14065+00		Field Station#	14066+77	
Pic 1 Desc.	Vegetation continues to fill in throughout this section		Pic 2 Desc.	Equipment bridge ECDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14070+00		Field Station#	14082+00	
Pic 3 Desc.	CWD is functioning as intended		Pic 4 Desc.	Perimeter P1 is in good condition throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14090+00		Field Station#	14100+00	
Pic 5 Desc.	Topsoil berm remains stabilized		Pic 6 Desc.	SSF is in good condition throughout this section	

AFE	124300139	Date/Time	3/21/2022 3:35 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14103+00		Field Station#	14105+32	
Pic 7 Desc.	Waterbars are in good condition		Pic 8 Desc.	Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14131+28		Field Station#	14072+70	
Pic 9 Desc.	RCEs are in good condition at all road crossings		Pic 10 Desc.	MVP-FR-309.05 remains in good condition with controls in place.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14133+00		Field Station#	14141+62	
Pic 11 Desc.	CWD is functioning as intended		Pic 12 Desc.	P1 is in good condition at all stream and wetland buffers	

AFE	124300139	Date/Time	3/21/2022 3:35 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14157+00		Field Station#	14162+00	
Pic 13 Desc.	Slope drain is in good condition and functioning		Pic 14 Desc.	Perimeter CFS is in good condition.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 15 Desc.			Pic 16 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 17 Desc.			Pic 18 Desc.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35677
Inspector	Logan Box			Date/Time	3/21/2022 4:29 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/21/2022 4:29 PM	Report #	35677
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p> <p>During row inspection today the EI monitored the contractor working to replace ECDs as needed and working to stabilize areas of the row.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/21/2022 4:29 PM	Report #	
Pictures					
GPS Location	0000	GPS Location	0000		
Field Station#	13692+20	Field Station#	13740+00		
Pic 1 Desc.	Monitored row perimeter ECDs throughout, no environmental issues observed at the time of inspection.		Pic 2 Desc.	During row inspection today the EI observed the contractor working to stabilize areas of the row.	
GPS Location	0000	GPS Location	000		
Field Station#	13693+00	Field Station#	13692+69		
Pic 3 Desc.	Monitored row perimeter ECDs throughout, no environmental issues observed at the time of inspection.		Pic 4 Desc.	Monitored stream crossing and ECDs, all functioning at the time of inspection.	
GPS Location	0000	GPS Location	0000		
Field Station#	13679+10	Field Station#	13728+18		
Pic 5 Desc.	Monitored newly installed ECDs along the row perimeter, all functioning at the time of inspection.		Pic 6 Desc.	Throughout today's inspection the EI observed the contractor working to replace ECDs as well as stabilize areas of the row.	

A/E	124300139	Date/Time	3/21/2022 4:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/21/2022 4:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	35678		
Inspector	Charles Head	Date/Time	3/21/2022 1:11 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Full	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Dry	Temperature (°F)	66.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
3rd Party Damages	Communication	Replace CFS damaged by livestock			
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Replace sections damaged by livestock			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Replace damaged/ weathered section			
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to chain link			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/21/2022 1:11 PM	Report #	35678
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/21/2022 1:11 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14981+50	Field Station#	14963+00		
Pic 1 Desc.	Approximately 14981+50. Overview of road crossing and RCEs.	Pic 2 Desc.	Approximately 14963+00. Overview of ROW. Permanent vegetation.		
GPS Location	0	GPS Location	0		
Field Station#	15055+80	Field Station#	15002+00		
Pic 3 Desc.	Approximately 15055+80. Overview of stream crossing, equipment bridge and ECDs at stream S-D1.	Pic 4 Desc.	Approximately 15002+00. Overview of ROW.		
GPS Location	0	GPS Location	0		
Field Station#	14950+47	Field Station#	14946+00		
Pic 5 Desc.	Approximately 14950+47. Overview of stream crossing, equipment bridge and ECDs at stream S-G13.	Pic 6 Desc.	Approximately 14946+00. Overview of ROW.		

AFE	124300139	Date/Time	3/21/2022 1:11 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14950+90	Field Station#	14951+50		
Pic 7 Desc.	Approximately 14950+00. P-1 requires maintenance.	Pic 8 Desc.	Approximately 14951+50. SSF requires maintenance. Reattach fabric to chain link.		
		<div style="text-align: center;">Insert image here</div>			
GPS Location	0	GPS Location			
Field Station#	14990+50	Field Station#			
Pic 9 Desc.	Approximately 14990+50. CFS requires maintenance. Damaged by livestock.	Pic 10 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	3/21/2022 1:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35734
Inspector	Charles Head			Date/Time	3/22/2022 12:45 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Full	Station End	15142+66
County	Franklin/Pittsylvania	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/22/2022 12:45 PM	Report #	35734
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/22/2022 12:45 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	15072+86		Field Station#	15092+95	
Pic 1 Desc.	Approximately 15072+86. Overview of stream crossing, equipment bridge and ECDs at stream S-G11.		Pic 2 Desc.	Approximately 15092+95. Overview of stream crossing, equipment bridge and ECDs at stream S-G9.	
					
GPS Location	0		GPS Location	0	
Field Station#	15096+00		Field Station#	15103+45	
Pic 3 Desc.	Approximately 15096+00. Overview of ROW.		Pic 4 Desc.	Approximately 15103+45. Overview of stream crossing, equipment bridge and ECDs at stream S-G8.	
					
GPS Location	0		GPS Location	0	
Field Station#	15113+00		Field Station#	15122+00	
Pic 5 Desc.	Approximately 15113+00. Overview of road crossing and RCEs.		Pic 6 Desc.	Approximately 15122+00. Overview of ROW.	

A/E	124300139	Date/Time	3/22/2022 12:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/22/2022 12:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35735
Inspector	John White			Date/Time	3/22/2022 12:49 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	3/22/2022 12:49 PM	Report #	35735
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/22/2022 12:49 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	16022+00	Field Station#	16017+00		
Pic 1 Desc.	Observing temporary stabilization and water bar	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	16016+00	Field Station#	16010+00		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	16004+00	Field Station#	16007+00		
Pic 5 Desc.	Observing temporary stabilization, signage and buffer	Pic 6 Desc.	Observing temporary stabilization, sump and end treatment		

A/E	124300139	Date/Time	3/22/2022 12:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/22/2022 12:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I
Contractor	Precision	Report #	35729		
Inspector	John White	Date/Time	3/22/2022 12:26 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	24+53
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
			Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Housekeeping		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Sump Pit		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar End Treatment		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/22/2022 12:26 PM	Report #	35729
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/22/2022 12:26 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	14+00	Field Station#	22+00		
Pic 1 Desc.	Observing temporary stabilization,ECD's, road crossing and RCE's	Pic 2 Desc.	Observing temporary stabilization, signage and buffer		
GPS Location	O	GPS Location	O		
Field Station#	10+00	Field Station#	6+00		
Pic 3 Desc.	Observing temporary stabilization and water bars	Pic 4 Desc.	Observing temporary stabilization, sump and end treatment		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	3/22/2022 12:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/22/2022 12:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35674
Inspector	Ben Davenport			Date/Time	3/22/2022 10:36 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Partial	Station End	14694+77
County	Franklin	Ground	Dry	Temperature (°F)	68.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Equipment Bridge	Acceptable				
Compost Filter Sock	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sediment Filter Log	Acceptable				
Temporary Diversion Berm	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/22/2022 10:36 AM	Report #	35674
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14649+67 — 14694+77 (Hwy 40 to Jacks Creek Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/22/2022 10:36 AM	Report #	
Pictures					
					
36°59'25" N 79°43'25" W 193°S COURSE 102' GPS 9400-9598 Old Franklin Tpke, Union Hall, VA 24176, United States 03.22.2022 09:41:38 Accur +/-39.7 Ft ALT 976 Ft			36°59'21" N 79°43'21" W 121°SE COURSE 133' GPS Union Hall, VA 24176, United States 03.22.2022 09:43:41 Accur +/-22.1 Ft ALT 933 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14652+00	Field Station#	14656+87		
Pic 1 Desc.	ROW stabilized and vegetated in final cleanup area. Perimeter controls in place and functional.		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	
					
36°59'17" N 79°43'6" W 184°S COURSE 112' GPS Union Hall, VA 24176, United States 03.22.2022 09:49:36 Accur +/-99.8 Ft ALT 1015 Ft			36°59'17" N 79°43'4" W 126°SE COURSE 113' GPS Union Hall, VA 24176, United States 03.22.2022 09:50:05 Accur +/-18.7 Ft ALT 976 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14665+00	Field Station#	14673+10		
Pic 3 Desc.	Water bar performing intended function; ROW stabilized and vegetated in temporary area.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	
					
36°59'17" N 79°42'51" W 240°SW COURSE 244' GPS Union Hall, VA 24176, United States 03.22.2022 10:08:33 Accur +/-27.2 Ft ALT 928 Ft			36°59'16" N 79°42'42" W 287°W COURSE 252' GPS Union Hall, VA 24176, United States 03.22.2022 10:04:48 Accur +/-27.9 Ft ALT 921 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14680+55	Field Station#	14689+36		
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.		Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	

A/E	124300139	Date/Time	3/22/2022 10:36 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	3/22/2022 10:36 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		















Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35709
Inspector	Logan Box			Date/Time	3/22/2022 3:54 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication				
Silt Fence (Filter Fabric Fence)	Communication				
Vegetative Stabilization (Temporary)	Acceptable				
Rock Construction Entrance	Acceptable				
Equipment Bridge	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/22/2022 3:54 PM	Report #	35709
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections the EI observed multiple locations of CFS and P1 that required maintenance or to be replaced.</p> <p>Documented the locations and added to the punch list.</p> <p>The EI talked with the contractor about the issues as they were working in the area.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/22/2022 3:54 PM	Report #	
Pictures					
	West Elevation 			North East Elevation 	
GPS Location	00000	GPS Location	00000		
Field Station#	13803+20	Field Station#	13771+12		
Pic 1 Desc.	P1 requires maintenance along the Deb of the LOD, documented and added to the punch list.	Pic 2 Desc.	CFS at stream buffer requires maintenance due to being weathered. Added to the punch list.		
				North East Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13788+00	Field Station#	13807+50		
Pic 3 Desc.	CFS end treatment needs replaced.	Pic 4 Desc.	CFS end treatment needs replaced, added to the punch list.		
	South Elevation 				
GPS Location	00000	GPS Location	00000		
Field Station#	13834+00	Field Station#	13800+00		
Pic 5 Desc.	P1 requires maintenance, added to the punch list.	Pic 6 Desc.	CFS needs replaced.		

AFE	124300139	Date/Time	3/22/2022 3:54 PM	Report #	
Pictures					
					
GPS Location	0000	GPS Location	00000		
Field Station#	13792+25	Field Station#	13845+70		
Pic 7 Desc.	CFS end treatment needs maintenance.	Pic 8 Desc.	CFS on row edge needs replaced. Added to the punch list.		
					
GPS Location	00000	GPS Location	00000		
Field Station#	13815+00	Field Station#	13786+55		
Pic 9 Desc.	CFS end treatment needs replaced, added to the punch list.	Pic 10 Desc.	Perimeter CFS needs replaced due to being weathered .		
					
GPS Location	00000	GPS Location	00000		
Field Station#	13777+00	Field Station#	13820+00		
Pic 11 Desc.	Perimeter CFS needs replaced.	Pic 12 Desc.	P1 requires maintenance, added to the punch list.		






AFE	124300139	Date/Time	3/22/2022 3:54 PM	Report #	
Pictures					
South Elevation 		North West Elevation 			
GPS Location	00000	GPS Location	00000		
Field Station#	13820+00	Field Station#	13803+00		
Pic 13 Desc.	Perimeter CFS requires maintenance.	Pic 14 Desc.	CFS end treatment needs maintenance.		
South West Elevation 		North Elevation 			
GPS Location	00000	GPS Location	000000		
Field Station#	13805+00	Field Station#	13787+00		
Pic 15 Desc.	CFS at stream crossing requires maintenance, added to the punch list.	Pic 16 Desc.	CFS end treatment requires maintenance.		
					
GPS Location	0000	GPS Location	00000		
Field Station#	13784+90	Field Station#	13782+20		
Pic 17 Desc.	Perimeter CFS around work space needs replaced.	Pic 18 Desc.	P1 at stream buffer needs replaced.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35777
Inspector	Glenn Mike Renfro			Date/Time	3/22/2022 12:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00
State	VA	Inspection Area	Full	Station End	0000+00
County	Franklin	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Other - Explain in Comments	Acceptable	Inlet protection for catch basins			
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/22/2022 12:41 PM	Report #	35777
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have received .30" of rainfall since the previous inspection and site conditions were dry. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were found to be in acceptable condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/22/2022 12:41 PM	Report #	
Pictures					
 <p><small>Date & Time: Tue Mar 22, 2022 09:44:55 EDT Position: +036°57'07.74" N, -079°57'04.53" W ±11.24ft Altitude: 11197ft ±19.30ft Datum: WGS-84 Azimuth Bearing: 278° NS20W 4522mils True ±13 ft Elevation Angle: +0.2° Horizon Angle: +00.3° Zoom: 1.0x</small></p>		 <p><small>Date & Time: Tue Mar 22, 2022 09:27:14 EDT Position: +036°57'07.74" N, -079°57'04.53" W ±11.24ft Altitude: 11197ft ±19.30ft Datum: WGS-84 Azimuth Bearing: 159° S01E 2822mils True ±13 ft Elevation Angle: +0.2° Horizon Angle: +00.3° Zoom: 1.0x</small></p>			
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	00+00		
Pic 1 Desc.	Housekeeping in order at LY-046.	Pic 2 Desc.	Inlet protection and perimeter ECD's in good condition at LY-046.		
 <p><small>Date & Time: Tue Mar 22, 2022 09:15:55 EDT Position: +036°58'15.11" N, -079°52'52.91" W ±11.24ft Altitude: 11197ft ±19.30ft Datum: WGS-84 Azimuth Bearing: 007° S07E 1844mils True ±13 ft Elevation Angle: +0.2° Horizon Angle: +00.3° Zoom: 1.0x</small></p>		 <p><small>Date & Time: Tue Mar 22, 2022 09:04:07 EDT Position: +036°58'15.11" N, -079°52'52.91" W ±11.24ft Altitude: 11197ft ±19.30ft Datum: WGS-84 Azimuth Bearing: 007° S07E 1844mils True ±13 ft Elevation Angle: +0.2° Horizon Angle: +00.3° Zoom: 1.0x</small></p>			
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 3 Desc.	Secondary containment structure for near station at LY-045 in good condition.	Pic 4 Desc.	Secondary containment structure for light plant at LY-046 in good condition.		
 <p><small>SE 120 150 S 180 210 SW 240 W 270 203°S (T) 36°58'15"N, 79°52'9"W ±13ft ▲ 1194ft</small></p>		Insert image here			
GPS Location	See picture	GPS Location			
Field Station#	0000+00	Field Station#			
Pic 5 Desc.	Perimeter ECD's on north end of LY-045 in acceptable condition.	Pic 6 Desc.			

A/E	124300139	Date/Time	3/22/2022 12:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/22/2022 12:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	35744		
Inspector	Ben Farmer	Date/Time	3/22/2022 3:39 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Partial	Station End	14311+57
County	Pittsylvania	Ground	Dry	Temperature (°F)	46.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Slope Drain Pipe		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/22/2022 3:39 PM	Report #	35744
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 46F) Rain Gauge= 0.0" 14171+36-14311+57 -EI began inspection at Angle Plantation Rd. -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in place and functioning. -SSF is in good condition. -CWD/CWD inlets are in good condition and functioning as intended -Topsoil berm remains stabilized. -P1 is in good condition at all stream and wetland buffers. -Waterbars are in good condition throughout this section. -MVP-FR-311 is in good condition with controls in place. -Perimeter P1 is in good condition throughout this section. -Slope drain is in good condition and functioning at 14232+00. -Slope on the GAS of S-F11 remains stabilized and waterbars are in good condition. -CFS is in good condition throughout this section. -Resource buffers remain well vegetated. -Waterbars are functioning as intended. -Resource buffers remain well vegetated at all stream and wetland crossings. -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/22/2022 3:39 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14171+36	Field Station#	14176+09		
Pic 1 Desc.	RCEs are in good condition at all road crossings	Pic 2 Desc.	Equipment bridge ECDs are in good condition and functioning		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14182+00	Field Station#	14185+00		
Pic 3 Desc.	SSF is in good condition	Pic 4 Desc.	Topsoil berms remain stabilized		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14190+00	Field Station#	14203+00		
Pic 5 Desc.	P1 is in good condition at all stream and wetland buffers	Pic 6 Desc.	CWDs are functioning as intended		

AFE	124300139	Date/Time	3/22/2022 3:39 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14206+00		Field Station#	14232+00	
Pic 7 Desc.	Waterbars are in good condition		Pic 8 Desc.	Slope drain is in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14252+00		Field Station#	14260+00	
Pic 9 Desc.	Slope remains stabilized and ECDs are in good condition.		Pic 10 Desc.	Vegetation continues to fill in throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14274+00		Field Station#	14278+93	
Pic 11 Desc.	CFS is in good condition along this drainage.		Pic 12 Desc.	Resource buffers remain well vegetated.	

A/E	124300139	Date/Time	3/22/2022 3:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	35732	
Inspector	John White			Date/Time	3/22/2022 12:43 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	3/22/2022 12:43 PM	Report #	35732
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/22/2022 12:43 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	12+65		
Pic 1 Desc.	Observing temporary stabilization and access road	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	13+50	Field Station#	19+00		
Pic 3 Desc.	Observing temporary stabilization, water bar, sump, end treatment and ECD's	Pic 4 Desc.	Observing temporary stabilization and ECD's		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	3/22/2022 12:43 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/22/2022 12:43 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35723
Inspector	Justin Burch			Date/Time	3/22/2022 11:37 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Full	Station End	15584+23
County	Pittsylvania	Ground	Damp	Temperature (°F)	70.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.90
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/22/2022 11:37 AM	Report #	35723
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI observed that the solar farm ECDs adjacent to the ROW on the GAS of Climax Road appeared to be in acceptable condition. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has received one rain event with totals of 0.90" at Snowberry Road and 0.80" at Anderson Mill Road 2 The ROW ground condition is damp. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15482+00 to 15495+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/22/2022 11:37 AM	Report #	
Pictures					
14°N (T) 36°54'20"N, 79°28'23"W ±85ft ▲ 895ft  15501+00 03-22-2022, 09:16:05		59°NE (T) 36°54'20"N, 79°28'23"W ±42ft ▲ 890ft  15501+00 03-22-2022, 09:16:41			
GPS Location	0	GPS Location	0		
Field Station#	15501+00	Field Station#	15501+00		
Pic 1 Desc.	Waterbar in acceptable condition	Pic 2 Desc.	Waterbar end treatment in acceptable condition		
150°SE (T) 36°54'15"N, 79°28'11"W ±32ft ▲ 866ft  15514+00 03-22-2022, 09:40:18		196°S (T) 36°54'11"N, 79°28'6"W ±91ft ▲ 840ft  15520+00 03-22-2022, 10:22:00			
GPS Location	0	GPS Location	0		
Field Station#	15514+00	Field Station#	15520+00		
Pic 3 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions	Pic 4 Desc.	Super silt fence in acceptable condition		
320°NW (T) 36°53'57"N, 79°27'43"W ±295ft ▲ 774ft  15542+19 03-22-2022, 10:56:41		47°NE (T) 36°53'52"N, 79°27'29"W ±39ft ▲ 822ft  15556+00 03-22-2022, 11:09:36			
GPS Location	0	GPS Location	0		
Field Station#	15542+19	Field Station#	15556+00		
Pic 5 Desc.	Equipment bridge in acceptable condition	Pic 6 Desc.	P1 silt fence in acceptable condition		

AFE	124300139	Date/Time	3/22/2022 11:37 AM	Report #	
Pictures					
75°E (T) 36°53'44"N, 79°27'8"W ±515ft ▲ 776ft  15575+00 03-22-2022, 11:29:13		314°NW (T) 36°54'28"N, 79°28'33"W ±16ft ▲ 928ft  15492+00 03-22-2022, 12:46:15			
GPS Location	0	GPS Location	0		
Field Station#	15575+00	Field Station#	15492+00		
Pic 7 Desc.	Slope drain pipe in acceptable condition	Pic 8 Desc.	Permanent vegetative stabilization in acceptable condition		
112°E (T) 36°54'20"N, 79°28'23"W ±26ft ▲ 887ft  15502+00 03-22-2022, 09:16:49		114°SE (T) 36°54'18"N, 79°28'14"W ±13ft ▲ 871ft  15512+00 03-22-2022, 12:20:33			
GPS Location	0	GPS Location	0		
Field Station#	15502+00	Field Station#	15512+00		
Pic 9 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 10 Desc.	Super silt fence on solar farm perimeter in acceptable condition		
156°SE (T) 36°54'16"N, 79°28'36"W ±1377ft ▲ 940ft  15500+00 03-22-2022, 12:42:41		49°NE (T) 36°53'59"N, 79°27'50"W ±652ft ▲ 812ft  15538+00 03-22-2022, 10:42:28			
GPS Location	0	GPS Location	0		
Field Station#	15500+00	Field Station#	15538+00		
Pic 11 Desc.	ECDs on Solar Farm perimeter in acceptable conditions	Pic 12 Desc.	Temporary vegetative stabilization in acceptable condition		







A/E	124300139	Date/Time	3/22/2022 11:37 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	35740	
Inspector	Frank Craycroft			Date/Time	3/22/2022 3:15 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Dry	Temperature (°F)	70.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Communication	LY-032 Secondary containment around	Addressed	3/22/2022	
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	3/22/2022 3:15 PM	Report #	35740
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. Secondary containment in LY-032 needed maintenance to restore liner around structure to contain any potential leaks. Light plant at LY-032 had no secondary containment. Contractor addressed both issues today. No other issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/22/2022 3:15 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 1 Desc.	LY-032 Rock entrance		Pic 2 Desc.	LY-032 Secondary containment needs maintenance	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 3 Desc.	LY-033 Timber mat staging area		Pic 4 Desc.	LY-033 Light plant needs secondary containment around it	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 5 Desc.	ANC-006 Southeast perimeter CFS		Pic 6 Desc.	ANC-006 Stormwater drain inlet protection	

AFE	124300139	Date/Time	3/22/2022 3:15 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-048 South perimeter CFS		Pic 8 Desc.	LY-048 North perimeter CFS	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	3/22/2022 3:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35719
Inspector	Ben Davenport			Date/Time	3/23/2022 10:34 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Partial	Station End	14454+22
County	Franklin	Ground	Wet	Temperature (°F)	60.00
Municipality	N/A	Weather	Heavy Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Temporary Diversion Berm	Acceptable				
Compost Filter Sock	Acceptable				
Secondary Containment	Acceptable				
Waterbar	Acceptable				
Rock Construction Entrance	Acceptable				
Erosion Control Blanket	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/23/2022 10:34 AM	Report #	35719
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Heavy rain with wet ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/23/2022 10:34 AM	Report #	
Pictures					
					
37°2'34" N 79°48'36" W 179°S COURSE 216° GPS 362-532 Farm View Rd, Glade Hill, VA 24092, United States 03.23.2022 12:00:09 Accur +/-15.4 Ft ALT 1059 Ft			37°2'20" N 79°48'19" W 304°NW COURSE 79° GPS 1807 Golden View Rd, Glade Hill, VA 24092, United States 03.23.2022 12:02:56 Accur +/-15.4 Ft ALT 1185 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14313+00	Field Station#	14325+00		
Pic 1 Desc.	Perimeter P1 silt fence in good condition. Spoil pile stabilized and vegetated.		Pic 2 Desc.	ROW stabilized and vegetated in temporary area; perimeter controls and ECDs in place and functional.	
					
37°2'20" N 79°48'19" W 23°N COURSE 71° GPS 1807 Golden View Rd, Glade Hill, VA 24092, United States 03.23.2022 12:02:54 Accur +/-15.4 Ft ALT 1186 Ft			37°2'34" N 79°48'36" W 145°SE COURSE 17° GPS 362-532 Farm View Rd, Glade Hill, VA 24092, United States 03.23.2022 11:59:44 Accur +/-28.4 Ft ALT 1086 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14333+00	Field Station#	14311+57		
Pic 3 Desc.	Perimeter SSF and CFS in place and functional.		Pic 4 Desc.	RCE in good condition.	
					
37°1'36" N 79°46'6" W 53°NE COURSE 204° GPS 2753-2799 Webster Rd, Glade Hill, VA 24092, United States 03.23.2022 09:43:49 Accur +/-46.7 Ft ALT 1104 Ft			37°1'35" N 79°46'6" W 284°W COURSE 204° GPS 2753-2799 Webster Rd, Glade Hill, VA 24092, United States 03.23.2022 09:43:38 Accur +/-15.4 Ft ALT 1104 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14450+00	Field Station#	14454+00		
Pic 5 Desc.	ROW stabilized and vegetated in temporary area; perimeter controls and ECDs in place and functional.		Pic 6 Desc.	Portajon properly contained in secondary containment at road crossing.	

A/E	124300139	Date/Time	3/23/2022 10:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/23/2022 10:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35766
Inspector	John White			Date/Time	3/23/2022 8:43 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Damp	Temperature (°F)	55.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/23/2022 8:43 AM	Report #	35766
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/23/2022 8:43 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15585+50	Field Station#	15590+00		
Pic 1 Desc.	Observing temporary stabilization, sump, end treatment and ECD's	Pic 2 Desc.	Observing temporary stabilization and water bars		
GPS Location	O	GPS Location	O		
Field Station#	15614+94	Field Station#	15619+48		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing road crossing and RCE's		
GPS Location	O	GPS Location	O		
Field Station#	15624+00	Field Station#	15623+00		
Pic 5 Desc.	Observing temporary stabilization and water bars	Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's		

AFE	124300139	Date/Time	3/23/2022 8:43 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15629+00	Field Station#	15632+00		
Pic 7 Desc.	Observing temporary stabilization and CWD berm	Pic 8 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/23/2022 8:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35771
Inspector	Justin Burch			Date/Time	3/23/2022 10:00 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Full	Station End	15260+00
County	Pittsylvania	Ground	Wet	Temperature (°F)	65.00
Municipality	Chatham	Weather	Heavy Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/23/2022 10:00 AM	Report #	35771
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has not received a rain event except for one that began this morning. The gauges will be read tomorrow morning after this event is over. The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/23/2022 10:00 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15147+00	Field Station#	15159+00		
Pic 1 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 2 Desc.	Waterbar in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	15159+00	Field Station#	15160+00		
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	P1 silt fence in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	15158+00	Field Station#	15207+00		
Pic 5 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 6 Desc.	Waterbar in acceptable condition		

AFE	124300139	Date/Time	3/23/2022 10:00 AM	Report #	
Pictures					
 <p>15222+00 03-23-2022, 10:02:41</p>		 <p>15142+80 03-23-2022, 10:55:59</p>			
GPS Location	0	GPS Location	0		
Field Station#	15222+00	Field Station#	15142+80		
Pic 7 Desc.	Perimeter CFS and permanent vegetative stabilization in acceptable conditions		Pic 8 Desc.	Rock construction entrance in acceptable condition	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	3/23/2022 10:00 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35787
Inspector	Charles Head			Date/Time	3/23/2022 1:50 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Full	Station End	14802+19
County	Franklin	Ground	Wet	Temperature (°F)	56.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/23/2022 1:50 PM	Report #	35787
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/23/2022 1:50 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14695+00	Field Station#	14801+50		
Pic 1 Desc.	Approximately 14695+00. Overview of road crossing and RCE.	Pic 2 Desc.	Approximately 14801+50. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14775+00	Field Station#	14778+00		
Pic 3 Desc.	Approximately 14775+00. Overview of ROW.	Pic 4 Desc.	Approximately 14778+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14748+00	Field Station#	14761+00		
Pic 5 Desc.	Approximately 14748+00. Overview of ROW.	Pic 6 Desc.	Approximately 14761+00. Overview of ROW.		

A/E	124300139	Date/Time	3/23/2022 1:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	3/23/2022 1:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35789
Inspector	Ben Farmer			Date/Time	3/23/2022 3:07 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Partial	Station End	13958+31
County	Franklin	Ground	Wet	Temperature (°F)	54.00
Municipality	N/A	Weather	Heavy Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Sediment Trap	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	3/23/2022 3:07 PM	Report #	35789
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 54F) Rain Gauge= 0.0" 13853+45-13958+31 -EI began inspection at MVP-FR-303.1 -FR-303.1 remains in good condition with controls in place. -SSF is in good condition throughout this area. -Resource buffers remain well vegetated at all stream and wetland crossings. -CWDs are in good condition and functioning as intended -Perimeter P1 is in good condition. -Equipment bridge ECDs are in good condition and functioning. -Perimeter CFS is in good condition throughout this section. -Slope drain/Slope drain outlets are in good condition and functioning. -Steep slope at 13889+00 remains stabilized. -RCEs are in good condition at all road crossings. -Sediment trap at 13897+00 is in good condition with no evidence of discharge. -Vegetation continues to fill in throughout this section. -Topsoil berms remain stabilized.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/23/2022 3:07 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13853+45		Field Station#	13860+00	
Pic 1 Desc.	MVP-FR-303.1 is in good condition with controls in place		Pic 2 Desc.	SSF is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13862+60		Field Station#	13889+00	
Pic 3 Desc.	Equipment bridge ECDs are in good condition and functioning		Pic 4 Desc.	Slope drain is functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13890+00		Field Station#	13892+00	
Pic 5 Desc.	Slope on the CIS of Iron Ridge Rd. remains stabilized with controls in place		Pic 6 Desc.	Waterbars are functioning as intended	

AFE	124300139	Date/Time	3/23/2022 3:07 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13894+00		Field Station#	13897+00	
Pic 7 Desc.	Perimeter P1 is in the throughout this section		Pic 8 Desc.	Sediment trap is in good condition condition with no evidence of discharge.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13905+00		Field Station#	13941+00	
Pic 9 Desc.	Vegetation continues to fill in throughout this section		Pic 10 Desc.	Topsoil berms remain stabilized	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13943+00		Field Station#	13948+00	
Pic 11 Desc.	CWDs are functioning as intended		Pic 12 Desc.	End treatments are functioning as intended	







AFE	124300139	Date/Time	3/23/2022 3:07 PM	Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13950+00		Field Station#	13955+00	
Pic 13 Desc.	Resource buffers remain well vegetated		Pic 14 Desc.	Slope drain outlet is in good condition and functioning.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 15 Desc.			Pic 16 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 17 Desc.			Pic 18 Desc.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35828
Inspector	Justin Burch			Date/Time	3/24/2022 11:53 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Full	Station End	15370+62
County	Pittsylvania	Ground	Wet	Temperature (°F)	69.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.20
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Plunge Pool	Acceptable				
Compost Filter Sock	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/24/2022 11:53 AM	Report #	35828
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has received one rain event with totals of 1.25" at Armstrong Road and 1.20" at Snowberry Road. The ROW ground condition is wet. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15355+00 to 15370+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/24/2022 11:53 AM	Report #	
Pictures					
 <p>15369+00 03-24-2022, 09:10:18</p>			 <p>15310+00 03-24-2022, 09:45:34</p>		
GPS Location	0		GPS Location	0	
Field Station#	15369+00		Field Station#	15310+00	
Pic 1 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 2 Desc.	P1 silt fence in acceptable condition	
 <p>15315+00 03-24-2022, 10:10:06</p>			 <p>15315+00 03-24-2022, 10:10:23</p>		
GPS Location	0		GPS Location	0	
Field Station#	15315+00		Field Station#	15315+00	
Pic 3 Desc.	Waterbar in acceptable condition		Pic 4 Desc.	Waterbar end treatment in acceptable condition	
 <p>15334+00 03-24-2022, 10:41:31</p>			 <p>15338+00 03-24-2022, 10:47:06</p>		
GPS Location	0		GPS Location	0	
Field Station#	15334+00		Field Station#	15338+00	
Pic 5 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		Pic 6 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions	

A/E	124300139	Date/Time	3/24/2022 11:53 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	15355+00	Field Station#	15357+00		
Pic 7 Desc.	Perimeter CFS in acceptable condition	Pic 8 Desc.	Permanent vegetative stabilization in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	3/24/2022 11:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35785
Inspector	Ben Davenport			Date/Time	3/24/2022 9:43 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Partial	Station End	14546+75
County	Franklin	Ground	Muddy	Temperature (°F)	67.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	2.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Waterbar	Acceptable				
Equipment Bridge	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/24/2022 9:43 AM	Report #	35785
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Checked rain gauges in covered area -Cloudy with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list -Rain Gauge Totals: +Farm View: 2.00 inches recorded +Timber Ridge: 1.90 inches recorded					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/24/2022 9:43 AM	Report #	
Pictures					
					
37°13'4" N 79°46'4" W 141°SE COURSE 101' GPS 2750 Webster Rd, Glade Hill, VA 24092, United States 03.24.2022 11:03:46 Accur +/-15.3 Ft ALT 0 Ft			37°13'1" N 79°46'0" W 148°SE COURSE -1' GPS Glade Hill, VA 24092, United States 03.24.2022 11:06:47 Accur +/-87.9 Ft ALT 1101 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14457+00	Field Station#	14460+00		
Pic 1 Desc.	Minor rutting occurring in travel lane. Will monitor for signs of worsening.		Pic 2 Desc.	CWD pipe in good condition; contractor replaced perimeter CFS per punch list item.	
					
37°0'41" N 79°45'17" W 351°N COURSE 13' GPS 1705 SR-674, Glade Hill, VA 24092, United States 03.24.2022 10:12:09 Accur +/-34.9 Ft ALT 1057 Ft			37°0'39" N 79°45'15" W 214°SW COURSE 177' GPS 1760 SR-674, Glade Hill, VA 24092, United States 03.24.2022 09:57:59 Accur +/-15.2 Ft ALT 1050 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14521+00	Field Station#	14527+00		
Pic 3 Desc.	ROW stabilized and vegetated in temporary area; perimeter controls in place and functional.		Pic 4 Desc.	ROW stabilized and vegetated in temporary area; perimeter controls in place and functional.	
					
37°0'34" N 79°45'14" W 165°S COURSE 77' GPS Glade Hill, VA 24092, United States 03.24.2022 10:00:59 Accur +/-153.9 Ft ALT 1061 Ft			37°0'28" N 79°45'15" W 155°SE COURSE 117' GPS 1886 SR-674, Glade Hill, VA 24092, United States 03.24.2022 10:05:11 Accur +/-34.5 Ft ALT 1044 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14531+58	Field Station#	14540+00		
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 6 Desc.	ROW stabilized and vegetated in temporary area; perimeter controls in place and functional.	

A/E	124300139	Date/Time	3/24/2022 9:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/24/2022 9:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35836
Inspector	Charles Head			Date/Time	3/24/2022 1:37 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Full	Station End	14928+52
County	Franklin	Ground	Muddy	Temperature (°F)	68.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.80
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
3rd Party Damages	Communication	Install orange waddles across third p		
Compost Filter Sock	Communication	Replace third party damage with ora		
Cleanwater Diversion Pipe	Communication	Repair joint		
Equipment Bridge	Communication	Remove sediment and debris		
Rock Construction Entrance	Acceptable			
Waterbar End Treatment	Communication	Install curlex behind triple stack		
Waterbar	Communication	Remove sediment and debris		
Silt Fence (Filter Fabric Fence)	Communication	Replace/remove panel		
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to chain link/ repair t		

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	3/24/2022 1:37 PM	Report #	35836
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/24/2022 1:37 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14812+00	Field Station#	14845+75		
Pic 1 Desc.	Approximately 14812+00. Overview of ROW.		Pic 2 Desc.	Approximately 14845+75. Overview of road crossing and RCEs.	
					
GPS Location	0	GPS Location	0		
Field Station#	14916+00	Field Station#	14896+00		
Pic 3 Desc.	Approximately 14916+00. Overview of stream crossing, equipment bridge and ECDs at stream S-G16.		Pic 4 Desc.	Approximately 14896+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14843+00	Field Station#	14804+00		
Pic 5 Desc.	Approximately 14843+00. Overview of ROW.		Pic 6 Desc.	Approximately 14804+00. Overview of ROW.	

AFE	124300139	Date/Time	3/24/2022 1:37 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14823+50	Field Station#	14850+80		
Pic 7 Desc.	Approximately 14823+50. Sediment from beyond LOD migrated onto LOD and onto equipment bridge. Caused by rain event 03/22/22 and last rain event 03/24/22		Pic 8 Desc.	Approximately 14850+80. CWD piping requires maintenance.	
					
GPS Location	0	GPS Location	0		
Field Station#	14855+40	Field Station#	14871+50		
Pic 9 Desc.	Approximately 14855+40. Breaker trough requires maintenance. Pooling issue. Remove sediment and debris.		Pic 10 Desc.	Approximately 14871+50. SSF requires maintenance. Holes in fabric	
					
GPS Location	0	GPS Location	0		
Field Station#	14877+00	Field Station#	14881+75		
Pic 11 Desc.	Approximately 14877+00. LOD CFS damaged by third party.		Pic 12 Desc.	Approximately 14881+75. P-1 requires maintenance. Repair/remove. Secondary ECD.	

A/E	124300139	Date/Time	3/24/2022 1:37 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35821
Inspector	John White			Date/Time	3/24/2022 10:15 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Wet	Temperature (°F)	63.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.20
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Perform maintenance			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/24/2022 10:15 AM	Report #	35821
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There was one issue identified and added to the punch list. Checked rain gauges, Anderson Mill #2=1.2", Mill Creek =1.2", Transco =1.2". Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/24/2022 10:15 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15690+00	Field Station#	15700+35		
Pic 1 Desc.	Observing temporary stabilization, water bars and CFS checks.	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15693+89	Field Station#	15738+00		
Pic 3 Desc.	Observing road crossing and RCE's	Pic 4 Desc.	Observing temporary stabilization, sump and end treatment		
GPS Location	O	GPS Location	O		
Field Station#	15735+00	Field Station#	15763+80		
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

AFE	124300139	Date/Time	3/24/2022 10:15 AM	Report #	
Pictures					
		<p>Insert image here</p>			
GPS Location	O	GPS Location			
Field Station#	15768+00	Field Station#			
Pic 7 Desc.	Observing P1 that requires maintenance	Pic 8 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/24/2022 10:15 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		










Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35837
Inspector	Ben Farmer			Date/Time	3/24/2022 2:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Partial	Station End	14062+17
County	Franklin	Ground	Wet	Temperature (°F)	54.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	3.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	CFS has been undermined and nee			
Equipment Bridge	Acceptable				
Rock Check Dam	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to			
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/24/2022 2:25 PM	Report #	35837
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in good			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 54F) Rain Gauge= 3.0" 13958+31-14062+17 -EI began inspection at Foggy Ridge Rd. -CWD/CWD inlets are in good condition and functioning as intended -CFS has been undermined at 13970+00. -3rd party pond spillway is discharging onto ROW at 14000+00. LEI has been notified and EI will continue to monitor. (See daily report) -Waterbars are in good condition. -MVP-ATWS-1446 remains stabilized with controls in place. -Equipment bridge ECDs are in good condition and functioning. -Perimeter P1 is in good condition. -Slope on the CIS of Highway 220 remains stabilized with controls in place. -Resource buffers remain well vegetated at all stream and wetland crossings. -P1 has been damaged and needs to be replaced at 14036+00. -Check dams are functioning as intended at 14057+50. -Slope drain is in good condition and functioning at 14057+50. -Vegetation continues to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/24/2022 2:25 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13962+00		Field Station#	13970+00	
Pic 1 Desc.	CWDs are in good condition and functioning as intended		Pic 2 Desc.	CFS is undermined and needs to be keyed in	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14000+00		Field Station#	13997+50	
Pic 3 Desc.	3rd party pond is discharging onto MVP ROW. (See daily report #35839)		Pic 4 Desc.	3rd party pond is discharging onto MVP ROW. (See daily report #35839)	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14000+00		Field Station#	14009+20	
Pic 5 Desc.	3rd party pond is discharging onto MVP ROW. (See daily report #35839)		Pic 6 Desc.	Equipment bridge ECDs are in place and functioning	

AFE	124300139	Date/Time	3/24/2022 2:25 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14015+00		Field Station#	14018+47	
Pic 7 Desc.	Vegetation continues to fill in throughout this section		Pic 8 Desc.	RCEs are in good condition at all road crossings.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14033+00		Field Station#	14035+28	
Pic 9 Desc.	Waterbars are in good condition and functioning		Pic 10 Desc.	Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14036+00		Field Station#	14057+50	
Pic 11 Desc.	P1 has been damaged and needs to be replaced		Pic 12 Desc.	Rock check dams are functioning along drainage.	

A/E	124300139	Date/Time	3/24/2022 2:25 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location			
Field Station#	14057+50	Field Station#			
Pic 13 Desc.	Slope drain is functioning as intended.	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35886
Inspector	Justin Burch			Date/Time	3/25/2022 1:11 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Full	Station End	15480+67
County	Pittsylvania	Ground	Wet	Temperature (°F)	62.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.20
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Plunge Pool	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/25/2022 1:11 PM	Report #	35886
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI observed that stream S-G4 (15426+55) was turbid entering the ROW. This is a result of an upstream disturbance not related to MVP ROW. The EI observed that the perimeter solar farm ECDs on the CIS of Toshes Road appeared to be in acceptable condition and that no sediment from solar farm was entering the clean water diversion pipes. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has received one rain event with totals of 1.20" at Snowberry Road and 1.20" at Anderson Mill Road 2 The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15438+00 to 15445+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/25/2022 1:11 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15376+00	Field Station#	15384+00		
Pic 1 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 2 Desc.	P1 silt fence and temporary vegetative stabilization in acceptable conditions		
					
GPS Location	0	GPS Location	0		
Field Station#	15387+00	Field Station#	15387+00		
Pic 3 Desc.	Waterbar in acceptable condition	Pic 4 Desc.	Waterbar end treatment in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	15404+00	Field Station#	15442+00		
Pic 5 Desc.	Plunge pool in acceptable condition	Pic 6 Desc.	Permanent vegetative stabilization and perimeter CFS in acceptable conditions		

A/E	124300139	Date/Time	3/25/2022 1:11 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	15435+00	Field Station#	15401+00		
Pic 7 Desc.	Equipment bridge and sensitive resource buffer in acceptable conditions	Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition		
GPS Location	0	GPS Location	0		
Field Station#	15426+54	Field Station#	15461+00		
Pic 9 Desc.	Turbidity in stream S-G4. This is a result of an upstream disturbance not related to MVP ROW	Pic 10 Desc.	Solar farm ECDs in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	3/25/2022 1:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35884
Inspector	Charles Head			Date/Time	3/25/2022 12:53 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Full	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Wet	Temperature (°F)	57.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/25/2022 12:53 PM	Report #	35884
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/25/2022 12:53 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15045+00	Field Station#	14984+00		
Pic 1 Desc.	Approximately 15045+00. Overview of stream crossing, equipment bridge and ECDs at stream S-D2.		Pic 2 Desc.	Approximately 14984+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14981+00	Field Station#	14970+00		
Pic 3 Desc.	Approximately 14981+00. Overview of road crossing and RCEs.		Pic 4 Desc.	Approximately 14970+00. Overview of ROW. Permanent vegetation.	
					
GPS Location	0	GPS Location	0		
Field Station#	14950+47	Field Station#	14937+00		
Pic 5 Desc.	Approximately 14950+47. Overview of stream crossing, equipment bridge and ECDs at stream S-G13.		Pic 6 Desc.	Approximately 14937+00. Overview of ROW.	

A/E	124300139	Date/Time	3/25/2022 12:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/25/2022 12:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35875
Inspector	Logan Box			Date/Time	3/25/2022 4:17 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Wet	Temperature (°F)	64.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)		Acceptable			
Compost Filter Sock		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Equipment Bridge		Acceptable			
Timber Mat		Acceptable			
Rock Construction Entrance		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/25/2022 4:17 PM	Report #	35875
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p> <p>Row conditions were saturated during row travel today. Newly installed ECDs and stabilization were in place and functioning after recent rain events.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/25/2022 4:17 PM	Report #	
Pictures					
	East Elevation 			North West Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13728+23	Field Station#	13705+00		
Pic 1 Desc.	Monitored ECDs and stabilization on hill sides above stream crossing, no environmental issues observed at the time of inspection.		Pic 2 Desc.	Stream observation photo facing downstream during routine inspection today, no issues observed at the time of inspection.	
	South Elevation 			North East Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13705+00	Field Station#	13704+90		
Pic 3 Desc.	Stream observation photo facing upstream during routine inspection today.		Pic 4 Desc.	Monitored ECDs at stream and wetland crossing, no environmental issues observed at the time of inspection.	
	North Elevation 			South East Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13740+00	Field Station#	13696+90		
Pic 5 Desc.	Vegetation observation photo showing good stabilization.		Pic 6 Desc.	Row photo showing mats in place in low area of row with ECDs in place, no environmental issues observed at the time of inspection.	

A/E	124300139	Date/Time	3/25/2022 4:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/25/2022 4:17 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35859
Inspector	Ben Davenport			Date/Time	3/25/2022 9:30 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+77
State	VA	Inspection Area	Partial	Station End	14649+67
County	Franklin	Ground	Muddy	Temperature (°F)	60.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Compost Filter Sock	Acceptable			
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Plunge Pool	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Sump Pit	Acceptable			
Waterbar End Treatment	Acceptable			
Rock Filter Outlet	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	3/25/2022 9:30 AM	Report #	35859
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Sunny with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14546+77 — 14649+67 (Tobacco Rd to Hwy 40) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/25/2022 9:30 AM	Report #	
Pictures					
					
37°0'18" N 79°45'9" W 192°S COURSE 230' GPS 594 Tobacco Rd, Glade Hill, VA 24092, United States 03.25.2022 10:28:25 Accur +/-15.4 Ft ALT 936 Ft			37°0'16" N 79°45'7" W 165°S COURSE 131' GPS 594 Tobacco Rd, Glade Hill, VA 24092, United States 03.25.2022 10:29:36 Accur +/-15.3 Ft ALT 927 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14547+00	Field Station#	14551+00		
Pic 1 Desc.	Perimeter SSF and CFS in place and functional.	Pic 2 Desc.	Temporary diversion berm stabilized and vegetated. ROW stabilized and vegetated in temporary area.		
					
37°0'15" N 79°45'7" W 182°S COURSE 167' GPS 594 Tobacco Rd, Glade Hill, VA 24092, United States 03.25.2022 10:30:00 Accur +/-15.3 Ft ALT 916 Ft			36°59'54" N 79°44'22" W 61°NE COURSE 282' GPS 753 Simmons Creek Rd, Union Hall, VA 24176, United States 03.25.2022 10:38:33 Accur +/-15.4 Ft ALT 928 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14555+00	Field Station#	14590+00		
Pic 3 Desc.	Plunge pool performing intended function.	Pic 4 Desc.	Sump pit and CFS end treatment performing intended functions.		
					
36°59'50" N 79°44'15" W 300°NW COURSE 134' GPS 504-798 Simmons Creek Rd, Union Hall, VA 24176, United States 03.25.2022 10:42:42 Accur +/-15.5 Ft ALT 906 Ft			36°59'49" N 79°44'16" W 304°NW COURSE 148' GPS 504-798 Simmons Creek Rd, Union Hall, VA 24176, United States 03.25.2022 10:41:49 Accur +/-18.7 Ft ALT 916 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14602+00	Field Station#	14606+00		
Pic 5 Desc.	Temporary diversion berm stabilized and vegetated. ROW stabilized and vegetated in temporary area.	Pic 6 Desc.	CWD outlet and CFS triple stack in good condition.		

A/E	124300139	Date/Time	3/25/2022 9:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/25/2022 9:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35876
Inspector	John White			Date/Time	3/25/2022 9:36 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Wet	Temperature (°F)	57.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	1.20
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock-lined Channel	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/25/2022 9:36 AM	Report #	35876
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/25/2022 9:36 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15776+00	Field Station#	15781+22		
Pic 1 Desc.	Observing temporary stabilization,water bar, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15826+77	Field Station#	15825+00		
Pic 3 Desc.	Observing road crossing and RCE's	Pic 4 Desc.	Observing temporary stabilization,plunge pool and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15835+00	Field Station#	15838+00		
Pic 5 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 6 Desc.	Observing temporary stabilization, rock lined channel and ECD's		

A/E	124300139	Date/Time	3/25/2022 9:36 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/25/2022 9:36 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35894
Inspector	Ben Farmer			Date/Time	3/25/2022 3:30 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Partial	Station End	14171+36
County	Franklin	Ground	Damp	Temperature (°F)	47.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	CFS has been displaced and needs			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	P1 needs to be restaked			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/25/2022 3:30 PM	Report #	35894
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 47F) Rain Gauge= 0.0" 14062+17-14171+36 -EI began inspection at Bonbrook Mill #2. -Equipment bridge ECDs are in place and functioning. -MVP-FR-309.05 is in good condition with controls in place. -CWD/CWD inlets are in good condition and functioning as intended -Topsoil berm remains stabilized. -SSF is in good condition. -Waterbars are functioning as intended. -Resource buffers remain well vegetated at all stream and wetland crossings. -RCEs are in good condition at all road crossings. -P1 needs to be restaked at 14127+00 -CFS has been displaced and needs to be restaked at 14132+00. -Slope drain is in good condition and functioning at 14157+00 -EI was instructed to inspect area of landowner complaint at 14158+50. EI inspected this area and found ECDs to be installed and functioning to specs. No sediment discharging from ROW. -Vegetation continues to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/25/2022 3:30 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14063+00		Field Station#	14066+77	
Pic 1 Desc.	Vegetation continues to fill in throughout this section		Pic 2 Desc.	Equipment bridge ECDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14072+87		Field Station#	14070+00	
Pic 3 Desc.	FR-309.06 is in good condition with controls in place		Pic 4 Desc.	CWDs are functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14085+00		Field Station#	14090+00	
Pic 5 Desc.	Vegetation continues to fill in throughout this section		Pic 6 Desc.	Topsoil berms remain stabilized	

AFE	124300139	Date/Time	3/25/2022 3:30 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14103+00		Field Station#	14195+20	
Pic 7 Desc.	Waterbars are in good condition		Pic 8 Desc.	Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14107+00		Field Station#	14127+00	
Pic 9 Desc.	SSF is in good condition throughout this section		Pic 10 Desc.	P1 needs to be restaked along drainage feature	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14132+00		Field Station#	14141+62	
Pic 11 Desc.	CFS has been displaced and needs to be restaked		Pic 12 Desc.	P1 is in good condition at all stream and wetland buffers	

AFE	124300139	Date/Time	3/25/2022 3:30 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14157+00	Field Station#	14158+50		
Pic 13 Desc.	Slope drain is functioning as intended	Pic 14 Desc.	Area of landowner complaint. No evidence of sedimentation or damaged ECDs at this location		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	14171+36	Field Station#			
Pic 15 Desc.	RCEs are in good condition at all road crossings.	Pic 16 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	35731
Inspector	John White			Date/Time	3/22/2022 12:37 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Filter	Acceptable			
Sediment Basin	Acceptable			
Rock Filter Outlet	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Erosion Control Blanket	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	3/22/2022 12:37 PM	Report #	35731
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	3/22/2022 12:37 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O	GPS Location	O
Field Station#	00+00	Field Station#	00+00	Field Station#	00+00
Pic 1 Desc.	Observing Lay down yard	Pic 2 Desc.	Observing temporary stabilization and sediment basin	Pic 3 Desc.	Observing temporary stabilization, erosion control blanket, rock drain and CFS check
GPS Location	O	GPS Location	O	GPS Location	O
Field Station#	00+00	Field Station#	00+00	Field Station#	00+00
Pic 4 Desc.	Observing temporary stabilization and sediment basin	Pic 5 Desc.	Observing storm water pond	Pic 6 Desc.	Observing emergency overflow at the storm water pond

A/E	124300113	Date/Time	3/22/2022 12:37 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	3/22/2022 12:37 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		