










Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	35192	
Inspector	Ben Davenport				Date/Time	3/7/2022 2:36 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	14311+57	
State	VA	Inspection Area	Partial		Station End	14454+22	
County	Franklin	Ground	Dry		Temperature (°F)	70.00	
Municipality	N/A	Weather	Cloudy		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Communication	Routine maintenance				
Compost Filter Sock		Communication	Routine maintenance				
Compost Filter Sock		Communication	Routine maintenance				
Compost Filter Sock		Communication	Routine maintenance				
Equipment Bridge		Communication	Routine maintenance				
Silt Fence (Filter Fabric Fence)		Communication	Routine maintenance				
Silt Fence (Filter Fabric Fence)		Communication	Routine maintenance				
Vegetative Stabilization (Temporary)		Acceptable					
Waterbar		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	3/7/2022 2:36 PM	Report #	35192
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Cloudy with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd) -Walked ROW making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; multiple issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; multiple issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -7 items added to environmental punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/7/2022 2:36 PM	Report #	
Pictures					
					
37°15'1" N 79°46'43" W 241°SW COURSE 322° GPS Glade Hill, VA 24092, United States 03.07.2022 10:20:42 Accur +/-140.2 Ft ALT 1012 Ft			37°15'0" N 79°46'40" W 34°NE COURSE 322° GPS Glade Hill, VA 24092, United States 03.07.2022 10:20:10 Accur +/-329.9 Ft ALT 1012 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14419+75	Field Station#	14421+00		
Pic 1 Desc.	Routine maintenance. Fallen tree down on perimeter CFS.		Pic 2 Desc.	Routine maintenance. Multiple fallen trees down on CFS in resource buffer.	
					
37°146" N 79°46'33" W 333°NW COURSE 278° GPS Glade Hill, VA 24092, United States 03.07.2022 10:16:27 Accur +/-249.5 Ft ALT 1078 Ft			37°145" N 79°46'33" W 322°NW COURSE 321° GPS Glade Hill, VA 24092, United States 03.07.2022 10:15:22 Accur +/-51.1 Ft ALT 1021 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14426+00	Field Station#	14430+00		
Pic 3 Desc.	Routine maintenance. Fallen tree down on perimeter CFS.		Pic 4 Desc.	Routine maintenance. Fallen tree down on perimeter CFS.	
					
37°143" N 79°46'26" W 337°NW COURSE 182° GPS Glade Hill, VA 24092, United States 03.07.2022 10:13:50 Accur +/-693.7 Ft ALT 1021 Ft			37°143" N 79°46'26" W 44°NE COURSE 16° GPS Glade Hill, VA 24092, United States 03.07.2022 10:10:54 Accur +/-52.8 Ft ALT 1021 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14434+01	Field Station#	14437+00		
Pic 5 Desc.	Routine maintenance. Fallen tree down on equipment bridge of S-GH40.		Pic 6 Desc.	Routine maintenance. Replace damaged row of P1 silt fence.	

AFE	124300139	Date/Time	3/7/2022 2:36 PM	Report #	
Pictures					
		Insert image here			
GPS Location	7	GPS Location			
Field Station#	14445+00	Field Station#			
Pic 7 Desc.	Routine maintenance. Replace damaged P1 silt fence where stakes are broken or fabric is beyond effective lifespan.		Pic 8 Desc.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	3/7/2022 2:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35183
Inspector	Justin Burch			Date/Time	3/7/2022 12:01 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Damp	Temperature (°F)	76.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Slope Drain Pipe	Communication				
Cleanwater Diversion Pipe	Acceptable				
Plunge Pool	Acceptable				
Waterbar End Treatment	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/7/2022 12:01 PM	Report #	35183
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). One issue was submitted for the punch list consisting of a location where a slope drain pipe had a separated pipe joint. Other inspected ECDs were observed as in compliance at the time of inspection. The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed the items on the punch list. The area has not received any rain events since the last SWPPP inspection. The ROW ground condition is damp. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13910+00 and from 13921+00 to 13940+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/7/2022 12:01 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13890+40	Field Station#	13941+00		
Pic 1 Desc.	A slope drain pipe with a separated pipe joint		Pic 2 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions	
					
GPS Location	0	GPS Location	0		
Field Station#	13946+00	Field Station#	13930+00		
Pic 3 Desc.	Waterbar end treatment in acceptable condition		Pic 4 Desc.	Permanent vegetative stabilization in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	13917+00	Field Station#	13918+00		
Pic 5 Desc.	Temporary vegetative stabilization in acceptable condition		Pic 6 Desc.	Waterbar in acceptable condition	

A/E	124300139	Date/Time	3/7/2022 12:01 PM	Report #	
Pictures					
 <p>13945+00 03-07-2022, 09:29:23</p>		 <p>13854+00 03-07-2022, 10:49:11</p>			
GPS Location	0	GPS Location	0		
Field Station#	13945+00	Field Station#	13854+00		
Pic 7 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		Pic 8 Desc.	P1 silt fence in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/7/2022 12:01 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35182
Inspector	John White			Date/Time	3/7/2022 11:18 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Dry	Temperature (°F)	78.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
3rd Party Damages	Communication	Contractor is going to restabilize loc			
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Contractor is working on repairs			
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Vegetative Stabilization (Temporary)	Communication	Contractor is working on restabilizing			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/7/2022 11:18 AM	Report #	35182
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/7/2022 11:18 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15592+00	Field Station#	15593+00		
Pic 1 Desc.	Observing temporary stabilization and water bar	Pic 2 Desc.	Observing CFS that requires maintenance		
					
GPS Location	O	GPS Location	O		
Field Station#	15594+00	Field Station#	15594+00		
Pic 3 Desc.	Observing CFS that requires maintenance	Pic 4 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15608+00	Field Station#	15608+00		
Pic 5 Desc.	Observing location that needs to be restabilized (3rd party damage)	Pic 6 Desc.	Observing location that needs to be restabilized (3rd party damage)		

AFE	124300139	Date/Time	3/7/2022 11:18 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15630+00	Field Station#	15636+45		
Pic 7 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 8 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/7/2022 11:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35190
Inspector	Ben Davenport			Date/Time	3/7/2022 9:17 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance		
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Sump Pit	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Equipment Bridge	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300139	Date/Time	3/7/2022 9:17 AM	Report #	35190
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Cloudy with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 — 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; 1 issue identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -1 item added to environmental punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/7/2022 9:17 AM	Report #	
Pictures					
					
36°59'15" N 79°42'0" W 92°E COURSE 170° GPS Union Hall, VA 24176, United States			36°59'16" N 79°41'58" W 113°E COURSE 170° GPS Union Hall, VA 24176, United States		
03.07.2022 13:21:57 Accur +/-1219.6 Ft ALT 890 Ft			03.07.2022 13:22:00 Accur +/-82.9 Ft ALT 890 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14721+50	Field Station#	14727+62		
Pic 1 Desc.	Routine maintenance. Replace damaged row of P1 silt fence.		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	
					
36°58'44" N 79°41'2" W 303°NW COURSE 326° GPS Penhook, VA 24137, United States			36°58'44" N 79°41'1" W 311°NW COURSE 247° GPS Penhook, VA 24137, United States		
03.07.2022 09:36:52 Accur +/-15.4 Ft ALT 851 Ft			03.07.2022 09:37:08 Accur +/-15.4 Ft ALT 859 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14782+25	Field Station#	14785+00		
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 4 Desc.	Sump pit and CFS end treatment performing intended functions.	
					
36°58'38" N 79°40'45" W 168°S COURSE 314° GPS 245 Zeigler Ln, Union Hall, VA 24176, United States			36°58'40" N 79°40'50" W 330°NW COURSE 32° GPS Penhook, VA 24137, United States		
03.07.2022 09:44:22 Accur +/-368.2 Ft ALT 857 Ft			03.07.2022 09:33:50 Accur +/-261.1 Ft ALT 870 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14797+00	Field Station#	14788+77		
Pic 5 Desc.	ROW seeded and stabilized where contractor dug anode bed.		Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	

A/E	124300139	Date/Time	3/7/2022 9:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	3/7/2022 9:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35189
Inspector	Ben Farmer			Date/Time	3/7/2022 1:49 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/7/2022 1:49 PM	Report #	35189
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 70F) Rain Gauge= 0.0" 15142+66-15260+00 -EI began inspection at Rockcreek Rd. -RCE is in good condition at Rockcreek Rd. -Perimeter CFS/P1 is in good condition. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00 -P1 is in good condition at stream buffer. -Equipment bridge ECDs are in place and functioning. -Slope drain is functioning as intended at 15170+00. -Waterbars are in good condition throughout this section. -Drainage feature ECDs are in good condition and functioning at 15195+00. -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/7/2022 1:49 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15142+66		Field Station#	15150+00	
Pic 1 Desc.	RCE is in good condition at Rockcreek Rd.		Pic 2 Desc.	Perimeter CFS is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15160+00		Field Station#	15165+57	
Pic 3 Desc.	Perimeter P1 is in good condition		Pic 4 Desc.	Rock outlet is functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15166+00		Field Station#	15167+00	
Pic 5 Desc.	Rock outlet remains in good condition.		Pic 6 Desc.	P1 is in good condition at stream buffer	

AFE	124300139	Date/Time	3/7/2022 1:49 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15167+00		Field Station#	15168+49	
Pic 7 Desc.	Equipment bridge ECDs are in good condition and functioning		Pic 8 Desc.	Resource buffer remains well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15172+00	
Pic 9 Desc.	Slope drain is functioning as intended		Pic 10 Desc.	Waterbars are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15195+00		Field Station#	15230+00	
Pic 11 Desc.	Drainage ECDs are in place and functioning		Pic 12 Desc.	Vegetation continues to fill in throughout this section.	






A/E	124300139	Date/Time	3/7/2022 1:49 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35193
Inspector	Ben Davenport			Date/Time	3/8/2022 12:40 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Muddy	Temperature (°F)	55.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Compost Filter Sock	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Slope Drain Pipe	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/8/2022 12:40 PM	Report #	35193
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Checked rain gauges in covered area -Received instruction from Lead EI for daily tasks -Performed SWPPP inspection on portion of MVP Spread I project -Inspection covered area between station# 14802+19–14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Sunny with muddy ground conditions during inspection -Verified the completion of punch list items in covered area from previous inspection -Inspection observed condition of perimeter controls and ECDs in section; no issues observed -Inspection observed condition of equipment bridges and ECDs around stream crossings and resource buffers; multiple issues observed -Inspection observed condition of RCEs and culverts at road crossings in section; no issues observed -Inspection observed condition of temporary and permanent vegetation throughout section; no issues observed -No items added to environmental punch list -Rain Gauge Totals: +Indian Cave: 0.30 inches recorded +Armstrong: 0.20 inches recorded					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/8/2022 12:40 PM	Report #	
Pictures					
					
36°58'35" N 79°40'40" W 164°S COURSE 116° GPS Penhook, VA 24137, United States			36°58'35" N 79°40'39" W 189°S COURSE 95° GPS Penhook, VA 24137, United States		
03.08.2022 11:59:37 Accur +/-61.9 Ft ALT 940 Ft			03.08.2022 12:02:08 Accur +/-656.2 Ft ALT 922 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14804+99		Field Station#	14811+00	
Pic 1 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 2 Desc.	Contractor seeded and stabilized disturbed area where anode beds were dug.	
					
36°58'21" N 79°40'0" W 299°NW COURSE 299° GPS 355 Listening Hill Rd, Penhook, VA 24137, United States			36°58'22" N 79°40'2" W 353°N COURSE -1° GPS 1120 Listening Hill Rd, Penhook, VA 24137, United States		
03.08.2022 10:03:54 Accur +/-15.3 Ft ALT 958 Ft			03.08.2022 10:04:26 Accur +/-15.3 Ft ALT 963 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14834+00		Field Station#	14839+00	
Pic 3 Desc.	ROW stabilized and vegetated in temporary area.		Pic 4 Desc.	P1 silt fence on slope in good condition.	
					
36°58'20" N 79°39'54" W 101°E COURSE -1° GPS 355 Listening Hill Rd, Penhook, VA 24137, United States			36°58'20" N 79°39'52" W 155°SE COURSE -1° GPS 355 Listening Hill Rd, Penhook, VA 24137, United States		
03.08.2022 10:00:24 Accur +/-16.8 Ft ALT 980 Ft			03.08.2022 10:01:05 Accur +/-14.6 Ft ALT 950 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14847+68		Field Station#	14851+00	
Pic 5 Desc.	Sump pit and CFS end treatment performing intended functions.		Pic 6 Desc.	Sump pit and slope drain pipe in place and functional.	

A/E	124300139	Date/Time	3/8/2022 12:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/8/2022 12:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35236
Inspector	Ben Farmer			Date/Time	3/8/2022 1:52 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Damp	Temperature (°F)	48.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	CFS is damaged and needs to be re			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	P1 is damaged and needs to be rep			
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/8/2022 1:52 PM	Report #	35236
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 48F) Rain Gauge= 0.2" 15260+00-15370+62 -EI began inspection at Oxford Rd. -RCEs are in good condition at all road crossings. -CWDs are functioning as intended -CFS end treatment needs to be repaired at 15310+00. -P1 remains in good condition around wetland buffer at 15311+87. -Equipment bridge ECDs are in good condition and functioning. -P1 is in good condition at all stream and wetland buffers. -Perimeter CFS needs to be extended to end treatment at 15317+00. -All drainage feature ECDs are in good condition. -P1 check is degraded and needs to be replaced at 15331+00. -Waterbars are in good condition. -Resource buffers remain well vegetated. -P1 has been damaged by livestock and needs to be restaked at 15349+00. -CFS has been damaged by livestock along MVP-PI-332 and needs to be replaced. -CFS needs to be repaired at 15364+00-15370+00. -Vegetation continues to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/8/2022 1:52 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15296+00		Field Station#	15299+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings		Pic 2 Desc.	CWD is functioning as intended.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15310+00		Field Station#	15311+78	
Pic 3 Desc.	CFS end treatment needs to be repaired		Pic 4 Desc.	P1 is in good condition at wetland buffer.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15314+00		Field Station#	15314+50	
Pic 5 Desc.	Equipment bridge ECDs are in good condition and functioning		Pic 6 Desc.	P1 is in good condition at all stream and wetland buffers.	

AFE	124300139	Date/Time	3/8/2022 1:52 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15317+00		Field Station#	15330+00	
Pic 7 Desc.	CFS needs to be extended to end treatment.		Pic 8 Desc.	Drainage feature ECDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15331+00		Field Station#	15338+00	
Pic 9 Desc.	P1 check is degraded and needs to be replaced		Pic 10 Desc.	CWD is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15345+00		Field Station#	15346+87	
Pic 11 Desc.	Waterbars are in good condition		Pic 12 Desc.	Resource buffers remain well vegetated	

AFE	124300139	Date/Time	3/8/2022 1:52 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15349+00	Field Station#	15350+00		
Pic 13 Desc.	P1 has been damaged by livestock and needs to be restaked	Pic 14 Desc.	CFS has been damaged by livestock along MVP-PI-332.		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	15364+00	Field Station#			
Pic 15 Desc.	CFS needs to be repaired from 15364+00-15370+00.	Pic 16 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35237
Inspector	Charles Head			Date/Time	3/8/2022 2:01 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Damp	Temperature (°F)	59.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.25
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/8/2022 2:01 PM	Report #	35237
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/8/2022 2:01 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14546+33	Field Station#	14524+50		
Pic 1 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.		Pic 2 Desc.	Approximately 14524+50. Overview of road crossing and RCEs.	
GPS Location	0	GPS Location	0		
Field Station#	14528+00	Field Station#	14519+00		
Pic 3 Desc.	Approximately 14528+00. Overview of ROW.		Pic 4 Desc.	Approximately 14519+00. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14464+00	Field Station#	14456+50		
Pic 5 Desc.	Approximately 14464+00. Overview of ROW.		Pic 6 Desc.	Approximately 14456+50. Overview of ROW.	

A/E	124300139	Date/Time	3/8/2022 2:01 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 7 Desc.		Pic 8 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/8/2022 2:01 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35224
Inspector	John White			Date/Time	3/8/2022 10:48 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Wet	Temperature (°F)	50.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Communication	Contractor is working on repairs		
Equipment Bridge		Acceptable			
Housekeeping		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Communication	Contractor is working on repairs		
Silt Fence (Reinforced Filter Fabric Fence)		Communication	Contractor is working on repairs		
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/8/2022 10:48 AM	Report #	35224
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Checked rain gauges, Anderson Mill #2=.3", Mill Creek =.3", Transco =.3". Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/8/2022 10:48 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15735+00	Field Station#	15713+52		
Pic 1 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 2 Desc.	Observing temporary stabilization,water bar,signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15713+30	Field Station#	15713+00		
Pic 3 Desc.	Observing P1 that requires maintenance	Pic 4 Desc.	Observing SSF that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15700+00	Field Station#	15693+89		
Pic 5 Desc.	Observing CFS that requires maintenance	Pic 6 Desc.	Observing road crossing and RCE's		

AFE	124300139	Date/Time	3/8/2022 10:48 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15665+50	Field Station#	15860+00		
Pic 7 Desc.	Observing, signage, equipment crossing and ECD's	Pic 8 Desc.	Observing CFS that requires maintenance		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	3/8/2022 10:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	35226		
Inspector	Justin Burch	Date/Time	3/8/2022 11:32 AM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Wet	Temperature (°F)	60.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.25
			Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Cleanwater Diversion Berm		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Sump Pit		Acceptable			
Compost Filter Sock		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/8/2022 11:32 AM	Report #	35226
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area received one rain event with a total 0.25" at Bonbrook Mill Road #1. The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14011+00 to 14018+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/8/2022 11:32 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14032+00	Field Station#	14032+00		
Pic 1 Desc.	Waterbar in acceptable condition		Pic 2 Desc.	Waterbar end treatment in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14038+00	Field Station#	14040+00		
Pic 3 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		Pic 4 Desc.	P1 silt fence in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	13994+00	Field Station#	13968+00		
Pic 5 Desc.	Temporary vegetative stabilization in acceptable condition		Pic 6 Desc.	Sump pit and perimeter CFS in acceptable conditions	

A/E	124300139	Date/Time	3/8/2022 11:32 AM	Report #	
Pictures					
  <p>13970+00 03-08-2022, 11:13:29</p>		  <p>13970+00 03-08-2022, 11:13:14</p>			
GPS Location	0	GPS Location	0		
Field Station#	13970+00	Field Station#	13970+00		
Pic 7 Desc.	Waterbar in acceptable condition		Pic 8 Desc.	Waterbar end treatment in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.			Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	3/8/2022 11:32 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	35321		
Inspector	Frank Craycroft	Date/Time	3/9/2022 4:49 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Full	Station End	13748+30
County	Franklin	Ground	Muddy	Temperature (°F)	55.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Erosion Control Blanket		Acceptable			
Sensitive Resource Buffer		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/9/2022 4:49 PM	Report #	35321
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of ROW from Spread H/I break to Green Level Rd. Vegetation is generally excellent to full with isolated areas less productive. Recent anode dig site near SN 13710+00 is still stabilized with straw mulch, but no signs of new growth were observed. All resource buffers in area are intact and no signs of erosion or runoff were seen in buffers. Bridges are clean and free of sediment deposits. All perimeter ECDs were functional and in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/9/2022 4:49 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13680+00	Field Station#	13873+00		
Pic 1 Desc.	GAS S-E29 Vegetation and ECDs	Pic 2 Desc.	Perimeter CFS		
					
GPS Location	0	GPS Location	0		
Field Station#	13691+50	Field Station#	13692+50		
Pic 3 Desc.	GAS Grassy Hill Rd ATWS Stabilization and silt fence	Pic 4 Desc.	CIS S-E28 Bank stabilization		
					
GPS Location	0	GPS Location	0		
Field Station#	13701+00	Field Station#	13702+00		
Pic 5 Desc.	Perimeter silt fence and fill slope stabilization	Pic 6 Desc.	CIS W-E8 Perimeter ECDs		

AFE	124300139	Date/Time	3/9/2022 4:49 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13708+00	Field Station#	13717+00		
Pic 7 Desc.	Temporary stabilization and Waterbar	Pic 8 Desc.	Perimeter CFS		
					
GPS Location	0	GPS Location	0		
Field Station#	13720+00	Field Station#	13722+00		
Pic 9 Desc.	Sideslope stabilization	Pic 10 Desc.	Sideslope stabilization		
				<p>rt image here</p>	
GPS Location	0	GPS Location	0		
Field Station#	13727+00	Field Station#	13730+00		
Pic 11 Desc.	Sump	Pic 12 Desc.	GAS S-EF4 Perimeter ECDs and travel lane stabilization		






A/E	124300139	Date/Time	3/9/2022 4:49 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13735+00	Field Station#	13740+00		
Pic 13 Desc.	Perimeter CFS and sump	Pic 14 Desc.	Permanent vegetation		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35232
Inspector	Ben Davenport			Date/Time	3/9/2022 10:45 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Muddy	Temperature (°F)	45.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.90
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Compost Filter Sock	Acceptable				
Slope Drain Pipe	Acceptable				
Sump Pit	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Temporary Diversion Berm	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	3/9/2022 10:45 AM	Report #	35232
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Checked rain gauges in covered area -Cloudy with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14928+52 —15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Walked ROW looking for potential environmental issues or maintenance requirements -Perimeter controls and ECDs were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed of stabilization and vegetation in section both permanent and temporary areas of ROW; no issues observed -Continue to monitor ROW for signs of erosion -No items added to environmental punch list -Rain Gauge Totals: +Indian Cave: 0.90 inches recorded +Armstrong: 0.80 inches recorded					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/9/2022 10:45 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	14934+46	Field Station#	14940+00		
Pic 1 Desc.	Perimeter SSF and CFS triple stack in good condition.	Pic 2 Desc.	Natural drainage area and surrounding ECDs in place and functional.		
					
GPS Location	3	GPS Location	4		
Field Station#	14950+47	Field Station#	14952+00		
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 4 Desc.	Slope drain pipe and outlet sump in place and functional.		
					
GPS Location	5	GPS Location	6		
Field Station#	15060+00	Field Station#	15063+85		
Pic 5 Desc.	Temporary diversion berm stabilized and vegetated along perimeter of ROW.	Pic 6 Desc.	Water ponding at approach on Armstrong Rd but causing no issues. Will monitor area.		

A/E	124300139	Date/Time	3/9/2022 10:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/9/2022 10:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35270
Inspector	Justin Burch			Date/Time	3/9/2022 9:25 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Wet	Temperature (°F)	55.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.05
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Sump Pit	Acceptable				
Compost Filter Sock	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/9/2022 9:25 AM	Report #	35270
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area has received two rain events with totals of 1.05" at Bonbrook Mill Road #1 and 1.25" at Farm View Road. • The ROW ground condition is wet. • At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. • At the time of inspection temporary vegetative stabilization was established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/9/2022 9:25 AM	Report #	
Pictures					
GPS Location 0			GPS Location 0		
Field Station# 14080+00			Field Station# 14085+00		
Pic 1 Desc. Temporary vegetative stabilization and waterbar in acceptable conditions			Pic 2 Desc. Sump pit in acceptable condition		
GPS Location 0			GPS Location 0		
Field Station# 14123+00			Field Station# 14110+00		
Pic 3 Desc. Temporary vegetative stabilization and perimeter CFS in acceptable conditions			Pic 4 Desc. Waterbar in acceptable condition		
GPS Location 0			GPS Location 0		
Field Station# 14110+00			Field Station# 14107+00		
Pic 5 Desc. Waterbar end treatment in acceptable condition			Pic 6 Desc. P1 silt fence in acceptable condition		

A/E	124300139	Date/Time	3/9/2022 9:25 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14168+00	Field Station#	14160+00		
Pic 7 Desc.	Waterbar in acceptable condition	Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/9/2022 9:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35281
Inspector	John White			Date/Time	3/9/2022 12:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Wet	Temperature (°F)	44.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Contractor is working on repairs			
Housekeeping	Acceptable				
Equipment Bridge	Acceptable				
Plunge Pool	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/9/2022 12:03 PM	Report #	35281
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Checked rain gauges, Anderson Mill #2=.8", Mill Creek =.8", Transco =1.0". Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/9/2022 12:03 PM	Report #	
Pictures					
GPS Location		O		GPS Location	
Field Station#		15781+22		Field Station#	
Pic 1 Desc.		Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		Pic 2 Desc.	
GPS Location		O		GPS Location	
Field Station#		15797+00		Field Station#	
Pic 3 Desc.		Observing temporary stabilization and CFS checks.		Pic 4 Desc.	
GPS Location		O		GPS Location	
Field Station#		15845+00		Field Station#	
Pic 5 Desc.		Observing temporary stabilization, CWD pipe, outlet and ECD's		Pic 6 Desc.	
				Observing CFS that requires maintenance	

AFE	124300139	Date/Time	3/9/2022 12:03 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15860+00	Field Station#	15930+00		
Pic 7 Desc.	Observing temporary stabilization,water bar and CFS checks	Pic 8 Desc.	Observing temporary stabilization		
GPS Location	O	GPS Location	O		
Field Station#	15936+00	Field Station#	15941+97		
Pic 9 Desc.	Observing temporary stabilization, sump and end treatment	Pic 10 Desc.	Observing CFS that requires maintenance		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/9/2022 12:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35274
Inspector	Charles Head			Date/Time	3/9/2022 10:56 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Wet	Temperature (°F)	43.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	1.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Repair/replace damaged/weathered			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/9/2022 10:56 AM	Report #	35274
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/9/2022 10:56 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14646+00	Field Station#	14676+00		
Pic 1 Desc.	Approximately 14646+00. Overview of ROW. Permanent vegetation.	Pic 2 Desc.	Approximately 14576+00. Overview of ROW.		
GPS Location	0	GPS Location	0		
Field Station#	14603+00	Field Station#	14568+10		
Pic 3 Desc.	Approximately 14603+00. Overview of ROW.	Pic 4 Desc.	Approximately 14568+10. Overview of stream crossing, equipment bridge and ECDs at stream S-E18.		
GPS Location	0	GPS Location	0		
Field Station#	14599+50	Field Station#	14599+10		
Pic 5 Desc.	Approximately 14599+50. Overview of road crossing and RCEs.	Pic 6 Desc.	Approximately 14599+10. CFS requires maintenance.		

A/E	124300139	Date/Time	3/9/2022 10:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/9/2022 10:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35287
Inspector	Ben Farmer			Date/Time	3/9/2022 2:54 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Wet	Temperature (°F)	40.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Other - Explain in Comments	Communication	Tree has fallen across CFS and nee		





5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300139	Date/Time	3/9/2022 2:54 PM	Report #	35287
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 40F) Rain Gauge= 0.8" 15370+62-15480+67 -EI began inspection at Toshes Rd. -RCEs are in good condition at all road crossings. -3rd party rock outlet appears to be in good condition along drainage feature at 15475+00. -No evidence of sedimentation from 3rd party rock outlet at 15465+00. -CWD is in good condition at 15460+81. No evidence of sedimentation from 3rd party rock outlet into CWD inlet. -Drainage ECDs are in good condition at 15457+00 with no evidence of sedimentation from 3rd party disturbance. -CWD is in good condition at 15453+00 with no evidence of sedimentation from 3rd party disturbance. -P1 is in good condition at all stream and wetland buffers. -Perimeter CFS is in good condition. -Stream and wetland buffers remain well vegetated. -Stream S-G4 (15426+40) was turbid entering ROW during inspection. This is a result of upstream disturbance and not from MVP ROW. -Equipment bridge ECDs are in place and in good condition. -Waterbars are functioning as intended throughout this section. -Tree has fallen across perimeter CFS due to high wind conditions and needs to be removed at 15380+00. -Drainage ECDs are in place and functioning at 15375+00. -Vegetation continues to fill in throughout this section of ROW					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/9/2022 2:54 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15480+67		Field Station#	15475+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings.		Pic 2 Desc.	3rd party rock outlet appears to be in good condition along drainage feature.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15465+00		Field Station#	15460+81	
Pic 3 Desc.	No evidence of sedimentation from 3rd party disturbance.		Pic 4 Desc.	No evidence of sedimentation from 3rd party disturbance into CWD inlet.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15460+81		Field Station#	15457+00	
Pic 5 Desc.	CWD is functioning as intended		Pic 6 Desc.	No evidence of sedimentation into drainage feature.	

AFE	124300139	Date/Time	3/9/2022 2:54 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15453+00		Field Station#	15447+60	
Pic 7 Desc.	CWD is in good condition		Pic 8 Desc.	P1 is in good condition at all stream and wetland buffers.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15445+00		Field Station#	15440+00	
Pic 9 Desc.	CFS is in good condition		Pic 10 Desc.	Vegetation continues to fill in throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15427+00		Field Station#	15426+40	
Pic 11 Desc.	Resource buffers remain well vegetated		Pic 12 Desc.	S-G4 is turbid entering ROW. This is a result of upstream disturbance not related to MVP ROW.	

AFE 124300139		Date/Time 3/9/2022 2:54 PM		Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15384+74	Field Station#	15381+00		
Pic 13 Desc.	Equipment bridge ECDs are in place and functioning	Pic 14 Desc.	Waterbars are functioning as intended		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15380+00	Field Station#	15375+00		
Pic 15 Desc.	Tree has fallen across CFS due to high wind conditions and needs to be removed.	Pic 16 Desc.	Drainage ECDs are in good condition and functioning.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	35382	
Inspector	Frank Craycroft			Date/Time	3/10/2022 5:35 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Wet	Temperature (°F)	50.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	3/10/2022 5:35 PM	Report #	35382
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All stormwater drain inlets had proper perimeter protection and were free of debris and vegetation. All trash and waste materials were maintained within bulk dumpsters on-site which had adequate additional storage. All perimeter ECDs were functional and in good condition. Entrances to sites were free of mud and dirt buildup. No issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/10/2022 5:35 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-032 Rock construction entrance	Pic 2 Desc.	LY-032 Secondary containment		
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-033 Rock construction entrance	Pic 4 Desc.	LY-033 Stormwater drain inlet protection		
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	ANC-006 Stormwater drain inlet protection	Pic 6 Desc.	ANC-006 Southeast perimeter CFS		

AFE	124300139	Date/Time	3/10/2022 5:35 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-048 Temporary vegetation	Pic 8 Desc.	LY-048 West perimeter CFS		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/10/2022 5:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	35335	
Inspector	John White			Date/Time	3/10/2022 12:25 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Wet	Temperature (°F)	50.00	
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.30	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Other - Explain in Comments		Communication	Safety fence that is protecting Envir			
Housekeeping		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar End Treatment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	3/10/2022 12:25 PM	Report #	35335
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There was one issue identified and added to the punch list. The Contractor is working on repairing the identified issue. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/10/2022 12:25 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	14+00	Field Station#	22+00		
Pic 1 Desc.	Observing temporary stabilization, signage and buffer	Pic 2 Desc.	Observing temporary stabilization, signage and buffer		
GPS Location	O	GPS Location	O		
Field Station#	12+00	Field Station#	10+00		
Pic 3 Desc.	Observing sump and end treatment	Pic 4 Desc.	Observing temporary stabilization		
		Insert image here			
GPS Location	O	GPS Location			
Field Station#	2+00	Field Station#			
Pic 5 Desc.	Observing safety fence that requires maintenance	Pic 6 Desc.			

A/E	124300139	Date/Time	3/10/2022 12:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/10/2022 12:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35341
Inspector	John White			Date/Time	3/10/2022 12:53 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Wet	Temperature (°F)	50.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.30
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Contractor is working on repairs			
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Contractor is working on repairs			
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Contractor is working on repairs			
3rd Party Damages	Communication	Contractor is working on restabilizing			
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/10/2022 12:53 PM	Report #	35341
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section, there were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/10/2022 12:53 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15970+00	Field Station#	15977+35		
Pic 1 Desc.	Observing temporary stabilization	Pic 2 Desc.	Observing temporary stabilization,water bar,signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15987+31	Field Station#	15999+30		
Pic 3 Desc.	Observing temporary stabilization,water bar,signage, buffer , equipment crossing and ECD's	Pic 4 Desc.	Observing CfS and P1 that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	15999+16	Field Station#	15996+50		
Pic 5 Desc.	Observing P1 that requires maintenance	Pic 6 Desc.	Observing CFS that requires maintenance		

AFE	124300139	Date/Time	3/10/2022 12:53 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15997+50	Field Station#	15984+00		
Pic 7 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 8 Desc.	Observing location that requires additional stabilization (3rd party damage)		
					
GPS Location	O	GPS Location	O		
Field Station#	15796+00	Field Station#	15795+50		
Pic 9 Desc.	Observing SSF that requires maintenance	Pic 10 Desc.	Observing P1 that requires maintenance		
					
GPS Location	O	GPS Location	O		
Field Station#	15795+50	Field Station#	16016+36		
Pic 11 Desc.	Observing CFS that requires maintenance	Pic 12 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

A/E	124300139	Date/Time	3/10/2022 12:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35344
Inspector	Glenn Mike Renfro			Date/Time	3/10/2022 1:48 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00
State	VA	Inspection Area	Full	Station End	0000+00
County	Franklin	Ground	Wet	Temperature (°F)	50.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.05
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Housekeeping		Communication	Trash clean up at LY-045		
Rock Construction Entrance		Acceptable			
Other - Explain in Comments		Acceptable	Inlet protection for catch basins		
Secondary Containment		Acceptable	Liners need repair at LY-045		
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/10/2022 1:48 PM	Report #	35344
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations received 1.05" of rainfall since the last inspection and site conditions were wet at the time of inspection. - One housekeeping issue was observed at LY-045 trash has been blown from container by high winds. (See pic 7) - All perimeter ECD's were inspected and no issues were identified. - The inlet protection for the catch basins at LY-046 were found to be in good condition. - All secondary containment structures were inspected and two issues were observed at LY-045 liners need to be stapled down both have been blown loss by high winds. (See pics 5&6) - The RCE at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. -Any issues observed during today's inspection have be placed on the punch list and given to the contractor to address 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/10/2022 1:48 PM	Report #	
Pictures					
					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 1 Desc.	Perimeter ECD's on northwest corner of LY-046 in good condition.		Pic 2 Desc.	Perimeter ECD's and inlet protection for catch basin on southwest corner of LY-046 in good condition.	
					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 3 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.		Pic 4 Desc.	Equipment at LY-045 inspected and no leaks observed at the time of inspection.	
					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 5 Desc.	Perimeter ECD's on north end of LY-045 in good condition liner for secondary containment structure needs repair.		Pic 6 Desc.	Liner for secondary containment structure for generator near tent at LY-045 needs repair damaged by high winds.	







AFE	124300139	Date/Time	3/10/2022 1:48 PM	Report #	
Pictures					
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 7 Desc.	Housekeeping need near RCE at LY-045 trash blow from container by high winds.		Pic 8 Desc.	RCE at LY-045 in good condition	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 9 Desc.			Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	3/10/2022 1:48 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35345
Inspector	Ben Farmer			Date/Time	3/10/2022 2:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Partial	Station End	15584+23
County	Pittsylvania	Ground	Damp	Temperature (°F)	41.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	3/10/2022 2:28 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15490+00		Field Station#	15495+00	
Pic 1 Desc.	Perimeter CFS is in good condition		Pic 2 Desc.	Vegetation continues to fill in throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15496+70		Field Station#	15501+00	
Pic 3 Desc.	RCEs are in good condition at all road crossings.		Pic 4 Desc.	No evidence of sedimentation from 3rd party disturbance	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15507+50		Field Station#	15510+00	
Pic 5 Desc.	P1 is in good condition at all stream and wetland buffers		Pic 6 Desc.	3rd party ECDs appear to be in good condition	

AFE	124300139	Date/Time	3/10/2022 2:28 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15515+00		Field Station#	15521+00	
Pic 7 Desc.	CWDs are functioning as intended		Pic 8 Desc.	S-MM8 is turbid entering ROW. This is a result of upstream disturbance not related to MVP ROW.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15540+00		Field Station#	15542+20	
Pic 9 Desc.	Equipment bridge ECDs are in place and functioning		Pic 10 Desc.	S-CC5 is turbid entering ROW. This is a result of upstream disturbance not related to MVP ROW.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15570+00		Field Station#	15573+20	
Pic 11 Desc.	Waterbars remain in good condition		Pic 12 Desc.	Resource buffers remain well vegetated	







AFE	124300139	Date/Time	3/10/2022 2:28 PM	Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15575+00		Field Station#	15584+00	
Pic 13 Desc.	Slope drain is in good condition and functioning		Pic 14 Desc.	P1 is in good condition around road pipe outlet.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 15 Desc.			Pic 16 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 17 Desc.			Pic 18 Desc.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35327
Inspector	Logan Box			Date/Time	3/10/2022 4:39 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Wet	Temperature (°F)	48.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Silt Fence (Reinforce Filter Fence)	Communication				
Rock Construction Entrance	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/10/2022 4:39 PM	Report #	35327
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout inspections today the EI observed 2 areas where reinforced silt fence required maintenance , the EI Documented and added to the punch list to be repaired by the contractor.</p> <p>Other than the items listed there were no other environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/10/2022 4:39 PM	Report #	
Pictures					
					
GPS Location	00000	GPS Location	00000		
Field Station#	13837+08	Field Station#	13834+04		
Pic 1 Desc.	Reinforced silt fence requires maintenance, added to the punch list for repair. Wind damage.	Pic 2 Desc.	Stream observation photo facing downstream during routine inspection today, no environmental issues observed at the time of inspection.		
					
GPS Location	00000	GPS Location	00000		
Field Station#	13830+08	Field Station#	13834+04		
Pic 3 Desc.	Reinforced silt fence requires maintenance, added to the punch list for repair.	Pic 4 Desc.	Stream observation photo facing upstream during routine inspection today. No environmental issues observed at the time of inspection.		
					
GPS Location	00000	GPS Location	00000		
Field Station#	13836+50	Field Station#	13829+00		
Pic 5 Desc.	Vegetation observation photo showing good coverage. No environmental issues observed at the time of inspection.	Pic 6 Desc.	Row photo showing stabilization and equipment bridge in place over stream crossing, no environmental issues observed at the time of inspection today.		

A/E	124300139	Date/Time	3/10/2022 4:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/10/2022 4:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	35283	
Inspector	Ben Davenport				Date/Time	3/10/2022 9:45 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	15063+85	
State	VA	Inspection Area	Partial		Station End	15142+66	
County	Pittsylvania	Ground	Muddy		Temperature (°F)	48.00	
Municipality	Chatham	Weather	Cloudy		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)		Communication	Routine maintenance				
Compost Filter Sock		Acceptable					
Sump Pit		Acceptable					
Waterbar End Treatment		Acceptable					
Plunge Pool		Acceptable					
Temporary Diversion Berm		Acceptable					
Equipment Bridge		Acceptable					
Sensitive Resource Buffer		Acceptable					
Sensitive Resource Signage		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	3/10/2022 9:45 AM	Report #	35283
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Cloudy with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -Walked ROW looking for potential environmental issues or maintenance requirements -Landowner stripper topsoil from spoil pile; separate report filed -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed of stabilization and vegetation in section both permanent and temporary areas of ROW; no issues observed -Continue to monitor ROW for signs of erosion -1 item added to environmental punch list -No other issues observed at time of inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/10/2022 9:45 AM	Report #	
Pictures					
					
36°57'19" N 79°34'52" W 15°N COURSE -1° GPS 8850-8968 Museville Rd, Sandy Level, VA 24161, United States 03.10.2022 11:39:12 Accur +/-34.7 Ft ALT 914 Ft			36°57'16" N 79°34'52" W 187°S COURSE 139° GPS 8850-8968 Museville Rd, Sandy Level, VA 24161, United States 03.10.2022 11:56:54 Accur +/-275.4 Ft ALT 921 Ft		
GPS Location	1		GPS Location	2	
Field Station#	15115+00		Field Station#	15118+00	
Pic 1 Desc.	Routine maintenance. Seed and stabilize disturbed areas.		Pic 2 Desc.	Temporary diversion berm stabilized and vegetated.	
					
36°57'15" N 79°34'51" W 193°S COURSE 163° GPS 8850-8968 Museville Rd, Sandy Level, VA 24161, United States 03.10.2022 11:57:19 Accur +/-17.6 Ft ALT 901 Ft			36°57'8" N 79°34'50" W 214°SW COURSE -1° GPS Sandy Level, VA 24161, United States 03.10.2022 12:00:48 Accur +/-112.6 Ft ALT 895 Ft		
GPS Location	3		GPS Location	4	
Field Station#	15121+00		Field Station#	15126+40	
Pic 3 Desc.	Plunge pool performing intended function.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	
					
36°57'11" N 79°34'47" W 168°S COURSE 133° GPS Sandy Level, VA 24161, United States 03.10.2022 12:04:36 Accur +/-15.4 Ft ALT 906 Ft			36°57'11" N 79°34'47" W 183°S COURSE 161° GPS Sandy Level, VA 24161, United States 03.10.2022 12:04:49 Accur +/-15.4 Ft ALT 906 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15131+00		Field Station#	15137+00	
Pic 5 Desc.	Sump pit and CFS end treatment in good condition.		Pic 6 Desc.	Area seeded and stabilized where contractor recently dug anode beds.	

A/E	124300139	Date/Time	3/10/2022 9:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	3/10/2022 9:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35329
Inspector	Charles Head			Date/Time	3/10/2022 10:55 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Damp	Temperature (°F)	49.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/10/2022 10:55 AM	Report #	35329
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/10/2022 10:55 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14653+00	Field Station#	14675+00		
Pic 1 Desc.	Approximately 14653+00. Overview of ROW. Permanent vegetation.	Pic 2 Desc.	Approximately 14675+00. Overview of ROW. Livestock in area.		
					
GPS Location	0	GPS Location	0		
Field Station#	14673+10	Field Station#	14680+40		
Pic 3 Desc.	Approximately 14673+10. Overview of stream crossing, equipment bridge and ECDs at stream S-H37. Livestock in area.	Pic 4 Desc.	Approximately 14680+40. Overview of stream crossing, equipment bridge and ECDs at stream S-H36.		
					
GPS Location	0	GPS Location	0		
Field Station#	14691+00	Field Station#	14694+40		
Pic 5 Desc.	Approximately 14691+00. Overview of ROW.	Pic 6 Desc.	Approximately 14694+40. Overview of road crossing and RCE.		

A/E	124300139	Date/Time	3/10/2022 10:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/10/2022 10:55 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	35336		
Inspector	Justin Burch	Date/Time	3/10/2022 12:29 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Full	Station End	14311+57
County	Franklin	Ground	Wet	Temperature (°F)	51.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	1.25
			Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other - Explain in Comments		Communication			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Plunge Pool		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/10/2022 12:29 PM	Report #	35336
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). Two issues were submitted for the punch list consisting of two locations where electric fence was damaged by livestock. Inspected ECDs were observed as in compliance at the time of inspection. The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed two punch list items submitted by DEQ inspectors. Since the last SWPPP inspection the area has received two rain events with totals of 1.05" at Bonbrook Mill Road #1 and 1.25" at Farm View Road. The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14258+00 to 14277+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/10/2022 12:29 PM	Report #	
Pictures					
31°NE (T) 37°3'30"N, 79°50'14"W ±13ft ▲952ft  14205+00 03-10-2022, 11:53:52		318°NW (T) 37°3'33"N, 79°50'28"W ±298ft ▲983ft  14187+00 03-10-2022, 12:06:48			
GPS Location	0	GPS Location	0		
Field Station#	14205+00	Field Station#	14187+00		
Pic 1 Desc.	Electric fence at cattle pass damaged by livestock	Pic 2 Desc.	Electric fence damaged by livestock from 14186+00 to 14187+00		
188°S (T) 37°2'35"N, 79°48'37"W ±52ft ▲1065ft  14311+00 03-10-2022, 09:11:09		159°S (T) 37°2'57"N, 79°48'53"W ±26236ft ▲1027ft  14296+00 03-10-2022, 09:36:56			
GPS Location	0	GPS Location	0		
Field Station#	14311+00	Field Station#	14296+00		
Pic 3 Desc.	P1 silt fence in acceptable condition	Pic 4 Desc.	Temporary vegetative stabilization in acceptable condition		
163°S (T) 37°3'24"N, 79°49'43"W ±1456ft ▲887ft  14236+00 03-10-2022, 10:48:03		28°NE (T) 37°3'15"N, 79°49'40"W ±4416ft ▲912ft  14246+00 03-10-2022, 10:52:01			
GPS Location	0	GPS Location	0		
Field Station#	14236+00	Field Station#	14246+00		
Pic 5 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions	Pic 6 Desc.	Waterbar in acceptable condition		

A/E	124300139	Date/Time	3/10/2022 12:29 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14246+00	Field Station#	14185+00		
Pic 7 Desc.	Waterbar end treatment in acceptable condition	Pic 8 Desc.	Temporary vegetative stabilization and waterbar in acceptable conditions		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	3/10/2022 12:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	35340	
Inspector	John White			Date/Time	3/10/2022 12:45 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Wet	Temperature (°F)	50.00	
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.30	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sump Pit		Acceptable				
Waterbar End Treatment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	3/10/2022 12:45 PM	Report #	35340
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/10/2022 12:45 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	12+65		
Pic 1 Desc.	Observing temporary stabilization and access road	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	13+50	Field Station#	15+00		
Pic 3 Desc.	Observing temporary stabilization, water bar, sump, end treatment and ECD's	Pic 4 Desc.	Observing temporary stabilization and signage		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	3/10/2022 12:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		


A/E	124300139	Date/Time	3/10/2022 12:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35394
Inspector	Ben Farmer			Date/Time	3/11/2022 1:39 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Damp	Temperature (°F)	45.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/11/2022 1:39 PM	Report #	35394
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 45F) Rain Gauge= 0.0" 15142+66-15260+00 -EI began inspection at Rockcreek Rd. -RCE is in good condition at Rockcreek Rd. -Perimeter CFS/P1 is in good condition. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00 -P1 is in good condition at stream buffer. -Equipment bridge ECDs are in place and functioning. -Resource buffer remains well vegetated. -Slope drain is functioning as intended at 15170+00. -Waterbars are in good condition throughout this section. -Drainage feature ECDs are in good condition and functioning at 15195+00. -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/11/2022 1:39 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15142+66		Field Station#	15150+00	
Pic 1 Desc.	RCE is in good condition at Rockcreek Rd.		Pic 2 Desc.	Perimeter CFS is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15160+00		Field Station#	15165+57	
Pic 3 Desc.	Perimeter P1 is in good condition		Pic 4 Desc.	Rock filter inlet/outlet remains in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15167+00		Field Station#	15167+00	
Pic 5 Desc.	P1 is in good condition at stream buffer		Pic 6 Desc.	Equipment bridge ECDs are in place and functioning	

AFE	124300139	Date/Time	3/11/2022 1:39 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15168+49		Field Station#	15170+00	
Pic 7 Desc.	Resource buffer remains well vegetated		Pic 8 Desc.	Slope drain is functioning as intended	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15195+00	
Pic 9 Desc.	Waterbars are in good condition		Pic 10 Desc.	Drainage ECDs are in place and functioning	
		Insert image here			
GPS Location	See photo		GPS Location		
Field Station#	15230+00		Field Station#		
Pic 11 Desc.	Vegetation continues to fill in throughout this section.		Pic 12 Desc.		

A/E	124300139	Date/Time	3/11/2022 1:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35390
Inspector	John White			Date/Time	3/11/2022 10:33 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Damp	Temperature (°F)	47.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	1.10
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Contractor is working on repairs			
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/11/2022 10:33 AM	Report #	35390
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/11/2022 10:33 AM	Report #	
Pictures					
				GPS Location	O
Field Station#	15585+00	Field Station#	15594+00	GPS Location	O
Pic 1 Desc.	Observing temporary stabilization, sump and end treatment		Pic 2 Desc.	Observing temporary stabilization and water bars	
				GPS Location	O
Field Station#	15619+48	Field Station#	15620+00	GPS Location	O
Pic 3 Desc.	Observing road crossing and RCE's		Pic 4 Desc.	Observing CFS that requires maintenance	
				GPS Location	O
Field Station#	15624+00	Field Station#	15630+00	GPS Location	O
Pic 5 Desc.	Observing CFS that requires maintenance		Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's	

AFE	124300139	Date/Time	3/11/2022 10:33 AM	Report #	
Pictures					
		Insert image here			
GPS Location	O	GPS Location			
Field Station#	15636+45	Field Station#			
Pic 7 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			













A/E	124300139	Date/Time	3/11/2022 10:33 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35392
Inspector	Charles Head			Date/Time	3/11/2022 10:51 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Damp	Temperature (°F)	61.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to chain link			
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/11/2022 10:51 AM	Report #	35392
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	3/11/2022 10:51 AM	Report #	
Pictures					
 		 			
GPS Location	0	GPS Location	0		
Field Station#	14317+00	Field Station#	14333+60		
Pic 1 Desc.	Approximately 14317+00. Overview of ROW.		Pic 2 Desc.	Approximately 14333+60. Overview of road crossing and RCEs.	
 		 			
GPS Location	0	GPS Location	0		
Field Station#	14326+00	Field Station#	14416+00		
Pic 3 Desc.	Approximately 14326+00. Overview of ROW.		Pic 4 Desc.	Approximately 14416+00. Overview of ROW.	
 		 			
GPS Location	0	GPS Location	0		
Field Station#	14391+50	Field Station#	14394+00		
Pic 5 Desc.	Approximately 14391+50. Overview of stream crossing, equipment bridge and ECDs at stream S-A41.		Pic 6 Desc.	Approximately 14394+00. SSF requires maintenance.	

A/E	124300139	Date/Time	3/11/2022 10:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/11/2022 10:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35380
Inspector	Ben Davenport			Date/Time	3/11/2022 9:38 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Muddy	Temperature (°F)	57.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Routine maintenance			
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/11/2022 9:38 AM	Report #	35380
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Sunny with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 — 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; 1 issue identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -1 item added to environmental punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/11/2022 9:38 AM	Report #	
Pictures					
					
36°59'16" N 79°42'13" W 96°E COURSE 70° GPS 496 Holliday Ln, Union Hall, VA 24176, United States 03.11.2022 09:34:40 Accur +/-177.2 Ft ALT 917 Ft			36°59'17" N 79°42'26" W 4°N COURSE -1° GPS 496 Holliday Ln, Union Hall, VA 24176, United States 03.11.2022 09:30:52 Accur +/-15.4 Ft ALT 915 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14713+00	Field Station#	14700+75		
Pic 1 Desc.	Routine maintenance. Reattach geotextile fabric to SSF fencing.		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact; ROW stabilized and vegetated in temporary	
					
36°59'17" N 79°42'17" W 236°SW COURSE 174° GPS 496 Holliday Ln, Union Hall, VA 24176, United States 03.11.2022 09:28:00 Accur +/-46.3 Ft ALT 927 Ft			36°58'58" N 79°41'23" W 69°E COURSE -1° GPS Union Hall, VA 24176, United States 03.11.2022 09:52:26 Accur +/-92.7 Ft ALT 905 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14710+00	Field Station#	14761+00		
Pic 3 Desc.	Slope drain pipe and outlet sump in place and functional.		Pic 4 Desc.	Spoil piles in extra workspace stabilized and vegetated.	
					
36°58'57" N 79°41'15" W 23°N COURSE 97° GPS 701-1081 Indian Cave Rd, Union Hall, VA 24176, United States 03.11.2022 09:47:30 Accur +/-15.5 Ft ALT 911 Ft			36°58'56" N 79°41'15" W 172°S COURSE 120° GPS Sorry no results found 03.11.2022 09:47:46 Accur +/-15.4 Ft ALT 915 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14766+15	Field Station#	14768+00		
Pic 5 Desc.	Contractor replaced CFS triple stack in resource buffer per punch list item.		Pic 6 Desc.	Contractor replaced perimeter P1 silt fence per punch list item.	

A/E	124300139	Date/Time	3/11/2022 9:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/11/2022 9:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	35379
Inspector	Justin Burch			Date/Time	3/11/2022 8:22 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Wet	Temperature (°F)	64.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.05
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)		Communication			
Waterbar		Acceptable			
Sump Pit		Acceptable			
Slope Drain Pipe		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Compost Filter Sock		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	3/11/2022 8:22 AM	Report #	35379
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). Two issues were submitted for the punch list consisting of two locations where P1 silt fence required maintenance due to torn fabric and broken stakes. Other inspected ECDs were observed as in compliance at the time of inspection. The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed the items on the punch list. Since the last SWPPP inspection the area received two rain events with totals of 0.90" at Grassy Hill Road and 1.05" at Bonbrook Mill Road #1. The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13910+00 and from 13921+00 to 13940+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	3/11/2022 8:22 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13914+00	Field Station#	13914+00		
Pic 1 Desc.	P1 silt fence with broken stakes	Pic 2 Desc.	P1 silt fence with a hole in fabric and a broken stake		
					
GPS Location	0	GPS Location	0		
Field Station#	13956+00	Field Station#	13956+00		
Pic 3 Desc.	Waterbar in acceptable condition	Pic 4 Desc.	Sump pit and slope drain pipe in acceptable conditions		
					
GPS Location	0	GPS Location	0		
Field Station#	13932+00	Field Station#	13868+00		
Pic 5 Desc.	Permanent Vegetation stabilization and perimeter CFS in acceptable conditions	Pic 6 Desc.	Temporary vegetative stabilization and perimeter CFS in acceptable conditions		

A/E	124300139	Date/Time	3/11/2022 8:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	3/11/2022 8:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	35338
Inspector	John White			Date/Time	3/10/2022 12:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Wet	Temperature (°F)	50.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	1.30
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Contractor is working on repairs		
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter	Acceptable			
Sediment Basin	Acceptable			
Sediment Filter Log	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	3/10/2022 12:36 PM	Report #	35338
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300113	Date/Time	3/10/2022 12:36 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 1 Desc.	Observing RCE	Pic 2 Desc.	Observing CFS that requires maintenance		
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 3 Desc.	Observing CFS that requires maintenance	Pic 4 Desc.	Observing rock drain and CFS checks		
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 5 Desc.	Observing rock drain, erosion control blanket and CFS checks	Pic 6 Desc.	Observing temporary stabilization and sediment basin		

AFE	124300113	Date/Time	3/10/2022 12:36 PM	Report #	
Pictures					
		Insert image here			
GPS Location	O	GPS Location			
Field Station#	00+00	Field Station#			
Pic 7 Desc.	Observing storm water pond and ECD's	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300113	Date/Time	3/10/2022 12:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		