



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36425
Inspector	Eric Hanlon			Date/Time	4/11/2022 7:33 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11184+85
State	VA	Inspection Area	Full	Station End	11254+99
County	Giles	Ground	Muddy	Temperature (°F)	60.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Communication			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Housekeeping	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/11/2022 7:33 AM	Report #	36425
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Accompanied fellow EI Joe Sweeden on a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). Compliance issues noted: @11222+50 to 11206+27 needs to be over seeded. Observance: Perimeter controls in place & functioning as designed Permanent & temporary stabilization in place. - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. - Temporary stabilization near 11222+50 to near 11253+50. This section of row has been stabilized for the winter months. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. AR-249.02 & 244 RCE's are maintained in acceptable condition. Some subsidence on both sides of winding way also monitoring it. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/11/2022 7:33 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11184+79	Field Station#	11191+47		
Pic 1 Desc.	AR 249.02 in good condition Rock check dams in place	Pic 2 Desc.	Clean water drainage feature in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11194+57	Field Station#	11253+00		
Pic 3 Desc.	Permanent water bars and level spreader in place	Pic 4 Desc.	Water bars in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11250+00	Field Station#	11246+00		
Pic 5 Desc.	Erosion control blanket in place	Pic 6 Desc.	ET in place		

AFE	124300137	Date/Time	4/11/2022 7:33 AM	Report #	
Pictures					
 <p><small>Date & Time: Mon, Apr 11, 2022 09:16:41 EDT Position: -937.384008 / -930.506492 / 619.111 Altitude: 1870ft (z:11.76) Datum: WGS 84 Azimuth/Bearing: 187 / S13E 2989mils from z:12 Deviation/Angle: 0.7 Horizontal Angle: 02.3 Zoom: 1.0x 11215+00</small></p>		 <p><small>Date & Time: Mon, Apr 11, 2022 09:16:41 EDT Position: -937.384008 / -930.506492 / 619.111 Altitude: 1870ft (z:11.76) Datum: WGS 84 Azimuth/Bearing: 187 / S13E 2989mils from z:12 Deviation/Angle: 0.7 Horizontal Angle: 02.3 Zoom: 1.0x 11215+00</small></p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11206+27	Field Station#	11215+00		
Pic 7 Desc.	Permanent stabilization needs over seeding	Pic 8 Desc.	Permanent stabilization needs over seeding		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/11/2022 7:33 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36448
Inspector	Daniel Fortune			Date/Time	4/11/2022 2:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11098+47
County	Giles	Ground	Damp	Temperature (°F)	51.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Added to punch list		
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock-lined Channel	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/11/2022 2:25 PM	Report #	36448
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. Fellow EI David Schoolcraft has assisted in the inspection today. Minor Deficiencies observed for repairs today. Sediment build up on perimeter CFS near 11097+34. This has been added to the punch list.</p> <p>"Station numbers are approximate".</p> <p>Observed Activity: Environmental Crew (1702) making repairs to the ditch line settling between 11048+00 to 11043+66.</p> <p>ROW CONDITIONS: Remain damp and wet in some areas.</p> <p>The ROW in that area received 0.00" of precipitation in the last 24 hrs.</p> <p>The ROW from AR 244 near 11025+02 to near 11070+21 has been temporarily stabilized. No erosion issues.</p> <p>The ROW from station 11070+21 to near 11098+00 has had final Restoration completed. There are 12" CFS that are being used as water bars at this time. There are no erosion issues visible in the final restored areas. The perimeter controls appear to be functional at this time.</p> <p>One area of open ditch (approximately 270') near 11061+00. Rock Road approaches were cleaned and functioning as intended. No sensitive resources have been impacted.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 4/11/2022 2:25 PM		Report #			
Pictures							
							
GPS Location		See Photo		GPS Location		See Photo	
Field Station#		11097+34		Field Station#		11098+50	
Pic 1 Desc.		Perimeter CFS requiring maintenance. This has been added to the punch list.		Pic 2 Desc.		Slight new vegetation emerging in the final restoration area.	
							
GPS Location		See Photo		GPS Location		See Photo	
Field Station#		11092+00		Field Station#		11092+30	
Pic 3 Desc.		Sparse area of vegetation in the permanent restored area. The vegetation appears to be re-emerging at this time.		Pic 4 Desc.		Final Restoration Area	
							
GPS Location		See Photo		GPS Location		See Photo	
Field Station#		11085+00		Field Station#		11061+00	
Pic 5 Desc.		Final Restoration Area		Pic 6 Desc.		Open ditch line, and temporary row stabilization.	

AFE	124300137	Date/Time	4/11/2022 2:25 PM	Report #	
Pictures					
<small> Date & Time: Mon, Apr 11, 2022, 09:42:40 EDT Position: +037 315283 / -080 543044 (+20 6ft) Altitude: 2155ft (+26 2ft) Datum: WGS-84 Azimuth/Bearing: 227° S47W 4036mils True (+12°) Elevation Grade: +01° Horizon Grade: +00° Zoom: 0.5X 11068+00 </small> 		<small> Date & Time: Mon, Apr 11, 2022, 09:44:51 EDT Position: +037 315333 / -080 542688 (+19 3ft) Altitude: 2161ft (+25 2ft) Datum: WGS-84 Azimuth/Bearing: 161° N46E 1071mils True (+12°) Elevation Grade: +02° Horizon Grade: +00° Zoom: 0.5X 11069+00 </small> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11068+00		Field Station#	11069+00	
Pic 7 Desc.	Temporary water bar condition. Adequate stabilization.		Pic 8 Desc.	Sump pit, water bar end treatment, and P1 silt fencing conditions	
<small> Date & Time: Mon, Apr 11, 2022, 09:44:43 EDT Position: +037 311006 / -080 542910 (+21 4ft) Altitude: 2100ft (+19 3ft) Datum: WGS-84 Azimuth/Bearing: 142° S00E 3084mils True (+12°) Elevation Grade: +00° Horizon Grade: +00° Zoom: 0.5X 11069+00 </small> 		<small> Date & Time: Mon, Apr 11, 2022, 10:02:07 EDT Position: +037 322617 / -080 552227 (+28 6ft) Altitude: 2410ft (+26 2ft) Datum: WGS-84 Azimuth/Bearing: 284° N76W 5049mils True (+12°) Elevation Grade: +00° Horizon Grade: +00° Zoom: 0.5X 11025+50 S-1J18 </small> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11069+00		Field Station#	11025+50	
Pic 9 Desc.	Temporary stabilization of row		Pic 10 Desc.	Equipment bridge condition	
<small> Date & Time: Mon, Apr 11, 2022, 10:17:07 EDT Position: +037 318474 / -080 549540 (+22 9ft) Altitude: 2334ft (+26 2ft) Datum: WGS-84 Azimuth/Bearing: 102° S70E 1181mils True (+12°) Elevation Grade: +02° Horizon Grade: +00° Zoom: 0.5X 11049+00 </small> 		<small> Date & Time: Mon, Apr 11, 2022, 10:20:52 EDT Position: +037 318596 / -080 549548 (+16 6ft) Altitude: 2321ft (+16 6ft) Datum: WGS-84 Azimuth/Bearing: 061° N61E 1108mils True (+12°) Elevation Grade: +07° Horizon Grade: +01° Zoom: 0.5X 11043+66 </small> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11049+00		Field Station#	11043+66	
Pic 11 Desc.	Ditch line settling repair and temporary water bar replacement to 2-5%.		Pic 12 Desc.	Additional Curlex added between water bars to help prevent rilling.	

A/E	124300137	Date/Time	4/11/2022 2:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36437
Inspector	Clint Sears			Date/Time	4/11/2022 11:22 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10929+80
State	VA	Inspection Area	Partial	Station End	11023+80
County	Giles	Ground	Damp	Temperature (°F)	66.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Vegetative Stabilization (Temporary)	Communication	See punch list		
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/11/2022 11:22 AM	Report #	36437
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Performed SWPPP inspection from MP 207 (10929+80) and MP 208.78 (11023+80). Accompanied by fellow EI Trey Ingram. Deficiencies found at the following station number. Sta#10991+00 Erosion above sump pit. All deficiencies were communicated to PPL personal via punch list. A portion of this section of RoW has been permanently restored. Assessed AR 242.01. AR 242.01 is partially completed, incomplete portions are stabilized. All perimeter controls, ECDs and BMPs functional at time of inspection less punch list items. Vegetation or stabilization sufficient less punch list item. Stream buffers and controls in place at the time of inspection. No impact to sensitive resources observed. Row is damp and in stable condition. Karst ECD's are in acceptable condition. Section 6 - CFS waterbars (other).					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/11/2022 11:22 AM	Report #	
Pictures					
 <p>Date & Time: Mon, Apr 11, 2022, 10:00:01 EDT Position: +031.332927° / +080.655427° (+0000) Altitude: 2330ft (+63.9ft) Datum: WGS-84 Azimuth/Bearing: 305° N55W 5422mils True (±12°) Elevation Angle: -15.4° Horizon Angle: +01.3° Zoom: 1.0X 10937+00</p>		 <p>Date & Time: Mon, Apr 11, 2022, 10:00:01 EDT Position: +031.332927° / +080.655427° (+0000) Altitude: 2330ft (+63.9ft) Datum: WGS-84 Azimuth/Bearing: 140° E08E 3270mils True (±13°) Elevation Angle: -13.8° Horizon Angle: +01.6° Zoom: 1.0X 10957+75</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10937+00	Field Station#	10957+75		
Pic 1 Desc.	Section of Row showing conditions and controls	Pic 2 Desc.	Punch list item from 4/5/2022 has been addressed		
 <p>Date & Time: Mon, Apr 11, 2022, 09:46:00 EDT Position: +031.327606° / +080.655001° (+0000) Altitude: 2297ft (+63.9ft) Datum: WGS-84 Azimuth/Bearing: 084° N08E 1470mils True (±12°) Elevation Angle: +02.2° Horizon Angle: +02.5° Zoom: 1.0X 10965+50</p>		 <p>Date & Time: Mon, Apr 11, 2022, 09:46:00 EDT Position: +031.327606° / +080.655001° (+0000) Altitude: 2297ft (+63.9ft) Datum: WGS-84 Azimuth/Bearing: 110° S70E 1936mils True (±13°) Elevation Angle: -09.1° Horizon Angle: -01.0° Zoom: 1.0X 10976+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10965+50	Field Station#	10976+00		
Pic 3 Desc.	Section of Row showing conditions and controls	Pic 4 Desc.	Section of Row showing conditions and controls		
 <p>Date & Time: Mon, Apr 11, 2022, 09:47:24 EDT Position: +031.333000° / +080.655600° (+0000) Altitude: 2374ft (+63.9ft) Datum: WGS-84 Azimuth/Bearing: 030° N03E 0333mils True (±12°) Elevation Angle: -03.9° Horizon Angle: +00.3° Zoom: 1.0X 10985+48 S-E24</p>		 <p>Date & Time: Mon, Apr 11, 2022, 09:47:24 EDT Position: +031.333000° / +080.655600° (+0000) Altitude: 2374ft (+63.9ft) Datum: WGS-84 Azimuth/Bearing: 062° N02E 1102mils True (±12°) Elevation Angle: -01.1° Horizon Angle: +03.3° Zoom: 1.0X 10987+50 S-E25</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10985+48	Field Station#	10987+50		
Pic 5 Desc.	S-E24	Pic 6 Desc.	S-E25		

AFE	124300137	Date/Time	4/11/2022 11:22 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10991+00	Field Station#	10991+20		
Pic 7 Desc.	Erosion above sump pit that was added to the punch list	Pic 8 Desc.	Section of Row showing conditions and controls		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11003+60	Field Station#	11015+58		
Pic 9 Desc.	Section of Row showing conditions and controls	Pic 10 Desc.	S-RR5		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11020+40	Field Station#	10930+40		
Pic 11 Desc.	Section of Row showing conditions and controls	Pic 12 Desc.	RCE at Doe Creek is maintained in acceptable condition		

A/E	124300137	Date/Time	4/11/2022 11:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36450
Inspector	Patrick Shields			Date/Time	4/11/2022 3:55 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11098+47
State	VA	Inspection Area	Full	Station End	11184+85
County	Giles	Ground	Damp	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/11/2022 3:55 PM	Report #	36450
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11098+47 (AR-245.02) to ST# 11184+85 (AR-249.02) MP 210.2 to MP 211.83. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. ST# 11445+50 to ST# 11170+00 has undergone temporary stabilization. Cleanwater diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Final restoration has occurred between ST# 11098+47 and ST# 11145+50 and between ST# 11170+00 and ST# 11184+85. CFS perimeter controls, end treatments and temporary waterbars are in place. Daylight drains with outlet protection and Permanent waterbars (section 6-other) with level spreaders are in place. AR-245.02, 249, 249.03, 249.01 and 249.02 RCEs are maintained in acceptable condition. The ROW is damp and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/11/2022 3:55 PM	Report #	
Pictures					
<p>Date & Time: Mon, Apr 11, 2022, 08:38:01 EDT Position: +037.311037° / +080.526507° (+47.91%) Altitude: 21070 (+100.00) Datum: WGS-84 Azimuth/Bearing: 000° (000mils True (+12°)) Elevation Grade: +000 Horizon Grade: +000 Zoom: 1.0x 11107+00</p> 		<p>Date & Time: Mon, Apr 11, 2022, 08:45:10 EDT Position: +037.311037° / +080.526511° (+47.91%) Altitude: 21070 (+100.00) Datum: WGS-84 Azimuth/Bearing: 000° (000mils True (+12°)) Elevation Grade: +000 Horizon Grade: +000 Zoom: 1.0x 11112+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11107+00	Field Station#	11112+00		
Pic 1 Desc.	CFS end treatments in place	Pic 2 Desc.	Triple stack CFS perimeter control in place		
<p>Date & Time: Mon, Apr 11, 2022, 09:53:04 EDT Position: +037.315629° / +080.526620° (+47.91%) Altitude: 19980 (+78.78) Datum: WGS-84 Azimuth/Bearing: 270° (000mils True (+12°)) Elevation Grade: +010 Horizon Grade: +000 Zoom: 1.0x 11120+00</p> 		<p>Date & Time: Mon, Apr 11, 2022, 09:59:44 EDT Position: +037.315631° / +080.526113° (+47.91%) Altitude: 21370 (+100.00) Datum: WGS-84 Azimuth/Bearing: 000° (000mils True (+12°)) Elevation Grade: +000 Horizon Grade: +000 Zoom: 1.0x 11141+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11120+00	Field Station#	11141+00		
Pic 3 Desc.	Temporary CFS waterbars in place	Pic 4 Desc.	Permanent vegetation present		
<p>Date & Time: Mon, Apr 11, 2022, 09:14:30 EDT Position: +037.315624° / +080.517839° (+47.91%) Altitude: 20630 (+26.21) Datum: WGS-84 Azimuth/Bearing: 142° (S19E 2880mils True (+12°)) Elevation Grade: +040 Horizon Grade: +000 Zoom: 1.0x 11146+00</p> 		<p>Date & Time: Mon, Apr 11, 2022, 09:14:30 EDT Position: +037.315624° / +080.517839° (+47.91%) Altitude: 20630 (+26.21) Datum: WGS-84 Azimuth/Bearing: 142° (S19E 2880mils True (+12°)) Elevation Grade: +040 Horizon Grade: +000 Zoom: 1.0x 11148+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11146+40	Field Station#	11148+00		
Pic 5 Desc.	Cleanwater diversion berm in place	Pic 6 Desc.	Supersilt fence perimeter control in place		

AFE		Date/Time	Report #
124300137		4/11/2022 3:55 PM	
Pictures			
<p>Date & Time: Mon, Apr 11, 2022, 09:19:21 EDT Position: +437.312492° / -480.518299° (s31.18) Altitude: 3020ft (s30.49) Datum: WGS-84 Azimuth/Bearing: 161° S29L 2494mils True (s12°) Elevation Grade: -033° Horizon Grade: +005° Zoom: 1.0X 11152+50</p> 		<p>Date & Time: Mon, Apr 11, 2022, 09:20:44 EDT Position: +437.511515° / -480.514559° (s49.88) Altitude: 1918ft (s49.88) Datum: WGS-84 Azimuth/Bearing: 111° S49E 1973mils True (s12°) Elevation Grade: -003° Horizon Grade: +003° Zoom: 1.0X 11163+00</p> 	
GPS Location	See photo	GPS Location	See photo
Field Station#	11152+50	Field Station#	11163+00
Pic 7 Desc.	Waterbars in place	Pic 8 Desc.	P1 silt fence perimeter control in place
<p>Date & Time: Mon, Apr 11, 2022, 09:31:48 EDT Position: +437.211888° / -480.514297° (s49.79) Altitude: 1000ft (s49.49) Datum: WGS-84 Azimuth/Bearing: 406° S28W 4571mils True (s12°) Elevation Grade: -47.6X Horizon Grade: +001X Zoom: 1.0X 11165+50</p> 		<p>Date & Time: Mon, Apr 11, 2022, 09:32:26 EDT Position: +437.211888° / -480.514297° (s49.79) Altitude: 1000ft (s49.49) Datum: WGS-84 Azimuth/Bearing: 304° S33W 4602mils True (s12°) Elevation Grade: +001X Horizon Grade: +002X Zoom: 1.0X 11166+00</p> 	
GPS Location	See photo	GPS Location	See photo
Field Station#	11167+50	Field Station#	11168+00
Pic 9 Desc.	Cleanwater diversion outlet protection in place	Pic 10 Desc.	RCE in place
<p>Date & Time: Mon, Apr 11, 2022, 09:34:45 EDT Position: +437.208846° / -480.513981° (s51.41) Altitude: 1907ft (s51.10) Datum: WGS-84 Azimuth/Bearing: 168° S35W 4711mils True (s12°) Elevation Grade: -022° Horizon Grade: -009° Zoom: 1.0X 11177+00</p> 		<p>Date & Time: Mon, Apr 11, 2022, 09:41:24 EDT Position: +437.349428° / -480.511773° (s37.41) Altitude: 1948ft (s37.41) Datum: WGS-84 Azimuth/Bearing: 144° S44E 173mils True (s12°) Elevation Grade: -003° Horizon Grade: +003° Zoom: 1.0X 11184+15</p> 	
GPS Location	See photo	GPS Location	See photo
Field Station#	11177+00	Field Station#	11184+15
Pic 11 Desc.	Permanent waterbar with Level spreader in place	Pic 12 Desc.	Daylight drain in place

A/E	124300137	Date/Time	4/11/2022 3:55 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36498
Inspector	Patrick Shields			Date/Time	4/12/2022 3:00 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+67
State	VA	Inspection Area	Full	Station End	11471+56
County	Giles	Ground	Damp	Temperature (°F)	69.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/12/2022 3:00 PM	Report #	36498
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed VA SWPPP inspection from ST# 11353+67 (Old Furnace) to ST# 11471+56 (Steele Acres) MP 215.04 to MP 217.26 Accompanied on inspection by fellow EI Jared Saunders. No compliance issues found. Observed environmental maintenance crew patching holes in CFS at ST# 11459+00. ST# 11353+67 to ST# 11367+00 and ST# 11443+50 to ST# 11471+56 have undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Triple protection ECDs are in place at karst feature. Final restoration has occurred between ST# 11367+00 and ST# 11443+50. CFS perimeter controls, end treatments and temporary waterbars are in place. Permanent waterbars(section 6-other) with level spreaders are in place. Sensitive resource buffers are in place at stream crossings S-KL43, S-0014, S-0013, S-0012, and S-CD14. AR-256 and 258.01 RCEs are maintained in acceptable condition. The ROW is damp and in stable condition. No sensitive resources have been impacted.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/12/2022 3:00 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11353+75	Field Station#	11362+00		
Pic 1 Desc.	RCE in place	Pic 2 Desc.	Erosion control blanket in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11363+00	Field Station#	11397+00		
Pic 3 Desc.	End treatments in place	Pic 4 Desc.	Level spreader in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11411+00	Field Station#	11433+00		
Pic 5 Desc.	Temporary CFS waterbars	Pic 6 Desc.	Permanent waterbar in place		

AFE	124300137	Date/Time	4/12/2022 3:00 PM	Report #	
Pictures					
<p>Date & Time: Tue, Apr 12, 2022, 09:36:34 EDT Position: +337.326259° / -920.449397° (s=774.50) Altitude: 2026ft (s=89.00) Datum: WGS-84 Azimuth/Bearing: 300° N30E 9222mN True (s=12°) Elevation Grade: +01% Horizon Grade: +011% Zoom: 1.0X 11437+00</p> 		<p>Date & Time: Tue, Apr 12, 2022, 09:36:34 EDT Position: +337.318480° / -920.443071° (s=11.40) Altitude: 2120ft (s=9.00) Datum: WGS-84 Azimuth/Bearing: 105° S30E 9222mN True (s=12°) Elevation Grade: +02% Horizon Grade: +002% Zoom: 1.0X 11448+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11437+00	Field Station#	11448+00		
Pic 7 Desc.	Permanent vegetation present	Pic 8 Desc.	Cleanwater diversion berm in place		
<p>Date & Time: Tue, Apr 12, 2022, 09:38:00 EDT Position: +337.324780° / -920.440437° (s=11.40) Altitude: 2140ft (s=9.00) Datum: WGS-84 Azimuth/Bearing: 201° S21W 4449mN True (s=12°) Elevation Grade: +02% Horizon Grade: +00% Zoom: 1.0X 11452+00</p> 		<p>Date & Time: Tue, Apr 12, 2022, 09:38:14 EDT Position: +337.318480° / -920.443071° (s=11.40) Altitude: 2120ft (s=9.00) Datum: WGS-84 Azimuth/Bearing: 258° S78W 4289mN True (s=12°) Elevation Grade: +03% Horizon Grade: +004% Zoom: 1.0X 11461+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11452+66	Field Station#	11461+00		
Pic 9 Desc.	Stream buffer in place	Pic 10 Desc.	CFS perimeter control in place		
<p>Date & Time: Tue, Apr 12, 2022, 09:28:36 EDT Position: +337.320265° / -920.436775° (s=15.10) Altitude: 2251ft (s=17.00) Datum: WGS-84 Azimuth/Bearing: 279° N89W 4899mN True (s=12°) Elevation Grade: +6% Horizon Grade: +000% Zoom: 1.0X 11466+00</p> 		<p>Date & Time: Tue, Apr 12, 2022, 09:28:51 EDT Position: +337.320265° / -920.436775° (s=15.10) Altitude: 2251ft (s=17.00) Datum: WGS-84 Azimuth/Bearing: 279° N89W 4899mN True (s=12°) Elevation Grade: +6% Horizon Grade: +00% Zoom: 1.0X 11469+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11466+00	Field Station#	11469+00		
Pic 11 Desc.	Plunge pool in place	Pic 12 Desc.	Triple protection ECDs in place at karst feature		

A/E	124300137	Date/Time	4/12/2022 3:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36475
Inspector	Eric Hanlon			Date/Time	4/12/2022 7:50 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Full	Station End	11600+01
County	Giles	Ground	Wet	Temperature (°F)	58.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/12/2022 7:50 AM	Report #	36475
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to 219.70)</p> <p>No Compliance issues noted:</p> <p>The ROW from 258.02 to the JNF Forest has been fully restored. Permanent waterbars(other) and level spreaders are installed as per the approved plan and are functioning as designed. No maintenance is needed; Vegetation growth is currently acceptable. The Forest has been temporarily stabilized.</p> <p>Observed:</p> <p>The aged P1 on the JNF from the top of the Mtn down to Craig Creek road has been replaced.</p> <p>The restored area is in good shape and the vegetation is sufficient. The environmental controls in the forest are aged, but functional.</p> <p>The ECDs at WBs, S-PP 20,21,22 are new and in good shape.</p> <p>No construction being performed in the area.</p> <p>RCE's functional, highway at Craig Creek station 11600+01, was clean and free of any loose rock.</p> <p>LOD ECDs were in place and functional.</p> <p>Water bars have been installed to specifications.</p> <p>The ROW is wet but in stable condition.</p> <p>No sensitive resources have been impacted</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/12/2022 7:50 AM	Report #	
Pictures					
GPS Location		See photo		GPS Location	
Field Station#		11537+00		Field Station#	
Pic 1 Desc.		Picture showing condition of row Over seeding complete		Pic 2 Desc.	
GPS Location		See photo		GPS Location	
Field Station#		11580+00		Field Station#	
Pic 3 Desc.		Water bars in place		Pic 4 Desc.	
GPS Location		See photo		GPS Location	
Field Station#		11585+00		Field Station#	
Pic 5 Desc.		Equipment bridge functional		Pic 6 Desc.	

A/E	124300137	Date/Time	4/12/2022 7:50 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11591+00	Field Station#	11600+01		
Pic 7 Desc.	ET in place	Pic 8 Desc.	RCE & culvert functional		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/12/2022 7:50 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36481
Inspector	Clint Sears			Date/Time	4/12/2022 11:17 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11471+56
State	VA	Inspection Area	Partial	Station End	11524+16
County	Giles	Ground	Damp	Temperature (°F)	65.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Rock-lined Channel	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/12/2022 11:17 AM	Report #	36481
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Performed VA SWPPP inspection from MP 217.26 (11471+56) and MP 218.26 (11524+16). Fellow EI Trey Ingram accompanied during inspection. No deficiencies found at this time. This section of RoW has no current construction. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed AR 258.02 and Steele Acres. Karst ECD's are in place and in acceptable condition. Row is damp and in stable condition					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/12/2022 11:17 AM	Report #	
Pictures					
<p>Date & Time: Tue, Apr 12, 2022 10:00:50 EDT Position: +037 325606 / -080 433617 (x1672ft) Altitude: 2229ft (x32.6ft) Datum: WGS-84 Azimuth/Bearing: 222° S43W 33mils True (x141) Elevation Angle: -04.2° Horizon Angle: -02.2° Zoom: 1.0x 11519+00 S-PP4</p> 		<p>Date & Time: Tue, Apr 12, 2022 10:01:00 EDT Position: +037 325606 / -080 433617 (x1672ft) Altitude: 2229ft (x32.6ft) Datum: WGS-84 Azimuth/Bearing: 188° N88E 120mils True (x157) Elevation Angle: -01.1° Horizon Angle: -00.3° Zoom: 1.0x 11507+87</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11519+00	Field Station#	11507+87		
Pic 1 Desc.	Section of Row showing conditions and controls at S-PP4	Pic 2 Desc.	ECD's are in acceptable condition at S-PP3		
<p>Date & Time: Tue, Apr 12, 2022 10:01:45 EDT Position: +037 325606 / -080 433617 (x1672ft) Altitude: 2229ft (x32.6ft) Datum: WGS-84 Azimuth/Bearing: 008° N08E 0142mils True (x157) Elevation Angle: -12.5° Horizon Angle: -02.7° Zoom: 1.0x 11504+50</p> 		<p>Date & Time: Tue, Apr 12, 2022 10:01:41 EDT Position: +037 325606 / -080 431754 (x1443ft) Altitude: 2165ft (x31.9ft) Datum: WGS-84 Azimuth/Bearing: 059° N59E 103mils True (x157) Elevation Angle: -04.2° Horizon Angle: -00.2° Zoom: 1.0x 11490+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11504+50	Field Station#	11490+00		
Pic 3 Desc.	Rock lined channel and perimeter controls are in acceptable condition	Pic 4 Desc.	RCE at Stevers Gap is in acceptable condition		
<p>Date & Time: Tue, Apr 12, 2022 10:00:36 EDT Position: +037 325606 / -080 431659 (x1671ft) Altitude: 2156ft (x32.6ft) Datum: WGS-84 Azimuth/Bearing: 331° N29W 580mils True (x19) Elevation Angle: -13.0° Horizon Angle: -01.3° Zoom: 1.0x 11488+52</p> 		<p>Date & Time: Tue, Apr 12, 2022 09:59:50 EDT Position: +037 323104 / -080 439225 (x1653ft) Altitude: 2225ft (x32.6ft) Datum: WGS-84 Azimuth/Bearing: 092° S88E 100mils True (x19) Elevation Angle: -11.8° Horizon Angle: -01.7° Zoom: 1.0x 11479+65</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11488+52	Field Station#	11479+65		
Pic 5 Desc.	Section of Row showing conditions and controls	Pic 6 Desc.	Perimeter controls are in place and in acceptable condition		

A/E	124300137	Date/Time	4/12/2022 11:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/12/2022 11:17 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36482
Inspector	David Schoolcraft			Date/Time	4/12/2022 11:25 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Full	Station End	11353+67
County	Giles	Ground	Dry	Temperature (°F)	63.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sensitive Resource Buffer	Communication	See Comments / Punchlist		

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/12/2022 11:25 AM	Report #	36482
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Assisted fellow EI Daniel Fortune with SWPPP inspection from MP 213.6 (11254+99) and MP 215.04 (11353+67). Crews performing ROW and ECD maintenance as needed within this area. One area where fabric for Karst Protection Sump pit needs to be repaired 11351+00 (sensitive resource buffer) All perimeter controls, ECDs and BMPs functional at time of inspection. No sensitive resources have been impacted Vegetation or stabilization sufficient. Assessed AR 256.02.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/12/2022 11:25 AM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11257+50	Field Station#	11263+00		
Pic 1 Desc.	Waterbar and end treatment	Pic 2 Desc.	Stabilization		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11328+00	Field Station#	11282+00		
Pic 3 Desc.	S-NN12	Pic 4 Desc.	Sump pit and slope drain		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11286+00	Field Station#	11292+80		
Pic 5 Desc.	Erosion control blanket	Pic 6 Desc.	S-MM18		

AFE	124300137	Date/Time	4/12/2022 11:25 AM	Report #	
Pictures					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11297+20	Field Station#	11351+00		
Pic 7 Desc.	Waterbar	Pic 8 Desc.	Fabric on Karst Sump Pit needs repaired		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	See Photo	GPS Location			
Field Station#	11352+97	Field Station#			
Pic 9 Desc.	S-NN11	Pic 10 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/12/2022 11:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36533
Inspector	Rob Robertson			Date/Time	4/13/2022 11:06 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Dry	Temperature (°F)	55.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Repair torn SSF fabric	48 Hours	
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			



5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/13/2022 11:06 AM	Report #	36533
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<p>Completed a regular scheduled VADEQ SWPPP inspection on JNF and private property on Brush Mountain. The ROW surface on JNF land is stable with grasses emerging as soil temperatures continue to rise. Private tracts are stable with adequate mulch to prevent soil movement. ECDs are in place throughout this area. The contractor will be notified of need to repair/replace torn filter fabric on SSF at 11665+50. The repair is not urgent and 72 hours will be allowed for completion. Perimeter ECDs elsewhere are in acceptable condition. There is no sediment movement beyond LOD. Resource crossing buffers are stable. Slope breakers, sumps and end treatments are in acceptable condition. RCEs are in good condition. Access road MN-258.04 is in good condition. No evidence of vandalism or trespass discovered.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/13/2022 11:06 AM	Report #	
Pictures					
 <p>Date & Time: Wed, Apr 13, 2022, 08:37:07 EDT Position: +037.30241° / -080.395427° (±5.0m) Altitude: 813m (±16.0m) Datum: WGS-84 Azimuth/Bearing: 053° N53E 0942mils Magnetic (±12°) Elevation Angle: -36.9° Horizon Angle: -07.5° Zoom: 1.0X 11670+00</p>		 <p>Date & Time: Wed, Apr 13, 2022, 08:37:07 EDT Position: +037.30241° / -080.395427° (±5.0m) Altitude: 813m (±16.0m) Datum: WGS-84 Azimuth/Bearing: 053° N53E 0942mils Magnetic (±12°) Elevation Angle: -36.9° Horizon Angle: -07.5° Zoom: 1.0X 11665+50</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11670+00		Field Station#	11665+50	
Pic 1 Desc.	Top of Brush Mountain currently stable.		Pic 2 Desc.	COMMUNICATION, repair torn SSF fabric.	
 <p>Date & Time: Wed, Apr 13, 2022, 08:40:46 EDT Position: +037.30241° / -080.395427° (±5.0m) Altitude: 816m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 348° N12W 6187mils Magnetic (±12°) Elevation Angle: -22.5° Horizon Angle: -01.5° Zoom: 1.0X 11663+00</p>		 <p>Date & Time: Wed, Apr 13, 2022, 08:40:46 EDT Position: +037.30241° / -080.395427° (±5.0m) Altitude: 777m (±5.0m) Datum: WGS-84 Azimuth/Bearing: 149° S31E 3446mils Magnetic (±12°) Elevation Angle: -11.3° Horizon Angle: -08.0° Zoom: 1.0X 11660+00</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11663+00		Field Station#	11660+00	
Pic 3 Desc.	Slope breakers in place and functioning properly.		Pic 4 Desc.	Perimeter ECDs in good condition.	
 <p>Date & Time: Wed, Apr 13, 2022, 08:49:46 EDT Position: +037.30241° / -080.397127° (±5.0m) Altitude: 740m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 140° S46E 3407mils Magnetic (±12°) Elevation Angle: -04.3° Horizon Angle: -06.7° Zoom: 1.0X 11657+00</p>		 <p>Date & Time: Wed, Apr 13, 2022, 08:50:00 EDT Position: +037.30451° / -080.39701° (±5.0m) Altitude: 746m (±4.0m) Datum: WGS-84 Azimuth/Bearing: 336° N24W 3373mils Magnetic (±12°) Elevation Angle: -29.0° Horizon Angle: -00.1° Zoom: 1.0X 11656+00</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11657+00		Field Station#	11656+00	
Pic 5 Desc.	Perimeter ECDs in place, functional.		Pic 6 Desc.	CFS is worn on JNF and will be replaced before any ground disturbance occurs.	

AFE 124300137		Date/Time	4/13/2022 11:06 AM	Report #	
Pictures					
<p>Date & Time: Wed, Apr 13, 2022 09:11:29 EDT Position: +037.313129° / -080.397269° (±5.0m) Altitude: 629m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 168° S17E 3890mils Magnetic (±12°) Elevation Angle: -02.2° Horizon Angle: -02.2° Zoom: 1.0X 11634+00</p> 		<p>Date & Time: Wed, Apr 13, 2022 09:14:52 EDT Position: +037.313326° / -080.397450° (±10.0m) Altitude: 625m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 081° N81E 1440mils Magnetic (±12°) Elevation Angle: -20.9° Horizon Angle: +01.7° Zoom: 1.0X 11630+00</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11634+00	Field Station#	11630+00		
Pic 7 Desc.	ROW stable. Slope breakers controlling runoff.	Pic 8 Desc.	ECDs functional.		
<p>Date & Time: Wed, Apr 13, 2022 09:19:57 EDT Position: +037.313810° / -080.395578° (±5.0m) Altitude: 590m (±10.0m) Datum: WGS-84 Azimuth/Bearing: 238° S58W 4631mils Magnetic (±12°) Elevation Angle: -24.0° Horizon Angle: -00.8° Zoom: 1.0X 11626+50</p> 		<p>Date & Time: Wed, Apr 13, 2022 09:19:05 EDT Position: +037.313914° / -080.394449° (±5.0m) Altitude: 588m (±10.0m) Datum: WGS-84 Azimuth/Bearing: 293° N67W 5209mils Magnetic (±15°) Elevation Angle: -20.3° Horizon Angle: -00.5° Zoom: 1.0X S-HH18</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11626+50	Field Station#	11626+04		
Pic 9 Desc.	ECDs in place.	Pic 10 Desc.	Resource buffers stable at the S-HH18 crossing.		
<p>Date & Time: Wed, Apr 13, 2022 09:23:51 EDT Position: +037.314075° / -080.401431° (±10.0m) Altitude: 594m (±24.0m) Datum: WGS-84 Azimuth/Bearing: 264° S86W 4728mils Magnetic (±13°) Elevation Angle: -15.9° Horizon Angle: -05.5° Zoom: 1.0X 11618+00</p> 		<p>Date & Time: Wed, Apr 13, 2022 09:29:58 EDT Position: +037.313625° / -080.401930° (±30.0m) Altitude: 596m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 342° S42°W 6080mils Magnetic (±13°) Elevation Angle: -08.2° Horizon Angle: -00.8° Zoom: 1.0X 11614+75</p> 			
GPS Location	On photo	GPS Location	On		
Field Station#	11618+00	Field Station#	11614+75		
Pic 11 Desc.	ECDs functional.	Pic 12 Desc.	Perimeter ECDs in place.		

AFE	124300137	Date/Time	4/13/2022 11:06 AM	Report #	
Pictures					
<small>Date & Time: Wed, Apr 13, 2022, 05:49:38 EDT Position: +037.313659 / +080.404620 (±5.0m) Altitude: 588m (±12.0m) Datum: WGS-84 Azimuth/Bearing: 277° N83W 532mils Magnetic (±14°) Elevation Angle: -02.7° Horizon Angle: -00.7° Zoom: 1.0X 11614+20 S-RR14</small> 		<small>Date & Time: Wed, Apr 13, 2022, 05:49:38 EDT Position: +037.313659 / +080.404620 (±5.0m) Altitude: 572m (±6.0m) Datum: WGS-84 Azimuth/Bearing: 196° S16W 348mils Magnetic (±14°) Elevation Angle: -05.7° Horizon Angle: +01.0° Zoom: 1.0X S-006</small> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11614+20	Field Station#	11608+17		
Pic 13 Desc.	The S-RR14 crossing is stable.	Pic 14 Desc.	The S-006 crossing is currently stable.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36544
Inspector	Patrick Shields			Date/Time	4/13/2022 1:45 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Full	Station End	11788+52
County	Montgomery	Ground	Dry	Temperature (°F)	71.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/13/2022 1:45 PM	Report #	36544
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 (Brush Mt) to ST# 11788+52 (Mt Tabor) MP 221.02 to MP 223.27 Accompanied on inspection by fellow EI Jared Saunders. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection are in place where needed. Perimeter controls and waterbars with end treatments are in place. Sensitive resource buffers are in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCEs are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/13/2022 1:45 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11670+00	Field Station#	11672+50		
Pic 1 Desc.	P1 silt fence perimeter control in place	Pic 2 Desc.	End treatments in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11682+50	Field Station#	11688+00		
Pic 3 Desc.	Slope drain pipe in place	Pic 4 Desc.	Erosion control blanket in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11704+75	Field Station#	11714+00		
Pic 5 Desc.	Sediment filter logs in place	Pic 6 Desc.	Waterbars in place		

AFE	124300137	Date/Time	4/13/2022 1:45 PM	Report #	
Pictures					
 <p>Date & Time: Wed, Apr 13, 2022, 10:52:52 EDT Position: +037.296899° / -080.043700° (s22.29) Altitude: 2062ft (628.5m) Datum: WGS-84 Azimuth/Bearing: 231° S81W 4.07mils True (±12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11741+00</p>		 <p>Date & Time: Wed, Apr 13, 2022, 10:58:57 EDT Position: +037.296899° / -080.043700° (s22.29) Altitude: 2057ft (626.7m) Datum: WGS-84 Azimuth/Bearing: 176° N76E 1.51mils True (±12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11749+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11741+00	Field Station#	11749+00		
Pic 7 Desc.	Stream buffer in place	Pic 8 Desc.	End treatments in place		
 <p>Date & Time: Wed, Apr 13, 2022, 10:53:02 EDT Position: +037.296899° / -080.043700° (s22.29) Altitude: 2062ft (628.5m) Datum: WGS-84 Azimuth/Bearing: 121° S59E 2.15mils True (±12°) Elevation Grade: +04% Horizon Grade: +01% Zoom: 1.0X 11758+00</p>		 <p>Date & Time: Wed, Apr 13, 2022, 10:53:07 EDT Position: +037.296899° / -080.043700° (s22.29) Altitude: 2022ft (616.4m) Datum: WGS-84 Azimuth/Bearing: 089° N89E 1.582mils True (±12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 1.0X 11766+35</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11758+00	Field Station#	11766+35		
Pic 9 Desc.	Supersilt fence perimeter control in place	Pic 10 Desc.	RCE in place		
 <p>Date & Time: Wed, Apr 13, 2022, 10:53:07 EDT Position: +037.296899° / -080.043700° (s22.29) Altitude: 2114ft (643.5m) Datum: WGS-84 Azimuth/Bearing: 308° N75W 5.087mils True (±12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 1.0X 11782+50</p>		 <p>Date & Time: Wed, Apr 13, 2022, 10:53:07 EDT Position: +037.296899° / -080.043700° (s22.29) Altitude: 2057ft (626.7m) Datum: WGS-84 Azimuth/Bearing: 202° N42W 1.015mils True (±12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 1.0X 11785+45</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11782+50	Field Station#	11785+45		
Pic 11 Desc.	Cleanwater drainage feature in place	Pic 12 Desc.	CFS perimeter control in place		

A/E	124300137	Date/Time	4/13/2022 1:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36535
Inspector	David Schoolcraft			Date/Time	4/13/2022 11:50 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+89
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/13/2022 11:50 AM	Report #	36535
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Preformed VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). Accompanied by fellow EI Daniel Fortune. This section of RoW is partially restored with heavy vegetation. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Waterbars(others) No sensitive resources have been impacted Assessed AR 266.03 and AR266					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/13/2022 11:50 AM	Report #	
Pictures					
<p>Date & Time: Wed, Apr 13, 2022 09:18:50 EDT Position: +437.237122° / -80.334328° (±12.11) Altitude: 2163 ft (±1.21) Datum: WGS-84 Azimuth/Bearing: 140° 31'W 338mils True (±10°) Elevation Angle: +07.9° Horizon Angle: -02.5° Zoom: 0.5X 11905+00</p> 		<p>Date & Time: Wed, Apr 13, 2022 09:18:50 EDT Position: +437.237122° / -80.334328° (±12.11) Altitude: 2163 ft (±1.21) Datum: WGS-84 Azimuth/Bearing: 131° 31'W 338mils True (±10°) Elevation Angle: +07.5° Horizon Angle: -00.0° Zoom: 0.5X 11905+00</p> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11905+00		Field Station#	11906+00	
Pic 1 Desc.	Section of ROW showing conditions and controls		Pic 2 Desc.	Level Spreader	
<p>Date & Time: Wed, Apr 13, 2022 09:34:45 EDT Position: +437.237122° / -80.334328° (±12.11) Altitude: 2163 ft (±1.21) Datum: WGS-84 Azimuth/Bearing: 301° 28'W 338mils True (±10°) Elevation Angle: +03.3° Horizon Angle: -03.3° Zoom: 0.5X 11929+78</p> 		<p>Date & Time: Wed, Apr 13, 2022 09:34:45 EDT Position: +437.237122° / -80.334328° (±12.11) Altitude: 2163 ft (±1.21) Datum: WGS-84 Azimuth/Bearing: 131° 28'W 338mils True (±10°) Elevation Angle: -03.0° Horizon Angle: -00.0° Zoom: 1.0X 11945+00</p> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11929+78		Field Station#	11945+00	
Pic 3 Desc.	Access 266		Pic 4 Desc.	Waterbars	
<p>Date & Time: Wed, Apr 13, 2022 10:07:42 EDT Position: +437.237122° / -80.334328° (±12.11) Altitude: 1630 ft (±3.44) Datum: WGS-84 Azimuth/Bearing: 020° N03E 302mils True (±10°) Elevation Angle: +1.1° Horizon Angle: -02.2° Zoom: 0.5X 11979+86</p> 		<p>Date & Time: Wed, Apr 13, 2022 10:13:42 EDT Position: +437.237122° / -80.334328° (±12.11) Altitude: 1630 ft (±3.44) Datum: WGS-84 Azimuth/Bearing: 134° S04E 324mils True (±10°) Elevation Angle: +07.1° Horizon Angle: -00.0° Zoom: 0.5X 11988+66</p> 			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11979+86		Field Station#	11988+66	
Pic 5 Desc.	Karst Protection ECDs		Pic 6 Desc.	Catawba Road Crossing	

A/E	124300137	Date/Time	4/13/2022 11:50 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	4/13/2022 11:50 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36534
Inspector	Clint Sears			Date/Time	4/13/2022 11:48 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	11899+89
County	Montgomery	Ground	Dry	Temperature (°F)	74.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/13/2022 11:48 AM	Report #	36534
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Performed VA SWPPP inspection, from MP 223.27 (11788+52) and MP 225.37 (11899+89). Fellow EI Trey Ingram accompanied during SWPPP inspection. This section of RoW has no current construction. Temporary controls within this area are partially removed, remaining temporary controls to be removed once ground/weather conditions improve. All remaining perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Assessed AR 266.03 and RCE at Mt Tabor Rd. Row is dry and in stable condition. Section 6- Waterbars (other).					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/13/2022 11:48 AM	Report #	
Pictures					
<p>Date & Time: Wed, Apr 13, 2022, 10:29:25 EDT Position: +387 289547 / +380 345731 (e49.1ft) Altitude: 2272 ft (692.6m) Datum: WGS-84 Azimuth/Bearing: 336° SSW 330/mile True (e1.6°) Elevation Angle: -18.1° Horizon Angle: +01.1° Zoom: 1.0x 11804+00</p> 		<p>Date & Time: Wed, Apr 13, 2022, 10:30:08 EDT Position: +387 289547 / +380 345731 (e49.1ft) Altitude: 2272 ft (692.6m) Datum: WGS-84 Azimuth/Bearing: 180° SSW 330/mile True (e1.6°) Elevation Angle: -18.1° Horizon Angle: +01.1° Zoom: 1.0x 11827+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11804+00	Field Station#	11827+00		
Pic 1 Desc.	Section of Row showing conditions	Pic 2 Desc.	Section of Row showing conditions and controls		
<p>Date & Time: Wed, Apr 13, 2022, 10:14:35 EDT Position: +387 289550 / +380 345731 (e49.1ft) Altitude: 2271 ft (692.3m) Datum: WGS-84 Azimuth/Bearing: 111° SSW 330/mile True (e1.6°) Elevation Angle: -17.2° Horizon Angle: +01.3° Zoom: 1.0x 11835+00</p> 		<p>Date & Time: Wed, Apr 13, 2022, 10:12:16 EDT Position: +387 289550 / +380 345731 (e49.1ft) Altitude: 2136 ft (e50.3ft) Datum: WGS-84 Azimuth/Bearing: 010° N13E 330/mile True (e1.6°) Elevation Angle: -13.0° Horizon Angle: +01.5° Zoom: 1.0x 11843+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11835+00	Field Station#	11843+00		
Pic 3 Desc.	Section of Row showing conditions and controls	Pic 4 Desc.	Section of Row showing conditions and controls		
<p>Date & Time: Wed, Apr 13, 2022, 10:09:55 EDT Position: +387 289547 / +380 345731 (e49.1ft) Altitude: 2234 ft (e68.0m) Datum: WGS-84 Azimuth/Bearing: 35° N57W 330/mile True (e1.6°) Elevation Angle: -11.6° Horizon Angle: +00.6° Zoom: 1.0x 11855+00</p> 		<p>Date & Time: Wed, Apr 13, 2022, 10:09:55 EDT Position: +387 289547 / +380 345731 (e49.1ft) Altitude: 2183 ft (e66.4m) Datum: WGS-84 Azimuth/Bearing: 30° N57W 330/mile True (e1.6°) Elevation Angle: -10.8° Horizon Angle: +00.6° Zoom: 1.0x 11864+00</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11855+00	Field Station#	11864+00		
Pic 5 Desc.	Section of Row showing conditions and controls	Pic 6 Desc.	Section of Row showing conditions and controls at P-KL2		

AFE	124300137	Date/Time	4/13/2022 11:48 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11873+50	Field Station#	11880+00		
Pic 7 Desc.	Section of Row showing conditions and controls	Pic 8 Desc.	Section of Row showing conditions and controls		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11873+00	Field Station#	11791+70		
Pic 9 Desc.	Adequate vegetation	Pic 10 Desc.	Rain gage at Tabor RCE no measurable amount of precipitation		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/13/2022 11:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36519
Inspector	Eric Hanlon			Date/Time	4/13/2022 7:45 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	62.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/13/2022 7:45 AM	Report #	36519
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP at LY 029. The perimeter controls consist of 18" triple stacked CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 028. The perimeter controls CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 026. The perimeter controls CFS functioning as designed. The RCE was clean, no mud or other debris on road. The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/13/2022 7:45 AM	Report #	
Pictures					
<p>Date & Time: Wed Apr 13, 2022 07:45:19 EDT Position: -037.334544° / -080.809970° (-10.170) Altitude: 1566ft (-11.7ft) Datum: WGS 84 Azimuth: Bearing: 253° 57'3W, 4488mils True (-10.1) Elevation Angle: -02.3° Horizon Angle: +01.0° Zoom: 1.0x Y28</p> 		<p>Date & Time: Wed Apr 13, 2022 07:45:19 EDT Position: -037.334544° / -080.809970° (-10.170) Altitude: 1566ft (-11.7ft) Datum: WGS 84 Azimuth: Bearing: 253° 57'3W, 4488mils True (-10.1) Elevation Angle: -02.3° Horizon Angle: +01.0° Zoom: 1.0x Y28</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	Housekeeping trash in good condition y28	Pic 2 Desc.	CFS perimeter controls functional y28		
<p>Date & Time: Wed Apr 13, 2022 07:45:19 EDT Position: -037.334544° / -080.809970° (-10.170) Altitude: 1566ft (-11.7ft) Datum: WGS 84 Azimuth: Bearing: 253° 57'3W, 4488mils True (-10.1) Elevation Angle: -02.3° Horizon Angle: +01.0° Zoom: 1.0x Y28</p> 		<p>Date & Time: Wed Apr 13, 2022 07:45:19 EDT Position: -037.334544° / -080.809970° (-10.170) Altitude: 1566ft (-11.7ft) Datum: WGS 84 Azimuth: Bearing: 253° 57'3W, 4488mils True (-10.1) Elevation Angle: -02.3° Horizon Angle: +01.0° Zoom: 1.0x Y28</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	CFS perimeter controls functional Permanent stabilization in place y28	Pic 4 Desc.	RCE functional y28		
<p>Date & Time: Wed Apr 13, 2022 07:45:19 EDT Position: -037.334544° / -080.809970° (-10.170) Altitude: 1566ft (-11.7ft) Datum: WGS 84 Azimuth: Bearing: 253° 57'3W, 4488mils True (-10.1) Elevation Angle: -02.3° Horizon Angle: +01.0° Zoom: 1.0x Y28</p> 		<p>Date & Time: Wed Apr 13, 2022 07:45:19 EDT Position: -037.334544° / -080.809970° (-10.170) Altitude: 1566ft (-11.7ft) Datum: WGS 84 Azimuth: Bearing: 253° 57'3W, 4488mils True (-10.1) Elevation Angle: -02.3° Horizon Angle: +01.0° Zoom: 1.0x Y28</p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	CFS perimeter controls functional y28	Pic 6 Desc.	CFS perimeter controls functional y28		

AFE	124300137	Date/Time	4/13/2022 7:45 AM	Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 7 Desc.	CFS perimeter controls functional RCE functional y26		Pic 8 Desc.	Housekeeping trash in good condition y26	
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 9 Desc.	Secondary containment in place y26		Pic 10 Desc.	Secondary containment in place y26	
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 11 Desc.	CFS perimeter controls functional y26		Pic 12 Desc.	RCE functional y26	

AFE	124300137	Date/Time	4/13/2022 7:45 AM	Report #	
Pictures					
 <p> <small> Date & Time: Wed, Apr 13, 2022, 05:52:55 Position: +48°24'34"N / -80°47'33"W (s11.43) Altitude: 1700ft (s11.43) Datum: WGS-84 Datum/Heading: 35° N20W 430mils True (s10°) Declination Angle: -0.2° Horizon Angle: -0.0° Zoom: 1.0X Y29 </small> </p>		 <p> <small> Date & Time: Wed, Apr 13, 2022, 05:54:01 Position: +48°24'34"N / -80°47'33"W (s11.43) Altitude: 1700ft (s11.43) Datum: WGS-84 Datum/Heading: 35° N20W 430mils True (s10°) Declination Angle: -0.2° Horizon Angle: -0.0° Zoom: 1.0X Y29 </small> </p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 13 Desc.	RCE functional y29	Pic 14 Desc.	Broad base dips functional y29		
 <p> <small> Date & Time: Wed, Apr 13, 2022, 05:54:01 Position: +48°24'34"N / -80°47'33"W (s11.43) Altitude: 1700ft (s11.43) Datum: WGS-84 Datum/Heading: 35° N20W 430mils True (s10°) Declination Angle: -0.2° Horizon Angle: -0.0° Zoom: 1.0X Y29 </small> </p>		 <p> <small> Date & Time: Wed, Apr 13, 2022, 05:54:01 Position: +48°24'34"N / -80°47'33"W (s11.43) Altitude: 1700ft (s11.43) Datum: WGS-84 Datum/Heading: 35° N20W 430mils True (s10°) Declination Angle: -0.2° Horizon Angle: -0.0° Zoom: 1.0X Y29 </small> </p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 15 Desc.	Secondary containment in place y29	Pic 16 Desc.	Housekeeping trash in good y29		
 <p> <small> Date & Time: Wed, Apr 13, 2022, 05:54:01 Position: +48°24'34"N / -80°47'33"W (s11.43) Altitude: 1700ft (s11.43) Datum: WGS-84 Datum/Heading: 35° N20W 430mils True (s10°) Declination Angle: -0.2° Horizon Angle: -0.0° Zoom: 1.0X Y29 </small> </p>		 <p> <small> Date & Time: Wed, Apr 13, 2022, 05:54:01 Position: +48°24'34"N / -80°47'33"W (s11.43) Altitude: 1700ft (s11.43) Datum: WGS-84 Datum/Heading: 35° N20W 430mils True (s10°) Declination Angle: -0.2° Horizon Angle: -0.0° Zoom: 1.0X Y29 </small> </p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 17 Desc.	Permanent stabilization in place y29	Pic 18 Desc.	CFS perimeter controls functional y29		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36596
Inspector	Patrick Shields			Date/Time	4/14/2022 3:37 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10798+92
State	VA	Inspection Area	Full	Station End	10859+46
County	Giles	Ground	Dry	Temperature (°F)	66.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/14/2022 3:37 PM	Report #	36596
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 10798+92 (Cascade) to ST# 10859+46 (Kow Camp Gravel) MP 204.53 to MP 205.67 Accompanied on inspection by fellow EI Jared Saunders. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. Perimeter controls and end treatments are in place. This section of ROW has undergone temporary stabilization. Topsoil piles and cleanwater diversion berms have been stabilized. Sensitive resource buffers are in place at stream crossings S-A33, S-A34, and S-Z14. AR-241.02, 241.03, Cascade Drive, and Kow Camp #2 road crossing RCEs are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted,					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/14/2022 3:37 PM	Report #	
Pictures					
 <p>Date & Time: Thu, Apr 14, 2022, 09:43:52 EDT Position: +389 241497 / -680 618237 (+46.21) Altitude: 2221ft (+78.7m) Datum: WGS-84 Azimuth: Bearing: 350° N10W 6222mils True (+12°) Elevation Grade: -067% Horizon Grade: +008% Zoom: 1.0X 10803+00</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:47:43 EDT Position: +387 341499 / -680 618237 (+46.21) Altitude: 2221ft (+78.7m) Datum: WGS-84 Azimuth: Bearing: 350° N10W 6222mils True (+12°) Elevation Grade: -067% Horizon Grade: +008% Zoom: 1.0X 10803+00</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	10803+00		Field Station#	10808+15	
Pic 1 Desc.	RCE in place		Pic 2 Desc.	Stone inlet protection in place	
 <p>Date & Time: Thu, Apr 14, 2022, 09:45:08 EDT Position: +387 341499 / -680 618237 (+46.21) Altitude: 2221ft (+78.7m) Datum: WGS-84 Azimuth: Bearing: 350° N10W 6222mils True (+12°) Elevation Grade: -067% Horizon Grade: +008% Zoom: 1.0X 10812+00</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:45:11 EDT Position: +387 341499 / -680 618237 (+46.21) Altitude: 2221ft (+78.7m) Datum: WGS-84 Azimuth: Bearing: 350° N10W 6222mils True (+12°) Elevation Grade: -067% Horizon Grade: +008% Zoom: 1.0X 10815+00</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	10812+00		Field Station#	10815+00	
Pic 3 Desc.	Cleanwater diversion outlet protection in place		Pic 4 Desc.	Erosion control blanket in place	
 <p>Date & Time: Thu, Apr 14, 2022, 09:45:08 EDT Position: +387 341499 / -680 618237 (+46.21) Altitude: 2221ft (+78.7m) Datum: WGS-84 Azimuth: Bearing: 350° N10W 6222mils True (+12°) Elevation Grade: -067% Horizon Grade: +008% Zoom: 1.0X 10831+00</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:45:11 EDT Position: +387 341499 / -680 618237 (+46.21) Altitude: 2221ft (+78.7m) Datum: WGS-84 Azimuth: Bearing: 350° N10W 6222mils True (+12°) Elevation Grade: -067% Horizon Grade: +008% Zoom: 1.0X 10833+00</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	10831+00		Field Station#	10833+00	
Pic 5 Desc.	Triple protection ECDs in place at karst feature		Pic 6 Desc.	Waterbars in place	

AFE	124300137	Date/Time	4/14/2022 3:37 PM	Report #	
Pictures					
 <p>Date & Time: Thu, Apr 14, 2022, 09:53:58 EDT Position: +037.340133, -080.609327, +120.10m Altitude: 2331ft (+1211ft) Datum: WGS-84 Azimuth/Bearing: 036° N36E 0604mils True (+12°) Elevation Grade: +009° Horizon Grade: +006° Zoom: 1.0X 10843+30</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:55:38 EDT Position: +037.339551, -080.608844, +119.210m Altitude: 2328ft (+1208ft) Datum: WGS-84 Azimuth/Bearing: 036° N36E 0573mils True (+12°) Elevation Grade: +009° Horizon Grade: +001° Zoom: 1.0X 10843+75</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10840+30	Field Station#	10843+75		
Pic 7 Desc.	Daylight drain in place	Pic 8 Desc.	Cleanwater diversion pipe in place		
 <p>Date & Time: Thu, Apr 14, 2022, 09:57:09 EDT Position: +037.338785, -080.609711, +120.10m Altitude: 2344ft (+1224ft) Datum: WGS-84 Azimuth/Bearing: 127° S53E 2258mils True (+12°) Elevation Grade: +022° Horizon Grade: +003° Zoom: 1.0X 10848+00</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:15:49 EDT Position: +037.312452, -080.607331, +130.930m Altitude: 2291ft (+1269ft) Datum: WGS-84 Azimuth/Bearing: 296° N64W 5262mils True (+12°) Elevation Grade: +015° Horizon Grade: +000° Zoom: 1.0X 10856+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10848+00	Field Station#	10856+00		
Pic 9 Desc.	CFS perimeter control in place	Pic 10 Desc.	Stream buffer in place		
 <p>Date & Time: Thu, Apr 14, 2022, 09:13:02 EDT Position: +037.337023, -080.607210, +120.10m Altitude: 2269ft (+1249ft) Datum: WGS-84 Azimuth/Bearing: 330° N30W 5807mils True (+12°) Elevation Grade: +051° Horizon Grade: +001° Zoom: 1.0X 10858+00</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:12:03 EDT Position: +037.340133, -080.602254, +139.959m Altitude: 2360ft (+1201ft) Datum: WGS-84 Azimuth/Bearing: 357° N03W 6307mils True (+12°) Elevation Grade: +054° Horizon Grade: +013° Zoom: 1.0X 10859+00</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10858+00	Field Station#	10859+00		
Pic 11 Desc.	End treatments in place	Pic 12 Desc.	Supersilt fence perimeter control in place		

A/E	124300137	Date/Time	4/14/2022 3:37 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36587
Inspector	David Schoolcraft			Date/Time	4/14/2022 12:04 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10859+46
State	VA	Inspection Area	Full	Station End	10929+80
County	Giles	Ground	Damp	Temperature (°F)	64.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Erosion Control Blanket	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/14/2022 12:04 PM	Report #	36587
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Performed VA SWPPP inspection from MP 205.6 (10859+46) to MP 207 (10929+80). Accompanied by fellow EI Daniel Fortune No deficiencies found All perimeter controls, ECDs and BMPs were functional at the time of inspection. Vegetation or stabilization sufficient less punch list items or areas disturbed for maintenance. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/14/2022 12:04 PM	Report #	
Pictures					
 <p>Date & Time: Thu, Apr 14, 2022, 09:04:53 EDT Position: +037.332291 / -080.577671 (-15.7ft) Altitude: 2180ft (-39.4ft) Datum: WGS-84 Azimuth/Bearing: 269 S12E 232mils True (-18°) Elevation Angle: -017° Horizon Grade: +000° Zoom: 2.0x 10881+00</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:02:18 EDT Position: +037.332291 / -080.577671 (-15.7ft) Altitude: 2180ft (-39.4ft) Datum: WGS-84 Azimuth/Bearing: 168 S12E 2987mils True (-12°) Elevation Angle: -027° Horizon Grade: +010° Zoom: 2.0x 10881+20</p>			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11869+00		Field Station#	10881+20	
Pic 1 Desc.	Stabilization		Pic 2 Desc.	Waterbar and CFS checks	
 <p>Date & Time: Thu, Apr 14, 2022, 09:04:09 EDT Position: +037.332291 / -080.577671 (-15.7ft) Altitude: 2257ft (-19.7ft) Datum: WGS-84 Azimuth/Bearing: 271 N89W 4018mils True (-12°) Elevation Angle: -18.3° Horizon Grade: -01.4° Zoom: 1.0x 10887+75</p>		 <p>Date & Time: Thu, Apr 14, 2022, 08:30:33 EDT Position: +037.332291 / -080.577671 (-15.7ft) Altitude: 2257ft (-19.7ft) Datum: WGS-84 Azimuth/Bearing: 271 N89W 4018mils True (-12°) Elevation Angle: -18.3° Horizon Grade: -01.4° Zoom: 1.0x 10887+75</p>			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	10883+00		Field Station#	10887+75	
Pic 3 Desc.	S-A32		Pic 4 Desc.	Plunge Pool	
 <p>Date & Time: Thu, Apr 14, 2022, 08:43:57 EDT Position: +037.332291 / -080.577671 (-15.7ft) Altitude: 2257ft (-19.7ft) Datum: WGS-84 Azimuth/Bearing: 064 N45E 3630mils True (-12°) Elevation Angle: -015° Horizon Grade: +000° Zoom: 1.0x 10899+00</p>		 <p>Date & Time: Thu, Apr 14, 2022, 08:43:57 EDT Position: +037.332291 / -080.577671 (-15.7ft) Altitude: 2257ft (-19.7ft) Datum: WGS-84 Azimuth/Bearing: 064 N45E 3630mils True (-12°) Elevation Angle: -015° Horizon Grade: +000° Zoom: 1.0x 10899+00</p>			
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	10888+50		Field Station#	10899+00	
Pic 5 Desc.	Erosion control blanket		Pic 6 Desc.	Perimeter controls	

AFE	124300137	Date/Time	4/14/2022 12:04 PM	Report #	
Pictures					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10906+83	Field Station#	10926+30		
Pic 7 Desc.	Section of row showing conditions and controls	Pic 8 Desc.	Erosion control blanket and Waterbars		
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10927+71	Field Station#	10929+50		
Pic 9 Desc.	S-Y3	Pic 10 Desc.	S-Y2		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/14/2022 12:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36586
Inspector	Clint Sears			Date/Time	4/14/2022 11:48 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10749+92
State	VA	Inspection Area	Partial	Station End	10798+92
County	Giles	Ground	Damp	Temperature (°F)	68.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Waterbar End Treatment	Acceptable			
Cleanwater Diversion Pipe	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/14/2022 11:48 AM	Report #	36586
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from Sta#10749+92 to Sta#10798+92 (MP 203.6 to MP 204.53) Fellow EI Trey Ingram accompanied during SWPPP inspection. No deficiencies were found at time of inspection. This section of Row has undergone temporary vegetation and stabilization. All other perimeter controls, ECD'S and BMPs were functional at time of inspection. There are no crews actively working on this section of Row. Equipment bridges and stream buffers were in acceptable condition at time of inspection. No sensitive resource have been impacted. Row is damp and in stable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/14/2022 11:48 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10795+00	Field Station#	10791+00		
Pic 1 Desc.	Temporary vegetation/stabilization are acceptable	Pic 2 Desc.	Section of Row showing conditions and controls		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10788+65	Field Station#	10780+50		
Pic 3 Desc.	Section of Row showing conditions and controls	Pic 4 Desc.	Conditions and controls at S-Z7		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10773+75	Field Station#	10764+70		
Pic 5 Desc.	Conditions and controls at S-Z9	Pic 6 Desc.	Conditions and controls at S-SS4		

AFE	124300137	Date/Time	4/14/2022 11:48 AM	Report #	
Pictures					
 <p><small>Date & Time: Thu Apr 14 2022 10:45:54 EDT Position: +037 344347 / -90 635430 (+46 20') Altitude: 2088ft (+635.4m) Datum: WGS-84 Azimuth Bearing: 329 N35W 579mils True (+15') Elevation Angle: +04.3 Horizon Angle: +00.3 Zoom: 1.0X 10758+18 S-G35</small></p>		 <p><small>Date & Time: Thu Apr 14 2022 10:55:09 EDT Position: +037 344473 / -90 635522 (+46 20') Altitude: 2278ft (+693.6m) Datum: WGS-84 Azimuth Bearing: 072 N72E 1280mils True (+15') Elevation Angle: +17.5 Horizon Angle: +02.1 Zoom: 1.0X 10751+00</small></p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10758+18	Field Station#	10751+00		
Pic 7 Desc.	Conditions and controls at S-G35	Pic 8 Desc.	Section of Row showing conditions and controls		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/14/2022 11:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36580
Inspector	Eric Hanlon			Date/Time	4/14/2022 10:38 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10655+00
State	VA	Inspection Area	Full	Station End	10749+92
County	Giles	Ground	Wet	Temperature (°F)	63.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Energy Dissipater	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/14/2022 10:38 AM	Report #	36580
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
Completed aVA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). No Compliance issues noted: Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. The ROW is wet but in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/14/2022 10:38 AM	Report #	
Pictures					
 <p>Date & Time: Thu, Apr 14, 2022, 09:45:01 EDT Position: +037.342659, -080.622674 (+32.8H) Altitude: 2340ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mils True (+12°) Elevation Angle: 18.8° Horizon Angle: +00.3° Zoom: 1.0X 10712+73</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:46:01 EDT Position: +037.342659, -080.622674 (+32.8H) Altitude: 2340ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mils True (+12°) Elevation Angle: 18.8° Horizon Angle: +00.3° Zoom: 1.0X 10729+82</p>		GPS Location	See photo
Field Station#	10712+73	Field Station#	10729+82	GPS Location	See photo
Pic 1 Desc.	Resource buffers in place	Pic 2 Desc.	Water bars and ET in place		
 <p>Date & Time: Thu, Apr 14, 2022, 09:46:01 EDT Position: +037.342659, -080.622674 (+32.8H) Altitude: 2340ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mils True (+12°) Elevation Angle: 18.8° Horizon Angle: +00.3° Zoom: 1.0X 10698+50</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:46:01 EDT Position: +037.342659, -080.622674 (+32.8H) Altitude: 2340ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mils True (+12°) Elevation Angle: 18.8° Horizon Angle: +00.3° Zoom: 1.0X 10733+18</p>		GPS Location	See photo
Field Station#	10698+50	Field Station#	10733+18	GPS Location	See photo
Pic 3 Desc.	Equipment bridge functional	Pic 4 Desc.	P1 and wattles in place		
 <p>Date & Time: Thu, Apr 14, 2022, 09:47:28 EDT Position: +037.342659, -080.622674 (+32.8H) Altitude: 2340ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mils True (+12°) Elevation Angle: 18.8° Horizon Angle: +00.3° Zoom: 1.0X 10694+15</p>		 <p>Date & Time: Thu, Apr 14, 2022, 09:47:28 EDT Position: +037.342659, -080.622674 (+32.8H) Altitude: 2340ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mils True (+12°) Elevation Angle: 18.8° Horizon Angle: +00.3° Zoom: 1.0X 10742+69</p>		GPS Location	See photo
Field Station#	10694+15	Field Station#	10742+69	GPS Location	See photo
Pic 5 Desc.	Clean water drainage feature functional	Pic 6 Desc.	Clean water drainage feature functional		

AFE	124300137	Date/Time	4/14/2022 10:38 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10779+71	Field Station#	10749+00		
Pic 7 Desc.	Equipment bridge functional	Pic 8 Desc.	RCE functional		
		<div style="text-align: center;">Insert image here</div>			
GPS Location	See photo	GPS Location			
Field Station#	10683+00	Field Station#			
Pic 9 Desc.	Energy dissipater	Pic 10 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/14/2022 10:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36649
Inspector	Daniel Fortune			Date/Time	4/15/2022 6:30 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11098+47
County	Giles	Ground	Dry	Temperature (°F)	49.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/15/2022 6:30 PM	Report #	36649
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. "Station numbers are approximate". Observed Activity: Environmental Crew (1702) has completed making repairs to the ditch line settling between 11048+00 to 11043+66. This area has been temporarily stabilized and this crew has also addressed a previously documented punch list item to the perimeter CFS. -(Sediment build up on perimeter CFS near 11097+34.) The ROW in that area received 0.00" of precipitation in the last 24 hrs. The ROW from AR 244 near 11025+02 to near 11070+21 has been temporarily stabilized. No erosion issues. The ROW from station 11070+21 to near 11098+00 has had final Restoration completed. There are 12" CFS that are being used as water bars at this time. There are no erosion issues visible in the final restored areas. The perimeter controls appear to be functional at this time. One area of open ditch (approximately 270') near 11061+00. Rock Road approaches were cleaned and functioning as intended. No sensitive resources have been impacted.</p>					
<p>Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.</p>					

AFE	124300137	Date/Time	4/15/2022 6:30 PM	Report #	
Pictures					
 <p>Date & Time: Fri, Apr 15, 2022 10:10:45 EDT Position: +037.318485 / -080.549569 / ±15.6m Altitude: 2320m / ±11.0m Datum: WGS-84 Azimuth/Bearing: 107.573E 1902mils True (±12) Elevation Grade: -016 Horizon Grade: -001 Zoom: 0.5X 11054+00</p>		 <p>Date & Time: Fri, Apr 15, 2022 10:10:50 EDT Position: +037.318485 / -080.549569 / ±15.6m Altitude: 2399m / ±20.0m Datum: WGS-84 Azimuth/Bearing: 044.806E 055mils True (±12) Elevation Grade: -016 Horizon Grade: -001 Zoom: 0.5X 11046+00</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11054+00	Field Station#	11046+00		
Pic 1 Desc.	Over view of temporary stabilization of row.	Pic 2 Desc.	Over view of additional stabilization of steep slope conditions with ECB and high velocity CC4 coconut blanket over the water bars.		
 <p>Date & Time: Fri, Apr 15, 2022 10:40:06 EDT Position: +037.318485 / -080.549569 / ±15.6m Altitude: 2334m / ±19.0m Datum: WGS-84 Azimuth/Bearing: 090.590E 1600mils True (±12) Elevation Grade: -061 Horizon Grade: -004 Zoom: 0.5X 11043+66</p>		 <p>Date & Time: Fri, Apr 15, 2022 10:40:06 EDT Position: +037.318485 / -080.549569 / ±15.6m Altitude: 2245m / ±28.0m Datum: WGS-84 Azimuth/Bearing: 124.806E 000mils True (±12) Elevation Grade: -020 Horizon Grade: -001 Zoom: 1.0X 11038+00</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11043+66	Field Station#	11038+00		
Pic 3 Desc.	View of re-worked sunken ditch line area with additional ECB stabilization.	Pic 4 Desc.	View of perimeter CFS and stabilized earthen berm.		
 <p>Date & Time: Fri, Apr 15, 2022 09:32:28 EDT Position: +037.232224 / -080.538447 / ±20.4m Altitude: 2317m / ±29.4m Datum: WGS-84 Azimuth/Bearing: 006.310E 010mils True (±12) Elevation Grade: -052 Horizon Grade: -002 Zoom: 1.0X 11026+85</p>		 <p>Date & Time: Fri, Apr 15, 2022 09:32:28 EDT Position: +037.232224 / -080.538447 / ±20.4m Altitude: 2317m / ±29.4m Datum: WGS-84 Azimuth/Bearing: 006.310E 010mils True (±12) Elevation Grade: -052 Horizon Grade: -002 Zoom: 1.0X 11025+23</p>			
GPS Location	See Photo	GPS Location	1102523		
Field Station#	11026+85	Field Station#	11025+23		
Pic 5 Desc.	Over view of the S-IJ18 stream buffer zones and equipment bridge crossing conditions.	Pic 6 Desc.	AR 244 entrance to row. Travel lane has been recently temporary stabilized.		

AFE	124300137	Date/Time	4/15/2022 6:30 PM	Report #	
Pictures					
<p><small>Date & Time: Fri, Apr 15, 2022, 09:26:00 EDT Position: +037 315431 / +080 543990 (±12.8ft) Altitude: 2071ft (±11.3ft) Datum: WGS-84 Azimuth/Bearing: 012° N12E 0213mils True (±12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 0.5X 11065+00</small></p> 		<p><small>Date & Time: Fri, Apr 15, 2022, 09:40:27 EDT Position: +037 315369 / +080 543993 (±12.8ft) Altitude: 2034ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 317° S31W 0086mils True (±12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11063+44</small></p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11065+00	Field Station#	11063+44		
Pic 7 Desc.	View of sunken ditch line through the drainage feature. The contractor is aware.	Pic 8 Desc.	View of steep slope and perimeter controls and equipment bridge crossing conditions.		
<p><small>Date & Time: Fri, Apr 15, 2022, 09:40:12 EDT Position: +037 311207 / +080 532108 (±12.85ft) Altitude: 1820ft (±9.4ft) Datum: WGS-84 Azimuth/Bearing: 110° S92E 192mils True (±12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11067+00</small></p> 		<p><small>Date & Time: Fri, Apr 15, 2022, 09:18:42 EDT Position: +037 313336 / +080 534142 (±12.94ft) Altitude: 1800ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 301° S37W 410mils True (±12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11097+34</small></p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11067+00	Field Station#	11097+34		
Pic 9 Desc.	Steep slope and temporary stabilization conditions of row.	Pic 10 Desc.	Additional stabilization and re-seeded portion of final restoration area.		
<p><small>Date & Time: Fri, Apr 15, 2022, 09:15:19 EDT Position: +037 313336 / +080 534142 (±12.94ft) Altitude: 1920ft (±11.0ft) Datum: WGS-84 Azimuth/Bearing: 086° N86E 1529mils True (±12°) Elevation Grade: +02% Horizon Grade: +00% Zoom: 0.5X 11097+34</small></p> 		<p><small>Date & Time: Fri, Apr 15, 2022, 09:10:10 EDT Position: +037 313734 / +080 535529 (±10.4ft) Altitude: 2013ft (±11.3ft) Datum: WGS-84 Azimuth/Bearing: 091° S59E 1613mils True (±12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11093+00</small></p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11097+34	Field Station#	11093+00		
Pic 11 Desc.	Cleaned off CFS perimeter controls.	Pic 12 Desc.	Final Restoration Area. Adequate vegetation visible.		

A/E	124300137	Date/Time	4/15/2022 6:30 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36632
Inspector	Clint Sears			Date/Time	4/15/2022 11:33 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10929+80
State	VA	Inspection Area	Partial	Station End	11023+80
County	Giles	Ground	Damp	Temperature (°F)	61.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Waterbar	Acceptable			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Rock Construction Entrance	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/15/2022 11:33 AM	Report #	36632
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Performed SWPPP inspection from MP 207 (10929+80) and MP 208.78 (11023+80). Accompanied by fellow EI Trey Ingram. No deficiencies were found at this. A portion of this section of RoW has been permanently restored. Assessed AR 242.01. AR 242.01 is partially completed, incomplete portions are stabilized. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at time of inspection. No impact to sensitive resources observed. Row is damp and in stable condition. Karst ECD's are in acceptable condition. Section 6 - CFS waterbars (other).					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/15/2022 11:33 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	see photo	
Field Station#	10936+00		Field Station#	10957+80	
Pic 1 Desc.	Section of Row showing conditions and controls		Pic 2 Desc.	Section of Row showing conditions and controls	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10965+50		Field Station#	10969+73	
Pic 3 Desc.	Karst ECD's are in acceptable condition		Pic 4 Desc.	Section of Row showing conditions and controls	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10977+25		Field Station#	10985+65	
Pic 5 Desc.	Section of Row showing conditions and controls		Pic 6 Desc.	Condition and controls at S-E24	

AFE	124300137	Date/Time	4/15/2022 11:33 AM	Report #	
Pictures					
<p><small>Date & Time: Fri, Apr 15, 2022, 10:57:57 EST Position: +037.233934° / -080.54357° (-80.91) Altitude: 2448ft (+24.00) Datum: WGS-84 Azimuth/Bearing: 145° NSW 0.13mils True (+23°) Elevation Angle: +38.0 Horizon Angle: +02.8 Zoom: 1.0X 10987-50 S-E25</small></p> 		<p><small>Date & Time: Fri, Apr 15, 2022, 10:58:47 EST Position: +037.233934° / -080.54357° (-80.91) Altitude: 2448ft (+24.00) Datum: WGS-84 Azimuth/Bearing: 145° NSW 0.13mils True (+23°) Elevation Angle: +38.0 Horizon Angle: +02.8 Zoom: 1.0X 10988-45</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10987+50	Field Station#	10988+45		
Pic 7 Desc.	Section of Row showing conditions and controls at S-E25	Pic 8 Desc.	Section of Row showing conditions and controls		
<p><small>Date & Time: Fri, Apr 15, 2022, 10:59:07 EST Position: +037.233934° / -080.54357° (-80.91) Altitude: 2448ft (+24.00) Datum: WGS-84 Azimuth/Bearing: 145° NSW 0.13mils True (+23°) Elevation Angle: +38.0 Horizon Angle: +02.8 Zoom: 1.0X 10990-79</small></p> 		<p><small>Date & Time: Fri, Apr 15, 2022, 10:59:40 EST Position: +037.233934° / -080.54357° (-80.91) Altitude: 2448ft (+24.00) Datum: WGS-84 Azimuth/Bearing: 145° NSW 0.13mils True (+23°) Elevation Angle: +38.0 Horizon Angle: +02.8 Zoom: 1.0X 10996-50</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10990+79	Field Station#	10996+50		
Pic 9 Desc.	Erosion control blanket installed where previous erosion had occurred	Pic 10 Desc.	Clean water diversion pipe, level spreader and perimeter controls are in acceptable condition		
<p><small>Date & Time: Fri, Apr 15, 2022, 09:45:13 EST Position: +037.323821° / -080.555844° (-80.93) Altitude: 2469ft (+24.90) Datum: WGS-84 Azimuth/Bearing: 139° S42E 2453mils True (+7.7) Elevation Angle: +28.8 Horizon Angle: +03.8 Zoom: 1.0X 11013+75</small></p> 		<p><small>Date & Time: Fri, Apr 15, 2022, 09:46:13 EST Position: +037.323821° / -080.555844° (-80.93) Altitude: 2469ft (+24.90) Datum: WGS-84 Azimuth/Bearing: 139° S42E 2453mils True (+7.7) Elevation Angle: +28.8 Horizon Angle: +03.8 Zoom: 1.0X 11017-39 S-PA07</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11013+75	Field Station#	11017+35		
Pic 11 Desc.	Section of Row showing conditions and controls	Pic 12 Desc.	Section of Row showing conditions and controls at S-PA07		

A/E	124300137	Date/Time	4/15/2022 11:33 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36638
Inspector	Patrick Shields			Date/Time	4/15/2022 1:24 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11098+47
State	VA	Inspection Area	Full	Station End	11184+85
County	Giles	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/15/2022 1:24 PM	Report #	36638
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11098+47 (AR-245.02) to ST# 11184+85 (AR-249.02) MP 210.2 to MP 211.83. Accompanied on inspection by fellow EI Jared Saunders. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. ST# 11445+50 to ST# 11170+00 has undergone temporary stabilization. Cleanwater diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Final restoration has occurred between ST# 11098+47 and ST# 11145+50 and between ST# 11170+00 and ST# 11184+85. CFS perimeter controls, end treatments and temporary waterbars are in place. Daylight drains with outlet protection and Permanent waterbars (section 6-other) with level spreaders are in place. AR-245.02, 249, 249.03, 249.01 and 249.02 RCEs are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/15/2022 1:24 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11106+00	Field Station#	11112+00		
Pic 1 Desc.	CFS perimeter control in place	Pic 2 Desc.	CFS triple stack perimeter control in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11120+00	Field Station#	11134+00		
Pic 3 Desc.	Temporary CFS waterbars in place	Pic 4 Desc.	Permanent waterbars with level spreaders in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11140+00	Field Station#	11146+00		
Pic 5 Desc.	Permanent vegetation present	Pic 6 Desc.	Cleanwater diversion berm in place		

AFE	124300137	Date/Time	4/15/2022 1:24 PM	Report #	
Pictures					
 <p>Date & Time: Fri, Apr 15, 2022, 05:49:59 EDT Position: +387.312605° / -080.519123° (+15.4m) Altitude: 3038ft (+11.2m) Datum: WGS-84 Azimuth/Bearing: 108° S27E 1270mils True (+12°) Elevation Grade: +04% Horizon Grade: +002% Zoom: 1.0X 11149+00</p>		 <p>Date & Time: Fri, Apr 15, 2022, 15:56:14 EDT Position: +387.313512° / -080.519388° (+15.8m) Altitude: 3038ft (+11.2m) Datum: WGS-84 Azimuth/Bearing: 151° S27E 238mils True (+12°) Elevation Grade: +03% Horizon Grade: +002% Zoom: 1.0X 11152+50</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11149+00	Field Station#	11152+50		
Pic 7 Desc.	Supersilt fence perimeter control in place	Pic 8 Desc.	Waterbars in place		
 <p>Date & Time: Fri, Apr 15, 2022, 05:47:09 EDT Position: +387.310392° / -080.516554° (+15.3m) Altitude: 1938ft (+11.2m) Datum: WGS-84 Azimuth/Bearing: 108° S30E 1700mils True (+12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.0X 11163+00</p>		 <p>Date & Time: Fri, Apr 15, 2022, 06:46:05 EDT Position: +387.310431° / -080.514393° (+15.4m) Altitude: 1938ft (+11.2m) Datum: WGS-84 Azimuth/Bearing: 113° N27W 5920mils True (+12°) Elevation Grade: +00% Horizon Grade: +000% Zoom: 1.0X 11167+50</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11163+00	Field Station#	11167+50		
Pic 9 Desc.	P1 silt fence perimeter control in place	Pic 10 Desc.	Cleanwater outlet protection in place		
 <p>Date & Time: Fri, Apr 15, 2022, 05:45:25 EDT Position: +387.310392° / -080.514393° (+15.4m) Altitude: 1938ft (+11.2m) Datum: WGS-84 Azimuth/Bearing: 207° S28W 1660mils True (+13°) Elevation Grade: +000% Horizon Grade: +00% Zoom: 1.0X 11168+00</p>		 <p>Date & Time: Fri, Apr 15, 2022, 08:39:45 EDT Position: +387.307552° / -080.511914° (+15.8m) Altitude: 1928ft (+11.0m) Datum: WGS-84 Azimuth/Bearing: 069° N09E 1582mils True (+12°) Elevation Grade: +00% Horizon Grade: +01% Zoom: 1.0X 11184+15</p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	11168+00	Field Station#	11184+15		
Pic 11 Desc.	RCE in place	Pic 12 Desc.	Daylight drain in place		

A/E	124300137	Date/Time	4/15/2022 1:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36615
Inspector	Eric Hanlon			Date/Time	4/15/2022 7:08 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11184+85
State	VA	Inspection Area	Full	Station End	11254+99
County	Giles	Ground	Damp	Temperature (°F)	56.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/15/2022 7:08 AM	Report #	36615
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). Compliance issues noted: Observance: Perimeter controls in place & functioning as designed Permanent & temporary stabilization in place. - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. - Temporary stabilization near 11222+50 to near 11253+50. This section of row has been stabilized for the winter months. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. AR-249.02 & 244 RCE's are maintained in acceptable condition. Some subsidence on both sides of winding way also monitoring it. The ROW is damp and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/15/2022 7:08 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11184+79	Field Station#	11191+47		
Pic 1 Desc.	Rock check dams in place	Pic 2 Desc.	Clean water drainage feature in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11194+00	Field Station#	11253+00		
Pic 3 Desc.	Permanent water bars and level spreader in place	Pic 4 Desc.	Erosion control blanket in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11246+00	Field Station#	11226+00		
Pic 5 Desc.	Water bars and ET in place	Pic 6 Desc.	Picture showing condition of row		

A/E	124300137	Date/Time	4/15/2022 7:08 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/15/2022 7:08 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		