



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36933
Inspector	Rob Robertson			Date/Time	4/25/2022 11:18 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Dry	Temperature (°F)	61.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/25/2022 11:18 AM	Report #	36933
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
A regular scheduled VADEQ SWPPP inspection on JNF and private property was completed today on Brush Mountain. The ROW surface remains stable with adequate grasses and/or mulch in place to resist erosion. ECDs are in place and functional. No ECD maintenance needs were identified. Slope breakers, sumps and end treatments are effectively controlling stormwater runoff. No slips or rilling was discovered. No impact has occurred at resource crossings and buffers are stable. RCEs are in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/25/2022 11:18 AM	Report #	
Pictures					
 <p>Date & Time: Mon, Apr 25, 2022, 11:18:00 EDT Position: +037.312222 / +080.384331 (+5.0m) Altitude: 656m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 129.551E (+29.3mils Magnetic (+15)) Elevation Angle: -19.1 Horizon Angle: +01.7 Zoom: 1.0X S-HH18</p>		 <p>Date & Time: Mon, Apr 25, 2022, 11:18:00 EDT Position: +037.312222 / +080.384331 (+5.0m) Altitude: 656m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 220.540W (-39.1mils Magnetic (+15)) Elevation Angle: -36.7 Horizon Angle: -03.3 Zoom: 1.0X S-HH18</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11667+00	Field Station#	11665+50		
Pic 1 Desc.	ROW stable at top of Brush Mountain. ECDs are in place.	Pic 2 Desc.	ROW stable. End treatments acceptable.		
 <p>Date & Time: Mon, Apr 25, 2022, 09:07:34 EDT Position: +037.312222 / +080.384331 (+5.0m) Altitude: 773m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 107.711E (+10.7mils Magnetic (+12)) Elevation Angle: -30.7 Horizon Angle: -03.7 Zoom: 1.0X S-HH18</p>		 <p>Date & Time: Mon, Apr 25, 2022, 09:07:34 EDT Position: +037.312222 / +080.384331 (+5.0m) Altitude: 773m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 107.711E (+10.7mils Magnetic (+12)) Elevation Angle: -30.7 Horizon Angle: -03.7 Zoom: 1.0X S-HH18</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11658+00	Field Station#	11638+00		
Pic 3 Desc.	Sumps and end treatments functional.	Pic 4 Desc.	Perimeter ECDs are acceptable.		
 <p>Date & Time: Mon, Apr 25, 2022, 09:07:34 EDT Position: +037.312222 / +080.384331 (+5.0m) Altitude: 872m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 158.540E (+58.5mils Magnetic (+12)) Elevation Angle: -10.7 Horizon Angle: +02.7 Zoom: 1.0X S-HH18</p>		 <p>Date & Time: Mon, Apr 25, 2022, 09:07:34 EDT Position: +037.312222 / +080.384331 (+5.0m) Altitude: 576m (+5.0m) Datum: WGS-84 Azimuth/Bearing: 160.540E (+60.5mils Magnetic (+12)) Elevation Angle: -11.6 Horizon Angle: +02.7 Zoom: 1.0X S-RR14</p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11626+04	Field Station#	11614+20		
Pic 5 Desc.	The S-HH18 crossing is stable.	Pic 6 Desc.	The S-RR14 crossing is stable.		

AFE	124300137	Date/Time	4/25/2022 11:18 AM	Report #	
Pictures					
 <p> Date & Time Wed, 4/25/2022 05:50:41 EDT Position: 43°31'42.40" N -93°40'22.35" W (0.0m) Altitude: 182m (+5.0m) Datum: WGS-84 Azimuth Bearing: 116.544E 2062mils Magnetic (+15°) Elevation Angle: 10.1° Zoom: 1.0X S-006 </p>		 <p> Date & Time Wed, 4/25/2022 05:50:41 EDT Position: 43°31'42.40" N -93°40'22.35" W (0.0m) Altitude: 182m (+5.0m) Datum: WGS-84 Azimuth Bearing: 116.544E 2062mils Magnetic (+15°) Elevation Angle: 10.1° Zoom: 1.0X S-006 </p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11613+69	Field Station#	11608+17		
Pic 7 Desc.	The S-RR13 crossing on access road MN-258.04.	Pic 8 Desc.	The S-006 crossing is stable.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/25/2022 11:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36951
Inspector	Jared Saunders			Date/Time	4/25/2022 3:38 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+50
State	VA	Inspection Area	Partial	Station End	11788+52
County	Montgomery	Ground	Dry	Temperature (°F)	81.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/25/2022 3:38 PM	Report #	36951
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) Accompanied by El Pat Shields on SWPPP inspection from MP 223.27 to MP 225.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) and level spreaders in place where designated on E&S sheets. Majority of perimeter controls have been removed due to final restoration vegetation growth. Sensitive resource buffers are in place at pond P-KL2. Mount Tabor road crossing RCE is maintained and in acceptable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/25/2022 3:38 PM	Report #	
Pictures					
 <p>Date & Time: Mon Apr 25 2022 09:03:49 EDT Position: +037.257432, -080.337362, +54.041 Altitude: 2213ft (+59.2m) Datum: WGS-84 Azimuth Bearing: 261° NW 5310' Azimuth True (+14) Elevation Angle: -04.2° Horizon Angle: -03.2° Zoom: 1.0X 11891+00</p>		 <p>Date & Time: Mon Apr 25 2022 09:16:36 EDT Position: +037.258729, -080.346101, +54.54m Altitude: 2213ft (+67.1m) Datum: WGS-84 Azimuth Bearing: 340° NW 4220mils True (+14) Elevation Angle: -11.2° Horizon Angle: -02.8° Zoom: 1.0X 11864+00</p>			
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	11891+00		Field Station#	11864+00	
Pic 1 Desc.	ROW permanently restored. Waterbar and level spreader in place.		Pic 2 Desc.	Sensitive resource buffer in place at P-KL2.	
 <p>Date & Time: Mon Apr 25 2022 09:35:00 EDT Position: +037.257718, -080.342802, +54.850m Altitude: 2131ft (+65.2m) Datum: WGS-84 Azimuth Bearing: 042° N49E 0971mils True (+14) Elevation Angle: -12.8° Horizon Angle: -00.7° Zoom: 1.0X 11841+00</p>		 <p>Date & Time: Mon Apr 25 2022 09:35:00 EDT Position: +037.257718, -080.342802, +54.850m Altitude: 2131ft (+65.2m) Datum: WGS-84 Azimuth Bearing: 042° N49E 0971mils True (+14) Elevation Angle: -12.8° Horizon Angle: -00.7° Zoom: 1.0X 11841+00</p>			
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	11841+00		Field Station#	11836+00	
Pic 3 Desc.	Triple stack 18 inch CFS in place along LOD.		Pic 4 Desc.	Triple stack 18 inch CFS and super silt fence in place along LOD.	
 <p>Date & Time: Mon Apr 25 2022 10:13:09 EDT Position: +037.259370, -080.346593, +52.7m Altitude: 2135ft (+65.2m) Datum: WGS-84 Azimuth Bearing: 328° N12W 6187mils True (+16) Elevation Angle: -13.3° Horizon Angle: -02.3° Zoom: 1.0X 11830+00</p>		 <p>Date & Time: Mon Apr 25 2022 10:13:09 EDT Position: +037.259370, -080.346593, +52.7m Altitude: 2135ft (+65.2m) Datum: WGS-84 Azimuth Bearing: 279° N81W 4960mils True (+20) Elevation Angle: -04.5° Horizon Angle: -03.2° Zoom: 1.0X 11789+00</p>			
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	11830+00		Field Station#	11789+00	
Pic 5 Desc.	ROW permanently restored. Waterbar and level spreader in place.		Pic 6 Desc.	RCE in place at Mount Tabor Road crossing.	

A/E	124300137	Date/Time	4/25/2022 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/25/2022 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36924
Inspector	Chris Burns			Date/Time	4/25/2022 7:18 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+52
County	Montgomery	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/25/2022 7:18 AM	Report #	36924
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 221.02 (11670+00) and MP 223.27 (11788+52). Accompanied by fellow EI Clint Sears. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/25/2022 7:18 AM	Report #	
Pictures					
 <p>Date & Time: Mon, Apr 25, 2022, 08:43:11 EDT Position: 145233.225 E / 355111.514 N (+11.4M) Altitude: 2255ft (+7.3M) Datum: WGS-84 Azimuth/Bearing: 133° 20'35" 3337mils True (+12°) Elevation Angle: +0.6° Horizon Angle: +0.0° Zoom: 0.25 Photo: 01</p>		 <p>Date & Time: Mon, Apr 25, 2022, 08:52:12 EDT Position: 145233.225 E / 355111.514 N (+11.4M) Altitude: 2255ft (+7.3M) Datum: WGS-84 Azimuth/Bearing: 133° 20'35" 3337mils True (+12°) Elevation Angle: +0.6° Horizon Angle: +0.0° Zoom: 0.25 Photo: 02</p>			
GPS Location	1	GPS Location	2		
Field Station#	11676+75	Field Station#	11683+00		
Pic 1 Desc.	Section of RoW showing conditions and controls.	Pic 2 Desc.	Slope drain inlet protection functional.		
 <p>Date & Time: Mon, Apr 25, 2022, 09:00:38 EDT Position: 145233.225 E / 355111.514 N (+11.4M) Altitude: 2255ft (+7.3M) Datum: WGS-84 Azimuth/Bearing: 133° 20'35" 3337mils True (+12°) Elevation Angle: +0.6° Horizon Angle: +0.0° Zoom: 0.25 Photo: 03</p>		 <p>Date & Time: Mon, Apr 25, 2022, 09:00:38 EDT Position: 145233.225 E / 355111.514 N (+11.4M) Altitude: 2255ft (+7.3M) Datum: WGS-84 Azimuth/Bearing: 133° 20'35" 3337mils True (+12°) Elevation Angle: +0.6° Horizon Angle: +0.0° Zoom: 0.25 Photo: 04</p>			
GPS Location	3	GPS Location	4		
Field Station#	11695+00	Field Station#	11704+10		
Pic 3 Desc.	CFS perimeter controls functional.	Pic 4 Desc.	S-MN22		
 <p>Date & Time: Mon, Apr 25, 2022, 09:07:42 EDT Position: 145233.225 E / 355111.514 N (+11.4M) Altitude: 2255ft (+7.3M) Datum: WGS-84 Azimuth/Bearing: 133° 20'35" 3337mils True (+12°) Elevation Angle: +0.6° Horizon Angle: +0.0° Zoom: 0.25 Photo: 05</p>		 <p>Date & Time: Mon, Apr 25, 2022, 09:11:41 EDT Position: 145233.225 E / 355111.514 N (+11.4M) Altitude: 2255ft (+7.3M) Datum: WGS-84 Azimuth/Bearing: 133° 20'35" 3337mils True (+12°) Elevation Angle: +0.6° Horizon Angle: +0.0° Zoom: 0.25 Photo: 06</p>			
GPS Location	5	GPS Location	6		
Field Station#	11707+00	Field Station#	11717+00		
Pic 5 Desc.	Section of RoW showing conditions and controls.	Pic 6 Desc.	Section of RoW showing conditions and controls.		

AFE	124300137	Date/Time	4/25/2022 7:18 AM	Report #	
Pictures					
					
GPS Location	7	GPS Location	8		
Field Station#	11723+00	Field Station#	11740+55		
Pic 7 Desc.	Section of RoW showing conditions and controls.	Pic 8 Desc.	S-EF65.		
					
GPS Location	9	GPS Location	10		
Field Station#	11743+97	Field Station#	11753+00		
Pic 9 Desc.	S-EF62.	Pic 10 Desc.	Section of RoW showing conditions and controls.		
					
GPS Location	11	GPS Location	12		
Field Station#	11767+44	Field Station#	11780+00		
Pic 11 Desc.	S-IJ52/W-IJ46.	Pic 12 Desc.	P-1 perimeter controls functional.		

AFE	124300137	Date/Time	4/25/2022 7:18 AM	Report #	
Pictures					
					
GPS Location	13	GPS Location			
Field Station#	11788+52	Field Station#			
Pic 13 Desc.	RCE off of Mt Tabor rd.	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36944
Inspector	Daniel Fortune			Date/Time	4/25/2022 1:16 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+89
State	VA	Inspection Area	Partial	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	68.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/25/2022 1:16 PM	Report #	36944
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>See photos for GPS coordinates.</p> <p>Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). There had been about 0.0" of precipitation in the last 24 hours. The row is well vegetated and no erosion issues at this time.</p> <p>No Deficiencies documented for repairs today.</p> <p>This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time.</p> <p>Permanent water bars remain installed and are functioning as intended at this time. (Other in section 6 above).</p> <p>Level Spreaders are functional</p> <p>Precision Crews: (1710) was on site near access road 266.03. This crew has been observed walking the row and looking for damaged ECDs for repairs. At this time there has been no items communicated to the EI staff. No repairs observed today at the time of inspection.</p> <p>All other perimeter controls, ECDs and BMPs are weathered but appear to be functional at time of inspection. Vegetation and stabilization are sufficient at this time.</p> <p>No impact to sensitive resources observed. Assessed Ar 266.03</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		4/25/2022 1:16 PM		Report #							
Pictures															
<p>Date & Time: Mon, Apr 25, 2022, 08:57:57 EDT Position: +000.000000 / +000.000000 (Error) Altitude: 0ft (Error) Datum: WGS-84 Azimuth/Bearing: 006° N06E 0107mils Error (Error) Elevation Grade: -015° Horizon Grade: -001° Zoom: 0.5X 11900+81</p> 				<p>Date & Time: Mon, Apr 25, 2022, 08:49:22 EDT Position: +000.000000 / +000.000000 (Error) Altitude: 2189ft (±100.0ft) Datum: WGS-84 Azimuth/Bearing: 188° S08E 263mils True (±15°) Elevation Grade: -000° Horizon Grade: -000° Zoom: 1.0X 11920+00</p> 											
GPS Location				See Photo				GPS Location				See Photo			
Field Station#				11900+81				Field Station#				11920+00			
Pic 1 Desc.				Permanent level spreader condition				Pic 2 Desc.				Permanent water bar location and conditions. No Issues at this time.			
<p>Date & Time: Mon, Apr 25, 2022, 09:34:38 EDT Position: +037.272930 / -080.325122 (±24.4ft) Altitude: 2164ft (±75.7ft) Datum: WGS-84 Azimuth/Bearing: 275° S02W 444mils True (±12°) Elevation Grade: -015° Horizon Grade: -004° Zoom: 1.0X 11942+57</p> 				<p>Date & Time: Mon, Apr 25, 2022, 09:34:38 EDT Position: +037.272930 / -080.325122 (±24.4ft) Altitude: 1956ft (±13.4ft) Datum: WGS-84 Azimuth/Bearing: 275° S02W 444mils True (±12°) Elevation Grade: -015° Horizon Grade: -018° Zoom: 0.5X 11967+00</p> 											
GPS Location				See Photo				GPS Location				See Photo			
Field Station#				119+43				Field Station#				11967+00			
Pic 3 Desc.				Super silt fence conditions. No issues at this time.				Pic 4 Desc.				P1 perimeter silt fencing conditions and final restoration area.			
<p>Date & Time: Mon, Apr 25, 2022, 09:49:50 EDT Position: +037.269702 / -080.322927 (±91.5ft) Altitude: 1756ft (±215.0ft) Datum: WGS-84 Azimuth/Bearing: 019° N19E 0338mils True (±12°) Elevation Grade: -024° Horizon Grade: -008° Zoom: 0.5X 11973+00</p> 				<p>Date & Time: Mon, Apr 25, 2022, 09:49:50 EDT Position: +037.269702 / -080.322927 (±91.5ft) Altitude: 1756ft (±215.0ft) Datum: WGS-84 Azimuth/Bearing: 019° N19E 0338mils True (±12°) Elevation Grade: -024° Horizon Grade: -008° Zoom: 0.5X 11973+86</p> 											
GPS Location				See Photo				GPS Location				See Photo			
Field Station#				11973+00				Field Station#				11978+86			
Pic 5 Desc.				Final Restoration Area				Pic 6 Desc.				Perimeter ECDs near presumed karst area.			

AFE	124300137	Date/Time	4/25/2022 1:16 PM	Report #	
Pictures					
 <p> <small> Date & Time: Mon, Apr 25, 2022, 09:50:12 EDT Position: +037.269411° / -080.322739° (-101.1ft) Altitude: 1687ft (-11.7ft) Datum: WGS-84 Azimuth/Bearing: 109° S77E 1931mils True (-12°) Elevation Grade: -026% Horizon Grade: +000% Zoom: 0.5X 11978+86 </small> </p>		 <p> <small> Date & Time: Mon, Apr 25, 2022, 09:50:49 EDT Position: +037.307552° / -080.319992° (-117.4ft) Altitude: 1690ft (-10.5ft) Datum: WGS-84 Azimuth/Bearing: 107° S71E 1796mils True (-12°) Elevation Grade: -012% Horizon Grade: +005% Zoom: 2.0X 11977+ </small> </p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11978+86	Field Station#	11993+00		
Pic 7 Desc.	AR 266	Pic 8 Desc.	Final Restoration near spread break.		
 <p> <small> Date & Time: Mon, Apr 25, 2022, 15:01:04 EDT Position: +037.249708° / -080.312697° (-127.8ft) Altitude: 1521ft (-10.0ft) Datum: WGS-84 Azimuth/Bearing: 177° S01E 4100mils True (-12°) Elevation Grade: -017% Horizon Grade: +000% Zoom: 2.0X 12005+00 </small> </p>				<p style="text-align: center;">Insert image here</p>	
GPS Location	See Photo	GPS Location			
Field Station#	12005+00	Field Station#			
Pic 9 Desc.	Row conditions at the Spread break.	Pic 10 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/25/2022 1:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36921
Inspector	Eric Hanlon			Date/Time	4/25/2022 6:50 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	56.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Secondary Containment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/25/2022 6:50 AM	Report #	36921
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP at LY 029. The perimeter controls consist of 18" triple stacked CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 028. The perimeter controls CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 026. The perimeter controls CFS functioning as designed. The RCE was clean, no mud or other debris on road. The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/25/2022 6:50 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	CFS perimeter controls functional Permanent stabilization in place y28		Pic 2 Desc.	CFS perimeter controls functional Secondary containment in place y28	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Housekeeping trash in good condition y28		Pic 4 Desc.	RCE functional y28	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	CFS perimeter controls functional y28		Pic 6 Desc.	CFS perimeter controls functional y28	

AFE 124300137		Date/Time	4/25/2022 6:50 AM	Report #	
Pictures					
<p>Date & Time: Mon, Apr 25, 2022, 08:32:44 EDT Position: +037.318128° / -080.658700° (-15.5ft) Altitude: 1808ft (-1.1ft) Datum: WGS-84 Azimuth/Bearing: 248° S48W 6609mils True (-10°) Elevation Angle: +00.9° Horizon Angle: +05.6° Zoom: 1.0X Y26</p> 		<p>Date & Time: Mon, Apr 25, 2022, 08:33:56 EDT Position: +037.318172° / -080.657838° (-15.5ft) Altitude: 1808ft (-1.1ft) Datum: WGS-84 Azimuth/Bearing: 249° S47W 6680mils True (-10°) Elevation Angle: +00.9° Horizon Angle: +05.6° Zoom: 1.0X Y26</p> 			
GPS Location		See photo		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 7 Desc.		CFS perimeter controls functional Permanent stabilization in place y26		Pic 8 Desc.	
				Housekeeping trash in good condition y26	
<p>Date & Time: Mon, Apr 25, 2022, 08:33:27 EDT Position: +037.318680° / -080.657250° (-14.0ft) Altitude: 1804ft (-13.4ft) Datum: WGS-84 Azimuth/Bearing: 248° S48W 6609mils True (-10°) Elevation Angle: +00.9° Horizon Angle: +05.6° Zoom: 1.0X Y26</p> 		<p>Date & Time: Mon, Apr 25, 2022, 08:33:58 EDT Position: +037.318352° / -080.657052° (-14.1ft) Altitude: 1810ft (-6.9ft) Datum: WGS-84 Azimuth/Bearing: 249° S47W 6720mils True (-10°) Elevation Angle: +00.8° Horizon Angle: +01.8° Zoom: 2.0X Y26</p> 			
GPS Location		See photo		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 9 Desc.		Secondary containment in place y26		Pic 10 Desc.	
				Secondary containment in place y26	
<p>Date & Time: Mon, Apr 25, 2022, 08:31:33 EDT Position: +037.318779° / -080.656503° (-14.5ft) Altitude: 1795ft (-13.4ft) Datum: WGS-84 Azimuth/Bearing: 032° N42E 1102mils True (-10°) Elevation Angle: +00.9° Horizon Angle: -02.2° Zoom: 1.0X Y26</p> 		<p>Date & Time: Mon, Apr 25, 2022, 08:32:23 EDT Position: +037.318842° / -080.655531° (-14.2ft) Altitude: 1803ft (-13.4ft) Datum: WGS-84 Azimuth/Bearing: 175° S85E 8150mils True (-10°) Elevation Angle: +00.9° Horizon Angle: +00.3° Zoom: 1.0X Y26</p> 			
GPS Location		See photo		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 11 Desc.		RCE functional y26		Pic 12 Desc.	
				CFS perimeter controls functional y26	

AFE 124300137		Date/Time	4/25/2022 6:50 AM	Report #	
Pictures					
 <p>Date & Time: Mon, Apr 25, 2022, 08:23:17 EDT Position: +037 361113 / -080 679924 (±16.1m) Altitude: 1670ft (±16.2m) Datum: WGS-84 Azimuth Bearing: 300° N14W 615mils True (±10°) Elevation Angle: -02.0° Horizontal Angle: -00.0° Zoom: 2.0X Y29</p>		 <p>Date & Time: Mon, Apr 25, 2022, 08:22:24 EDT Position: +037 360917 / -080 678852 (±16.5m) Altitude: 1670ft (±16.2m) Datum: WGS-84 Azimuth Bearing: 264° S80W 627mils True (±10°) Elevation Angle: -02.0° Horizontal Angle: -02.0° Zoom: 2.0X Y29</p>			
GPS Location		See photo		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 13 Desc.		RCE functional y29		Pic 14 Desc.	
				Broad base dips functional y29	
 <p>Date & Time: Mon, Apr 25, 2022, 08:20:49 EDT Position: +037 362409 / -080 677336 (±16.5m) Altitude: 1710ft (±16.1m) Datum: WGS-84 Azimuth Bearing: 141° S14E 2962mils True (±10°) Elevation Angle: -13.8° Horizontal Angle: -00.6° Zoom: 1.0X Y29</p>		 <p>Date & Time: Mon, Apr 25, 2022, 08:19:54 EDT Position: +037 363436 / -080 676550 (±16.5m) Altitude: 1710ft (±16.1m) Datum: WGS-84 Azimuth Bearing: 141° S14E 3367mils True (±10°) Elevation Angle: -13.8° Horizontal Angle: -00.6° Zoom: 1.0X Y29</p>			
GPS Location		See photo		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 15 Desc.		Culvert functional		Pic 16 Desc.	
		CFS perimeter controls functional y29			
 <p>Date & Time: Mon, Apr 25, 2022, 08:18:48 EDT Position: +037 363136 / -080 676986 (±16.3m) Altitude: 1716ft (±11.4m) Datum: WGS-84 Azimuth Bearing: 308° N52W 5678mils True (±10°) Elevation Angle: -02.6° Horizontal Angle: -00.7° Zoom: 1.0X Y29</p>		 <p>Date & Time: Mon, Apr 25, 2022, 08:18:48 EDT Position: +037 363136 / -080 676986 (±16.3m) Altitude: 1716ft (±11.4m) Datum: WGS-84 Azimuth Bearing: 308° N52W 5678mils True (±10°) Elevation Angle: -02.6° Horizontal Angle: -00.7° Zoom: 1.0X Y29</p>			
GPS Location		See photo		GPS Location	
Field Station#		12005+00		Field Station#	
Pic 17 Desc.		Permanent stabilization in place y29		Pic 18 Desc.	
				CFS perimeter controls functional y29	



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36995
Inspector	David Schoolcraft			Date/Time	4/26/2022 1:23 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10655+00
State	VA	Inspection Area	Full	Station End	10749+92
County	Giles	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/26/2022 1:23 PM	Report #	36995
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental team Accompanied by fellow EI Eric Hanlon preformed VA SWPPP inspection from 10655+00 (MP 201.6) to 10749+92 (MP 203.6) This section of ROW has no current construction. No deficiencies found. All perimeter controls, ECDs and BMPs functional at time of inspection. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	4/26/2022 1:23 PM	Report #	
Pictures					
<p>Date & Time: Tue Apr 26, 2022, 08:46:17 EDT Position: +037 338524 / -080 674714 (±4720 ft) Altitude: 2319ft (±581ft) Datum: WGS-84 Azimuth/Bearing: 328 N32W 5831mils True (±12°) Elevation Angle: +07.9° Horizon Angle: +03.4° Zoom: 0.5X 10656+75</p> 		<p>Date & Time: Tue Apr 26, 2022, 08:46:07 EDT Position: +037 338524 / -080 666432 (±1511ft) Altitude: 2239ft (±170ft) Datum: WGS-84 Azimuth/Bearing: 106° N04E 8301mils True (±2°) Elevation Angle: +11.2° Horizon Angle: +11.8° Zoom: 0.5X 10667+75</p> 			
GPS Location		See Photo		GPS Location	
Field Station#		10656+57		Field Station#	
Pic 1 Desc.		Stabilization		Pic 2 Desc.	
<p>Date & Time: Tue Apr 26, 2022, 09:11:08 EDT Position: +037 338524 / -080 655975 (±116ft) Altitude: 2066ft (±88ft) Datum: WGS-84 Azimuth/Bearing: 053 N53E 0942mils True (±12°) Elevation Angle: +09.0° Horizon Angle: +00.1° Zoom: 0.5X 10678+75</p> 		<p>Date & Time: Tue Apr 26, 2022, 09:11:08 EDT Position: +037 349189 / -080 652947 (±154ft) Altitude: 2066ft (±112ft) Datum: WGS-84 Azimuth/Bearing: 330 N26W 5938mils True (±12°) Elevation Angle: +08.0° Horizon Angle: +01.1° Zoom: 0.5X 10695+00</p> 			
GPS Location		See Photo		GPS Location	
Field Station#		10678+75		Field Station#	
Pic 3 Desc.		Stream overview		Pic 4 Desc.	
<p>Date & Time: Tue Apr 26, 2022, 09:12:42 EDT Position: +037 349189 / -080 661925 (±136ft) Altitude: 2055ft (±126ft) Datum: WGS-84 Azimuth/Bearing: 107° N07E 1527mils True (±12°) Elevation Angle: +01.4° Horizon Angle: +05.4° Zoom: 0.5X 10698+00 S-G32</p> 		<p>Date & Time: Tue Apr 26, 2022, 09:13:08 EDT Position: +037 349189 / -080 661925 (±136ft) Altitude: 2055ft (±126ft) Datum: WGS-84 Azimuth/Bearing: 107° N07E 1527mils True (±12°) Elevation Angle: +26.0° Horizon Angle: +05.4° Zoom: 2.0X 10702+25</p> 			
GPS Location		See Photo		GPS Location	
Field Station#		10698+00		Field Station#	
Pic 5 Desc.		S-G32		Pic 6 Desc.	
				Water bars	

AFE	124300137	Date/Time	4/26/2022 1:23 PM	Report #	
Pictures					
 <p><small>Date & Time: Tue, Apr 26, 2022, 06:58:19 EDT Position: +087.243517° / +080.423156° Lat: 43° Altitude: 2331ft (±1.1ft) Datum: WGS-84 Azimuth/Bearing: 268° S88W 4764mils True (±12°) Elevation Angle: -20.4° Horizon Angle: +01.4° Zoom: 1.0X 10738+00</small></p>		 <p><small>Date & Time: Tue, Apr 26, 2022, 06:58:19 EDT Position: +087.243517° / +080.423156° Lat: 43° Altitude: 2331ft (±1.1ft) Datum: WGS-84 Azimuth/Bearing: 268° S88W 4764mils True (±12°) Elevation Angle: -20.4° Horizon Angle: +01.4° Zoom: 1.0X 10738+00</small></p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10728+00	Field Station#	10738+00		
Pic 7 Desc.	Section of row showing conditions	Pic 8 Desc.	Slope drain		
 <p><small>Date & Time: Tue, Apr 26, 2022, 06:58:19 EDT Position: +087.243517° / +080.423156° Lat: 43° Altitude: 2331ft (±1.1ft) Datum: WGS-84 Azimuth/Bearing: 268° S88W 4764mils True (±12°) Elevation Angle: -20.4° Horizon Angle: +01.4° Zoom: 1.0X 10742+69</small></p>		 <p><small>Date & Time: Tue, Apr 26, 2022, 06:58:19 EDT Position: +087.243517° / +080.423156° Lat: 43° Altitude: 2331ft (±1.1ft) Datum: WGS-84 Azimuth/Bearing: 146° S34W 4764mils True (±12°) Elevation Angle: -20.4° Horizon Angle: +01.4° Zoom: 1.0X 10749+00</small></p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10742+69	Field Station#	10749+00		
Pic 9 Desc.	Equipment bridge	Pic 10 Desc.	RCE		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/26/2022 1:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37006
Inspector	Jared Saunders			Date/Time	4/26/2022 4:35 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10749+92
State	VA	Inspection Area	Partial	Station End	10798+92
County	Giles	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/26/2022 4:35 PM	Report #	37006
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10747+92 (Hendrickson Road) to ST# 10798+92 (Cascade Road) Accompanied by El Pat Shields on SWPPP inspection from MP 204.53 to MP 205.67. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crews walking through section checking ECDs. This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. Sensitive resource buffers are in place at streams S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2. Hendrickson Road, Big Branch Hollow Road, and Cascade Road crossings RCEs are maintained and in acceptable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/26/2022 4:35 PM	Report #	
Pictures					
					
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	10750+00		Field Station#	10753+00	
Pic 1 Desc.	RCE in place at Hendrickson Road.		Pic 2 Desc.	Waterbars in place. ROW temporarily stabilized with seed and mulch.	
					
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	10758+00		Field Station#	10762+00	
Pic 3 Desc.	Sensitive resource buffer in place at stream S-G35.		Pic 4 Desc.	Rock inlet in place at slope drain.	
					
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	10779+00		Field Station#	10793+00	
Pic 5 Desc.	Super silt fence in place along LOD.		Pic 6 Desc.	ROW temporarily stabilized with seed and mulch. Vegetation growth is present.	

A/E	124300137	Date/Time	4/26/2022 4:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/26/2022 4:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	36976
Inspector	Chris Burns			Date/Time	4/26/2022 7:47 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10798+92
State	VA	Inspection Area	Partial	Station End	10859+46
County	Giles	Ground	Dry	Temperature (°F)	68.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/26/2022 7:47 AM	Report #	36976
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46). Accompanied by fellow EI Clint Sears. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Updated SWPPP documents.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	4/26/2022 7:47 AM	Report #	
Pictures					
 <p>Date & Time: Tue, Apr 26, 2022, 09:42:42 EST Position: 108556+04 E / 344749.83 N (+12889.87) Altitude: 2251 ft (+694.41) Datum: WGS-84 Azimuth/Bearing: 35° N 65° E 1087mils True (+12°) Elevation Angle: +11.5° Horizon Angle: +01.2° Zoom: 0.5X 10855+04 S-A33</p>		 <p>Date & Time: Tue, Apr 26, 2022, 09:45:59 EST Position: 10854+70 E / 344810.438 N (+1515.71) Altitude: 2247 ft (+694.41) Datum: WGS-84 Azimuth/Bearing: 35° N 65° W 1087mils True (+12°) Elevation Angle: +11.5° Horizon Angle: +01.0° Zoom: 0.5X 10854+70 S-A34</p>			
GPS Location	1	GPS Location	2		
Field Station#	10856+04	Field Station#	10854+70		
Pic 1 Desc.	S-A33.	Pic 2 Desc.	S-A34.		
 <p>Date & Time: Tue, Apr 26, 2022, 09:43:44 EST Position: 10843+50 E / 338170.34 N (+1615.91) Altitude: 2291 ft (+700.11) Datum: WGS-84 Azimuth/Bearing: 319° N 59° W 558mils True (+12°) Elevation Angle: +35.8° Horizon Angle: +33.8° Zoom: 0.5X 10843+50</p>		 <p>Date & Time: Tue, Apr 26, 2022, 09:43:59 EST Position: 10838+00 E / 338347.117 N (+1625.91) Altitude: 2281 ft (+700.11) Datum: WGS-84 Azimuth/Bearing: 308° N 52° W 524mils True (+12°) Elevation Angle: +32.4° Horizon Angle: +30.4° Zoom: 0.5X 10838+00</p>			
GPS Location	3	GPS Location	4		
Field Station#	10843+50	Field Station#	10838+00		
Pic 3 Desc.	Section of RoW showing conditions and controls.	Pic 4 Desc.	Section of RoW showing conditions and controls.		
 <p>Date & Time: Tue, Apr 26, 2022, 09:43:11 EST Position: 10835+00 E / 338365.247 N (+174.91) Altitude: 2251 ft (+694.41) Datum: WGS-84 Azimuth/Bearing: 344° N 56° W 498mils True (+12°) Elevation Angle: +39.4° Horizon Angle: +39.4° Zoom: 1.0X 10835+00</p>		 <p>Date & Time: Tue, Apr 26, 2022, 09:43:58 EST Position: 10826+00 E / 338377.100 N (+175.91) Altitude: 2530 ft (+780.11) Datum: WGS-84 Azimuth/Bearing: 326° N 51° W 534mils True (+12°) Elevation Angle: +22.4° Horizon Angle: +01.0° Zoom: 0.5X 10826+00</p>			
GPS Location	5	GPS Location	6		
Field Station#	10835+00	Field Station#	10826+00		
Pic 5 Desc.	Section of RoW showing conditions and controls.	Pic 6 Desc.	CWDP outlet protection functional.		

AFE	124300137	Date/Time	4/26/2022 7:47 AM	Report #	
Pictures					
					
GPS Location	7	GPS Location	8		
Field Station#	10809+04	Field Station#	10803+75		
Pic 7 Desc.	S-Z14.	Pic 8 Desc.	Section of RoW showing conditions and controls.		
					
GPS Location	9	GPS Location	10		
Field Station#	10801+52	Field Station#	10799+00		
Pic 9 Desc.	Overview S-Z12/S-Z13.	Pic 10 Desc.	Overview S-Z10/W-Z3/S-Z11.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/26/2022 7:47 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37001
Inspector	Daniel Fortune			Date/Time	4/26/2022 3:09 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10859+46
State	VA	Inspection Area	Partial	Station End	10929+80
County	Giles	Ground	Dry	Temperature (°F)	57.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/26/2022 3:09 PM	Report #	37001
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. - ALL STATION NUMBERS ARE APPROXIMATE - Completed a VA SWPPP inspection from MP 205.67 (10859+46) to MP 207.0 (10929+80). No Deficiencies documented for repairs today. Other deficiencies may be found and documented my other EI's and or contractor staff. No crew activity observed at the time of inspection. This section of row has been adequately stabilized for the winter months. Temporary vegetation is visible with no erosion visible at this time of inspection. The temporary water bars appear to be functioning as intended. Sump pits, water bar end treatments, and temporary slope drain pipes also appear to be functioning as intended with no maintenance required at this time. All other perimeter controls, ECDs and BMPs functional at time of inspection. There are three (3) stream resources within this section of row inspected. No impacts at this time of inspection. S-Y2...10929+43 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional. S-Y3...10927+77 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional. S-A32...10929+43 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/26/2022 3:09 PM	Report #	
Pictures					
<p><small>Date & Time: Tue, Apr 26, 2022 09:24:25 EDT Position: +037.335228° / -080.597095° (+15.2ft) Altitude: 2143ft (+12.6ft) Datum: WGS-84 Azimuth/Bearing: 163° S17E 2698mils True (+12.1) Elevation Grade: -038° Horizon Grade: +001° Zoom: 0.5X 10883+10</small></p> 		<p><small>Date & Time: Tue, Apr 26, 2022 09:24:10 EDT Position: +037.335228° / -080.597095° (+15.2ft) Altitude: 2159ft (+11.9ft) Datum: WGS-84 Azimuth/Bearing: 107° S73E 1902mils True (+12.1) Elevation Grade: -032° Horizon Grade: -002° Zoom: 0.5X 10883+10</small></p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10883+10	Field Station#	10883+10		
Pic 1 Desc.	S-A32 Stream resource and vegetated buffer zones	Pic 2 Desc.	Equipment bridge crossing condition.		
<p><small>Date & Time: Tue, Apr 26, 2022 09:23:42 EDT Position: +037.335228° / -080.597095° (+15.2ft) Altitude: 2163ft (+11.6ft) Datum: WGS-84 Azimuth/Bearing: 277° N81W 4960mils True (+12.1) Elevation Grade: +023° Horizon Grade: +006° Zoom: 0.5X 10882+00</small></p> 		<p><small>Date & Time: Tue, Apr 26, 2022 09:23:40 EDT Position: +037.335228° / -080.626054° (+21426.2ft) Altitude: 5354ft (+63.4ft) Datum: WGS-84 Azimuth/Bearing: 180° S00E 3200mils True (+12.1) Elevation Grade: -003° Horizon Grade: -003° Zoom: 0.5X 10881+00</small></p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10882+00	Field Station#	10881+00		
Pic 3 Desc.	Temporary stabilization of travel lane.	Pic 4 Desc.	Functional water bar throat with CFS checks.		
<p><small>Date & Time: Tue, Apr 26, 2022 09:10:37 EDT Position: +037.335228° / -080.600542° (+122.8ft) Altitude: 2451ft (+58.4ft) Datum: WGS-84 Azimuth/Bearing: 074° N74E 1816mils True (+12.1) Elevation Grade: -035° Horizon Grade: -001° Zoom: 0.5X 10871+00</small></p> 		<p><small>Date & Time: Tue, Apr 26, 2022 09:09:49 EDT Position: +037.335228° / -080.597095° (+15.2ft) Altitude: 2454ft (+52.5ft) Datum: WGS-84 Azimuth/Bearing: 120° S00E 3100mils True (+12.1) Elevation Grade: -019° Horizon Grade: -001° Zoom: 0.5X 10868+32</small></p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10871+00	Field Station#	10868+32		
Pic 5 Desc.	Temporary level spreader with sump pits, slope drain pipes and ECB stabilization.	Pic 6 Desc.	Temporary stabilization of row		

AFE	124300137	Date/Time	4/26/2022 3:09 PM	Report #	
Pictures					
<p>Date & Time: Tue, Apr 26, 2022, 08:43:07 EDT Position: +037.339256° / -080.600198° (+14.0ft) Altitude: 2314ft (+19.7ft) Datum: WGS-84 Azimuth Bearing: 036° NVDL 40°mils True (+12°) Elevation Grade: +00% Horizon Grade: +01% Zoom: 0.5X 10860+00</p> 		<p>Date & Time: Tue, Apr 26, 2022, 08:46:09 EDT Position: +037.331373° / -080.583302° (+11.9ft) Altitude: 2102ft (+13.1ft) Datum: WGS-84 Azimuth Bearing: 238° SSW 42°mils True (+12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 1.5X 10929+70</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10860+00	Field Station#	10929+70		
Pic 7 Desc.	Temporary stabilization of water bar and travel lane conditions.		Pic 8 Desc.	S-Y2 Stream bed conditions	
<p>Date & Time: Tue, Apr 26, 2022, 08:45:38 EDT Position: +037.291217° / -080.430027° (+15.4ft) Altitude: 2110ft (+11.0ft) Datum: WGS-84 Azimuth Bearing: 155° S21E 27°mils True (+12°) Elevation Grade: +040% Horizon Grade: +005% Zoom: 0.5X 10929+70</p> 		<p>Date & Time: Tue, Apr 26, 2022, 08:50:01 EDT Position: +037.287183° / -080.433343° (+16.4ft) Altitude: 2110ft (+13.0ft) Datum: WGS-84 Azimuth Bearing: 159° S21E 22°mils True (+12°) Elevation Grade: +047% Horizon Grade: +005% Zoom: 0.5X 10928+56</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10929+70	Field Station#	10928+56		
Pic 9 Desc.	Equipment bridge condition over the S-Y2 stream resource		Pic 10 Desc.	TLS at the Doe Creek RCE area.	
<p>Date & Time: Tue, Apr 26, 2022, 08:44:50 EDT Position: +037.291217° / -080.433301° (+15.0ft) Altitude: 2083ft (+16.2ft) Datum: WGS-84 Azimuth Bearing: 19° S30W 03°mils True (+12°) Elevation Grade: +01% Horizon Grade: +001% Zoom: 1.0X 10928+56</p> 		<p>Date & Time: Tue, Apr 26, 2022, 08:43:57 EDT Position: +037.331801° / -080.583343° (+19.9ft) Altitude: 2106ft (+39.4ft) Datum: WGS-84 Azimuth Bearing: 202° SSW 41°mils True (+12°) Elevation Grade: +00% Horizon Grade: +000% Zoom: 0.5X 10927+77</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10928+56	Field Station#	10927+77		
Pic 11 Desc.	CWDP to the TLS at the Doe Creek RCE area.		Pic 12 Desc.	S-Y3 vegetated stream bed conditions.	

AFE	124300137	Date/Time	4/26/2022 3:09 PM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10924+00	Field Station#	10924+30		
Pic 13 Desc.	Over view of row stabilization.	Pic 14 Desc.	Steep slope stabilization with functional water bars.		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10909+00	Field Station#	10895+00		
Pic 15 Desc.	Temporary stabilization of row	Pic 16 Desc.	TSP and sump pit conditions.		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	10893+00	Field Station#	10904+00		
Pic 17 Desc.	Temporary stabilization of steep slope	Pic 18 Desc.	Perimeter P1 Silt fencing and stabilization of top subsoil storage.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37058
Inspector	Daniel Fortune			Date/Time	4/27/2022 10:56 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11098+47
County	Giles	Ground	Damp	Temperature (°F)	42.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.03
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/27/2022 10:56 AM	Report #	37058
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. "Station numbers are approximate". Observed Activity: No Activity observed today. This area has been temporarily stabilized and is in a stable repose at this time. The ROW in that area received 0.00" of precipitation in the last 24 hrs. The ROW from AR 244 near 11025+02 to near 11070+21 has been temporarily stabilized. No erosion issues. The ROW from station 11070+21 to near 11098+00 has had final Restoration completed. There are 12" CFS that are being used as water bars (section 6) at this time. There are no erosion issues visible in the final restored areas. The perimeter controls appear to be functional at this time. One area of open ditch (approximately 270') near 11061+00. Rock Road approaches were cleaned and functioning as intended. No sensitive resources have been impacted.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/27/2022 10:56 AM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11078+00		Field Station#	11087+00	
Pic 1 Desc.	Final Restoration Area and current vegetated status.		Pic 2 Desc.	Final Restoration Area. This has been discussed with the contractor. There will be needed re-seeding at this location.	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11098+67		Field Station#	11065+84	
Pic 3 Desc.	AR 245.02 current conditions.		Pic 4 Desc.	Over view of drainage feature and equipment bridge condition.	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11058+00		Field Station#	11050+00	
Pic 5 Desc.	Temporary stabilization of row		Pic 6 Desc.	S-IJ16 and 17 stream resources.	

AFE	124300137	Date/Time	4/27/2022 10:56 AM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11049+92	Field Station#	11043+66		
Pic 7 Desc.	View of temporary water bar and stabilization.	Pic 8 Desc.	Temporary stabilization of steep slopes.		
		<div style="text-align: center;">Insert image here</div>			
GPS Location	See Photo	GPS Location			
Field Station#	11025+23	Field Station#			
Pic 9 Desc.	Over view of the S-IJ 18 stream resource	Pic 10 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/27/2022 10:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37043
Inspector	Jared Saunders			Date/Time	4/27/2022 10:25 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	10929+80
County	Giles	Ground	Dry	Temperature (°F)	50.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.05
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/27/2022 10:25 AM	Report #	37043
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10929+80 (Doe Creek Road) to ST# 11023+80 (Access Road 244) Accompanied by EI Pat Shields on SWPPP inspection from MP 207 to MP 208.78. Station number 11016+75 priority one silt fence stake broken. Item added to the punchlist and communicated to the environmental coordinator Mike Perry via text message. Active construction site; additional deficiencies may be identified by other EIs. This section of ROW is temporarily stabilized with seed and mulch. Minor vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. ROW permanently stabilized from station number 10961+75 to station number 10940+25. Area is stabilized with seed and mulch. Vegetation growth is present. CFS in place to minimize rilling and maintain sheet flow. Sensitive resource buffers are in place at streams S-PA07, S-RR5, S-E24, and S-E25. Triple barrier protection around karst feature located at station number 10966+00. RCEs in place and maintained at Doe Creek Road crossing, Access Road 244, and Access Road 241.02. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		4/27/2022 10:25 AM		Report #			
Pictures											
<p>Date & Time: Wed Apr 27, 2022 09:04:55 EDT Position: -037.323897, -080.554890 (-15.4m) Altitude: 2227ft (-11.3ft) Datum: WGS 84 Azimuth/Bearing: 212 N43W 502mils True (-17) Elevation Angle: -18.5 Horizon Angle: +05.2 Zoom: 1.0X 11019+00</p> 				<p>Date & Time: Wed Apr 27, 2022 09:04:02 EDT Position: -037.323425, -080.554890 (-15.4m) Altitude: 2201ft (-11.4ft) Datum: WGS 84 Azimuth/Bearing: 293 N47W 5209mils True (-19) Elevation Angle: -04.4 Horizon Angle: -02.8 Zoom: 1.0X 11016+00</p> 							
GPS Location		See photo.				GPS Location		See photo.			
Field Station#		11019+00				Field Station#		11016+00			
Pic 1 Desc.		Clean water diversion berm in place.				Pic 2 Desc.		Sensitive resource buffer in place at streams S-PA07 and S-RR5.			
<p>Date & Time: Wed Apr 27, 2022 09:18:31 EDT Position: -037.324026, -080.559423 (-15.4ft) Altitude: 2640ft (-11.3ft) Datum: WGS 84 Azimuth/Bearing: 201 S21W 3573mils True (-18) Elevation Angle: -22.7 Horizon Angle: -02.0 Zoom: 1.0X 11004+00</p> 				<p>Date & Time: Wed Apr 27, 2022 09:07:07 EDT Position: -037.323893, -080.552265 (-15.4ft) Altitude: 2372ft (-11.3ft) Datum: WGS 84 Azimuth/Bearing: 235 N28W 5903mils True (-19) Elevation Angle: -23.5 Horizon Angle: -02.2 Zoom: 1.0X 11016+75</p> 							
GPS Location		See photo.				GPS Location		See photo.			
Field Station#		11004+00				Field Station#		11016+75			
Pic 3 Desc.		Clean water diversion pipe and level spreader in place.				Pic 4 Desc.		Priority one silt fence stake broken at stream S-PA07 buffer.			
<p>Date & Time: Wed Apr 27, 2022 09:41:04 EDT Position: -037.327998, -080.572923 (-15.4ft) Altitude: 2273ft (-11.3ft) Datum: WGS 84 Azimuth/Bearing: 281 N75W 4996mils True (-16) Elevation Angle: -00.8 Horizon Angle: +05.8 Zoom: 1.0X 10961+75</p> 				<p>Date & Time: Wed Apr 27, 2022 09:56:08 EDT Position: -037.331242, -080.532873 (-15.4ft) Altitude: 2124ft (-11.3ft) Datum: WGS 84 Azimuth/Bearing: 277 NW 4653mils True (-16) Elevation Angle: -11.1 Horizon Angle: -04.0 Zoom: 1.0X 10930+25</p> 							
GPS Location		See photo.				GPS Location		See photo.			
Field Station#		10961+75				Field Station#		10930+25			
Pic 5 Desc.		ROW permanently restored.				Pic 6 Desc.		RCE in place at Doe Creek Road.			

A/E	124300137	Date/Time	4/27/2022 10:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/27/2022 10:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37026
Inspector	Chris Burns			Date/Time	4/27/2022 7:12 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11098+47
State	VA	Inspection Area	Partial	Station End	11184+85
County	Giles	Ground	Damp	Temperature (°F)	58.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.05
				Rain Accumulation Time (days)	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/27/2022 7:12 AM	Report #	37026
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85) Accompanied by fellow EI Clint Sears. This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Assessed AR 245.02 and AR 249.02.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		4/27/2022 7:12 AM		Report #							
Pictures															
<p>Date & Time: Wed, Apr 27, 2022, 09:13:57 EDT Position: 1409154.805 E / 343439.191 N (=41.8M) Altitude: 2101ft (=63.9m) Datum: WGS-84 Azimuth/Bearing: 024° N24E 0427mils True (=12°) Elevation Angle: -10.1° Horizon Angle: -04.7° Zoom: 0.5X 11105+00</p> 								<p>Date & Time: Wed, Apr 27, 2022, 09:22:01 EDT Position: 1410204.956 E / 343952.956 N (=45.5M) Altitude: 2055ft (=62.7m) Datum: WGS-84 Azimuth/Bearing: 029° N29E 1496mils True (=12°) Elevation Angle: -10.5° Horizon Angle: -02.4° Zoom: 0.5X 11118+00</p> 							
GPS Location				1				GPS Location				2			
Field Station#				11105+00				Field Station#				11118+00			
Pic 1 Desc.				Section of restored RoW showing conditions and controls.				Pic 2 Desc.				Section of restored RoW showing conditions and controls.			
<p>Date & Time: Wed, Apr 27, 2022, 09:27:59 EDT Position: 1400142.231 E / 347110.147 N (=10262.0M) Altitude: 2038ft (=62.3m) Datum: WGS-84 Azimuth/Bearing: 110° S67E 3003mils True (=12°) Elevation Angle: -48.8° Horizon Angle: -02.2° Zoom: 0.5X 11128+50</p> 								<p>Date & Time: Wed, Apr 27, 2022, 09:29:49 EDT Position: 1411231.308 E / 345565.796 N (=75.5M) Altitude: 1994ft (=60.4m) Datum: WGS-84 Azimuth/Bearing: 022° S88E 1386mils True (=12°) Elevation Angle: -04.5° Horizon Angle: -01.9° Zoom: 0.5X 11133+25</p> 							
GPS Location				3				GPS Location				4			
Field Station#				11128+50				Field Station#				11133+25			
Pic 3 Desc.				Section of restored RoW showing conditions and controls.				Pic 4 Desc.				Representative photo of permanent waterbar and level spreaders installed.			
<p>Date & Time: Wed, Apr 27, 2022, 09:33:18 EDT Position: 1411372.707 E / 345104.685 N (=15.4M) Altitude: 2126ft (=64.8m) Datum: WGS-84 Azimuth/Bearing: 101° S55E 1793mils True (=12°) Elevation Angle: -00.2° Horizon Angle: -05.3° Zoom: 0.5X 11139+25</p> 								<p>Date & Time: Wed, Apr 27, 2022, 09:50:07 EDT Position: 1413440.531 E / 342846.748 N (=16.5M) Altitude: 1897ft (=57.8m) Datum: WGS-84 Azimuth/Bearing: 071° N71E 1262mils True (=12°) Elevation Angle: -23.7° Horizon Angle: -08.7° Zoom: 0.5X 11155+00</p> 							
GPS Location				5				GPS Location				6			
Field Station#				11139+25				Field Station#				11155+00			
Pic 5 Desc.				Section of restored RoW showing conditions and controls.				Pic 6 Desc.				Section of RoW showing conditions and controls.			

AFE	124300137	Date/Time	4/27/2022 7:12 AM	Report #	
Pictures					
					
GPS Location	7	GPS Location	8		
Field Station#	11159+30	Field Station#	11167+00		
Pic 7 Desc.	S-NN17.	Pic 8 Desc.	CWDP outlet protection functional.		
					
GPS Location	9	GPS Location	10		
Field Station#	11177+00	Field Station#	11184+85		
Pic 9 Desc.	Section of restored RoW showing conditions and controls.	Pic 10 Desc.	Section of restored RoW showing conditions and controls.		
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location	11	GPS Location	12		
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/27/2022 7:12 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37035
Inspector	David Schoolcraft			Date/Time	4/27/2022 9:48 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11184+85
State	VA	Inspection Area	Full	Station End	11254+99
County	Giles	Ground	Dry	Temperature (°F)	50.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/27/2022 9:48 AM	Report #	37035
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable				
Level Spreader	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental team Performed VA SWPPP inspection from 11184+85 (MP 211.83) to 11254+99 (MP 213.6) accompanied by fellow EI Eric Hanlon This section of ROW has no current construction. No deficiencies found Water bars (other) All perimeter controls, ECDs and BMPs functional at time of inspection. Stream buffers and controls in place at the time of inspection. 11222+50 to 11206+27 stabilization in restoration is thin and continuing to be monitored by inspection. Was over seeded on 4/12/22 and 4/13/22 No sensitive resources have been impacted					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/27/2022 9:48 AM	Report #	
Pictures					
 <p>Date & Time: Wed, Apr 27, 2022, 07:44:57 EDT Position: +037 305892 / -080 505797 (+14.870) Altitude: 1983ft (+52.9ft) Datum: WGS-84 Azimuth/Bearing: 071 N71E 1262mils True (+12°) Elevation Angle: +14.3 Horizon Angle: -02.1 Zoom: 0.5X 11185+00</p>		 <p>Date & Time: Wed, Apr 27, 2022, 07:44:57 EDT Position: +037 305892 / -080 505797 (+14.870) Altitude: 1983ft (+52.9ft) Datum: WGS-84 Azimuth/Bearing: 108 S32E 1262mils True (+12°) Elevation Angle: +15.0 Horizon Angle: -04.5 Zoom: 0.5X 11189+00</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11185+00	Field Station#	11189+00		
Pic 1 Desc.	Access road and controls	Pic 2 Desc.	Level Spreader		
 <p>Date & Time: Wed, Apr 27, 2022, 07:44:57 EDT Position: +037 305892 / -080 505797 (+14.870) Altitude: 1983ft (+52.9ft) Datum: WGS-84 Azimuth/Bearing: 071 N71E 1262mils True (+12°) Elevation Angle: +14.3 Horizon Angle: -02.1 Zoom: 0.5X 11191+00</p>		 <p>Date & Time: Wed, Apr 27, 2022, 07:50:36 EDT Position: +037 305892 / -080 505797 (+14.870) Altitude: 1983ft (+52.9ft) Datum: WGS-84 Azimuth/Bearing: 080 N80E 1422mils True (+12°) Elevation Angle: +14.6 Horizon Angle: -01.0 Zoom: 0.5X 11196+00</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11191+00	Field Station#	11196+00		
Pic 3 Desc.	Drainage feature	Pic 4 Desc.	Perimeter controls		
 <p>Date & Time: Wed, Apr 27, 2022, 08:01:54 EDT Position: +037 302316 / -080 505409 (+15.1ft) Altitude: 2045ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 328 N32W 5831mils True (+12°) Elevation Angle: +38.4 Horizon Angle: -03.8 Zoom: 0.5X 11211+00</p>		 <p>Date & Time: Wed, Apr 27, 2022, 08:04:00 EDT Position: +037 302316 / -080 505409 (+15.1ft) Altitude: 2045ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 328 N32W 5831mils True (+12°) Elevation Angle: +38.4 Horizon Angle: -03.8 Zoom: 0.5X 11232+00</p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11211+00	Field Station#	11232+00		
Pic 5 Desc.	Monitoring restoration growth was over seeded 15 days ago	Pic 6 Desc.	Section of ROW showing conditions and controls		

AFE	124300137	Date/Time	4/27/2022 9:48 AM	Report #	
Pictures					
 <p><small>Date & Time: Wed, Apr 27, 2022, 08:29:00 EDT Position: +037 296842 / -080 494871 (±110.3M) Altitude: 1977ft (±157.5M) Datum: WGS 84 Azimuth Bearing: 102° N58W 5369mils True (±12.9) Elevation Angle: ±0.0° Horizon Angle: ±0.0° Zoom: 0.5X 11252+00</small></p>		 <p><small>Date & Time: Wed, Apr 27, 2022, 08:29:00 EDT Position: +037 296842 / -080 494871 (±110.3M) Altitude: 1977ft (±157.5M) Datum: WGS 84 Azimuth Bearing: 102° N58W 5369mils True (±12.9) Elevation Angle: ±0.0° Horizon Angle: ±0.0° Zoom: 0.5X 11252+00</small></p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11245+00	Field Station#	11252+00		
Pic 7 Desc.	Water bars	Pic 8 Desc.	Perimeter controls CFS		
 <p><small>Date & Time: Wed, Apr 27, 2022, 09:32:56 EDT Position: +037 295449 / -080 494442 (±137.8M) Altitude: 1928ft (±146.9M) Datum: WGS 84 Azimuth Bearing: 262° S62W 6302mils True (±12.1) Elevation Angle: ±11.9° Horizon Angle: ±0.0° Zoom: 0.5X 11254+58</small></p>		<p style="text-align: center;">Insert image here</p>			
GPS Location	See Photo	GPS Location			
Field Station#	11254+58	Field Station#			
Pic 9 Desc.	Stream over view	Pic 10 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/27/2022 9:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37098
Inspector	David Schoolcraft			Date/Time	4/28/2022 1:00 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Full	Station End	11600+01
County	Craig	Ground	Dry	Temperature (°F)	62.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/28/2022 1:00 PM	Report #	37098
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental team Preformed VA SWPPP inspection from 11524+16 (MP 218.26) to 11600+01 (MP 219.70) accompanied by fellow EI Eric Hanlon This section of ROW has no current construction. No deficiencies found. Water bars (other) All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/28/2022 1:00 PM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	1152+67	Field Station#	11531+00		
Pic 1 Desc.	Silt Fence	Pic 2 Desc.	Level Spreader		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11543+00	Field Station#	11585+48		
Pic 3 Desc.	Section of ROW showing conditions and controls	Pic 4 Desc.	S-PP21		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11588+41	Field Station#	11593+00		
Pic 5 Desc.	S-PP20	Pic 6 Desc.	Perimeter controls		

A/E	124300137	Date/Time	4/28/2022 1:00 PM	Report #	
Pictures					
 <p><small>Date & Time: Tue Apr 28, 2022 09:05:57 EDT Position: -097.513927 / -090.426372 / +15.311 Altitude: 1842ft (562.4m) Datum: WGS 84 / 1.5 / 2.0 Azimuth/Bearing: 088.18deg / Azimuth/True: 82.2° Horizontal Angle: 0.0° Horizontal Angle: 0.1° Zoom: 1.0x 11599+00</small></p>		 <p><small>Date & Time: Tue Apr 28, 2022 09:05:57 EDT Position: -097.513927 / -090.426372 / +15.311 Altitude: 1842ft (562.4m) Datum: WGS 84 / 1.5 / 2.0 Azimuth/Bearing: 088.18deg / Azimuth/True: 82.2° Horizontal Angle: 0.0° Horizontal Angle: 0.1° Zoom: 1.0x 11600+01</small></p>			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11599+00	Field Station#	11600+01		
Pic 7 Desc.	Sump Pit	Pic 8 Desc.	RCE		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/28/2022 1:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37109
Inspector	Daniel Fortune			Date/Time	4/28/2022 4:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Damp	Temperature (°F)	47.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/28/2022 4:41 PM	Report #	37109
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
Comments (Reference above questions as appropriate.) Completed a Virginia SWPP inspection from station # 11254+99 to 11353+67 (MP 213.6-215.04) Rte 42 to Old Furnace Rd. Fellow EI Joe Sweeden assisted in the inspection today. No Deficiencies observed or documented for repairs today. "Station numbers are approximate." Observances: Environmental crew 1709 was on site near even Oaks continuing with temporary stabilization. The ROW has been temporarily stabilized and remains at a stable repose. No erosion issues at this time. There is slightly visible temporary grasses throughout the areas of inspection. Karst areas have been previously assumed in sump locations near station 11348+00 and near station 11349+77. These sumps are protected with additional ECDs. The water bars and compost sock remain in a functional condition in these areas as well as all other areas of inspection. Steep slopes have erosion control fabric (CC4) installed. There is limited visible growth where the CC4 ECB have been installed. The limited vegetation is presumed to return during the spring of 2022. There may be areas needing to be re-seeded. Slope drains are functioning as intended without issues. Stone inlet protections are also functional at this time. There are three stream resources in the areas of inspection. Conditions are as follows: S-MM18 - near 11292+80 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required. S-NN12 - near 11327+80 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required. S-NN11 - near 11352+97 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required. All perimeter controls, ECDs and BMPs were functional at time of inspection. No other crews were working in the area. Rock Road approaches and access roads are clean and free of loose rock and debris.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/28/2022 4:41 PM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11353+50		Field Station#	11352+72	
Pic 1 Desc.	AR 256.02 and RCE conditions.		Pic 2 Desc.	S-NN11 Over view of the stream resource, and the equipment bridge condition.	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11345+00		Field Station#	11336+40	
Pic 3 Desc.	Temporary stabilization of row and P1 silt fencing prior to the presumed Karst sump pit area.		Pic 4 Desc.	View of repaired fence gap and row stabilization.	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11328+00		Field Station#	11313+50	
Pic 5 Desc.	S-NN12 Vegetated Buffer zones.		Pic 6 Desc.	Water bar end treatment, Perimeter P1 silt fencing, super silt fencing conditions.	

AFE	124300137	Date/Time	4/28/2022 4:41 PM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11312+00	Field Station#	11293+05		
Pic 7 Desc.	Row stabilization	Pic 8 Desc.	Vegetated S-MM18 stream buffer zones. Soil disturbance from on site environmental crew traffic.		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11269+80	Field Station#	11259+00		
Pic 9 Desc.	Stone inlet protection	Pic 10 Desc.	Steep slope stabilization with CC4.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/28/2022 4:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37112
Inspector	Jared Saunders			Date/Time	4/28/2022 5:29 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11471+52
State	VA	Inspection Area	Partial	Station End	11524+16
County	Craig	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/28/2022 5:29 PM	Report #	37112
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11471+56 (Steele Acres) to ST# 11524+16 (258.02) Accompanied by El Pat Shields on SWPPP inspection from MP 217.26 to MP 218.26. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection, Perimeter controls, and waterbars with end treatments are in place Triple protection ECDs are in place at karst feature. Sensitive resource buffers are in place at stream crossings S-PP3, and S-PP4. AR-258.01, 258.02, and Stever's Gap road crossing RCEs are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 4/28/2022 5:29 PM	Report #
Pictures			
			
GPS Location	See photo.	GPS Location	See photo.
Field Station#	11472+00	Field Station#	11476+00
Pic 1 Desc.	Triple barrier ECDs in place at off ROW karst area.	Pic 2 Desc.	Stone inlet in place at slope drain pipe.
			
GPS Location	See photo.	GPS Location	See photo.
Field Station#	11487+00	Field Station#	11504+00
Pic 3 Desc.	Clean water diversion pipe and plunge pool in place.	Pic 4 Desc.	Rock lined channel in place.
			
GPS Location	See photo.	GPS Location	See photo.
Field Station#	11514+00	Field Station#	11518+00
Pic 5 Desc.	Slope drain in place over fill slope.	Pic 6 Desc.	Sensitive resource buffer in place at stream S-PP4.

A/E	124300137	Date/Time	4/28/2022 5:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/28/2022 5:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37089
Inspector	Chris Burns			Date/Time	4/28/2022 8:20 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+67
State	VA	Inspection Area	Partial	Station End	11471+56
County	Giles	Ground	Dry	Temperature (°F)	62.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/28/2022 8:20 AM	Report #	37089
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56). This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Assessed Steele Acres access.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/28/2022 8:20 AM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11469+00	Field Station#	11451+87		
Pic 1 Desc.	Section of RoW showing conditions and controls.	Pic 2 Desc.	S-0012.		
					
GPS Location	3	GPS Location	4		
Field Station#	11451+08	Field Station#	11448+93		
Pic 3 Desc.	S-0013.	Pic 4 Desc.	S-0014/W-CD12.		
					
GPS Location	5	GPS Location	6		
Field Station#	11438+75	Field Station#	11432+00		
Pic 5 Desc.	Section of restored RoW showing conditions and controls.	Pic 6 Desc.	Representative photo of permanent waterbar and level spreaders installed.		

AFE	124300137	Date/Time	4/28/2022 8:20 AM	Report #	
Pictures					
					
GPS Location	7	GPS Location	8		
Field Station#	11413+00	Field Station#	11397+00		
Pic 7 Desc.	Section of restored RoW showing conditions and controls.	Pic 8 Desc.	Section of restored RoW showing conditions and controls.		
					
GPS Location	9	GPS Location	10		
Field Station#	11381+00	Field Station#	11367+00		
Pic 9 Desc.	Section of restored RoW showing conditions and controls.	Pic 10 Desc.	Section of restored RoW showing conditions.		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	11	GPS Location			
Field Station#	11360+54	Field Station#			
Pic 11 Desc.	S-KL43.	Pic 12 Desc.			

A/E	124300137	Date/Time	4/28/2022 8:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37156
Inspector	Daniel Fortune			Date/Time	4/29/2022 6:27 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+89
State	VA	Inspection Area	Partial	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	55.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/29/2022 6:27 PM	Report #	37156
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>See photos for GPS coordinates.</p> <p>Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). Fellow EI Joe Sweeden assisted in the inspection today. There had been no rain fall accumulation in the last 24 hours. The row is well vegetated and no erosion issues at this time.</p> <p>No Deficiencies documented for repairs today.</p> <p>This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time.</p> <p>Permanent water bars have been installed and appear to be functioning as intended. (Other in section 6 above).</p> <p>Level Spreaders are functional</p> <p>Precision Crews: No crews observed on site.</p> <p>All other perimeter controls, ECDs and BMPs are weathered but appear to be functional at time of inspection. Vegetation or stabilization sufficient.</p> <p>No impact to sensitive resources observed. Assessed Ar 266.03. No issues</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/29/2022 6:27 PM	Report #	
Pictures					
<p>Date & Time: Fri, Apr 29, 2022, 06:27:00 Position: +37.92353° / -89.20639° (s13.57) Altitude: 1221 (s13.57) Datum: WGS-84 Azimuth/Bearing: 05° N74E 1316mils True (s13°) Elevation Grade: -61.2% Horizon Grade: -005% Zoom: 1.0X 11991+00</p> 		<p>Date & Time: Fri, Apr 29, 2022, 06:27:00 Position: +37.92353° / -89.20639° (s13.57) Altitude: 1221 (s13.57) Datum: WGS-84 Azimuth/Bearing: 07° N74E 1316mils True (s13°) Elevation Grade: -62.2% Horizon Grade: -005% Zoom: 1.0X 11978+00</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11991+00	Field Station#	11978+00		
Pic 1 Desc.	Final Restoration Area near the spread break.	Pic 2 Desc.	Final Restoration Area		
<p>Date & Time: Fri, Apr 29, 2022, 06:30:00 Position: +37.92353° / -89.20639° (s13.57) Altitude: 1712 (s13.57) Datum: WGS-84 Azimuth/Bearing: 34° N74E 1316mils True (s13°) Elevation Grade: -000% Horizon Grade: -004% Zoom: 1.0X 11971+00</p> 		<p>Date & Time: Fri, Apr 29, 2022, 06:30:00 Position: +37.92353° / -89.20639° (s13.57) Altitude: 2130 (s13.57) Datum: WGS-84 Azimuth/Bearing: 122° N74E 1316mils True (s13°) Elevation Grade: -024% Horizon Grade: -004% Zoom: 1.0X 11946+69</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11971+00	Field Station#	11946+69		
Pic 3 Desc.	Permanent vegetated steep slope area. (Final Restoration Area).	Pic 4 Desc.	Final Restoration Area and vegetated water bar conditions. Water bars functioning as intended		
<p>Date & Time: Fri, Apr 29, 2022, 06:40:00 Position: +37.92353° / -89.20639° (s13.57) Altitude: 2130 (s13.57) Datum: WGS-84 Azimuth/Bearing: 158° S22E 2809mils True (s12°) Elevation Grade: -038% Horizon Grade: -003% Zoom: 1.0X 11946+69</p> 		<p>Date & Time: Fri, Apr 29, 2022, 06:40:00 Position: +37.92353° / -89.20639° (s13.57) Altitude: 2130 (s13.57) Datum: WGS-84 Azimuth/Bearing: 045° N74E 1316mils True (s13°) Elevation Grade: -015% Horizon Grade: -001% Zoom: 1.0X 11944+10</p> 			
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11946+69	Field Station#	11944+10		
Pic 5 Desc.	Final Restoration Area with yearling re-growth over the ditch line.	Pic 6 Desc.	Final Restoration Area with perimeter P1 silt fencing conditions.		

AFE	124300137	Date/Time	4/29/2022 6:27 PM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11943+00	Field Station#	11939+66		
Pic 7 Desc.	Perimeter E&S controls to the presumed off LOD sensitive resource area.	Pic 8 Desc.	P1 Silt fencing and permanent vegetation.		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11924+00	Field Station#	11907+00		
Pic 9 Desc.	Permanent level spreader condition	Pic 10 Desc.	Final Restoration Area		
		<div>Insert image here</div>			
GPS Location	See Photo	GPS Location			
Field Station#	11900+81	Field Station#			
Pic 11 Desc.	AR 266.03 and vegetated water bar and row conditions.	Pic 12 Desc.			

A/E	124300137	Date/Time	4/29/2022 6:27 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37128
Inspector	Chris Burns			Date/Time	4/29/2022 8:02 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+52
County	Montgomery	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/29/2022 8:02 AM	Report #	37128
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 221.02 (11670+00) and MP 223.27 (11788+52). Accompanied by fellow EI Clint Sears. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/29/2022 8:02 AM	Report #	
Pictures					
 <p>Date & Time: Fri, Apr 29, 2022, 08:42:47 EDT Position: 11672+00 E / 353330.330 N (±15.51) Altitude: 2354.01 (±11.25) Datum: WGS-84 Azimuth/Bearing: 180° 333E 3701mils True (±12°) Elevation Angle: -17.8° Horizon Angle: -63.8° Zoom: 0.5X 11672+00</p>		 <p>Date & Time: Fri, Apr 29, 2022, 08:53:59 EDT Position: 11687+42 S / 357282.945 N (±15.47) Altitude: 2420.00 (±11.25) Datum: WGS-84 Azimuth/Bearing: 210° 530W 3733mils True (±12°) Elevation Angle: -21.6° Horizon Angle: -05.9° Zoom: 0.5X 11687+42 S-MN21</p>			
GPS Location	1	GPS Location	2		
Field Station#	11672+00	Field Station#	11687+42		
Pic 1 Desc.	Section of RoW showing conditions and controls.	Pic 2 Desc.	S-MN21.		
 <p>Date & Time: Fri, Apr 29, 2022, 09:05:46 EDT Position: 11696+00 E / 353330.780 N (±15.49) Altitude: 2354.01 (±11.25) Datum: WGS-84 Azimuth/Bearing: 180° 333E 3701mils True (±12°) Elevation Angle: -17.8° Horizon Angle: -63.8° Zoom: 0.5X 11696+00</p>		 <p>Date & Time: Fri, Apr 29, 2022, 09:10:31 EDT Position: 11704+10 S / 355630.670 N (±15.47) Altitude: 2437.00 (±11.25) Datum: WGS-84 Azimuth/Bearing: 042° N42E 0747mils True (±12°) Elevation Angle: -15.3° Horizon Angle: -01.1° Zoom: 0.5X 11704+10 S-MN22</p>			
GPS Location	3	GPS Location	4		
Field Station#	11696+00	Field Station#	11704+10		
Pic 3 Desc.	CFS perimeter controls functional.	Pic 4 Desc.	S-MN22.		
 <p>Date & Time: Fri, Apr 29, 2022, 09:06:50 EDT Position: 11710+00 E / 353329.230 N (±15.51) Altitude: 2353.01 (±11.25) Datum: WGS-84 Azimuth/Bearing: 180° 334E 3693mils True (±12°) Elevation Angle: -17.8° Horizon Angle: -63.8° Zoom: 0.5X 11710+00</p>		 <p>Date & Time: Fri, Apr 29, 2022, 09:20:45 EDT Position: 11740+55 S / 355826.150 N (±15.47) Altitude: 2410.00 (±11.25) Datum: WGS-84 Azimuth/Bearing: 131° 349E 1029mils True (±12°) Elevation Angle: -20.0° Horizon Angle: -01.3° Zoom: 0.5X 11740+55 EF65</p>			
GPS Location	5	GPS Location	6		
Field Station#	11710+00	Field Station#	11740+55		
Pic 5 Desc.	Section of RoW showing conditions and controls.	Pic 6 Desc.	S-EF65.		

AFE	124300137	Date/Time	4/29/2022 8:02 AM	Report #	
Pictures					
GPS Location	7		GPS Location	8	
Field Station#	11743+97		Field Station#	11752+00	
Pic 7 Desc.	S-EF62.		Pic 8 Desc.	Section of RoW showing conditions and controls.	
GPS Location	9		GPS Location	10	
Field Station#	11775+00		Field Station#	11767+64	
Pic 9 Desc.	Section of RoW showing conditions and controls.		Pic 10 Desc.	S-IJ52/W-IJ46.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300137	Date/Time	4/29/2022 8:02 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37154
Inspector	Jared Saunders			Date/Time	4/29/2022 4:31 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Full	Station End	11899+80
County	Montgomery	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/29/2022 4:31 PM	Report #	37154
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Level Spreader	Acceptable				
Other	Acceptable				
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) Accompanied by El Pat Shields on SWPPP inspection from MP 223.27 to MP 225.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crews actively working on this section of ROW at time of inspection. Crew was removing remaining ECDs from station number 11855+00 to 11830+00. This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) and level spreaders in place where designated on E&S sheets. Majority of perimeter controls have been removed due to final restoration vegetation growth. Sensitive resource buffers are in place at pond P-KL2. Mount Tabor road crossing RCE is maintained and in acceptable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	4/29/2022 4:31 PM	Report #	
Pictures					
					
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	11892+00		Field Station#	11864+00	
Pic 1 Desc.	Waterbar and level spreader in place.		Pic 2 Desc.	Sensitive resource buffer in place at P-KL2.	
					
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	11836+00		Field Station#	11830+00	
Pic 3 Desc.	Environmental crew mulching and seeding perimeter where ECDs were removed.		Pic 4 Desc.	Waterbars and level spreaders in place.	
					
GPS Location	See photo.		GPS Location	See photo.	
Field Station#	11819+00		Field Station#	11789+00	
Pic 5 Desc.	ROW permanently restored.		Pic 6 Desc.	RCE in place at Mount Tabor Road crossing.	

A/E	124300137	Date/Time	4/29/2022 4:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	4/29/2022 4:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37138
Inspector	Rob Robertson			Date/Time	4/29/2022 10:20 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Dry	Temperature (°F)	49.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	4/29/2022 10:20 AM	Report #	37138
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a regular scheduled VADEQ SWPPP inspection on JNF and private property at Brush Mountain. The ROW is currently stable with adequate grasses and or mulch to hold soils. No rilling of surface or slips of cuts was located. ECDs are in place with no maintenance needs identified today. Resource buffers are stable with no impact occurring to streams. Slope breakers are in place and functioning as designed. Sumps and end treatments are in good condition. RCEs and access road at 11613+69 are in good condition with ECDs in place. No environmental concerns were identified today.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 4/29/2022 10:20 AM		Report #			
Pictures							
 <p>Date & Time: Fri, Apr 29, 2022, 06:16:14 EDT Position: +037.305367, -080.394564 (+30.0m) Altitude: 845m (+30.0m) Datum: WGS-84 Azimuth/Bearing: 181° S09E 340km/mils Magnetic (+12°) Elevation Angle: +00.2° Horizon Angle: -09.4° Zoom: 1.0X 11670+00</p>		 <p>Date & Time: Fri, Apr 29, 2022, 08:24:55 EDT Position: +037.306752, -080.398105 (+10.0m) Altitude: 825m (+10.0m) Datum: WGS-84 Azimuth/Bearing: 201° S61W 428km/mils Magnetic (+12°) Elevation Angle: +00.3° Horizon Angle: -09.4° Zoom: 1.0X 11665+00</p>					
GPS Location		On photo		GPS Location		On photo	
Field Station#		11670+00		Field Station#		11664+00	
Pic 1 Desc.		Stable conditions at top of Brush Mountain. No evidence of vandalism observed.		Pic 2 Desc.		Perimeter ECDs are in acceptable condition and functional.	
 <p>Date & Time: Fri, Apr 29, 2022, 08:37:05 EDT Position: +037.305366, -080.394564 (+24.0m) Altitude: 785m (+3.0m) Datum: WGS-84 Azimuth/Bearing: 309° N51W 549km/mils Magnetic (+12°) Elevation Angle: +21.4° Horizon Angle: -04.0° Zoom: 1.0X 11659+00</p>		 <p>Date & Time: Fri, Apr 29, 2022, 08:46:55 EDT Position: +037.309026, -080.397927 (+10.0m) Altitude: 677m (+26.0m) Datum: WGS-84 Azimuth/Bearing: 006° N04E 007km/mils Magnetic (+11°) Elevation Angle: +24.8° Horizon Angle: +02.4° Zoom: 1.0X 11646+00</p>					
GPS Location		On photo		GPS Location		On photo	
Field Station#		11659+00		Field Station#		11646+00	
Pic 3 Desc.		Sumps and end treatments are functional.		Pic 4 Desc.		Perimeter ECDs are adequate at this time.	
 <p>Date & Time: Fri, Apr 29, 2022, 08:48:33 EDT Position: +037.307285, -080.397690 (+5.0m) Altitude: 623m (+8.0m) Datum: WGS-84 Azimuth/Bearing: 276° N54W 490km/mils Magnetic (+13°) Elevation Angle: +40.7° Horizon Angle: -02.4° Zoom: 1.0X 11645+00</p>		 <p>Date & Time: Fri, Apr 29, 2022, 08:51:55 EDT Position: +037.312622, -080.397690 (+30.0m) Altitude: 578m (+32.0m) Datum: WGS-84 Azimuth/Bearing: 130° S08E 231km/mils Magnetic (+13°) Elevation Angle: +00.3° Horizon Angle: +00.2° Zoom: 1.0X 11627+00</p>					
GPS Location		On photo		GPS Location		On photo	
Field Station#		11645+00		Field Station#		11627+50	
Pic 5 Desc.		End treatments are functional at this time.		Pic 6 Desc.		Perimeter ECDs are in good condition.	

AFE	124300137	Date/Time	4/29/2022 10:20 AM	Report #	
Pictures					
GPS Location	On photo	GPS Location	On photo		
Field Station#	11626+04	Field Station#	11614+20		
Pic 7 Desc.	The S-HH18 crossing is stable.	Pic 8 Desc.	The S-RR14 crossing is stable.		
		<div style="text-align: center;">Insert image here</div>			
GPS Location	On photo	GPS Location			
Field Station#	11608+17	Field Station#			
Pic 9 Desc.	The S-006 crossing is stable.	Pic 10 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	4/29/2022 10:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	37126
Inspector	Eric Hanlon			Date/Time	4/29/2022 7:44 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	51.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Broad-Based Dip	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Secondary Containment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	4/29/2022 7:44 AM	Report #	37126
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP at LY 029. The perimeter controls consist of 18" triple stacked CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 028. The perimeter controls CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 026. The perimeter controls CFS functioning as designed. The RCE was clean, no mud or other debris on road. The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		4/29/2022 7:44 AM		Report #			
Pictures											
											
GPS Location		See photo				GPS Location		See photo			
Field Station#		12005+00				Field Station#		12005+00			
Pic 1 Desc.		Picture showing condition of y28				Pic 2 Desc.		Housekeeping trash in good condition y28			
											
GPS Location		See photo				GPS Location		See photo			
Field Station#		12005+00				Field Station#		12005+00			
Pic 3 Desc.		CFS perimeter controls functional y28				Pic 4 Desc.		RCE functional y28			
											
GPS Location		See photo				GPS Location		See photo			
Field Station#		12005+00				Field Station#		12005+00			
Pic 5 Desc.		CFS perimeter controls functional y28				Pic 6 Desc.		CFS perimeter controls functional y28			

AFE	124300137	Date/Time	4/29/2022 7:44 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 7 Desc.	RCE functional y29	Pic 8 Desc.	Broad base dips functional y29		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 9 Desc.	Culvert functional y29	Pic 10 Desc.	Housekeeping in good condition y29		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 11 Desc.	Permanent stabilization in place y29	Pic 12 Desc.	CFS perimeter controls functional y29		

AFE	124300137	Date/Time	4/29/2022 7:44 AM	Report #	
Pictures					
<p><small>Date & Time Fri, Apr 29, 2022 06:14:42 EDT Position: +37.319381° / -80.48977° (+18.41) Altitude: 1795ft (+11.30) Datum: WGS-84 Azimuth/Bearing: 30°/30°W 400mils True (+10°) Declination Angle: +0.1° Horizon Angle: +0.2° Zoom: 1.0X Y26</small></p> 		<p><small>Date & Time Fri, Apr 29, 2022 06:14:42 EDT Position: +37.319381° / -80.48977° (+18.41) Altitude: 1795ft (+11.30) Datum: WGS-84 Azimuth/Bearing: 30°/30°W 400mils True (+10°) Declination Angle: +0.1° Horizon Angle: +0.2° Zoom: 1.0X Y26</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 13 Desc.	Permanent stabilization in place y26	Pic 14 Desc.	CFS perimeter controls functional y26		
<p><small>Date & Time Fri, Apr 29, 2022 06:14:42 EDT Position: +37.319381° / -80.48977° (+18.41) Altitude: 1795ft (+11.30) Datum: WGS-84 Azimuth/Bearing: 30°/30°W 400mils True (+10°) Declination Angle: +0.1° Horizon Angle: +0.2° Zoom: 1.0X Y26</small></p> 		<p><small>Date & Time Fri, Apr 29, 2022 06:14:42 EDT Position: +37.319381° / -80.48977° (+18.41) Altitude: 1795ft (+11.30) Datum: WGS-84 Azimuth/Bearing: 30°/30°W 400mils True (+10°) Declination Angle: +0.1° Horizon Angle: +0.2° Zoom: 1.0X Y26</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 15 Desc.	Housekeeping in good condition y26	Pic 16 Desc.	Secondary containment in place y26		
<p><small>Date & Time Fri, Apr 29, 2022 06:14:42 EDT Position: +37.319381° / -80.48977° (+18.41) Altitude: 1795ft (+11.30) Datum: WGS-84 Azimuth/Bearing: 30°/30°W 400mils True (+10°) Declination Angle: +0.1° Horizon Angle: +0.2° Zoom: 2.0X Y26</small></p> 		<p><small>Date & Time Fri, Apr 29, 2022 06:14:42 EDT Position: +37.319381° / -80.48977° (+18.41) Altitude: 1795ft (+11.30) Datum: WGS-84 Azimuth/Bearing: 30°/30°W 400mils True (+10°) Declination Angle: +0.1° Horizon Angle: +0.2° Zoom: 1.0X Y26</small></p> 			
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 17 Desc.	Secondary containment in place y26	Pic 18 Desc.	RCE functional y26		