



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37174
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	5/2/2022 7:11 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+46
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/2/2022 7:11 AM	<b>Report #</b>	37174
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed Virginia SWPP inspection from station # 10859+46-10929+80.(MP 205.67-207.00) Kow Camp gravel to Doe Creek, with El Daniel Fortune. No deficiencies found: The ROW receives 0.30" of precipitation over the weekend. The ROW was damp. Observances: Vegetation is growing. S-A 32 was flowing water. Environmental controls at water bodies are in place and functioning as designed. The ROW has been temporarily stabilized. There are areas of ditch subsidence, from station # 10875+00-10880+00 and 10896+00-10899+00. These areas are being monitored and will need repaired, when conditions allow. Precision has been made aware. Soil piles are stabilized. No trash on the ROW. No sensitive resources were impacted. All perimeter controls, ECDs and BMPs were functional at time of inspection. Rock Road approaches are clean and free of loose rock.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		5/2/2022 7:11 AM		Report #			
Pictures											
											
GPS Location		See photo				GPS Location		see photo			
Field Station#		10929+00				Field Station#		10928+00			
Pic 1 Desc.		SY 2				Pic 2 Desc.		SY 3			
											
GPS Location		see photo				GPS Location		see photo			
Field Station#		10910+00				Field Station#		108770+01			
Pic 3 Desc.		Stabilized ROW				Pic 4 Desc.		Water bars/stabilized soil piles			
											
GPS Location		see photo				GPS Location		see photo			
Field Station#		10899+00				Field Station#		10883+10			
Pic 5 Desc.		Perimeter controls/ temporary vegetation				Pic 6 Desc.		SA 32			



<b>AFE</b>	124300137	<b>Date/Time</b>	5/2/2022 7:11 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Mon, May 02, 2022, 09:01:45 EDT Position: +037.36220° / -080.600431° (-15.4m) Altitude: 2460ft (-11.0m) Datum: WGS-84 Azimuth/Bearing: 058° N88E 1031mils True (-12) Elevation/Angle: -002° Horizon Grade: +006% Zoom: 0.5X 10871+00</small></p>		 <p><small>Date &amp; Time: Mon, May 02, 2022, 08:51:42 EDT Position: +037.36220° / -080.597631° (-15.4m) Altitude: 2310ft (-1.0m) Datum: WGS-84 Azimuth/Bearing: 310° N88W 551mils True (-12) Elevation/Angle: -28.8° Horizon Grade: -005° Zoom: 0.5X 10890+00 Spread 6</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	10871+00	<b>Field Station#</b>	10890+00		
<b>Pic 7 Desc.</b>	Level spreader	<b>Pic 8 Desc.</b>	Water bars		
 <p><small>Date &amp; Time: Mon, May 02, 2022, 09:01:15 EDT Position: +037.36220° / -080.600431° (-15.4m) Altitude: 2460ft (-11.0m) Datum: WGS-84 Azimuth/Bearing: 284° N76W 5049mils True (-12) Elevation/Angle: -009° Horizon Grade: -008% Zoom: 1.0X 10870+00</small></p>				Insert image here	
<b>GPS Location</b>	see photo	<b>GPS Location</b>			
<b>Field Station#</b>	10870+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Stabilized ROW	<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/2/2022 7:11 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37179
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/2/2022 7:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10749+92
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

### 5. Site Conditions


Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/2/2022 7:40 AM	<b>Report #</b>	37179
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed aVA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). No Compliance issues noted: Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/2/2022 7:40 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10712+73	<b>Field Station#</b>	10703+00		
<b>Pic 1 Desc.</b>	Equipment bridge functional	<b>Pic 2 Desc.</b>	Water bars in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10698+00	<b>Field Station#</b>	10728+00		
<b>Pic 3 Desc.</b>	Equipment bridge functional	<b>Pic 4 Desc.</b>	Temporary stabilization in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10693+25	<b>Field Station#</b>	10733+00		
<b>Pic 5 Desc.</b>	Wattles in place	<b>Pic 6 Desc.</b>	P1 and wattles in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/2/2022 7:40 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Mon, May 02, 2022, 09:05:38 EDT Position: +037.350325 / -080.658185 / +126.4m Altitude: 2056ft (+39.4m) Datum: WGS-84 Azimuth/Bearing: 289° S89W 4782mils True (+12°) Elevation Angle: +16.2° Horizon Angle: +03.0° Zoom: 1.0X 10679+29</small></p>		 <p><small>Date &amp; Time: Mon, May 02, 2022, 09:01:19 EDT Position: +037.350657 / -080.655924 / +18.4m Altitude: 2168ft (+26.2m) Datum: WGS-84 Azimuth/Bearing: 109° S71E 1108mils True (+8.1°) Elevation Angle: +24.1° Horizon Angle: +00.6° Zoom: 1.0X 10675+10</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10679+29	<b>Field Station#</b>	10675+10		
<b>Pic 7 Desc.</b>	Resource buffers in place	<b>Pic 8 Desc.</b>	Erosion control blanket in		
 <p><small>Date &amp; Time: Mon, May 02, 2022, 08:57:15 EDT Position: +037.348275 / -080.634647 / +132.3m Altitude: 3000ft (+91.0m) Datum: WGS-84 Azimuth/Bearing: 140° S10E 2900mils True (+12°) Elevation Angle: +02.0° Horizon Angle: +01.0° Zoom: 0.5X 10748+00</small></p>		 <p><small>Date &amp; Time: Mon, May 02, 2022, 09:51:33 EDT Position: +037.352328 / -080.663810 / +89.5m Altitude: 3231ft (+99.7m) Datum: WGS-84 Azimuth/Bearing: 243° S83W 4424mils True (+12°) Elevation Angle: +01.4° Horizon Angle: +01.2° Zoom: 1.0X 10656+00</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10748+00	<b>Field Station#</b>	10656+00		
<b>Pic 9 Desc.</b>	RCE functional	<b>Pic 10 Desc.</b>	CFS perimeter controls functional		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	5/2/2022 7:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37195
<b>Inspector</b>	Clint Sears			<b>Date/Time</b>	5/2/2022 12:24 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10859+46
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/2/2022 12:24 PM	<b>Report #</b>	37195
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental staff. Completed VA SWPPP inspection from MP 204.53 (10798+92) To MP 205.67 (10859+46). No deficiencies found at this time. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Karst ECD's are in place and in acceptable condition. Assessed AR241.03 and RCE at Archer Trail/ Ar241.02 Row is damp and in stable condition. Participated in spread G conference call.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/2/2022 12:24 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10855+85	<b>Field Station#</b>	10840+00		
<b>Pic 1 Desc.</b>	Section of Row showing conditions and controls at S-A33/34	<b>Pic 2 Desc.</b>	Section of Row showing conditions and controls		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10851+00	<b>Field Station#</b>	10830+00		
<b>Pic 3 Desc.</b>	Section of Row showing conditions and controls	<b>Pic 4 Desc.</b>	Section of Row showing conditions and controls		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10818+41	<b>Field Station#</b>	10805+50		
<b>Pic 5 Desc.</b>	AR241.03 is maintained in acceptable condition	<b>Pic 6 Desc.</b>	Section of Row showing conditions and controls		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/2/2022 12:24 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10809+04	<b>Field Station#</b>	10810+00		
<b>Pic 7 Desc.</b>	Section of Row showing conditions and controls at S-Z14	<b>Pic 8 Desc.</b>	Section of Row showing conditions and controls at W-Z5		
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10815+45	<b>Field Station#</b>	10818+00		
<b>Pic 9 Desc.</b>	Clean water diversion pipe, level spreader, daylight drain with outlet protection and CFS are in acceptable condition	<b>Pic 10 Desc.</b>	Section of Row showing conditions and controls		
<div>Insert image here</div>		<div>Insert image here</div>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/2/2022 12:24 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37203
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/2/2022 4:18 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10797+92
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/2/2022 4:18 PM	<b>Report #</b>	37203
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10747+92 (Hendrickson Road) to ST# 10798+92 (Cascade Road) Accompanied by EI Trey Ingram on SWPPP inspection from MP 204.53 to MP 205.67. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crews walking through section checking ECDs. This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. Sensitive resource buffers are in place at streams S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2. Hendrickson Road, Big Branch Hollow Road, and Cascade Road crossings RCEs are maintained and in acceptable condition. No sensitive resources have been impacted. Checked rain gauges at Catawba Road and Mount Tabor Road. Both gauges read 0.3 inches.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time	5/2/2022 4:18 PM	Report #	
Pictures					
<p>Date &amp; Time: Mon, May 02, 2022, 09:20:31 EDT  Position: +037.44880117, -080.4322311 (A: 783.0 ft)  Altitude: 2120 ft (+130.0 ft)  Datum: WGS-84  Azimuth/Bearing: 131.546E, 2229mils True (+14.7)  Elevation Angle: +21.9  Horizon Angle: -03.1  Zoom: 1.0X  10765+00</p> 		<p>Date &amp; Time: Mon, May 02, 2022, 09:08:55 EDT  Position: +037.4344335, -080.4356434 (A: 1009.0 ft)  Altitude: 2260 ft (+140.0 ft)  Datum: WGS-84  Azimuth/Bearing: 095.585E, 1689mils True (+12.7)  Elevation Angle: +20.7  Horizon Angle: -00.8  Zoom: 1.0X  10754+00</p> 			
<b>GPS Location</b>		See photo.		<b>GPS Location</b>	
<b>Field Station#</b>		10765+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Clean water diversion pipe and level spreader in place.		<b>Pic 2 Desc.</b>	
				Waterbars in place. ROW temporarily stabilized with seed and mulch.	
<p>Date &amp; Time: Mon, May 02, 2022, 09:14:03 EDT  Position: +037.4204424, -080.420308 (A: 734.6 ft)  Altitude: 2241 ft (+120.6 ft)  Datum: WGS-84  Azimuth/Bearing: 082.182E, 1458mils True (+1.9)  Elevation Angle: -17.3  Horizon Angle: -03.8  Zoom: 1.0X  10758+00 S-G35</p> 		<p>Date &amp; Time: Mon, May 02, 2022, 09:17:31 EDT  Position: +037.340717, -080.420885 (A: 734.6 ft)  Altitude: 2088 ft (+387.3 ft)  Datum: WGS-84  Azimuth/Bearing: 126.554E, 2240mils True (+1.9)  Elevation Angle: -26.9  Horizon Angle: -03.4  Zoom: 1.0X  10762+00</p> 			
<b>GPS Location</b>		See photo.		<b>GPS Location</b>	
<b>Field Station#</b>		10758+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Sensitive resource buffer in place at stream S-G35.		<b>Pic 4 Desc.</b>	
				Rock inlet in place at slope drain.	
<p>Date &amp; Time: Mon, May 02, 2022, 09:53:29 EDT  Position: +037.4392247, -080.429115 (A: 366.8 ft)  Altitude: 2217 ft (+127.7 ft)  Datum: WGS-84  Azimuth/Bearing: 095.585E, 1689mils True (+14.7)  Elevation Angle: -13.1  Horizon Angle: -04.7  Zoom: 1.0X  10782+00</p> 		<p>Date &amp; Time: Mon, May 02, 2022, 09:40:59 EDT  Position: +037.424249, -080.421921 (A: 836.9 ft)  Altitude: 1905 ft (+315.9 ft)  Datum: WGS-84  Azimuth/Bearing: 110.570E, 1956mils True (+14.7)  Elevation Angle: -09.2  Horizon Angle: -00.7  Zoom: 1.0X  10797+00</p> 			
<b>GPS Location</b>		See photo.		<b>GPS Location</b>	
<b>Field Station#</b>		10782+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		ROW temporarily stabilized with seed, mulch, and vegetation growth.		<b>Pic 6 Desc.</b>	
				RCE in place at Cascade Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/2/2022 4:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/2/2022 4:18 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37246
<b>Inspector</b>	Clint Sears			<b>Date/Time</b>	5/3/2022 11:14 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11098+47
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11184+85
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	82.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Stone Inlet Protection	Acceptable			
Slope Drain Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Rock Construction Entrance	Acceptable			

## 5. Site Conditions







Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2022 11:14 AM	<b>Report #</b>	37246
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental staff. Completed VA SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85) This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Assessed AR 245.02, AR249, AR249.01, AR249.03 and AR 249.02. Row is dry and in stable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 5/3/2022 11:14 AM		Report #	
Pictures					
 <p>Date &amp; Time: Tue May 03 2022 11:14:01 EDT Position: +037.35241 / -080.51250* (+33.3m) Altitude: 1875ft (+25.4m) Datum: WGS-84 Azimuth/Bearing: 127.531E 229.5mils True (+13.1) Elevation Angle: -15.2 Horizon Angle: -04.8 Zoom: 1.0X 11182+00</p>		 <p>Date &amp; Time: Tue May 03 2022 10:58:03 EDT Position: +037.35241 / -080.51250* (+33.3m) Altitude: 1875ft (+25.4m) Datum: WGS-84 Azimuth/Bearing: 100.000W 300.0mils True (+13.1) Elevation Angle: -15.2 Horizon Angle: -02.7 Zoom: 1.0X 11179+00</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11182+00		Field Station#	11179+00	
Pic 1 Desc.	Section of Row showing conditions and controls		Pic 2 Desc.	Section of Row showing conditions and controls	
 <p>Date &amp; Time: Tue May 03 2022 10:00:11 EDT Position: +037.35241 / -080.51599* (+11.6m) Altitude: 1875ft (+25.4m) Datum: WGS-84 Azimuth/Bearing: 338.000W 338.0mils True (+13.1) Elevation Angle: -06.6 Horizon Angle: -00.2 Zoom: 1.0X 11167+70</p>		 <p>Date &amp; Time: Tue May 03 2022 10:00:11 EDT Position: +037.35241 / -080.51599* (+11.6m) Altitude: 1875ft (+25.4m) Datum: WGS-84 Azimuth/Bearing: 338.000W 338.0mils True (+13.1) Elevation Angle: -06.6 Horizon Angle: -00.4 Zoom: 1.0X 11159+19 S-NN17</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11167+70		Field Station#	11159+19	
Pic 3 Desc.	Clean water diversion pipe and level spreader are in acceptable condition		Pic 4 Desc.	S-NN17	
 <p>Date &amp; Time: Tue May 03 2022 09:43:08 EDT Position: +037.35241 / -080.51774* (+21.2m) Altitude: 1875ft (+25.4m) Datum: WGS-84 Azimuth/Bearing: 103.577E 183.1mils True (+13.1) Elevation Angle: -19.7 Horizon Angle: -02.1 Zoom: 1.0X 11152+50</p>		 <p>Date &amp; Time: Tue May 03 2022 09:43:04 EDT Position: +037.35241 / -080.52062* (+22.3m) Altitude: 1875ft (+25.4m) Datum: WGS-84 Azimuth/Bearing: 200.000W 300.0mils True (+13.1) Elevation Angle: -19.7 Horizon Angle: -06.6 Zoom: 1.0X 11143+50</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	11152+50		Field Station#	11143+50	
Pic 5 Desc.	Section of Row showing conditions and controls		Pic 6 Desc.	Section of Row showing conditions and controls	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/3/2022 11:14 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11138+40		<b>Field Station#</b>	11133+00	
<b>Pic 7 Desc.</b>	Section of Row showing conditions and controls		<b>Pic 8 Desc.</b>	Representational photo of water bar and level spreader	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11130+00		<b>Field Station#</b>	11126+00	
<b>Pic 9 Desc.</b>	Erosion control blanket is in place and in acceptable conditions		<b>Pic 10 Desc.</b>	Section of Row showing conditions and controls	
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11100+00		<b>Field Station#</b>	11167+83	
<b>Pic 11 Desc.</b>	Section of Row showing conditions and controls		<b>Pic 12 Desc.</b>	RCE at AR249.01 is in acceptable condition	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2022 11:14 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37235
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/3/2022 7:44 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11184+85
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Stone Inlet Protection	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			


### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2022 7:44 AM	<b>Report #</b>	37235
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). Compliance issues noted: @ 11185+00 P1 damaged Observance: Perimeter controls in place Permanent & temporary stabilization in place. - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. @11222+50 to 11206+27 the stabilization is thin and is being monitored. This area just over seeded last week 4/12/22 & 4/13/22. - Temporary stabilization near 11222+50 to near 11253+50. This section of row has been stabilized for the winter months. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. AR-249.02 & 244 RCE's are maintained in acceptable condition. Some subsidence on both sides of winding way also monitoring it. The ROW is damp and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/3/2022 7:44 AM	<b>Report #</b>	
<b>Pictures</b>					
<p> <small> Date &amp; Time Tue May 03 2022 09:52:00 EDT  Position: 43°29'27.21" N 80°45'55.1" W (11250)  Altitude: 2243ft (+131ft)  Datum: WGS-84  Azimuth/Bearing: 116.544° 2062mils True (+131°)  Elevation Angle: -17.0°  Horizon Angle: -02.1°  Zoom: 1.0x  11250+00 </small> </p> 		<p> <small> Date &amp; Time Tue May 03 2022 09:46:33 EDT  Position: 43°29'27.72" N 80°45'53.0" W (11239)  Altitude: 2243ft (+131ft)  Datum: WGS-84  Azimuth/Bearing: 273° N87W 4863mils True (+131°)  Elevation Angle: -13.2°  Horizon Angle: -00.8°  Zoom: 1.0x  11239+00 </small> </p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11250+00	<b>Field Station#</b>	11239+00		
<b>Pic 1 Desc.</b>	Picture showing condition of row	<b>Pic 2 Desc.</b>	Inlet in place		
<p> <small> Date &amp; Time Tue May 03 2022 09:15:00 EDT  Position: 43°29'27.55" N 80°46'03.0" W (11200)  Altitude: 2033ft (+130ft)  Datum: WGS-84  Azimuth/Bearing: 170° S010W 1700mils True (+130°)  Elevation Angle: -09.0°  Horizon Angle: -04.1°  Zoom: 1.0x  11200+00 </small> </p> 		<p> <small> Date &amp; Time Tue May 03 2022 09:15:00 EDT  Position: 43°29'27.71" N 80°46'03.0" W (11196)  Altitude: 2033ft (+130ft)  Datum: WGS-84  Azimuth/Bearing: 180° S00W 1700mils True (+130°)  Elevation Angle: -13.0°  Horizon Angle: -08.0°  Zoom: 1.0x  11196+00 </small> </p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11200+00	<b>Field Station#</b>	11196+00		
<b>Pic 3 Desc.</b>	Permanent water bars and level spreader in place	<b>Pic 4 Desc.</b>	Permanent stabilization in place		
<p> <small> Date &amp; Time Tue May 03 2022 09:03:35 EDT  Position: 43°29'27.22" N 80°46'01.92" W (11185)  Altitude: 1934ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 122.558° 2169mils True (+131°)  Elevation Angle: -09.2°  Horizon Angle: -01.2°  Zoom: 1.0x  11185+00 </small> </p> 		<p> <small> Date &amp; Time Tue May 03 2022 09:00:35 EDT  Position: 43°29'27.22" N 80°46'02.22" W (1184)  Altitude: 1934ft (+39.4ft)  Datum: WGS-84  Azimuth/Bearing: 047° N47E 3839mils True (+131°)  Elevation Angle: -06.5°  Horizon Angle: -02.7°  Zoom: 1.0x  1184+79 </small> </p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11185+00	<b>Field Station#</b>	1184+79		
<b>Pic 5 Desc.</b>	P1 damaged and needs repaired	<b>Pic 6 Desc.</b>	Rock check dams in place		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/3/2022 7:44 AM	<b>Report #</b>	
<b>Pictures</b>					
					
		Insert image here			
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	11191+02	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Clean water drainage feature in place	<b>Pic 8 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2022 7:44 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37232
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	5/3/2022 7:21 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11098+47
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	61.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2022 7:21 AM	<b>Report #</b>	37232
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Performed VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. With EI Daniel Fortune. No deficiencies found:  Observances: The ROW in that area received no precipitation overnight. The ROW was dry. The ROW from AR 244 to AR 245.01 has been temporarily stabilized. The ROW from 245.01 to 245.02 has been restored. The restored area is in good shape and the vegetation is sufficient. The water bars ( other ), in the restored area are in place and functioning as designed. The environmental controls are to specifications and and functioning as designed. No construction being performed in the area. One area of open ditch in the area. RCE's are clean. The EC's at the WB's in this area are in place and functioning as designed. LOD ECDs were in place and functional. Water bars have been installed to specifications. ECDS at the sensitive resources see in place and the resources have not been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/3/2022 7:21 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11025+00	<b>Field Station#</b>	11045+00		
<b>Pic 1 Desc.</b>	SIJ 18	<b>Pic 2 Desc.</b>	Perimeter controls		
					
<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11050+00	<b>Field Station#</b>	11055+00		
<b>Pic 3 Desc.</b>	SIJ 16B	<b>Pic 4 Desc.</b>	Silt fence		
					
<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	1165+84	<b>Field Station#</b>	11072+00		
<b>Pic 5 Desc.</b>	244.02	<b>Pic 6 Desc.</b>	Stabilized/restored ROW		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/3/2022 7:21 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p> Date &amp; Time Tue May 03 2022 10:15:00 EDT  Position +037°31'56.57" / -080°53'12.17" (-572.5m)  Altitude 2189ft (-69.4m)  Datum WGS-84  Azimuth Bearing 117°54'E 2080mils Magnetic (-200)  Elevation Angle -19.5  Horizon Angle -00.0  Zoom 1.0X  11085+00  Spread G </p>		 <p> Date &amp; Time Tue May 03 2022 10:16:29 EDT  Position +037°31'57.07" / -080°53'56.07" (-586.0m)  Altitude 2019ft (-62.2m)  Datum WGS-84  Azimuth Bearing 321°N39W 5707mils Magnetic (-600)  Elevation Angle -33.0  Horizon Angle -01.2  Zoom 1.0X  11085+00  Spread G </p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11080+00	<b>Field Station#</b>	11085+00		
<b>Pic 7 Desc.</b>	Water bars (other)	<b>Pic 8 Desc.</b>	Restored ROW		
 <p> Date &amp; Time Tue May 03 2022 10:22:42 EDT  Position +037°31'30.58" / -080°53'22.93" (-16.4m)  Altitude 1988ft (-19.8m)  Datum WGS-84  Azimuth Bearing 103°57'E 1831mils Magnetic (-121)  Elevation Angle -20.0  Horizon Angle -00.4  Zoom 1.0X  11098+00  Spread G </p>				Insert image here	
<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11098+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	245.02	<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2022 7:21 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37243
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/3/2022 10:52 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10929+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11023+80
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





AFE 124300137		Date/Time 5/3/2022 10:52 AM		Report #	
Pictures					
 <p>Date &amp; Time: Tue, May 03, 2022, 09:03:38 EDT Position: +4937.221894° / -080.553471° (+3468.9ft) Altitude: 3257ft (+193.2m) Datum: WGS-84 Azimuth/Bearing: 126° S54E, 2240mils True (±17.1) Elevation Angle: -38.0° Horizon Angle: -03.2° Zoom: 1.0X 11016+80</p>		 <p>Date &amp; Time: Tue, May 03, 2022, 09:15:53 EDT Position: +4937.222491° / -080.553471° (+3468.9ft) Altitude: 3257ft (+193.2m) Datum: WGS-84 Azimuth/Bearing: 126° S54E, 2240mils True (±17.1) Elevation Angle: -38.0° Horizon Angle: -03.2° Zoom: 1.0X 11016+80</p>			
GPS Location		See photo for GPS location and station.		GPS Location	
Field Station#		11023+80		Field Station#	
Pic 1 Desc.		Hole in P-1 silt fence.		Pic 2 Desc.	
				Priority one silt fence fabric torn.	
 <p>Date &amp; Time: Tue, May 03, 2022, 09:09:50 EDT Position: +4937.223596° / -080.553471° (+3468.9ft) Altitude: 3257ft (+193.2m) Datum: WGS-84 Azimuth/Bearing: 226° N62W, 5290mils True (±17.1) Elevation Angle: -01.7° Horizon Angle: -02.7° Zoom: 1.0X 11015+00</p>		 <p>Date &amp; Time: Tue, May 03, 2022, 09:15:53 EDT Position: +4937.222491° / -080.553471° (+3468.9ft) Altitude: 3257ft (+193.2m) Datum: WGS-84 Azimuth/Bearing: 226° N62W, 5290mils True (±17.1) Elevation Angle: -01.7° Horizon Angle: -02.7° Zoom: 1.0X 10966+00</p>			
GPS Location		See photo for GPS location and station.		GPS Location	
Field Station#		11015+00		Field Station#	
Pic 3 Desc.		Sensitive resource buffer in place at stream S-RR5.		Pic 4 Desc.	
				Triple barrier ECDs in place at karst feature.	
 <p>Date &amp; Time: Tue, May 03, 2022, 09:49:15 EDT Position: +4937.227971° / -080.572886° (+15.4ft) Altitude: 2279ft (+11.3m) Datum: WGS-84 Azimuth/Bearing: 286° N74W, 5080mils True (±17.1) Elevation Angle: -04.5° Horizon Angle: -00.8° Zoom: 1.0X 10961+75</p>		 <p>Date &amp; Time: Tue, May 03, 2022, 10:07:51 EDT Position: +4937.231911° / -080.582639° (+15.4ft) Altitude: 2319ft (+11.3m) Datum: WGS-84 Azimuth/Bearing: 272° N81W, 4960mils True (±16.1) Elevation Angle: -14.2° Horizon Angle: -01.8° Zoom: 1.0X 10930+50</p>			
GPS Location		See photo for GPS location and station.		GPS Location	
Field Station#		10961+75		Field Station#	
Pic 5 Desc.		ROW permanently stabilized.		Pic 6 Desc.	
				RCE in place at Doe Creek Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2022 10:52 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/3/2022 10:52 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37311
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/4/2022 1:50 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+49
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	61.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Sump Pit	Communication			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions


Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2022 1:50 PM	<b>Report #</b>	37311
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a Virginia SWPP inspection from station # 11254+99 to 11353+67 (MP 213.6-215.04) Rte 42 to Old Furnace Rd. A minor Deficiency was observed and documented for repairs today. (Geo-textile fabric unsecured).          "Station numbers are approximate."          Observances: Environmental crew 1709 was on site near even Oaks continuing with temporary stabilization. The ROW has been temporarily stabilized and remains at a stable repose. No erosion issues at this time. There is slightly visible temporary grasses throughout the areas of inspection. Karst areas have been previously assumed in sump locations near station 11348+00 and near station 11349+77. The geo-tech fabric in the sump near 11351+00 has been added to the punch list for repairs. The water bars and compost sock remain in a functional condition in these areas as well as all other areas of inspection. Steep slopes have erosion control fabric (CC4) installed. There is limited visible growth where the CC4 ECB have been installed. There is visible vegetation that has began to re-emerge. There may be more areas needing to be re-seeded. Slope drains are functioning as intended without issues. Stone inlet protections are also functional at this time. There are three stream resources in the areas of inspection. Conditions are as follows:          S-MM18 - near 11292+80 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required.          S-NN12 - near 11327+80 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required.          S-NN11 - near 11352+97 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required.          All perimeter controls, ECDs and BMPs were functional at time of inspection. No other crews were working in the area. Rock Road approaches and access roads are clean and free of loose rock and debris.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		5/4/2022 1:50 PM		Report #			
Pictures											
											
GPS Location		See Photo						GPS Location		See Photo	
Field Station#		11351+00						Field Station#		11353+22	
Pic 1 Desc.		Displaced geo-textile fabric at a presumed karst sump pit area. This has been added to today's punch list.						Pic 2 Desc.		S-NN11 vegetated stream buffer zones. Resource area adequately protected with functional ECDs.	
											
GPS Location		See Photo						GPS Location		See Photo	
Field Station#		11351+00						Field Station#		11346+00	
Pic 3 Desc.		Temporary stabilization of water bar and water bar throat.						Pic 4 Desc.		Adequate protection of presumed karst sump pit area.	
											
GPS Location		See Photo						GPS Location		See Photo	
Field Station#		11344+10						Field Station#		11353+47	
Pic 5 Desc.		Temporary stabilization of row						Pic 6 Desc.		RCE and AR 256.02 conditions.	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2022 1:50 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed May 04, 2022 09:41:59 EDT  Position: +037.300780° / -080.472749° (±19.2m)  Altitude: 2139ft (±9.8m)  Datum: WGS-84  Azimuth/Bearing: 297° S53°W 4215mils True (±12°)  Elevation Grade: +01%  Horizon Grade: +001%  Zoom: 1.0X  11328+32.5-NN12</p> 		<p>Date &amp; Time: Wed May 04, 2022 09:42:34 EDT  Position: +037.300618° / -080.473355° (±14.8m)  Altitude: 2148ft (±12.1m)  Datum: WGS-84  Azimuth/Bearing: 297° S53°W 4215mils True (±12°)  Elevation Grade: +01%  Horizon Grade: +001%  Zoom: 4.0X  11325+00</p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11328+32		<b>Field Station#</b>	11325+00	
<b>Pic 7 Desc.</b>	S-NN12 vegetated buffer zones and equipment bridge conditions.		<b>Pic 8 Desc.</b>	Temporary stabilization of steep slope row.	
<p>Date &amp; Time: Wed May 04, 2022 09:58:12 EDT  Position: +037.293211° / -080.473566° (±18.0m)  Altitude: 2124ft (±9.1m)  Datum: WGS-84  Azimuth/Bearing: 050° N50E 0887mils True (±15°)  Elevation Grade: +005%  Horizon Grade: +001%  Zoom: 1.0X  11331+00</p> 		<p>Date &amp; Time: Wed May 04, 2022 10:03:41 EDT  Position: +037.293445° / -080.451133° (±10.0m)  Altitude: 2120ft (±9.4m)  Datum: WGS-84  Azimuth/Bearing: 221° S41W 3929mils True (±12°)  Elevation Grade: +026%  Horizon Grade: +004%  Zoom: 0.5X  11293+66</p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11331+00		<b>Field Station#</b>	11293+66	
<b>Pic 9 Desc.</b>	Repaired and temporary stabilization of ditch line settling area.		<b>Pic 10 Desc.</b>	S-MM18 equipment bridge and undisturbed buffer zones.	
<p>Date &amp; Time: Wed May 04, 2022 11:05:38 EDT  Position: +037.276245° / -080.451425° (±9.0m)  Altitude: 2122ft (±9.1m)  Datum: WGS-84  Azimuth/Bearing: 208° S28W 3698mils True (±12°)  Elevation Grade: +22%  Horizon Grade: +006%  Zoom: 0.5X  11292+66</p> 		<p>Date &amp; Time: Wed May 04, 2022 11:05:58 EDT  Position: +037.276343° / -080.451425° (±9.0m)  Altitude: 2105ft (±9.8m)  Datum: WGS-84  Azimuth/Bearing: 293° S73W 4498mils True (±12°)  Elevation Grade: +03%  Horizon Grade: +000%  Zoom: 2.0X  11290+00</p> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11292+66		<b>Field Station#</b>	11290+00	
<b>Pic 11 Desc.</b>	S-MM18 vegetated undisturbed stream channel.		<b>Pic 12 Desc.</b>	Active disturbance within the travel lane. Contractor on site.	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2022 1:50 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>		See Photo		<b>GPS Location</b>	
<b>Field Station#</b>		11258+00		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		Temporary stabilization of steep slope.		<b>Pic 14 Desc.</b>	
Insert image here		Insert image here			
<b>GPS Location</b>				<b>GPS Location</b>	
<b>Field Station#</b>				<b>Field Station#</b>	
<b>Pic 15 Desc.</b>				<b>Pic 16 Desc.</b>	
Insert image here		Insert image here			
<b>GPS Location</b>				<b>GPS Location</b>	
<b>Field Station#</b>				<b>Field Station#</b>	
<b>Pic 17 Desc.</b>				<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37301
<b>Inspector</b>	Clint Sears			<b>Date/Time</b>	5/4/2022 11:44 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11471+56
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Equipment Bridge	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Plunge Pool	Acceptable			
Stone Inlet Protection	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2022 11:44 AM	<b>Report #</b>	37301
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
Level Spreader	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental staff. Completed VA SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56). This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Light rain during inspection. Assessed Steele Acres access. Row is wet and in stable condition. Cattle were inside the LOD, notified Lead EI Brian Shields. PPL personal were notified, did not observe and damaged to ECD's.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	5/4/2022 11:44 AM	Report #	
Pictures					
<p> <small> Date &amp; Time: Wed May 04, 2022 11:44:31 EDT  Position: +48°59'57.22" / -080°45'54.3" (-15.20)  Altitude: 192m (+11.4m)  Datum: WGS-84  Azimuth/Bearing: 168° S12E 2987mils True (+12°)  Elevation Angle: -09.1°  Horizon Angle: -03.2°  Zoom: 1.0x  11360+54 S-KL43 </small> </p> 		<p> <small> Date &amp; Time: Wed May 04, 2022 09:45:46 EDT  Position: +48°59'57.22" / -080°45'54.3" (-15.20)  Altitude: 230m (+11.4m)  Datum: WGS-84  Azimuth/Bearing: 286° N74W 3087mils True (+12°)  Elevation Angle: -18.0°  Horizon Angle: -03.6°  Zoom: 1.0x  11397+00 </small> </p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11360+54		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		Section of Row showing conditions and controls at S-KL43		<b>Pic 2 Desc.</b>	
<p> <small> Date &amp; Time: Wed May 04, 2022 09:42:56 EDT  Position: +48°59'57.22" / -080°45'54.3" (-15.20)  Altitude: 231m (+11.4m)  Datum: WGS-84  Azimuth/Bearing: 223° S43W 3964mils True (+12°)  Elevation Angle: -14.7°  Horizon Angle: -02.0°  Zoom: 1.0x  11412+50 </small> </p> 		<p> <small> Date &amp; Time: Wed May 04, 2022 09:42:56 EDT  Position: +48°59'57.22" / -080°45'54.3" (-15.20)  Altitude: 229m (+11.4m)  Datum: WGS-84  Azimuth/Bearing: 262° S82W 4002mils True (+12°)  Elevation Angle: -08.6°  Horizon Angle: -02.6°  Zoom: 1.0x  11425+00 </small> </p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11412+50		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Section of Row showing conditions and controls		<b>Pic 4 Desc.</b>	
<p> <small> Date &amp; Time: Wed May 04, 2022 09:40:47 EDT  Position: +48°59'57.22" / -080°44'59.4" (-15.06 2N)  Altitude: 222m (+11.4m)  Datum: WGS-84  Azimuth/Bearing: 351° N83E 3839mils True (+12°)  Elevation Angle: -16.2°  Horizon Angle: -03.1°  Zoom: 1.0x  11431+00 </small> </p> 		<p> <small> Date &amp; Time: Wed May 04, 2022 09:40:48 EDT  Position: +48°59'57.22" / -080°44'59.4" (-15.06 2N)  Altitude: 232m (+11.4m)  Datum: WGS-84  Azimuth/Bearing: 327° N33W 5813mils True (+12°)  Elevation Angle: -14.3°  Horizon Angle: -03.4°  Zoom: 1.0x  11432+00 </small> </p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11431+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Section of Row showing conditions and controls		<b>Pic 6 Desc.</b>	
				Representational photo of water bar and level spreader	



AFE	124300137	Date/Time	5/4/2022 11:44 AM	Report #	
Pictures					
<p><small>Date &amp; Time: Wed, May 04, 2022, 11:44:00 EST Position: +037.3183187, -080.4488888, 1450.91ft Altitude: 2221ft (+420.91ft) Datum: WGS-84 Azimuth/Bearing: 222° S42W 3947mils True (+12°) Elevation Angle: -08.9° Horizon Angle: -03.7° Zoom: 1.0X 11443+00</small></p> 				<p><small>Date &amp; Time: Wed, May 04, 2022, 11:44:00 EST Position: +037.3183187, -080.4488888, 1450.91ft Altitude: 2221ft (+420.91ft) Datum: WGS-84 Azimuth/Bearing: 222° S42W 3947mils True (+12°) Elevation Angle: -08.9° Horizon Angle: -03.7° Zoom: 1.0X 11443+00</small></p> 	
GPS Location	See photo		GPS Location	See photo	
Field Station#	11443+00		Field Station#	11448+98	
Pic 7 Desc.	Section of Row showing conditions and controls		Pic 8 Desc.	S-0014	
<p><small>Date &amp; Time: Wed, May 04, 2022, 11:45:28 EST Position: +037.3183187, -080.4488888, 1450.91ft Altitude: 2150ft (+350.91ft) Datum: WGS-84 Azimuth/Bearing: 203° S20W 3000mils True (+12°) Elevation Angle: -03.8° Horizon Angle: -00.0° Zoom: 1.0X 11451+28 S-0013</small></p> 				<p><small>Date &amp; Time: Wed, May 04, 2022, 11:45:28 EST Position: +037.3183187, -080.4488888, 1450.91ft Altitude: 2150ft (+350.91ft) Datum: WGS-84 Azimuth/Bearing: 203° S20W 3000mils True (+12°) Elevation Angle: -03.8° Horizon Angle: -00.0° Zoom: 1.0X 11451+28 S-0013</small></p> 	
GPS Location	See photo		GPS Location	See photo	
Field Station#	11451+28		Field Station#	11451+87	
Pic 9 Desc.	S-0013		Pic 10 Desc.	S-0012	
<p><small>Date &amp; Time: Wed, May 04, 2022, 11:45:45 EST Position: +037.321189, -080.455184, 1481.61ft Altitude: 2216ft (+416.61ft) Datum: WGS-84 Azimuth/Bearing: 246° S66W 4373mils True (+12°) Elevation Angle: -16.8° Horizon Angle: -01.5° Zoom: 1.0X 11454+75</small></p> 				<p><small>Date &amp; Time: Wed, May 04, 2022, 11:46:00 EST Position: +037.321189, -080.455184, 1481.61ft Altitude: 2254ft (+416.61ft) Datum: WGS-84 Azimuth/Bearing: 225° S45W 4000mils True (+12°) Elevation Angle: -09.1° Horizon Angle: -00.2° Zoom: 1.0X 11468+87 S-CD14</small></p> 	
GPS Location	See photo		GPS Location	See photo	
Field Station#	11454+75		Field Station#	11468+87	
Pic 11 Desc.	Section of Row showing conditions and controls		Pic 12 Desc.	Section of Row showing conditions and controls at S-CD14	



<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2022 11:44 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37286
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	5/4/2022 7:20 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11471+56
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11524+16
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.20
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2022 7:20 AM	<b>Report #</b>	37286
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>		<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<div></div>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11471+56 (Steele Acres) to ST# 11524+16 (258.02), MP 217.26 to MP 218.26. With EI, Trey Ingram. The ROW had received 0.20" Of precipitation at AR road, Stevers Gap. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized. Slope drains with stone inlet protection, Perimeter controls, and waterbars with end treatments are in place Triple protection ECDs are in place at karst feature. Sensitive resource buffers are in place at stream crossings S-PP3, and S-PP4. AR-258.01, 258.02, and Stever's Gap road crossing RCEs are maintained in acceptable condition. The ROW is damp, but stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



AFE 124300137		Date/Time	5/4/2022 7:20 AM	Report #	
Pictures					
					
GPS Location		See photo		GPS Location	
Field Station#		11524+00		Field Station#	
Pic 1 Desc.		Drainage		S-PP4	
					
GPS Location		see photo		GPS Location	
Field Station#		11512+00		Field Station#	
Pic 3 Desc.		Equipment bridge		S-PP3	
					
GPS Location		see photo		GPS Location	
Field Station#		11505+00		Field Station#	
Pic 5 Desc.		Rock channel		Stabilized ROW	
Pic 6 Desc.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2022 7:20 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Wed, May 04, 2022, 09:36:55 EDT Position: +037.322770 / -080.432085 (±16.4ft) Altitude: 2228ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 075° N75E 1333mils Magnetic (±12°) Elevation Angle: -12.6° Horizon Angle: +00.2° Zoom: 1.0X 11490+00 Spread G</small></p>		 <p><small>Date &amp; Time: Wed, May 04, 2022, 09:27:29 EDT Position: +037.322360 / -080.432922 (±16.4ft) Altitude: 2223ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 342° N18W 6080mils Magnetic (±12°) Elevation Angle: -15.9° Horizon Angle: -02.9° Zoom: 1.0X 11483+00 Spread G</small></p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11490+00		<b>Field Station#</b>	11483+00	
<b>Pic 7 Desc.</b>	Seven Oaks		<b>Pic 8 Desc.</b>	Water bar/sump	
 <p><small>Date &amp; Time: Wed, May 04, 2022, 09:26:15 EDT Position: +037.322770 / -080.432085 (±16.4ft) Altitude: 2228ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 068° N68E 1209mils Magnetic (±12°) Elevation Angle: -23.3° Horizon Angle: -00.0° Zoom: 1.0X 11480+00 Spread G</small></p>		 <p><small>Date &amp; Time: Wed, May 04, 2022, 09:21:59 EDT Position: +037.322375 / -080.435198 (±16.4ft) Altitude: 2263ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 105° S75E 1867mils Magnetic (±18°) Elevation Angle: -28.3° Horizon Angle: -03.6° Zoom: 1.0X 11475+00 Spread G</small></p>			
<b>GPS Location</b>	see photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	11480+00		<b>Field Station#</b>	11475+00	
<b>Pic 9 Desc.</b>	Drainage		<b>Pic 10 Desc.</b>	Slope drain	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2022 7:20 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37288
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/4/2022 7:28 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11524+16
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11600+01
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	58.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			




## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2022 7:28 AM	<b>Report #</b>	37288
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to 219.70)</p> <p>No Compliance issues noted:</p> <p>The ROW from 258.02 to the JNF Forest has been fully restored. Permanent waterbars(other) and level spreaders are installed as per the approved plan and are functioning as designed. No maintenance is needed; Vegetation growth is currently acceptable. The Forest has been temporarily stabilized.</p> <p>Observed:</p> <p>The aged P1 on the JNF from the top of the Mtn down to Craig Creek road has been replaced.</p> <p>The restored area is in good shape and the vegetation is sufficient. The environmental controls in the forest are aged, but functional.</p> <p>The ECDs at WBs, S-PP 20,21,22 are new and in good shape.</p> <p>No construction being performed in the area.</p> <p>RCE's functional, highway at Craig Creek station 11600+01, was clean and free of any loose rock.</p> <p>LOD ECDs were in place and functional.</p> <p>Water bars have been installed to specifications.</p> <p>The ROW is wet but in stable condition.</p> <p>No sensitive resources have been impacted</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 5/4/2022 7:28 AM		Report #			
Pictures							
 <p>Date &amp; Time: Wed, May 04, 2022, 08:14:00 EDT Position: +037.312331° / +036.419397° Lat (1.0°) Altitude: 2152ft (655.2m) Datum: WGS 84 Azimuth/Bearing: 136° S42E 2453mils True (±12°) Elevation Angle: +01.1 Horizon Angle: +01.2 Zoom: 0.5X 11524+16 AR258.02</p>		 <p>Date &amp; Time: Wed, May 04, 2022, 08:14:00 EDT Position: +037.312331° / +036.419397° Lat (1.0°) Altitude: 2152ft (655.2m) Datum: WGS 84 Azimuth/Bearing: 136° S42E 2453mils True (±12°) Elevation Angle: +01.1 Horizon Angle: +01.2 Zoom: 2.0X 11536+00</p>					
GPS Location		See photo		GPS Location		See photo	
Field Station#		11524+16		Field Station#		11536+00	
Pic 1 Desc.		Equipment bridge functional		Pic 2 Desc.		Permanent water bars and level spreader in place	
 <p>Date &amp; Time: Wed, May 04, 2022, 08:14:00 EDT Position: +037.312331° / +036.419397° Lat (1.0°) Altitude: 2152ft (655.2m) Datum: WGS 84 Azimuth/Bearing: 136° S42E 2453mils True (±12°) Elevation Angle: +01.1 Horizon Angle: +01.2 Zoom: 1.0X 11530+50</p>		 <p>Date &amp; Time: Wed, May 04, 2022, 08:14:00 EDT Position: +037.312331° / +036.419397° Lat (1.0°) Altitude: 2152ft (655.2m) Datum: WGS 84 Azimuth/Bearing: 214° S34W 3804mils True (±12°) Elevation Angle: +14.6 Horizon Angle: +05.3 Zoom: 1.0X 11584+00</p>					
GPS Location		See		GPS Location		See photo	
Field Station#		11530+50		Field Station#		11584+00	
Pic 3 Desc.		CFS perimeter controls functional		Pic 4 Desc.		ET in place	
 <p>Date &amp; Time: Wed, May 04, 2022, 08:14:00 EDT Position: +037.312331° / +036.419397° Lat (1.0°) Altitude: 2084ft (635.1m) Datum: WGS 84 Azimuth/Bearing: 138° S42E 2453mils True (±12°) Elevation Angle: +11.1 Horizon Angle: +02.9 Zoom: 1.0X 11585+00</p>		 <p>Date &amp; Time: Wed, May 04, 2022, 08:14:00 EDT Position: +037.312331° / +036.419397° Lat (1.0°) Altitude: 2084ft (635.1m) Datum: WGS 84 Azimuth/Bearing: 320° N40W 3683mils True (±12°) Elevation Angle: +14.6 Horizon Angle: +02.9 Zoom: 1.0X 11580+00</p>					
GPS Location		See photo		GPS Location		See photo	
Field Station#		11585+00		Field Station#		11580+00	
Pic 5 Desc.		Resource buffers in place		Pic 6 Desc.		Water bars in place	



<b>AFE</b>	124300137	<b>Date/Time</b>	5/4/2022 7:28 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Wed May 04, 2022 08:41:14 EDT Position: 43° 15' 25" N / -68° 08' 00" W (52933) Altitude: 209 ft (63.7m) Datum: WGS-84 Azimuth/Bearing: 100° 25' 1" NSW 692mils True (513°) Elevation Angle: -00.1° Horizon Angle: -00.3° Zoom: 1.0X 11588+00</small></p>		 <p><small>Date &amp; Time: Wed May 04, 2022 08:40:46 EDT Position: 43° 15' 25" N / -68° 08' 00" W (52933) Altitude: 209 ft (63.7m) Datum: WGS-84 Azimuth/Bearing: 100° 25' 1" NSW 692mils True (513°) Elevation Angle: -00.1° Horizon Angle: -00.3° Zoom: 1.0X 11596+50</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11588+00	<b>Field Station#</b>	11596+50		
<b>Pic 7 Desc.</b>	Equipment bridge functional	<b>Pic 8 Desc.</b>	Perimeter controls in place		
 <p><small>Date &amp; Time: Wed May 04, 2022 08:37:34 EDT Position: 43° 15' 25" N / -68° 08' 00" W (52933) Altitude: 194 ft (59.1m) Datum: WGS-84 Azimuth/Bearing: 278° 18' 0" NSW 692mils True (514°) Elevation Angle: -10.4° Horizon Angle: -00.4° Zoom: 1.0X 11600+01</small></p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	11600+01	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	RCE functional	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	5/4/2022 7:28 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37341
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/5/2022 7:37 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	52.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			


## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2022 7:37 AM	<b>Report #</b>	37341
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP at LY 029. The perimeter controls consist of 18" triple stacked CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 028. The perimeter controls CFS in place and functioning as designed. The RCE was clean, no mud or other debris on road. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p> <p>Completed a VA SWPPP at LY 026. The perimeter controls CFS functioning as designed. The RCE was clean, no mud or other debris on road. The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly. All other ECDs were clean of sediment and functioning properly. Trash receptacles in the Yard were clearly identified.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2022 7:37 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu May 05 2022 09:05:01 EDT  Position: +037.334539° / -080.80130° (-11.6W)  Altitude: 1555ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 161° S03W 3253mils True (±10°)  Elevation Angle: -05.5°  Horizon Angle: +00.2°  Zoom: 1.0X  Y28</p> 		<p>Date &amp; Time: Thu May 05 2022 09:09:17 EDT  Position: +037.334539° / -080.802708° (-11.6W)  Altitude: 1568ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 161° S03W 3253mils True (±10°)  Elevation Angle: -05.5°  Horizon Angle: +00.3°  Zoom: 1.0X  Y28</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Housekeeping trash in good condition y28	<b>Pic 2 Desc.</b>	CFS perimeter controls functional y28		
<p>Date &amp; Time: Thu May 05 2022 09:07:15 EDT  Position: +037.334539° / -080.80130° (-11.6W)  Altitude: 1555ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 254° S76W 450mils True (±10°)  Elevation Angle: -02.1°  Horizon Angle: +01.8°  Zoom: 1.0X  Y28</p> 		<p>Date &amp; Time: Thu May 05 2022 09:07:26 EDT  Position: +037.334703° / -080.808128° (-11.5W)  Altitude: 1567ft (+9.7ft)  Datum: WGS-84  Azimuth/Bearing: 161° S19E 2862mils True (±10°)  Elevation Angle: -10.2°  Horizon Angle: -02.1°  Zoom: 1.0X  Y28</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	CFS perimeter controls functional y28	<b>Pic 4 Desc.</b>	CFS perimeter controls functional y28		
<p>Date &amp; Time: Thu May 05 2022 09:04:32 EDT  Position: +037.334703° / -080.808128° (-11.5W)  Altitude: 1567ft (+9.7ft)  Datum: WGS-84  Azimuth/Bearing: 324° N43W 5162mils True (±10°)  Elevation Angle: -02.8°  Horizon Angle: -01.8°  Zoom: 1.0X  Y28</p> 		<p>Date &amp; Time: Thu May 05 2022 09:08:19 EDT  Position: +037.334703° / -080.808128° (-11.5W)  Altitude: 1568ft (+9.8ft)  Datum: WGS-84  Azimuth/Bearing: 007° N05E 0162mils True (±10°)  Elevation Angle: -03.2°  Horizon Angle: -01.3°  Zoom: 1.0X  Y28</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	CFS perimeter controls functional y28	<b>Pic 6 Desc.</b>	RCE functional y28		



AFE 124300137		Date/Time	5/5/2022 7:37 AM	Report #	
Pictures					
<p>Date &amp; Time: Thu, May 05, 2022 08:42:55 EDT  Position: +037.319075° / -080.656717° (-15.15 mi)  Altitude: 1755ft (-11.1 ft)  Datum: WGS 84  Azimuth/Bearing: 072° N 076.0302mi True (-10°)  Elevation Angle: +01.9°  Horizon Angle: +00.4°  Zoom: 1.0X  Y26</p> 		<p>Date &amp; Time: Thu, May 05, 2022 08:42:58 EDT  Position: +037.318825° / -080.656331° (-15.06 mi)  Altitude: 1755ft (-11.1 ft)  Datum: WGS 84  Azimuth/Bearing: 283° W 72W 5120mi True (-10°)  Elevation Angle: +00.4°  Horizon Angle: +00.4°  Zoom: 2.0X  Y26</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		Permanent stabilization in place y26		<b>Pic 8 Desc.</b>	
				CFS perimeter controls functional y26	
<p>Date &amp; Time: Thu, May 05, 2022 08:47:56 EDT  Position: +037.318491° / -080.657696° (-15.16 mi)  Altitude: 1800ft (-11.2 ft)  Datum: WGS 84  Azimuth/Bearing: 49W 53W 4516mi True (-10°)  Elevation Angle: +01.0°  Horizon Angle: +03.3°  Zoom: 2.0X  Y26</p> 		<p>Date &amp; Time: Thu, May 05, 2022 08:47:17 EDT  Position: +037.318491° / -080.657107° (-15.15 mi)  Altitude: 1800ft (-11.2 ft)  Datum: WGS 84  Azimuth/Bearing: 249° S88W 4766mi True (-10°)  Elevation Angle: +00.3°  Horizon Angle: +02.4°  Zoom: 2.0X  Y26</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		Housekeeping trash in good condition y26		<b>Pic 10 Desc.</b>	
				Secondary containment in place y26	
<p>Date &amp; Time: Thu, May 05, 2022 08:49:05 EDT  Position: +037.318382° / -080.656336° (-15.06 mi)  Altitude: 1755ft (-11.1 ft)  Datum: WGS 84  Azimuth/Bearing: 247° S67W 4391mi True (-10°)  Elevation Angle: +03.7°  Horizon Angle: +02.1°  Zoom: 2.0X  Y26</p> 		<p>Date &amp; Time: Thu, May 05, 2022 08:49:05 EDT  Position: +037.318382° / -080.656336° (-15.06 mi)  Altitude: 1755ft (-11.1 ft)  Datum: WGS 84  Azimuth/Bearing: 102° W02E 5933mi True (-10°)  Elevation Angle: +02.1°  Horizon Angle: +02.1°  Zoom: 1.0X  Y26</p> 			
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		12005+00		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		Secondary containment in place y26		<b>Pic 12 Desc.</b>	
				RCE functional y26	



AFE	124300137	Date/Time	5/5/2022 7:37 AM	Report #	
Pictures					
 <p>Date &amp; Time: Thu, May 05, 2022, 08:35:47 EDT Position: +037 361080, -080 679927, (+15.2N) Altitude: 672ft (+11.2N) Datum: WGS-84 Azimuth/Bearing: 300° N30W 5882mils True (+10.1) Elevation Angle: +03.4° Horizon Angle: +00.7° Zoom: 1.0X Y29</p>				 <p>Date &amp; Time: Thu, May 05, 2022, 08:35:47 EDT Position: +037 361080, -080 679927, (+15.2N) Altitude: 672ft (+11.2N) Datum: WGS-84 Azimuth/Bearing: 300° N30W 5882mils True (+10.1) Elevation Angle: +03.4° Horizon Angle: +00.7° Zoom: 1.0X Y29</p>	
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 13 Desc.	RCE functional y29		Pic 14 Desc.	Broad base dips functional y29	
 <p>Date &amp; Time: Thu, May 05, 2022, 08:31:03 EDT Position: +037 362521, -080 677380, (+13.0N) Altitude: 1697ft (+11.0N) Datum: WGS-84 Azimuth/Bearing: 173° S07E 3076mils True (+10.1) Elevation Angle: +05.3° Horizon Angle: +03.6° Zoom: 1.0X Y29</p>				 <p>Date &amp; Time: Thu, May 05, 2022, 08:32:11 EDT Position: +037 363454, -080 676578, (+15.2N) Altitude: 1703ft (+11.9N) Datum: WGS-84 Azimuth/Bearing: 315° N45W 5600mils True (+10.1) Elevation Angle: +03.7° Horizon Angle: +00.1° Zoom: 1.0X Y29</p>	
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 15 Desc.	Culvert in place y29		Pic 16 Desc.	Housekeeping trash in good condition y29	
 <p>Date &amp; Time: Thu, May 05, 2022, 08:31:30 EDT Position: +037 362521, -080 677380, (+13.0N) Altitude: 1730ft (+15.1N) Datum: WGS-84 Azimuth/Bearing: 316° N46W 5582mils True (+10.1) Elevation Angle: +05.5° Horizon Angle: +00.6° Zoom: 1.0X Y29</p>				 <p>Date &amp; Time: Thu, May 05, 2022, 08:33:56 EDT Position: +037 363522, -080 676521, (+13.07.5N) Altitude: 1715ft (+12.0N) Datum: WGS-84 Azimuth/Bearing: 301° S71W 4544mils True (+13.7) Elevation Angle: +04.0° Horizon Angle: +03.4° Zoom: 1.0X Y29</p>	
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 17 Desc.	CFS perimeter controls functional y29		Pic 18 Desc.	CFS perimeter controls functional y29	



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37339
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	5/5/2022 7:05 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11899+89
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	62.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 7:05 AM	<b>Report #</b>	37339
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03), with El Trey Ingram, MP 223.27 to MP 225.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. No crews working in the area at time of inspection. Crews have removed remaining ECDs from station number 11855+00 to 11830+00. Fence was being installed across the ROW at station # 11832+00 This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) and level spreaders in place where designated on E&S sheets. Majority of perimeter controls have been removed due to final restoration vegetation growth. Sensitive resource buffers are in place at pond P-KL2. Mount Tabor road crossing RCE is maintained and in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	5/5/2022 7:05 AM	Report #	
Pictures					
					
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11897+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		266.03.		<b>Pic 2 Desc.</b>	
					
<b>GPS Location</b>		see photo		<b>GPS Location</b>	
<b>Field Station#</b>		11852+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		Water bars (other)		<b>Pic 4 Desc.</b>	
					
<b>GPS Location</b>		see photo		<b>GPS Location</b>	
<b>Field Station#</b>		11820+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		Level spreaders		<b>Pic 6 Desc.</b>	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2022 7:05 AM	<b>Report #</b>	
<b>Pictures</b>					
				Insert image here	
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	11793+00	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Tabor RCE	<b>Pic 8 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			



<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 7:05 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37349
<b>Inspector</b>	Clint Sears			<b>Date/Time</b>	5/5/2022 11:31 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	See punch list		
Cleanwater Diversion Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2022 11:31 AM	<b>Report #</b>	37349
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental staff. Completed VA SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52) Deficiencies found at the following station number. Sta#11703+85 P1 silt fence was cut and straw bales had removed by third party. All deficiencies were communicated to PPL personal via punch list. Environmental crew began to make repairs to damaged Silt Fence before the end of the day. All other perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. RCE at MT Tabor RD was in acceptable condition. Row is wet and in stable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2022 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11783+00	<b>Field Station#</b>	11767+38		
<b>Pic 1 Desc.</b>	Section of Row showing conditions and controls	<b>Pic 2 Desc.</b>	S-IJ52		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11751+00	<b>Field Station#</b>	11743+97		
<b>Pic 3 Desc.</b>	Section of Row showing conditions and controls	<b>Pic 4 Desc.</b>	S-EF62		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11741+00	<b>Field Station#</b>	11735+00		
<b>Pic 5 Desc.</b>	Section of Row showing conditions and controls at S-EF65	<b>Pic 6 Desc.</b>	Section of Row showing conditions and controls		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2022 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, May 05, 2022, 08:55:08 EDT  Position: +037.27055° / -080.38411° (-23° 16')</p> <p>Altitude: 2370ft (+33.2ft)  Datum: WGS-84  Azimuth/Bearing: 143° S37E 2542mils True (+12°)  Elevation Angle: +22.3°  Horizon Angle: +01.2°  Zoom: 1.0X  11710+55</p> 		<p>Date &amp; Time: Thu, May 05, 2022, 08:55:08 EDT  Position: +037.27055° / -080.38411° (-23° 16')</p> <p>Altitude: 2370ft (+33.2ft)  Datum: WGS-84  Azimuth/Bearing: 143° S37E 2542mils True (+12°)  Elevation Angle: +22.3°  Horizon Angle: +01.2°  Zoom: 1.0X  11710+55</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11710+55	<b>Field Station#</b>	11709+00		
<b>Pic 7 Desc.</b>	Section of Row showing conditions and controls	<b>Pic 8 Desc.</b>	Section of Row showing conditions and controls		
<p>Date &amp; Time: Thu, May 05, 2022, 08:33:08 EDT  Position: +037.27104° / -080.38444° (-23° 16')</p> <p>Altitude: 2431ft (+33.9ft)  Datum: WGS-84  Azimuth/Bearing: 207° N34W 5102mils True (+12°)  Elevation Angle: +04.8°  Horizon Angle: +00.3°  Zoom: 1.0X  11703+85</p> 		<p>Date &amp; Time: Thu, May 05, 2022, 08:35:04 EDT  Position: +037.27155° / -080.37142° (-23° 16')</p> <p>Altitude: 2458ft (+37.4ft)  Datum: WGS-84  Azimuth/Bearing: 204° S24W 3627mils True (+12°)  Elevation Angle: +20.3°  Horizon Angle: +00.3°  Zoom: 1.0X  11687+42 S-MN21</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11703+85	<b>Field Station#</b>	11687+42		
<b>Pic 9 Desc.</b>	P1 silt fence damaged by third party added to punch list for repair	<b>Pic 10 Desc.</b>	Conditions and controls at S-MN21		
<p>Date &amp; Time: Thu, May 05, 2022, 08:35:08 EDT  Position: +037.27055° / -080.38411° (-23° 16')</p> <p>Altitude: 2570ft (+73ft)  Datum: WGS-84  Azimuth/Bearing: 122° S58E 2189mils True (+12°)  Elevation Angle: +01.0°  Horizon Angle: +01.2°  Zoom: 1.0X  11685+75</p> 		<p>Date &amp; Time: Thu, May 05, 2022, 08:35:08 EDT  Position: +037.27055° / -080.38411° (-23° 16')</p> <p>Altitude: 2570ft (+73ft)  Datum: WGS-84  Azimuth/Bearing: 122° S58E 2189mils True (+12°)  Elevation Angle: +01.0°  Horizon Angle: +01.2°  Zoom: 1.0X  11685+75</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11685+75	<b>Field Station#</b>	11677+35		
<b>Pic 11 Desc.</b>	Section of Row showing conditions and controls	<b>Pic 12 Desc.</b>	Section of Row showing conditions and controls		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 11:31 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37346
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	5/5/2022 10:09 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	59.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			




## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 10:09 AM	<b>Report #</b>	37346
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
A regular scheduled VADEQ SWPPP inspection was completed today on JNF and private property at Brush Mountain. The ROW surface remains stable with no erosion occurring. Grasses and/or mulch is adequate at this time. ECDs are in place and functional. No additional ECDs are needed and no maintenance needs were identified. Resource crossings are stable with acceptable buffers and environmental controls in place. No environmental concerns were identified.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 10:09 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu May 05 2022 08:13:27 EDT  Position: +037.252329, -080.479680 (+5022.5m)  Altitude: 247m (+41.2m)  Datum: WGS 84  Azimuth Bearing: 314.7645W 5582mils Magnetic (+12.1)  Elevation Angle: +01.2  Horizon Angle: +00.8  Zoom: 1.0x  11669+00</p> 		<p>Date &amp; Time: Thu May 05 2022 08:50:22 EDT  Position: +037.252329, -080.479680 (+5022.5m)  Altitude: 247m (+41.2m)  Datum: WGS 84  Azimuth Bearing: 251.57W 4400mils Magnetic (+12.1)  Elevation Angle: +33.7  Horizon Angle: -02.4  Zoom: 1.0x  11669+00</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11669+00	<b>Field Station#</b>	11664+00		
<b>Pic 1 Desc.</b>	Conditions stable at top of Brush Mountain.	<b>Pic 2 Desc.</b>	End treatments are functional and effectively controlling stormwater runoff.		
<p>Date &amp; Time: Thu May 05 2022 09:05:22 EDT  Position: +037.252329, -080.479680 (+5022.5m)  Altitude: 247m (+41.2m)  Datum: WGS 84  Azimuth Bearing: 170.510E 3022mils Magnetic (+12.1)  Elevation Angle: +04.5  Horizon Angle: +03.7  Zoom: 1.0x  11662+00</p> 		<p>Date &amp; Time: Thu May 05 2022 09:05:22 EDT  Position: +037.252329, -080.479680 (+5022.5m)  Altitude: 247m (+41.2m)  Datum: WGS 84  Azimuth Bearing: 170.510E 3022mils Magnetic (+12.1)  Elevation Angle: +04.5  Horizon Angle: +03.7  Zoom: 1.0x  11662+00</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11662+00	<b>Field Station#</b>	11656+00		
<b>Pic 3 Desc.</b>	Slope breakers functional. Grasses continue to emerge on JNF property.	<b>Pic 4 Desc.</b>	End treatments are functional. Worn CFS to be replaced once permits are curved and before any ground disturbance occurs.		
<p>Date &amp; Time: Thu May 05 2022 09:05:22 EDT  Position: +037.252329, -080.479680 (+5022.5m)  Altitude: 247m (+41.2m)  Datum: WGS 84  Azimuth Bearing: 170.510E 3022mils Magnetic (+12.1)  Elevation Angle: +04.5  Horizon Angle: +03.7  Zoom: 1.0x  11637+00</p> 		<p>Date &amp; Time: Thu May 05 2022 09:58:33 EDT  Position: +037.252329, -080.479680 (+5022.5m)  Altitude: 247m (+41.2m)  Datum: WGS 84  Azimuth Bearing: 202.50W 4302mils Magnetic (+12.1)  Elevation Angle: +27.7  Horizon Angle: +02.1  Zoom: 1.0x  11626+00</p> 			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11637+00	<b>Field Station#</b>	11626+50		
<b>Pic 5 Desc.</b>	Perimeter ECDs are in place and ROW stable.	<b>Pic 6 Desc.</b>	Sumps and end treatments are effective.		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/5/2022 10:09 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, May 05, 2022, 09:59:59 EDT Position: +037.314005 / -080.402203 (±50.0m) Altitude: 581m (±32.0m) Datum: WGS-84 Azimuth/Bearing: 307.0°/31W 616°mils Magnetic (±12°) Elevation Angle: -10.3° Horizon Angle: -00.2° Zoom: 1.0X 11626+04, S-HH18</small></p>		 <p><small>Date &amp; Time: Thu, May 05, 2022, 09:59:21 EDT Position: +037.314005 / -080.402203 (±50.0m) Altitude: 581m (±32.0m) Datum: WGS-84 Azimuth/Bearing: 307.0°/31W 616°mils Magnetic (±12°) Elevation Angle: -10.3° Horizon Angle: -00.2° Zoom: 1.0X 11614+75</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11614+75		
<b>Pic 7 Desc.</b>	The S-HH18 crossing is stable.	<b>Pic 8 Desc.</b>	Sumps and end treatments in good condition.		
 <p><small>Date &amp; Time: Thu, May 05, 2022, 09:13:11 EDT Position: +037.314005 / -080.402203 (±50.0m) Altitude: 590m (±32.0m) Datum: WGS-84 Azimuth/Bearing: 249° S69W 442°mils Magnetic (±12°) Elevation Angle: -10.3° Horizon Angle: -00.2° Zoom: 1.0X 11608+17, S-006</small></p>		<div style="text-align: center; height: 100px;">Insert image here</div>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>			
<b>Field Station#</b>	11608+17	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	The S-006 crossing is stable.	<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 10:09 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37356
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/5/2022 12:27 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+89
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	51.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 12:27 PM	<b>Report #</b>	37356
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>See photos for GPS coordinates.</p> <p>Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). There had been no rain fall accumulation in the last 24 hours. The row is well vegetated and no erosion issues at this time.</p> <p>No Deficiencies documented for repairs today.</p> <p>This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time. There are herbaceous vegetation that continue to grow from the permanent water bars. Permanent water bars have been installed and appear to be functioning as intended. (Other in section 6 above).</p> <p>Level Spreaders are functional</p> <p>Precision Crews: No crews observed on site.</p> <p>All other perimeter controls, ECDs and BMPs are weathered but appear to be functional at time of inspection. Vegetation is abundant and sufficient. At this time.</p> <p>No impact to sensitive resources observed. Assessed Ar 266.03. No issues</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		5/5/2022 12:27 PM		Report #							
Pictures															
															
GPS Location				See Photo				GPS Location				See Photo			
Field Station#				11978+86				Field Station#				11972+00			
Pic 1 Desc.				P1, super silt fence, and CFS remain functional along the perimeters of the row.				Pic 2 Desc.				Final Restoration Area. Permanent water bars extend across the LOD. No erosion issues.			
															
GPS Location				See Photo				GPS Location				See Photo			
Field Station#				11949+00				Field Station#				11921+00			
Pic 3 Desc.				Final Restoration Area. There are shrubs that have re-emerged within the permanent water bars. This one is roughly about 1" in diameter.				Pic 4 Desc.				Final Restoration Area. Staggered permanent water bars and row conditions.			
															
GPS Location				See Photo				GPS Location				See Photo			
Field Station#				11913+00				Field Station#				11900+81			
Pic 5 Desc.				Permanent level spreader and heavily vegetated permanent water bar.				Pic 6 Desc.				Heavy vegetation of row adjacent to 266.03 AR.			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 12:27 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/5/2022 12:27 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37386
<b>Inspector</b>	Joe Sweeden			<b>Date/Time</b>	5/6/2022 7:28 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+46
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			


## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No





AFE 124300137		Date/Time	5/6/2022 7:28 AM	Report #	
Pictures					
					
GPS Location		See photo		GPS Location	
Field Station#		10882+90		Field Station#	
Pic 1 Desc.		PL item		Pic 2 Desc.	
				S-Y 2	
					
GPS Location		see photo		GPS Location	
Field Station#		10928+00		Field Station#	
Pic 3 Desc.		S-Y 3		Pic 4 Desc.	
				Erosion control blanket	
					
GPS Location		see photo		GPS Location	
Field Station#		10878+00		Field Station#	
Pic 5 Desc.		Water bars		Pic 6 Desc.	
				S-A 32	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2022 7:28 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p> Date &amp; Time: Fri, May 06, 2022, 09:38:58 EDT  Position: -83.7337178, 43.180603759, 1116.411  Altitude: 2352ft (+5.8ft)  Datum: WGS-84  Azimuth/Bearing: 043, N43E, 0764mils Magnetic (+12.1)  Elevation/Angle: -29.8  Horizon/Angle: -07.6  Zoom: 100  10864+00  Spread G </p>		 <p> Date &amp; Time: Fri, May 06, 2022, 09:40:31 EDT  Position: -83.7337178, 43.180603759, 1116.411  Altitude: 2352ft (+5.8ft)  Datum: WGS-84  Azimuth/Bearing: 122, S58E, 2169mils Magnetic (+12.1)  Elevation/Angle: -11.7  Horizon/Angle: -01.2  Zoom: 100  10869+00  Spread G </p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	see photo	
<b>Field Station#</b>	10864+00		<b>Field Station#</b>	10869+00	
<b>Pic 7 Desc.</b>	Slope drain		<b>Pic 8 Desc.</b>	Temporary vegetation	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2022 7:28 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		





# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37388
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/6/2022 7:32 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10749+92
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			




## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2022 7:32 AM	<b>Report #</b>	37388
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed aVA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). No Compliance issues noted: Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2022 7:32 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time Fri May 06, 2022 05:14:35 EDT  Position: +48°34'52.97" / -90.677748" (-100.678)  Altitude: 2419ft (-1.34ft)  Datum: WGS-84  Azimuth Bearing: 143° 54'00" 529mils True (+10°)  Elevation Angle: -0.2°  Horizon Angle: -0.5°  Zoom: 1.0x  10715+31</p> 		<p>Date &amp; Time Fri May 06, 2022 08:09:11 EDT  Position: +48°34'52.97" / -90.641421" (-100.641421)  Altitude: 2319ft (-1.34ft)  Datum: WGS-84  Azimuth Bearing: 103° 57'E 1891mils True (+10°)  Elevation Angle: +0.1°  Horizon Angle: +0.2°  Zoom: 2.0x  10712+73</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10715+31	<b>Field Station#</b>	10712+73		
<b>Pic 1 Desc.</b>	Water bars in place	<b>Pic 2 Desc.</b>	Equipment bridge functional		
<p>Date &amp; Time Fri May 06, 2022 08:09:11 EDT  Position: +48°34'52.97" / -90.677748" (-100.678)  Altitude: 2419ft (-1.34ft)  Datum: WGS-84  Azimuth Bearing: 103° 57'E 1891mils True (+10°)  Elevation Angle: +0.1°  Horizon Angle: +0.3°  Zoom: 1.0x  10698+00</p> 		<p>Date &amp; Time Fri May 06, 2022 08:09:11 EDT  Position: +48°34'52.97" / -90.641421" (-100.641421)  Altitude: 2319ft (-1.34ft)  Datum: WGS-84  Azimuth Bearing: 103° 57'E 1891mils True (+10°)  Elevation Angle: +0.1°  Horizon Angle: +0.2°  Zoom: 1.0x  10703+00</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10698+00	<b>Field Station#</b>	10703+00		
<b>Pic 3 Desc.</b>	P1 and wattles in place	<b>Pic 4 Desc.</b>	Water bars and ET in place		
<p>Date &amp; Time Fri May 06, 2022 08:09:11 EDT  Position: +48°34'52.97" / -90.677748" (-100.678)  Altitude: 2419ft (-1.34ft)  Datum: WGS-84  Azimuth Bearing: 103° 57'E 1891mils True (+10°)  Elevation Angle: +0.1°  Horizon Angle: +0.0°  Zoom: 1.0x  10694+00</p> 		<p>Date &amp; Time Fri May 06, 2022 09:00:10 EDT  Position: +48°34'52.97" / -90.641421" (-100.641421)  Altitude: 2306ft (-1.34ft)  Datum: WGS-84  Azimuth Bearing: 298° N42W 5298mils True (+12°)  Elevation Angle: +0.0°  Horizon Angle: -0.0°  Zoom: 1.0x  10733+20</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10694+00	<b>Field Station#</b>	10733+20		
<b>Pic 5 Desc.</b>	Clean water drainage feature functional	<b>Pic 6 Desc.</b>	Equipment bridge functional		



<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2022 7:32 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10683+50	<b>Field Station#</b>	10748+00		
<b>Pic 7 Desc.</b>	Level spreader in place	<b>Pic 8 Desc.</b>	RCE functional		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	10658+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Water bars and ET in place	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2022 7:32 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37410
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/6/2022 4:25 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10797+92
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2022 4:25 PM	<b>Report #</b>	37410
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10747+92 (Hendrickson Road) to ST# 10798+92 (Cascade Road) Accompanied by EI Trey Ingram on SWPPP inspection from MP 204.53 to MP 205.67. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crews walking through section checking ECDs. This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. Sensitive resource buffers are in place at streams S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2. Hendrickson Road, Big Branch Hollow Road, and Cascade Road crossings RCEs are maintained and in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2022 4:25 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo.	<b>GPS Location</b>	See photo.		
<b>Field Station#</b>	10752+00	<b>Field Station#</b>	10758+00		
<b>Pic 1 Desc.</b>	Waterbars in place.	<b>Pic 2 Desc.</b>	Sensitive resource buffer in place at stream S-G35.		
					
<b>GPS Location</b>	See photo.	<b>GPS Location</b>	See photo.		
<b>Field Station#</b>	10762+00	<b>Field Station#</b>	10766+50		
<b>Pic 3 Desc.</b>	Rock inlet in place at slope drain.	<b>Pic 4 Desc.</b>	Clean water diversion pipe and level spreader in place.		
					
<b>GPS Location</b>	See photo.	<b>GPS Location</b>	See photo.		
<b>Field Station#</b>	10780+00	<b>Field Station#</b>	10797+00		
<b>Pic 5 Desc.</b>	ROW temporarily stabilized. Vegetation growth present.	<b>Pic 6 Desc.</b>	RCE in place at Cascade Road.		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2022 4:25 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2022 4:25 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37391
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/6/2022 8:42 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10859+46
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Stone Inlet Protection	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			



## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2022 8:42 AM	<b>Report #</b>	37391
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46). Accompanied by fellow EI Clint Sears. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Updated SWPPP documents.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					



<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2022 8:42 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	10859+46	<b>Field Station#</b>	10856+04		
<b>Pic 1 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	S-A33.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	10865+70	<b>Field Station#</b>	10835+50		
<b>Pic 3 Desc.</b>	S-A34.	<b>Pic 4 Desc.</b>	Section of RoW showing conditions and controls.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	10826+00	<b>Field Station#</b>	10818+50		
<b>Pic 5 Desc.</b>	CWDP outlet protection functional.	<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/6/2022 8:42 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	10799+11	<b>Field Station#</b>	10801+52		
<b>Pic 7 Desc.</b>	Overview S-Z10/W-Z3.	<b>Pic 8 Desc.</b>	Overview S-Z11/S-Z12/S-Z13.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/6/2022 8:42 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		