



# Visual Site Inspection Report


<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37483
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/9/2022 6:09 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11098+47
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	51.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	2.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Stone Inlet Protection	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/9/2022 6:09 PM	<b>Report #</b>	37483
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. Fellow EI Joe Sweeden assisted in the inspection today          "Station numbers are approximate".          Observed Activity: No Activity observed in this area of inspection today.          The ROW in that area received 0.5" of precipitation in the last 48 hours. the row remains damp with small patches of storm water. No issues at this time.</p> <p>The ROW from AR 244 near 11025+02 to near 11070+21 has been temporarily stabilized. No erosion issues.          The ROW from station 11070+21 to near 11098+00 has had final Restoration completed. There are 12" CFS that are being used as water bars (section 6) at this time. There are no erosion issues visible in the final restored areas. The perimeter controls appear to be functional at this time.          One area of open ditch (approximately 270') near 11061+00. Rock Road approaches were cleaned and functioning as intended. No sensitive resources have been impacted. Undisturbed Fully vegetated buffer zones are protected with functional ECDs.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/9/2022 6:09 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11025+25	<b>Field Station#</b>	11045+00		
<b>Pic 1 Desc.</b>	S-IJ18 Equipment bridge condition.	<b>Pic 2 Desc.</b>	Temporary stabilization of water bar and sump pit condition.		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11050+10	<b>Field Station#</b>	11054+20		
<b>Pic 3 Desc.</b>	S-IJ 16 & 17. Adequate vegetation remains. Buffer zones protected as well.	<b>Pic 4 Desc.</b>	Temporary stabilization of row		
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11066+00	<b>Field Station#</b>	11064+85		
<b>Pic 5 Desc.</b>	Temporary stabilization of steep slope and water bars. Perimeter controls	<b>Pic 6 Desc.</b>	Drainage feature conditions. Re-emerging vegetation visible.		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/9/2022 6:09 PM	<b>Report #</b>	
<b>Pictures</b>					
<small>Date &amp; Time: Mon, May 09, 2022, 09:31:03 EDT  Position: +037 315378 / -080 541650 (+50 9ft)  Altitude: 2115ft (+78 7ft)  Datum: WGS-84  Azimuth/Bearing: 098° N78E 1387mils True (+12°)  Elevation Grade: +005%  Horizon Grade: +004%  Zoom: 0.5X  11072+00</small> 		<small>Date &amp; Time: Mon, May 09, 2022, 09:42:41 EDT  Position: +037 313246 / -080 533870 (+34 4ft)  Altitude: 1953ft (+52 5ft)  Datum: WGS-84  Azimuth/Bearing: 185° S05W 3289mils True (+12°)  Elevation Grade: +005%  Horizon Grade: +004%  Zoom: 0.5X  11093+47</small> 			
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11072+00		<b>Field Station#</b>	11093+47	
<b>Pic 7 Desc.</b>	Final Restoration Area		<b>Pic 8 Desc.</b>	Permanent restoration area. Recent reseedling has occurred.	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 9 Desc.</b>			<b>Pic 10 Desc.</b>		
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/9/2022 6:09 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37458
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/9/2022 9:06 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11098+47
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11184+85
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.50
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Problem Area	See punch list		
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Cleanwater Diversion Pipe	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/9/2022 9:06 AM	<b>Report #</b>	37458
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85) Accompanied by fellow EI Clint Sears. One location of insufficient vegetation/stabilization identified and added to the punch list following proper notifications. Location with insufficient permanent vegetation, 11099+00-11105+00, is within tract VA-GI-066. Discussed permanent seed mix reference, for this tract, within LoWs with LEI Brian Shields, Josh Gledhill, Fellow EI Clint Sears, PPL environmental Coordinator Mike Perry and Environmental Foreman Grant Hercules. Seed mix in LoWs states Orchard Grass and 10% red clover. This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient, less area added to punch list. No impact to sensitive resources observed. Section 6 - other (waterbars) Assessed AR 245.02 and AR 249.02.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/9/2022 9:06 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11184+85	<b>Field Station#</b>	11175+50		
<b>Pic 1 Desc.</b>	Section of restored RoW showing conditions and controls.		<b>Pic 2 Desc.</b>	Section of restored RoW showing conditions and controls.	
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11167+50	<b>Field Station#</b>	11159+25		
<b>Pic 3 Desc.</b>	CWDP outlet protection functional.		<b>Pic 4 Desc.</b>	S-NN17.	
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11105+00	<b>Field Station#</b>	11117+00		
<b>Pic 5 Desc.</b>	Insufficient permanent vegetation.		<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/9/2022 9:06 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Mon, May 09, 2022, 10:24:52 EDT  Position: 1412976.118 E / 362817.170 N (±15.1ft)  Altitude: 2042ft (±11.7ft)  Datum: WGS-84  Azimuth/Bearing: 294° N66W 5227mils True (±12°)  Elevation Angle: +11.4°  Horizon Angle: +01.0°  Zoom: 0.5X  11151+00</p> 		<p>Date &amp; Time: Mon, May 09, 2022, 10:12:45 EDT  Position: 141202.966 E / 363781.706 N (±18.8ft)  Altitude: 1943ft (±11.4ft)  Datum: WGS-84  Azimuth/Bearing: 117° S63E 2080mils True (±12°)  Elevation Angle: +12.2°  Horizon Angle: -02.3°  Zoom: 0.5X  11129+00</p> 			
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	11151+00	<b>Field Station#</b>	11129+00		
<b>Pic 7 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 8 Desc.</b>	Section of restored RoW showing conditions and controls.	
<p>Date &amp; Time: Mon, May 09, 2022, 10:16:55 EDT  Position: 1411505.580 E / 363525.040 N (±42.3ft)  Altitude: 2131ft (±105.0ft)  Datum: WGS-84  Azimuth/Bearing: 112° S68E 1991mils True (±12°)  Elevation Angle: +00.9°  Horizon Angle: +02.2°  Zoom: 0.5X  11133+50</p> 		<p>Date &amp; Time: Mon, May 09, 2022, 10:19:20 EDT  Position: 1411999.040 E / 363173.882 N (±19.9ft)  Altitude: 2140ft (±11.7ft)  Datum: WGS-84  Azimuth/Bearing: 103° S77E 1831mils True (±12°)  Elevation Angle: +01.2°  Horizon Angle: -05.3°  Zoom: 0.5X  11139+25</p> 			
<b>GPS Location</b>	9	<b>GPS Location</b>	10		
<b>Field Station#</b>	11133+50	<b>Field Station#</b>	11139+50		
<b>Pic 9 Desc.</b>	Representative photo of permanent waterbar and level spreaders installed.		<b>Pic 10 Desc.</b>	Section of restored RoW showing conditions and controls.	
Insert image here		Insert image here			
<b>GPS Location</b>	11	<b>GPS Location</b>			
<b>Field Station#</b>	11151+00	<b>Field Station#</b>			
<b>Pic 11 Desc.</b>	Section of RoW showing conditions and controls.		<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/9/2022 9:06 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37450
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/9/2022 7:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11184+85
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Muddy	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.60
				<b>Rain Accumulation Time (days)</b>	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/9/2022 7:40 AM	<b>Report #</b>	37450
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). No Compliance issues noted: Observance: Perimeter controls in place Permanent & temporary stabilization in place. - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. @11222+50 to 11206+27 the stabilization is thin and is being monitored. This area just over seeded last week 4/12/22 & 4/13/22. - Temporary stabilization near 11222+50 to near 11253+50. This section of row has been stabilized for the winter months. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. AR-249.02 & 244 RCE's are maintained in acceptable condition. Some subsidence on both sides of winding way also monitoring it. The ROW is muddy but in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/9/2022 7:40 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Mon, May 09, 2022, 08:30:36 EDT Position: -037.326881 / -080.519111 (-111.19) Altitude: 1920ft (-111.19) Datum: WGS-84 Azimuth/Bearing: 17.555E 330mils True (+12.5) Elevation Angle: -10.3 Horizon Angle: -02.9 Zoom: 2.0X 11191+02</p>		 <p>Date &amp; Time: Mon, May 09, 2022, 08:30:36 EDT Position: -037.326881 / -080.519111 (-111.19) Altitude: 1920ft (-111.19) Datum: WGS-84 Azimuth/Bearing: 17.555E 330mils True (+12.5) Elevation Angle: -10.3 Horizon Angle: -02.9 Zoom: 2.0X 11193+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11191+02	<b>Field Station#</b>	11193+00		
<b>Pic 1 Desc.</b>	Clean water drainage feature functional	<b>Pic 2 Desc.</b>	Permanent water bars and level spreader in place		
 <p>Date &amp; Time: Mon, May 09, 2022, 08:19:35 EDT Position: -037.307261 / -080.519111 (-111.19) Altitude: 1953ft (-111.19) Datum: WGS-84 Azimuth/Bearing: 084.584E 152mils True (+12.5) Elevation Angle: +07.1 Horizon Angle: -00.3 Zoom: 2.0X 11185+00</p>		 <p>Date &amp; Time: Mon, May 09, 2022, 08:19:35 EDT Position: -037.307261 / -080.519111 (-111.19) Altitude: 2064ft (-111.19) Datum: WGS-84 Azimuth/Bearing: 082.582E 145mils True (+12.5) Elevation Angle: -02.4 Horizon Angle: -02.2 Zoom: 2.0X 11220+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11185+00	<b>Field Station#</b>	11220+00		
<b>Pic 3 Desc.</b>	Erosion control blanket in place	<b>Pic 4 Desc.</b>	Area being monitored on stabilization		
 <p>Date &amp; Time: Mon, May 09, 2022, 08:18:38 EDT Position: -037.320154 / -080.504098 (-111.19) Altitude: 2089ft (-111.19) Datum: WGS-84 Azimuth/Bearing: 337.577W 510mils True (+12.5) Elevation Angle: +07.1 Horizon Angle: -02.3 Zoom: 1.0X 11218+00</p>		 <p>Date &amp; Time: Mon, May 09, 2022, 08:18:38 EDT Position: -037.320154 / -080.504098 (-111.19) Altitude: 2119ft (-111.19) Datum: WGS-84 Azimuth/Bearing: 341.581E 350mils True (+12.5) Elevation Angle: +07.1 Horizon Angle: -00.3 Zoom: 2.0X 11233+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11218+00	<b>Field Station#</b>	11233+00		
<b>Pic 5 Desc.</b>	Picture showing condition of row	<b>Pic 6 Desc.</b>	Water bars in place		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/9/2022 7:40 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11227+59	<b>Field Station#</b>	11252+50		
<b>Pic 7 Desc.</b>	Rock check dams in place	<b>Pic 8 Desc.</b>	SSF and ET in place		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/9/2022 7:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report







<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Roberts Corrosion			<b>Report #</b>	37478
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/9/2022 3:50 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10929+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11023+80
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	65.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.30
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

<b>5. Site Conditions</b>	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/9/2022 3:50 PM	<b>Report #</b>	37478
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10929+80 (Doe Creek Road) to ST# 11023+80 (Access Road 244) Accompanied by EI Trey Ingram on SWPPP inspection from MP 207 to MP 208.78. No deficiencies located during inspection. Active construction site; additional deficiencies may be identified by other EIs. This section of ROW is temporarily stabilized with seed and mulch. Minor vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. ROW permanently stabilized from station number 10961+75 to station number 10940+25. Area is stabilized with seed and mulch. Vegetation growth is present. CFS in place to minimize rilling and maintain sheet flow. Sensitive resource buffers are in place at streams S-PA07, S-RR5, S-E24, and S-E25. Triple barrier protection around karst feature located at station number 10966+00. RCEs in place and maintained at Doe Creek Road crossing, Access Road 244, and Access Road 241.02. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137	Date/Time	5/9/2022 3:50 PM	Report #	
Pictures						
 <p>Date &amp; Time: Mon, May 09, 2022, 03:53:25 EDT Position: +037.325741° / -080.554920° (±6295.9ft) Altitude: 2399ft (±168.6ft) Datum: WGS-84 Azimuth Bearing: 297° N±3W 3480mils True (±18°) Elevation Angle: -01.7° Horizon Angle: +03.3° Zoom: 1.0X 11015+00</p>			 <p>Date &amp; Time: Mon, May 09, 2022, 09:06:56 EDT Position: +037.325741° / -080.554920° (±6295.9ft) Altitude: 2424ft (±179.0ft) Datum: WGS-84 Azimuth Bearing: 193° S±3W 3431mils True (±18°) Elevation Angle: -26.7° Horizon Angle: +03.6° Zoom: 1.0X 11008+75</p>			
GPS Location		See photo.		GPS Location		See photo.
Field Station#		11015+00		Field Station#		11008+75
Pic 1 Desc.		Sensitive resource buffer in place at streams S-PA09 and S-RR5.		Pic 2 Desc.		Clean water diversion pipe and level spreader in place.
 <p>Date &amp; Time: Mon, May 09, 2022, 09:22:17 EDT Position: +037.325741° / -080.554920° (±6295.9ft) Altitude: 2399ft (±168.6ft) Datum: WGS-84 Azimuth Bearing: 204° S±2W 3462mils True (±15°) Elevation Angle: -30.4° Horizon Angle: -00.1° Zoom: 1.0X 10978+00</p>			 <p>Date &amp; Time: Mon, May 09, 2022, 09:55:34 EDT Position: +037.325741° / -080.554920° (±6295.9ft) Altitude: 2424ft (±179.0ft) Datum: WGS-84 Azimuth Bearing: 300° N±2W 3093mils True (±16°) Elevation Angle: -16.4° Horizon Angle: +01.7° Zoom: 1.0X 10966+00</p>			
GPS Location		See photo.		GPS Location		See photo.
Field Station#		10978+00		Field Station#		10966+00
Pic 3 Desc.		Rock inlet in place at slope drain.		Pic 4 Desc.		Triple barrier ECDs in place at cave.
 <p>Date &amp; Time: Mon, May 09, 2022, 09:37:14 EDT Position: +037.322699° / -080.572848° (±6377.4ft) Altitude: 2299ft (±1345.8ft) Datum: WGS-84 Azimuth Bearing: 292° N±8W 5191mils True (±16°) Elevation Angle: -05.1° Horizon Angle: +03.7° Zoom: 1.0X 10961+75</p>			 <p>Date &amp; Time: Mon, May 09, 2022, 09:55:34 EDT Position: +037.325741° / -080.554920° (±6295.9ft) Altitude: 2128ft (±111.3ft) Datum: WGS-84 Azimuth Bearing: 340° N±2W 3000mils True (±16°) Elevation Angle: -14.1° Horizon Angle: +00.1° Zoom: 1.0X 10930+25</p>			
GPS Location		See photo.		GPS Location		See photo.
Field Station#		10961+75		Field Station#		10930+25
Pic 5 Desc.		ROW permanently stabilized.		Pic 6 Desc.		RCE in place at Doe Creek Road.

<b>A/E</b>	124300137	<b>Date/Time</b>	5/9/2022 3:50 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/9/2022 3:50 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37523
<b>Inspector</b>	Clint Sears			<b>Date/Time</b>	5/10/2022 1:25 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11471+56
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Housekeeping	Acceptable			
Equipment Bridge	Acceptable			
Waterbar	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 1:25 PM	<b>Report #</b>	37523
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental staff. Completed VA SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56). This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Row is damp and in stable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 5/10/2022 1:25 PM		Report #			
Pictures							
<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:50:40 EDT Position: +037.307643° / -080.446504° (-60.0ft) Altitude: 1958ft (-64.1ft) Datum: WGS-84 Azimuth/Bearing: 001° S41W 428mils True (-121°) Elevation Angle: -06.8° Horizon Angle: +00.9° Zoom: 1.0X 11360+65</div><div></div></div></div>				<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:44:57 EDT Position: +037.309591° / -080.426721° (-62.9ft) Altitude: 206ft (-62.8ft) Datum: WGS-84 Azimuth/Bearing: 040° N00E 671mils True (-121°) Elevation Angle: -02.0° Horizon Angle: +00.0° Zoom: 1.0X 11374+00</div><div></div></div></div>			
GPS Location		See photo		GPS Location		See photo	
Field Station#		11360+65		Field Station#		11374+00	
Pic 1 Desc.		Section of Row showing conditions and controls at S-KL43		Pic 2 Desc.		Section of Row showing conditions and controls	
<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:36:55 EDT Position: +047.309222° / -081.458192° (-78.8ft) Altitude: 232ft (-78.7ft) Datum: WGS-84 Azimuth/Bearing: 288° N80W 458mils True (-121°) Elevation Angle: -15.6° Horizon Angle: -02.0° Zoom: 1.0X 11397+15</div><div></div></div></div>				<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:31:26 EDT Position: +057.312835° / -080.451841° (-63.7ft) Altitude: 227ft (-68.7ft) Datum: WGS-84 Azimuth/Bearing: 221° S41W 392mils True (-121°) Elevation Angle: -11.7° Horizon Angle: -00.3° Zoom: 1.0X 11412+00</div><div></div></div></div>			
GPS Location		See photo		GPS Location		See photo	
Field Station#		11397+15		Field Station#		11412+00	
Pic 3 Desc.		Section of Row showing conditions and controls		Pic 4 Desc.		Section of Row showing conditions and controls	
<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:18:52 EDT Position: +037.318466° / -080.449925° (-62.9ft) Altitude: 233ft (-74.4ft) Datum: WGS-84 Azimuth/Bearing: 231° S51W 410mils True (-121°) Elevation Angle: -00.5° Horizon Angle: +01.1° Zoom: 1.0X 11418+45</div><div></div></div></div>				<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:12:19 EDT Position: +037.324424° / -080.448727° (-62.9ft) Altitude: 213ft (-62.4ft) Datum: WGS-84 Azimuth/Bearing: 077° N06E 106mils True (-121°) Elevation Angle: -03.1° Horizon Angle: +01.8° Zoom: 1.0X 11432+00</div><div></div></div></div>			
GPS Location		See photo		GPS Location		See photo	
Field Station#		11418+45		Field Station#		11432+00	
Pic 5 Desc.		Section of Row showing conditions and controls		Pic 6 Desc.		Section of Row showing conditions and controls	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/10/2022 1:25 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11443+00	<b>Field Station#</b>	11448+70		
<b>Pic 7 Desc.</b>	Section of Row showing conditions and controls	<b>Pic 8 Desc.</b>	W-CD12		
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11451+35	<b>Field Station#</b>	11468+87		
<b>Pic 9 Desc.</b>	Conditions and controls at S-OO12&13	<b>Pic 10 Desc.</b>	S-CD14		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 1:25 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37523
<b>Inspector</b>	Clint Sears			<b>Date/Time</b>	5/10/2022 1:25 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11471+56
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	73.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Housekeeping	Acceptable			
Equipment Bridge	Acceptable			
Waterbar	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sensitive Resource Buffer	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 1:25 PM	<b>Report #</b>	37523
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental staff. Completed VA SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56). This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Row is damp and in stable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 5/10/2022 1:25 PM		Report #			
Pictures							
<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:50:40 EDT Position: +037.307643° / -080.446504° (-60.0ft) Altitude: 1958ft (-64.1ft) Datum: WGS-84 Azimuth/Bearing: 001° S41W 428mils True (-121°) Elevation Angle: -06.8° Horizon Angle: +00.9° Zoom: 1.0X 11360+65</div><div></div></div></div>				<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:44:57 EDT Position: +037.309591° / -080.426721° (-62.9ft) Altitude: 206ft (-62.8ft) Datum: WGS-84 Azimuth/Bearing: 040° N00E 671mils True (-121°) Elevation Angle: -02.0° Horizon Angle: +00.0° Zoom: 1.0X 11374+00</div><div></div></div></div>			
GPS Location		See photo		GPS Location		See photo	
Field Station#		11360+65		Field Station#		11374+00	
Pic 1 Desc.		Section of Row showing conditions and controls at S-KL43		Pic 2 Desc.		Section of Row showing conditions and controls	
<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:36:55 EDT Position: +047.309222° / -081.458192° (-78.8ft) Altitude: 232ft (-78.8ft) Datum: WGS-84 Azimuth/Bearing: 288° N80W 458mils True (-121°) Elevation Angle: -15.6° Horizon Angle: -02.0° Zoom: 1.0X 11397+15</div><div></div></div></div>				<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:31:26 EDT Position: +057.312835° / -080.451841° (-63.7ft) Altitude: 227ft (-68.7ft) Datum: WGS-84 Azimuth/Bearing: 221° S41W 392mils True (-121°) Elevation Angle: -11.7° Horizon Angle: -00.3° Zoom: 1.0X 11412+00</div><div></div></div></div>			
GPS Location		See photo		GPS Location		See photo	
Field Station#		11397+15		Field Station#		11412+00	
Pic 3 Desc.		Section of Row showing conditions and controls		Pic 4 Desc.		Section of Row showing conditions and controls	
<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:18:52 EDT Position: +037.318466° / -080.449925° (-62.9ft) Altitude: 233ft (-77.4ft) Datum: WGS-84 Azimuth/Bearing: 231° S51W 4107mils True (-121°) Elevation Angle: -00.5° Horizon Angle: +01.1° Zoom: 1.0X 11418+45</div><div></div></div></div>				<div><div><div>Date &amp; Time: Tue, May 10, 2022, 09:12:19 EDT Position: +037.324424° / -080.448727° (-62.9ft) Altitude: 213ft (-62.4ft) Datum: WGS-84 Azimuth/Bearing: 077° N06E 1069mils True (-121°) Elevation Angle: -03.1° Horizon Angle: +01.8° Zoom: 1.0X 11432+00</div><div></div></div></div>			
GPS Location		See photo		GPS Location		See photo	
Field Station#		11418+45		Field Station#		11432+00	
Pic 5 Desc.		Section of Row showing conditions and controls		Pic 6 Desc.		Section of Row showing conditions and controls	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/10/2022 1:25 PM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11443+00	<b>Field Station#</b>	11448+70		
<b>Pic 7 Desc.</b>	Section of Row showing conditions and controls	<b>Pic 8 Desc.</b>	W-CD12		
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11451+35	<b>Field Station#</b>	11468+87		
<b>Pic 9 Desc.</b>	Conditions and controls at S-OO12&13	<b>Pic 10 Desc.</b>	S-CD14		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 1:25 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37524
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/10/2022 1:31 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11353+67
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	49.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

- |   |     |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?   | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings?<br>(If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)          | No  |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)  |     |



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Plunge Pool	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 1:31 PM	<b>Report #</b>	37524
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Temporary stabilization near 11296+00.					
<b>Comments</b> (Reference above questions as appropriate.) Completed a Virginia SWPP inspection from station # 11254+99 to 11353+67 (MP 213.6-215.04) Rte 42 to Old Furnace Rd. "Station numbers are approximate." Observances: Environmental crew 1709 was on site near even Oaks and completed the temporary stabilization requirements. The ROW has been temporarily stabilized and remains at a stable repose. No erosion issues at this time. There is slightly visible temporary grasses throughout the areas of inspection. Karst areas have been previously assumed in sump locations near station 11348+00 and near station 11349+77. The water bars and compost sock remain in a functional condition in these areas as well as all other areas of inspection. Steep slopes have erosion control fabric (CC4) installed. There is limited visible growth where the CC4 ECB have been installed. There is visible vegetation that has begun to re-emerge. There may be more areas needing to be re-seeded. Slope drains are functioning as intended without issues. Stone inlet protections are also functional at this time. There are three stream resources in the areas of inspection. Conditions are as follows: S-MM18 - near 11292+80 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required. S-NN12 - near 11327+80 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required. S-NN11 - near 11352+97 - Equipment bridge functional, vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required. All perimeter controls, ECDs and BMPs were functional at time of inspection. No other crews were working in the area. Rock Road approaches and access roads are clean and free of loose rock and debris.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 1:31 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Tue May 10, 2022 08:17:35 EDT Position: +037.205412 / -080.467182 (±23.4ft) Altitude: 200ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 196° S16W 3484mils True (±12°) Elevation Grade: +001% Horizon Grade: -009% Zoom: 2.0x 11353+22</p>		 <p>Date &amp; Time: Tue May 10, 2022 08:18:00 EDT Position: +037.296386 / -080.451727 (±15.9ft) Altitude: 2169ft (±9.8ft) Datum: WGS-84 Azimuth/Bearing: 069° N49E 1227mils True (±12°) Elevation Grade: +030% Horizon Grade: +001% Zoom: 1.0x 11293+00 S-MM18</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11353+22	<b>Field Station#</b>	11293+00		
<b>Pic 1 Desc.</b>	S-NN11 stream bridge condition.	<b>Pic 2 Desc.</b>	Over view of the S-MM18 stream resource. Adequate stabilization and perimeter controls are functional.		
 <p>Date &amp; Time: Tue May 10, 2022 08:43:29 EDT Position: +037.298223 / -080.474579 (±11.6ft) Altitude: 2308ft (±13.1ft) Datum: WGS-84 Azimuth/Bearing: 196° S16W 3484mils True (±12°) Elevation Grade: +012% Horizon Grade: -002% Zoom: 0.5x 11317+00</p>		 <p>Date &amp; Time: Tue May 10, 2022 08:23:20 EDT Position: +037.296608 / -080.479794 (±15.7ft) Altitude: 2189ft (±10.9ft) Datum: WGS-84 Azimuth/Bearing: 209° S29W 3716mils True (±12°) Elevation Grade: -022% Horizon Grade: -012% Zoom: 0.5x 11296+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11317+00	<b>Field Station#</b>	11296+00		
<b>Pic 3 Desc.</b>	Temporary stabilization and vegetated top soil pile.	<b>Pic 4 Desc.</b>	Completed temporary stabilization near Seven Oaks Rd.		
 <p>Date &amp; Time: Tue May 10, 2022 08:10:42 EDT Position: +037.234926 / -080.483348 (±16.3ft) Altitude: 2233ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 277° N83W 4926mils True (±12°) Elevation Grade: -038% Horizon Grade: -011% Zoom: 1.0x 11289+00</p>		 <p>Date &amp; Time: Tue May 10, 2022 08:01:56 EDT Position: +037.246174 / -080.488930 (±10.3ft) Altitude: 2312ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 069° N49E 1227mils True (±12°) Elevation Grade: -048% Horizon Grade: -005% Zoom: 0.5x 11269+33</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11289+00	<b>Field Station#</b>	11269+33		
<b>Pic 5 Desc.</b>	Temporary stabilization of side slope with CC4 ECB.	<b>Pic 6 Desc.</b>	Stone inlet protection conditions.		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/10/2022 1:31 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11269+00	<b>Field Station#</b>	11259+00		
<b>Pic 7 Desc.</b>	CWDB and Plunge Pool conditions.	<b>Pic 8 Desc.</b>	Temporary stabilization of row and temporary water bar condition.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 1:31 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37511
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/10/2022 3:48 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11471+56
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11524+16
<b>County</b>	Craig	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	74.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/10/2022 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11473+00		<b>Field Station#</b>	11476+00	
<b>Pic 1 Desc.</b>	Triple barrier ECD protection at off ROW karst area.		<b>Pic 2 Desc.</b>	Rock inlet in place at slope drain.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11486+50		<b>Field Station#</b>	11490+00	
<b>Pic 3 Desc.</b>	Clean water diversion pipe and plunge pool in place.		<b>Pic 4 Desc.</b>	RCE in place at Stevers Gap Road.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11504+00		<b>Field Station#</b>	11514+00	
<b>Pic 5 Desc.</b>	Rock lined channel in place.		<b>Pic 6 Desc.</b>	Sensitive resource buffer in place at stream S-PP4.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/10/2022 3:48 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37555
<b>Inspector</b>	Rob Robertson			<b>Date/Time</b>	5/11/2022 10:54 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11670+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Rock Construction Entrance	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 10:54 AM	<b>Report #</b>	37555
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
A regular scheduled VADEQ SWPPP inspection on JNF and private properties at Brush Mountain was completed today. The ROW remains stable with no erosion occurring. The perimeter ECDs are in place and adequate for control of any sediment movement. Slope breakers are in place and functioning properly. No ECD maintenance needs were identified today. There is no impact to resources crossed by the route and the stream buffers are stable. RCEs are in good condition. No environmental					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/11/2022 10:54 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11668+00	<b>Field Station#</b>	11666+00		
<b>Pic 1 Desc.</b>	Perimeter ECDs are functional.	<b>Pic 2 Desc.</b>	Perimeter ECDs are functional.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11662+00	<b>Field Station#</b>	11659+00		
<b>Pic 3 Desc.</b>	Slope breakers are working properly.	<b>Pic 4 Desc.</b>	Perimeter ECDs are functional.		
					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11645+00	<b>Field Station#</b>	11636+00		
<b>Pic 5 Desc.</b>	Perimeter ECDs are in place.	<b>Pic 6 Desc.</b>	Sumps and end treatments are functioning.		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/11/2022 10:54 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11628+00	<b>Field Station#</b>	11626+04		
<b>Pic 7 Desc.</b>	Perimeter ECDs are adequate.	<b>Pic 8 Desc.</b>	The S-HH18 crossing is stable.		
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11614+20	<b>Field Station#</b>	11607+81		
<b>Pic 9 Desc.</b>	The S-RR14 crossing is stable.	<b>Pic 10 Desc.</b>	The S-006 crossing is stable.		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 10:54 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37564
<b>Inspector</b>	Clint Sears			<b>Date/Time</b>	5/11/2022 12:49 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	77.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Compost Filter Sock	Communication	See punch list		
Vegetative Stabilization (Temporary)	Acceptable			
Stone Inlet Protection	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Housekeeping	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 12:49 PM	<b>Report #</b>	37564
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Met with environmental staff. Completed VA SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52) Deficiencies found at the following station number. Sta#11745+50 CFS need maintenance. All deficiencies were communicated to PPL personal via punch list All other perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. RCE at MT Tabor RD was in acceptable condition. Row is damp and in stable condition.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 12:49 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11682+50		<b>Field Station#</b>	11712+00	
<b>Pic 1 Desc.</b>	Stone inlet protection is in acceptable condition		<b>Pic 2 Desc.</b>	Perimeter controls at sump pit are in acceptable condition	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11688+00		<b>Field Station#</b>	11707+00	
<b>Pic 3 Desc.</b>	Section of Row showing conditions and controls		<b>Pic 4 Desc.</b>	Erosion control blanket is in acceptable condition	
					
<b>GPS Location</b>	see photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11745+50		<b>Field Station#</b>	11767+31	
<b>Pic 5 Desc.</b>	CFS added to punch list for maintenance		<b>Pic 6 Desc.</b>	S-IJ52	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/11/2022 12:49 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>North West Elevation Q 159°SE (T) • 37.297312° -80.387668° ±5 m ▲ 730 m</p>		 <p>North West Elevation Q 267°W (T) • 37.296721° -80.361528° ±10 m ▲ 631 m</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11701+00	<b>Field Station#</b>	11785+94		
<b>Pic 7 Desc.</b>	Perimeter controls are in place	<b>Pic 8 Desc.</b>	Section of Row showing conditions and controls		
 <p>South West Elevation Q 190°S (T) • 37.296064° -80.366942° ±6 m ▲ 588 m</p>		 <p>South West Elevation Q 77°NE (T) • 37.294918° -80.37815° ±4 m ▲ 655 m</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11769+00	<b>Field Station#</b>	11737+00		
<b>Pic 9 Desc.</b>	Sump pit and perimeter controls are in acceptable condition	<b>Pic 10 Desc.</b>	Section of Row showing conditions and controls		
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 12:49 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37586
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/11/2022 7:55 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+89
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	12005+00
<b>County</b>	Montgomery	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	55.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Other - Explain in Comments	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 7:55 PM	<b>Report #</b>	37586
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>See photos for GPS coordinates.</p> <p>Completed a VA SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00). There had been no rain fall accumulation in the last 24 hours. The row is well vegetated and no erosion issues at this time.</p> <p>No Deficiencies documented for repairs today.</p> <p>This section of row has been finally restored with heavy vegetation. Perennial and annual grasses are visible at this time. There are herbaceous vegetation that continue to grow from the permanent water bars. Permanent water bars have been installed and appear to be functioning as intended. (Other in section 6 above).</p> <p>Level Spreaders are functional</p> <p>Precision Crews: No crews observed on site.</p> <p>All other perimeter controls, ECDs and BMPs are weathered but appear to be functional at time of inspection. Vegetation is abundant and sufficient. At this time.</p> <p>No impact to sensitive resources observed. Assessed Ar 266.03. No issues</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/11/2022 7:55 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, May 11, 2022 09:39:31 EDT Position: +037.269433° / +080.322691° (+11.6ft) Altitude: 1690ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 068° N48E 3209mils True (+13.1) Elevation Grade: -017% Horizon Grade: -000% Zoom: 0.5X 11978+86 Spread G</p>		 <p>Date &amp; Time: Wed, May 11, 2022 09:38:57 EDT Position: +037.269494° / +080.322724° (+142.0ft) Altitude: 1203ft (+29.6ft) Datum: WGS-84 Azimuth/Bearing: 348° N12W 6187mils True (+13.1) Elevation Grade: -027% Horizon Grade: -005% Zoom: 0.5X 11978+86 Spread G</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11978+86	<b>Field Station#</b>	11978+86		
<b>Pic 1 Desc.</b>	AR 266 and adjacent vegetated row conditions.	<b>Pic 2 Desc.</b>	Perimeter controls protecting presumed		
 <p>Date &amp; Time: Wed, May 11, 2022 09:39:27 EDT Position: +037.269433° / +080.317322° (+7421.6ft) Altitude: 1694ft (+65.4ft) Datum: WGS-84 Azimuth/Bearing: 156° S33E 2798mils True (+13.1) Elevation Grade: +020% Horizon Grade: +011% Zoom: 0.5X 11970+00 Spread G</p>		 <p>Date &amp; Time: Wed, May 11, 2022 09:15:15 EDT Position: +037.269433° / +080.322691° (+15.6ft) Altitude: 2595ft (+11.0ft) Datum: WGS-84 Azimuth/Bearing: 156° S33E 2798mils True (+12.1) Elevation Grade: +053% Horizon Grade: +003% Zoom: 1.0X 11929+78 Spread G</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11970+00	<b>Field Station#</b>	11929+78		
<b>Pic 3 Desc.</b>	Steep slope vegetated conditions and permanent water bar visual.	<b>Pic 4 Desc.</b>	ROW condition adjacent to AR 266		
 <p>Date &amp; Time: Wed, May 11, 2022 09:15:24 EDT Position: +037.269494° / +080.322587° (+80.6ft) Altitude: 2375ft (+33.3ft) Datum: WGS-84 Azimuth/Bearing: 234° S54W 4160mils True (+12.1) Elevation Grade: -007% Horizon Grade: -002% Zoom: 1.0X 11929+78 Spread G</p>		 <p>Date &amp; Time: Wed, May 11, 2022 09:08:26 EDT Position: +037.269433° / +080.31742° (+15.6ft) Altitude: 2595ft (+11.0ft) Datum: WGS-84 Azimuth/Bearing: 136° S46E 2382mils True (+12.1) Elevation Grade: +003% Horizon Grade: +003% Zoom: 1.0X 11919+00 Spread G</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11929+78	<b>Field Station#</b>	11919+00		
<b>Pic 5 Desc.</b>	AR 266 stabilization conditions.	<b>Pic 6 Desc.</b>	Staggered permanent water bar and heavily vegetated row conditions. Final Restoration Area.		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/11/2022 7:55 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11917+00	<b>Field Station#</b>	11906+44		
<b>Pic 7 Desc.</b>	Final Restoration Area. Perimeter P1 silt fencing. Functional and no issues.	<b>Pic 8 Desc.</b>	Final Restoration Area vegetation. Uniform and abundant.		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>			
<b>Field Station#</b>	11900+81	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	Permanent level spreader condition and functional.	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 7:55 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37557
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/11/2022 11:00 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11899+89
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11788+52
<b>County</b>	Montgomery	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 11:00 AM	<b>Report #</b>	37557
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Comments (Reference above questions as appropriate.) Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) Accompanied by EI Pat Shields on SWPPP inspection from MP 223.27 to MP 225.37. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed environmental maintenance crews actively working on this section of ROW at time of inspection. Crew was repairing sunken ditch, seeding, and mulching travel lane. This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) and level spreaders in place where designated on E&S sheets. Majority of perimeter controls have been removed due to final restoration vegetation growth. Sensitive resource buffers are in place at pond P-KL2. Mount Tabor road crossing RCE is maintained and in acceptable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/11/2022 11:00 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed, May 11, 2022, 09:00:00 EDT  Position: +037.297881 / -080.334796 (+24.7ft)  Altitude: 2241ft (+35.2ft)  Datum: WGS-84  Azimuth/Bearing: 257.577W 4569mils True (+22.1)  Elevation Angle: -55.7  Horizon Angle: -02.6  Zoom: 1.0X  11898+00</p> 		<p>Date &amp; Time: Wed, May 11, 2022, 09:02:54 EDT  Position: +037.297482 / -080.337304 (+31.8ft)  Altitude: 2225ft (+45.1ft)  Datum: WGS-84  Azimuth/Bearing: 242.562W 4302mils True (+22.1)  Elevation Angle: -66.8  Horizon Angle: -02.0  Zoom: 1.0X  11899+00</p> 			
<b>GPS Location</b>	See photo.		<b>GPS Location</b>	See photo.	
<b>Field Station#</b>	11898+00		<b>Field Station#</b>	11890+00	
<b>Pic 1 Desc.</b>	ROW permanently restored. Travel lane seeded and mulch.		<b>Pic 2 Desc.</b>	Waterbar and level spreader in place.	
<p>Date &amp; Time: Wed, May 11, 2022, 09:10:13 EDT  Position: +037.289924 / -080.344865 (+15.6ft)  Altitude: 2188ft (+11.0ft)  Datum: WGS-84  Azimuth/Bearing: 044.164E 0918mils True (+19.1)  Elevation Angle: -69.7  Horizon Angle: -02.5  Zoom: 1.0X  11864+00 P-RL2</p> 		<p>Date &amp; Time: Wed, May 11, 2022, 09:16:07 EDT  Position: +037.289452 / -080.347991 (+15.3ft)  Altitude: 2218ft (+11.4ft)  Datum: WGS-84  Azimuth/Bearing: 143.537E 2542mils True (+20.1)  Elevation Angle: -23.5  Horizon Angle: -00.5  Zoom: 1.0X  11860+00</p> 			
<b>GPS Location</b>	See photo.		<b>GPS Location</b>	See photo.	
<b>Field Station#</b>	11864+00		<b>Field Station#</b>	11860+00	
<b>Pic 3 Desc.</b>	Priority one silt fence in place at P-KL2.		<b>Pic 4 Desc.</b>	Location where sunken ditch was repaired. ECB installed on denuded soils.	
<p>Date &amp; Time: Wed, May 11, 2022, 10:34:19 EDT  Position: +037.297997 / -080.365541 (+15.6ft)  Altitude: 2228ft (+45.1ft)  Datum: WGS-84  Azimuth/Bearing: 323.137W 5742mils True (+23.1)  Elevation Angle: -21.1  Horizon Angle: -01.6  Zoom: 1.0X  11789+00</p> 		<p>Date &amp; Time: Wed, May 11, 2022, 10:14:51 EDT  Position: +037.297997 / -080.360773 (+15.4ft)  Altitude: 2147ft (+11.2ft)  Datum: WGS-84  Azimuth/Bearing: 333.127W 5920mils True (+23.1)  Elevation Angle: -69.9  Horizon Angle: -01.6  Zoom: 1.0X  11789+00</p> 			
<b>GPS Location</b>	See photo.		<b>GPS Location</b>	See photo.	
<b>Field Station#</b>	11789+00		<b>Field Station#</b>	11789+00	
<b>Pic 5 Desc.</b>	Super silt fence in place along LOD.		<b>Pic 6 Desc.</b>	RCE in place at Mount Tabor Road crossing.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 11:00 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/11/2022 11:00 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37568
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/11/2022 6:27 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	12005+00
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	54.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			







## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



AFE 124300137		Date/Time 5/11/2022 6:27 AM		Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Permanent stabilization and perimeter controls in place y28		Pic 2 Desc.	Housekeeping trash in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	CFS perimeter controls functional y28		Pic 4 Desc.	RCE functional y28	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	CFS perimeter controls functional y28		Pic 6 Desc.	CFS perimeter controls functional y28	

<b>AFE</b>	124300137	<b>Date/Time</b>	5/11/2022 6:27 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Wed, May 11, 2022, 11:03:51 EDT Position: +037.360994 / -080.679791 (+29.11h) Altitude: 1620ft (+39.40i) Datum: WGS-84 Azimuth Bearing: 336° N20W 5570mils True (+10°) Elevation Angle: +02.8° Horizon Angle: +03.1° Zoom: 2.0X y29</p>		 <p>Date &amp; Time: Wed, May 11, 2022, 11:02:58 EDT Position: +037.361035 / -080.678799 (+19.00h) Altitude: 1687ft (+26.20i) Datum: WGS-84 Azimuth Bearing: 271° N85W 4840mils True (+10°) Elevation Angle: +02.8° Horizon Angle: +02.8° Zoom: 2.0X y29</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 7 Desc.</b>	RCE functional y29	<b>Pic 8 Desc.</b>	Broad base dips functional y29		
 <p>Date &amp; Time: Wed, May 11, 2022, 11:01:55 EDT Position: +037.362076 / -080.679285 (+15.50h) Altitude: 1708ft (+11.20i) Datum: WGS-84 Azimuth Bearing: 169° S11E 3004mils True (+10°) Elevation Angle: -07.8° Horizon Angle: +06.4° Zoom: 1.0X y29</p>		 <p>Date &amp; Time: Wed, May 11, 2022, 11:00:20 EDT Position: +037.362076 / -080.678528 (+15.40h) Altitude: 1709ft (+11.20i) Datum: WGS-84 Azimuth Bearing: 157° N54W 5440mils True (+10°) Elevation Angle: -07.8° Horizon Angle: +06.4° Zoom: 1.0X y29</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 9 Desc.</b>	Culvert in place y29	<b>Pic 10 Desc.</b>	Housekeeping trash in good condition y29		
 <p>Date &amp; Time: Wed, May 11, 2022, 10:59:57 EDT Position: +037.363101 / -080.676986 (+15.50h) Altitude: 1708ft (+11.20i) Datum: WGS-84 Azimuth Bearing: 312° N68W 5507mils True (+10°) Elevation Angle: +02.8° Horizon Angle: +00.5° Zoom: 1.0X y29</p>		 <p>Date &amp; Time: Wed, May 11, 2022, 10:58:54 EDT Position: +037.361969 / -080.677234 (+17.11h) Altitude: 1731ft (+19.70i) Datum: WGS-84 Azimuth Bearing: 288° S79W 4400mils True (+10°) Elevation Angle: +02.8° Horizon Angle: +02.8° Zoom: 1.0X y29</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 11 Desc.</b>	Permanent stabilization in place y29	<b>Pic 12 Desc.</b>	CFS perimeter controls functional y29		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/11/2022 6:27 AM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Wed, May 11, 2022, 10:48:52 EDT  Position: +037 319139 / -080 658676 (±15 4ft)  Altitude: 1813ft (±11.0ft)  Datum: WGS-84  Azimuth Bearing: 036° N34E 0604mils True (±10°)  Elevation Angle: +01.0°  Horizon Angle: +01.2°  Zoom: 1.0X  y26</p> 		<p>Date &amp; Time: Wed, May 11, 2022, 10:47:48 EDT  Position: +037 318556 / -080 657681 (±15 3ft)  Altitude: 1800ft (±11.4ft)  Datum: WGS-84  Azimuth Bearing: 266° S64W 4373mils True (±10°)  Elevation Angle: +01.2°  Horizon Angle: +02.4°  Zoom: 1.0X  y26</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 13 Desc.</b>	CFS perimeter controls in place y26	<b>Pic 14 Desc.</b>	Housekeeping trash in good condition y26		
<p>Date &amp; Time: Wed, May 11, 2022, 10:47:18 EDT  Position: +037 318638 / -080 657035 (±15 5ft)  Altitude: 1810ft (±11.1ft)  Datum: WGS-84  Azimuth Bearing: 263° S83W 4676mils True (±10°)  Elevation Angle: +01.2°  Horizon Angle: +03.7°  Zoom: 2.0X  y26</p> 		<p>Date &amp; Time: Wed, May 11, 2022, 10:47:09 EDT  Position: +037 318578 / -080 656964 (±15 3ft)  Altitude: 1808ft (±11.4ft)  Datum: WGS-84  Azimuth Bearing: 253° S62W 3971mils True (±10°)  Elevation Angle: +03.4°  Horizon Angle: +01.0°  Zoom: 2.0X  y26</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 15 Desc.</b>	Secondary containment in place y26	<b>Pic 16 Desc.</b>	Secondary containment in place y26		
<p>Date &amp; Time: Wed, May 11, 2022, 10:48:42 EDT  Position: +037 318819 / -080 656560 (±15 1ft)  Altitude: 1816ft (±11.7ft)  Datum: WGS-84  Azimuth Bearing: 051° N51E 0907mils True (±10°)  Elevation Angle: +02.9°  Horizon Angle: +00.9°  Zoom: 1.0X  y26</p> 		<p>Date &amp; Time: Wed, May 11, 2022, 10:48:31 EDT  Position: +037 318894 / -080 656930 (±15 3ft)  Altitude: 1789ft (±11.5ft)  Datum: WGS-84  Azimuth Bearing: 268° S68W 4764mils True (±10°)  Elevation Angle: +02.9°  Horizon Angle: +00.1°  Zoom: 1.0X  y26</p> 			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 17 Desc.</b>	RCE functional y26	<b>Pic 18 Desc.</b>	Construction of a parking lot started.		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37603
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/12/2022 8:40 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10859+46
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 8:40 AM	<b>Report #</b>	37603
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46). Accompanied by fellow EI Clint Sears. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Updated SWPPP documents.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	10856+04	<b>Field Station#</b>	10854+70		
<b>Pic 1 Desc.</b>	S-A33.	<b>Pic 2 Desc.</b>	S-A34.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	10845+00	<b>Field Station#</b>	10835+00		
<b>Pic 3 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 4 Desc.</b>	Section of RoW showing conditions and controls.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	10819+25	<b>Field Station#</b>	10809+04		
<b>Pic 5 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 6 Desc.</b>	S-Z14.		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/12/2022 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	7	<b>GPS Location</b>	8		
<b>Field Station#</b>	10804+00	<b>Field Station#</b>	10801+75		
<b>Pic 7 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 8 Desc.</b>	S-Z11/S-Z12/S-Z13.		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	9	<b>GPS Location</b>			
<b>Field Station#</b>	10799+00	<b>Field Station#</b>			
<b>Pic 9 Desc.</b>	S-Z10/W-Z3.	<b>Pic 10 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 8:40 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37612
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/12/2022 12:26 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10859+47
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10929+80
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	60.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>AFE</b>	124300137	<b>Date/Time</b>	5/12/2022 12:26 PM	<b>Report #</b>	37612
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
<p>See photos for GPS coordinates.  - ALL STATION NUMBERS ARE APPROXIMATE -  Completed a VA SWPPP inspection from MP 205.67 (10859+46) to MP 207.0 (10929+80).  No Deficiencies documented for repairs today. Other deficiencies may be found and documented my other EI's and or contractor staff.  No crew activity observed at the time of inspection. Briefly discussed row conditions with the contractor environmental Forman Brady Yachere Crew (1706).  This section of row has been adequately stabilized at the time of inspection. Temporary vegetation is slightly visible with no erosion visible at this time of inspection. The temporary water bars appear to be functioning as intended. Sump pits, water bar end treatments, and temporary slope drain pipes also appear to be functioning as intended with no maintenance required at this time. All other perimeter controls, ECDs and BMPs functional at time of inspection. There are three (3) stream resources within this section of row inspected. No impacts at this time of inspection.  S-Y2...10929+43 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional.  S-Y3...10927+77 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional.  S-A32...10929+43 (Doe Creek Rd)- No impact to stream. Buffer zones are undisturbed and vegetated. Equipment bridge clean and functional.</p>					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		5/12/2022 12:26 PM		Report #			
Pictures											
											
Date & Time: Thu, May 12, 2022, 10:55:43 EDT Position: +037 331682 / -080 582934 (x15.4ft) Altitude: 2126ft (x11.0ft) Datum: WGS-84 Azimuth/Bearing: 300° N50W 5333mils True (x12.1) Elevation Grade: +004 Horizon Grade: +003 Zoom: 0.5X 10929+70				Date & Time: Thu, May 12, 2022, 10:55:50 EDT Position: +037 331668 / -080 583180 (x15.4ft) Altitude: 2126ft (x11.2ft) Datum: WGS-84 Azimuth/Bearing: 207° S27W 3680mils True (x12.1) Elevation Grade: +015 Horizon Grade: +003 Zoom: 0.5X 10928+56							
GPS Location		See Photo		GPS Location		See Photo					
Field Station#		10929+70		Field Station#		10928+56					
Pic 1 Desc.		S-Y2 undisturbed vegetated stream banks. Light water flow. Clean and clear no issues.		Pic 2 Desc.		RCE and TLS. S-Y3 perimeter controls protecting the buffer zones.					
											
Date & Time: Thu, May 12, 2022, 10:54:51 EDT Position: +037 331783 / -080 583215 (x14.9ft) Altitude: 2135ft (x13.4ft) Datum: WGS-84 Azimuth/Bearing: 204° S24W 3627mils True (x12.1) Elevation Grade: +023 Horizon Grade: +003 Zoom: 0.5X 10927+77				Date & Time: Thu, May 12, 2022, 10:49:34 EDT Position: +037 331719 / -080 583369 (x15.4ft) Altitude: 2119ft (x19.7ft) Datum: WGS-84 Azimuth/Bearing: 209° S49W 4427mils True (x12.1) Elevation Grade: +021 Horizon Grade: +001 Zoom: 0.5X 10927+50							
GPS Location		See Photo		GPS Location		See Photo					
Field Station#		10927+77		Field Station#		10927+50					
Pic 3 Desc.		S-Y3 Heavily vegetated stream channel. No water flowing.		Pic 4 Desc.		Western buffer zone to the S-Y3 resource.					
											
Date & Time: Thu, May 12, 2022, 10:52:10 EDT Position: +037 332272 / -080 583542 (x15.0ft) Altitude: 2142ft (x11.6ft) Datum: WGS-84 Azimuth/Bearing: 307° N53W 5458mils True (x12.1) Elevation Grade: +018 Horizon Grade: +009 Zoom: 0.5X 10924+00				Date & Time: Thu, May 12, 2022, 10:50:27 EDT Position: +037 332122 / -080 583622 (x15.0ft) Altitude: 2132ft (x15.2ft) Datum: WGS-84 Azimuth/Bearing: 322° N38W 5724mils True (x12.1) Elevation Grade: +028 Horizon Grade: +008 Zoom: 0.5X 10923+00							
GPS Location		See Photo		GPS Location		See Photo					
Field Station#		10924+00		Field Station#		10923+00					
Pic 5 Desc.		Steep slope stabilization with ECB.		Pic 6 Desc.		Perimeter CFS controls and temporary vegetation					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/12/2022 12:26 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, May 12, 2022, 10:35:02 EDT Position: +037.334738° / -080.595328° (+15.4ft) Altitude: 2272ft (+11.1ft) Datum: WGS-84 Azimuth/Bearing: 289° N71W 5138mils True (+12°) Elevation Grade: -036° Horizon Grade: +003° Zoom: 1.0X 10884+33</p>		 <p>Date &amp; Time: Thu, May 12, 2022, 10:32:43 EDT Position: +037.334738° / -080.595328° (+20.3ft) Altitude: 2256ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 164° S18E 2319mils True (+12°) Elevation Grade: -029° Horizon Grade: -009° Zoom: 1.0X 10887+96</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10886+33	<b>Field Station#</b>	10887+96		
<b>Pic 7 Desc.</b>	Temporary water bar conditions. Water bars remain functional.	<b>Pic 8 Desc.</b>	Plunge pool conditions. Standing water within the plunge pool.		
 <p>Date &amp; Time: Thu, May 12, 2022, 10:26:49 EDT Position: +037.333212° / -080.470027° (+25.3ft) Altitude: 2164ft (+10.9ft) Datum: WGS-84 Azimuth/Bearing: 127° S53E 2258mils True (+12°) Elevation Grade: -025° Horizon Grade: -000° Zoom: 0.5X 10882+90</p>		 <p>Date &amp; Time: Thu, May 12, 2022, 10:09:03 EDT Position: +037.331837° / -080.453226° (+17.2ft) Altitude: 2330ft (+29.4ft) Datum: WGS-84 Azimuth/Bearing: 108° S72E 1920mils True (+12°) Elevation Grade: -029° Horizon Grade: +001° Zoom: 1.0X 10875+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10882+90	<b>Field Station#</b>	10875+00		
<b>Pic 9 Desc.</b>	S-A32 equipment bridge and vegetated buffer zones.	<b>Pic 10 Desc.</b>	Steep slope stabilization.		
 <p>Date &amp; Time: Thu, May 12, 2022, 10:11:24 EDT Position: +037.336260° / -080.400901° (+15.1ft) Altitude: 2400ft (+11.7ft) Datum: WGS-84 Azimuth/Bearing: 083° N53E 0942mils True (+12°) Elevation Grade: -040° Horizon Grade: +002° Zoom: 0.5X 10871+00</p>		 <p>Date &amp; Time: Thu, May 12, 2022, 10:04:03 EDT Position: +037.337131° / -080.403315° (+14.7ft) Altitude: 2403ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 041° N41E 0729mils True (+15°) Elevation Grade: -057° Horizon Grade: +006° Zoom: 0.5X 10863+50</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	10871+00	<b>Field Station#</b>	10863+50		
<b>Pic 11 Desc.</b>	TLS, Slope drain pipe, and sump pit conditions.	<b>Pic 12 Desc.</b>	Stone inlet protection condition.		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 12:26 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37624
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/12/2022 7:12 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	10797+92
<b>County</b>	Giles	<b>Ground</b>	Dry	<b>Temperature (°F)</b>	75.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No



<b>AFE</b>	124300137	<b>Date/Time</b>	5/12/2022 7:12 PM	<b>Report #</b>	
<b>Pictures</b>					
<p>Date &amp; Time: Thu, May 12, 2022, 08:20:29 EDT  Position: +037.344600, -080.633767 (+17.6ft)  Altitude: 2282ft (+28.7ft)  Datum: WGS-84  Azimuth/Bearing: 025° N25E 044mils True (+15°)  Elevation Angle: -25.4°  Horizon Angle: -05.1°  Zoom: 1.0X  10750+00</p> 		<p>Date &amp; Time: Thu, May 12, 2022, 08:21:47 EDT  Position: +037.344600, -080.633724 (+17.2ft)  Altitude: 2282ft (+28.5ft)  Datum: WGS-84  Azimuth/Bearing: 095° S95E 1689mils True (+15°)  Elevation Angle: -27.7°  Horizon Angle: -00.9°  Zoom: 1.0X  10754+00</p> 			
<b>GPS Location</b>	See photo.	<b>GPS Location</b>	See photo.		
<b>Field Station#</b>	10750+00	<b>Field Station#</b>	10754+00		
<b>Pic 1 Desc.</b>	Rock inlet in place at slope drain.	<b>Pic 2 Desc.</b>	Waterbars in place. ROW temporarily stabilized with seed and mulch.		
<p>Date &amp; Time: Thu, May 12, 2022, 08:27:07 EDT  Position: +037.340311, -080.628114 (+10781.4ft)  Altitude: 2263ft (+26.0ft)  Datum: WGS-84  Azimuth/Bearing: 070° N70E 1387mils True (+15°)  Elevation Angle: -18.3°  Horizon Angle: -04.3°  Zoom: 1.0X  10758+00 S-1035</p> 		<p>Date &amp; Time: Thu, May 12, 2022, 08:35:09 EDT  Position: +037.344588, -080.631060 (+82.8ft)  Altitude: 2164ft (+15.0ft)  Datum: WGS-84  Azimuth/Bearing: 199° S19W 3520mils True (+15°)  Elevation Angle: -26.8°  Horizon Angle: -01.9°  Zoom: 1.0X  10767+00</p> 			
<b>GPS Location</b>	See photo.	<b>GPS Location</b>	See photo.		
<b>Field Station#</b>	10758+00	<b>Field Station#</b>	10767+00		
<b>Pic 3 Desc.</b>	Sensitive resource buffer in place at stream S-G35.	<b>Pic 4 Desc.</b>	Level spreader and clean water diversion pipe in place.		
<p>Date &amp; Time: Thu, May 12, 2022, 08:39:18 EDT  Position: +037.345924, -080.618689 (+15985.0ft)  Altitude: 1905ft (+18.3ft)  Datum: WGS-84  Azimuth/Bearing: 085° N85E 1511mils True (+15°)  Elevation Angle: -16.5°  Horizon Angle: -01.9°  Zoom: 1.0X  10792+00</p> 		<p>Date &amp; Time: Thu, May 12, 2022, 08:40:07 EDT  Position: +037.345924, -080.618689 (+15985.0ft)  Altitude: 1919ft (+17.3ft)  Datum: WGS-84  Azimuth/Bearing: 081° N81E 1440mils True (+15°)  Elevation Angle: -07.2°  Horizon Angle: -02.2°  Zoom: 1.0X  10797+00</p> 			
<b>GPS Location</b>	See photo.	<b>GPS Location</b>	See photo.		
<b>Field Station#</b>	10792+00	<b>Field Station#</b>	10797+00		
<b>Pic 5 Desc.</b>	Clean water diversion berm in place.	<b>Pic 6 Desc.</b>	RCE in place at Cascade Road.		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 7:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 7:12 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37599
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/12/2022 7:39 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	10749+92
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	57.00
<b>Municipality</b>	N/A	<b>Weather</b>	Sunny	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Energy Dissipater	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 7:39 AM	<b>Report #</b>	37599
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed aVA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). No Compliance issues noted: Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 7:39 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Thu, May 12, 2022, 09:24:26 EDT Position: +037.345797 / -080.447695 (+11.68m) Altitude: 2639ft (+79.7m) Datum: WGS-84 Azimuth/Bearing: 098° S82E 1742mils True (+12°) Elevation Angle: -09.2° Horizon Angle: -02.2° Zoom: 2.0x 10712+73</p>		 <p>Date &amp; Time: Thu, May 12, 2022, 09:20:16 EDT Position: +037.345298 / -080.653127 (+13.7m) Altitude: 2051ft (+62.2m) Datum: WGS-84 Azimuth/Bearing: 289° N21W 5138mils True (+12°) Elevation Angle: -07.0° Horizon Angle: -01.0° Zoom: 3.0x 10693+50</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10712+73	<b>Field Station#</b>	10693+50		
<b>Pic 1 Desc.</b>	Equipment bridge functional	<b>Pic 2 Desc.</b>	Clean water drainage feature functional		
 <p>Date &amp; Time: Thu, May 12, 2022, 09:17:32 EDT Position: +037.347734 / -080.443621 (+13.8m) Altitude: 2403ft (+73.7m) Datum: WGS-84 Azimuth/Bearing: 110° S10E 1956mils True (+12°) Elevation Angle: -03.5° Horizon Angle: -01.5° Zoom: 0.5x 10724+00</p>		 <p>Date &amp; Time: Thu, May 12, 2022, 09:13:13 EDT Position: +037.350175 / -080.656958 (+13.5m) Altitude: 2146ft (+65.7m) Datum: WGS-84 Azimuth/Bearing: 161° S19E 2862mils True (+12°) Elevation Angle: -19.9° Horizon Angle: -00.6° Zoom: 1.0x 10684+00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10724+00	<b>Field Station#</b>	10684+00		
<b>Pic 3 Desc.</b>	Temporary stabilization in place	<b>Pic 4 Desc.</b>	Level spreader in place		
 <p>Date &amp; Time: Thu, May 12, 2022, 09:11:02 EDT Position: +037.345594 / -080.441990 (+14.4m) Altitude: 2287ft (+69.2m) Datum: WGS-84 Azimuth/Bearing: 062° N62E 1102mils True (+12°) Elevation Angle: -00.8° Horizon Angle: -02.5° Zoom: 0.5x 10733+50</p>		 <p>Date &amp; Time: Thu, May 12, 2022, 09:08:31 EDT Position: +037.350424 / -080.658615 (+29.1m) Altitude: 2141ft (+65.4m) Datum: WGS-84 Azimuth/Bearing: 099° S81E 1760mils True (+12°) Elevation Angle: -13.2° Horizon Angle: -04.7° Zoom: 1.0x 10679+39</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10733+50	<b>Field Station#</b>	10679+39		
<b>Pic 5 Desc.</b>	Wattles and P1 in place	<b>Pic 6 Desc.</b>	Resource buffers in place		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/12/2022 7:39 AM	<b>Report #</b>	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, May 12, 2022 07:38 EDT Position: -037.350746, -080.693229, (-34.8h) Altitude: 2185ft (+157.5h) Datum: WGS-84 Azimuth/Bearing: 108° S72E 1920mils True (+12°) Elevation Angle: -26.2° Horizon Angle: +01.1° Zoom: 1.0X 10675+10</small></p>		 <p><small>Date &amp; Time: Thu, May 12, 2022 07:38 EDT Position: -037.350746, -080.693229, (-34.8h) Altitude: 1887ft (+140.5h) Datum: WGS-84 Azimuth/Bearing: 039° 078E 1107mils True (+13.3°) Elevation Angle: -01.0° Horizon Angle: +01.4° Zoom: 1.0X 10698+00</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10675+10	<b>Field Station#</b>	10698+00		
<b>Pic 7 Desc.</b>	Erosion control blanket in place	<b>Pic 8 Desc.</b>	Equipment bridge functional		
 <p><small>Date &amp; Time: Thu, May 12, 2022 08:58:39 EDT Position: -037.353621, -080.662782, (-15.5h) Altitude: 3320ft (+259.0h) Datum: WGS-84 Azimuth/Bearing: 129° S50E 2290mils True (+17°) Elevation Angle: +05.5° Horizon Angle: -01.3° Zoom: 1.0X 10748+00</small></p>		 <p><small>Date &amp; Time: Thu, May 12, 2022 08:54:29 EDT Position: -037.353621, -080.662782, (-15.5h) Altitude: 2200ft (+170) Datum: WGS-84 Azimuth/Bearing: 135° S55W 478mils True (+12.7°) Elevation Angle: -02.9° Horizon Angle: -01.0° Zoom: 1.0X 10656+00</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10748+00	<b>Field Station#</b>	10656+00		
<b>Pic 9 Desc.</b>	RCE functional	<b>Pic 10 Desc.</b>	CFS perimeter controls functional		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/12/2022 7:39 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37660
<b>Inspector</b>	Daniel Fortune			<b>Date/Time</b>	5/13/2022 2:22 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11098+47
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	57.00
<b>Municipality</b>	N/A	<b>Weather</b>	Cloudy	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	0.00




1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 2:22 PM	<b>Report #</b>	37660
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b> Additional stabilization and over seeding near 11070+00.					
<b>Comments</b> (Reference above questions as appropriate.) Completed a VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. "Station numbers are approximate". Observed Activity: Environmental Crew (1702) was on site staged up at the 245.02 AR near 11065+84. This crew had continued with additional stabilization and over seeding of sparse areas between Doe Creek and AR 245.02 near 11072+00. The ROW in that area received 0" of precipitation in the last 24 hours. The row condition is damp from morning dew. No issues at this time. The ROW from AR 244 near 11025+02 to near 11070+21 has been temporarily stabilized. No erosion issues. The ROW from station 11070+21 to near 11098+00 has had final Restoration completed. There are annual grasses thriving and remain visible. There are 12" CFS that are being used as water bars (section 6) at this time. There are no erosion issues visible in the final restored areas. The perimeter controls appear to be functional at this time. One area of open ditch near 11061+00. Rock Road approaches were cleaned and functioning as intended. No sensitive resources have been impacted. Undisturbed Fully vegetated buffer zones are protected with functional ECDs					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/13/2022 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
 <p>Date &amp; Time: Fri, May 13, 2022, 10:12:01 EDT Position: +037.312355° / +080.832631° (+12.24) Altitude: 2030 ft (+61.10) Datum: WGS-84 Azimuth/Bearing: 102° S03E 1800mils True (+13°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11098+00</p>		 <p>Date &amp; Time: Fri, May 13, 2022, 10:15:01 EDT Position: +037.312355° / +080.832631° (+12.24) Altitude: 2030 ft (+61.10) Datum: WGS-84 Azimuth/Bearing: 102° S03E 1800mils True (+13°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11099+00</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11098+47	<b>Field Station#</b>	11090+00		
<b>Pic 1 Desc.</b>	Final Restoration Area and recently re-seeded of sparse areas.	<b>Pic 2 Desc.</b>	Final Restoration Area. Annual grasses visible at this time.		
 <p>Date &amp; Time: Fri, May 13, 2022, 11:06:01 EDT Position: +037.312355° / +080.832631° (+12.24) Altitude: 2080 ft (+61.20) Datum: WGS-84 Azimuth/Bearing: 332° N27W 3000mils True (+13°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11066+00</p>		 <p>Date &amp; Time: Fri, May 13, 2022, 11:06:01 EDT Position: +037.312355° / +080.832631° (+12.24) Altitude: 2080 ft (+61.20) Datum: WGS-84 Azimuth/Bearing: 332° N27W 3000mils True (+13°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11065+84</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11066+00	<b>Field Station#</b>	11065+84		
<b>Pic 3 Desc.</b>	Steep Slope stabilization	<b>Pic 4 Desc.</b>	Over view of steep slope stabilization and drainage feature.		
 <p>Date &amp; Time: Fri, May 13, 2022, 11:06:01 EDT Position: +037.312355° / +080.832631° (+12.24) Altitude: 2419 ft (+73.43) Datum: WGS-84 Azimuth/Bearing: 302° N51W 5493mils True (+13°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11025+00</p>		 <p>Date &amp; Time: Fri, May 13, 2022, 11:06:01 EDT Position: +037.312355° / +080.832631° (+12.24) Altitude: 2419 ft (+73.43) Datum: WGS-84 Azimuth/Bearing: 302° N51W 5493mils True (+13°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 11025+50</p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11025+00	<b>Field Station#</b>	11025+50		
<b>Pic 5 Desc.</b>	Additional stabilization, Sump Pit conditions and water bar end treatment condition.	<b>Pic 6 Desc.</b>	Over view looking at the S-IJ18 stream resource with adequate vegetation in the undisturbed buffer zones.		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/13/2022 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11031+00		<b>Field Station#</b>	11033+00	
<b>Pic 7 Desc.</b>	Slope drain pipe into sump pit.		<b>Pic 8 Desc.</b>	Over view of temporary stabilized row.	
					
<b>GPS Location</b>	See Photo		<b>GPS Location</b>	See Photo	
<b>Field Station#</b>	11045+66		<b>Field Station#</b>	11048+00	
<b>Pic 9 Desc.</b>	ECB stabilization of temporary water bar.		<b>Pic 10 Desc.</b>	Steep slope stabilization and ECB covered water bars.	
Insert image here			Insert image here		
<b>GPS Location</b>			<b>GPS Location</b>		
<b>Field Station#</b>			<b>Field Station#</b>		
<b>Pic 11 Desc.</b>			<b>Pic 12 Desc.</b>		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 2:22 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37635
<b>Inspector</b>	Eric Hanlon			<b>Date/Time</b>	5/13/2022 6:57 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11184+85
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11254+99
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	56.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 6:57 AM	<b>Report #</b>	37635
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). No Compliance issues noted: Observance: Perimeter controls in place Permanent & temporary stabilization in place. - Permanent waterbars (other) and level spreaders are installed as per the approved plan and are functioning as designed. The row has been final stabilized from 11184+85 to near station 11222+50. @11222+50 to 11206+27 the stabilization is thin and is being monitored. This area just over seeded last week 4/12/22 & 4/13/22. - Temporary stabilization near 11222+50 to near 11253+50. This section of row has been stabilized for the winter months. There are temporary ECDs (water bars, TSDP, P1 silt fencing, CFS, and CC4 ECB that all appear to function according to design. AR-249.02 & 244 RCE's are maintained in acceptable condition. Some subsidence on both sides of winding way also monitoring it. The ROW is wet but in stable condition. No sensitive resources have been impacted.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/13/2022 6:57 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11184+79	<b>Field Station#</b>	11227+59		
<b>Pic 1 Desc.</b>	Rock check dams in place	<b>Pic 2 Desc.</b>	RCE functional		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11189+00	<b>Field Station#</b>	11191+00		
<b>Pic 3 Desc.</b>	Permanent water bars and level spreader in place	<b>Pic 4 Desc.</b>	Clean water drainage feature functional		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11231+00	<b>Field Station#</b>	11237+00		
<b>Pic 5 Desc.</b>	Perimeter controls in place	<b>Pic 6 Desc.</b>	Inlet in place		

<b>AFE</b>	124300137	<b>Date/Time</b>	5/13/2022 6:57 AM	<b>Report #</b>	
<b>Pictures</b>					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11198+00	<b>Field Station#</b>	11245+00		
<b>Pic 7 Desc.</b>	Permanent stabilization in place	<b>Pic 8 Desc.</b>	Water bars and ET in place		
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11253+00	<b>Field Station#</b>	11215+00		
<b>Pic 9 Desc.</b>	SSF in place	<b>Pic 10 Desc.</b>	Monitoring over seeding		
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 6:57 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			



# Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37668
<b>Inspector</b>	Jared Saunders			<b>Date/Time</b>	5/13/2022 6:16 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	10929+80
<b>State</b>	VA	<b>Inspection Area</b>	Full	<b>Station End</b>	11023+80
<b>County</b>	Giles	<b>Ground</b>	Damp	<b>Temperature (°F)</b>	70.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

## 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 6:16 PM	<b>Report #</b>	37668
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from ST# 10929+80 (Doe Creek Road) to ST# 11023+80 (Access Road 244) Accompanied by EI Trey Ingram on SWPPP inspection from MP 207 to MP 208.78. No deficiencies located during inspection. Active construction site; additional deficiencies may be identified by other EIs. This section of ROW is temporarily stabilized with seed and mulch. Minor vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets. ROW permanently stabilized from station number 10961+75 to station number 10940+25. Area is stabilized with seed and mulch. Vegetation growth is present. CFS in place to minimize rilling and maintain sheet flow. Sensitive resource buffers are in place at streams S-PA07, S-RR5, S-E24, and S-E25. Triple barrier protection around karst feature located at station number 10966+00. RCEs in place and maintained at Doe Creek Road crossing, Access Road 244, and Access Road 241.02. No sensitive resources have been impacted. Light rain throughout the day. Showers project throughout the evening. Rain gauges will be checked on 5/14/22.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	5/13/2022 6:16 PM	Report #	
Pictures					
	 <p>Date &amp; Time: Fri, May 13, 2022, 08:27:21 EDT Position: +037330477 / +080544323 (+13068.2ft) Altitude: 2234ft (+75.9ft) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (+21°) Elevation Angle: -19.8° Horizon Angle: -04.1° Zoom: 1.0X 11023+00</p>		 <p>Date &amp; Time: Fri, May 13, 2022, 08:00:50 EDT Position: +037331973 / +080559474 (+7812.2ft) Altitude: 2383ft (+108.2ft) Datum: WGS-84 Azimuth/Bearing: 162° S18E 2880mils True (+16°) Elevation Angle: -19.4° Horizon Angle: -01.4° Zoom: 1.0X 11023+80</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11023+00		Field Station#	11023+80	
Pic 1 Desc.	Waterbar, sump pit, and end treatment in place.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-IJ18.	
	 <p>Date &amp; Time: Fri, May 13, 2022, 05:46:07 EDT Position: +409332333 / +080571240 (+1177.4ft) Altitude: 2333ft (+69.9ft) Datum: WGS-84 Azimuth/Bearing: 312° N49W 5529mils True (+14°) Elevation Angle: -18.2° Horizon Angle: -03.1° Zoom: 1.0X 10966+00</p>		 <p>Date &amp; Time: Fri, May 13, 2022, 05:46:07 EDT Position: +409332333 / +080571240 (+1177.4ft) Altitude: 2333ft (+69.9ft) Datum: WGS-84 Azimuth/Bearing: 312° N49W 5529mils True (+14°) Elevation Angle: -18.2° Horizon Angle: -03.1° Zoom: 1.0X 10966+00</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10966+00		Field Station#	10961+00	
Pic 3 Desc.	Triple barrier ECDs in place at cave location.		Pic 4 Desc.	ROW permanently stabilized.	
	 <p>Date &amp; Time: Fri, May 13, 2022, 09:23:31 EDT Position: +409332333 / +080571240 (+1177.4ft) Altitude: 2333ft (+69.9ft) Datum: WGS-84 Azimuth/Bearing: 352° N06W 6258mils True (+12°) Elevation Angle: -24.7° Horizon Angle: -04.0° Zoom: 1.0X 10938+00</p>		 <p>Date &amp; Time: Fri, May 13, 2022, 09:26:16 EDT Position: +037331127 / +080582919 (+119.4ft) Altitude: 2131ft (+11.3ft) Datum: WGS-84 Azimuth/Bearing: 339° N21W 6027mils True (+31°) Elevation Angle: -18.2° Horizon Angle: -00.3° Zoom: 1.0X 10930+25</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10938+00		Field Station#	10930+25	
Pic 5 Desc.	Clean water diversion pipe and level spreader in place.		Pic 6 Desc.	RCE in place at Doe Creek Road.	

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 6:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 6:16 PM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		



## Visual Site Inspection Report

<b>Project Name</b>	H-600 Pipeline Spread G	<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>	Precision			<b>Report #</b>	37638
<b>Inspector</b>	Chris Burns			<b>Date/Time</b>	5/13/2022 8:16 AM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP	<b>Station Begin</b>	11098+47
<b>State</b>	VA	<b>Inspection Area</b>	Partial	<b>Station End</b>	11184+85
<b>County</b>	Giles	<b>Ground</b>	Wet	<b>Temperature (°F)</b>	68.00
<b>Municipality</b>	N/A	<b>Weather</b>	Light Rain	<b>Rain Gauge (in)</b>	0.00
				<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

### 5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 8:16 AM	<b>Report #</b>	37638
<b>6. PCSM BMPs</b> (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>	
Level Spreader	Acceptable				
Other	Acceptable				
<b>7. Identify all remedial measures that have been taken since the previous inspection was conducted.</b>					
<b>Comments</b> (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Discussed RoW/ECD conditions, within this section, with fellow EI Clint Sears. Performed SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85) Inspection completed during ongoing rain event. Accompanied by fellow EI Clint Sears. This section of RoW is partially restored. All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Section 6 - other (waterbars) Assessed AR 245.02 and AR 249.02.					
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

<b>AFE</b>	124300137	<b>Date/Time</b>	5/13/2022 8:16 AM	<b>Report #</b>	
<b>Pictures</b>					
					
<b>GPS Location</b>	1	<b>GPS Location</b>	2		
<b>Field Station#</b>	11105+00	<b>Field Station#</b>	11136+00		
<b>Pic 1 Desc.</b>	Punch list item from 5/9/2022 completed. Oversees and stabilize	<b>Pic 2 Desc.</b>	Representative photo of permanent waterbar and level spreaders installed.		
					
<b>GPS Location</b>	3	<b>GPS Location</b>	4		
<b>Field Station#</b>	11139+50	<b>Field Station#</b>	11159+25		
<b>Pic 3 Desc.</b>	Section of restored RoW showing conditions and controls.	<b>Pic 4 Desc.</b>	S-NN17.		
					
<b>GPS Location</b>	5	<b>GPS Location</b>	6		
<b>Field Station#</b>	11167+50	<b>Field Station#</b>	11184+85		
<b>Pic 5 Desc.</b>	CWDP outlet protection functional.	<b>Pic 6 Desc.</b>	Section of restored RoW showing conditions and controls.		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 8:16 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 7 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 9 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 11 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		

<b>A/E</b>	124300137	<b>Date/Time</b>	5/13/2022 8:16 AM	<b>Report #</b>	
<b>Pictures</b>					
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 13 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 15 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>		<b>Field Station#</b>	
<b>Field Station#</b>		<b>Field Station#</b>		<b>Pic 17 Desc.</b>	
Insert image here			Insert image here		
Insert image here			Insert image here		