









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36412
Inspector	Ben Davenport			Date/Time	4/11/2022 9:38 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Partial	Station End	14546+75
County	Franklin	Ground	Damp	Temperature (°F)	66.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Routine maintenance			
Silt Fence (Reinforced Filter Fabric Fence)	Communication	Routine maintenance			
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance; cattle damage			
Other - Explain in Comments	Communication	Routine maintenance; missing permit			
Equipment Bridge	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Slope Drain Pipe	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/11/2022 9:38 AM	Report #	36412
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Contacted LEI to complete avian survey through section -Perimeter controls and ECD's were inspected; 4 issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -4 items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/11/2022 9:38 AM	Report #	
Pictures					
					
37°1'27" N 79°45'55" W 189°S COURSE -1' GPS Glade Hill, VA 24092, United States 04.11.2022 11:35:12 Accur +/-438.6 Ft ALT 1061 Ft			37°1'26" N 79°45'55" W 30°NE COURSE -1' GPS Glade Hill, VA 24092, United States 04.11.2022 11:33:27 Accur +/-105.7 Ft ALT 998 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14461+00		Field Station#	14464+00	
Pic 1 Desc.	Routine maintenance. Reattach geotextile fabric to SSF fencing.		Pic 2 Desc.	Routine maintenance. Reattach geotextile fabric to SSF fencing.	
					
37°1'12" N 79°45'46" W 233°SW COURSE 271' GPS Glade Hill, VA 24092, United States 04.11.2022 11:09:45 Accur +/-36.3 Ft ALT 941 Ft			37°1'12" N 79°45'43" W 96°E COURSE -1' GPS 1142 SR-703, Glade Hill, VA 24092, United States 04.11.2022 11:25:45 Accur +/-360.0 Ft ALT 998 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14481+00		Field Station#	14485+00	
Pic 3 Desc.	Routine maintenance. Replace damaged perimeter P1 silt fence from cattle damage.		Pic 4 Desc.	Routine maintenance. Missing perimeter ECD from landowner damage.	
					
37°14" N 79°45'36" W 188°S COURSE -1' GPS 1142 SR-703, Glade Hill, VA 24092, United States 04.11.2022 11:19:10 Accur +/-15.4 Ft ALT 899 Ft			37°0'58" N 79°45'31" W 100°E COURSE 3' GPS 1401 SR-674, Glade Hill, VA 24092, United States 04.11.2022 12:05:14 Accur +/-594.0 Ft ALT 932 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14496+58		Field Station#	14516+00	
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; ROW stabilized and vegetated in temporary area.		Pic 6 Desc.	Slope drain pipe and outlet in place and functional.	

A/E	124300139	Date/Time	4/11/2022 9:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/11/2022 9:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36443
Inspector	Charles Head			Date/Time	4/11/2022 12:51 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Full	Station End	14928+52
County	Franklin	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/11/2022 12:51 PM	Report #	36443
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/11/2022 12:51 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14923+00	Field Station#	14864+00		
Pic 1 Desc.	Approximately 14923+00. Overview of ROW.	Pic 2 Desc.	Approximately 14864+00. Overview of ROW.		
GPS Location	0	GPS Location	0		
Field Station#	14845+50	Field Station#	14828+50		
Pic 3 Desc.	Approximately 14845+50. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14828+50. Overview of ROW.		
GPS Location	0	GPS Location	0		
Field Station#	14811+00	Field Station#	14806+00		
Pic 5 Desc.	Approximately 14811+00. Overview of ROW. Permanent vegetation.	Pic 6 Desc.	Approximately 14806+00. Overview ROW.		

A/E	124300139	Date/Time	4/11/2022 12:51 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/11/2022 12:51 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36447
Inspector	Ben Farmer			Date/Time	4/11/2022 2:19 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Partial	Station End	14062+17
County	Franklin	Ground	Dry	Temperature (°F)	40.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300139	Date/Time	4/11/2022 2:19 PM	Report #	36447
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 40F) Rain Gauge= 0.0" 13958+31-14062+17 -EI began inspection at Foggy Ridge Rd. -This section remains stabilized. -CWD/CWD inlets are in good condition and functioning as intended -MVP-ATWS-1446 remains stabilized with controls in place. -No evidence of 3rd party pond discharging onto ROW. -Equipment bridge ECDs are in good condition and functioning. -Resource buffers remain well vegetated. -Slope on the CIS of Highway 220 remains stabilized with controls in place. -Waterbars and end treatments are in good condition -P1 is in good condition at all stream and wetland buffers -CFS is in good condition -Slope drain is functioning as intended at 14058+00 -Vegetation continues to fill in throughout this section					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/11/2022 2:19 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	13960+00	Field Station#	13961+00		
Pic 1 Desc.	CWDs are functioning as intended	Pic 2 Desc.	End treatments are functioning as intended		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	13969+00	Field Station#	13991+69		
Pic 3 Desc.	This area remains stabilized	Pic 4 Desc.	Equipment bridge ECDs are in good condition and functioning		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	13995+50	Field Station#	13998+15		
Pic 5 Desc.	ATWS-1466 remains stabilized	Pic 6 Desc.	P1 is in good condition at all stream and wetland buffers		

AFE	124300139	Date/Time	4/11/2022 2:19 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14000+00	Field Station#	14108+47		
Pic 7 Desc.	No evidence of 3rd party pond discharging onto ROW.	Pic 8 Desc.	RCEs are in good condition at all road crossings.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14022+00	Field Station#	14033+00		
Pic 9 Desc.	CFS is in good condition	Pic 10 Desc.	Waterbars are functioning as intended		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14035+00	Field Station#	14058+00		
Pic 11 Desc.	Resource buffers remain well vegetated	Pic 12 Desc.	Slope drain is in good condition		







AFE	124300139	Date/Time	4/11/2022 2:19 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location			
Field Station#	14060+00	Field Station#			
Pic 13 Desc.	Rock checks are functioning as intended.	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36434
Inspector	John White			Date/Time	4/11/2022 10:42 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Dry	Temperature (°F)	67.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.60
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/11/2022 10:42 AM	Report #	36434
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/11/2022 10:42 AM	Report #	
Pictures					
South East Elevation 329°NW (T) ● 36°53'16"N, 79°25'56"W ±91ft ▲ 796ft 		North East Elevation 248°SW (T) ● 36°53'16"N, 79°25'56"W ±22ft ▲ 801ft 			
GPS Location	O	GPS Location	O		
Field Station#	15650+00	Field Station#	15654+00		
Pic 1 Desc.	Observing temporary stabilization,water bar, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization		
East Elevation 250°W (T) ● 36°52'56"N, 79°24'49"W ±68136ft ▲ 772ft 		North West Elevation 153°SE (T) ● 36°52'49"N, 79°25'19"W ±318ft ▲ 845ft 			
GPS Location	O	GPS Location	O		
Field Station#	15658+43	Field Station#	15693+89		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing road crossing and RCE's		
South West Elevation 33°NE (T) ● 36°52'49"N, 79°25'19"W ±1197ft ▲ 825ft 		North East Elevation 228°SW (T) ● 36°52'24"N, 79°24'41"W ±426ft ▲ 881ft 			
GPS Location	O	GPS Location	O		
Field Station#	15690+00	Field Station#	15735+00		
Pic 5 Desc.	Observing temporary stabilization,water bar and CFS Checks	Pic 6 Desc.	Observing temporary stabilization,CWD outlet and ECD's		

A/E	124300139	Date/Time	4/11/2022 10:42 AM	Report #	
Pictures					
South East Elevation 335°NW (T) 36°52'7"N, 79°24'6"W ±6814ft ▲ 810ft 		West Elevation 69°E (T) 36°52'13"N, 79°24'9"W ±32ft ▲ 795ft 			
GPS Location	O	GPS Location	O		
Field Station#	15768+00	Field Station#	15763+80		
Pic 7 Desc.	Observing temporary stabilization and water bar	Pic 8 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/11/2022 10:42 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36441
Inspector	Justin Burch			Date/Time	4/11/2022 11:31 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Full	Station End	15370+62
County	Pittsylvania	Ground	Damp	Temperature (°F)	79.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.60
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)		Acceptable			
Waterbar		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Waterbar End Treatment		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Plunge Pool		Acceptable			
Compost Filter Sock		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/11/2022 11:31 AM	Report #	36441
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area has received two rain events with totals of 0.50" at Armstrong Road and 0.60" at Snowberry Road. • The ROW ground condition is damp. • At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. • At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15355+00 to 15370+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/11/2022 11:31 AM	Report #	
Pictures					
⚙ 316°NW (T) ● 36°55'20"N, 79°30'39"W ±13ft ▲ 784ft  15369+00 04-11-2022, 09:18:25		⚙ 250°W (T) ● 36°55'22"N, 79°30'44"W ±22ft ▲ 764ft  15365+00 04-11-2022, 09:21:57			
GPS Location	0	GPS Location	0		
Field Station#	15369+00	Field Station#	15365+00		
Pic 1 Desc.	P1 silt fence in acceptable condition	Pic 2 Desc.	Waterbar end treatment and permanent vegetative stabilization in acceptable conditions		
⚙ 198°S (T) ● 36°55'21"N, 79°30'44"W ±16ft ▲ 764ft  15365+00 04-11-2022, 09:22:20		⚙ 256°W (T) ● 36°53'41"N, 79°32'32"W ±26246ft ▲ 710ft  15340+00 04-11-2022, 09:56:20			
GPS Location	0	GPS Location	0		
Field Station#	15365+00	Field Station#	15340+00		
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	Temporary vegetative stabilization in acceptable condition		
⚙ 246°SW (T) ● 36°55'35"N, 79°31'10"W ±22ft ▲ 771ft  15339+00 04-11-2022, 09:57:27		⚙ 254°W (T) ● 36°55'35"N, 79°31'10"W ±19ft ▲ 770ft  15339+00 04-11-2022, 09:57:42			
GPS Location	0	GPS Location	0		
Field Station#	15339+00	Field Station#	15339+00		
Pic 5 Desc.	Waterbar in acceptable condition	Pic 6 Desc.	Waterbar end treatment in acceptable condition		

AFE	124300139	Date/Time	4/11/2022 11:31 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	15338+00	Field Station#	15325+00		
Pic 7 Desc.	Clean water diversion pipe and sump pit in acceptable conditions	Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition		
GPS Location	0	GPS Location	0		
Field Station#	15333+00	Field Station#	15313+00		
Pic 9 Desc.	CFS and P1 silt fence in acceptable conditions	Pic 10 Desc.	Super silt fence in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/11/2022 11:31 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		















Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36496
Inspector	Ben Farmer			Date/Time	4/12/2022 2:43 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Partial	Station End	14171+36
County	Franklin	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Communication	CFS is degraded and needs to be re		
Silt Fence (Filter Fabric Fence)		Communication	P1 is degraded and needs to be rep		
Waterbar End Treatment		Communication	Multiple end treatments need to be r		
Slope Drain Pipe		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Rock Construction Entrance		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Waterbar		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/12/2022 2:43 PM	Report #	36496
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 65F) Rain Gauge= 0.0" 14062+17-14171+36 -Multiple areas of CFS need to be replaced throughout this section. (See photos/punch list) -Multiple areas of P1 need to be replaced throughout this section. (See photos/punch list) -Slope drain is in good condition and functioning at 14157+00 -Topsoil berm remains stabilized. -SSF is in good condition. -Waterbars are functioning as intended. -Resource buffers remain well vegetated at all stream and wetland crossings. -RCEs are in good condition at all road crossings. -CWDs are functioning as intended -Vegetation continues to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/12/2022 2:43 PM	Report #	
Pictures					
 <p>39°NE (T) LAT: 37.061274 LON: -79.854521 ±36ft ▲ 1094ft</p> <p>14132+00 12 Apr 2022, 07:37:44</p>		 <p>299°NW (T) LAT: 37.060995 LON: -79.854503 ±19ft ▲ 1062ft</p> <p>14133+00 12 Apr 2022, 07:38:54</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	14132+00		Field Station#	14133+00	
Pic 1 Desc.	CFS is degraded at CWD inlet and needs to be replaced		Pic 2 Desc.	CFS checks need to be replaced	
 <p>141°SE (T) LAT: 37.059587 LON: -79.854088 ±26ft ▲ 1045ft</p> <p>14139+00 12 Apr 2022, 07:41:07</p>		 <p>187°S (T) LAT: 37.055741 LON: -79.854516 ±9258ft ▲ 1014ft</p> <p>14140+00 12 Apr 2022, 07:47:24</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	14139+00		Field Station#	14140+00	
Pic 3 Desc.	Perimeter CFS is degraded and needs to be replaced		Pic 4 Desc.	CFS end treatment needs to be replaced	
 <p>128°SE (T) LAT: 37.059225 LON: -79.853862 ±22ft ▲ 1033ft</p> <p>14141+62 12 Apr 2022, 07:43:52</p>		 <p>102°E (T) LAT: 37.059261 LON: -79.853740 ±16ft ▲ 1013ft</p> <p>14141+62 12 Apr 2022, 07:44:34</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	14141+62		Field Station#	14141+62	
Pic 5 Desc.	P1 needs to be replaced at stream buffer		Pic 6 Desc.	CFS needs to be replaced at stream buffer	

AFE	124300139	Date/Time	4/12/2022 2:43 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14143+00		Field Station#	14143+00	
Pic 7 Desc.	CFS end treatment needs to be replaced		Pic 8 Desc.	P1 is degraded and needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14144+00		Field Station#	14144+50	
Pic 9 Desc.	CFS end treatment needs to be replaced		Pic 10 Desc.	Perimeter CFS is degraded and needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14144+50		Field Station#	14146+00	
Pic 11 Desc.	CFS check needs to be replaced and area regraded.		Pic 12 Desc.	CFS needs to be replaced	

AFE	124300139	Date/Time	4/12/2022 2:43 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14147+50		Field Station#	14149+00	
Pic 13 Desc.	P1 checks need to be replaced		Pic 14 Desc.	Triple stack CFS needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14150+00		Field Station#	14152+00	
Pic 15 Desc.	Perimeter CFS needs to be replaced		Pic 16 Desc.	Perimeter CFS needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14153+00		Field Station#	14155+00	
Pic 17 Desc.	CFS needs to be replaced		Pic 18 Desc.	CFS end treatment needs to be replaced	



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36438
Inspector	Logan Box			Date/Time	4/12/2022 4:20 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Dry	Temperature (°F)	78.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/12/2022 4:20 PM	Report #	36438
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/12/2022 4:20 PM	Report #	
Pictures					
	North West Elevation 169°S (T) • 37.085403, -79.948088 ±5 m ▲ 305 m 			North East Elevation 251°SW (T) • 37.085394, -79.948094 ±6 m ▲ 305 m 	
GPS Location	0000	GPS Location	0000		
Field Station#	13692+72	Field Station#	13692+60		
Pic 1 Desc.	Monitored stream crossing and ECDs , no environmental issues observed at the time of inspection.		Pic 2 Desc.	Monitored perimeter ECDs , all functioning at the time of inspection.	
	North Elevation 209°S (T) • 37.088528, -79.950236 ±8 m ▲ 348 m 			South Elevation 27°N (T) • 37.088528, -79.950236 ±8 m ▲ 348 m 	
GPS Location	0000	GPS Location	0000		
Field Station#	13678+72	Field Station#	13678+72		
Pic 3 Desc.	Stream observation photo facing downstream during routine inspection, no environmental issues observed at the time of inspection.		Pic 4 Desc.	Stream observation photo facing upstream during routine inspection, no environmental issues observed at the time of inspection.	
	East Elevation 262°W (T) • 37.088514, -79.950347 ±4 m ▲ 313 m 			South Elevation 16°N (T) • 37.085776, -79.948194 ±3 m ▲ 314 m 	
GPS Location	00000	GPS Location	00000		
Field Station#	13678+70	Field Station#	13691+24		
Pic 5 Desc.	Observed ECDs throughout the row, no environmental issues observed at the time of inspection		Pic 6 Desc.	Monitored ECDs around wetland area inside work space. All functioning at the time of inspection.	

A/E	124300139	Date/Time	4/12/2022 4:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/12/2022 4:20 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36444
Inspector	Ben Davenport			Date/Time	4/12/2022 10:38 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Partial	Station End	14649+67
County	Franklin	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sump Pit	Acceptable				
Compost Filter Sock	Acceptable				
Temporary Diversion Berm	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/12/2022 10:38 AM	Report #	36444
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14546+75 — 14649+67 (Tobacco Rd to Hwy 40) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/12/2022 10:38 AM	Report #	
Pictures					
					
37°02' N 79°44'35" W 185°S COURSE 249° GPS Glade Hill, VA 24092, United States 04.12.2022 10:54:45 Accur +/-15.3 Ft ALT 846 Ft			37°01' N 79°44'34" W 322°NW COURSE -1° GPS Glade Hill, VA 24092, United States 04.12.2022 10:53:53 Accur +/-353.7 Ft ALT 877 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14566+23	Field Station#	14582+85		
Pic 1 Desc.	Perimeter controls in good condition.		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	
					
36°59'59" N 79°44'28" W 19°N COURSE 0° GPS 753 Simmons Creek Rd, Union Hall, VA 24176, United States 04.12.2022 10:50:42 Accur +/-122.0 Ft ALT 0 Ft			36°59'46" N 79°44'10" W 227°SW COURSE 139° GPS Union Hall, VA 24176, United States 04.12.2022 10:36:48 Accur +/-15.4 Ft ALT 897 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14591+00	Field Station#	14606+00		
Pic 3 Desc.	Sump pit and CFS end treatment performing intended functions.		Pic 4 Desc.	Plunge pool performing intended function.	
					
36°59'44" N 79°44'6" W 64°NE COURSE 213° GPS Union Hall, VA 24176, United States 04.12.2022 10:39:04 Accur +/-85.8 Ft ALT 866 Ft			36°59'44" N 79°44'5" W 188°S COURSE -1° GPS Union Hall, VA 24176, United States 04.12.2022 10:39:29 Accur +/-82.0 Ft ALT 874 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14611+17	Field Station#	14614+43		
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 6 Desc.	Temporary diversion berm stabilized and vegetated; ROW stabilized and vegetated in temporary area.	

A/E	124300139	Date/Time	4/12/2022 10:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/12/2022 10:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36490
Inspector	Charles Head			Date/Time	4/12/2022 1:42 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Full	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Dry	Temperature (°F)	76.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to chain link			
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/12/2022 1:42 PM	Report #	36490
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/12/2022 1:42 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14981+55	Field Station#	15061+00		
Pic 1 Desc.	Approximately 14981+55. Overview of road crossing and RCEs.	Pic 2 Desc.	Approximately 15061+00. Overview of ROW.		
GPS Location	0	GPS Location	0		
Field Station#	14969+00	Field Station#	14983+50		
Pic 3 Desc.	Approximately 14969+00. Overview of ROW. Permanent vegetation.	Pic 4 Desc.	Approximately 14983+50. Overview of ROW.		
GPS Location	0	GPS Location	0		
Field Station#	14930+00	Field Station#	14950+47		
Pic 5 Desc.	Approximately 14930+00. SSF requires maintenance. Reattach fabric to chain link.	Pic 6 Desc.	Approximately 14950+47. Overview of stream crossing, equipment bridge and ECDs at stream S-G13.		

A/E	124300139	Date/Time	4/12/2022 1:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/12/2022 1:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36476
Inspector	John White			Date/Time	4/12/2022 10:09 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Dry	Temperature (°F)	65.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/12/2022 10:09 AM	Report #	36476
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/12/2022 10:09 AM	Report #	
Pictures					
West Elevation 91°E (T) 36°52'1"N, 79°24'2"W ±262ft ▲ 834ft  Your Watermark 12 Apr 2022, 09:19:54		South West Elevation 22°NE (T) 36°51'55"N, 79°23'57"W ±45ft ▲ 810ft  Your Watermark 12 Apr 2022, 09:22:59			
GPS Location	O	GPS Location	O		
Field Station#	15781+22	Field Station#	15784+00		
Pic 1 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
West Elevation 90°E (T) 36°51'53"N, 79°23'56"W ±12017ft ▲ 810ft  Your Watermark 12 Apr 2022, 09:26:09		West Elevation 76°E (T) 36°51'20"N, 79°23'36"W ±144ft ▲ 844ft  Your Watermark 12 Apr 2022, 09:53:20			
GPS Location	O	GPS Location	O		
Field Station#	15794+77	Field Station#	15826+77		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing road crossing and RCE's		
West Elevation 97°E (T) 36°51'24"N, 79°23'32"W ±32ft ▲ 830ft  Your Watermark 12 Apr 2022, 09:55:43		North Elevation 183°S (T) 36°51'13"N, 79°22'38"W ±5452ft ▲ 801ft  Your Watermark 12 Apr 2022, 10:05:56			
GPS Location	O	GPS Location	O		
Field Station#	15825+00	Field Station#	15852+88		
Pic 5 Desc.	Observing temporary stabilization, plunge pool and ECD's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

A/E	124300139	Date/Time	4/12/2022 10:09 AM	Report #	
Pictures					
		<div>Insert image here</div>			
GPS Location	O	GPS Location			
Field Station#	15860+00	Field Station#			
Pic 7 Desc.	Observing temporary stabilization,water bar,cfs checks and equipment crossing	Pic 8 Desc.			
<div>Insert image here</div>		<div>Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<div>Insert image here</div>		<div>Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	4/12/2022 10:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36479
Inspector	Justin Burch			Date/Time	4/12/2022 10:53 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Full	Station End	15480+67
County	Pittsylvania	Ground	Damp	Temperature (°F)	77.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Sump Pit		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Compost Filter Sock		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Sensitive Resource Buffer		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Cleanwater Diversion Berm		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/12/2022 10:53 AM	Report #	36479
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). No issues punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection. The EI observed that the perimeter solar farm ECDs on the CIS of Toshes Road appeared to be in acceptable condition. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has received one rain event with totals of 0.10" at Snowberry Road and 0.10" at Anderson Mill Road 2 The ROW ground condition is damp. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15438+00 to 15445+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/12/2022 10:53 AM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	15466+00		Field Station#	15462+00	
Pic 1 Desc.	Sump pit in acceptable condition		Pic 2 Desc.	Waterbar in acceptable condition	
					
GPS Location	0		GPS Location	0	
Field Station#	15462+00		Field Station#	15456+00	
Pic 3 Desc.	Waterbar end treatment in acceptable condition		Pic 4 Desc.	CFS and super silt fence in acceptable conditions	
					
GPS Location	0		GPS Location	0	
Field Station#	15443+00		Field Station#	15418+00	
Pic 5 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 6 Desc.	Waterbar in acceptable condition	

A/E	124300139	Date/Time	4/12/2022 10:53 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15418+00	Field Station#	15414+00		
Pic 7 Desc.	Waterbar end treatment in acceptable condition	Pic 8 Desc.	Sensitive resource buffer and P1 silt fence in acceptable conditions		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	0	GPS Location			
Field Station#	15406+00	Field Station#			
Pic 9 Desc.	Clean water diversion berm in acceptable condition	Pic 10 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			





A/E	124300139	Date/Time	4/12/2022 10:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	36523	
Inspector	John White			Date/Time	4/13/2022 9:01 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Dry	Temperature (°F)	65.00	
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.10	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	4/13/2022 9:01 AM	Report #	36523
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/13/2022 9:01 AM	Report #	
Pictures					
West Elevation ☉ 96°E (T) ● 36°50'7"N, 79°20'23"W ±22ft ▲ 649ft 			North East Elevation ☉ 225°SW (T) ● 36°50'1"N, 79°20'15"W ±13ft ▲ 656ft 		
GPS Location	O		GPS Location	O	
Field Station#	14+00		Field Station#	22+00	
Pic 1 Desc.	Observing temporary stabilization, RCE, signage, buffer and ECD's		Pic 2 Desc.	Observing temporary stabilization, signage and buffer	
North East Elevation ☉ 204°SW (T) ● 36°50'6"N, 79°20'23"W ±82ft ▲ 651ft 			West Elevation ☉ 109°E (T) ● 36°50'6"N, 79°20'24"W ±13ft ▲ 664ft 		
GPS Location	O		GPS Location	O	
Field Station#	13+00		Field Station#	8+00	
Pic 3 Desc.	Observing temporary stabilization and ECD's		Pic 4 Desc.	Observing temporary stabilization and water bar	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	4/13/2022 9:01 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/13/2022 9:01 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300138	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	36543		
Inspector	Glenn Mike Renfro	Date/Time	4/13/2022 1:56 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00
State	VA	Inspection Area	Full	Station End	0000+00
County	Franklin	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.30
			Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
Other - Explain in Comments	Acceptable	Inlet protection for catch basins			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300138	Date/Time	4/13/2022 1:56 PM	Report #	36543
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have received .30" of rainfall since the last inspection and site conditions were wet. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were found to be in acceptable condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300138	Date/Time	4/13/2022 1:56 PM	Report #	
Pictures					
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 1 Desc.	Perimeter ECD's on northwest corner of LY-046 in good condition.	Pic 2 Desc.	Inlet protection for catch basin near storage building at LY-046 in good condition.		
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 3 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.	Pic 4 Desc.	Secondary containment structure for in front of tent at LY-045 in good condition.		
		Insert image here			
GPS Location	See picture	GPS Location			
Field Station#	0000+00	Field Station#			
Pic 5 Desc.	Perimeter ECD's on north end of LY-045 in good condition.	Pic 6 Desc.			

A/E	124300138	Date/Time	4/13/2022 1:56 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300138	Date/Time	4/13/2022 1:56 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	36573	
Inspector	Frank Craycroft				Date/Time	4/13/2022 8:02 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	0+00	
State	VA	Inspection Area	Full		Station End	0+00	
County	Franklin	Ground	Dry		Temperature (°F)	75.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Housekeeping		Acceptable					
Rock Construction Entrance		Acceptable					
Secondary Containment		Acceptable					
Timber Mat		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
Waste Management		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	4/13/2022 8:02 AM	Report #	36573
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed SWPPP inspection of LY-048, -032, -033, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All stormwater drain inlets had proper perimeter protection and were free of debris and vegetation. All entrances were free of mud buildup. All perimeter ECDs were functional and in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/13/2022 8:02 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-048 West perimeter CFS		Pic 2 Desc.	LY-048 Housekeeping	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	ANC-006 Secondary containment		Pic 4 Desc.	ANC-006 Stormwater drain inlet protection	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	LY-032 Secondary containment		Pic 6 Desc.	LY-032 Rock entrance	

A/E	124300139	Date/Time	4/13/2022 8:02 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-033 Secondary containment	Pic 8 Desc.	LY-033 Timber mat staging area		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/13/2022 8:02 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		















Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36546
Inspector	Ben Farmer			Date/Time	4/13/2022 2:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Partial	Station End	14311+57
County	Franklin	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Communication	CFS is degraded and needs to be re		
Silt Fence (Filter Fabric Fence)		Communication	P1 is degraded/damaged and needs		
Waterbar End Treatment		Communication	CFS end treatments are degraded a		
Cleanwater Diversion Pipe		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Waterbar		Acceptable			
Slope Drain Pipe		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/13/2022 2:28 PM	Report #	36546
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 65F) Rain Gauge= 0.0" 14171+36-14311+57 -EI began inspection at Angle Plantation Rd. -Multiple areas of CFS need to be replaced throughout this section. (See photos/punchlist) -Multiple areas of P1 need to be replaced throughout this section. (See photos/punchlist) -Environmental crew on site to complete punchlist items. -Waterbars are in good condition throughout this section. -Resource buffers remain well vegetated. -Equipment bridge ECDs are in good condition -Slope drain is in good condition and functioning. -CWDs are functioning as intended. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/13/2022 2:28 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14177+00		Field Station#	14179+00	
Pic 1 Desc.	CFS end treatment needs to be replaced		Pic 2 Desc.	CFS end treatment needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14190+00		Field Station#	14190+25	
Pic 3 Desc.	P1 needs to be replaced at resource buffer		Pic 4 Desc.	CFS needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14190+50		Field Station#	14191+00	
Pic 5 Desc.	CFS needs to be replaced		Pic 6 Desc.	CFS outlet needs to be replaced	

AFE	124300139	Date/Time	4/13/2022 2:28 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14191+00		Field Station#	14195+00	
Pic 7 Desc.	P1 needs to be replaced at resource buffer		Pic 8 Desc.	Perimeter P1 needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14210+00		Field Station#	14212+63	
Pic 9 Desc.	CFS needs to be replaced		Pic 10 Desc.	CFS end treatment needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14212+75		Field Station#	14213+00	
Pic 11 Desc.	P1 needs to be replaced		Pic 12 Desc.	CFS end treatment needs to be replaced	

AFE	124300139	Date/Time	4/13/2022 2:28 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14213+00		Field Station#	14213+75	
Pic 13 Desc.	P1 needs to be replaced at resource buffer		Pic 14 Desc.	CFS needs to be replaced at resource buffer	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14215+00		Field Station#	14216+00	
Pic 15 Desc.	CFS end treatment needs to be replaced		Pic 16 Desc.	Perimeter CFS needs to be replaced	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14217+00		Field Station#	14218+00	
Pic 17 Desc.	CFS end treatment needs to be replaced		Pic 18 Desc.	CFS end treatment needs to be replaced	



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36536
Inspector	Charles Head			Date/Time	4/13/2022 12:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Full	Station End	15142+66
County	Pittsylvania	Ground	Dry	Temperature (°F)	79.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/13/2022 12:03 PM	Report #	36536
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/13/2022 12:03 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15068+00	Field Station#	15092+95		
Pic 1 Desc.	Approximately 15068+00. Overview of ROW.	Pic 2 Desc.	Approximately 15092+95. Overview of stream crossing, equipment bridge and ECDs at stream S-G9. Permanent vegetation on hillside.		
					
GPS Location	0	GPS Location	0		
Field Station#	15103+50	Field Station#	15113+00		
Pic 3 Desc.	Approximately 15103+50. Overview of stream crossing, equipment bridge and ECDs at stream S-G8.	Pic 4 Desc.	Approximately 15113+00. Overview of road crossing and RCEs.		
					
GPS Location	0	GPS Location	0		
Field Station#	15118+00	Field Station#	15126+40		
Pic 5 Desc.	Approximately 15118+00. Overview of ROW.	Pic 6 Desc.	Approximately 15126+40. Overview of stream crossing, equipment bridge and ECDs at stream S-A6.		

A/E	124300139	Date/Time	4/13/2022 12:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/13/2022 12:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36487
Inspector	Ben Davenport			Date/Time	4/13/2022 10:22 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Partial	Station End	14694+77
County	Franklin	Ground	Dry	Temperature (°F)	78.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Sediment Filter Log	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Temporary Diversion Berm	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/13/2022 10:22 AM	Report #	36487
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14649+67 — 14694+77 (Hwy 40 to Jacks Creek Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/13/2022 10:22 AM	Report #	
Pictures					
					
36°59'16" N 79°42'43" W 201°S COURSE 248' GPS Union Hall, VA 24176, United States 04.13.2022 09:57:23 Accur +/-15.3 Ft ALT 897 Ft			36°59'16" N 79°42'47" W 296°NW COURSE 222' GPS Union Hall, VA 24176, United States 04.13.2022 09:58:47 Accur +/-15.3 Ft ALT 954 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14657+00	Field Station#	14670+00		
Pic 1 Desc.	Signage visible and intact at stream crossing.		Pic 2 Desc.	Sump pit and CFS end treatment performing intended functions.	
					
36°59'16" N 79°42'46" W 238°SW COURSE 220' GPS Union Hall, VA 24176, United States 04.13.2022 09:58:20 Accur +/-15.3 Ft ALT 943 Ft			36°59'16" N 79°42'50" W 236°SW COURSE 209' GPS Union Hall, VA 24176, United States 04.13.2022 09:59:42 Accur +/-15.3 Ft ALT 940 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14678+00	Field Station#	14683+62		
Pic 3 Desc.	ROW stabilized and vegetated in temporary area.		Pic 4 Desc.	Perimeter controls in place and functional.	
					
36°59'16" N 79°42'47" W 165°S COURSE 208' GPS Union Hall, VA 24176, United States 04.13.2022 09:58:42 Accur +/-15.4 Ft ALT 954 Ft			36°59'16" N 79°42'41" W 316°NW COURSE 292' GPS Union Hall, VA 24176, United States 04.13.2022 09:56:27 Accur +/-25.5 Ft ALT 927 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14686+00	Field Station#	14689+36		
Pic 5 Desc.	Temporary diversion berm stabilized and vegetated.		Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	

A/E	124300139	Date/Time	4/13/2022 10:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/13/2022 10:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		







Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36529
Inspector	Justin Burch			Date/Time	4/13/2022 10:32 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Full	Station End	15584+23
County	Pittsylvania	Ground	Damp	Temperature (°F)	82.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Sump Pit	Acceptable				
Equipment Bridge	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/13/2022 10:32 AM	Report #	36529
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI observed that the solar farm ECDs adjacent to the ROW on the GAS of Climax Road appeared to be in acceptable condition. The EI observed that the turbidity in stream S-MM8 (15521+00) has cleared up. This turbidity was a result of upstream activities not related to MVP. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has received one rain event with totals of 0.10" at Snowberry Road and 0.10" at Anderson Mill Road 2. The ROW ground condition is damp. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15482+00 to 15495+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/13/2022 10:32 AM	Report #	
Pictures					
203°SW (T) 36°54'33"N, 79°28'36"W ±13ft ▲898ft  15486+00 04-13-2022, 09:05:23		231°SW (T) 36°54'5"N, 79°27'58"W ±2585ft ▲810ft  15528+00 04-13-2022, 09:28:59			
GPS Location	0	GPS Location	0		
Field Station#	15486+00	Field Station#	15528+00		
Pic 1 Desc.	Permanent vegetative stabilization and perimeter CFS in acceptable conditions	Pic 2 Desc.	Super silt fence and sump pit in acceptable conditions		
271°W (T) 36°54'6"N, 79°27'59"W ±19ft ▲807ft  15527+00 04-13-2022, 09:29:38		50°NE (T) 36°53'58"N, 79°27'46"W ±741ft ▲790ft  15540+00 04-13-2022, 09:42:12			
GPS Location	0	GPS Location	0		
Field Station#	15527+00	Field Station#	15540+00		
Pic 3 Desc.	Equipment bridge in acceptable condition	Pic 4 Desc.	Waterbar in acceptable condition		
91°E (T) 36°53'59"N, 79°27'46"W ±19ft ▲791ft  15540+00 04-13-2022, 09:42:34		286°W (T) 36°53'54"N, 79°27'39"W ±72ft ▲839ft  15548+00 04-13-2022, 09:46:56			
GPS Location	0	GPS Location	0		
Field Station#	15540+00	Field Station#	15548+00		
Pic 5 Desc.	Waterbar end treatment in acceptable condition	Pic 6 Desc.	Temporary vegetative stabilization in acceptable condition		

AFE	124300139	Date/Time	4/13/2022 10:32 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15552+00	Field Station#	15580+00		
Pic 7 Desc.	Clean water diversion pipe in acceptable condition	Pic 8 Desc.	Waterbar in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	15580+00	Field Station#	15498+00		
Pic 9 Desc.	Waterbar end treatment in acceptable condition	Pic 10 Desc.	Solar farm ECDs appear to be in acceptable conditions		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/13/2022 10:32 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36526
Inspector	John White			Date/Time	4/13/2022 9:19 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	65.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/13/2022 9:19 AM	Report #	36526
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/13/2022 9:19 AM	Report #	
Pictures					
South West Elevation ☉ 58°NE (T) ● 36°49'50"N, 79°20'37"W ±387ft ▲ 627ft  <small>Your Watermark 13 Apr 2022, 08:46:48</small>			North Elevation ☉ 199°S (T) ● 36°49'50"N, 79°20'37"W ±42ft ▲ 639ft  <small>Your Watermark 13 Apr 2022, 08:46:52</small>		
GPS Location	O		GPS Location	O	
Field Station#	16024+00		Field Station#	16020+00	
Pic 1 Desc.	Observing temporary stabilization		Pic 2 Desc.	Observing temporary stabilization and water bars	
North West Elevation ☉ 116°SE (T) ● 36°49'50"N, 79°20'39"W ±2805ft ▲ 625ft  <small>Your Watermark 13 Apr 2022, 08:49:08</small>			East Elevation ☉ 257°W (T) ● 36°49'48"N, 79°20'44"W ±13ft ▲ 611ft  <small>Your Watermark 13 Apr 2022, 08:50:10</small>		
GPS Location	O		GPS Location	O	
Field Station#	16018+00		Field Station#	16016+36	
Pic 3 Desc.	Observing temporary stabilization, sump and end treatment		Pic 4 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	
North Elevation ☉ 182°S (T) ● 36°49'47"N, 79°20'46"W ±13ft ▲ 609ft  <small>Your Watermark 13 Apr 2022, 08:51:20</small>			North Elevation ☉ 171°S (T) ● 36°49'45"N, 79°20'49"W ±528ft ▲ 610ft  <small>Your Watermark 13 Apr 2022, 08:52:41</small>		
GPS Location	O		GPS Location	O	
Field Station#	16015+50		Field Station#	16010+00	
Pic 5 Desc.	Observing temporary stabilization, signage, buffer and ECD's		Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's	

A/E	124300139	Date/Time	4/13/2022 9:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/13/2022 9:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36528
Inspector	Logan Box			Date/Time	4/13/2022 2:50 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Dry	Temperature (°F)	75.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Erosion Control Blanket	Acceptable				
Equipment Bridge	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/13/2022 2:50 PM	Report #	36528
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>The EI traveled to S-MM42 and observed the punch list item completed, the contractor installed erosion control blanket in the area.</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/13/2022 2:50 PM	Report #	
Pictures					
	South Elevation 			North Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13755+49	Field Station#	13770+69		
Pic 1 Desc.	Stream observation photo facing downstream during routine inspection today. No environmental issues observed at the time of inspection.		Pic 2 Desc.	Photo showing S-MM42 after the contractor completed the punch list item , installed erosion control blanket.	
	North Elevation 			West Elevation 	
GPS Location	0000	GPS Location	00000		
Field Station#	13755+49	Field Station#	13770+69		
Pic 3 Desc.	Stream observation photo facing upstream during routine inspection today, no environmental issues observed at the time of inspection.		Pic 4 Desc.	Photo showing S-MM42 after the contractor completed the punch list item , installed erosion control blanket.	
	North West Elevation 			East Elevation 	
GPS Location	00000	GPS Location	00000		
Field Station#	13811+66	Field Station#	13806+90		
Pic 5 Desc.	Monitored RCEs and ECDs at road crossings, no issues observed at the time of inspection.		Pic 6 Desc.	Stream observation photo showing stabilization on hill sides, ECDs in place and functioning at the time of inspection.	

A/E	124300139	Date/Time	4/13/2022 2:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		


A/E	124300139	Date/Time	4/13/2022 2:50 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	36525	
Inspector	John White			Date/Time	4/13/2022 9:14 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Dry	Temperature (°F)	65.00	
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.10	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sump Pit		Acceptable				
Waterbar		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	4/13/2022 9:14 AM	Report #	36525
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/13/2022 9:14 AM	Report #	
Pictures					
West Elevation 104°E (T) 36°49'27"N, 79°21'53"W ±13103ft ▲ 648ft  Your Watermark 13 Apr 2022, 08:36:18		North Elevation 180°S (T) 36°49'45"N, 79°20'40"W ±104ft ▲ 622ft  Your Watermark 13 Apr 2022, 08:41:52			
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	12+65		
Pic 1 Desc.	Observing temporary stabilization and access road		Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	
West Elevation 72°E (T) 36°49'43"N, 79°20'40"W ±13ft ▲ 628ft  Your Watermark 13 Apr 2022, 08:42:57		North East Elevation 246°SW (T) 36°49'43"N, 79°20'40"W ±13ft ▲ 630ft  Your Watermark 13 Apr 2022, 08:43:09			
GPS Location	O	GPS Location	O		
Field Station#	13+50	Field Station#	15+00		
Pic 3 Desc.	Observing temporary stabilization, water bar, sump, end treatment and ECD's		Pic 4 Desc.	Observing temporary stabilization and signage	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	4/13/2022 9:14 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/13/2022 9:14 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36593
Inspector	Ben Farmer			Date/Time	4/14/2022 2:55 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Partial	Station End	13958+31
County	Franklin	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Sediment Trap	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Problem Area				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/14/2022 2:55 PM	Report #	36593
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 65F) Rain Gauge= 0.0" 13853+45-13958+31 -EI began inspection at MVP-FR-303.1 -FR-303.1 remains in good condition with controls in place. -Waterbars/end treatments are in good condition. -Resource buffers remain well vegetated at all stream and wetland crossings. -CWDs are in good condition and functioning as intended -Equipment bridge ECDs are in good condition and functioning. -Slope drain/Slope drain outlets are in good condition and functioning. -Steep slope at 13889+00 remains stabilized. -RCEs are in good condition at all road crossings. -Topsoil berms remain stabilized. -Sediment trap at 13897+00 is in good condition with no evidence of discharge. -CFS is in good condition. -P1 is in good condition at all stream and wetland buffers -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/14/2022 2:55 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13892+00		Field Station#	13891+00	
Pic 1 Desc.	Waterbars are in good condition and functioning		Pic 2 Desc.	Slope remains stabilized	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13889+00		Field Station#	13876+00	
Pic 3 Desc.	Slope drain is functioning as intended		Pic 4 Desc.	P1 is in good condition at all stream and wetland buffers	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13875+73		Field Station#	13895+00	
Pic 5 Desc.	Equipment bridge ECDs are in good condition and functioning		Pic 6 Desc.	Stockpile remains stabilized	

AFE	124300139	Date/Time	4/14/2022 2:55 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13898+00		Field Station#	13923+00	
Pic 7 Desc.	Sediment trap is functioning as intended		Pic 8 Desc.	CFS is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13942+00		Field Station#	13943+00	
Pic 9 Desc.	Topsoil berms remain stabilized		Pic 10 Desc.	CWDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13949+00		Field Station#	13955+00	
Pic 11 Desc.	Resource buffers remain well vegetated		Pic 12 Desc.	Slope drain is functioning as intended.	







A/E	124300139	Date/Time	4/14/2022 2:55 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36584
Inspector	Justin Burch			Date/Time	4/14/2022 11:31 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Full	Station End	15260+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/14/2022 11:31 AM	Report #	36584
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has received no rain events. The ROW ground condition is dry. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/14/2022 11:31 AM	Report #	
Pictures					
340°N (T) 36°56'4"N, 79°32'38"W ±154ft ▲ 797ft  15257+00 04-14-2022, 09:13:08		145°SE (T) 36°56'7"N, 79°32'37"W ±544ft ▲ 762ft  15258+00 04-14-2022, 09:16:14			
GPS Location	0	GPS Location	0		
Field Station#	15257+00	Field Station#	15258+00		
Pic 1 Desc.	Permanent vegetative stabilization and waterbar in acceptable conditions	Pic 2 Desc.	Waterbar end treatment in acceptable condition		
89°E (T) 36°56'25"N, 79°33'44"W ±39ft ▲ 794ft  15199+00 04-14-2022, 10:42:39		24°NE (T) 36°56'36"N, 79°34'14"W ±13ft ▲ 790ft  15171+00 04-14-2022, 10:50:23			
GPS Location	0	GPS Location	0		
Field Station#	15199+00	Field Station#	15171+00		
Pic 3 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 4 Desc.	Waterbar in acceptable condition		
356°N (T) 36°56'36"N, 79°34'13"W ±13ft ▲ 791ft  15171+00 04-14-2022, 10:50:11		130°SE (T) 36°56'36"N, 79°34'13"W ±2811ft ▲ 791ft  15171+00 04-14-2022, 10:52:14			
GPS Location	0	GPS Location	0		
Field Station#	15171+00	Field Station#	15171+00		
Pic 5 Desc.	Waterbar end treatment in acceptable condition	Pic 6 Desc.	Super silt fence in acceptable condition		

A/E	124300139	Date/Time	4/14/2022 11:31 AM	Report #	
Pictures					
 <p>15185+00 04-14-2022, 10:59:40</p>		 <p>15158+00 04-14-2022, 11:21:42</p>			
GPS Location	0	GPS Location	0		
Field Station#	15185+00	Field Station#	15158+00		
Pic 7 Desc.	Perimeter CFS and permanent vegetative stabilization in acceptable conditions		Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition	
 <p>15168+59 04-14-2022, 11:41:17</p>		 <p>15143+00 04-14-2022, 11:48:27</p>			
GPS Location	0	GPS Location	0		
Field Station#	15168+59	Field Station#	15143+00		
Pic 9 Desc.	Equipment bridge in acceptable condition		Pic 10 Desc.	P1 silt fence in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		







A/E	124300139	Date/Time	4/14/2022 11:31 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36559
Inspector	Ben Davenport			Date/Time	4/14/2022 9:03 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Partial	Station End	14454+22
County	Franklin	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Compost Filter Sock	Acceptable				
Erosion Control Blanket	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Plunge Pool	Acceptable				
Sump Pit	Acceptable				
Temporary Diversion Berm	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/14/2022 9:03 AM	Report #	36559
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Cloudy with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/14/2022 9:03 AM	Report #	
Pictures					
					
37°1'52" N 79°47'5" W 351°N COURSE 110° GPS Glade Hill, VA 24092, United States 04.14.2022 10:02:47 Accur +/-15.3 Ft ALT 1044 Ft			37°1'51" N 79°47'3" W 193°S COURSE 217° GPS Glade Hill, VA 24092, United States 04.14.2022 10:04:54 Accur +/-15.4 Ft ALT 1063 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14349+00	Field Station#	14361+00		
Pic 1 Desc.	ROW stabilized and vegetated in temporary area.	Pic 2 Desc.	Temporary diversion berm stabilized and vegetated.		
					
37°1'51" N 79°47'3" W 122°SE COURSE 206° GPS Glade Hill, VA 24092, United States 04.14.2022 10:04:51 Accur +/-15.4 Ft ALT 1061 Ft			37°1'52" N 79°47'4" W 131°SE COURSE 51° GPS Glade Hill, VA 24092, United States 04.14.2022 10:03:14 Accur +/-15.4 Ft ALT 1048 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14380+00	Field Station#	14401+00		
Pic 3 Desc.	Plunge pool performing intended function.	Pic 4 Desc.	Perimeter CFS in good condition.		
					
37°1'35" N 79°46'8" W 345°N COURSE 212° GPS 2753-2799 Webster Rd, Glade Hill, VA 24092, United States 04.14.2022 09:56:42 Accur +/-15.5 Ft ALT 1105 Ft			37°1'38" N 79°46'9" W 81°E COURSE 349° GPS 2701-2751 Webster Rd, Glade Hill, VA 24092, United States 04.14.2022 09:54:50 Accur +/-15.3 Ft ALT 1108 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14448+00	Field Station#	14450+00		
Pic 5 Desc.	Perimeter P1 silt fence in place and functional.	Pic 6 Desc.	Erosion control blanket performing intended function.		

A/E	124300139	Date/Time	4/14/2022 9:03 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



A/E	124300139	Date/Time	4/14/2022 9:03 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36582
Inspector	John White			Date/Time	4/14/2022 11:18 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/14/2022 11:18 AM	Report #	36582
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/14/2022 11:18 AM	Report #	
Pictures					
<div>West Elevation</div> <div>☉ 102°E (T) ● 36°53'26"N, 79°24'35"W ±12893ft ▲ 809ft</div> <div></div> <div>Your Watermark14 Apr 2022, 10:43:52</div>			<div>North West Elevation</div> <div>☉ 122°SE (T) ● 36°53'39"N, 79°26'49"W ±108ft ▲ 785ft</div> <div></div> <div>Your Watermark14 Apr 2022, 10:45:39</div>		
GPS Location			O		
Field Station#			15590+00		
Pic 1 Desc.			Observing temporary stabilization and water bars		
GPS Location			O		
Field Station#			15595+00		
Pic 2 Desc.			Observing temporary stabilization,water bars,signage, buffer, equipment crossing and ECD's		
<div>South East Elevation</div> <div>☉ 322°NW (T) ● 36°53'32"N, 79°26'21"W ±91ft ▲ 836ft</div> <div></div> <div>Your Watermark14 Apr 2022, 11:10:37</div>			<div>South West Elevation</div> <div>☉ 62°NE (T) ● 36°53'32"N, 79°26'20"W ±13ft ▲ 845ft</div> <div></div> <div>Your Watermark14 Apr 2022, 11:11:06</div>		
GPS Location			O		
Field Station#			15618+00		
Pic 3 Desc.			Observing temporary stabilization,water bar, sump and end treatment		
GPS Location			O		
Field Station#			15619+48		
Pic 4 Desc.			Observing road crossing and RCE's		
<div>South West Elevation</div> <div>☉ 64°NE (T) ● 36°53'34"N, 79°26'9"W ±616ft ▲ 811ft</div> <div></div> <div>Your Watermark14 Apr 2022, 11:15:17</div>			<div>East Elevation</div> <div>☉ 277°W (T) ● 36°53'34"N, 79°26'9"W ±26ft ▲ 805ft</div> <div></div> <div>Your Watermark14 Apr 2022, 11:15:24</div>		
GPS Location			O		
Field Station#			15630+00		
Pic 5 Desc.			Observing temporary stabilization,CWD outlet and ECD's		
GPS Location			O		
Field Station#			15628+00		
Pic 6 Desc.			Observing temporary stabilization and CWD berm		

A/E	124300139	Date/Time	4/14/2022 11:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/14/2022 11:18 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36592
Inspector	Charles Head			Date/Time	4/14/2022 2:46 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Full	Station End	14802+19
County	Franklin	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/14/2022 2:46 PM	Report #	36592
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/14/2022 2:46 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14758+00	Field Station#	14748+00		
Pic 1 Desc.	Approximately 14758+00. Overview of road crossing and RCEs.		Pic 2 Desc.	Approximately 14748+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14775+00	Field Station#	14716+50		
Pic 3 Desc.	Approximately 14775+00. Overview of ROW.		Pic 4 Desc.	Approximately 14716+50. Overview of wetland crossing, equipment bridge and ECDs at wetland W-H11. Third party disturbance and ECDs beyond LOD on north end of wetland.	
					
GPS Location	0	GPS Location	0		
Field Station#	14729+10	Field Station#	14801+00		
Pic 5 Desc.	Approximately 14729+19. Overview of stream crossing, equipment bridge and ECDs at stream S-A20.		Pic 6 Desc.	Approximately 14801+00. Overview of ROW.	

A/E	124300139	Date/Time	4/14/2022 2:46 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/14/2022 2:46 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36624
Inspector	Ben Davenport			Date/Time	4/15/2022 9:43 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Partial	Station End	14546+75
County	Franklin	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Waterbar	Acceptable				
Sump Pit	Acceptable				
Plunge Pool	Acceptable				
Equipment Bridge	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Temporary Diversion Berm	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/15/2022 9:43 AM	Report #	36624
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/15/2022 9:43 AM	Report #	
Pictures					
					
<small>37°0'40" N 79°45'16" W 20°N COURSE -1° GPS 1705 SR-674, Glade Hill, VA 24092, United States 04.15.2022 10:29:26 Accur +/-40.6 Ft ALT 0 Ft</small>			<small>37°0'38" N 79°45'16" W 310°NW COURSE 0° GPS 1694 SR-674, Glade Hill, VA 24092, United States 04.15.2022 10:21:40 Accur +/-135.5 Ft ALT 0 Ft</small>		
GPS Location	1	GPS Location	2		
Field Station#	14520+00	Field Station#	14528+00		
Pic 1 Desc.	ROW stabilized and vegetated in temporary area.	Pic 2 Desc.	ROW stabilized and vegetated in temporary area.		
					
<small>37°0'33" N 79°45'15" W 156°SE COURSE 211° GPS Glade Hill, VA 24092, United States 04.15.2022 10:24:20 Accur +/-38.8 Ft ALT 1006 Ft</small>			<small>37°0'31" N 79°45'15" W 46°NE COURSE 329° GPS Glade Hill, VA 24092, United States 04.15.2022 10:25:10 Accur +/-15.3 Ft ALT 1026 Ft</small>		
GPS Location	3	GPS Location	4		
Field Station#	14531+58	Field Station#	14533+00		
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 4 Desc.	Plunge pool performing intended function.		
					
<small>37°0'37" N 79°45'13" W 203°S COURSE 184° GPS 1694 SR-674, Glade Hill, VA 24092, United States 04.15.2022 10:22:54 Accur +/-112.1 Ft ALT 1060 Ft</small>			<small>37°0'21" N 79°45'11" W 273°W COURSE -1° GPS 2-98 Tobacco Rd, Glade Hill, VA 24092, United States 04.15.2022 10:02:56 Accur +/-119.0 Ft ALT 947 Ft</small>		
GPS Location	5	GPS Location	6		
Field Station#	14536+00	Field Station#	14544+00		
Pic 5 Desc.	Temporary diversion berm stabilized and vegetated.	Pic 6 Desc.	Sump pit and CFS end treatment performing intended functions.		

A/E	124300139	Date/Time	4/15/2022 9:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/15/2022 9:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36639
Inspector	Charles Head			Date/Time	4/15/2022 1:31 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Full	Station End	14928+52
County	Franklin	Ground	Dry	Temperature (°F)	72.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/15/2022 1:31 PM	Report #	36639
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/15/2022 1:31 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14867+00	Field Station#	14850+00		
Pic 1 Desc.	Approximately 14867+00. Overview of ROW.		Pic 2 Desc.	Approximately 14850+00. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14845+50	Field Station#	14823+54		
Pic 3 Desc.	Approximately 14845+50. Overview of road crossing and RCEs.		Pic 4 Desc.	Approximately 14823+54. Overview of stream crossing, equipment bridge and ECDs at stream S-A13.	
GPS Location	0	GPS Location	0		
Field Station#	14820+00	Field Station#	14811+00		
Pic 5 Desc.	Approximately 14820+00. Overview of ROW.		Pic 6 Desc.	Approximately 14811+00. Overview of ROW. Permanent vegetation.	

A/E	124300139	Date/Time	4/15/2022 1:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/15/2022 1:31 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36642
Inspector	Ben Farmer			Date/Time	4/15/2022 2:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Partial	Station End	14062+17
County	Franklin	Ground	Dry	Temperature (°F)	50.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Check Dam	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/15/2022 2:59 PM	Report #	36642
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 50F) Rain Gauge= 0.0" 13958+31-14062+17 -EI began inspection at Foggy Ridge Rd. -This section remains stabilized. -CWD/CWD inlets are in good condition and functioning as intended -MVP-ATWS-1446 remains stabilized with controls in place. -No evidence of 3rd party pond discharging onto ROW. -Equipment bridge ECDs are in good condition and functioning. -Resource buffers remain well vegetated. -Slope on the CIS of Highway 220 remains stabilized with controls in place. -Waterbars and end treatments are in good condition -P1 is in good condition at all stream and wetland buffers -CFS is in good condition -Slope drain is functioning as intended at 14058+00 -Vegetation continues to fill in throughout this section					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/15/2022 2:59 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	13960+00	Field Station#	13963+00		
Pic 1 Desc.	CWDs are functioning as intended	Pic 2 Desc.	This section remains temporarily stabilized		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	13991+69	Field Station#	13998+15		
Pic 3 Desc.	Equipment bridge ECDs are in good condition	Pic 4 Desc.	P1 is in good condition at all stream and wetland buffers		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14000+00	Field Station#	14034+00		
Pic 5 Desc.	No evidence of 3rd party pond discharging onto ROW.	Pic 6 Desc.	End treatments are in good condition and functioning		

AFE	124300139	Date/Time	4/15/2022 2:59 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14034+00		Field Station#	14035+00	
Pic 7 Desc.	Waterbars are functioning as intended		Pic 8 Desc.	Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14020+00		Field Station#	14018+47	
Pic 9 Desc.	CFS is in good condition		Pic 10 Desc.	RCEs are in good condition at all road crossings.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14059+00		Field Station#	14058+00	
Pic 11 Desc.	Rock check dams are functioning as intended		Pic 12 Desc.	Slope drain is in good condition and functioning	







A/E	124300139	Date/Time	4/15/2022 2:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36626
Inspector	John White			Date/Time	4/15/2022 9:24 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Dry	Temperature (°F)	65.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/15/2022 9:24 AM	Report #	36626
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/15/2022 9:24 AM	Report #	
Pictures					
North Elevation ☉ 170°S (T) ● 36°53'16"N, 79°25'56"W ±134ft ▲ 803ft  <small>Your Watermark 15 Apr 2022 08:28:34</small>		North East Elevation ☉ 242°SW (T) ● 36°53'16"N, 79°25'56"W ±59ft ▲ 801ft  <small>Your Watermark 15 Apr 2022 08:28:43</small>			
GPS Location	O	GPS Location	O		
Field Station#	15653+00	Field Station#	15650+00		
Pic 1 Desc.	Observing temporary stabilization	Pic 2 Desc.	Observing temporary stabilization, water bar, sump and end treatment		
South West Elevation ☉ 66°NE (T) ● 36°52'48"N, 79°25'32"W ±2339ft ▲ 757ft  <small>Your Watermark 15 Apr 2022 08:35:22</small>		North East Elevation ☉ 241°SW (T) ● 36°52'49"N, 79°25'19"W ±2604ft ▲ 823ft  <small>Your Watermark 15 Apr 2022 08:37:22</small>			
GPS Location	O	GPS Location	O		
Field Station#	15690+00	Field Station#	15693+89		
Pic 3 Desc.	Observing temporary stabilization, water bar and CFS checks	Pic 4 Desc.	Observing road crossing and RCE's		
North East Elevation ☉ 210°SW (T) ● 36°52'44"N, 79°25'13"W ±150ft ▲ 762ft  <small>Your Watermark 15 Apr 2022 08:41:22</small>		East Elevation ☉ 249°W (T) ● 0°0'0"N, 0°0'0"E ▲ 0ft  <small>Your Watermark 15 Apr 2022 08:57:00</small>			
GPS Location	O	GPS Location	O		
Field Station#	15700+46	Field Station#	15735+00		
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's		

A/E	124300139	Date/Time	4/15/2022 9:24 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location			
Field Station#	15720+00	Field Station#			
Pic 7 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	4/15/2022 9:24 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36627
Inspector	Justin Burch			Date/Time	4/15/2022 9:34 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Full	Station End	15370+62
County	Pittsylvania	Ground	Dry	Temperature (°F)	74.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/15/2022 9:34 AM	Report #	36627
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area has not received a rain event. • The ROW ground condition is damp. • At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15355+00 to 15370+00. • At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/15/2022 9:34 AM	Report #	
Pictures					
GPS Location 0		GPS Location 0			
Field Station# 15366+00		Field Station# 15361+00			
Pic 1 Desc. Permanent vegetative stabilization in acceptable condition		Pic 2 Desc. Waterbar in acceptable condition			
GPS Location 0		GPS Location 0			
Field Station# 15361+00		Field Station# 15348+00			
Pic 3 Desc. Waterbar end treatment in acceptable condition		Pic 4 Desc. Waterbar in acceptable condition			
GPS Location 0		GPS Location 0			
Field Station# 15348+00		Field Station# 15346+80			
Pic 5 Desc. Waterbar end treatment in acceptable condition		Pic 6 Desc. Equipment bridge in acceptable condition			

A/E	124300139	Date/Time	4/15/2022 9:34 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	15346+00	Field Station#	15298+00		
Pic 7 Desc.	P1 silt fence and sensitive resource buffer in acceptable conditions	Pic 8 Desc.	Temporary vegetative stabilization and waterbar in acceptable conditions		
GPS Location	0	GPS Location	0		
Field Station#	15296+00	Field Station#	15296+00		
Pic 9 Desc.	Perimeter CFS in acceptable condition	Pic 10 Desc.	Rock construction entrance in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	4/15/2022 9:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	36524
Inspector	John White			Date/Time	4/13/2022 9:08 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	65.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	6.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Sediment Basin	Acceptable			
Rock Filter Outlet	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	4/13/2022 9:08 AM	Report #	36524
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300113	Date/Time	4/13/2022 9:08 AM	Report #	
Pictures					
<p>North Elevation</p> <p>☉ 200°S (T) ● 36°50'7"N, 79°20'24"W ±13ft ▲ 655ft</p>  <p>Your Watermark 13 Apr 2022, 08:25:15</p>			<p>North West Elevation</p> <p>☉ 134°SE (T) ● 36°50'4"N, 79°20'33"W ±7230ft ▲ 665ft</p>  <p>Your Watermark 13 Apr 2022, 08:28:13</p>		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 1 Desc.	Observing RCE		Pic 2 Desc.	Observing rock drain,temporary stabilization,erosion control blanket and cfs checks	
<p>North West Elevation</p> <p>☉ 139°SE (T) ● 36°49'57"N, 79°20'36"W ±13ft ▲ 649ft</p>  <p>Your Watermark 13 Apr 2022, 08:28:32</p>			<p>North East Elevation</p> <p>☉ 236°SW (T) ● 36°50'1"N, 79°20'38"W ±65ft ▲ 650ft</p>  <p>Your Watermark 13 Apr 2022, 08:30:49</p>		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 3 Desc.	Observing temporary stabilization and sediment basin		Pic 4 Desc.	Observing temporary stabilization and sediment basin	
<p>North East Elevation</p> <p>☉ 219°SW (T) ● 36°50'1"N, 79°20'39"W ±16ft ▲ 652ft</p>  <p>Your Watermark 13 Apr 2022, 08:31:04</p>			<p>South West Elevation</p> <p>☉ 65°NE (T) ● 36°50'1"N, 79°20'37"W ±13ft ▲ 659ft</p>  <p>Your Watermark 13 Apr 2022, 08:31:17</p>		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 5 Desc.	Observing temporary stabilization and overflow at sediment basin		Pic 6 Desc.	Observing lay down yard	

A/E	124300113	Date/Time	4/13/2022 9:08 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	4/13/2022 9:08 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		