







Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	36934	
Inspector	John White			Date/Time	4/25/2022 11:20 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Dry	Temperature (°F)	80.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
Waterbar End Treatment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	4/25/2022 11:20 AM	Report #	36934
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/25/2022 11:20 AM	Report #	
Pictures					
North West Elevation 136°SE (T) 36°50'7"N, 79°20'23"W ±36ft ▲ 660ft 		West Elevation 92°E (T) 36°50'1"N, 79°20'15"W ±13ft ▲ 650ft 			
GPS Location	O	GPS Location	O		
Field Station#	14+00	Field Station#	22+00		
Pic 1 Desc.	Observing temporary stabilization and ECD's	Pic 2 Desc.	Observing temporary stabilization, signage and buffer		
East Elevation 259°W (T) 36°50'4"N, 79°20'30"W ±131ft ▲ 645ft 		South Elevation 341°N (T) 36°50'6"N, 79°20'24"W ±22ft ▲ 662ft 			
GPS Location	O	GPS Location	O		
Field Station#	12+00	Field Station#	6+00		
Pic 3 Desc.	Observing temporary stabilization, water bar, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	4/25/2022 11:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/25/2022 11:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36946
Inspector	Ben Farmer			Date/Time	4/25/2022 2:11 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Partial	Station End	14311+57
County	Franklin	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged by livestock		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300139	Date/Time	4/25/2022 2:11 PM	Report #	36946
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 65F) Rain Gauge= 0.0" 14171+36-14311+57 -EI began inspection at Angle Plantation Rd. -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in good condition and functioning -P1 has been damaged by livestock and needs to be replaced at 14190+50. -Waterbars/end treatments are in good condition throughout this section. -Resource buffers remain well vegetated. -CWDs are functioning as intended. -SSF is in good condition -CFS remains in good condition -Slope drain is in good condition and functioning at 14232+00 -Drainage ECDs are in good condition at 14275+00. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/25/2022 2:11 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14171+36		Field Station#	14176+09	
Pic 1 Desc.	RCEs are in good condition at all road crossings		Pic 2 Desc.	Equipment bridge ECDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14180+00		Field Station#	14183+00	
Pic 3 Desc.	CWDs are functioning as intended		Pic 4 Desc.	SSF is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14190+50		Field Station#	14232+00	
Pic 5 Desc.	P1 has been damaged by livestock and needs to be replaced		Pic 6 Desc.	Slope drain is in good condition	

AFE	124300139	Date/Time	4/25/2022 2:11 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14233+00		Field Station#	14278+93	
Pic 7 Desc.	Equipment bridge ECDs are in good condition and functioning		Pic 8 Desc.	Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14285+00		Field Station#	14297+00	
Pic 9 Desc.	ROW remains stabilized		Pic 10 Desc.	Waterbars are in good condition	
				<p>Insert image here</p>	
GPS Location	See photo		GPS Location		
Field Station#	14300+00		Field Station#		
Pic 11 Desc.	CFS is in good condition throughout this section.		Pic 12 Desc.		







A/E	124300139	Date/Time	4/25/2022 2:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	36948	
Inspector	Frank Craycroft			Date/Time	4/25/2022 2:23 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Dry	Temperature (°F)	80.00	
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Communication	ANC-006 Clean out debris on top of	Addressed	4/25/2022	
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	4/25/2022 2:23 PM	Report #	36948
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All construction debris was maintained within bulk dumpsters on-site. All perimeter ECDs were functional and in good condition. Perimeter ECDs at stormwater drain inlets are in place and functioning. Stormwater drain inlet at ANC-006 needed to have woody debris removed from inlet cover to allow runoff to drain properly. Contractor addressed issue today. No other issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/25/2022 2:23 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-048 North perimeter CFS		Pic 2 Desc.	LY-048 Temporary vegetation	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	ANC-006 Secondary containment		Pic 4 Desc.	ANC-006 Clean out debris from stormwater drain inlet	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	LY-032 Equipment staging		Pic 6 Desc.	LY-032 Secondary containment's	

A/E	124300139	Date/Time	4/25/2022 2:23 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-033 Stormwater drain inlet protection	Pic 8 Desc.	LY-033 Staging area and RCE.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/25/2022 2:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36932
Inspector	Justin Burch			Date/Time	4/25/2022 10:35 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Full	Station End	15584+23
County	Pittsylvania	Ground	Dry	Temperature (°F)	88.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Equipment Bridge	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Slope Drain Pipe	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/25/2022 10:35 AM	Report #	36932
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI observed that the solar farm ECDs adjacent to the ROW on the GAS of Climax Road appeared to be in acceptable condition. The EI observed that the turbidity in streams S-MM8 (15521+00) and S-CC5 at 15542+19 has cleared up. This turbidity was result of upstream activities not related to MVP. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has not received a rain event. The ROW ground condition is dry. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15482+00 to 15495+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/25/2022 10:35 AM	Report #	
Pictures					
 <p>15500+00 04-25-2022, 09:20:45</p>		 <p>15530+00 04-25-2022, 10:01:23</p>			
GPS Location	0	GPS Location	0		
Field Station#	15500+00	Field Station#	15530+00		
Pic 1 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 2 Desc.	Waterbar in acceptable condition		
 <p>15530+00 04-25-2022, 10:01:00</p>		 <p>15535+00 04-25-2022, 10:04:06</p>			
GPS Location	0	GPS Location	0		
Field Station#	15530+00	Field Station#	15535+00		
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	CFS in acceptable condition		
 <p>15538+00 04-25-2022, 10:05:23</p>		 <p>15562+00 04-25-2022, 10:21:53</p>			
GPS Location	0	GPS Location	0		
Field Station#	15538+00	Field Station#	15562+00		
Pic 5 Desc.	Clean water diversion pipe and CFS in acceptable conditions	Pic 6 Desc.	P1 silt fence in acceptable condition		

AFE	124300139	Date/Time	4/25/2022 10:35 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15562+68	Field Station#	15567+00		
Pic 7 Desc.	Equipment bridge in acceptable condition		Pic 8 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions	
		<p style="text-align: center;">Insert image here</p>			
GPS Location	0	GPS Location			
Field Station#	15498+00	Field Station#			
Pic 9 Desc.	Solar farm ECDs appear to be in acceptable conditions		Pic 10 Desc.		
<p style="text-align: center;">Insert image here</p>			<p style="text-align: center;">Insert image here</p>		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		


A/E	124300139	Date/Time	4/25/2022 10:35 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36913
Inspector	Ben Davenport			Date/Time	4/25/2022 11:22 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Partial	Station End	14694+77
County	Franklin	Ground	Damp	Temperature (°F)	83.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Equipment Bridge	Acceptable				
Sediment Filter Log	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Waterbar	Acceptable				
Compost Filter Sock	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/25/2022 11:22 AM	Report #	36913
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14649+67 — 14694+77 (Hwy 40 to Jacks Creek Rd) -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosions -No items added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/25/2022 11:22 AM	Report #	
Pictures					
					
36°59'16" N 79°43'22" W 294°W COURSE 65° GPS Union Hall, VA 24176, United States			36°59'25" N 79°43'26" W 183°S COURSE 148° GPS 9400-9598 Old Franklin Tpke, Union Hall, VA 24176, United States		
04.25.2022 09:57:44 Accur +/-15.4 Ft ALT 953 Ft			04.25.2022 09:46:27 Accur +/-728.4 Ft ALT 989 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14673+10		Field Station#	14652+00	
Pic 1 Desc.	Contractor seeded and stabilized disturbed area per punch list item.		Pic 2 Desc.	ROW stabilized and vegetated in final cleanup area.	
					
36°59'22" N 79°43'22" W 177°S COURSE 130° GPS 9400-9598 Old Franklin Tpke, Union Hall, VA 24176, United States			36°59'16" N 79°42'41" W 288°W COURSE -1° GPS 1559-2499 Jacks Creek Rd, Union Hall, VA 24176, United States		
04.25.2022 09:47:54 Accur +/-39.7 Ft ALT 935 Ft			04.25.2022 07:38:10 Accur +/-20.9 Ft ALT 927 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14656+37		Field Station#	14689+36	
Pic 3 Desc.	P1 silt fence along resource buffer in good condition; signage visible and intact.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	
					
36°59'16" N 79°42'44" W 268°W COURSE -1° GPS Sorry no results found			36°59'17" N 79°42'38" W 254°W COURSE 47° GPS 1559-2499 Jacks Creek Rd, Union Hall, VA 24176, United States		
04.25.2022 07:39:39 Accur +/-15.5 Ft ALT 943 Ft			04.25.2022 07:36:54 Accur +/-70.2 Ft ALT 0 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14686+00		Field Station#	14692+00	
Pic 5 Desc.	ROW stabilized and vegetated in temporary area.		Pic 6 Desc.	Water bar performing intended function.	

A/E	124300139	Date/Time	4/25/2022 11:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





A/E	124300139	Date/Time	4/25/2022 11:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I		AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision				Report #	36937	
Inspector	John White				Date/Time	4/25/2022 11:39 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	00+00	
State	VA	Inspection Area	Full		Station End	19+25	
County	Pittsylvania	Ground	Dry		Temperature (°F)	80.00	
Municipality	Chatham	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Housekeeping		Acceptable					
Sediment Filter Log		Acceptable					
Sensitive Resource Buffer		Acceptable					
Sensitive Resource Signage		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Sump Pit		Acceptable					
Waterbar		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	4/25/2022 11:39 AM	Report #	36937
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/25/2022 11:39 AM	Report #	
Pictures					
South East Elevation 320°NW (T) 36°49'50"N, 79°20'35"W ±449ft ▲29ft 		South West Elevation 45°NE (T) 36°49'45"N, 79°20'40"W ±2746ft ▲631ft 			
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	12+65		
Pic 1 Desc.	Observing temporary stabilization and ECD's	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
South East Elevation 334°NW (T) 36°49'44"N, 79°20'40"W ±13ft ▲619ft 		South East Elevation 307°NW (T) 36°49'43"N, 79°20'40"W ±13ft ▲630ft 			
GPS Location	O	GPS Location	O		
Field Station#	12+65	Field Station#	13+50		
Pic 3 Desc.	Observing stream side board on equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization, water bar, sump, end treatment and ECD's		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	4/25/2022 11:39 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/25/2022 11:39 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36941
Inspector	Glenn Mike Renfro			Date/Time	4/25/2022 12:07 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00
State	VA	Inspection Area	Full	Station End	0000+00
County	Franklin	Ground	Dry	Temperature (°F)	77.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Other - Explain in Comments	Acceptable	Inlet protection for catch basins			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/25/2022 12:07 PM	Report #	36941
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have not received any rainfall since the last inspection and site conditions were dry. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were found to be in acceptable condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300139		Date/Time 4/25/2022 12:07 PM		Report #	
Pictures					
GPS Location See picture		GPS Location See picture			
Field Station# 0000+00		Field Station# 0000+00			
Pic 1 Desc. Secondary containment structure for fuel cell at LY-046 in good condition.		Pic 2 Desc. Perimeter ECD's on south end of LY-046 in good condition.			
GPS Location See picture		GPS Location See picture			
Field Station# 0000+00		Field Station# 0000+00			
Pic 3 Desc. Inlet protection and perimeter ECD's on west side of LY-046 in good condition.		Pic 4 Desc. Perimeter ECD's on northwest corner of LY-045 in good condition.			
GPS Location See picture		GPS Location See picture			
Field Station# 0000+00		Field Station# 0000+00			
Pic 5 Desc. Equipment inspected at LY-045 and no leaks observed at the time of inspection.		Pic 6 Desc. RCE at LY-045 in good condition.			

A/E	124300139	Date/Time	4/25/2022 12:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





A/E	124300139	Date/Time	4/25/2022 12:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36940
Inspector	John White			Date/Time	4/25/2022 11:48 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	80.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/25/2022 11:48 AM	Report #	36940
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/25/2022 11:48 AM	Report #	
Pictures					
North West Elevation 120°SE (T) 36°50'10"N, 79°21'39"W ±59ft ▲ 609ft 			East Elevation 252°W (T) 36°49'49"N, 79°20'37"W ±6751ft ▲ 646ft 		
GPS Location	O		GPS Location	O	
Field Station#	15951+72		Field Station#	16024+00	
Pic 1 Desc.	Observing wetland, temporary stabilization, equipment crossing and ECD's		Pic 2 Desc.	Observing temporary stabilization	
North West Elevation 123°SE (T) 36°49'50"N, 79°20'37"W ±32ft ▲ 643ft 			East Elevation 277°W (T) 36°49'51"N, 79°20'40"W ±4255ft ▲ 634ft 		
GPS Location	O		GPS Location	O	
Field Station#	16022+00		Field Station#	16020+00	
Pic 3 Desc.	Observing temporary stabilization and water bars		Pic 4 Desc.	Observing temporary stabilization, sump, end treatment and ECD's	
North East Elevation 220°SW (T) 36°49'28"N, 79°22'13"W ±24412ft ▲ 622ft 			North East Elevation 210°SW (T) 36°49'48"N, 79°20'46"W ±1722ft ▲ 614ft 		
GPS Location	O		GPS Location	O	
Field Station#	16016+36		Field Station#	16016+36	
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		Pic 6 Desc.	Observing side board on equipment crossing and stream	

A/E	124300139	Date/Time	4/25/2022 11:48 AM	Report #	
Pictures					
North Elevation 163°S (T) 36°49'47"N, 79°20'46"W ±75ft ▲ 612ft 		East Elevation 251°W (T) 36°49'46"N, 79°20'48"W ±311ft ▲ 615ft 			
GPS Location	O	GPS Location	O		
Field Station#	16015+70	Field Station#	16010+00		
Pic 7 Desc.	Observing temporary stabilization, signage, buffer and ECD's	Pic 8 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	4/25/2022 11:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36942
Inspector	Charles Head			Date/Time	4/25/2022 12:16 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Full	Station End	15142+66
County	Pittsylvania	Ground	Dry	Temperature (°F)	84.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/25/2022 12:16 PM	Report #	36942
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/25/2022 12:16 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	15068+00	Field Station#	15072+86	Field Station#	15085+00
Pic 1 Desc.	Approximately 15068+00. Overview of ROW.	Pic 2 Desc.	Approximately 15072+86. Overview of stream crossing, equipment bridge and ECDs at stream S-G11.	Pic 3 Desc.	Approximately 15085+00. Overview of ROW.
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	15085+00	Field Station#	15113+00	Field Station#	15120+00
Pic 4 Desc.	Approximately 15113+00. Overview of road crossing and RCEs.	Pic 5 Desc.	Approximately 15120+00. Overview of ROW.	Pic 6 Desc.	Approximately 15137+00. Overview of ROW.

A/E	124300139	Date/Time	4/25/2022 12:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/25/2022 12:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36930
Inspector	Logan Box			Date/Time	4/25/2022 4:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Erosion Control Blanket	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/25/2022 4:28 PM	Report #	36930
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspection the EI observed a section of P1 that requires maintenance due to wildlife damages, documented and added to the punch list for repair.</p> <p>Other than the item listed there were no other issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/25/2022 4:28 PM	Report #	
Pictures					
	South Elevation 			East Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13851+00	Field Station#	13846+93		
Pic 1 Desc.	Monitored reinforced silt fence along the perimeter of the row during inspection, no environmental issues observed at the time of inspection.		Pic 2 Desc.	Stream observation photo facing downstream during routine inspection today. All ECDs in place and no issues were observed at the time of inspection.	
	South Elevation 			West Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13847+20	Field Station#	13846+93		
Pic 3 Desc.	Photo showing stabilization above stream crossing, ECDs observed and functioning at the time of inspection.		Pic 4 Desc.	Stream observation photo facing upstream during routine inspection today, no issues were observed at the time of inspection.	
	South East Elevation 			North Elevation 	
GPS Location	00000	GPS Location	0000		
Field Station#	13749+00	Field Station#	13770+69		
Pic 5 Desc.	P1 requires maintenance due to wildlife damage , added to the punch list for repair.		Pic 6 Desc.	Observed stream crossing where erosion blanket was installed recently, no environmental issues observed at the time of inspection.	

A/E	124300139	Date/Time	4/25/2022 4:28 PM	Report #	
Pictures					
GPS Location	0000	GPS Location	0000		
Field Station#	13850+00	Field Station#	13770+67		
Pic 7 Desc.	Vegetation observation photo showing good coverage.		Pic 8 Desc.	Monitored equipment bridge and protection during routine inspection, no issues were observed at the time of inspection.	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/25/2022 4:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36980
Inspector	John White			Date/Time	4/26/2022 9:36 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Dry	Temperature (°F)	75.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/26/2022 9:36 AM	Report #	36980
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/26/2022 9:36 AM	Report #	
Pictures					
North West Elevation ☉ 115°SE (T) ● 36°53'39"N, 79°26'59"W ±459ft ▲ 804ft 		East Elevation ☉ 272°W (T) ● 36°53'41"N, 79°26'15"W ±9921ft ▲ 805ft 			
GPS Location	O	GPS Location	O		
Field Station#	15584+23	Field Station#	15590+00		
Pic 1 Desc.	Observing road crossing and RCE's	Pic 2 Desc.	Observing temporary stabilization and water bars		
East Elevation ☉ 292°W (T) ● 36°53'40"N, 79°26'49"W ±167ft ▲ 776ft 		South Elevation ☉ 341°N (T) ● 36°53'32"N, 79°26'21"W ±91ft ▲ 834ft 			
GPS Location	O	GPS Location	O		
Field Station#	15595+60	Field Station#	15617+00		
Pic 3 Desc.	Observing temporary stabilization, water bars, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization, water bar, sump and end treatment		
North Elevation ☉ 173°S (T) ● 36°52'54"N, 79°24'32"W ±5433ft ▲ 798ft 		North East Elevation ☉ 224°SW (T) ● 36°53'29"N, 79°26'0"W ±124ft ▲ 781ft 			
GPS Location	O	GPS Location	O		
Field Station#	15642+00	Field Station#	15636+45		
Pic 5 Desc.	Observing temporary stabilization	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

A/E	124300139	Date/Time	4/26/2022 9:36 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location			
Field Station#	15632+00	Field Station#			
Pic 7 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/26/2022 9:36 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36938
Inspector	Ben Davenport			Date/Time	4/26/2022 11:43 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Partial	Station End	14454+22
County	Franklin	Ground	Damp	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Sump Pit	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Erosion Control Blanket	Acceptable				
Temporary Diversion Berm	Acceptable				
Rock Construction Entrance	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	4/26/2022 11:43 AM	Report #	36938
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd) -Contractor finished replacing ECDs and seeding and stabilizing ROW in section -Walked ROW making note of condition of ROW and environmental controls -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/26/2022 11:43 AM	Report #	
Pictures					
					
37°2'34" N 79°48'33" W 191°S COURSE 100° GPS 530 Farm View Rd, Glade Hill, VA 24092, United States 04.26.2022 11:54:40 Accur +/-37.1 Ft ALT 1056 Ft			37°2'34" N 79°48'33" W 141°SE COURSE 286° GPS 530 Farm View Rd, Glade Hill, VA 24092, United States 04.26.2022 11:57:11 Accur +/-120.3 Ft ALT 1061 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14313+00	Field Station#	14314+79		
Pic 1 Desc.	Contractor replaced damaged ECDs throughout section.		Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	
					
37°2'32" N 79°48'31" W 333°NW COURSE 224° GPS 530 Farm View Rd, Glade Hill, VA 24092, United States 04.26.2022 11:58:03 Accur +/-57.4 Ft ALT 1065 Ft			37°2'18" N 79°48'17" W 196°S COURSE 35° GPS 1634-1816 Golden View Rd, Glade Hill, VA 24092, United States 04.26.2022 12:03:22 Accur +/-52.2 Ft ALT 1164 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14316+00	Field Station#	14335+00		
Pic 3 Desc.	Contractor replaced damaged ECDs throughout section.		Pic 4 Desc.	Contractor temporary seeded and stabilized ROW throughout section.	
					
37°2'18" N 79°48'17" W 108°E COURSE 157° GPS 1634-1816 Golden View Rd, Glade Hill, VA 24092, United States 04.26.2022 12:04:25 Accur +/-114.8 Ft ALT 1165 Ft			37°1'35" N 79°46'6" W 57°NE COURSE 153° GPS 2753-2799 Webster Rd, Glade Hill, VA 24092, United States 04.26.2022 12:13:07 Accur +/-15.4 Ft ALT 1092 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14338+56	Field Station#	14454+22		
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 6 Desc.	Contractor replaced rock on RCE after completion of activity in section.	

A/E	124300139	Date/Time	4/26/2022 11:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/26/2022 11:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36987
Inspector	Justin Burch			Date/Time	4/26/2022 10:19 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Full	Station End	15260+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	82.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Compost Filter Sock	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Sensitive Resource Buffer	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/26/2022 10:19 AM	Report #	36987
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area has not received a rain event. • The ROW ground condition is dry. • At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. • At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/26/2022 10:19 AM	Report #	
Pictures					
101°E (T) 36°53'37"N, 79°32'29"W ±21046ft ▲ 794ft  15240+00 04-26-2022, 09:03:33		241°SW (T) 36°56'4"N, 79°32'34"W ±13ft ▲ 746ft  15260+00 04-26-2022, 09:08:42			
GPS Location	0	GPS Location	0		
Field Station#	15240+00	Field Station#	15260+00		
Pic 1 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 2 Desc.	Perimeter CFS in acceptable condition		
27°NE (T) 36°56'23"N, 79°33'36"W ±666ft ▲ 815ft  15206+00 04-26-2022, 09:24:05		282°W (T) 36°56'24"N, 79°33'34"W ±45ft ▲ 815ft  15206+00 04-26-2022, 09:24:41			
GPS Location	0	GPS Location	0		
Field Station#	15206+00	Field Station#	15206+00		
Pic 3 Desc.	Waterbar in acceptable condition	Pic 4 Desc.	Waterbar end treatment in acceptable condition		
274°W (T) 36°56'24"N, 79°33'35"W ±13ft ▲ 831ft  15205+00 04-26-2022, 09:25:08		135°SE (T) 36°56'43"N, 79°34'28"W ±456ft ▲ 804ft  15159+00 04-26-2022, 11:00:39			
GPS Location	0	GPS Location	0		
Field Station#	15205+00	Field Station#	15159+00		
Pic 5 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 6 Desc.	Waterbar in acceptable condition		

A/E	124300139	Date/Time	4/26/2022 10:19 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	15159+00	Field Station#	15169+00		
Pic 7 Desc.	Waterbar end treatment in acceptable condition	Pic 8 Desc.	P1 silt fence and sensitive resource buffer in acceptable conditions		
GPS Location	0	GPS Location	0		
Field Station#	15170+00	Field Station#	15169+00		
Pic 9 Desc.	Temporary vegetative stabilization and perimeter CFS in acceptable conditions	Pic 10 Desc.	Super silt fence in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	4/26/2022 10:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36998
Inspector	Ben Farmer			Date/Time	4/26/2022 2:27 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Partial	Station End	13958+31
County	Franklin	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/26/2022 2:27 PM	Report #	36998
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 65F) Rain Gauge= 0.0" 13853+45-13958+31 -EI began inspection at MVP-FR-303.1 -FR-303.1 remains in good condition with controls in place. -Waterbars/end treatments are in good condition. -Resource buffers remain well vegetated at all stream and wetland crossings. -CWDs are in good condition and functioning as intended -Equipment bridge ECDs are in good condition and functioning. -Slope drain/Slope drain outlets are in good condition and functioning. -Steep slope at 13889+00 remains stabilized. -RCEs are in good condition at all road crossings. -Topsoil berms remain stabilized. -Sediment trap at 13897+00 is in good condition with no evidence of discharge. -CFS is in good condition. -P1 is in good condition at all stream and wetland buffers -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/26/2022 2:27 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13858+00		Field Station#	13863+00	
Pic 1 Desc.	Vegetation continues to fill in throughout this section		Pic 2 Desc.	Equipment bridge ECDs are in good condition. Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13867+00		Field Station#	13875+50	
Pic 3 Desc.	CWDs are functioning as intended		Pic 4 Desc.	P1 is in good condition at all stream and wetland buffers	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13888+50		Field Station#	13889+00	
Pic 5 Desc.	Slope drain is in good condition		Pic 6 Desc.	Slope remains stabilized with controls in place	

AFE	124300139	Date/Time	4/26/2022 2:27 PM	Report #	
Pictures					
					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13892+45		Field Station#	13897+00	
Pic 7 Desc.	RCEs are in good condition at all road crossings		Pic 8 Desc.	Topsoil pile remains stabilized	
					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13897+00		Field Station#	13925+00	
Pic 9 Desc.	Sediment trap is in good condition and functioning		Pic 10 Desc.	CFS is in good condition	
					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13939+50		Field Station#	13955+00	
Pic 11 Desc.	SSF is in good condition along across road.		Pic 12 Desc.	Waterbars remain stabilized and in good condition	







AFE	124300139	Date/Time	4/26/2022 2:27 PM	Report #	
Pictures					
		<p>Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	13954+00	Field Station#			
Pic 13 Desc.	Slope drain is in is functioning as intended	Pic 14 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	36994
Inspector	Charles Head			Date/Time	4/26/2022 1:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Full	Station End	14802+19
County	Franklin	Ground	Dry	Temperature (°F)	76.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/26/2022 1:25 PM	Report #	36994
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/26/2022 1:25 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14697+00	Field Station#	14716+50		
Pic 1 Desc.	Approximately 14697+00. Overview of ROW.	Pic 2 Desc.	Overview of wetland crossing, equipment bridge and ECDs at wetland W-H11. Third party disturbance and ECDs along and beyond north LOP.		
					
GPS Location	0	GPS Location	0		
Field Station#	14758+00	Field Station#	14775+00		
Pic 3 Desc.	Approximately 14758+00. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14775+00. Overview of ROW.		
					
GPS Location	0	GPS Location	0		
Field Station#	14782+25	Field Station#	14788+77		
Pic 5 Desc.	Approximately 14782+25. Overview of stream crossing, equipment bridge and ECDs at stream S-MM48.	Pic 6 Desc.	Approximately 14788+77. Overview of stream crossing, equipment bridge and ECDs at stream S-H25.		

A/E	124300139	Date/Time	4/26/2022 1:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/26/2022 1:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37052
Inspector	Ben Farmer			Date/Time	4/27/2022 1:50 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Partial	Station End	14062+17
County	Franklin	Ground	Damp	Temperature (°F)	50.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Communication	Equipment bridge fabric needs to be			
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/27/2022 1:50 PM	Report #	37052
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 50F) Rain Gauge= 0.2" 13958+31-14062+17 -EI began inspection at Foggy Ridge Rd. -This section remains stabilized. -CWD/CWD inlets are in good condition and functioning as intended -MVP-ATWS-1446 remains stabilized with controls in place. -No evidence of 3rd party pond discharging onto ROW. -Resource buffers remain well vegetated. -Slope on the CIS of Highway 220 remains stabilized with controls in place. -Waterbars/end treatments are functioning as intended. -P1 is in good condition at all stream and wetland buffers -Equipment bridge fabric needs to be reattached at 14035+28. -CFS is in good condition -Slope drain is functioning as intended at 14058+00 -Rock check dams are functioning at 14059+00. -Vegetation continues to fill in throughout this section *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/27/2022 1:50 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13960+00		Field Station#	13968+00	
Pic 1 Desc.	CWDs are functioning as intended		Pic 2 Desc.	This section remains temporarily stabilized	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13987+00		Field Station#	13991+29	
Pic 3 Desc.	Waterbars are in good condition		Pic 4 Desc.	CFS is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13995+20		Field Station#	13998+15	
Pic 5 Desc.	ATWS-1446 remains stabilized with controls in place.		Pic 6 Desc.	P1 is in good condition at all stream and wetland buffers	

AFE	124300139	Date/Time	4/27/2022 1:50 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14000+00		Field Station#	14018+47	
Pic 7 Desc.	No evidence of 3rd party pond discharging onto ROW		Pic 8 Desc.	RCEs are in good condition at all road crossings	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14034+00		Field Station#	14035+00	
Pic 9 Desc.	Waterbar end treatments are functioning as intended		Pic 10 Desc.	Resource buffers remain well vegetated	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14035+28		Field Station#	14050+00	
Pic 11 Desc.	Equipment bridge fabric needs to be reattached		Pic 12 Desc.	This slope remains stabilized	







AFE	124300139	Date/Time	4/27/2022 1:50 PM	Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14057+00		Field Station#	14059+00	
Pic 13 Desc.	Slope drain is in good condition and functioning		Pic 14 Desc.	Rock check dams are functioning as intended	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 15 Desc.			Pic 16 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 17 Desc.			Pic 18 Desc.		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37003
Inspector	Ben Davenport			Date/Time	4/27/2022 9:21 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Partial	Station End	14546+75
County	Franklin	Ground	Damp	Temperature (°F)	63.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Slope Drain Pipe	Acceptable				
Sump Pit	Acceptable				
Waterbar	Acceptable				
Sensitive Resource Buffer	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/27/2022 9:21 AM	Report #	37003
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="border: 1px solid black; height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Checked rain gauges in covered area -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd) -Walked ROW making note of condition of ROW and environmental controls -Contractor was replacing ECDs and completing punch list items in section during inspection -Contractor was seeding and stabilizing ROW during inspection -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No items added to environmental punch list <ul style="list-style-type: none"> -Rain Gauge Totals: +Farm View: 0.20 inches recorded +Timber Ridge: 0.10 inches recorded 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/27/2022 9:21 AM	Report #	
Pictures					
					
37°1'0" N 79°45'35" W 45°NE COURSE 259' GPS 1142 SR-703, Glade Hill, VA 24092, United States 04.27.2022 10:33:56 Accur +/-15.9 Ft ALT 894 Ft			37°0'47" N 79°45'22" W 255°W COURSE 318' GPS Glade Hill, VA 24092, United States 04.27.2022 10:24:24 Accur +/-15.4 Ft ALT 966 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14496+00	Field Station#	14521+00		
Pic 1 Desc.	Contractor seeding and stabilizing ROW.	Pic 2 Desc.	Contractor removing damaged ECDs per punch list item.		
					
37°0'49" N 79°45'24" W 161°S COURSE 168' GPS 1979 SR-674, Glade Hill, VA 24092, United States 04.27.2022 10:39:42 Accur +/-53.4 Ft ALT 941 Ft			37°1'2" N 79°45'35" W 67°NE COURSE 311' GPS 1979 SR-674, Glade Hill, VA 24092, United States 04.27.2022 10:31:51 Accur +/-143.2 Ft ALT 880 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14521+00	Field Station#	14497+50		
Pic 3 Desc.	Contractor replacing ECDs per punch list item.	Pic 4 Desc.	Contractor replaced damaged ECDs per punch list item.		
					
37°0'59" N 79°45'33" W 37°NE COURSE 232' GPS 1979 SR-674, Glade Hill, VA 24092, United States 04.27.2022 10:30:25 Accur +/-102.8 Ft ALT 944 Ft			37°0'52" N 79°45'27" W 33°NE COURSE 334' GPS 1979 SR-674, Glade Hill, VA 24092, United States 04.27.2022 10:26:37 Accur +/-54.4 Ft ALT 961 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14501+50	Field Station#	14509+00		
Pic 5 Desc.	Contractor replaced damaged ECDs per punch list item.	Pic 6 Desc.	Contractor replaced damaged ECDs per punch list item.		

A/E	124300139	Date/Time	4/27/2022 9:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/27/2022 9:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37044
Inspector	John White			Date/Time	4/27/2022 10:53 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Dry	Temperature (°F)	58.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/27/2022 10:53 AM	Report #	37044
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/27/2022 10:53 AM	Report #	
Pictures					
South Elevation 340°N (T) 36°52'10"N, 79°24'8"W ±82ft ▲ 807ft  <small>Your Watermark 27 Apr 2022, 10:03:17</small>		South East Elevation 337°NW (T) 36°52'14"N, 79°24'8"W ±144ft ▲ 835ft  <small>Your Watermark 27 Apr 2022, 10:05:35</small>			
GPS Location	O	GPS Location	O		
Field Station#	15770+00	Field Station#	15763+80		
Pic 1 Desc.	Observing temporary stabilization	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
North West Elevation 151°SE (T) 36°52'13"N, 79°24'45"W ±7490ft ▲ 842ft  <small>Your Watermark 27 Apr 2022, 10:22:21</small>		North West Elevation 124°SE (T) 36°52'23"N, 79°24'42"W ±52ft ▲ 861ft  <small>Your Watermark 27 Apr 2022, 10:25:44</small>			
GPS Location	O	GPS Location	O		
Field Station#	15739+00	Field Station#	15735+00		
Pic 3 Desc.	Observing temporary stabilization, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
North West Elevation 126°SE (T) 36°52'49"N, 79°24'2"W ±20767ft ▲ 820ft  <small>Your Watermark 27 Apr 2022, 10:51:55</small>		North Elevation 181°S (T) 36°52'49"N, 79°25'19"W ±68ft ▲ 826ft  <small>Your Watermark 27 Apr 2022, 11:55:37</small>			
GPS Location	O	GPS Location	O		
Field Station#	15700+40	Field Station#	15693+89		
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing road crossing and RCE's		

A/E	124300139	Date/Time	4/27/2022 10:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/27/2022 10:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	37048		
Inspector	Charles Head	Date/Time	4/27/2022 12:29 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Full	Station End	14928+52
County	Franklin	Ground	Dry	Temperature (°F)	62.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/27/2022 12:29 PM	Report #	37048
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/27/2022 12:29 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	14921+00	Field Station#	14865+00	Field Station#	14846+00
Pic 1 Desc.	Approximately 14921+00. Overview of ROW.		Pic 2 Desc.	Approximately 14865+00. Overview of ROW.	
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	14846+00	Field Station#	14841+00	Field Station#	14823+54
Pic 3 Desc.	Approximately 14846+00. Overview of road crossing and RCEs.		Pic 4 Desc.	Approximately 14841+00. Overview of ROW.	
Pic 5 Desc.	Approximately 14823+54. Overview of stream crossing, equipment bridge and ECDs at stream S-A13.		Pic 6 Desc.	Approximately 14812+00. Overview of ROW. Permanent vegetation.	

A/E	124300139	Date/Time	4/27/2022 12:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




A/E	124300139	Date/Time	4/27/2022 12:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37046
Inspector	Justin Burch			Date/Time	4/27/2022 11:16 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Full	Station End	15370+62
County	Pittsylvania	Ground	Dry	Temperature (°F)	68.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Reinforce Filter Fence)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Plunge Pool	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Rock Construction Entrance	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/27/2022 11:16 AM	Report #	37046
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No punch list issues were submitted due to the inspected ECDs being in compliance at the time of inspection. • The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed the items on the punch list. • Since the last SWPPP inspection the area has not received any rainfall. • The ROW ground condition is dry. • At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15355+00 to 15370+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/27/2022 11:16 AM	Report #	
Pictures					
 <p>15348+00 04-27-2022, 09:23:20</p>		 <p>15338+00 04-27-2022, 10:02:48</p>			
GPS Location	0	GPS Location	0		
Field Station#	15348+00	Field Station#	15338+00		
Pic 1 Desc.	P1 silt fence in acceptable condition	Pic 2 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions		
 <p>15325+00 04-27-2022, 10:18:19</p>		 <p>15323+50 04-27-2022, 10:26:41</p>			
GPS Location	0	GPS Location	0		
Field Station#	15325+00	Field Station#	15323+50		
Pic 3 Desc.	Perimeter CFS and temporary vegetative stabilization in acceptable conditions	Pic 4 Desc.	Rock construction entrance in acceptable condition		
 <p>15301+00 04-27-2022, 10:38:02</p>		 <p>15301+00 04-27-2022, 10:38:36</p>			
GPS Location	0	GPS Location	0		
Field Station#	15301+00	Field Station#	15301+00		
Pic 5 Desc.	Waterbar in acceptable condition	Pic 6 Desc.	Waterbar end treatment in acceptable condition		

A/E	124300139	Date/Time	4/27/2022 11:16 AM	Report #	
Pictures					
 <p>15307+00 04-27-2022, 10:41:05</p>		 <p>15312+00 04-27-2022, 10:55:06</p>			
GPS Location	0	GPS Location	0		
Field Station#	15307+00	Field Station#	15312+00		
Pic 7 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable condition	Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/27/2022 11:16 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37095
Inspector	Justin Burch			Date/Time	4/28/2022 9:49 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Full	Station End	15480+67
County	Pittsylvania	Ground	Dry	Temperature (°F)	71.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Vegetative Stabilization (Permanent)		Acceptable			
Waterbar End Treatment		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
Cleanwater Diversion Berm		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/28/2022 9:49 AM	Report #	37095
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). No punch list items were submitted because the inspected ECDs were in compliance at the time of inspection. The EI observed that the perimeter solar farm ECDs on the CIS of Toshes Road appeared to be in acceptable condition. No contractor activity was observed in the inspection area since the last SWPPP inspection. Since the last SWPPP inspection the area has not received any rainfall. The ROW ground condition is dry. At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15438+00 to 15445+00. At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/28/2022 9:49 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15477+00	Field Station#	15453+00		
Pic 1 Desc.	Waterbar in acceptable condition	Pic 2 Desc.	Clean water diversion pipe and CFS in acceptable conditions		
					
GPS Location	0	GPS Location	0		
Field Station#	15441+00	Field Station#	15434+00		
Pic 3 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 4 Desc.	Waterbar in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	15434+00	Field Station#	15428+00		
Pic 5 Desc.	Waterbar end treatment in acceptable condition	Pic 6 Desc.	Super silt fence in acceptable condition		

AFE	124300139	Date/Time	4/28/2022 9:49 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	15421+00	Field Station#	15414+00		
Pic 7 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 8 Desc.	P1 silt fence and CFS in acceptable conditions		
GPS Location	0	GPS Location	0		
Field Station#	15388+00	Field Station#	15473+00		
Pic 9 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable condition	Pic 10 Desc.	Solar farm ECDs appear to be in acceptable conditions		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	4/28/2022 9:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37088
Inspector	Logan Box			Date/Time	4/28/2022 3:56 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Damp	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication				
Silt Fence (Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/28/2022 3:56 PM	Report #	37088
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspection the EI observed CFS that was damaged from wildlife activities, documented and added to the punch list for repair by the contractor.</p> <p>EI discussed the issues with the contractor and the locations.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/28/2022 3:56 PM	Report #	
Pictures					
	North East Elevation 			South Elevation 	
GPS Location	00000	GPS Location	0000		
Field Station#	13678+71	Field Station#	13738+90		
Pic 1 Desc.	Stream observation photo facing downstream during routine inspection today, all ECDs in place and functioning at the time of inspection.		Pic 2 Desc.	Vegetation observation photo in permanent area of row. Good stabilization noted during inspection.	
	North West Elevation 			South Elevation 	
GPS Location	000	GPS Location	0000		
Field Station#	13741+00	Field Station#	13678+71		
Pic 3 Desc.	Monitored sump pit and end treatment during routine inspection, no environmental issues observed at the time of inspection.		Pic 4 Desc.	Stream observation photo facing upstream during routine inspection today. No issues were observed at the time of inspection.	
	North East Elevation 			South Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13747+45	Field Station#	13691+20		
Pic 5 Desc.	CFS requires maintenance due to wildlife damage, documented and added to the punch list.		Pic 6 Desc.	Inspected ECDs round wetland area inside work space, no issues were observed at the time of inspection.	

AFE	124300139	Date/Time	4/28/2022 3:56 PM	Report #	
Pictures					
 <p>North Elevation 191°S (T) • 37.075241, -79.940901 ±6 m ▲ 317 m</p>		 <p>East Elevation 283°W (T) • 37.0885, -79.950275 ±7 m ▲ 315 m</p>			
GPS Location	0000	GPS Location	0000		
Field Station#	13747+67	Field Station#	13678+50		
Pic 7 Desc.	CFS requires maintenance due to wildlife damage, documented and added to the punch list.	Pic 8 Desc.	Monitored vegetation and ECDs during row inspection today. No environmental issues observed at the time of inspection.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	4/28/2022 3:56 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	37101	
Inspector	Ben Farmer				Date/Time	4/28/2022 1:37 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	14062+17	
State	VA	Inspection Area	Partial		Station End	14171+36	
County	Franklin	Ground	Dry		Temperature (°F)	45.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe		Acceptable					
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Rock Construction Entrance		Acceptable					
Sensitive Resource Buffer		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Slope Drain Pipe		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
Waterbar		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	4/28/2022 1:37 PM	Report #	37101
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 45F) Rain Gauge= 0.0" 14062+17-14171+36 -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in place and functioning -CWDs are functioning as intended. -MVP-FR-309.05 is in good condition with controls in place. -P1 is in good condition at all stream and wetland buffers. -Ground nest located at 14105+25 in S-KL41 buffer. ESI has been notified. -Slope drain is functioning as intended at 14157+00. -Resource buffers remain well vegetated. -Waterbars/end treatments are in good condition and functioning -CFS is in good condition throughout this section -Vegetation continues to fill in throughout this section					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/28/2022 1:37 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14062+17		Field Station#	14066+77	
Pic 1 Desc.	RCEs are in good condition at all road crossings		Pic 2 Desc.	Equipment bridge ECDs are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14070+00		Field Station#	14085+00	
Pic 3 Desc.	CWDs are functioning as intended		Pic 4 Desc.	Topsoil berms remain stabilized	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14087+00		Field Station#	14104+00	
Pic 5 Desc.	Vegetation continues to fill in throughout this section		Pic 6 Desc.	Waterbars are in good condition	

AFE	124300139	Date/Time	4/28/2022 1:37 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14105+25	Field Station#	14105+32		
Pic 7 Desc.	Ground nest found at this location. ESI has been notified	Pic 8 Desc.	Resource buffers remain well vegetated		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14141+62	Field Station#	14157+00		
Pic 9 Desc.	P1 is in good condition at all stream and wetland buffers	Pic 10 Desc.	Slope drain is in good condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14157+75	Field Station#	14165+00		
Pic 11 Desc.	Resource buffers remain well vegetated	Pic 12 Desc.	CFS is in good condition throughout this section.		







A/E	124300139	Date/Time	4/28/2022 1:37 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	37092		
Inspector	John White	Date/Time	4/28/2022 8:31 AM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Dry	Temperature (°F)	55.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Housekeeping		Acceptable			
Plunge Pool		Acceptable			
Rock Construction Entrance		Acceptable			
Rock Filter Outlet		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/28/2022 8:31 AM	Report #	37092
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/28/2022 8:31 AM	Report #	
Pictures					
West Elevation 111°E (T) 36°51'15"N, 79°23'27"W ±26ft ▲ 819ft 		North West Elevation 153°SE (T) 36°51'15"N, 79°23'25"W ±85ft ▲ 817ft 			
GPS Location	O	GPS Location	O		
Field Station#	15835+00	Field Station#	15837+00		
Pic 1 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 2 Desc.	Observing rock lined channel and ECD's		
South Elevation 20°N (T) 36°51'21"N, 79°23'31"W ±964ft ▲ 837ft 		North Elevation 161°S (T) 36°51'20"N, 79°23'37"W ±114ft ▲ 840ft 			
GPS Location	O	GPS Location	O		
Field Station#	15826+77	Field Station#	15825+00		
Pic 3 Desc.	Observing road crossing and RCE's	Pic 4 Desc.	Observing temporary stabilization,plunge pool and ECD's		
North Elevation 191°S (T) 36°51'34"N, 79°23'24"W ±10925ft ▲ 786ft 		North West Elevation 154°SE (T) 36°51'4"N, 79°23'3"W ±88ft ▲ 771ft 			
GPS Location	O	GPS Location	O		
Field Station#	15852+88	Field Station#	15860+00		
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing temporary stabilization,water bar and CFS checks		

A/E	124300139	Date/Time	4/28/2022 8:31 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/28/2022 8:31 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37100
Inspector	Charles Head			Date/Time	4/28/2022 1:16 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Full	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Dry	Temperature (°F)	65.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/28/2022 1:16 PM	Report #	37100
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/28/2022 1:16 PM	Report #	
Pictures					
				 28 Apr 2022, 13:14:14	
GPS Location	0	GPS Location	0		
Field Station#	15061+00	Field Station#	14983+50		
Pic 1 Desc.	Approximately 15061+00. Overview of ROW.	Pic 2 Desc.	Approximately 14983+50. Overview of ROW.		
				 28 Apr 2022, 13:01:11	
GPS Location	0	GPS Location	0		
Field Station#	14981+50	Field Station#	14965+00		
Pic 3 Desc.	Approximately 14981+50. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14965+00. Overview of ROW. Permanent vegetation.		
				 28 Apr 2022, 12:35:38	
GPS Location	0	GPS Location	0		
Field Station#	14950+47	Field Station#	14935+00		
Pic 5 Desc.	Approximately 14950+47. Overview of stream crossing, equipment bridge and ECDs at stream S-G13.	Pic 6 Desc.	Approximately 14935+00. Overview of ROW.		

A/E	124300139	Date/Time	4/28/2022 1:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/28/2022 1:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37096
Inspector	Ben Davenport			Date/Time	4/28/2022 11:53 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Partial	Station End	14649+67
County	Franklin	Ground	Damp	Temperature (°F)	66.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Routine maintenance			
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance			
Waterbar End Treatment	Communication	Routine maintenance			
Compost Filter Sock	Communication	Routine maintenance			
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance			
Waterbar End Treatment	Communication	Routine maintenance			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/28/2022 11:53 AM	Report #	37096
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Received instruction from Lead EI for daily tasks -Sunny with damp ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14546+75 — 14649+67 (Tobacco Rd to Hwy 40) -Walked ROW making note of condition of ROW and environmental controls -Walked with contractor to determine ECDs in section to be replaced -Verified the completion and accuracy of punch list items in covered area from previous inspections -Perimeter controls and ECD's were inspected; multiple issues identified -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -Multiple items added to environmental punch list 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/28/2022 11:53 AM	Report #	
Pictures					
					
37°02'0" N 79°45'10" W 171°S COURSE -1° GPS 04.28.2022 08:58:59 Sorry no results found Accur +/-184.4 Ft ALT 951 Ft			37°01'8" N 79°45'9" W 243°SW COURSE -1° GPS 04.28.2022 09:00:30 Sorry no results found Accur +/-216.1 Ft ALT 951 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14548+00	Field Station#	14551+00		
Pic 1 Desc.	Routine maintenance. Replace damaged/worn perimeter CFS.		Pic 2 Desc.	Routine maintenance. Replace damaged/worn P1 silt fence and CFS at plunge pool.	
					
37°01'5" N 79°45'7" W 311°NW COURSE 299° GPS 04.28.2022 09:01:48 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-656.2 Ft ALT 938 Ft			37°07' N 79°44'57" W 32°NE COURSE 150° GPS 04.28.2022 09:13:03 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-217.6 Ft ALT 930 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14552+00	Field Station#	14566+50		
Pic 3 Desc.	Routine maintenance. Replace CFS end treatment.		Pic 4 Desc.	Routine maintenance. Replace CFS end treatment.	
					
37°04' N 79°44'52" W 99°E COURSE -1° GPS 04.28.2022 09:14:25 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-121.9 Ft ALT 878 Ft			37°04' N 79°44'52" W 81°E COURSE -1° GPS 04.28.2022 09:15:11 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-91.1 Ft ALT 883 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14567+60	Field Station#	14568+10		
Pic 5 Desc.	Routine maintenance. Replace worn P1 silt fence in resource buffer.		Pic 6 Desc.	Routine maintenance. Replace damaged/worn CFS in resource buffer.	

A/E	124300139	Date/Time	4/28/2022 11:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		













A/E	124300139	Date/Time	4/28/2022 11:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37152
Inspector	Charles Head			Date/Time	4/29/2022 2:32 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Full	Station End	15142+66
County	Pittsylvania	Ground	Dry	Temperature (°F)	62.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/29/2022 2:32 PM	Report #	37152
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 2:32 PM	Report #	
Pictures					
  <small>29 Apr 2022, 10:34:53</small>		  <small>29 Apr 2022, 10:29:54</small>			
GPS Location	0	GPS Location	0		
Field Station#	15068+00	Field Station#	15085+00		
Pic 1 Desc.	Approximately 15068+00. Overview of ROW.	Pic 2 Desc.	Approximately 15085+00. Overview of ROW.		
  <small>29 Apr 2022, 10:26:03</small>		  <small>29 Apr 2022, 10:25:03</small>			
GPS Location	0	GPS Location	0		
Field Station#	15110+00	Field Station#	15113+50		
Pic 3 Desc.	Approximately 15110+00. Overview of ROW.	Pic 4 Desc.	Approximately 15113+50. Overview of road crossing and RCEs.		
  <small>29 Apr 2022, 10:20:34</small>		  <small>29 Apr 2022, 09:27:02</small>			
GPS Location	0	GPS Location	0		
Field Station#	15126+40	Field Station#	15140+00		
Pic 5 Desc.	Approximately 15126+40. Overview of stream crossing, equipment bridge and ECDs at stream S-A6.	Pic 6 Desc.	Approximately 15140+00. Overview of ROW.		

A/E	124300139	Date/Time	4/29/2022 2:32 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/29/2022 2:32 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	37135	
Inspector	John White			Date/Time	4/29/2022 9:58 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Dry	Temperature (°F)	53.00	
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	4.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Waterbar End Treatment		Acceptable				
Sump Pit		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	4/29/2022 9:58 AM	Report #	37135
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 9:58 AM	Report #	
Pictures					
South West Elevation 28°NE (T) 36°49'51"N, 79°21'40"W ±16217ft ▲ 675ft 			North West Elevation 128°SE (T) 36°49'45"N, 79°20'39"W ±32ft ▲ 625ft 		
GPS Location	O		GPS Location	O	
Field Station#	6+00		Field Station#	12+65	
Pic 1 Desc.	Observing temporary stabilization and access road		Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	
South West Elevation 31°NE (T) 36°49'43"N, 79°20'40"W ±13ft ▲ 631ft 			West Elevation 110°E (T) 36°49'43"N, 79°20'40"W ±13ft ▲ 626ft 		
GPS Location	O		GPS Location	O	
Field Station#	13+50		Field Station#	15+00	
Pic 3 Desc.	Observing temporary stabilization, water bar, sump, end treatment and ECD's		Pic 4 Desc.	Observing temporary stabilization and signage	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	4/29/2022 9:58 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/29/2022 9:58 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37131
Inspector	Justin Burch			Date/Time	4/29/2022 9:43 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Full	Station End	15584+23
County	Pittsylvania	Ground	Dry	Temperature (°F)	70.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Permanent)	Acceptable				
Equipment Bridge	Acceptable				
Sump Pit	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Waterbar End Treatment	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/29/2022 9:43 AM	Report #	37131
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection. The EI observed that the solar farm ECDs adjacent to the ROW on the GAS of Climax Road appeared to be in acceptable condition. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area has not received any rainfall. The ROW ground condition is dry. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 15482+00 to 15495+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 9:43 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15481+00	Field Station#	15507+77		
Pic 1 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 2 Desc.	Equipment bridge in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	15516+00	Field Station#	15514+00		
Pic 3 Desc.	Sump pit and clean water diversion pipe in acceptable conditions	Pic 4 Desc.	Waterbar end treatment in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	15527+00	Field Station#	15530+00		
Pic 5 Desc.	P1 silt fence in acceptable condition	Pic 6 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		

A/E	124300139	Date/Time	4/29/2022 9:43 AM	Report #	
Pictures					
323°NW (T) 36°53'53"N, 79°27'36"W ±19ft ▲ 841ft  15550+00 04-29-2022, 10:28:06		315°NW (T) 36°53'54"N, 79°27'36"W ±19ft ▲ 841ft  15550+00 04-29-2022, 10:28:31			
GPS Location	0	GPS Location	0		
Field Station#	15550+00	Field Station#	15550+00		
Pic 7 Desc.	Waterbar in acceptable condition	Pic 8 Desc.	Waterbar end treatment in acceptable condition		
81°E (T) 36°53'54"N, 79°27'36"W ±13ft ▲ 838ft  15551+00 04-29-2022, 10:29:19		75°E (T) 36°53'47"N, 79°27'15"W ±242ft ▲ 791ft  15568+00 04-29-2022, 11:11:11			
GPS Location	0	GPS Location	0		
Field Station#	15551+00	Field Station#	15568+00		
Pic 9 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 10 Desc.	Temporary vegetative stabilization in acceptable condition		
297°NW (T) 36°53'41"N, 79°27'4"W ±347ft ▲ 771ft  15580+00 04-29-2022, 11:29:45		345°N (T) 36°54'18"N, 79°28'14"W ±29ft ▲ 875ft  15510+00 04-29-2022, 09:48:03			
GPS Location	0	GPS Location	0		
Field Station#	15580+00	Field Station#	15510+00		
Pic 11 Desc.	Temporary vegetative stabilization and waterbar in acceptable conditions	Pic 12 Desc.	Solar farm ECDs appear to be in acceptable conditions		







A/E	124300139	Date/Time	4/29/2022 9:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	37148	
Inspector	Ben Farmer				Date/Time	4/29/2022 12:44 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	14171+36	
State	VA	Inspection Area	Partial		Station End	14311+57	
County	Franklin	Ground	Dry		Temperature (°F)	50.00	
Municipality	N/A	Weather	Cloudy		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe		Acceptable					
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Rock Construction Entrance		Acceptable					
Sensitive Resource Buffer		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Silt Fence (Reinforced Filter Fabric Fence)		Acceptable					
Slope Drain Pipe		Acceptable					
Waterbar		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

AFE	124300139	Date/Time	4/29/2022 12:44 PM	Report #	37148
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 50F) Rain Gauge= 0.0" 14171+36-14311+57 -EI began inspection at Angle Plantation Rd. -RCEs are in good condition at all road crossings. -Equipment bridge ECDs are in good condition and functioning -P1 is in good condition at all stream and wetland buffers. -Waterbars/end treatments are in good condition throughout this section. -Resource buffers remain well vegetated. -CWDs are functioning as intended. -SSF is in good condition -CFS remains in good condition -Slope drain is in good condition and functioning at 14232+00 -Ground nest located along MVP-FR-313. ESI has been notified. -Drainage ECDs are in good condition at 14275+00.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	4/29/2022 12:44 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14171+36		Field Station#	14176+09	
Pic 1 Desc.	RCEs are in good condition at all road crossings		Pic 2 Desc.	Equipment bridge ECDs are in place and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14180+00		Field Station#	14182+00	
Pic 3 Desc.	CWDs are functioning as intended		Pic 4 Desc.	SSF is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14188+00		Field Station#	14190+40	
Pic 5 Desc.	End treatments are functioning		Pic 6 Desc.	P1 is in good condition at all stream and wetland buffers	

AFE	124300139	Date/Time	4/29/2022 12:44 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14223+41		Field Station#	14220+00	
Pic 7 Desc.	MVP-FR-311 remains in good condition with controls in place.		Pic 8 Desc.	This area remains stabilized	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14232+00		Field Station#	14272+62	
Pic 9 Desc.	Slope drain is in good condition		Pic 10 Desc.	Ground nest found at this location. ESI has been notified	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14273+00		Field Station#	14278+93	
Pic 11 Desc.	Drainage ECDs are in good condition and functioning		Pic 12 Desc.	Resource buffers remain well vegetated.	






A/E	124300139	Date/Time	4/29/2022 12:44 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	37181	
Inspector	Frank Craycroft				Date/Time	4/29/2022 2:06 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	0+00	
State	VA	Inspection Area	Partial		Station End	0+00	
County	Franklin	Ground	Dry		Temperature (°F)	65.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Housekeeping		Acceptable					
Rock Construction Entrance		Acceptable					
Secondary Containment		Acceptable					
Timber Mat		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
Waste Management		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	4/29/2022 2:06 PM	Report #	37181
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All perimeter ECDs were functional and in good condition. Stormwater drain inlets had proper perimeter protection and were free of vegetation and debris. Yards were free of loose construction debris and trash, and on-site dumpsters have adequate additional storage capacity.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 2:06 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-032 Rock construction entrance	Pic 2 Desc.	LY-032 Secondary containment		
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-033 Secondary containment	Pic 4 Desc.	LY-033 Stormwater drain inlet protection		
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	ANC-006 Southeast perimeter CFS	Pic 6 Desc.	ANC-006 Stormwater drain inlet protection		

A/E	124300139	Date/Time	4/29/2022 2:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/29/2022 2:06 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	37141	
Inspector	John White			Date/Time	4/29/2022 10:44 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	00+00	
County	Pittsylvania	Ground	Dry	Temperature (°F)	55.00	
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00	
			Rain Accumulation Time (days)	6.00		
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes	
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No	
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes	
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No	
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes	
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes	
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No	

A/E	124300139	Date/Time	4/29/2022 10:44 AM	Report #	37141
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Blairs yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 10:44 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 1 Desc.	Observing entrance to the Blairs yard		Pic 2 Desc.	Observing temporary stabilization and ECD's	
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 3 Desc.	Observing temporary stabilization and ECD's		Pic 4 Desc.	Observing temporary stabilization and ECD's	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	4/29/2022 10:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/29/2022 10:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37147
Inspector	Ben Farmer			Date/Time	4/29/2022 12:44 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Partial	Station End	14694+77
County	Franklin	Ground	Dry	Temperature (°F)	50.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/29/2022 12:44 PM	Report #	37147
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 50F) Rain Gauge= 0.0" 14649+67-14694+77 -EI began inspection at Highway 40 -Vegetation continues to fill in throughout this section. -P1 is in good condition at all resource buffers. -Equipment bridge ECDs are in place and functioning -Waterbars are in good condition and functioning. -SSF is in good condition. -End treatments are functioning as intended. -Topsoil berms remain stabilized -CFS is in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 12:44 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14649+67		Field Station#	14651+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings.		Pic 2 Desc.	Vegetation continues to fill in throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14656+87		Field Station#	14656+87	
Pic 3 Desc.	P1 is in good condition at all stream and wetland buffers		Pic 4 Desc.	Equipment bridge ECDs are in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14660+00		Field Station#	14680+00	
Pic 5 Desc.	Waterbars are in good condition		Pic 6 Desc.	SSF is in good condition	

AFE 124300139		Date/Time 4/29/2022 12:44 PM		Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14680+67		Field Station#	14687+00	
Pic 7 Desc.	CFS is in good condition throughout this section		Pic 8 Desc.	End treatments are functioning as intended	
				Insert image here	
GPS Location	See photo		GPS Location		
Field Station#	14688+00		Field Station#		
Pic 9 Desc.	Topsoil berms remain stabilized.		Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		




A/E	124300139	Date/Time	4/29/2022 12:44 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37139
Inspector	Glenn Mike Renfro			Date/Time	4/29/2022 10:25 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00
State	VA	Inspection Area	Full	Station End	0000+00
County	Franklin	Ground	Dry	Temperature (°F)	55.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Other - Explain in Comments	Acceptable	Inlet protection for catch basins			
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Secondary Containment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/29/2022 10:25 AM	Report #	37139
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have received .20" of rainfall since the last inspection and site conditions were dry. - All perimeter ECD's were inspected and no issues were observed. - The inlet protection for the catch basins at LY-046 were found to be in acceptable condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no issues found to report during today's inspection 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 10:25 AM	Report #	
Pictures					
	South West Elevation 58°NE (T) 36°58'11"N, 79°52'5"W ±13ft ▲1199ft 			North West Elevation 126°SE (T) 36°58'11"N, 79°52'7"W ±13ft ▲1175ft 	
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 1 Desc.	RCE for LY-045 in good condition.		Pic 2 Desc.	Perimeter ECD's on on west side of LY-045 in good condition.	
	North Elevation 184°S (T) 36°58'14"N, 79°52'9"W ±13ft ▲1193ft 			South West Elevation 41°NE (T) 36°58'16"N, 79°52'12"W ±13ft ▲1186ft 	
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 3 Desc.	Secondary containment structure on north end of LY-045 in good condition.		Pic 4 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.	
	North Elevation 199°S (T) 36°58'16"N, 79°52'11"W ±13ft ▲1180ft 			North Elevation 184°S (T) 36°58'17"N, 79°52'14"W ±13ft ▲1176ft 	
GPS Location	See picture		GPS Location	See picture	
Field Station#	0000+00		Field Station#	0000+00	
Pic 5 Desc.	Perimeter ECD's on south end of LY-046 in acceptable condition.		Pic 6 Desc.	Perimeter ECD's on west side of LY-046 in acceptable condition.	

A/E	124300139	Date/Time	4/29/2022 10:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







AFE	124300139	Date/Time	4/29/2022 10:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37137
Inspector	John White			Date/Time	4/29/2022 10:04 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	53.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/29/2022 10:04 AM	Report #	37137
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 10:04 AM	Report #	
Pictures					
<div>South Elevation</div> <div>☉ 341°N (T) ● 36°49'51"N, 79°20'38"W ±16ft ▲ 638ft</div> <div></div> <div>Your Watermark 29 Apr 2022, 09:34:20</div>			<div>West Elevation</div> <div>☉ 103°E (T) ● 36°49'51"N, 79°20'37"W ±29ft ▲ 640ft</div> <div></div> <div>Your Watermark 29 Apr 2022, 09:34:08</div>		
GPS Location	O		GPS Location	O	
Field Station#	16023+00		Field Station#	16025+00	
Pic 1 Desc.	Observing temporary stabilization and water bars		Pic 2 Desc.	Observing temporary stabilization	
<div>South Elevation</div> <div>☉ 13°N (T) ● 36°49'50"N, 79°20'41"W ±55ft ▲ 620ft</div> <div></div> <div>Your Watermark 29 Apr 2022, 09:35:32</div>			<div>North West Elevation</div> <div>☉ 136°SE (T) ● 36°49'48"N, 79°20'44"W ±45ft ▲ 608ft</div> <div></div> <div>Your Watermark 29 Apr 2022, 09:36:50</div>		
GPS Location	O		GPS Location	O	
Field Station#	16020+00		Field Station#	16016+36	
Pic 3 Desc.	Observing temporary stabilization, sump and end treatment		Pic 4 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	
<div>West Elevation</div> <div>☉ 100°E (T) ● 36°49'47"N, 79°20'45"W ±2417ft ▲ 608ft</div> <div></div> <div>Your Watermark 29 Apr 2022, 09:37:38</div>			<div>West Elevation</div> <div>☉ 83°E (T) ● 36°49'45"N, 79°20'46"W ±4084ft ▲ 608ft</div> <div></div> <div>Your Watermark 29 Apr 2022, 09:38:58</div>		
GPS Location	O		GPS Location	O	
Field Station#	16015+50		Field Station#	16010+00	
Pic 5 Desc.	Observing temporary stabilization and ECD's		Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's	

A/E	124300139	Date/Time	4/29/2022 10:04 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location			
Field Station#	16004+00	Field Station#			
Pic 7 Desc.	Observing temporary stabilization, signage, buffer and water bars	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			





A/E	124300139	Date/Time	4/29/2022 10:04 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	37132	
Inspector	John White			Date/Time	4/29/2022 9:45 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Dry	Temperature (°F)	53.00	
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	4.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Sensitive Resource Buffer		Acceptable				
Silt Fence (Filter Fabric Fence)		Acceptable				
Sensitive Resource Signage		Acceptable				
Sump Pit		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waterbar		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	4/29/2022 9:45 AM	Report #	37132
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 9:45 AM	Report #	
Pictures					
South Elevation 20°N (T) 36°50'7"N, 79°20'23"W ±29ft ▲660ft 		South Elevation 350°N (T) 36°50'3"N, 79°20'18"W ±13ft ▲647ft 			
GPS Location	O	GPS Location	O		
Field Station#	14+00	Field Station#	20+00		
Pic 1 Desc.	Observing temporary stabilization, signage, buffer, RCE and ECD's		Pic 2 Desc.	Observing temporary stabilization, signage and buffer	
North Elevation 158°S (T) 36°50'6"N, 79°20'24"W ±72ft ▲657ft 		West Elevation 69°E (T) 36°50'6"N, 79°20'24"W ±29ft ▲652ft 			
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	12+00		
Pic 3 Desc.	Observing temporary stabilization and water bar		Pic 4 Desc.	Observing temporary stabilization, water bar, sump and end treatment	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	4/29/2022 9:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	4/29/2022 9:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	37142
Inspector	Logan Box			Date/Time	4/29/2022 4:36 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Dry	Temperature (°F)	70.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Sump Pit	Acceptable				
Equipment Bridge	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	4/29/2022 4:36 PM	Report #	37142
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored RCEs and vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	4/29/2022 4:36 PM	Report #	
Pictures					
	West Elevation 			North West Elevation 	
GPS Location	00000	GPS Location	0000		
Field Station#	13827+30	Field Station#	13812+00		
Pic 1 Desc.	Observed perimeter ECDs during row inspection today, no environmental issues observed at the time of inspection.		Pic 2 Desc.	Monitored ECDs at road crossings during inspection, no issues were observed.	
	North Elevation 			South Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13790+47	Field Station#	13790+47		
Pic 3 Desc.	Stream observation photo facing downstream during routine inspection today. No issues were observed at the time of inspection.		Pic 4 Desc.	Stream observation photo facing upstream during routine inspection today.	
	West Elevation 			North East Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13756+60	Field Station#	13811+50		
Pic 5 Desc.	Monitored perimeter ECDs during inspection today, no environmental issues observed at the time of inspection.		Pic 6 Desc.	Monitored sump pits and end treatment during routine inspection.	

A/E	124300139	Date/Time	4/29/2022 4:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	4/29/2022 4:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	36936
Inspector	John White			Date/Time	4/25/2022 11:34 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	80.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Rock Filter Outlet	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sediment Basin	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	4/25/2022 11:34 AM	Report #	36936
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	4/25/2022 11:34 AM	Report #	
Pictures					
West Elevation 69°E (T) 36°50'7"N, 79°20'24"W ±13ft ▲658ft  Your Watermark 25 Apr 2022, 10:48:23			South Elevation 22°N (T) 36°50'0"N, 79°20'40"W ±7431ft ▲669ft  Your Watermark 25 Apr 2022, 10:50:41		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 1 Desc.	Observing RCE		Pic 2 Desc.	Observing temporary stabilization and Lay down yard	
South East Elevation 311°NW (T) 36°50'5"N, 79°20'31"W ±1742ft ▲664ft  Your Watermark 25 Apr 2022, 10:53:11			South Elevation 358°N (T) 36°49'57"N, 79°20'36"W ±13ft ▲651ft  Your Watermark 25 Apr 2022, 10:53:38		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 3 Desc.	Observing temporary stabilization, erosion control blanket, CFS checks and rock drain		Pic 4 Desc.	Observing temporary stabilization and sediment basin	
West Elevation 101°E (T) 36°50'1"N, 79°20'38"W ±1669ft ▲664ft  Your Watermark 25 Apr 2022, 10:56:32			South West Elevation 68°NE (T) 36°50'1"N, 79°20'38"W ±16ft ▲654ft  Your Watermark 25 Apr 2022, 10:56:49		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 5 Desc.	Observing temporary stabilization and sediment basin		Pic 6 Desc.	Observing temporary stabilization and rock overflow at sediment basin	

A/E	124300113	Date/Time	4/25/2022 11:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	4/25/2022 11:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	37134
Inspector	John White			Date/Time	4/29/2022 9:53 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	53.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Sediment Basin	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sediment Filter Log	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	4/29/2022 9:53 AM	Report #	37134
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300113	Date/Time	4/29/2022 9:53 AM	Report #	
Pictures					
South Elevation 338°N (T) 0°0'0"N, 0°0'0"E ▲ 0ft 			North West Elevation 147°SE (T) 36°50'5"N, 79°20'31"W ±377ft ▲ 674ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 1 Desc.	Observing RCE		Pic 2 Desc.	Observing temporary stabilization, access road, rock check dams and ECD's	
North East Elevation 216°SW (T) 36°50'4"N, 79°20'29"W ±318ft ▲ 673ft 			West Elevation 89°E (T) 36°47'51"N, 79°18'30"W ±25413ft ▲ 661ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 3 Desc.	Observing Lay down yard		Pic 4 Desc.	Observing temporary stabilization and sediment basin	
South East Elevation 318°NW (T) 36°49'56"N, 79°20'36"W ±301ft ▲ 596ft 			North East Elevation 246°SW (T) 36°49'57"N, 79°20'36"W ±36ft ▲ 645ft 		
GPS Location	O		GPS Location	O	
Field Station#	00+00		Field Station#	00+00	
Pic 5 Desc.	Observing temporary stabilization and sediment basin		Pic 6 Desc.	Observing temporary stabilization, rock drain, erosion control blanket and cfs checks	

A/E	124300113	Date/Time	4/29/2022 9:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	4/29/2022 9:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		